






T20250504054838




BLK: 4, SNR1: 0.69921 , SNR2: 4.3218




F20250504054839









BLK: 4, SNR1: 0.46905 , SNR2: 2.0290




2045+483 2025/05/03 20.84UT TOYOKAWA-FUJI










T20250504061854




BLK: 8, SNR1: 76.334 , SNR2: 292.66




F20250504061855






BLK: 8, SNR1: 9.5432 , SNR2: 11.812







2114+247 2025/05/03 21.34UT TOYOKAWA-FUJI















BLK: 4,SNR1: 2.6537 ,SNR2: 14.511









BLK: 4,SNR1: 2.6232 ,SNR2: 8.4047




2131+379 2025/05/03 21.62UT TOYOKAWA-FUJI









T20250504064408




BLK: 6,SNR1: 6.4237 ,SNR2: 25.110




F20250504064409








BLK: 6,SNR1: 0.65392 ,SNR2: 5.0091




2139+028 2025/05/03 21.76UT TOYOKAWA-FUJI









2139+028 2025/05/03 21.76UT FUJI -KISO








T20250504065215




No.Good Data




F20250504065216








No.Good Data




2147+145 2025/05/03 21.90UT TOYOKAWA-FUJI










2147+145 2025/05/03 21.90UT FUJI -KISO



T20250504070119





BLK: 1, SNR1: 2.7358 , SNR2: 12.807




Frequency (Hz)

F20250504070119






BLK: 1, SNR1: 0.83330 , SNR2: 6.1800




Frequency (Hz)




2156-043 2025/05/03 22.05UT TOYOKAWA-FUJI







2156-043 2025/05/03 22.05UT TOYOKAWA-KISO








T20250504070808




No.Good Data




F20250504070809






No.Good Data










2203-18 2025/05/03 22.16UT TOYOKAWA-FUJI




















2210+016 2025/05/03 22.27UT TOYOKAWA-FUJI









T20250504072153




BLK: 3, SNR1: 1.2373 , SNR2: 6.4535




F20250504072154









BLK: 3, SNR1: -0.15568 , SNR2: 0.89045







2217+128 2025/05/03 22.39UT TOYOKAWA-FUJI
















3C446 2025/05/03 22.49UT TOYOKAWA-FUJI













T20250504073423




BLK: 3, SNR1: 3.8264 , SNR2: 11.755




F20250504073424









BLK: 3, SNR1: -0.13647 , SNR2: 2.3430




2229-093 2025/05/03 22.60UT TOYOKAWA-FUJI









T20250504074250




BLK: 8, SNR1: 16.851 , SNR2: 40.928




F20250504074250









BLK: 8, SNR1: 6.5786 , SNR2: 19.684



2238-113 2025/05/03 22.74UT TOYOKAWA-FUJI











T20250504075539




BLK: 5, SNR1: 1.1338 , SNR2: 3.4772








3C454.3 2025/05/03 22.96UT TOYOKAWA-FUJI




F20250504075540





BLK: 5, SNR1: 0.81286 , SNR2: 3.9069










T20250504080322




No. Good Data




F20250504080322









No. Good Data





2259+481 2025/05/03 23.08UT TOYOKAWA-FUJI








T20250504081816





BLK: 9, SNR1: 8.8331 ,SNR2: 31.028








3C459 2025/05/03 23.33UT TOYOKAWA-FUJI

F20250504081817










BLK: 9, SNR1: 1.3182 ,SNR2: 4.1529






















2347-02 2025/05/03 23.90UT TOYOKAWA-FUJI


















3C2 2025/05/04 0.16UT TOYOKAWA-FUJI









T20250504091518




BLK: 6, SNR1: 9.0732 , SNR2: 22.868




F20250504091518





BLK: 6, SNR1: 6.0207 , SNR2: 15.455




0011+344 2025/05/04 0.28UT TOYOKAWA-FUJI















0011+344 2025/05/04 0.28UT TOYOKAWA-KISO














0019-00 2025/05/04 0.43UT TOYOKAWA-FUJI









T20250504093409




BLK:12,SNR1: 3.8446 ,SNR2: 9.4988




F20250504093409









BLK:12,SNR1: 3.7245 ,SNR2: 10.213



3C12 2025/05/04 0.60UT TOYOKAWA-FUJI














T20250504094811




BLK: 8, SNR1: 8.5604 , SNR2: 21.487




F20250504094812





BLK: 8, SNR1: 3.1974 , SNR2: 8.7778







0044-056 2025/05/04 0.83UT TOYOKAWA-FUJI







0044-056 2025/05/04 0.83UT TOYOKAWA-KISO








T20250504095532




BLK:12,SNR1: 0.94148E-01,SNR2: 1.7680




F20250504095532









BLK:12,SNR1:-0.17529 ,SNR2: 0.90952







3C26 2025/05/04 0.95UT TOYOKAWA-FUJI













0056-00 2025/05/04 1.04UT TOYOKAWA-FUJI









0056-00 2025/05/04 1.04UT TOYOKAWA-KISO









T20250504101013




BLK: 9,SNR1: 2.0869 ,SNR2: 5.5261




F20250504101013









BLK: 9,SNR1: 4.4157 ,SNR2: 13.242





0106+01 2025/05/04 1.20UT TOYOKAWA-FUJI










T20250504102103




BLK: 7,SNR1: 0.43851 ,SNR2: 1.8117




F20250504102104





BLK: 7,SNR1: 0.22998 ,SNR2: 1.5517






0116+31 2025/05/04 1.38UT TOYOKAWA-FUJI






0116+31 2025/05/04 1.38UT TOYOKAWA-KISO







0116+31 2025/05/04 1.38UT FUJI -KISO




T20250504103126




BLK:18,SNR1: 1.3032 ,SNR2: 3.6082




F20250504103127






BLK:18,SNR1: 1.4784 ,SNR2: 4.9968






3C43 2025/05/04 1.55UT TOYOKAWA-FUJI












T20250504103910




BLK:22,SNR1: 18.806 ,SNR2: 127.61




F20250504103910









BLK:22,SNR1: 0.29857 ,SNR2: 4.7900




3C48 2025/05/04 1.68UT TOYOKAWA-FUJI













BLK: 7,SNR1: 0.62880 ,SNR2: 1.5044









BLK: 7,SNR1: 0.25095 ,SNR2: 2.2557



0155-109 2025/05/04 2.01UT TOYOKAWA-FUJI













T20250504110601




BLK:21,SNR1: 1.5848 ,SNR2: 5.5336




F20250504110602









BLK:21,SNR1: 4.7921 ,SNR2: 14.587





0202+15 2025/05/04 2.13UT TOYOKAWA-FUJI









T20250504111752




BLK:16,SNR1: 5.9713 ,SNR2: 16.705




F20250504111752





BLK:16,SNR1: 8.4460 ,SNR2: 16.085







0213+178 2025/05/04 2.33UT TOYOKAWA-FUJI







0213+178 2025/05/04 2.33UT TOYOKAWA-KISO







T20250504112534




BLK:19,SNR1: 20.728 ,SNR2: 30.122




F20250504112535





BLK:19,SNR1: 0.71486 ,SNR2: 2.3509




3C67 2025/05/04 2.45UT TOYOKAWA-FUJI




T20250504112534




BLK:18,SNR1: 20.867 ,SNR2: 30.325




K20250504112532



BLK:18,SNR1: 4.7366 ,SNR2: 9.9106




3C67 2025/05/04 2.45UT TOYOKAWA-KISO







F20250504112535




BLK:22,SNR1: 0.23368 ,SNR2: 2.8264




K20250504112532





BLK:22,SNR1: 4.5362 ,SNR2: 9.1847




3C67 2025/05/04 2.45UT FUJI -KISO




T20250504114349




BLK:23,SNR1: 144.66 ,SNR2: 293.65




F20250504114349









BLK:23,SNR1: 1.7477 ,SNR2: 14.353





3C71 2025/05/04 2.76UT TOYOKAWA-FUJI









T20250504120304




BLK:11,SNR1: 3.7671 ,SNR2: 11.188




F20250504120304









BLK:11,SNR1: 0.25781 ,SNR2: 3.3732








0258+350 2025/05/04 3.08UT TOYOKAWA-FUJI






















0308+305 2025/05/04 3.24UT TOYOKAWA-KISO









BLK:13,SNR1: 10.433 ,SNR2: 35.464








BLK:13,SNR1:-0.14468 ,SNR2: 0.86902




0320+05 2025/05/04 3.44UT TOYOKAWA-FUJI










0320+05 2025/05/04 3.44UT FUJI -KISO




T20250504123746




BLK: 7,SNR1: 0.13121 ,SNR2: 2.4864




F20250504123746





BLK: 7,SNR1: 0.59245 ,SNR2: 2.1078






0333+32 2025/05/04 3.66UT TOYOKAWA-FUJI






0333+32 2025/05/04 3.66UT TOYOKAWA-KISO







0333+32 2025/05/04 3.66UT FUJI -KISO






T20250504125048





BLK: 9,SNR1: 0.35415 ,SNR2: 1.3215




Frequency (Hz)

F20250504125049







BLK: 9,SNR1:-0.26943 ,SNR2: 0.35973





Frequency (Hz)


0347+05 2025/05/04 3.87UT TOYOKAWA-FUJI










0347+05 2025/05/04 3.87UT FUJI -KISO







BLK: 8, SNR1: 64.912 , SNR2: 204.93





BLK: 8, SNR1: -0.86154E-01, SNR2: 4.8046







0403-132 2025/05/04 4.13UT TOYOKAWA-FUJI








0403-132 2025/05/04 4.13UT TOYOKAWA-KISO









BLK: 8,SNR1: 0.33891 ,SNR2: 1.1307





BLK: 8,SNR1: -0.19719 ,SNR2: 0.78069




0411+05 2025/05/04 4.29UT TOYOKAWA-FUJI









0411+05 2025/05/04 4.29UT TOYOKAWA-KISO













BLK: 9,SNR1: 0.14677 ,SNR2: 1.8500





BLK: 9,SNR1: 14.605 ,SNR2: 38.745







0422+178 2025/05/04 4.47UT TOYOKAWA-FUJI







0422+178 2025/05/04 4.47UT TOYOKAWA-KISO







T20250504133402




BLK: 6,SNR1: 0.28699 ,SNR2: 1.0574




F20250504133402









BLK: 6,SNR1: 0.79767E-02,SNR2: 4.4208





3C120 2025/05/04 4.60UT TOYOKAWA-FUJI









T20250504142202




BLK:21,SNR1: 1.7408 ,SNR2: 6.3429




F20250504142202






BLK:21,SNR1:-0.31526 ,SNR2: 0.0000






3C138 2025/05/04 5.40UT TOYOKAWA-FUJI













T20250504143535




BLK:12,SNR1: 0.51766 ,SNR2: 2.0441




F20250504143535





BLK:12,SNR1: 0.25789 ,SNR2: 4.2700







0531+194 2025/05/04 5.62UT TOYOKAWA-FUJI








0531+194 2025/05/04 5.62UT TOYOKAWA-KISO









BLK:14,SNR1: 1.8495 ,SNR2: 5.8058









BLK:14,SNR1:-0.30793 ,SNR2: 0.23977




3C147 2025/05/04 5.76UT TOYOKAWA-FUJI















BLK: 3,SNR1: 1.1341 ,SNR2: 2.1036





BLK: 3,SNR1: 1.0678 ,SNR2: 4.1374







0548+16 2025/05/04 5.90UT TOYOKAWA-FUJI






0548+16 2025/05/04 5.90UT TOYOKAWA-KISO







T20250504145617




BLK: 7,SNR1: 6.9327 ,SNR2: 70.865




F20250504145617





BLK: 7,SNR1: 0.36399 ,SNR2: 5.6237







0552+12 2025/05/04 5.97UT TOYOKAWA-FUJI







0552+12 2025/05/04 5.97UT TOYOKAWA-KISO








T20250504150044




BLK: 5,SNR1: 2.3698 ,SNR2: 6.9078




F20250504150044





BLK: 5,SNR1: 6.2879 ,SNR2: 18.261




0556+191 2025/05/04 6.04UT TOYOKAWA-FUJI










0556+191 2025/05/04 6.04UT TOYOKAWA-KISO









T20250504150516




BLK: 9,SNR1: 1.8202 ,SNR2: 5.3746




F20250504150516









BLK: 9,SNR1: 0.42333E-01,SNR2: 2.4021





3C152 2025/05/04 6.12UT TOYOKAWA-FUJI










T20250504152737




BLK:10,SNR1: 4.0351 ,SNR2: 11.829




F20250504152737









BLK:10,SNR1: 12.093 ,SNR2: 22.825








3C161 2025/05/04 6.49UT TOYOKAWA-FUJI





















0652-130 2025/05/04 6.95UT TOYOKAWA-KISO






T20250504160647





BLK: 8,SNR1: 0.86650 ,SNR2: 1.8914




Frequency (Hz)

F20250504160648






BLK: 8,SNR1: 4.5841 ,SNR2: 11.757




Frequency (Hz)




0703+138 2025/05/04 7.14UT TOYOKAWA-FUJI








0703+138 2025/05/04 7.14UT TOYOKAWA-KISO









BLK: 2,SNR1: 2.1527 ,SNR2: 9.5299





BLK: 2,SNR1:-0.20203 ,SNR2: 0.99326







0713-024 2025/05/04 7.30UT TOYOKAWA-FUJI






0713-024 2025/05/04 7.30UT TOYOKAWA-KISO













BLK:12,SNR1: 1.3379 ,SNR2: 3.3948





BLK:12,SNR1: 0.18385 ,SNR2: 3.3470







0723+10 2025/05/04 7.47UT TOYOKAWA-FUJI








0723+10 2025/05/04 7.47UT TOYOKAWA-KISO









BLK: 5,SNR1: 1.3069 ,SNR2: 3.4105





BLK: 5,SNR1: 6.0349 ,SNR2: 10.284







0732+33 2025/05/04 7.64UT TOYOKAWA-FUJI







0732+33 2025/05/04 7.64UT TOYOKAWA-KISO








T20250504164437





F20250504164437




0741-06 2025/05/04 7.77UT TOYOKAWA-FUJI









0741-06 2025/05/04 7.77UT TOYOKAWA-KISO








T20250504170157




BLK: 1, SNR1: 0.35667 , SNR2: 1.7728




Frequency (Hz)

F20250504170157







BLK: 1, SNR1: 3.2325 , SNR2: 8.1629






Frequency (Hz)



3C190 2025/05/04 8.06UT TOYOKAWA-FUJI








T20250504171422





BLK:19,SNR1: 2.9047 ,SNR2: 13.772




Frequency (Hz)

F20250504171423







BLK:19,SNR1: 1.7954 ,SNR2: 5.9871







Frequency (Hz)

3C196 2025/05/04 8.27UT TOYOKAWA-FUJI













BLK: 7, SNR1: 10.688 , SNR2: 26.607






BLK: 7, SNR1: 6.0212 , SNR2: 18.028











0821+394 2025/05/04 8.45UT TOYOKAWA-FUJI















0840+424 2025/05/04 8.76UT TOYOKAWA-KISO

