






T20250509055556




BLK: 2, SNR1: 7.6216 , SNR2: 18.082




F20250509055557





BLK: 2, SNR1: 6.9433 , SNR2: 17.462




2111+301 2025/05/08 20.96UT TOYOKAWA-FUJI




T20250509055556




BLK: 5, SNR1: 7.7090 , SNR2: 18.228




K20250509055554



BLK: 5, SNR1: 8.6582 , SNR2: 21.302





2111+301 2025/05/08 20.96UT TOYOKAWA-KISO







F20250509055557




BLK: 4, SNR1: 8.7047 , SNR2: 21.783




K20250509055554




BLK: 4, SNR1: 19.051 , SNR2: 39.934





2111+301 2025/05/08 20.96UT FUJI -KISO







BLK: 4,SNR1: 9.7417 ,SNR2: 24.822




BLK: 4,SNR1: 10.017 ,SNR2: 18.325





2124+349 2025/05/08 21.18UT TOYOKAWA-FUJI







BLK: 4,SNR1: 26.495 ,SNR2: 46.930




BLK: 4,SNR1: 13.819 ,SNR2: 30.752





2124+349 2025/05/08 21.18UT TOYOKAWA-KISO







BLK: 1, SNR1: 4.7717 , SNR2: 11.808





BLK: 1, SNR1: 7.9584 , SNR2: 17.337




2124+349 2025/05/08 21.18UT FUJI -KISO




T20250509061557




BLK: 3, SNR1: 0.11270 , SNR2: 1.7234




F20250509061558





BLK: 3, SNR1: 0.84635 , SNR2: 4.3951




2131+379 2025/05/08 21.29UT TOYOKAWA-FUJI





T20250509061557




BLK: 2, SNR1: 1.0631 , SNR2: 15.670




K20250509061555




BLK: 2, SNR1: 0.21984 , SNR2: 4.3325




2131+379 2025/05/08 21.29UT TOYOKAWA-KISO





F20250509061558




BLK: 4,SNR1: 0.76692E-01,SNR2: 4.4785




K20250509061555




BLK: 4,SNR1: 2.6309 ,SNR2: 9.2167





2131+379 2025/05/08 21.29UT FUJI -KISO







BLK: 8,SNR1: 9.3337 ,SNR2: 27.024



BLK: 8,SNR1: 8.0582 ,SNR2: 23.272





2147+145 2025/05/08 21.57UT TOYOKAWA-FUJI






T20250509063235





BLK: 4, SNR1: 10.709 , SNR2: 30.994




Frequency (Hz)

K20250509063233




BLK: 4, SNR1: 14.478 , SNR2: 27.747





Frequency (Hz)


2147+145 2025/05/08 21.57UT TOYOKAWA-KISO




F20250509063236




BLK: 7, SNR1: 9.4838 , SNR2: 23.158




K20250509063233







BLK: 7, SNR1: 11.370 , SNR2: 28.046








2147+145 2025/05/08 21:57UT FUJI -KISO









2156-043 2025/05/08 21.72UT TOYOKAWA-FUJI










2156-043 2025/05/08 21.72UT TOYOKAWA-KISO










2210+016 2025/05/08 21.94UT TOYOKAWA-FUJI





T20250509065450




BLK: 2, SNR1: 11.952 , SNR2: 30.331




K20250509065447





BLK: 2, SNR1: 7.3474 , SNR2: 18.593




2210+016 2025/05/08 21.94UT TOYOKAWA-KISO



F20250509065451





BLK: 6, SNR1: 8.8309 ,SNR2: 25.960




Frequency (Hz)

K20250509065447




BLK: 6, SNR1: 8.1257 ,SNR2: 19.743





Frequency (Hz)

2210+016 2025/05/08 21.94UT FUJI -KISO







T20250509070214




BLK: 7,SNR1: 0.47688E-01,SNR2: 0.94323




F20250509070214





BLK: 7,SNR1: 0.45802 ,SNR2: 1.3594




2217+128 2025/05/08 22.07UT TOYOKAWA-FUJI




T20250509070214




BLK:11,SNR1: 0.18191 ,SNR2: 0.55132




K20250509070211




BLK:11,SNR1: 3.8119 ,SNR2: 9.6517




2217+128 2025/05/08 22.07UT TOYOKAWA-KISO




F20250509070214




BLK:14,SNR1: 0.10502 ,SNR2: 1.1996




K20250509070211












BLK:14,SNR1: 3.9620 ,SNR2: 6.0566




2217+128 2025/05/08 22.07UT FUJI -KISO













3C446 2025/05/08 22.16UT TOYOKAWA-KISO







3C446 2025/05/08 22.16UT FUJI -KISO







BLK: 2,SNR1: -0.31227E-01,SNR2: 2.5818




BLK: 2,SNR1: -0.39677E-01,SNR2: 0.67981





2229-093 2025/05/08 22.27UT TOYOKAWA-FUJI







BLK: 6,SNR1:-0.43665E-01,SNR2: 0.56735






BLK: 6,SNR1: 2.8851 ,SNR2: 10.265







2229-093 2025/05/08 22.27UT TOYOKAWA-KISO
















2238-113 2025/05/08 22.41UT TOYOKAWA-FUJI







2238-113 2025/05/08 22.41UT TOYOKAWA-KISO







BLK: 1,SNR1:-0.16120E-02,SNR2: 0.50947







BLK: 1,SNR1: 1.8949 ,SNR2: 5.4808








2238-113 2025/05/08 22.41UT FUJI -KISO










3C454.3 2025/05/08 22.63UT TOYOKAWA-FUJI






3C454.3 2025/05/08 22.63UT TOYOKAWA-KISO








3C454.3 2025/05/08 22.63UT FUJI -KISO





T20250509074342




BLK: 5, SNR1: 8.9791 , SNR2: 25.934




F20250509074343



BLK: 5, SNR1: 5.9577 , SNR2: 15.927





2259+481 2025/05/08 22.76UT TOYOKAWA-FUJI








T20250509074342




BLK: 4, SNR1: 0.15529 ,SNR2: 1.0775




K20250509074340




BLK: 4, SNR1: 4.5108 ,SNR2: 13.350




2259+481 2025/05/08 22.76UT TOYOKAWA-KISO




F20250509074343




BLK: 4, SNR1: 9.9063 , SNR2: 28.212




K20250509074340





BLK: 4, SNR1: 9.1936 , SNR2: 26.118




2259+481 2025/05/08 22.76UT FUJI -KISO



T20250509075836




BLK: 5, SNR1: 4.0805 , SNR2: 71.892





3C459 2025/05/08 23.00UT TOYOKAWA-FUJI


F20250509075837




BLK: 5, SNR1: -0.12562 , SNR2: 2.0037





T20250509075836




BLK:14,SNR1: 5.0323 ,SNR2: 17.387




K20250509075834




BLK:14,SNR1: 1.7124 ,SNR2: 5.3652




3C459 2025/05/08 23.00UT TOYOKAWA-KISO




F20250509075837




BLK: 9,SNR1: 0.54197E-01,SNR2: 1.5946




K20250509075834







BLK: 9,SNR1: 5.7441 ,SNR2: 10.013





3C459 2025/05/08 23.00UT FUJI -KISO







2347-02 2025/05/08 23.57UT TOYOKAWA-FUJI







BLK:11,SNR1: 38.075 ,SNR2: 140.59








BLK:11,SNR1: 0.23080 ,SNR2: 2.9693




2347-02 2025/05/08 23.57UT TOYOKAWA-KISO













BLK: 3, SNR1: 0.20370 , SNR2: 1.8549




BLK: 3, SNR1: 1.3095 , SNR2: 2.7569





2354+14 2025/05/08 23.68UT TOYOKAWA-FUJI







BLK: 7, SNR1: 1.3965 , SNR2: 2.1473




BLK: 7, SNR1: 10.980 , SNR2: 27.765





2354+14 2025/05/08 23.68UT TOYOKAWA-KISO







BLK: 5,SNR1:-0.11205E-02,SNR2: 1.5226





BLK: 5,SNR1: 2.7793 ,SNR2: 7.9504




2354+14 2025/05/08 23.68UT FUJI -KISO




T20250509084817




BLK: 8, SNR1: 0.39077 , SNR2: 1.7998




F20250509084818





BLK: 8, SNR1: 3.4521 , SNR2: 9.4974




3C2 2025/05/08 23.83UT TOYOKAWA-FUJI



T20250509084817





BLK:13,SNR1: 2.0789 ,SNR2: 6.2688





3C2 2025/05/08 23.83UT TOYOKAWA-KISO


K20250509084814




BLK:13,SNR1: 3.5454 ,SNR2: 9.4028



F20250509084818





BLK:10,SNR1: 0.60868 ,SNR2: 2.0535







3C2 2025/05/08 23.83UT FUJI -KISO

K20250509084814







BLK:10,SNR1: 5.8832 ,SNR2: 12.336






0009-190 2025/05/08 23.93UT TOYOKAWA-FUJI








F20250509085418





BLK: 8, SNR1: 0.18620 , SNR2: 2.0886





0009-190 2025/05/08 23.93UT FUJI -KISO


K20250509085415




BLK: 8, SNR1: 8.4726 , SNR2: 45.487




T20250509090416




BLK:10,SNR1: 0.18951 ,SNR2: 1.6724




F20250509090416





BLK:10,SNR1: 1.2070 ,SNR2: 10.154




0019-00 2025/05/09 0.10UT TOYOKAWA-FUJI





T20250509090416




BLK: 4, SNR1: 0.38075 , SNR2: 1.1855




K20250509090413




BLK: 4, SNR1: 6.0504 , SNR2: 11.265




0019-00 2025/05/09 0.10UT TOYOKAWA-KISO





F20250509090416




BLK: 1, SNR1: 2.6464 , SNR2: 5.3559




K20250509090413





BLK: 1, SNR1: 0.68599 , SNR2: 2.3119




0019-00 2025/05/09 0.10UT FUJI -KISO








3C12 2025/05/09 0.27UT TOYOKAWA-FUJI



T20250509091430





BLK:10,SNR1: 0.16602 ,SNR2: 0.96360









3C12 2025/05/09 0.27UT TOYOKAWA-KISO

K20250509091427




BLK:10,SNR1: 1.4260 ,SNR2: 4.7195







3C12 2025/05/09 0.27UT FUJI -KISO




T20250509092832




BLK: 3,SNR1: 0.63844 ,SNR2: 4.2034




F20250509092832



BLK: 3,SNR1: 1.6507 ,SNR2: 8.9747




0044-056 2025/05/09 0.50UT TOYOKAWA-FUJI








T20250509092832




BLK: 5, SNR1: 1.7138 , SNR2: 12.691




K20250509092829





BLK: 5, SNR1: 30.470 , SNR2: 41.312




0044-056 2025/05/09 0.50UT TOYOKAWA-KISO





F20250509092832




BLK: 4,SNR1: 0.13490 ,SNR2: 1.3637




K20250509092829





BLK: 4,SNR1: 0.98770E-01,SNR2: 0.40944




0044-056 2025/05/09 0.50UT FUJI -KISO





T20250509093553




BLK: 6, SNR1: 0.17015 , SNR2: 2.2370




F20250509093553







BLK: 6, SNR1: 4.2397 , SNR2: 7.6333









3C26 2025/05/09 0.63UT TOYOKAWA-FUJI







3C26 2025/05/09 0.63UT TOYOKAWA-KISO







T20250509094052




BLK:11,SNR1: 2.0970 ,SNR2: 6.3410




F20250509094053






BLK:11,SNR1: 0.40988 ,SNR2: 3.6006







0056-00 2025/05/09 0.71UT TOYOKAWA-FUJI




T20250509094052




K20250509094049




F20250509094053




BLK:24,SNR1: 0.22228 ,SNR2: 3.0213




K20250509094049



BLK:24,SNR1: 17.131 ,SNR2: 26.110




0056-00 2025/05/09 0.71UT FUJI -KISO








T20250509095034




BLK: 6,SNR1: 0.27857 ,SNR2: 2.0799




F20250509095034





BLK: 6,SNR1:-0.29805 ,SNR2: 0.29968




0106+01 2025/05/09 0.87UT TOYOKAWA-FUJI





T20250509095034




BLK:12,SNR1: 0.19974 ,SNR2: 1.6178




K20250509095031








BLK:12,SNR1: 12.355 ,SNR2: 16.018




0106+01 2025/05/09 0.87UT TOYOKAWA-KISO







T20250509100124




BLK: 8,SNR1: 0.65210 ,SNR2: 4.6285




F20250509100125





BLK: 8,SNR1:-0.33174E-01,SNR2: 1.1144




0116+31 2025/05/09 1.05UT TOYOKAWA-FUJI




T20250509100124




BLK:15,SNR1: 0.65197 ,SNR2: 3.6044




K20250509100121




BLK:15,SNR1: 4.2189 ,SNR2: 10.358




0116+31 2025/05/09 1.05UT TOYOKAWA-KISO





F20250509100125




BLK: 7,SNR1: 0.74664E-01,SNR2: 1.3312




K20250509100121




BLK: 7,SNR1: 3.0357 ,SNR2: 7.5870




0116+31 2025/05/09 1.05UT FUJI -KISO



T20250509101146




BLK:19,SNR1: 1.3566 ,SNR2: 4.7094





3C43 2025/05/09 1.22UT TOYOKAWA-FUJI


F20250509101147




BLK:19,SNR1: 0.25159 ,SNR2: 1.3844





T20250509101146




BLK:10,SNR1: 2.0869 ,SNR2: 7.1102




K20250509101143



BLK:10,SNR1: 9.5350 ,SNR2: 19.274




3C43 2025/05/09 1.22UT TOYOKAWA-KISO








F20250509101147




BLK:11,SNR1: 0.43516E-02,SNR2: 3.6969




K20250509101143




BLK:11,SNR1: 17.185 ,SNR2: 34.301




3C43 2025/05/09 1.22UT FUJI -KISO





T20250509101930




BLK:28,SNR1: 20.086 ,SNR2: 54.705




F20250509101930




BLK:28,SNR1: 5.3863 ,SNR2: 14.321





3C48 2025/05/09 1.35UT TOYOKAWA-FUJI







BLK:13,SNR1: 32.068 ,SNR2: 57.535





BLK:13,SNR1: 3.7556 ,SNR2: 9.9705




3C48 2025/05/09 1.35UT TOYOKAWA-KISO



F20250509101930





BLK:10,SNR1: 2.1175 ,SNR2: 3.7953










3C48 2025/05/09 1.35UT FUJI -KISO


K20250509101927





BLK:10,SNR1: 7.4482 ,SNR2: 21.327









BLK:14,SNR1: 0.28242 ,SNR2: 3.0919




BLK:14,SNR1: 4.1719 ,SNR2: 11.018





0155-109 2025/05/09 1.68UT TOYOKAWA-KISO







BLK:11,SNR1: 0.30868E-01,SNR2: 2.1718








BLK:11,SNR1: 0.11232 ,SNR2: 0.22508




0155-109 2025/05/09 1.68UT FUJI -KISO













BLK:12,SNR1: 3.0535 ,SNR2: 9.2963




BLK:12,SNR1: 0.72594 ,SNR2: 3.1331




0202+15 2025/05/09 1.80UT TOYOKAWA-KISO





F20250509104623




BLK:10,SNR1: 1.7301 ,SNR2: 13.135




K20250509104619








BLK:10,SNR1: 0.38269 ,SNR2: 1.7050




0202+15 2025/05/09 1.80UT FUJI -KISO







T20250509105812




BLK:11,SNR1: 9.5795 ,SNR2: 34.761




K20250509105809







BLK:11,SNR1: 21.662 ,SNR2: 59.045




0213+178 2025/05/09 2.00UT TOYOKAWA-KISO







0213+178 2025/05/09 2.00UT FUJI -KISO




T20250509110555




BLK:18,SNR1: 1.0084 ,SNR2: 3.4522




F20250509110556




BLK:18,SNR1: 2.6129 ,SNR2: 7.1960




3C67 2025/05/09 2.13UT TOYOKAWA-FUJI




T20250509110555




BLK:16,SNR1: 1.0198 ,SNR2: 3.3380




K20250509110552




BLK:16,SNR1: 0.58830 ,SNR2: 2.4594




3C67 2025/05/09 2.13UT TOYOKAWA-KISO



F20250509110556




BLK:12,SNR1: 1.0473 ,SNR2: 3.2270





3C67 2025/05/09 2.13UT FUJI -KISO






K20250509110552




BLK:12,SNR1: 0.35070 ,SNR2: 1.6303













BLK:14,SNR1: 0.36924 ,SNR2: 1.0030




BLK:14,SNR1: 4.7836 ,SNR2: 7.3537




3C71 2025/05/09 2.43UT TOYOKAWA-KISO



F20250509112410





BLK: 3,SNR1: 0.33266E-01,SNR2: 2.2767






3C71 2025/05/09 2.43UT FUJI -KISO

K20250509112408





BLK: 3,SNR1: 2.3184 ,SNR2: 5.3824







BLK:33,SNR1: 180.63 ,SNR2: 241.24




BLK:33,SNR1: 61.266 ,SNR2: 99.491




0258+350 2025/05/09 2.75UT TOYOKAWA-FUJI




T20250509114325




BLK:29,SNR1: 180.59 ,SNR2: 242.78




K20250509114322




BLK:29,SNR1: 3.8410 ,SNR2: 8.8282





0258+350 2025/05/09 2.75UT TOYOKAWA-KISO







BLK:25,SNR1: 88.349 ,SNR2: 102.48









BLK:25,SNR1: 3.4584 ,SNR2: 7.8325





0258+350 2025/05/09 2.75UT FUJI -KISO









BLK:20,SNR1: 3.4617 ,SNR2: 16.794



BLK:20,SNR1: 17.079 ,SNR2: 23.823





0308+305 2025/05/09 2.92UT TOYOKAWA-KISO








F20250509115314




BLK:10,SNR1: 1.0709 ,SNR2: 3.6235




K20250509115311













BLK:10,SNR1: 5.8393 ,SNR2: 19.471




0308+305 2025/05/09 2.92UT FUJI -KISO










F20250509120445




BLK: 7,SNR1: 0.14698 ,SNR2: 2.5541




K20250509120442




BLK: 7,SNR1: 5.5631 ,SNR2: 12.502




0320+05 2025/05/09 3.11UT FUJI -KISO




T20250509121807




BLK:10,SNR1: 0.28118 ,SNR2: 1.3877




F20250509121807




BLK:10,SNR1: 0.57248 ,SNR2: 5.7738




0333+32 2025/05/09 3.33UT TOYOKAWA-FUJI





T20250509121807




BLK: 9,SNR1: 0.20567 ,SNR2: 1.7125




K20250509121804




BLK: 9,SNR1: 0.20425 ,SNR2: 1.0377




0333+32 2025/05/09 3.33UT TOYOKAWA-KISO





F20250509121807




BLK:13,SNR1: 0.62004 ,SNR2: 5.4164




K20250509121804




BLK:13,SNR1: 0.30805E-01,SNR2: 1.8359





0333+32 2025/05/09 3.33UT FUJI -KISO







BLK: 4,SNR1: 0.87550E-03,SNR2: 1.7694





BLK: 4,SNR1:-0.85925E-01,SNR2: 0.58234




0347+05 2025/05/09 3.55UT TOYOKAWA-FUJI










0347+05 2025/05/09 3.55UT TOYOKAWA-KISO







BLK: 8,SNR1: 0.53381E-01,SNR2: 1.6297





BLK: 8,SNR1: 0.86834 ,SNR2: 3.6125




0347+05 2025/05/09 3.55UT FUJI -KISO





T20250509124642




BLK:14,SNR1: 4.7714 ,SNR2: 13.569




F20250509124643





BLK:14,SNR1: 3.6555 ,SNR2: 10.080




0403-132 2025/05/09 3.81UT TOYOKAWA-FUJI




T20250509124642




BLK: 8,SNR1: 1.6783 ,SNR2: 5.0492




K20250509124639




BLK: 8,SNR1: 9.6331 ,SNR2: 27.480




0403-132 2025/05/09 3.81UT TOYOKAWA-KISO




F20250509124643




BLK: 8,SNR1: 3.4929 ,SNR2: 16.949




K20250509124639





BLK: 8,SNR1: 6.4276 ,SNR2: 18.025




0403-132 2025/05/09 3.81UT FUJI -KISO





T20250509125553




BLK: 9,SNR1: 6.5884 ,SNR2: 16.593




F20250509125553





BLK: 9,SNR1: 4.2278 ,SNR2: 13.072




0411+05 2025/05/09 3.96UT TOYOKAWA-FUJI




T20250509125553




BLK:12,SNR1: 1.7387 ,SNR2: 3.4964




K20250509125550





BLK:12,SNR1: 15.212 ,SNR2: 34.194




0411+05 2025/05/09 3.96UT TOYOKAWA-KISO




F20250509125553




BLK: 7,SNR1: 1.6768 ,SNR2: 5.1606




K20250509125550







BLK: 7,SNR1: 16.666 ,SNR2: 31.893




0411+05 2025/05/09 3.96UT FUJI -KISO










0422+178 2025/05/09 4.14UT TOYOKAWA-FUJI







BLK:10,SNR1: 2.5367 ,SNR2: 6.1123




BLK:10,SNR1: 10.188 ,SNR2: 25.808





0422+178 2025/05/09 4.14UT TOYOKAWA-KISO







BLK: 9,SNR1: 10.483 ,SNR2: 29.469





BLK: 9,SNR1: 8.2536 ,SNR2: 21.506




0422+178 2025/05/09 4.14UT FUJI -KISO





T20250509131422




BLK:13,SNR1: 2.4163 ,SNR2: 8.5130




F20250509131422





BLK:13,SNR1:-0.11193 ,SNR2: 1.0168





3C120 2025/05/09 4.27UT TOYOKAWA-FUJI







3C120 2025/05/09 4.27UT TOYOKAWA-KISO








BLK:10,SNR1: 0.46596 ,SNR2: 2.0837





BLK:10,SNR1: 0.30655 ,SNR2: 1.7425







BLK:21,SNR1: 7.4476 ,SNR2: 20.358




BLK:21,SNR1: 10.444 ,SNR2: 25.213





3C138 2025/05/09 5.07UT TOYOKAWA-FUJI







BLK:18,SNR1: 5.5454 ,SNR2: 14.790



BLK:18,SNR1: 7.2301 ,SNR2: 20.307





3C138 2025/05/09 5.07UT TOYOKAWA-KISO








F20250509140222




K20250509140219





3C138 2025/05/09 5.07UT FUJI -KISO







BLK:14,SNR1: 7.5386 ,SNR2: 21.386




BLK:14,SNR1: 8.5034 ,SNR2: 24.631





0531+194 2025/05/09 5.29UT TOYOKAWA-FUJI







BLK: 7,SNR1: 6.1678 ,SNR2: 17.488




BLK: 7,SNR1: 7.8991 ,SNR2: 20.112





0531+194 2025/05/09 5.29UT TOYOKAWA-KISO







BLK: 8,SNR1: 8.7841 ,SNR2: 22.200




BLK: 8,SNR1: 6.8011 ,SNR2: 18.357





0531+194 2025/05/09 5.29UT FUJI -KISO







BLK:31,SNR1: 9.1285 ,SNR2: 21.854




BLK:31,SNR1: 0.26420 ,SNR2: 3.3057





3C147 2025/05/09 5.43UT TOYOKAWA-FUJI







BLK:15,SNR1: 10.381 ,SNR2: 26.183




BLK:15,SNR1: 1.7876 ,SNR2: 3.6109





3C147 2025/05/09 5.43UT TOYOKAWA-KISO







BLK: 8,SNR1: 0.18285 ,SNR2: 2.2612





BLK: 8,SNR1: 2.1923 ,SNR2: 4.3778




3C147 2025/05/09 5.43UT FUJI -KISO





T20250509143227




BLK:24,SNR1: 8.5375 ,SNR2: 15.239




F20250509143227



BLK:24,SNR1: 4.7377 ,SNR2: 9.8141





0548+16 2025/05/09 5.57UT TOYOKAWA-FUJI








T20250509143227




BLK:26,SNR1: 8.5062 ,SNR2: 15.187




K20250509143224





BLK:26,SNR1: 8.4162 ,SNR2: 19.739




0548+16 2025/05/09 5.57UT TOYOKAWA-KISO



F20250509143227





BLK:26,SNR1: 4.6723 ,SNR2: 9.6970




Frequency (Hz)

K20250509143224





BLK:26,SNR1: 7.2651 ,SNR2: 18.588





Frequency (Hz)

0548+16 2025/05/09 5.57UT FUJI -KISO







BLK:13,SNR1: 14.305 ,SNR2: 35.677







BLK:13,SNR1: 5.1461 ,SNR2: 13.953





0552+12 2025/05/09 5.64UT TOYOKAWA-FUJI







0552+12 2025/05/09 5.64UT TOYOKAWA-KISO








BLK: 9,SNR1: 2.8866 ,SNR2: 7.7467





BLK: 9,SNR1: 12.482 ,SNR2: 31.524







BLK: 4,SNR1: 23.139 ,SNR2: 49.953




BLK: 4,SNR1: 0.31718 ,SNR2: 2.7421





0556+191 2025/05/09 5.71UT TOYOKAWA-FUJI







BLK: 7,SNR1: 3.5274 ,SNR2: 10.561





BLK: 7,SNR1: 6.0420 ,SNR2: 11.918




0556+191 2025/05/09 5.71UT TOYOKAWA-KISO





F20250509144104




BLK: 9,SNR1: 11.376 ,SNR2: 26.488




K20250509144101




BLK: 9,SNR1: 8.5874 ,SNR2: 22.998





0556+191 2025/05/09 5.71UT FUJI -KISO









BLK:10,SNR1: 15.411 ,SNR2: 38.711




BLK:10,SNR1: 2.9049 ,SNR2: 9.0942





0605-08 2025/05/09 5.84UT TOYOKAWA-FUJI







BLK:10,SNR1: 3.2132 ,SNR2: 8.9894




BLK:10,SNR1: 12.628 ,SNR2: 30.067




0605-08 2025/05/09 5.84UT TOYOKAWA-KISO




F20250509144850




BLK: 6,SNR1: 3.3791 ,SNR2: 10.693




K20250509144847




BLK: 6,SNR1: 12.073 ,SNR2: 30.496





0605-08 2025/05/09 5.84UT FUJI -KISO









BLK:18,SNR1: 5.7775 ,SNR2: 16.103




BLK:18,SNR1: 1.0466 ,SNR2: 5.6747





T20250509150758




BLK: 5, SNR1: 3.4779 , SNR2: 10.371




K20250509150755




BLK: 5, SNR1: 9.7356 , SNR2: 17.058





3C161 2025/05/09 6.16UT TOYOKAWA-KISO







BLK: 6,SNR1: 1.1055 ,SNR2: 6.0685




BLK: 6,SNR1: 3.2888 ,SNR2: 9.8988





3C161 2025/05/09 6.16UT FUJI -KISO







BLK: 9,SNR1: 10.629 ,SNR2: 24.001





BLK: 9,SNR1: 9.2045 ,SNR2: 25.163




0652-130 2025/05/09 6.62UT TOYOKAWA-FUJI









0652-130 2025/05/09 6.62UT TOYOKAWA-KISO













BLK: 6,SNR1: 11.578 ,SNR2: 28.833





BLK: 6,SNR1: 8.2267 ,SNR2: 23.791







0703+138 2025/05/09 6.81UT TOYOKAWA-FUJI







0703+138 2025/05/09 6.81UT TOYOKAWA-KISO








T20250509155630




BLK: 3,SNR1: 8.4131 ,SNR2: 21.219




F20250509155630





BLK: 3,SNR1: 0.61024 ,SNR2: 6.1056







0713-024 2025/05/09 6.97UT TOYOKAWA-FUJI







0713-024 2025/05/09 6.97UT TOYOKAWA-KISO






T20250509160642





BLK:16,SNR1: 2.5162 ,SNR2: 12.245




Frequency (Hz)

F20250509160642




BLK:16,SNR1: 1.5287 ,SNR2: 4.1078





Frequency (Hz)


0723+10 2025/05/09 7.14UT TOYOKAWA-FUJI













0723+10 2025/05/09 7.14UT TOYOKAWA-KISO









BLK:10,SNR1: 2.2827 ,SNR2: 5.3862









BLK:10,SNR1: 2.9006 ,SNR2: 12.276







0732+33 2025/05/09 7.31UT TOYOKAWA-FUJI
















0741-06 2025/05/09 7.44UT TOYOKAWA-FUJI











T20250509164217




BLK:12,SNR1: 7.9178 ,SNR2: 20.587




Frequency (Hz)

F20250509164218







BLK:12,SNR1: 4.1192 ,SNR2: 11.022










Frequency (Hz)

3C190 2025/05/09 7.73UT TOYOKAWA-FUJI

















3C196 2025/05/09 7.94UT TOYOKAWA-FUJI













BLK: 8,SNR1: 0.14210 ,SNR2: 1.0082





BLK: 8,SNR1: 5.4138 ,SNR2: 29.129



0821+394 2025/05/09 8.13UT TOYOKAWA-FUJI





0821+394 2025/05/09 8.13UT TOYOKAWA-KISO

