





T20250510060512




BLK: 4, SNR1: 7.1280 , SNR2: 20.579




F20250510060513





BLK: 4, SNR1: 9.6160 , SNR2: 25.591




2124+349 2025/05/09 21.11UT TOYOKAWA-FUJI





T20250510060512




BLK: 4, SNR1: 13.259 , SNR2: 38.203




K20250510060510



BLK: 4, SNR1: 8.1880 , SNR2: 24.187




2124+349 2025/05/09 21.11UT TOYOKAWA-KISO








F20250510060513




BLK: 1, SNR1: 12.742 , SNR2: 36.189




K20250510060510




BLK: 1, SNR1: 13.970 , SNR2: 34.136





2124+349 2025/05/09 21.11UT FUJI -KISO







BLK: 4,SNR1: 0.68847 ,SNR2: 1.8711







BLK: 4,SNR1: 0.73916 ,SNR2: 2.0452





2131+379 2025/05/09 21.23UT TOYOKAWA-FUJI









BLK: 9,SNR1: 1.0767 ,SNR2: 2.7966




BLK: 9,SNR1: 1.1550 ,SNR2: 3.6955





2131+379 2025/05/09 21.23UT FUJI -KISO







BLK: 1,SNR1: 7.6106 ,SNR2: 21.935







BLK: 1,SNR1: 8.9333 ,SNR2: 22.576




2147+145 2025/05/09 21.51UT TOYOKAWA-FUJI







2147+145 2025/05/09 21.51UT TOYOKAWA-KISO





F20250510062840




BLK: 8, SNR1: 8.7040 , SNR2: 21.827




K20250510062836





BLK: 8, SNR1: 12.838 , SNR2: 30.117




2147+145 2025/05/09 21.51UT FUJI -KISO




T20250510063744




BLK: 9,SNR1: 6.6596 ,SNR2: 18.625




F20250510063744




BLK: 9,SNR1: 12.301 ,SNR2: 30.920





2156-043 2025/05/09 21.66UT TOYOKAWA-FUJI









BLK: 8,SNR1: 8.8805 ,SNR2: 23.323




BLK: 8,SNR1: 10.756 ,SNR2: 26.760




2156-043 2025/05/09 21.66UT TOYOKAWA-KISO





F20250510063744




BLK: 8, SNR1: 13.179 , SNR2: 32.752




K20250510063741





BLK: 8, SNR1: 11.636 , SNR2: 28.712




2156-043 2025/05/09 21.66UT FUJI -KISO



T20250510065054





BLK: 6,SNR1: 8.4230 ,SNR2: 20.570




Frequency (Hz)

F20250510065055








BLK: 6,SNR1: 10.029 ,SNR2: 24.669




Frequency (Hz)

2210+016 2025/05/09 21.88UT TOYOKAWA-FUJI








2210+016 2025/05/09 21.88UT TOYOKAWA-KISO





F20250510065055




BLK: 5, SNR1: 9.8493 , SNR2: 28.353




K20250510065051





BLK: 5, SNR1: 12.531 , SNR2: 30.354




2210+016 2025/05/09 21.88UT FUJI -KISO





T20250510065818




BLK: 6, SNR1: 9.5693 , SNR2: 27.636




F20250510065818





BLK: 6, SNR1: 9.5919 , SNR2: 28.270




2217+128 2025/05/09 22.00UT TOYOKAWA-FUJI





T20250510065818




BLK: 2, SNR1: 7.9465 , SNR2: 22.935




K20250510065815








BLK: 2, SNR1: 2.2631 , SNR2: 7.0696




2217+128 2025/05/09 22.00UT TOYOKAWA-KISO













BLK: 8,SNR1: 0.80114 ,SNR2: 2.3679












BLK: 8,SNR1: 3.4852 ,SNR2: 7.7444




3C446 2025/05/09 22.10UT TOYOKAWA-FUJI









3C446 2025/05/09 22.10UT FUJI -KISO





T20250510071048




BLK: 6, SNR1: 7.1800 , SNR2: 21.105




F20250510071049





BLK: 6, SNR1: 15.019 , SNR2: 45.227




2229-093 2025/05/09 22.21UT TOYOKAWA-FUJI





T20250510071048




BLK: 8, SNR1: 6.1605 , SNR2: 16.634




K20250510071045




BLK: 8, SNR1: 12.396 , SNR2: 30.969




2229-093 2025/05/09 22.21UT TOYOKAWA-KISO





F20250510071049




BLK: 7, SNR1: 7.6284 , SNR2: 21.438




K20250510071045




BLK: 7, SNR1: 7.3653 , SNR2: 18.703




2229-093 2025/05/09 22.21UT FUJI -KISO





T20250510071915




BLK: 6, SNR1: 20.151 , SNR2: 45.251




F20250510071915




BLK: 6, SNR1: -0.12041 , SNR2: 1.7243




2238-113 2025/05/09 22.35UT TOYOKAWA-FUJI





T20250510071915




BLK: 5, SNR1: 3.8870 , SNR2: 7.5048




K20250510071912



BLK: 5, SNR1: 0.39946 , SNR2: 1.8416




2238-113 2025/05/09 22.35UT TOYOKAWA-KISO








F20250510071915




BLK: 5, SNR1: 0.57154 , SNR2: 2.7475




K20250510071912





BLK: 5, SNR1: 1.1329 , SNR2: 4.2125




2238-113 2025/05/09 22.35UT FUJI -KISO





T20250510073204




BLK: 8, SNR1: 2.5756 , SNR2: 5.9302




F20250510073205







BLK: 8, SNR1: 0.15570 , SNR2: 3.2532




3C454.3 2025/05/09 22.56UT TOYOKAWA-FUJI







3C454.3 2025/05/09 22.56UT TOYOKAWA-KISO





F20250510073205




BLK: 9,SNR1: 0.15012 ,SNR2: 3.2351




K20250510073201




BLK: 9,SNR1: 9.5913 ,SNR2: 27.204





3C454.3 2025/05/09 22.56UT FUJI -KISO







BLK: 5,SNR1: 0.33872 ,SNR2: 5.1895




BLK: 5,SNR1: 1.3718 ,SNR2: 4.2240




2259+481 2025/05/09 22.69UT TOYOKAWA-FUJI





T20250510073946




BLK: 4, SNR1: 0.39433 , SNR2: 1.6856




K20250510073943




BLK: 4, SNR1: -0.27708E-01, SNR2: 0.70659





2259+481 2025/05/09 22.69UT TOYOKAWA-KISO







BLK: 1, SNR1: 4.9621 , SNR2: 15.109




BLK: 1, SNR1: 0.33430E-01, SNR2: 1.6661




2259+481 2025/05/09 22.69UT FUJI -KISO




T20250510075440




BLK: 7, SNR1: 2.8103 , SNR2: 8.3052




F20250510075440








BLK: 7, SNR1: 0.85243 , SNR2: 2.4942




3C459 2025/05/09 22.94UT TOYOKAWA-FUJI








F20250510075440





BLK:12,SNR1: 2.8813 ,SNR2: 7.7346





3C459 2025/05/09 22.94UT FUJI -KISO


K20250510075437




BLK:12,SNR1: 2.2061 ,SNR2: 6.7956




T20250510082825




BLK:11,SNR1: 2.5980 ,SNR2: 5.9456




F20250510082825




BLK:11,SNR1: 4.0419 ,SNR2: 10.448




2347-02 2025/05/09 23.50UT TOYOKAWA-FUJI



T20250510082825





BLK:17,SNR1: 1.2946 ,SNR2: 7.1232





2347-02 2025/05/09 23.50UT TOYOKAWA-KISO


K20250510082822




BLK:17,SNR1: 1.2467 ,SNR2: 4.7787





F20250510082825




BLK:19,SNR1: 3.2964 ,SNR2: 7.3943




K20250510082822




BLK:19,SNR1: 1.0606 ,SNR2: 3.4868





2347-02 2025/05/09 23.50UT FUJI -KISO







BLK: 3,SNR1: 0.18052 ,SNR2: 0.66660




BLK: 3,SNR1: 4.6666 ,SNR2: 10.406





2354+14 2025/05/09 23.62UT TOYOKAWA-FUJI







BLK: 4,SNR1: 0.38856E-01,SNR2: 0.30051




BLK: 4,SNR1: 0.90075 ,SNR2: 6.2871




2354+14 2025/05/09 23.62UT TOYOKAWA-KISO




F20250510083519




BLK: 5, SNR1: 2.5187 , SNR2: 12.344




K20250510083515








BLK: 5, SNR1: 0.75716 , SNR2: 5.3742







2354+14 2025/05/09 23.62UT FUJI -KISO













3C2 2025/05/09 23.77UT TOYOKAWA-KISO



F20250510084421





BLK:26,SNR1: 6.9836 ,SNR2: 8.0196










3C2 2025/05/09 23.77UT FUJI -KISO


K20250510084418





BLK:26,SNR1: 8.6117 ,SNR2: 15.462









BLK: 5, SNR1: 0.81743E-01, SNR2: 0.46839




BLK: 5, SNR1: 2.8914 , SNR2: 7.9770




0011+344 2025/05/09 23.89UT TOYOKAWA-KISO





F20250510085143




BLK:12,SNR1: 0.98570 ,SNR2: 3.1860




K20250510085140








BLK:12,SNR1: 1.5734 ,SNR2: 3.1097




0011+344 2025/05/09 23.89UT FUJI -KISO






T20250510090020




BLK: 5,SNR1: 0.13494 ,SNR2: 0.90691




0019-00 2025/05/10 0.03UT TOYOKAWA-KISO


K20250510090017







BLK: 5,SNR1: 0.65374 ,SNR2: 3.0392




Frequency (Hz)

















0019-00 2025/05/10 0.03UT FUJI -KISO







3C12 2025/05/10 0.20UT TOYOKAWA-FUJI








F20250510091035




BLK:13,SNR1: 7.8815 ,SNR2: 16.021




K20250510091031







BLK:13,SNR1: 6.9331 ,SNR2: 12.064








3C12 2025/05/10 0.20UT FUJI -KISO






0044-056 2025/05/10 0.44UT TOYOKAWA-FUJI







0044-056 2025/05/10 0.44UT TOYOKAWA-KISO





F20250510092437




BLK:15,SNR1: 0.54884 ,SNR2: 3.0618




K20250510092433







BLK:15,SNR1: 1.1115 ,SNR2: 3.4236




0044-056 2025/05/10 0.44UT FUJI -KISO










3C26 2025/05/10 0.56UT TOYOKAWA-FUJI










3C26 2025/05/10 0.56UT TOYOKAWA-KISO





F20250510093157




BLK:19,SNR1: 1.0703 ,SNR2: 2.6695




K20250510093154







BLK:19,SNR1: 3.7239 ,SNR2: 10.295









3C26 2025/05/10 0.56UT FUJI -KISO










0056-00 2025/05/10 0.64UT TOYOKAWA-FUJI










0056-00 2025/05/10 0.64UT FUJI -KISO





T20250510094638




BLK:19,SNR1: 2.1210 ,SNR2: 6.5656




F20250510094638





BLK:19,SNR1: 2.6647 ,SNR2: 7.8236




0106+01 2025/05/10 0.81UT TOYOKAWA-FUJI





T20250510094638




BLK:23,SNR1: 1.9879 ,SNR2: 6.1509




K20250510094635





BLK:23,SNR1: 8.0356 ,SNR2: 15.012




0106+01 2025/05/10 0.81UT TOYOKAWA-KISO



F20250510094638





BLK:31,SNR1: 2.4812 ,SNR2: 7.3960





0106+01 2025/05/10 0.81UT FUJI -KISO

K20250510094635




BLK:31,SNR1: 7.7984 ,SNR2: 20.210







T20250510095728




BLK: 9,SNR1: 1.0712 ,SNR2: 6.5637




F20250510095728




BLK: 9,SNR1:-0.47461E-01,SNR2: 0.72474




0116+31 2025/05/10 0.99UT TOYOKAWA-FUJI




T20250510095728




BLK:12,SNR1: 0.87652 ,SNR2: 7.0114




K20250510095725




BLK:12,SNR1: 0.14845 ,SNR2: 1.2206




0116+31 2025/05/10 0.99UT TOYOKAWA-KISO





F20250510095728




BLK: 7,SNR1: 0.85854E-01,SNR2: 1.8587




K20250510095725







BLK: 7,SNR1: 0.16212 ,SNR2: 0.73650








0116+31 2025/05/10 0.99UT FUJI -KISO








3C43 2025/05/10 1.16UT TOYOKAWA-FUJI







3C43 2025/05/10 1.16UT TOYOKAWA-KISO







3C43 2025/05/10 1.16UT FUJI -KISO







BLK:19,SNR1: 3.8052 ,SNR2: 11.295




BLK:19,SNR1: 0.76444 ,SNR2: 5.8828





3C48 2025/05/10 1.29UT TOYOKAWA-FUJI







BLK:14,SNR1: 3.6533 ,SNR2: 10.904





BLK:14,SNR1: 8.2623 ,SNR2: 17.208






F20250510101534





BLK:29,SNR1: 2.4845 ,SNR2: 7.9309










3C48 2025/05/10 1.29UT FUJI -KISO




K20250510101531











BLK:29,SNR1: 19.284 ,SNR2: 22.403












































T20250510110159




BLK:20,SNR1: 1.9419 ,SNR2: 14.134




F20250510110200









BLK:20,SNR1: 0.17380 ,SNR2: 3.1951




3C67 2025/05/10 2.06UT TOYOKAWA-FUJI









T20250510112014




BLK:26,SNR1: 3.0761 ,SNR2: 10.801




F20250510112014









BLK:26,SNR1: 0.79336 ,SNR2: 2.8108








3C71 2025/05/10 2.37UT TOYOKAWA-FUJI


















BLK:25,SNR1: 16.834 ,SNR2: 31.910




BLK:25,SNR1: 2.2406 ,SNR2: 4.4739




0258+350 2025/05/10 2.69UT TOYOKAWA-KISO





F20250510113929




BLK:19,SNR1: 1.1725 ,SNR2: 2.8512




K20250510113927







BLK:19,SNR1: 0.84036 ,SNR2: 3.5058





0258+350 2025/05/10 2.69UT FUJI -KISO







0308+305 2025/05/10 2.85UT TOYOKAWA-FUJI







BLK:37,SNR1: 563.93 ,SNR2: 953.97




BLK:37,SNR1: 3.2677 ,SNR2: 13.751




0308+305 2025/05/10 2.85UT TOYOKAWA-KISO




F20250510114919




BLK:27,SNR1: 1.2269 ,SNR2: 10.483




K20250510114915







BLK:27,SNR1: 4.4156 ,SNR2: 20.668





0308+305 2025/05/10 2.85UT FUJI -KISO







0320+05 2025/05/10 3.04UT TOYOKAWA-FUJI







BLK:23,SNR1: 24.161 ,SNR2: 48.560




BLK:23,SNR1: 0.42938 ,SNR2: 2.3672





0320+05 2025/05/10 3.04UT TOYOKAWA-KISO









BLK:29,SNR1: 1.9934 ,SNR2: 9.0238




BLK:29,SNR1: 0.44271 ,SNR2: 1.8220





0320+05 2025/05/10 3.04UT FUJI -KISO







BLK:30,SNR1: 1.5231 ,SNR2: 4.7085




BLK:30,SNR1: 4.0178 ,SNR2: 10.627




0333+32 2025/05/10 3.26UT TOYOKAWA-FUJI




T20250510121411




BLK:25,SNR1: 1.6653 ,SNR2: 5.8853




K20250510121408








BLK:25,SNR1: 5.5747 ,SNR2: 10.776




0333+32 2025/05/10 3.26UT TOYOKAWA-KISO







T20250510122712




BLK: 8,SNR1: 2.0056 ,SNR2: 5.8052




F20250510122712





BLK: 8,SNR1: 5.5631 ,SNR2: 15.829




0347+05 2025/05/10 3.48UT TOYOKAWA-FUJI





T20250510122712




BLK: 5,SNR1: 1.9142 ,SNR2: 5.8984




K20250510122709




BLK: 5,SNR1: 7.9922 ,SNR2: 22.672




0347+05 2025/05/10 3.48UT TOYOKAWA-KISO




F20250510122712




BLK:14,SNR1: 7.7435 ,SNR2: 18.700




K20250510122709





BLK:14,SNR1: 6.1740 ,SNR2: 17.684




0347+05 2025/05/10 3.48UT FUJI -KISO




T20250510124246




BLK: 6,SNR1: 0.23390 ,SNR2: 1.3895




F20250510124246



BLK: 6,SNR1: -0.29309 ,SNR2: 0.48752





0403-132 2025/05/10 3.74UT TOYOKAWA-FUJI








T20250510124246




BLK: 5,SNR1: 0.19173 ,SNR2: 1.2728




K20250510124243




BLK: 5,SNR1: 0.52856E-01,SNR2: 0.65889




0403-132 2025/05/10 3.74UT TOYOKAWA-KISO




F20250510124246




BLK: 6,SNR1:-0.34143 ,SNR2: 0.12083




K20250510124243





BLK: 6,SNR1: 1.4736 ,SNR2: 4.6100




0403-132 2025/05/10 3.74UT FUJI -KISO





T20250510125157




BLK: 6,SNR1: 3.2637 ,SNR2: 9.8451




F20250510125157





BLK: 6,SNR1: 2.0177 ,SNR2: 6.0357




0411+05 2025/05/10 3.89UT TOYOKAWA-FUJI





T20250510125157




BLK: 7,SNR1: 8.8760 ,SNR2: 19.222




K20250510125155





BLK: 7,SNR1: 8.2874 ,SNR2: 21.424




0411+05 2025/05/10 3.89UT TOYOKAWA-KISO





F20250510125157




BLK: 9, SNR1: 6.6860 , SNR2: 18.655




K20250510125155







BLK: 9, SNR1: 7.7371 , SNR2: 21.802








0411+05 2025/05/10 3.89UT FUJI -KISO











0422+178 2025/05/10 4.08UT TOYOKAWA-FUJI







0422+178 2025/05/10 4.08UT TOYOKAWA-KISO









T20250510131026




BLK: 9,SNR1: 6.6653 ,SNR2: 19.210




F20250510131026





BLK: 9,SNR1: 4.1449 ,SNR2: 12.296




3C120 2025/05/10 4.20UT TOYOKAWA-FUJI





T20250510131026




BLK:13,SNR1: 0.96150 ,SNR2: 2.5908




K20250510131023




BLK:13,SNR1: 6.7314 ,SNR2: 13.089





3C120 2025/05/10 4.20UT TOYOKAWA-KISO







BLK: 7,SNR1: 4.3209 ,SNR2: 11.537




BLK: 7,SNR1: 9.5058 ,SNR2: 23.902





3C120 2025/05/10 4.20UT FUJI -KISO








BLK:21,SNR1: 15.488 ,SNR2: 39.112





BLK:21,SNR1: 28.253 ,SNR2: 55.904







BLK:21,SNR1: 15.488 ,SNR2: 39.113





BLK:21,SNR1: 100.17 ,SNR2: 93.711




3C138 2025/05/10 5.00UT TOYOKAWA-KISO





F20250510135827




BLK:18,SNR1: 27.623 ,SNR2: 54.667




K20250510135823




BLK:18,SNR1: 81.803 ,SNR2: 97.682





3C138 2025/05/10 5.00UT FUJI -KISO







BLK:20,SNR1: 20.514 ,SNR2: 22.377




BLK:20,SNR1: 3.6421 ,SNR2: 10.869





0531+194 2025/05/10 5.23UT TOYOKAWA-FUJI







BLK:22,SNR1: 20.519 ,SNR2: 22.262




BLK:22,SNR1: 2.3562 ,SNR2: 7.5609





0531+194 2025/05/10 5.23UT TOYOKAWA-KISO









BLK:18,SNR1: 3.6518 ,SNR2: 10.901




BLK:18,SNR1: 2.6587 ,SNR2: 8.3413





0531+194 2025/05/10 5.23UT FUJI -KISO







BLK:17,SNR1: 9.2221 ,SNR2: 26.507




BLK:17,SNR1: 2.8302 ,SNR2: 8.3801





3C147 2025/05/10 5.37UT TOYOKAWA-FUJI







BLK: 7,SNR1: 9.6010 ,SNR2: 27.632




BLK: 7,SNR1: 6.5938 ,SNR2: 19.275





3C147 2025/05/10 5.37UT TOYOKAWA-KISO







BLK: 8,SNR1: 9.9948 ,SNR2: 14.484




BLK: 8,SNR1: 7.1627 ,SNR2: 20.270





3C147 2025/05/10 5.37UT FUJI -KISO







BLK:15,SNR1: 0.85928 ,SNR2: 2.4646





BLK:15,SNR1:-0.32095E-01,SNR2: 1.6637




0548+16 2025/05/10 5.50UT TOYOKAWA-FUJI





T20250510142831




BLK: 9,SNR1: 0.27419 ,SNR2: 1.9891




K20250510142828




BLK: 9,SNR1: 8.5790 ,SNR2: 24.760





0548+16 2025/05/10 5.50UT TOYOKAWA-KISO








BLK: 9,SNR1: 0.59791E-01,SNR2: 1.7916





BLK: 9,SNR1: 1.2203 ,SNR2: 2.4994







BLK:19,SNR1: 11.440 ,SNR2: 27.768




BLK:19,SNR1: 1.7395 ,SNR2: 4.6734





0552+12 2025/05/10 5.57UT TOYOKAWA-FUJI









BLK:22,SNR1: 12.731 ,SNR2: 29.512





BLK:22,SNR1: 7.2801 ,SNR2: 18.891





0552+12 2025/05/10 5.57UT TOYOKAWA-KISO







0552+12 2025/05/10 5.57UT FUJI -KISO







BLK:11,SNR1: 8.6337 ,SNR2: 19.355




BLK:11,SNR1: 0.16105 ,SNR2: 3.0076





0556+191 2025/05/10 5.65UT TOYOKAWA-FUJI







BLK:17,SNR1: 2.9436 ,SNR2: 13.063




BLK:17,SNR1: 1.0199 ,SNR2: 3.2855





0556+191 2025/05/10 5.65UT TOYOKAWA-KISO








BLK:17,SNR1: 0.60173 ,SNR2: 6.2496





BLK:17,SNR1: 1.0740 ,SNR2: 5.1310







BLK: 5,SNR1: 4.6526 ,SNR2: 11.872




BLK: 5,SNR1: 2.7657 ,SNR2: 8.1905





0605-08 2025/05/10 5.78UT TOYOKAWA-FUJI







BLK: 6,SNR1: 5.5370 ,SNR2: 15.693




BLK: 6,SNR1: 8.4771 ,SNR2: 21.448




0605-08 2025/05/10 5.78UT TOYOKAWA-KISO




F20250510144454




BLK:10,SNR1: 6.1224 ,SNR2: 17.148




K20250510144451




BLK:10,SNR1: 8.0086 ,SNR2: 21.334





0605-08 2025/05/10 5.78UT FUJI -KISO










BLK:12,SNR1: 0.13228 ,SNR2: 1.7671





BLK:12,SNR1: 0.96064 ,SNR2: 8.0625







BLK: 8,SNR1: 0.36251 ,SNR2: 2.6438




BLK: 8,SNR1: 0.96571 ,SNR2: 3.8215





3C161 2025/05/10 6.10UT TOYOKAWA-KISO







BLK: 6,SNR1: 4.1840 ,SNR2: 13.764




BLK: 6,SNR1: 1.9291 ,SNR2: 3.9032





3C161 2025/05/10 6.10UT FUJI -KISO







BLK: 3,SNR1: 0.34463E-01,SNR2: 0.32319




BLK: 3,SNR1:-0.15711,SNR2: 0.83583





0652-130 2025/05/10 6.55UT TOYOKAWA-FUJI







BLK:10,SNR1: 0.10825 ,SNR2: 0.87047









BLK:10,SNR1: 1.9832 ,SNR2: 6.4524





0652-130 2025/05/10 6.55UT TOYOKAWA-KISO









BLK: 5,SNR1: 13.947 ,SNR2: 31.110




BLK: 5,SNR1: 11.352 ,SNR2: 25.550





0703+138 2025/05/10 6.75UT TOYOKAWA-FUJI







BLK: 6,SNR1: 10.601 ,SNR2: 24.513








BLK: 6,SNR1: 10.213 ,SNR2: 23.616




0703+138 2025/05/10 6.75UT TOYOKAWA-KISO










T20250510155234




BLK: 7, SNR1: 20.934 , SNR2: 50.055




F20250510155235




BLK: 7, SNR1: 12.797 , SNR2: 32.752




0713-024 2025/05/10 6.90UT TOYOKAWA-FUJI





T20250510155234




BLK: 7, SNR1: 79.310 , SNR2: 96.990




K20250510155232




BLK: 7, SNR1: 9.8977 , SNR2: 24.418





0713-024 2025/05/10 6.90UT TOYOKAWA-KISO







BLK:14,SNR1: 13.055 ,SNR2: 33.401





BLK:14,SNR1: 10.294 ,SNR2: 25.332




0713-024 2025/05/10 6.90UT FUJI -KISO





T20250510160246




BLK: 6,SNR1: 2.1404 ,SNR2: 7.2411




F20250510160246





BLK: 6,SNR1: 4.1912 ,SNR2: 9.2562




0723+10 2025/05/10 7.07UT TOYOKAWA-FUJI





T20250510160246




BLK:10,SNR1: 3.7048 ,SNR2: 6.9104




K20250510160243





BLK:10,SNR1: 11.742 ,SNR2: 28.503




0723+10 2025/05/10 7.07UT TOYOKAWA-KISO



F20250510160246





BLK: 2, SNR1: 1.8397 , SNR2: 4.6667




Frequency (Hz)

K20250510160243





BLK: 2, SNR1: 3.5954 , SNR2: 11.673





Frequency (Hz)

0723+10 2025/05/10 7.07UT FUJI -KISO







BLK:11,SNR1: 0.30668 ,SNR2: 0.60897



BLK:11,SNR1: 1.4483 ,SNR2: 3.5473





0732+33 2025/05/10 7.25UT TOYOKAWA-FUJI






T20250510161301





BLK: 8,SNR1: 0.15260 ,SNR2: 0.81688




Frequency (Hz)

K20250510161258




BLK: 8,SNR1: 0.76631 ,SNR2: 3.5033




Frequency (Hz)


0732+33 2025/05/10 7.25UT TOYOKAWA-KISO



F20250510161301





BLK:12,SNR1: 0.74382 ,SNR2: 3.7501




Frequency (Hz)

K20250510161258





BLK:12,SNR1: 0.67307 ,SNR2: 2.9998





Frequency (Hz)

0732+33 2025/05/10 7.25UT FUJI -KISO







BLK: 7,SNR1: 0.43766 ,SNR2: 2.8437







BLK: 7,SNR1: 1.3882 ,SNR2: 3.5803





0741-06 2025/05/10 7.38UT TOYOKAWA-FUJI







0741-06 2025/05/10 7.38UT TOYOKAWA-KISO







BLK:23,SNR1: 1.4370 ,SNR2: 3.9488









BLK:23,SNR1: 2.4086 ,SNR2: 9.6003





0741-06 2025/05/10 7.38UT FUJI -KISO









BLK: 6,SNR1: 0.48643 ,SNR2: 1.4232




BLK: 6,SNR1: 0.23015 ,SNR2: 1.0428





3C190 2025/05/10 7.67UT TOYOKAWA-KISO








BLK: 4,SNR1: 0.20272 ,SNR2: 2.6616





BLK: 4,SNR1:-0.13342E-01,SNR2: 0.90503









BLK: 7, SNR1: 10.312 , SNR2: 30.380




BLK: 7, SNR1: 5.5601 , SNR2: 13.936





3C196 2025/05/10 7.87UT TOYOKAWA-FUJI







BLK: 7, SNR1: 1.1366 , SNR2: 3.1824





BLK: 7, SNR1: 5.7114 , SNR2: 15.888




3C196 2025/05/10 7.87UT TOYOKAWA-KISO



F20250510165048




BLK: 5, SNR1: 4.3320 , SNR2: 10.234




Frequency (Hz)

K20250510165045








BLK: 5, SNR1: 4.4865 , SNR2: 8.7331




Frequency (Hz)

3C196 2025/05/10 7.87UT FUJI -KISO









0821+394 2025/05/10 8.06UT TOYOKAWA-FUJI




T20250510170156









K20250510170153





0821+394 2025/05/10 8.06UT TOYOKAWA-KISO











BLK: 7,SNR1:-0.30238E-01,SNR2: 1.5402




BLK: 7,SNR1: 1.9558 ,SNR2: 4.3088








3C216 2025/05/10 8.80UT TOYOKAWA-KISO








BLK: 5, SNR1: 1.1095 , SNR2: 3.4098



BLK: 5, SNR1: 0.65351 , SNR2: 2.6373



3C216 2025/05/10 8.80UT FUJI -KISO

