








BLK: 8, SNR1: 2.1315 , SNR2: 3.8138





BLK: 8, SNR1: 4.9297 , SNR2: 14.612




2119+435 2025/05/13 20.76UT TOYOKAWA-FUJI





T20250514054339




BLK:13,SNR1: 7.5253 ,SNR2: 21.983




K20250514054336







BLK:13,SNR1: 6.6884 ,SNR2: 18.793




2119+435 2025/05/13 20.76UT TOYOKAWA-KISO










2119+435 2025/05/13 20.76UT FUJI -KISO




T20250514055120




BLK: 8, SNR1: 8.1218 , SNR2: 49.011




F20250514055121





BLK: 8, SNR1: 0.87375 , SNR2: 6.6270




2127+456 2025/05/13 20.88UT TOYOKAWA-FUJI





T20250514055120




BLK:10,SNR1: 30.418 ,SNR2: 140.83




K20250514055118




BLK:10,SNR1: 1.2384 ,SNR2: 4.7918




2127+456 2025/05/13 20.88UT TOYOKAWA-KISO




F20250514055121




BLK: 7,SNR1: 0.35253 ,SNR2: 1.2293




K20250514055118







BLK: 7,SNR1: 2.4480 ,SNR2: 7.2557








2127+456 2025/05/13 20.88UT FUJI -KISO











2131+379 2025/05/13 20.97UT TOYOKAWA-FUJI







2131+379 2025/05/13 20.97UT TOYOKAWA-KISO







T20250514061256




BLK: 4,SNR1: 0.51308E-01,SNR2: 0.67352




F20250514061256



BLK: 4,SNR1: 9.2648 ,SNR2: 20.297




2147+145 2025/05/13 21.24UT TOYOKAWA-FUJI








T20250514061256




BLK: 6,SNR1: 0.64666E-01,SNR2: 1.1319




K20250514061254





BLK: 6,SNR1: 2.5480 ,SNR2: 8.0770




2147+145 2025/05/13 21.24UT TOYOKAWA-KISO





F20250514061256




BLK:11,SNR1: 8.9306 ,SNR2: 19.568




K20250514061254




BLK:11,SNR1: 2.5101 ,SNR2: 7.9713




2147+145 2025/05/13 21.24UT FUJI -KISO




T20250514062539




BLK: 5, SNR1: 12.438 , SNR2: 169.54




F20250514062540





BLK: 5, SNR1: 1.2436 , SNR2: 4.4712




2201+315 2025/05/13 21.46UT TOYOKAWA-FUJI





T20250514062539




BLK: 7, SNR1: 8.2968 ,SNR2: 112.75




K20250514062537





BLK: 7, SNR1: 1.4337 ,SNR2: 7.6157




2201+315 2025/05/13 21.46UT TOYOKAWA-KISO





F20250514062540




BLK: 6, SNR1: 0.73892 , SNR2: 3.8832




K20250514062537





BLK: 6, SNR1: 1.0174 , SNR2: 6.5731




2201+315 2025/05/13 21.46UT FUJI -KISO



T20250514063144





BLK: 9, SNR1: 3.5435 , SNR2: 10.736





2207+374 2025/05/13 21.56UT TOYOKAWA-FUJI



F20250514063144




BLK: 9, SNR1: 3.0389 , SNR2: 8.0310




T20250514063144




BLK:20,SNR1: 3.3621 ,SNR2: 10.157




K20250514063142




BLK:20,SNR1: 7.8207 ,SNR2: 13.882




2207+374 2025/05/13 21.56UT TOYOKAWA-KISO




F20250514063144




BLK:16,SNR1: 14.320 ,SNR2: 32.824




K20250514063142







BLK:16,SNR1: 8.4331 ,SNR2: 18.853




2207+374 2025/05/13 21.56UT FUJI -KISO












2217+128 2025/05/13 21.74UT TOYOKAWA-FUJI







F20250514064235




BLK:20,SNR1: 6.4757 ,SNR2: 11.841




K20250514064231









BLK:20,SNR1: 8.8858 ,SNR2: 20.122





2217+128 2025/05/13 21.74UT FUJI -KISO









BLK: 1, SNR1: 12.621 , SNR2: 255.81





BLK: 1, SNR1: 0.88140E-01, SNR2: 0.55048




3C446 2025/05/13 21.83UT TOYOKAWA-KISO



F20250514064822





BLK: 1,SNR1:-0.20576 ,SNR2: 1.8105




Frequency (Hz)

3C446 2025/05/13 21.83UT FUJI -KISO


K20250514064818





BLK: 1,SNR1: 0.89594E-01,SNR2: 0.91074




Frequency (Hz)





T20250514065504




BLK: 4,SNR1: 0.14178 ,SNR2: 0.38374




F20250514065504





BLK: 4,SNR1: 1.6447 ,SNR2: 5.0468




2229-093 2025/05/13 21.95UT TOYOKAWA-FUJI




T20250514065504




BLK: 5, SNR1: 0.40947E-02, SNR2: 0.29885




K20250514065501



BLK: 5, SNR1: 6.6555, SNR2: 17.564




2229-093 2025/05/13 21.95UT TOYOKAWA-KISO







F20250514065504




BLK: 9, SNR1: 1.5171 , SNR2: 3.7987




K20250514065501





BLK: 9, SNR1: 5.3988 , SNR2: 15.379




2229-093 2025/05/13 21.95UT FUJI -KISO




T20250514070331




BLK: 8, SNR1: 11.962 ,SNR2: 45.677




F20250514070332







BLK: 8, SNR1: 2.1525 ,SNR2: 6.6178




2238-113 2025/05/13 22.09UT TOYOKAWA-FUJI







2238-113 2025/05/13 22.09UT TOYOKAWA-KISO




F20250514070332




BLK: 7, SNR1: 1.6819 , SNR2: 7.4775




K20250514070328





BLK: 7, SNR1: 3.8565 , SNR2: 7.6138




2238-113 2025/05/13 22.09UT FUJI -KISO





T20250514071620




BLK: 6,SNR1: 0.35562E-01,SNR2: 0.53748




F20250514071621





BLK: 6,SNR1: 1.3099 ,SNR2: 2.9415




3C454.3 2025/05/13 22.30UT TOYOKAWA-FUJI




T20250514071620




BLK: 3, SNR1: 0.16630 , SNR2: 2.0716




K20250514071617




BLK: 3, SNR1: 2.8430 , SNR2: 8.1936




3C454.3 2025/05/13 22.30UT TOYOKAWA-KISO



F20250514071621




BLK: 9,SNR1: 5.5709 ,SNR2: 14.938





3C454.3 2025/05/13 22.30UT FUJI -KISO


K20250514071617




BLK: 9,SNR1: 2.9237 ,SNR2: 8.3795




T20250514072403




BLK: 6,SNR1: 0.36803 ,SNR2: 4.4956




F20250514072403



BLK: 6,SNR1: 0.51720E-01,SNR2: 1.3549




2259+481 2025/05/13 22.43UT TOYOKAWA-FUJI








T20250514072403




BLK: 4, SNR1: 0.37668 , SNR2: 2.8661




K20250514072400




BLK: 4, SNR1: 0.26406 , SNR2: 0.98091




2259+481 2025/05/13 22.43UT TOYOKAWA-KISO





F20250514072403




BLK: 8,SNR1: 1.0677 ,SNR2: 4.6032




K20250514072400





BLK: 8,SNR1: 0.92238E-01,SNR2: 0.94168




2259+481 2025/05/13 22.43UT FUJI -KISO




T20250514073856




BLK: 8,SNR1: 9.3582 ,SNR2: 30.604




F20250514073857




BLK: 8,SNR1:-0.23658E-01,SNR2: 1.4462




3C459 2025/05/13 22.68UT TOYOKAWA-FUJI




T20250514073856




BLK:13,SNR1: 4.5393 ,SNR2: 15.856




K20250514073853





BLK:13,SNR1: 8.0262 ,SNR2: 17.735




3C459 2025/05/13 22.68UT TOYOKAWA-KISO



F20250514073857





BLK:14,SNR1: 0.10479 ,SNR2: 2.4646




Frequency (Hz)

3C459 2025/05/13 22.68UT FUJI -KISO


K20250514073853




BLK:14,SNR1: 7.9268 ,SNR2: 20.557





Frequency (Hz)







BLK: 9, SNR1: 4.0795 , SNR2: 32.379







BLK: 9, SNR1: 3.1841 , SNR2: 8.5934





2347-02 2025/05/13 23.24UT TOYOKAWA-FUJI







2347-02 2025/05/13 23.24UT TOYOKAWA-KISO







BLK: 9, SNR1: 0.46919 , SNR2: 1.8291



BLK: 9, SNR1: 3.9274 , SNR2: 11.042





2347-02 2025/05/13 23.24UT FUJI -KISO







T20250514081935




BLK: 3,SNR1: 0.12646 ,SNR2: 1.4258




F20250514081936





BLK: 3,SNR1: 0.92502E-01,SNR2: 2.3433




2354+14 2025/05/13 23.35UT TOYOKAWA-FUJI





T20250514081935




BLK:12,SNR1: 0.62927E-01,SNR2: 0.45370




K20250514081932




BLK:12,SNR1: 0.97864 ,SNR2: 3.4123




2354+14 2025/05/13 23.35UT TOYOKAWA-KISO





F20250514081936




BLK:11,SNR1:-0.4233E-01,SNR2: 1.0566




K20250514081932





BLK:11,SNR1: 1.1265 ,SNR2: 3.8130




2354+14 2025/05/13 23.35UT FUJI -KISO





T20250514082838




BLK:11,SNR1: 5.8664 ,SNR2: 12.423




F20250514082839













BLK:11,SNR1: 10.449 ,SNR2: 20.309




3C2 2025/05/13 23.51UT TOYOKAWA-FUJI










T20250514083559




BLK: 4, SNR1: 0.96532 , SNR2: 6.4922




F20250514083559




BLK: 4, SNR1: 14.026 , SNR2: 31.911




0011+344 2025/05/13 23.63UT TOYOKAWA-FUJI





T20250514083559




BLK: 2, SNR1: 1.8725 , SNR2: 8.3094




K20250514083556



BLK: 2, SNR1: 1.4605 , SNR2: 4.2812





0011+344 2025/05/13 23.63UT TOYOKAWA-KISO








F20250514083559




BLK:10,SNR1: 1.1860 ,SNR2: 3.6290




K20250514083556







BLK:10,SNR1: 2.2199 ,SNR2: 6.6452





0011+344 2025/05/13 23.63UT FUJI -KISO







0019-00 2025/05/13 23.77UT TOYOKAWA-FUJI







BLK: 6,SNR1: 0.15388 ,SNR2: 0.84027




BLK: 6,SNR1: 0.47952 ,SNR2: 1.5337




0019-00 2025/05/13 23.77UT TOYOKAWA-KISO





F20250514084437




BLK: 7, SNR1: -0.15444 , SNR2: 0.85892




K20250514084433





BLK: 7, SNR1: 0.34627 , SNR2: 1.1384




0019-00 2025/05/13 23.77UT FUJI -KISO





T20250514085419




No.Good Data




F20250514085419




No.Good Data




0029+013 2025/05/13 23.93UT TOYOKAWA-FUJI





T20250514085419




BLK: 6,SNR1: 0.20967E-01,SNR2: 0.33507




K20250514085416




BLK: 6,SNR1: 1.2319 ,SNR2: 3.7785




0029+013 2025/05/13 23.93UT TOYOKAWA-KISO





F20250514085419




BLK: 5, SNR1: -0.18074 , SNR2: 0.62663




K20250514085416





BLK: 5, SNR1: 0.76607 , SNR2: 5.3888




0029+013 2025/05/13 23.93UT FUJI -KISO




T20250514090852




BLK: 5, SNR1: 0.25403 , SNR2: 1.4774




F20250514090853







BLK: 5, SNR1: 2.8892 , SNR2: 7.8698




0044-056 2025/05/14 0.18UT TOYOKAWA-FUJI










0044-056 2025/05/14 0.18UT TOYOKAWA-KISO







BLK: 4, SNR1: 0.39305 , SNR2: 1.9889





BLK: 4, SNR1: 0.29288 , SNR2: 1.2615




0044-056 2025/05/14 0.18UT FUJI -KISO




T20250514091613




BLK:13,SNR1: 3.0285 ,SNR2: 8.6873




F20250514091613





BLK:13,SNR1: 1.0152 ,SNR2: 4.3115




3C26 2025/05/14 0.30UT TOYOKAWA-FUJI




T20250514091613




BLK:21,SNR1: 2.3868 ,SNR2: 6.9238




K20250514091610








BLK:21,SNR1: 1.0075 ,SNR2: 3.3993




3C26 2025/05/14 0.30UT TOYOKAWA-KISO






T20250514092112




BLK: 8,SNR1: 0.52843 ,SNR2: 2.2116





0056-00 2025/05/14 0.38UT TOYOKAWA-FUJI


F20250514092112




BLK: 8,SNR1: 0.22893 ,SNR2: 3.4073




T20250514092112




BLK:14,SNR1: 0.43531 ,SNR2: 1.0719




K20250514092109





BLK:14,SNR1: 1.9626 ,SNR2: 6.2653




0056-00 2025/05/14 0.38UT TOYOKAWA-KISO





F20250514092112




BLK: 5, SNR1: 0.15597 , SNR2: 3.9912




K20250514092109



BLK: 5, SNR1: 1.6525 , SNR2: 4.9632





0056-00 2025/05/14 0.38UT FUJI -KISO






T20250514093054




BLK: 7, SNR1: 2.6542 , SNR2: 8.2157





0106+01 2025/05/14 0.54UT TOYOKAWA-FUJI



F20250514093055




BLK: 7, SNR1: 0.22262 , SNR2: 1.4235





T20250514093054




BLK:15,SNR1: 3.0980 ,SNR2: 9.5647




K20250514093051













BLK:15,SNR1: 0.87048 ,SNR2: 2.8994





0106+01 2025/05/14 0.54UT TOYOKAWA-KISO










T20250514094144




BLK:10,SNR1: 0.23566 ,SNR2: 3.5531




K20250514094141













BLK:10,SNR1: 2.4444 ,SNR2: 4.8115




0116+31 2025/05/14 0.72UT TOYOKAWA-KISO









T20250514095207




BLK:18,SNR1: 9.3850 ,SNR2: 20.532




K20250514095204



BLK:18,SNR1: 5.6659 ,SNR2: 12.696





3C43 2025/05/14 0.90UT TOYOKAWA-KISO






F20250514095207




BLK:19,SNR1: 0.69605 ,SNR2: 2.5689










3C43 2025/05/14 0.90UT FUJI -KISO

K20250514095204




BLK:19,SNR1: 5.9063 ,SNR2: 13.712








T20250514095951




BLK:36,SNR1: 25.496 ,SNR2: 136.41




K20250514095948




BLK:36,SNR1: 3.0524 ,SNR2: 10.519




3C48 2025/05/14 1.03UT TOYOKAWA-KISO



F20250514095951





BLK:37,SNR1: 0.49705E-02,SNR2: 4.1043





3C48 2025/05/14 1.03UT FUJI -KISO


K20250514095948




BLK:37,SNR1: 2.9528 ,SNR2: 10.157




T20250514101935




BLK:11,SNR1: 3.1348 ,SNR2: 9.6304




F20250514101935




BLK:11,SNR1: 4.9853 ,SNR2: 9.3051




0155-109 2025/05/14 1.35UT TOYOKAWA-FUJI





T20250514101935




BLK:16,SNR1: 2.7034 ,SNR2: 8.5389




K20250514101932




BLK:16,SNR1: 7.9362 ,SNR2: 20.572




0155-109 2025/05/14 1.35UT TOYOKAWA-KISO





F20250514101935




BLK:16,SNR1: 4.4900 ,SNR2: 9.9611




K20250514101932




BLK:16,SNR1: 7.8047 ,SNR2: 18.453




0155-109 2025/05/14 1.35UT FUJI -KISO




T20250514102642




BLK:21,SNR1: 1.9621 ,SNR2: 12.777




F20250514102642




BLK:21,SNR1: 0.38593 ,SNR2: 2.3889





0202+15 2025/05/14 1.47UT TOYOKAWA-FUJI









BLK:21,SNR1: 2.0964 ,SNR2: 11.385







BLK:21,SNR1: 1.1273 ,SNR2: 2.3568





0202+15 2025/05/14 1.47UT TOYOKAWA-KISO







0202+15 2025/05/14 1.47UT FUJI -KISO







BLK: 8,SNR1: 0.69306 ,SNR2: 2.0435








BLK: 8,SNR1: 2.4458 ,SNR2: 6.9342




0213+178 2025/05/14 1.67UT TOYOKAWA-FUJI








F20250514103834




BLK:13,SNR1: 7.0478 ,SNR2: 14.388




K20250514103830




BLK:13,SNR1: 3.8332 ,SNR2: 10.983




0213+178 2025/05/14 1.67UT FUJI -KISO



T20250514104615




BLK:16,SNR1: 2.7175 ,SNR2: 7.2407





3C67 2025/05/14 1.80UT TOYOKAWA-FUJI



F20250514104615




BLK:16,SNR1: 0.40600 ,SNR2: 3.1178



T20250514104615





BLK:24,SNR1: 2.7232 ,SNR2: 11.595




Frequency (Hz)

K20250514104612




BLK:24,SNR1: 0.84702 ,SNR2: 3.5431




Frequency (Hz)


3C67 2025/05/14 1.80UT TOYOKAWA-KISO



F20250514104615




BLK:18,SNR1: 0.50892 ,SNR2: 3.5839





3C67 2025/05/14 1.80UT FUJI -KISO


K20250514104612





BLK:18,SNR1: 0.77779 ,SNR2: 3.2183









BLK: 8,SNR1: 0.46544 ,SNR2: 2.2706




BLK: 8,SNR1: 0.85848 ,SNR2: 7.6349





3C71 2025/05/14 2.10UT TOYOKAWA-FUJI









BLK:11,SNR1: 1.7841 ,SNR2: 3.5824




BLK:11,SNR1: 4.6919 ,SNR2: 12.271




F20250514110431




BLK: 9,SNR1: 2.4588 ,SNR2: 6.1120




K20250514110427





BLK: 9,SNR1: 5.5704 ,SNR2: 14.315




3C71 2025/05/14 2.10UT FUJI -KISO



T20250514112345





BLK:12,SNR1: 0.78433 ,SNR2: 1.9424




Frequency (Hz)

F20250514112345




BLK:12,SNR1: 42.986 ,SNR2: 109.33





Frequency (Hz)


0258+350 2025/05/14 2.42UT TOYOKAWA-FUJI




T20250514112345




BLK:10,SNR1: 2.5959 ,SNR2: 7.2984




K20250514112342




BLK:10,SNR1: 8.2376 ,SNR2: 22.939





0258+350 2025/05/14 2.42UT TOYOKAWA-KISO







BLK:10,SNR1: 74.933 ,SNR2: 181.10




BLK:10,SNR1: 7.4298 ,SNR2: 20.351




0258+350 2025/05/14 2.42UT FUJI -KISO




T20250514113334




BLK:14,SNR1: 1.3426 ,SNR2: 3.4551




F20250514113334




BLK:14,SNR1: 4.1686 ,SNR2: 10.229




0308+305 2025/05/14 2.59UT TOYOKAWA-FUJI




T20250514113334




BLK:13,SNR1: 1.3493 ,SNR2: 3.6395




K20250514113331



BLK:13,SNR1: 7.2998 ,SNR2: 13.629




0308+305 2025/05/14 2.59UT TOYOKAWA-KISO







F20250514113334




BLK: 9,SNR1: 0.22210 ,SNR2: 3.5020




K20250514113331





BLK: 9,SNR1: 5.2537 ,SNR2: 12.194




0308+305 2025/05/14 2.59UT FUJI -KISO




T20250514114506




BLK:13,SNR1: 7.0223 ,SNR2: 18.622




F20250514114507





BLK:13,SNR1: 2.8612 ,SNR2: 8.4786




0320+05 2025/05/14 2.78UT TOYOKAWA-FUJI





T20250514114506




BLK:21,SNR1: 9.2302 ,SNR2: 23.305




K20250514114503




BLK:21,SNR1: 9.0677 ,SNR2: 22.847




0320+05 2025/05/14 2.78UT TOYOKAWA-KISO





F20250514114507




BLK:12,SNR1: 2.3256 ,SNR2: 7.0713




K20250514114503




BLK:12,SNR1: 9.0156 ,SNR2: 22.862





0320+05 2025/05/14 2.78UT FUJI -KISO







BLK: 8,SNR1: 8.5300 ,SNR2: 21.911





BLK: 8,SNR1: 7.6194 ,SNR2: 21.251




0333+32 2025/05/14 3.00UT TOYOKAWA-FUJI




T20250514115827




BLK: 6,SNR1: 9.8194 ,SNR2: 21.462




K20250514115824







BLK: 6,SNR1: 6.2025 ,SNR2: 17.771




0333+32 2025/05/14 3.00UT TOYOKAWA-KISO








0333+32 2025/05/14 3.00UT FUJI -KISO





T20250514121129




BLK: 4,SNR1: 6.1424 ,SNR2: 16.506




F20250514121130



BLK: 4,SNR1: 7.1022 ,SNR2: 19.850





0347+05 2025/05/14 3.22UT TOYOKAWA-FUJI








T20250514121129




BLK: 6,SNR1: 10.737 ,SNR2: 26.795




K20250514121126





BLK: 6,SNR1: 9.9227 ,SNR2: 24.443




0347+05 2025/05/14 3.22UT TOYOKAWA-KISO





F20250514121130




BLK: 2,SNR1: 4.3874 ,SNR2: 12.488




K20250514121126




BLK: 2,SNR1: 6.8709 ,SNR2: 19.814





0347+05 2025/05/14 3.22UT FUJI -KISO







BLK: 7,SNR1: 7.2398 ,SNR2: 8.5148




BLK: 7,SNR1: 2.1032 ,SNR2: 7.0270





0403-132 2025/05/14 3.48UT TOYOKAWA-FUJI







BLK:12,SNR1: 4.2559 ,SNR2: 5.9123




BLK:12,SNR1: 2.5489 ,SNR2: 7.9376




0403-132 2025/05/14 3.48UT TOYOKAWA-KISO





F20250514122703




BLK:15,SNR1: 1.8312 ,SNR2: 6.2305




K20250514122700





BLK:15,SNR1: 2.6027 ,SNR2: 8.1073




0403-132 2025/05/14 3.48UT FUJI -KISO




T20250514123614




BLK: 2,SNR1: 0.24693 ,SNR2: 0.92548




F20250514123614









BLK: 2,SNR1: 0.37434 ,SNR2: 6.8378





0411+05 2025/05/14 3.63UT TOYOKAWA-FUJI









BLK: 6,SNR1: 1.0333 ,SNR2: 6.2275




BLK: 6,SNR1: 8.9466 ,SNR2: 34.293





0411+05 2025/05/14 3.63UT FUJI -KISO









BLK:13,SNR1: 0.59900 ,SNR2: 1.3048




BLK:13,SNR1: 10.450 ,SNR2: 30.219





0422+178 2025/05/14 3.81UT TOYOKAWA-FUJI







BLK:14,SNR1: 0.13372 ,SNR2: 1.0189




BLK:14,SNR1: 3.9112 ,SNR2: 8.0365





0422+178 2025/05/14 3.81UT TOYOKAWA-KISO







BLK:14,SNR1: 5.3928 ,SNR2: 16.346





BLK:14,SNR1: 2.5341 ,SNR2: 8.9907




0422+178 2025/05/14 3.81UT FUJI -KISO





T20250514125436




BLK:17,SNR1: 10.266 ,SNR2: 17.957




F20250514125436





BLK:17,SNR1: 1.9951 ,SNR2: 6.6094




3C119 2025/05/14 3.94UT TOYOKAWA-FUJI





T20250514125436




BLK:21,SNR1: 10.186 ,SNR2: 17.849




K20250514125433




BLK:21,SNR1: 7.4475 ,SNR2: 12.941





3C119 2025/05/14 3.94UT TOYOKAWA-KISO







BLK:20,SNR1: 2.0240 ,SNR2: 6.6900





BLK:20,SNR1: 7.4641 ,SNR2: 12.965




3C119 2025/05/14 3.94UT FUJI -KISO




T20250514134243




BLK:19,SNR1: 3.3494 ,SNR2: 10.165




F20250514134244





BLK:19,SNR1:-0.12767 ,SNR2: 0.77890




3C138 2025/05/14 4.74UT TOYOKAWA-FUJI




T20250514134243




BLK:22,SNR1: 7.6149 ,SNR2: 13.806




K20250514134240



BLK:22,SNR1: 0.52096 ,SNR2: 1.9739





3C138 2025/05/14 4.74UT TOYOKAWA-KISO








F20250514134244




K20250514134240





3C138 2025/05/14 4.74UT FUJI -KISO







BLK:12,SNR1: 7.5387 ,SNR2: 21.443




BLK:12,SNR1: 14.415 ,SNR2: 33.173





0531+194 2025/05/14 4.97UT TOYOKAWA-FUJI







BLK: 8,SNR1: 10.704 ,SNR2: 25.101




BLK: 8,SNR1: 12.152 ,SNR2: 35.118





0531+194 2025/05/14 4.97UT TOYOKAWA-KISO







BLK: 8,SNR1: 13.735 ,SNR2: 33.035




BLK: 8,SNR1: 6.7827 ,SNR2: 18.965




0531+194 2025/05/14 4.97UT FUJI -KISO





T20250514140436




BLK:25,SNR1: 45.894 ,SNR2: 112.14




F20250514140436




BLK:25,SNR1: 3.7245 ,SNR2: 9.5279




3C147 2025/05/14 5.10UT TOYOKAWA-FUJI





T20250514140436




BLK:25,SNR1: 48.826 ,SNR2: 120.70




K20250514140433





BLK:25,SNR1: 8.3070 ,SNR2: 21.708




3C147 2025/05/14 5.10UT TOYOKAWA-KISO





F20250514140436




BLK:21,SNR1: 4.5508 ,SNR2: 11.759




K20250514140433





BLK:21,SNR1: 11.772 ,SNR2: 26.593




3C147 2025/05/14 5.10UT FUJI -KISO





T20250514141247




BLK: 6,SNR1: 0.44306 ,SNR2: 1.5983




F20250514141247



BLK: 6,SNR1:-0.10636 ,SNR2: 1.4239





0548+16 2025/05/14 5.24UT TOYOKAWA-FUJI








T20250514141247




BLK: 9,SNR1: 0.25746 ,SNR2: 1.5984




K20250514141244





BLK: 9,SNR1: 0.82819 ,SNR2: 3.0939




0548+16 2025/05/14 5.24UT TOYOKAWA-KISO





F20250514141247




BLK: 8,SNR1:-0.19893 ,SNR2: 1.6273




K20250514141244





BLK: 8,SNR1: 0.44097 ,SNR2: 1.7837




0548+16 2025/05/14 5.24UT FUJI -KISO




T20250514141658




BLK:11,SNR1: 30.846 ,SNR2: 142.51




F20250514141658




BLK:11,SNR1: 0.48047 ,SNR2: 3.1607




0552+12 2025/05/14 5.31UT TOYOKAWA-FUJI




T20250514141658




BLK: 8,SNR1: 21.000 ,SNR2: 177.38




K20250514141655




BLK: 8,SNR1: 112.65 ,SNR2: 137.80





0552+12 2025/05/14 5.31UT TOYOKAWA-KISO







BLK: 7,SNR1: 0.22826 ,SNR2: 2.4049





BLK: 7,SNR1: 83.525 ,SNR2: 111.55




0552+12 2025/05/14 5.31UT FUJI -KISO





T20250514142125




BLK:10,SNR1: 1.0430 ,SNR2: 2.7013




F20250514142125





BLK:10,SNR1: 0.34229E-01,SNR2: 2.0884




0556+191 2025/05/14 5.39UT TOYOKAWA-FUJI





T20250514142125




BLK: 9,SNR1: 0.60644 ,SNR2: 1.8790




K20250514142122





BLK: 9,SNR1: 86.554 ,SNR2: 117.90




0556+191 2025/05/14 5.39UT TOYOKAWA-KISO





F20250514142125




BLK:10,SNR1: 2.3888 ,SNR2: 8.8721




K20250514142122




BLK:10,SNR1: 0.49797 ,SNR2: 1.7507





0556+191 2025/05/14 5.39UT FUJI -KISO









BLK: 8,SNR1: 14.298 ,SNR2: 31.665




BLK: 8,SNR1: 9.9995 ,SNR2: 23.615





0605-08 2025/05/14 5.51UT TOYOKAWA-FUJI







BLK:11,SNR1: 14.204 ,SNR2: 31.440




BLK:11,SNR1: 29.467 ,SNR2: 63.143





0605-08 2025/05/14 5.51UT TOYOKAWA-KISO









BLK:16,SNR1: 9.9428 ,SNR2: 23.485




BLK:16,SNR1: 17.623 ,SNR2: 38.818




T20250514144818




BLK:12,SNR1: 42.335 ,SNR2: 55.818




F20250514144818




BLK:12,SNR1:-0.28769 ,SNR2: 0.79033




3C161 2025/05/14 5.83UT TOYOKAWA-FUJI











BLK:18,SNR1: 38.197 ,SNR2: 50.682





BLK:18,SNR1: 0.39524 ,SNR2: 1.6795

3C161 2025/05/14 5.83UT TOYOKAWA-KISO








T20250514151551




F20250514151551




0652-130 2025/05/14 6.29UT TOYOKAWA-FUJI




T20250514151551




BLK: 2,SNR1:-0.14483E-01,SNR2: 3.7348




K20250514151548




BLK: 2,SNR1: 9.2343 ,SNR2: 24.862





0652-130 2025/05/14 6.29UT TOYOKAWA-KISO









BLK: 8,SNR1: 1.1518 ,SNR2: 3.7570





BLK: 8,SNR1: 8.1619 ,SNR2: 22.425




0652-130 2025/05/14 6.29UT FUJI -KISO




T20250514152728




BLK: 6,SNR1: 0.21741E-01,SNR2: 0.27660




F20250514152729





BLK: 6,SNR1:-0.19726 ,SNR2: 2.2825




0703+138 2025/05/14 6.49UT TOYOKAWA-FUJI





T20250514152728




BLK: 2,SNR1:-0.25856E-01,SNR2: 0.73695E-01




K20250514152725




BLK: 2,SNR1:-0.66726E-01,SNR2: 0.57251





0703+138 2025/05/14 6.49UT TOYOKAWA-KISO







BLK: 3,SNR1: 0.38347E-01,SNR2: 0.72180




BLK: 3,SNR1: 0.61413E-01,SNR2: 1.4781





0703+138 2025/05/14 6.49UT FUJI -KISO







BLK: 6,SNR1: 7.9171 ,SNR2: 22.799




BLK: 6,SNR1: 0.96772 ,SNR2: 3.8343





0713-024 2025/05/14 6.64UT TOYOKAWA-FUJI







BLK: 7,SNR1: 2.8279 ,SNR2: 7.7250




BLK: 7,SNR1: 4.8098 ,SNR2: 14.131





0713-024 2025/05/14 6.64UT TOYOKAWA-KISO







BLK:10,SNR1: 6.6326 ,SNR2: 14.681




BLK:10,SNR1: 5.3869 ,SNR2: 10.707





0713-024 2025/05/14 6.64UT FUJI -KISO







BLK: 6,SNR1:-0.36517E-01,SNR2: 1.7886




BLK: 6,SNR1: 2.3883 ,SNR2: 6.5239





0723+10 2025/05/14 6.81UT TOYOKAWA-FUJI









BLK: 6,SNR1: 0.51363 ,SNR2: 1.5047









BLK: 6,SNR1: 0.98344 ,SNR2: 3.8738





0723+10 2025/05/14 6.81UT TOYOKAWA-KISO









BLK: 7,SNR1: 0.11027 ,SNR2: 2.0668





BLK: 7,SNR1:-0.20461E-01,SNR2: 3.0140




0732+33 2025/05/14 6.98UT TOYOKAWA-FUJI





T20250514155717




BLK: 8, SNR1: 0.57122E-01, SNR2: 1.2303




K20250514155714




BLK: 8, SNR1: 0.42628, SNR2: 2.8230





0732+33 2025/05/14 6.98UT TOYOKAWA-KISO








BLK: 5,SNR1:-0.74973E-01,SNR2: 2.7354




BLK: 5,SNR1: 0.42296 ,SNR2: 1.2865




T20250514160518




BLK:12,SNR1: 2.2580 ,SNR2: 6.5462




F20250514160518





BLK:12,SNR1: 5.1943 ,SNR2: 11.337





0741-06 2025/05/14 7.12UT TOYOKAWA-FUJI




T20250514160518





K20250514160515




0741-06 2025/05/14 7.12UT TOYOKAWA-KISO



F20250514160518





BLK: 8,SNR1: 1.8736 ,SNR2: 16.061




Frequency (Hz)

K20250514160515




BLK: 8,SNR1: 0.72125 ,SNR2: 3.0102




Frequency (Hz)



0741-06 2025/05/14 7.12UT FUJI -KISO









BLK:12,SNR1: 0.36328 ,SNR2: 2.8483







BLK:12,SNR1: 0.14000 ,SNR2: 2.5493




0752-200 2025/05/14 7.28UT TOYOKAWA-FUJI







0752-200 2025/05/14 7.28UT TOYOKAWA-KISO



F20250514161503





BLK:14,SNR1: 0.58169 ,SNR2: 3.1755




Frequency (Hz)

K20250514161500





BLK:14,SNR1: 3.9721 ,SNR2: 11.032





Frequency (Hz)

0752-200 2025/05/14 7.28UT FUJI -KISO







BLK: 9,SNR1: 0.35808 ,SNR2: 1.0507




BLK: 9,SNR1: 2.9354 ,SNR2: 7.1204





3C190 2025/05/14 7.41UT TOYOKAWA-FUJI







BLK:14,SNR1: 0.21654 ,SNR2: 0.97245









BLK:14,SNR1: 3.8547 ,SNR2: 11.072





3C190 2025/05/14 7.41UT TOYOKAWA-KISO









BLK:10,SNR1: 1.8430 ,SNR2: 4.6281




BLK:10,SNR1: 4.9033 ,SNR2: 12.081





3C196 2025/05/14 7.61UT TOYOKAWA-FUJI







BLK: 7, SNR1: 0.24982 , SNR2: 1.3997








BLK: 7, SNR1: 6.4888 , SNR2: 15.635




3C196 2025/05/14 7.61UT TOYOKAWA-KISO













BLK: 7,SNR1: 0.89438E-01,SNR2: 0.66188







BLK: 7,SNR1: 0.82297 ,SNR2: 5.5079





0821+394 2025/05/14 7.80UT TOYOKAWA-FUJI









BLK:16,SNR1: 41.346 ,SNR2: 56.734











BLK:16,SNR1: 2.2206 ,SNR2: 7.7408




0821+394 2025/05/14 7.80UT FUJI -KISO














BLK: 4,SNR1: 0.12417 ,SNR2: 2.7402





BLK: 4,SNR1: 0.30042 ,SNR2: 0.59722







BLK: 5, SNR1: 0.12927 , SNR2: 0.93093



BLK: 5, SNR1: 11.825 , SNR2: 25.704





3C216 2025/05/14 8.54UT TOYOKAWA-FUJI






T20250514173040





BLK: 8, SNR1: 0.31830 , SNR2: 0.72277




Frequency (Hz)

K20250514173037





BLK: 8, SNR1: 3.4248 , SNR2: 8.8630





Frequency (Hz)

3C216 2025/05/14 8.54UT TOYOKAWA-KISO







BLK: 4,SNR1: 3.3104 ,SNR2: 8.6944







BLK: 4,SNR1: 2.8414 ,SNR2: 5.5220





3C216 2025/05/14 8.54UT FUJI -KISO









BLK: 3, SNR1: 0.16419 , SNR2: 0.80700




BLK: 3, SNR1: 0.24675 , SNR2: 3.5221





0923+392 2025/05/14 8.83UT TOYOKAWA-KISO






BLK: 3,SNR1:-0.99885E-01,SNR2: 0.46261



BLK: 3,SNR1: 0.48734 ,SNR2: 5.8404



0923+392 2025/05/14 8.83UT FUJI -KISO

