











T20250516053547




BLK: 6, SNR1: 1.0810 , SNR2: 14.367




K20250516053544




BLK: 6, SNR1: 0.12618 , SNR2: 0.86767





2119+435 2025/05/15 20.62UT TOYOKAWA-KISO









BLK: 2,SNR1: 0.16474 ,SNR2: 2.0282





BLK: 2,SNR1: 0.80097 ,SNR2: 8.6341




2119+435 2025/05/15 20.62UT FUJI -KISO





T20250516054328




BLK:12,SNR1: 28.460 ,SNR2: 39.300




F20250516054328





BLK:12,SNR1: 2.1110 ,SNR2: 6.1175




2127+456 2025/05/15 20.75UT TOYOKAWA-FUJI




T20250516054328




BLK:12,SNR1: 18.241 ,SNR2: 58.990




K20250516054325





BLK:12,SNR1: 7.4921 ,SNR2: 19.286




2127+456 2025/05/15 20.75UT TOYOKAWA-KISO




F20250516054328




BLK: 8, SNR1: 2.7626 , SNR2: 8.0417




K20250516054325





BLK: 8, SNR1: 5.5614 , SNR2: 14.882




2127+456 2025/05/15 20.75UT FUJI -KISO








2131+379 2025/05/15 20.84UT TOYOKAWA-FUJI





T20250516054826




BLK: 4,SNR1: 0.30162E-01,SNR2: 0.71109




K20250516054823





BLK: 4,SNR1: 0.27998 ,SNR2: 1.5606






2131+379 2025/05/15 20.84UT TOYOKAWA-KISO







2131+379 2025/05/15 20.84UT FUJI -KISO







BLK: 4,SNR1: 0.65019 ,SNR2: 6.4596





BLK: 4,SNR1: 1.1970 ,SNR2: 2.5976






2142+279 2025/05/15 21.01UT TOYOKAWA-FUJI









BLK: 2,SNR1: 0.27550 ,SNR2: 3.6492




BLK: 2,SNR1: 0.21576 ,SNR2: 3.0883




2142+279 2025/05/15 21.01UT TOYOKAWA-KISO





F20250516055852




BLK: 4, SNR1: 0.87727E-01, SNR2: 0.72181




K20250516055848







BLK: 4, SNR1: 0.61354, SNR2: 1.9716





2142+279 2025/05/15 21.01UT FUJI -KISO









BLK:19,SNR1: 3.4413 ,SNR2: 10.416





BLK:19,SNR1: 2.3402 ,SNR2: 7.6119




2152+450 2025/05/15 21.17UT TOYOKAWA-KISO





F20250516060847




BLK:21,SNR1: 7.1023 ,SNR2: 12.241




K20250516060843




BLK:21,SNR1: 10.248 ,SNR2: 22.660





2152+450 2025/05/15 21.17UT FUJI -KISO







BLK:12,SNR1: 13.966 ,SNR2: 43.642








BLK:12,SNR1: 7.0632 ,SNR2: 17.855





2201+315 2025/05/15 21.32UT TOYOKAWA-FUJI








F20250516061749




BLK: 8,SNR1: 1.6426 ,SNR2: 5.0502




K20250516061745





BLK: 8,SNR1: 5.9331 ,SNR2: 17.284





2201+315 2025/05/15 21.32UT FUJI -KISO









BLK: 6,SNR1: 0.22243E-01,SNR2: 1.0776




BLK: 6,SNR1: 2.8686 ,SNR2: 8.1263





2207+374 2025/05/15 21.43UT TOYOKAWA-FUJI







BLK: 5,SNR1: 0.97466E-01,SNR2: 0.66749





BLK: 5,SNR1: 0.26120 ,SNR2: 1.1311




2207+374 2025/05/15 21.43UT TOYOKAWA-KISO





F20250516062352




BLK: 3, SNR1: 2.9360 , SNR2: 21.546




K20250516062349





BLK: 3, SNR1: 0.14884 , SNR2: 1.2839




2207+374 2025/05/15 21.43UT FUJI -KISO





T20250516063442




BLK:21,SNR1: 3.7647 ,SNR2: 11.228




F20250516063443





BLK:21,SNR1: 3.5210 ,SNR2: 10.513




2217+128 2025/05/15 21.61UT TOYOKAWA-FUJI





T20250516063442




BLK:23,SNR1: 3.7649 ,SNR2: 11.228




K20250516063439





BLK:23,SNR1: 9.2152 ,SNR2: 16.089




2217+128 2025/05/15 21.61UT TOYOKAWA-KISO



F20250516063443





BLK:31,SNR1: 3.4978 ,SNR2: 10.325




Frequency (Hz)

K20250516063439




BLK:31,SNR1: 8.5372 ,SNR2: 14.918





Frequency (Hz)


2217+128 2025/05/15 21.61UT FUJI -KISO




T20250516064029




BLK: 6,SNR1: 0.13152 ,SNR2: 0.89751




F20250516064030




BLK: 6,SNR1: 0.27699 ,SNR2: 1.6891





3C446 2025/05/15 21.70UT TOYOKAWA-FUJI







BLK:14,SNR1: 0.31600E-02,SNR2: 1.1778




BLK:14,SNR1: 5.9456 ,SNR2: 15.611





3C446 2025/05/15 21.70UT TOYOKAWA-KISO









BLK: 9,SNR1: -0.59216E-02,SNR2: 1.7764





BLK: 9,SNR1: 6.0838 ,SNR2: 15.857




3C446 2025/05/15 21.70UT FUJI -KISO




T20250516064712




BLK: 1, SNR1: 0.14714 , SNR2: 0.50502




F20250516064713





BLK: 1, SNR1: 0.60593 , SNR2: 5.2349




2229-093 2025/05/15 21.81UT TOYOKAWA-FUJI





T20250516064712




BLK: 3,SNR1:-0.77757E-02,SNR2: 0.53668




K20250516064709









BLK: 3,SNR1: 2.8517 ,SNR2: 8.0850





2229-093 2025/05/15 21.81UT TOYOKAWA-KISO









BLK: 2,SNR1: 0.69009 ,SNR2: 4.2729




BLK: 2,SNR1:-0.88178E-01,SNR2: 3.6534





2238-113 2025/05/15 21.96UT TOYOKAWA-FUJI







BLK: 4, SNR1: 18.211 , SNR2: 135.04




BLK: 4, SNR1: 0.20514 , SNR2: 0.83220





2238-113 2025/05/15 21.96UT TOYOKAWA-KISO







BLK: 5,SNR1: 0.66521 ,SNR2: 2.6687








BLK: 5,SNR1: 0.85980 ,SNR2: 2.5398




2238-113 2025/05/15 21.96UT FUJI -KISO













BLK: 7,SNR1: 0.38321 ,SNR2: 2.6602




BLK: 7,SNR1: 0.49782 ,SNR2: 2.4439




3C454.3 2025/05/15 22.17UT TOYOKAWA-KISO





F20250516070829




BLK: 7,SNR1: 0.78084 ,SNR2: 13.515




K20250516070826




BLK: 7,SNR1: 0.91312 ,SNR2: 4.7200





3C454.3 2025/05/15 22.17UT FUJI -KISO







BLK: 3,SNR1: 1.4398 ,SNR2: 4.5992




BLK: 3,SNR1: 0.13321E-01,SNR2: 2.3686





2259+481 2025/05/15 22.30UT TOYOKAWA-FUJI







BLK: 9,SNR1: 0.79839 ,SNR2: 2.6237




BLK: 9,SNR1: 0.96042 ,SNR2: 2.8103




2259+481 2025/05/15 22.30UT TOYOKAWA-KISO





F20250516071612




BLK: 6,SNR1: 2.1306 ,SNR2: 5.0430




K20250516071609




BLK: 6,SNR1: 0.23178 ,SNR2: 1.6512




2259+481 2025/05/15 22.30UT FUJI -KISO





T20250516073105




BLK: 7, SNR1: 13.189 , SNR2: 25.472




F20250516073106




BLK: 7, SNR1: 0.90101 , SNR2: 2.5519




3C459 2025/05/15 22.55UT TOYOKAWA-FUJI





T20250516073105




BLK:14,SNR1: 12.931 ,SNR2: 26.136




K20250516073102




BLK:14,SNR1: 2.6515 ,SNR2: 8.2699




3C459 2025/05/15 22.55UT TOYOKAWA-KISO





F20250516073106




BLK:17,SNR1: 10.598 ,SNR2: 16.666




K20250516073102



BLK:17,SNR1: 8.2080 ,SNR2: 21.293





3C459 2025/05/15 22.55UT FUJI -KISO






T20250516080450




BLK: 8,SNR1: 3.2390 ,SNR2: 9.8329





2347-02 2025/05/15 23.11UT TOYOKAWA-FUJI



F20250516080450




BLK: 8,SNR1: 0.22671 ,SNR2: 3.0369




T20250516080450




BLK:13,SNR1: 3.4086 ,SNR2: 10.252




K20250516080447











BLK:13,SNR1: 2.6153 ,SNR2: 8.1339





2347-02 2025/05/15 23.11UT TOYOKAWA-KISO









T20250516081143




BLK: 5, SNR1: 0.57239 , SNR2: 2.4703




K20250516081140








BLK: 5, SNR1: 0.60385 , SNR2: 2.5552





2354+14 2025/05/15 23.22UT TOYOKAWA-KISO








T20250516082046




BLK:14,SNR1: 0.53747 ,SNR2: 2.6452




F20250516082047





BLK:14,SNR1: 0.26287 ,SNR2: 2.7646




3C2 2025/05/15 23.37UT TOYOKAWA-FUJI



T20250516082046





BLK:10,SNR1: 0.48491 ,SNR2: 2.3699





3C2 2025/05/15 23.37UT TOYOKAWA-KISO

K20250516082044





BLK:10,SNR1: 0.90866 ,SNR2: 1.8737






F20250516082047





BLK: 8,SNR1: 0.47956 ,SNR2: 2.2137





3C2 2025/05/15 23.37UT FUJI -KISO



K20250516082044




BLK: 8,SNR1: 2.4591 ,SNR2: 7.2304





T20250516082808




BLK: 6,SNR1:-0.63973E-01,SNR2: 1.6916




F20250516082808





BLK: 6,SNR1: 1.8854 ,SNR2: 6.9922




0011+344 2025/05/15 23.50UT TOYOKAWA-FUJI




T20250516082808




BLK: 4, SNR1: 0.14221 , SNR2: 1.6968




K20250516082806




BLK: 4, SNR1: 0.75423 , SNR2: 2.8279




0011+344 2025/05/15 23.50UT TOYOKAWA-KISO





F20250516082808




BLK: 7, SNR1: 1.3403 , SNR2: 4.9941




K20250516082806




BLK: 7, SNR1: 0.34762 , SNR2: 1.7749




0011+344 2025/05/15 23.50UT FUJI -KISO



T20250516083644





BLK:10,SNR1: 0.22712 ,SNR2: 2.4430




Frequency (Hz)

F20250516083645




BLK:10,SNR1: 1.4591 ,SNR2: 9.7930





Frequency (Hz)


0019-00 2025/05/15 23.64UT TOYOKAWA-FUJI




T20250516083644




BLK:15,SNR1: 0.21966 ,SNR2: 1.3488




K20250516083642




BLK:15,SNR1: 0.34741 ,SNR2: 1.5623




0019-00 2025/05/15 23.64UT TOYOKAWA-KISO




F20250516083645




BLK: 6,SNR1: 0.33252 ,SNR2: 3.3503




K20250516083642





BLK: 6,SNR1: 0.24919 ,SNR2: 3.6078




0019-00 2025/05/15 23.64UT FUJI -KISO





T20250516084659




BLK: 6,SNR1: 0.11345 ,SNR2: 0.79962




F20250516084659



BLK: 6,SNR1: 0.63870 ,SNR2: 2.3178




3C12 2025/05/15 23.81UT TOYOKAWA-FUJI







T20250516084659




BLK: 8, SNR1: 0.18692 , SNR2: 1.5077




K20250516084656




BLK: 8, SNR1: 1.1071 , SNR2: 5.3017




3C12 2025/05/15 23.81UT TOYOKAWA-KISO




F20250516084659




BLK: 5, SNR1: 1.0389 , SNR2: 3.8367




K20250516084656





BLK: 5, SNR1: 1.0314 , SNR2: 3.8696




3C12 2025/05/15 23.81UT FUJI -KISO




T20250516085410




BLK: 5,SNR1: 0.18375 ,SNR2: 0.56677




F20250516085410







BLK: 5,SNR1: 0.37469 ,SNR2: 2.2233





0037+046 2025/05/15 23.93UT TOYOKAWA-FUJI









BLK: 5, SNR1: 0.56374 , SNR2: 3.0309




BLK: 5, SNR1: 0.55666 , SNR2: 2.4163




0037+046 2025/05/15 23.93UT FUJI -KISO




T20250516090100




BLK:18,SNR1: 2.9809 ,SNR2: 9.2821




F20250516090101




BLK:18,SNR1: 8.2400 ,SNR2: 14.444




0044-056 2025/05/16 0.04UT TOYOKAWA-FUJI





T20250516090100




BLK:27,SNR1: 3.0460 ,SNR2: 9.4471




K20250516090058





BLK:27,SNR1: 2.6986 ,SNR2: 8.3588




0044-056 2025/05/16 0.04UT TOYOKAWA-KISO










0044-056 2025/05/16 0.04UT FUJI -KISO















3C26 2025/05/16 0.17UT TOYOKAWA-FUJI

















3C26 2025/05/16 0.17UT FUJI -KISO







0056-00 2025/05/16 0.25UT TOYOKAWA-FUJI








F20250516091320




BLK: 4,SNR1: 0.84457E-01,SNR2: 0.98270




K20250516091318




BLK: 4,SNR1: 0.26766 ,SNR2: 0.64140




0056-00 2025/05/16 0.25UT FUJI -KISO



T20250516092302





BLK: 4,SNR1: 0.21889 ,SNR2: 2.0963







0106+01 2025/05/16 0.41UT TOYOKAWA-FUJI

F20250516092302




BLK: 4,SNR1: 0.49857E-01,SNR2: 2.0695






0106+01 2025/05/16 0.41UT TOYOKAWA-KISO








F20250516092302




BLK: 6,SNR1: 0.89382E-01,SNR2: 1.8069




K20250516092259





BLK: 6,SNR1: 0.21066 ,SNR2: 4.0686




0106+01 2025/05/16 0.41UT FUJI -KISO





T20250516093352




BLK: 7,SNR1: 0.47033 ,SNR2: 1.8658




F20250516093352









BLK: 7,SNR1: 0.16183 ,SNR2: 1.5207





0116+31 2025/05/16 0.59UT TOYOKAWA-FUJI









BLK: 8,SNR1: 0.48563 ,SNR2: 2.6606




BLK: 8,SNR1: 0.56073 ,SNR2: 3.5063





0116+31 2025/05/16 0.59UT FUJI -KISO







BLK:13,SNR1: 16.824 ,SNR2: 31.889













BLK:13,SNR1: 82.787 ,SNR2: 81.983




0128+03 2025/05/16 0.79UT TOYOKAWA-FUJI









T20250516095159




BLK:22,SNR1: 19.388 ,SNR2: 65.648




F20250516095159



BLK:22,SNR1: 3.0056 ,SNR2: 9.0121




3C48 2025/05/16 0.89UT TOYOKAWA-FUJI








T20250516095159




BLK:26,SNR1: 20.870 ,SNR2: 44.574




K20250516095157





BLK:26,SNR1: 4.7715 ,SNR2: 9.1663




3C48 2025/05/16 0.89UT TOYOKAWA-KISO



F20250516095159





BLK:16,SNR1: 4.0167 ,SNR2: 11.897










3C48 2025/05/16 0.89UT FUJI -KISO

K20250516095157





BLK:16,SNR1: 4.1303 ,SNR2: 7.8732







T20250516101143




BLK:12,SNR1: 1.3438 ,SNR2: 3.7467




K20250516101140




BLK:12,SNR1: 3.5773 ,SNR2: 10.870





0155-109 2025/05/16 1.22UT TOYOKAWA-KISO







BLK: 8,SNR1: 1.4696 ,SNR2: 4.9534




BLK: 8,SNR1: 11.639 ,SNR2: 22.329




0155-109 2025/05/16 1.22UT FUJI -KISO





T20250516101851




BLK:16,SNR1: 2.1584 ,SNR2: 13.329




F20250516101852




BLK:16,SNR1:-0.89980E-01,SNR2: 1.2157




0202+15 2025/05/16 1.34UT TOYOKAWA-FUJI




T20250516101851




BLK:21,SNR1: 1.3028 ,SNR2: 11.815




K20250516101848




BLK:21,SNR1: 0.22523 ,SNR2: 2.0238




0202+15 2025/05/16 1.34UT TOYOKAWA-KISO




F20250516101852




BLK:17,SNR1: 0.14179 ,SNR2: 1.9331




K20250516101848



BLK:17,SNR1: 0.54178 ,SNR2: 2.6603





0202+15 2025/05/16 1.34UT FUJI -KISO







T20250516103041




BLK: 4,SNR1: 0.63819E-01,SNR2: 0.72751




F20250516103041





BLK: 4,SNR1: 0.60838 ,SNR2: 6.9314




0213+178 2025/05/16 1.54UT TOYOKAWA-FUJI





T20250516103041




BLK: 4,SNR1:-0.21638E-01,SNR2: 0.52775




K20250516103038





BLK: 4,SNR1: 2.3877 ,SNR2: 11.033




0213+178 2025/05/16 1.54UT TOYOKAWA-KISO





F20250516103041




BLK: 2,SNR1: 13.803 ,SNR2: 49.260




K20250516103038









BLK: 2,SNR1: 3.1539 ,SNR2: 14.625





0213+178 2025/05/16 1.54UT FUJI -KISO









BLK:25,SNR1: 3.5181 ,SNR2: 7.6753





BLK:25,SNR1: 0.89199 ,SNR2: 2.7901




3C67 2025/05/16 1.67UT TOYOKAWA-KISO



F20250516103824





BLK:22,SNR1: 0.50662 ,SNR2: 3.4449




Frequency (Hz)

3C67 2025/05/16 1.67UT FUJI -KISO


K20250516103820





BLK:22,SNR1: 0.79810 ,SNR2: 2.6866




Frequency (Hz)





T20250516105638




BLK: 8, SNR1: 12.012 , SNR2: 34.692




F20250516105639





BLK: 8, SNR1: 2.4286 , SNR2: 6.9058




3C71 2025/05/16 1.97UT TOYOKAWA-FUJI



T20250516105638





BLK: 5, SNR1: 7.3373 , SNR2: 21.310





3C71 2025/05/16 1.97UT TOYOKAWA-KISO


K20250516105635





BLK: 5, SNR1: 15.805 , SNR2: 37.981









BLK: 5,SNR1: 0.86165 ,SNR2: 4.0041




BLK: 5,SNR1: 16.139 ,SNR2: 38.407





3C71 2025/05/16 1.97UT FUJI -KISO







BLK: 9,SNR1: 0.24513 ,SNR2: 1.0891




BLK: 9,SNR1: 11.804 ,SNR2: 44.209





0258+350 2025/05/16 2.29UT TOYOKAWA-FUJI







BLK:10,SNR1: 2.0582 ,SNR2: 7.0290





BLK:10,SNR1: 0.79043 ,SNR2: 2.6312




0258+350 2025/05/16 2.29UT TOYOKAWA-KISO





F20250516111554




BLK: 9,SNR1: 11.599 ,SNR2: 43.964




K20250516111550




BLK: 9,SNR1: 0.40325 ,SNR2: 1.4296




0258+350 2025/05/16 2.29UT FUJI -KISO




T20250516112543




BLK:11,SNR1: 0.78140 ,SNR2: 2.4854




F20250516112543




BLK:11,SNR1: 5.8152 ,SNR2: 20.650




0308+305 2025/05/16 2.46UT TOYOKAWA-FUJI




T20250516112543




BLK:20,SNR1: 1.1704 ,SNR2: 7.7552




K20250516112540




BLK:20,SNR1: 0.36167 ,SNR2: 2.9895




0308+305 2025/05/16 2.46UT TOYOKAWA-KISO




F20250516112543




BLK: 9,SNR1: 5.9527 ,SNR2: 21.409




K20250516112540




BLK: 9,SNR1: 0.59966 ,SNR2: 2.4691





0308+305 2025/05/16 2.46UT FUJI -KISO







BLK:16,SNR1: 4.9380 ,SNR2: 13.774




BLK:16,SNR1: 0.70412 ,SNR2: 3.5782





0320+05 2025/05/16 2.65UT TOYOKAWA-FUJI









BLK:29,SNR1: 4.8557 ,SNR2: 13.725




BLK:29,SNR1: 1.5534 ,SNR2: 4.8013





0320+05 2025/05/16 2.65UT TOYOKAWA-KISO







BLK:23,SNR1: 0.75362 ,SNR2: 3.8696




BLK:23,SNR1: 7.2824 ,SNR2: 19.132





0320+05 2025/05/16 2.65UT FUJI -KISO







BLK: 9,SNR1: 0.40841 ,SNR2: 3.7984




BLK: 9,SNR1: -0.12921 ,SNR2: 1.3908





0333+32 2025/05/16 2.87UT TOYOKAWA-FUJI







BLK:10,SNR1: 0.76148 ,SNR2: 2.2436




BLK:10,SNR1: 0.82539 ,SNR2: 3.2150





0333+32 2025/05/16 2.87UT TOYOKAWA-KISO







BLK: 9,SNR1: 0.65329 ,SNR2: 1.9893





BLK: 9,SNR1: 0.63467 ,SNR2: 3.2256





0333+32 2025/05/16 2.87UT FUJI -KISO




T20250516120337




F20250516120337




0347+05 2025/05/16 3.09UT TOYOKAWA-FUJI





T20250516120337




BLK:10,SNR1: 1.7310 ,SNR2: 4.8360




K20250516120334




BLK:10,SNR1: 6.7674 ,SNR2: 12.226




0347+05 2025/05/16 3.09UT TOYOKAWA-KISO





F20250516120337




BLK: 8,SNR1: 0.28901 ,SNR2: 2.4118




K20250516120334



BLK: 8,SNR1: 9.1469 ,SNR2: 21.356




0347+05 2025/05/16 3.09UT FUJI -KISO







T20250516121911




BLK: 3,SNR1: 1.8996 ,SNR2: 5.8163




F20250516121912




BLK: 3,SNR1: -0.25534 ,SNR2: 0.0000




0403-132 2025/05/16 3.35UT TOYOKAWA-FUJI




T20250516121911




BLK:14,SNR1: 7.7028 ,SNR2: 20.185




K20250516121908




BLK:14,SNR1: 10.113 ,SNR2: 29.206




0403-132 2025/05/16 3.35UT TOYOKAWA-KISO




F20250516121912




BLK: 2,SNR1: 0.30457 ,SNR2: 1.9781




K20250516121908





BLK: 2,SNR1: 3.6618 ,SNR2: 10.635




0403-132 2025/05/16 3.35UT FUJI -KISO





T20250516122822




BLK: 4,SNR1: 6.7073 ,SNR2: 18.239




F20250516122822





BLK: 4,SNR1: 6.4012 ,SNR2: 14.156




0411+05 2025/05/16 3.50UT TOYOKAWA-FUJI




T20250516122822




BLK:11,SNR1: 8.0542 ,SNR2: 19.851




K20250516122819





BLK:11,SNR1: 7.9074 ,SNR2: 20.480





0411+05 2025/05/16 3.50UT TOYOKAWA-KISO




F20250516122822





K20250516122819




0411+05 2025/05/16 3.50UT FUJI -KISO





T20250516123915




BLK: 7,SNR1: 10.793 ,SNR2: 25.233




F20250516123916





BLK: 7,SNR1: 17.139 ,SNR2: 37.179




0422+178 2025/05/16 3.68UT TOYOKAWA-FUJI




T20250516123915




BLK: 8,SNR1: 6.9845 ,SNR2: 18.321




K20250516123912



BLK: 8,SNR1: 13.598 ,SNR2: 30.274




0422+178 2025/05/16 3.68UT TOYOKAWA-KISO







F20250516123916




BLK: 6,SNR1: 9.6129 ,SNR2: 23.164




K20250516123912







BLK: 6,SNR1: 11.328 ,SNR2: 25.213





0422+178 2025/05/16 3.68UT FUJI -KISO









BLK:30,SNR1: 0.63966 ,SNR2: 3.1984




BLK:30,SNR1: 0.81476 ,SNR2: 2.3092




3C119 2025/05/16 3.81UT TOYOKAWA-KISO



F20250516124645




BLK:21,SNR1: 0.72285 ,SNR2: 13.902






3C119 2025/05/16 3.81UT FUJI -KISO

K20250516124641





BLK:21,SNR1: 0.92486 ,SNR2: 2.6336







BLK:25,SNR1: 12.048 ,SNR2: 21.389




BLK:25,SNR1: 2.8779 ,SNR2: 13.656





3C138 2025/05/16 4.61UT TOYOKAWA-FUJI







BLK:30,SNR1: 2.8592 ,SNR2: 13.606




BLK:30,SNR1: 7.1892 ,SNR2: 20.203




3C138 2025/05/16 4.61UT TOYOKAWA-KISO





F20250516133451




BLK:29,SNR1: 2.8647 ,SNR2: 13.599




K20250516133449





BLK:29,SNR1: 7.0577 ,SNR2: 20.112




3C138 2025/05/16 4.61UT FUJI -KISO




T20250516134824




BLK:11,SNR1: 10.487 ,SNR2: 25.929




F20250516134825




BLK:11,SNR1: 9.5384 ,SNR2: 23.831





0531+194 2025/05/16 4.83UT TOYOKAWA-FUJI









BLK:11,SNR1: 11.258 ,SNR2: 28.066




BLK:11,SNR1: 10.995 ,SNR2: 27.024





0531+194 2025/05/16 4.83UT TOYOKAWA-KISO







BLK:12,SNR1: 9.2871 ,SNR2: 22.145




BLK:12,SNR1: 9.2932 ,SNR2: 22.840




0531+194 2025/05/16 4.83UT FUJI -KISO



T20250516135645




BLK:32,SNR1: 15.814 ,SNR2: 86.708




Frequency (Hz)

F20250516135645








BLK:32,SNR1:-0.99585E-01,SNR2: 2.3203




Frequency (Hz)


3C147 2025/05/16 4.97UT TOYOKAWA-FUJI







3C147 2025/05/16 4.97UT TOYOKAWA-KISO







BLK:27,SNR1:-0.97400E-01,SNR2: 2.3919





BLK:27,SNR1: 1.5953 ,SNR2: 11.315




3C147 2025/05/16 4.97UT FUJI -KISO





T20250516140455




BLK: 7,SNR1: 0.23167 ,SNR2: 0.93676




F20250516140455




BLK: 7,SNR1: 1.3744 ,SNR2: 7.7023





0548+16 2025/05/16 5.11UT TOYOKAWA-FUJI







BLK:10,SNR1: 0.22932 ,SNR2: 2.7193




BLK:10,SNR1: 0.28442 ,SNR2: 1.7384





0548+16 2025/05/16 5.11UT TOYOKAWA-KISO








BLK: 7,SNR1: 1.2743 ,SNR2: 6.4842





BLK: 7,SNR1: 0.17443E-01,SNR2: 0.91660









BLK:10,SNR1: 14.839 ,SNR2: 36.320








BLK:10,SNR1: 5.3012 ,SNR2: 15.773





0552+12 2025/05/16 5.18UT TOYOKAWA-FUJI







F20250516140907




BLK: 6,SNR1: 6.9737 ,SNR2: 20.070




K20250516140903





BLK: 6,SNR1: 7.6982 ,SNR2: 19.590




0552+12 2025/05/16 5.18UT FUJI -KISO




T20250516141333




BLK: 5,SNR1: 0.78915 ,SNR2: 2.2460




F20250516141333




BLK: 5,SNR1: 6.4785 ,SNR2: 15.760





0556+191 2025/05/16 5.25UT TOYOKAWA-FUJI







BLK: 6,SNR1: 0.32227 ,SNR2: 0.78597




BLK: 6,SNR1: 0.64607 ,SNR2: 3.2848





0556+191 2025/05/16 5.25UT TOYOKAWA-KISO







BLK: 4,SNR1: 0.16577 ,SNR2: 1.7888




BLK: 4,SNR1: 0.85635 ,SNR2: 3.4226





0556+191 2025/05/16 5.25UT FUJI -KISO







BLK: 9,SNR1: 5.0407 ,SNR2: 11.199




BLK: 9,SNR1: 10.069 ,SNR2: 22.428





0605-08 2025/05/16 5.38UT TOYOKAWA-FUJI







BLK: 6,SNR1: 9.1912 ,SNR2: 22.790




BLK: 6,SNR1: 10.037 ,SNR2: 25.908





0605-08 2025/05/16 5.38UT TOYOKAWA-KISO









BLK: 6,SNR1: 3.3986 ,SNR2: 9.5753




BLK: 6,SNR1: 15.446 ,SNR2: 34.370





0605-08 2025/05/16 5.38UT FUJI -KISO







BLK: 7,SNR1: 1.1853 ,SNR2: 9.1557




BLK: 7,SNR1:-0.24879 ,SNR2: 0.0000





3C161 2025/05/16 5.70UT TOYOKAWA-FUJI







BLK:18,SNR1: 0.83161 ,SNR2: 3.2572









BLK:18,SNR1: 0.47581 ,SNR2: 2.2071





3C161 2025/05/16 5.70UT TOYOKAWA-KISO









BLK: 7,SNR1: 0.54116 ,SNR2: 3.2225




BLK: 7,SNR1:-0.14552 ,SNR2: 1.1815





0652-130 2025/05/16 6.16UT TOYOKAWA-FUJI







BLK:10,SNR1: 0.53189 ,SNR2: 4.8965




BLK:10,SNR1: 7.4680 ,SNR2: 19.704





0652-130 2025/05/16 6.16UT TOYOKAWA-KISO







BLK: 7, SNR1: -0.11878 , SNR2: 1.3598





BLK: 7, SNR1: 8.3447 , SNR2: 21.429




0652-130 2025/05/16 6.16UT FUJI -KISO



T20250516151936





BLK: 4,SNR1: 0.90282E-02,SNR2: 0.48750




Frequency (Hz)

F20250516151936




BLK: 4,SNR1:-0.18042 ,SNR2: 2.5511




Frequency (Hz)



0703+138 2025/05/16 6.35UT TOYOKAWA-FUJI









BLK:13,SNR1: 0.12308 ,SNR2: 1.1759









BLK:13,SNR1: 2.3655 ,SNR2: 10.749





0703+138 2025/05/16 6.35UT TOYOKAWA-KISO









BLK: 5,SNR1: 1.0051 ,SNR2: 5.4021





BLK: 5,SNR1: 1.1127 ,SNR2: 6.3768





0713-024 2025/05/16 6.51UT TOYOKAWA-FUJI




T20250516152858




K20250516152855





0713-024 2025/05/16 6.51UT TOYOKAWA-KISO







BLK: 6,SNR1:-0.79588E-01,SNR2: 2.2322





BLK: 6,SNR1: 5.1557 ,SNR2: 13.555




0713-024 2025/05/16 6.51UT FUJI -KISO



T20250516153910





BLK: 6,SNR1:-0.24985E-01,SNR2: 0.24324




Frequency (Hz)

F20250516153910









BLK: 6,SNR1: 13.131 ,SNR2: 23.292





Frequency (Hz)

0723+10 2025/05/16 6.68UT TOYOKAWA-FUJI






F20250516153910





BLK: 5, SNR1: 4.1790 , SNR2: 12.986




Frequency (Hz)

K20250516153908




BLK: 5, SNR1: 0.24453 , SNR2: 2.6585












Frequency (Hz)

0723+10 2025/05/16 6.68UT FUJI -KISO












0732+33 2025/05/16 6.85UT TOYOKAWA-KISO



F20250516154926




BLK: 5,SNR1: 0.78589E-01,SNR2: 1.9401




Frequency (Hz)

K20250516154923








BLK: 5,SNR1: 1.2179 ,SNR2: 4.7116




Frequency (Hz)


0732+33 2025/05/16 6.85UT FUJI -KISO







0741-06 2025/05/16 6.99UT TOYOKAWA-FUJI







BLK: 8,SNR1: 0.33056 ,SNR2: 2.4047




BLK: 8,SNR1: 0.21275 ,SNR2: 1.3567





0741-06 2025/05/16 6.99UT TOYOKAWA-KISO







BLK: 9,SNR1: 0.66450E-03,SNR2: 2.5399




BLK: 9,SNR1: 0.17632 ,SNR2: 2.4252





0741-06 2025/05/16 6.99UT FUJI -KISO







BLK: 7,SNR1: 0.98414 ,SNR2: 8.4071







BLK: 7,SNR1: 0.14010 ,SNR2: 1.4019




0752-200 2025/05/16 7.15UT TOYOKAWA-FUJI






0752-200 2025/05/16 7.15UT TOYOKAWA-KISO








F20250516160712




BLK: 7,SNR1: 0.13384 ,SNR2: 2.0255




K20250516160709




BLK: 7,SNR1: 0.51588 ,SNR2: 1.8395





0752-200 2025/05/16 7.15UT FUJI -KISO







BLK: 3,SNR1: 0.20641E-01,SNR2: 1.4137







BLK: 3,SNR1: 0.80085 ,SNR2: 2.7262









3C190 2025/05/16 7.27UT TOYOKAWA-FUJI








3C190 2025/05/16 7.27UT TOYOKAWA-KISO









BLK:17,SNR1: 1.6750 ,SNR2: 6.5504





BLK:17,SNR1: 1.4955 ,SNR2: 4.2623




3C196 2025/05/16 7.48UT TOYOKAWA-FUJI



T20250516162711





BLK:12,SNR1: 1.1395 ,SNR2: 3.6539




Frequency (Hz)

K20250516162708





BLK:12,SNR1: 0.34156 ,SNR2: 1.3502





Frequency (Hz)

3C196 2025/05/16 7.48UT TOYOKAWA-KISO












BLK: 5,SNR1:-0.14738E-01,SNR2: 1.8200




BLK: 5,SNR1: 0.44319 ,SNR2: 3.0743













BLK:10,SNR1: 0.37060 ,SNR2: 1.3538







BLK:10,SNR1: 1.5000 ,SNR2: 2.5346




0821+394 2025/05/16 7.67UT TOYOKAWA-KISO








0821+394 2025/05/16 7.67UT FUJI -KISO



T20250516170607





BLK: 6,SNR1: 0.35073E-01,SNR2: 1.3177




Frequency (Hz)

F20250516170608




BLK: 6,SNR1: 0.80167 ,SNR2: 8.2911





Frequency (Hz)


3C208 2025/05/16 8.13UT TOYOKAWA-FUJI



T20250516170607




BLK:10,SNR1: 0.31051E-01,SNR2: 0.90660




Frequency (Hz)

K20250516170605




BLK:10,SNR1: 7.9728 ,SNR2: 14.234




Frequency (Hz)


3C208 2025/05/16 8.13UT TOYOKAWA-KISO



F20250516170608





BLK: 9,SNR1:-0.20433 ,SNR2: 0.61317




Frequency (Hz)

3C208 2025/05/16 8.13UT FUJI -KISO


K20250516170605




BLK: 9,SNR1: 1.0341 ,SNR2: 3.6151





Frequency (Hz)







BLK: 6,SNR1: 0.22013 ,SNR2: 2.1008




BLK: 6,SNR1: 0.90972 ,SNR2: 3.8349





3C216 2025/05/16 8.41UT TOYOKAWA-FUJI







BLK: 5, SNR1: 0.17799 , SNR2: 3.6163




BLK: 5, SNR1: 0.30108 , SNR2: 5.1276





3C216 2025/05/16 8.41UT TOYOKAWA-KISO











BLK: 5,SNR1: 0.37777 ,SNR2: 3.8510




BLK: 5,SNR1: 0.63994 ,SNR2: 3.9840

















0923+392 2025/05/16 8.70UT TOYOKAWA-FUJI














0923+392 2025/05/16 8.70UT TOYOKAWA-KISO














BLK: 1,SNR1: 0.53174E-01,SNR2: 1.6791



BLK: 1,SNR1: 1.1640 ,SNR2: 6.3078



0931+399 2025/05/16 8.83UT FUJI -KISO

