








BLK: 6, SNR1: 4.1641 , SNR2: 28.081






BLK: 6, SNR1: 0.28147 , SNR2: 1.0090




2119+435 2025/05/16 20.56UT TOYOKAWA-FUJI














BLK:13,SNR1: 0.63973E-01,SNR2: 0.91480




BLK:13,SNR1: 0.38271 ,SNR2: 2.5964





2119+435 2025/05/16 20.56UT FUJI -KISO







BLK:14,SNR1: 6.0217 ,SNR2: 17.352




BLK:14,SNR1: 0.63377 ,SNR2: 2.0154





2127+456 2025/05/16 20.69UT TOYOKAWA-FUJI







BLK:22,SNR1: 4.2559 ,SNR2: 12.495





BLK:22,SNR1: 1.5746 ,SNR2: 4.7757




2127+456 2025/05/16 20.69UT TOYOKAWA-KISO





F20250517053933




BLK:13,SNR1: 0.90228 ,SNR2: 1.9880




K20250517053929





BLK:13,SNR1: 1.7534 ,SNR2: 5.3042




2127+456 2025/05/16 20.69UT FUJI -KISO





T20250517054430




BLK: 9, SNR1: 2.4955 , SNR2: 6.9636




F20250517054430




BLK: 9, SNR1: 2.8010 , SNR2: 8.4506





2131+379 2025/05/16 20.77UT TOYOKAWA-FUJI







BLK:13,SNR1: 4.8194 ,SNR2: 26.755




BLK:13,SNR1: 6.6090 ,SNR2: 17.123





2131+379 2025/05/16 20.77UT TOYOKAWA-KISO







BLK:15,SNR1: 1.0213 ,SNR2: 3.3196





BLK:15,SNR1: 7.9854 ,SNR2: 20.700





2131+379 2025/05/16 20.77UT FUJI -KISO







BLK: 2,SNR1: 0.69531E-01,SNR2: 0.52710




BLK: 2,SNR1: 2.1243 ,SNR2: 5.2877





2142+279 2025/05/16 20.94UT TOYOKAWA-FUJI









BLK: 6,SNR1: 0.16014 ,SNR2: 1.2270









BLK: 6,SNR1: 1.3588 ,SNR2: 2.7567




2142+279 2025/05/16 20.94UT TOYOKAWA-KISO













BLK: 7,SNR1: 35.850 ,SNR2: 291.53




BLK: 7,SNR1: 0.92454E-01,SNR2: 0.89078





2152+450 2025/05/16 21.11UT TOYOKAWA-KISO







BLK: 2,SNR1: 0.68880E-01,SNR2: 1.8338





BLK: 2,SNR1: 0.47069 ,SNR2: 4.4918




2152+450 2025/05/16 21.11UT FUJI -KISO





T20250517061217




BLK: 6, SNR1: 0.48242 , SNR2: 1.4336




F20250517061217





BLK: 6, SNR1: 1.9472 , SNR2: 4.9020




2159+408 2025/05/16 21.23UT TOYOKAWA-FUJI





T20250517061217




BLK: 8,SNR1: 0.40741 ,SNR2: 1.8123




K20250517061214





BLK: 8,SNR1: 6.4748 ,SNR2: 11.324




2159+408 2025/05/16 21.23UT TOYOKAWA-KISO





F20250517061217




BLK:14,SNR1: 0.85787 ,SNR2: 2.8461




K20250517061214






BLK:14,SNR1: 5.5703 ,SNR2: 12.897







2159+408 2025/05/16 21.23UT FUJI -KISO


















2207+374 2025/05/16 21.36UT TOYOKAWA-KISO










2217+128 2025/05/16 21.54UT TOYOKAWA-FUJI




T20250517063046




BLK: 3, SNR1: 0.11324 , SNR2: 0.55108




K20250517063044











BLK: 3, SNR1: 3.0708 , SNR2: 9.4653




2217+128 2025/05/16 21.54UT TOYOKAWA-KISO













BLK: 4, SNR1: 9.9209 , SNR2: 95.650



BLK: 4, SNR1: 0.31662 , SNR2: 1.6243





2238-113 2025/05/16 21.89UT TOYOKAWA-KISO








F20250517065145




BLK: 3, SNR1: 0.40310 , SNR2: 2.5535




K20250517065142




BLK: 3, SNR1: 0.67789 , SNR2: 2.7108





2238-113 2025/05/16 21.89UT FUJI -KISO







BLK:10,SNR1: 2.1153 ,SNR2: 4.5379




BLK:10,SNR1: 1.3558 ,SNR2: 4.5615





3C454.3 2025/05/16 22.10UT TOYOKAWA-FUJI







BLK:13,SNR1: 1.6778 ,SNR2: 4.8856




BLK:13,SNR1: 6.2016 ,SNR2: 16.033





3C454.3 2025/05/16 22.10UT TOYOKAWA-KISO







BLK:12,SNR1: 1.6476 ,SNR2: 5.2547









BLK:12,SNR1: 6.3615 ,SNR2: 16.426





3C454.3 2025/05/16 22.10UT FUJI -KISO









BLK:18,SNR1: 0.55537 ,SNR2: 2.4639






BLK:18,SNR1: 6.1149 ,SNR2: 15.696




2259+481 2025/05/16 22.23UT TOYOKAWA-KISO








T20250517072709




BLK: 9,SNR1: 18.782 ,SNR2: 44.848




F20250517072709



BLK: 9,SNR1: 0.41088E-01,SNR2: 1.2182




3C459 2025/05/16 22.48UT TOYOKAWA-FUJI







T20250517072709




BLK: 7, SNR1: 17.234 , SNR2: 68.858




K20250517072707





BLK: 7, SNR1: 0.23185 , SNR2: 1.0894




3C459 2025/05/16 22.48UT TOYOKAWA-KISO




F20250517072709




BLK: 3,SNR1: 0.89007 ,SNR2: 1.7783




K20250517072707




BLK: 3,SNR1: 0.81123 ,SNR2: 3.9828





3C459 2025/05/16 22.48UT FUJI -KISO







BLK: 7, SNR1: 32.037 , SNR2: 103.21




BLK: 7, SNR1: 0.45834 , SNR2: 3.2958





2347-02 2025/05/16 23.04UT TOYOKAWA-FUJI







BLK:10,SNR1: 19.983 ,SNR2: 79.848




BLK:10,SNR1: 1.3636 ,SNR2: 2.7743




2347-02 2025/05/16 23.04UT TOYOKAWA-KISO





F20250517080055




BLK:13,SNR1: 0.20771E-01,SNR2: 1.0736




K20250517080051




BLK:13,SNR1: 0.67770 ,SNR2: 2.2675





2347-02 2025/05/16 23.04UT FUJI -KISO







BLK:10,SNR1: 3.1347 ,SNR2: 9.4437




BLK:10,SNR1: 0.86896 ,SNR2: 2.5912





2354+14 2025/05/16 23.16UT TOYOKAWA-FUJI







BLK:13,SNR1: 3.0346 ,SNR2: 9.1602





BLK:13,SNR1: 2.4844 ,SNR2: 7.8383




2354+14 2025/05/16 23.16UT TOYOKAWA-KISO





F20250517080747




BLK: 7,SNR1: 1.1492 ,SNR2: 2.8497




K20250517080745








BLK: 7,SNR1: 2.4911 ,SNR2: 7.8562







2354+14 2025/05/16 23.16UT FUJI -KISO












3C2 2025/05/16 23.31UT TOYOKAWA-KISO




F20250517081651




BLK: 6, SNR1: 0.42952 , SNR2: 1.5338




K20250517081648





BLK: 6, SNR1: 0.16776 , SNR2: 0.62171




3C2 2025/05/16 23.31UT FUJI -KISO





T20250517082412




BLK: 4, SNR1: 0.24030 , SNR2: 2.2789




F20250517082413





BLK: 4, SNR1: 5.9083 , SNR2: 13.090




0011+344 2025/05/16 23.43UT TOYOKAWA-FUJI





T20250517082412




BLK: 4, SNR1: 0.10659 , SNR2: 1.7808




K20250517082409





BLK: 4, SNR1: 0.21728 , SNR2: 1.3443




0011+344 2025/05/16 23.43UT TOYOKAWA-KISO





F20250517082413




BLK:12,SNR1: 0.95802 ,SNR2: 5.4809




K20250517082409




BLK:12,SNR1: 2.8305 ,SNR2: 5.6167





0011+344 2025/05/16 23.43UT FUJI -KISO







BLK:19,SNR1: 10.135 ,SNR2: 17.856




BLK:19,SNR1: 2.4645 ,SNR2: 7.5057





0019-00 2025/05/16 23.57UT TOYOKAWA-FUJI







BLK:26,SNR1: 9.8735 ,SNR2: 17.390







BLK:26,SNR1: 2.5668 ,SNR2: 8.0443




0019-00 2025/05/16 23.57UT TOYOKAWA-KISO










0019-00 2025/05/16 23.57UT FUJI -KISO





T20250517084303




BLK: 4, SNR1: 0.51747 , SNR2: 1.8041




F20250517084303





BLK: 4, SNR1: 1.1049 , SNR2: 5.1358




3C12 2025/05/16 23.75UT TOYOKAWA-FUJI




T20250517084303




BLK: 6, SNR1: 0.37867 , SNR2: 1.3743




K20250517084300




BLK: 6, SNR1: 0.44143 , SNR2: 3.5274




3C12 2025/05/16 23.75UT TOYOKAWA-KISO




F20250517084303




BLK: 7, SNR1: 1.7578 , SNR2: 8.7732




K20250517084300





BLK: 7, SNR1: 0.35727 , SNR2: 1.0466




3C12 2025/05/16 23.75UT FUJI -KISO



T20250517085121





BLK:12,SNR1: 0.28372 ,SNR2: 2.2231





0038+328 2025/05/16 23.88UT TOYOKAWA-FUJI



F20250517085121




BLK:12,SNR1: 0.86140 ,SNR2: 2.7449





T20250517085121




BLK:16,SNR1: 0.41369 ,SNR2: 2.0501




K20250517085119




BLK:16,SNR1: 10.292 ,SNR2: 18.950




0038+328 2025/05/16 23.88UT TOYOKAWA-KISO





F20250517085121




BLK:12,SNR1: 0.65914 ,SNR2: 2.8879




K20250517085119







BLK:12,SNR1: 10.875 ,SNR2: 20.021




0038+328 2025/05/16 23.88UT FUJI -KISO










3C26 2025/05/17 0.10UT TOYOKAWA-FUJI










3C26 2025/05/17 0.10UT TOYOKAWA-KISO




F20250517090427




BLK:12,SNR1: 0.25322 ,SNR2: 1.5991




K20250517090423




BLK:12,SNR1: 0.42721 ,SNR2: 1.4100




3C26 2025/05/17 0.10UT FUJI -KISO




T20250517090924




BLK:11,SNR1: 0.55049 ,SNR2: 2.1174




F20250517090925




BLK:11,SNR1: 1.2715 ,SNR2: 3.4699




0056-00 2025/05/17 0.18UT TOYOKAWA-FUJI



T20250517090924




BLK: 8, SNR1: 0.18180 , SNR2: 1.7545





0056-00 2025/05/17 0.18UT TOYOKAWA-KISO


K20250517090921




BLK: 8, SNR1: 3.0527 , SNR2: 9.1550




F20250517090925




BLK: 5, SNR1: 1.5636 , SNR2: 4.7561




K20250517090921




BLK: 5, SNR1: 0.98953 , SNR2: 4.2009




0056-00 2025/05/17 0.18UT FUJI -KISO




T20250517091907




BLK: 4,SNR1: 0.48391 ,SNR2: 2.0582




F20250517091908




BLK: 4,SNR1: 0.51138 ,SNR2: 1.8343




0106+01 2025/05/17 0.35UT TOYOKAWA-FUJI




T20250517091907




BLK: 8, SNR1: 0.52821 , SNR2: 2.0914




K20250517091905




BLK: 8, SNR1: 9.6504 , SNR2: 20.643




0106+01 2025/05/17 0.35UT TOYOKAWA-KISO




F20250517091908




BLK:11,SNR1: 1.4490 ,SNR2: 3.9746




K20250517091905



BLK:11,SNR1: 10.998 ,SNR2: 23.743





0106+01 2025/05/17 0.35UT FUJI -KISO







T20250517092956




BLK: 8, SNR1: 1.8279 , SNR2: 4.0638




F20250517092956





BLK: 8, SNR1: 1.1291 , SNR2: 3.7929




0116+31 2025/05/17 0.53UT TOYOKAWA-FUJI





T20250517092956




BLK:18,SNR1: 0.38541 ,SNR2: 2.4538




K20250517092953





BLK:18,SNR1: 1.5972 ,SNR2: 4.6765




0116+31 2025/05/17 0.53UT TOYOKAWA-KISO




F20250517092956




BLK:14,SNR1: 0.81494 ,SNR2: 2.7514




K20250517092953







BLK:14,SNR1: 1.6316 ,SNR2: 5.1953




0116+31 2025/05/17 0.53UT FUJI -KISO







0128+03 2025/05/17 0.72UT TOYOKAWA-FUJI








F20250517094129




BLK:10,SNR1: 1.7070 ,SNR2: 5.0809




K20250517094129













BLK:10,SNR1: 1.9910 ,SNR2: 6.3447



0128+03 2025/05/17 0.72UT FUJI -KISO











F20250517094803




BLK:13,SNR1: 0.24615 ,SNR2: 2.9335










3C48 2025/05/17 0.83UT FUJI -KISO





K20250517094801




BLK:13,SNR1: 3.0024 ,SNR2: 11.849









0155-109 2025/05/17 1.16UT TOYOKAWA-KISO




F20250517100747




BLK: 6, SNR1: 3.8949 , SNR2: 10.441




K20250517100744







BLK: 6, SNR1: 8.7385 , SNR2: 25.672





0155-109 2025/05/17 1.16UT FUJI -KISO







0202+15 2025/05/17 1.28UT TOYOKAWA-FUJI







BLK:24,SNR1: 1.8103 ,SNR2: 8.4371




BLK:24,SNR1: 4.5455 ,SNR2: 11.720




0202+15 2025/05/17 1.28UT TOYOKAWA-KISO




F20250517101456




BLK:15,SNR1: 1.4434 ,SNR2: 7.3291




K20250517101453





BLK:15,SNR1: 2.6332 ,SNR2: 8.1948




0202+15 2025/05/17 1.28UT FUJI -KISO





T20250517102645




BLK:10,SNR1: 5.8261 ,SNR2: 17.136




F20250517102645



BLK:10,SNR1: 10.654 ,SNR2: 26.028





0213+178 2025/05/17 1.47UT TOYOKAWA-FUJI







T20250517102645




BLK: 9,SNR1: 1.7719 ,SNR2: 5.1790




K20250517102642





BLK: 9,SNR1: 11.248 ,SNR2: 27.636




0213+178 2025/05/17 1.47UT TOYOKAWA-KISO





F20250517102645




BLK:10,SNR1: 1.1189 ,SNR2: 3.1281




K20250517102642




BLK:10,SNR1: 6.8909 ,SNR2: 17.951




0213+178 2025/05/17 1.47UT FUJI -KISO




T20250517103427




BLK:14,SNR1: 0.82857 ,SNR2: 5.0513




F20250517103428




BLK:14,SNR1: 1.3763 ,SNR2: 6.7157




3C67 2025/05/17 1.60UT TOYOKAWA-FUJI





T20250517103427




BLK:23,SNR1: 0.98695 ,SNR2: 8.9545




K20250517103424




BLK:23,SNR1: 0.26615 ,SNR2: 1.3288




3C67 2025/05/17 1.60UT TOYOKAWA-KISO




F20250517103428




BLK: 7, SNR1: 1.0400 , SNR2: 7.0150




K20250517103424




BLK: 7, SNR1: 0.19387 , SNR2: 1.3800




3C67 2025/05/17 1.60UT FUJI -KISO



T20250517105242




BLK: 9,SNR1: 9.0313 ,SNR2: 23.889





3C71 2025/05/17 1.91UT TOYOKAWA-FUJI


F20250517105242




BLK: 9,SNR1: 11.966 ,SNR2: 28.034




T20250517105242




BLK: 8, SNR1: 8.3327 , SNR2: 22.501




K20250517105240





BLK: 8, SNR1: 10.886 , SNR2: 27.117




3C71 2025/05/17 1.91UT TOYOKAWA-KISO



F20250517105242




BLK: 4,SNR1: 11.846 ,SNR2: 28.772





3C71 2025/05/17 1.91UT FUJI -KISO

K20250517105240





BLK: 4,SNR1: 11.597 ,SNR2: 28.523








T20250517111158




BLK:10,SNR1: 11.541 ,SNR2: 29.093




F20250517111158








BLK:10,SNR1: 7.4069 ,SNR2: 13.136





0258+350 2025/05/17 2.23UT TOYOKAWA-FUJI








F20250517111158




BLK: 9,SNR1: 7.2535 ,SNR2: 18.959




K20250517111155




BLK: 9,SNR1: 13.282 ,SNR2: 31.219





0258+350 2025/05/17 2.23UT FUJI -KISO







BLK:11,SNR1: 1.3352 ,SNR2: 2.7688




BLK:11,SNR1: 0.78957E-01,SNR2: 2.0034




0308+305 2025/05/17 2.39UT TOYOKAWA-FUJI





T20250517112147




BLK:23,SNR1: 1.0736 ,SNR2: 3.3227




K20250517112145




BLK:23,SNR1: 6.6043 ,SNR2: 15.621





0308+305 2025/05/17 2.39UT TOYOKAWA-KISO







BLK:12,SNR1: 2.3823 ,SNR2: 7.5150




BLK:12,SNR1: 7.3043 ,SNR2: 17.089




0308+305 2025/05/17 2.39UT FUJI -KISO




T20250517113318




BLK: 6,SNR1: 4.6770 ,SNR2: 12.776




F20250517113319




BLK: 6,SNR1:-0.45397E-01,SNR2: 2.6997




0320+05 2025/05/17 2.58UT TOYOKAWA-FUJI





T20250517113318




BLK:27,SNR1: 4.7980 ,SNR2: 15.079




K20250517113316




BLK:27,SNR1: 1.2114 ,SNR2: 4.6360





0320+05 2025/05/17 2.58UT TOYOKAWA-KISO









BLK: 7, SNR1: 1.3925 , SNR2: 4.2853




BLK: 7, SNR1: 1.4279 , SNR2: 4.0675





0320+05 2025/05/17 2.58UT FUJI -KISO







BLK: 6,SNR1: 3.1493 ,SNR2: 8.8783




BLK: 6,SNR1: 7.4573 ,SNR2: 18.038




0333+32 2025/05/17 2.81UT TOYOKAWA-FUJI





T20250517114640




BLK: 9, SNR1: 0.82850 , SNR2: 2.9699




K20250517114637




BLK: 9, SNR1: 9.5028 , SNR2: 27.529





0333+32 2025/05/17 2.81UT TOYOKAWA-KISO







BLK: 9,SNR1: 6.6591 ,SNR2: 18.038





BLK: 9,SNR1: 5.9617 ,SNR2: 13.714




0333+32 2025/05/17 2.81UT FUJI -KISO




T20250517115941




BLK:10,SNR1: 0.28290 ,SNR2: 4.2800




F20250517115942





BLK:10,SNR1: 0.14151 ,SNR2: 4.1291




0347+05 2025/05/17 3.02UT TOYOKAWA-FUJI




T20250517115941




BLK:16,SNR1: 0.28325 ,SNR2: 4.2809




K20250517115938




BLK:16,SNR1: 7.0487 ,SNR2: 15.757




0347+05 2025/05/17 3.02UT TOYOKAWA-KISO




F20250517115942




BLK:15,SNR1: 0.27758 ,SNR2: 4.7745




K20250517115938







BLK:15,SNR1: 6.1590 ,SNR2: 13.906




0347+05 2025/05/17 3.02UT FUJI -KISO










0403-132 2025/05/17 3.28UT TOYOKAWA-FUJI










0403-132 2025/05/17 3.28UT TOYOKAWA-KISO





F20250517121516




BLK: 1,SNR1: 7.8821 ,SNR2: 18.833




K20250517121512




BLK: 1,SNR1: 9.8086 ,SNR2: 24.401




0403-132 2025/05/17 3.28UT FUJI -KISO





T20250517122426




BLK: 8,SNR1: 1.8568 ,SNR2: 7.1012




F20250517122426




BLK: 8,SNR1: 3.9390 ,SNR2: 5.7991




0411+05 2025/05/17 3.44UT TOYOKAWA-FUJI




T20250517122426




BLK:14,SNR1: 1.8188 ,SNR2: 6.8552




K20250517122423




BLK:14,SNR1: 0.67783 ,SNR2: 2.9318




0411+05 2025/05/17 3.44UT TOYOKAWA-KISO




F20250517122426




BLK: 6,SNR1: 3.9559 ,SNR2: 5.8236




K20250517122423




BLK: 6,SNR1: 1.7923 ,SNR2: 3.6420






0411+05 2025/05/17 3.44UT FUJI -KISO




T20250517123519







F20250517123519




0422+178 2025/05/17 3.62UT TOYOKAWA-FUJI







0422+178 2025/05/17 3.62UT TOYOKAWA-KISO




F20250517123519




BLK: 9,SNR1: 11.138 ,SNR2: 27.106




K20250517123516




BLK: 9,SNR1: 10.076 ,SNR2: 26.983





0422+178 2025/05/17 3.62UT FUJI -KISO









BLK:11,SNR1: 5.7358 ,SNR2: 27.781







BLK:11,SNR1: 1.3742 ,SNR2: 4.0801




3C119 2025/05/17 3.74UT TOYOKAWA-FUJI







3C119 2025/05/17 3.74UT TOYOKAWA-KISO





F20250517124248




BLK: 9,SNR1: 1.0126 ,SNR2: 3.0906




K20250517124245





BLK: 9,SNR1: 3.1894 ,SNR2: 5.6758




3C119 2025/05/17 3.74UT FUJI -KISO





T20250517133055




BLK:11,SNR1: 7.8470 ,SNR2: 22.642




F20250517133055




BLK:11,SNR1: 4.9585 ,SNR2: 14.033





3C138 2025/05/17 4.54UT TOYOKAWA-FUJI







BLK: 9,SNR1: 7.6118 ,SNR2: 22.004




BLK: 9,SNR1: 7.5427 ,SNR2: 19.484




3C138 2025/05/17 4.54UT TOYOKAWA-KISO




F20250517133055




BLK: 9,SNR1: 9.9563 ,SNR2: 24.398




K20250517133052




BLK: 9,SNR1: 9.1431 ,SNR2: 22.496





3C138 2025/05/17 4.54UT FUJI -KISO







BLK:16,SNR1: 4.8748 ,SNR2: 12.395




BLK:16,SNR1: 5.7363 ,SNR2: 14.431





0531+194 2025/05/17 4.77UT TOYOKAWA-FUJI







BLK:27,SNR1: 4.0862 ,SNR2: 10.353



BLK:27,SNR1: 8.6424 ,SNR2: 21.640




0531+194 2025/05/17 4.77UT TOYOKAWA-KISO








F20250517134428




BLK:28,SNR1: 7.9732 ,SNR2: 19.731




K20250517134425




BLK:28,SNR1: 8.5609 ,SNR2: 21.439





0531+194 2025/05/17 4.77UT FUJI -KISO









BLK:18,SNR1: 15.115 ,SNR2: 38.437




BLK:18,SNR1: 3.5174 ,SNR2: 9.6777




T20250517135249




BLK:19,SNR1: 14.656 ,SNR2: 39.218




K20250517135246




BLK:19,SNR1: 10.990 ,SNR2: 27.845





3C147 2025/05/17 4.91UT TOYOKAWA-KISO







BLK:16,SNR1: 3.7160 ,SNR2: 9.9867





BLK:16,SNR1: 8.5018 ,SNR2: 22.724




3C147 2025/05/17 4.91UT FUJI -KISO





T20250517140059




BLK: 5,SNR1: 0.37135 ,SNR2: 2.5833




F20250517140100





BLK: 5,SNR1: 1.1858 ,SNR2: 10.014




0548+16 2025/05/17 5.04UT TOYOKAWA-FUJI





T20250517140059




BLK: 1,SNR1: 0.13830 ,SNR2: 1.6550




K20250517140056






BLK: 1,SNR1: 1.6504 ,SNR2: 7.7563




0548+16 2025/05/17 5.04UT TOYOKAWA-KISO







T20250517140510




BLK:11,SNR1: 20.783 ,SNR2: 123.92




F20250517140510



BLK:11,SNR1: 2.9525 ,SNR2: 8.4532





0552+12 2025/05/17 5.11UT TOYOKAWA-FUJI








T20250517140510




BLK: 6,SNR1: 25.575 ,SNR2: 167.73




K20250517140507




BLK: 6,SNR1: 0.25013 ,SNR2: 2.2533





0552+12 2025/05/17 5.11UT TOYOKAWA-KISO







BLK: 7,SNR1: 8.3893 ,SNR2: 14.806





BLK: 7,SNR1: 0.34144E-01,SNR2: 0.70995




0552+12 2025/05/17 5.11UT FUJI -KISO





T20250517140937




BLK: 3,SNR1: 39.456 ,SNR2: 148.75




F20250517140937





BLK: 3,SNR1: 3.1149 ,SNR2: 23.239




0556+191 2025/05/17 5.19UT TOYOKAWA-FUJI





T20250517140937




BLK: 3,SNR1: 19.565 ,SNR2: 198.53




K20250517140934




BLK: 3,SNR1: 0.22403 ,SNR2: 0.66061





0556+191 2025/05/17 5.19UT TOYOKAWA-KISO







BLK: 1,SNR1: 2.0140 ,SNR2: 10.990




BLK: 1,SNR1: -0.66709E-01,SNR2: 0.41089E-01





0556+191 2025/05/17 5.19UT FUJI -KISO







BLK: 8,SNR1: 2.6840 ,SNR2: 6.8630




BLK: 8,SNR1: 5.0710 ,SNR2: 14.639





0605-08 2025/05/17 5.32UT TOYOKAWA-FUJI







BLK:12,SNR1: 4.8577 ,SNR2: 12.968




BLK:12,SNR1: 10.974 ,SNR2: 29.999





0605-08 2025/05/17 5.32UT TOYOKAWA-KISO








BLK: 8,SNR1: 7.2314 ,SNR2: 18.525





BLK: 8,SNR1: 12.463 ,SNR2: 31.507









BLK:11,SNR1: 0.44380 ,SNR2: 3.0459




BLK:11,SNR1: 0.64779 ,SNR2: 8.7661





3C161 2025/05/17 5.64UT TOYOKAWA-FUJI







BLK:24,SNR1: 0.51779 ,SNR2: 3.8911




BLK:24,SNR1: 0.22333 ,SNR2: 1.5785




3C161 2025/05/17 5.64UT TOYOKAWA-KISO




F20250517143631




BLK: 6,SNR1: 0.11641 ,SNR2: 3.5329




K20250517143627





BLK: 6,SNR1: 0.18493 ,SNR2: 0.89111




3C161 2025/05/17 5.64UT FUJI -KISO




T20250517150403




BLK: 9,SNR1: 0.89565E-02,SNR2: 0.28311




F20250517150403





BLK: 9,SNR1: 3.0117 ,SNR2: 7.7685




0652-130 2025/05/17 6.10UT TOYOKAWA-FUJI





T20250517150403




BLK: 5,SNR1: 0.71538E-01,SNR2: 0.41589




K20250517150400




BLK: 5,SNR1: 2.6837,SNR2: 8.0919




0652-130 2025/05/17 6.10UT TOYOKAWA-KISO





F20250517150403




BLK:12,SNR1: 2.1617 ,SNR2: 5.8698




K20250517150400




BLK:12,SNR1: 7.4092 ,SNR2: 19.056





0652-130 2025/05/17 6.10UT FUJI -KISO







BLK: 9,SNR1: 0.13453 ,SNR2: 0.56036




BLK: 9,SNR1: 7.5134 ,SNR2: 19.747





0703+138 2025/05/17 6.29UT TOYOKAWA-FUJI







BLK: 5,SNR1: 0.12340 ,SNR2: 0.37795




BLK: 5,SNR1: 4.0035 ,SNR2: 10.164





0703+138 2025/05/17 6.29UT TOYOKAWA-KISO











BLK:13,SNR1: 6.0158 ,SNR2: 10.638




BLK:13,SNR1: 0.82476 ,SNR2: 1.8079



T20250517152502





BLK: 3,SNR1: 0.63121E-01,SNR2: 0.31915




Frequency (Hz)

F20250517152502





BLK: 3,SNR1: 0.30931,SNR2: 4.5249





Frequency (Hz)

0713-024 2025/05/17 6.45UT TOYOKAWA-FUJI







BLK: 2,SNR1: 0.21922 ,SNR2: 0.60999




BLK: 2,SNR1: 0.84133 ,SNR2: 5.8442





0713-024 2025/05/17 6.45UT TOYOKAWA-KISO







BLK: 8,SNR1: 0.64025 ,SNR2: 5.8740




BLK: 8,SNR1: 0.34829 ,SNR2: 1.9060




0713-024 2025/05/17 6.45UT FUJI -KISO




T20250517153514




BLK: 5,SNR1: 0.63162 ,SNR2: 4.2022




F20250517153514







BLK: 5,SNR1: 2.7203 ,SNR2: 7.3450





0723+10 2025/05/17 6.62UT TOYOKAWA-FUJI







0723+10 2025/05/17 6.62UT TOYOKAWA-KISO







BLK: 3,SNR1: 1.5608 ,SNR2: 7.0648




BLK: 3,SNR1: 2.2680 ,SNR2: 8.6639





0723+10 2025/05/17 6.62UT FUJI -KISO







BLK:11,SNR1: 0.14837 ,SNR2: 1.2368



BLK:11,SNR1: 0.41950E-01,SNR2: 2.7102





0732+33 2025/05/17 6.79UT TOYOKAWA-FUJI








T20250517154529




BLK:25,SNR1: 0.16558 ,SNR2: 0.59568




K20250517154527




BLK:25,SNR1: 1.8443 ,SNR2: 5.9096





0732+33 2025/05/17 6.79UT TOYOKAWA-KISO








BLK:15,SNR1: 0.45454E-01,SNR2: 2.6046





BLK:15,SNR1: 1.5701 ,SNR2: 5.2711







BLK:11,SNR1: 1.6500 ,SNR2: 4.4196




BLK:11,SNR1: 5.8143 ,SNR2: 10.942





0741-06 2025/05/17 6.92UT TOYOKAWA-FUJI







BLK:15,SNR1: 31.216 ,SNR2: 30.047




BLK:15,SNR1: 4.0628 ,SNR2: 17.056





0741-06 2025/05/17 6.92UT TOYOKAWA-KISO







BLK:21,SNR1: 3.8874 ,SNR2: 16.342





BLK:21,SNR1: 4.1035 ,SNR2: 17.593




0741-06 2025/05/17 6.92UT FUJI -KISO



T20250517160315





BLK: 2, SNR1: 0.10517 , SNR2: 1.1134




Frequency (Hz)

F20250517160315




BLK: 2, SNR1: 1.5544 , SNR2: 4.5690





Frequency (Hz)


0752-200 2025/05/17 7.08UT TOYOKAWA-FUJI





T20250517160315




BLK: 7,SNR1:-0.41247E-01,SNR2: 1.1512




K20250517160312





BLK: 7,SNR1: 0.44026 ,SNR2: 2.4681




0752-200 2025/05/17 7.08UT TOYOKAWA-KISO



F20250517160315





BLK: 3, SNR1: 1.7520 , SNR2: 13.026




Frequency (Hz)

K20250517160312




BLK: 3, SNR1: 0.72465 , SNR2: 6.4766





Frequency (Hz)



0752-200 2025/05/17 7.08UT FUJI -KISO









BLK: 8,SNR1: 0.19690 ,SNR2: 0.71625




BLK: 8,SNR1: 5.0146 ,SNR2: 12.790





3C190 2025/05/17 7.21UT TOYOKAWA-FUJI







BLK: 5, SNR1: 0.25717 , SNR2: 0.70848




BLK: 5, SNR1: 1.4499 , SNR2: 4.1751





3C190 2025/05/17 7.21UT TOYOKAWA-KISO









BLK:14,SNR1: 1.3420 ,SNR2: 3.8189




BLK:14,SNR1: 0.49342 ,SNR2: 1.8454



T20250517162316




BLK:20,SNR1: 0.89238 ,SNR2: 5.7234




Frequency (Hz)

F20250517162316





BLK:20,SNR1: 1.3674 ,SNR2: 5.5013





Frequency (Hz)

3C196 2025/05/17 7.42UT TOYOKAWA-FUJI







BLK:26,SNR1: 0.93895 ,SNR2: 4.1207




BLK:26,SNR1: 0.29483 ,SNR2: 2.2386




3C196 2025/05/17 7.42UT TOYOKAWA-KISO



F20250517162316




BLK:15,SNR1: 1.5259 ,SNR2: 6.1911




Frequency (Hz)

K20250517162314









BLK:15,SNR1: 0.35513 ,SNR2: 1.1783




Frequency (Hz)



3C196 2025/05/17 7.42UT FUJI -KISO









BLK:11,SNR1: 0.11032 ,SNR2: 0.74910




BLK:11,SNR1: 0.43941 ,SNR2: 2.1027





0821+394 2025/05/17 7.60UT TOYOKAWA-KISO









BLK: 7, SNR1: 1.7663 , SNR2: 5.3502




BLK: 7, SNR1: 0.84656 , SNR2: 3.5769





0821+394 2025/05/17 7.60UT FUJI -KISO







BLK: 4,SNR1: 0.56285E-01,SNR2: 0.47522




BLK: 4,SNR1: 0.14708 ,SNR2: 2.4166





3C208 2025/05/17 8.06UT TOYOKAWA-FUJI







BLK: 9,SNR1: 0.31588E-02,SNR2: 0.68605





BLK: 9,SNR1: 2.2809 ,SNR2: 7.4074




3C208 2025/05/17 8.06UT TOYOKAWA-KISO



F20250517170211





BLK:12,SNR1: 0.53236 ,SNR2: 2.6987




Frequency (Hz)

K20250517170208








BLK:12,SNR1: 2.2741 ,SNR2: 7.3853




Frequency (Hz)





3C208 2025/05/17 8.06UT FUJI -KISO











3C216 2025/05/17 8.34UT TOYOKAWA-FUJI







3C216 2025/05/17 8.34UT TOYOKAWA-KISO






T20250517174417




BLK: 3,SNR1: 0.47279 ,SNR2: 2.4514




Frequency (Hz)

F20250517174417




BLK: 3,SNR1: 5.2651 ,SNR2: 27.516







Frequency (Hz)


0931+399 2025/05/17 8.77UT TOYOKAWA-FUJI











0931+399 2025/05/17 8.77UT TOYOKAWA-KISO





0931+399 2025/05/17 8.77UT FUJI -KISO

