








BLK:12,SNR1: 53.550 ,SNR2: 374.56




BLK:12,SNR1: 0.72227 ,SNR2: 6.3500





2152+450 2025/05/20 20.85UT TOYOKAWA-FUJI







BLK: 4, SNR1: 100.24 , SNR2: 726.92










BLK: 4, SNR1: 0.40562 , SNR2: 2.5544





2152+450 2025/05/20 20.85UT TOYOKAWA-KISO







T20250521055732




BLK: 5, SNR1: 3.8098 , SNR2: 32.286




F20250521055733




BLK: 5, SNR1: 0.62833 , SNR2: 5.4527





2200+420 2025/05/20 20.99UT TOYOKAWA-FUJI







BLK:12,SNR1: 1.6743 ,SNR2: 16.068




BLK:12,SNR1: 13.528 ,SNR2: 14.789




2200+420 2025/05/20 20.99UT TOYOKAWA-KISO




F20250521055733




BLK:22,SNR1: 2.4276 ,SNR2: 12.016




K20250521055729





BLK:22,SNR1: 12.301 ,SNR2: 13.375





2200+420 2025/05/20 20.99UT FUJI -KISO







BLK: 2,SNR1:-0.27007E-01,SNR2: 0.57050





BLK: 2,SNR1: 0.94389 ,SNR2: 3.3375






2207+374 2025/05/20 21.10UT TOYOKAWA-FUJI







BLK: 2,SNR1: 0.33861E-01,SNR2: 0.93065E-02





BLK: 2,SNR1: 1.4125 ,SNR2: 8.0312




2207+374 2025/05/20 21.10UT TOYOKAWA-KISO





F20250521060412




BLK: 6, SNR1: 0.79749 , SNR2: 2.9774




K20250521060409





BLK: 6, SNR1: 2.3626 , SNR2: 4.7592






2207+374 2025/05/20 21.10UT FUJI -KISO







BLK: 5, SNR1: 0.67367 , SNR2: 1.9481





BLK: 5, SNR1: 1.8653 , SNR2: 5.9087




2217+128 2025/05/20 21.28UT TOYOKAWA-FUJI





T20250521061503




BLK: 6,SNR1: 0.54017 ,SNR2: 1.6467




K20250521061500




BLK: 6,SNR1: 2.9216 ,SNR2: 9.1360





2217+128 2025/05/20 21.28UT TOYOKAWA-KISO







BLK: 9,SNR1: 2.1625 ,SNR2: 2.8405




BLK: 9,SNR1: 1.5986 ,SNR2: 4.9294





2217+128 2025/05/20 21.28UT FUJI -KISO







BLK: 9,SNR1: 1.8337 ,SNR2: 19.504








BLK: 9,SNR1: 0.37889 ,SNR2: 2.6656




2243+394 2025/05/20 21.70UT TOYOKAWA-FUJI







F20250521064036




BLK:11,SNR1: 0.49312E-01,SNR2: 1.3874




K20250521064032







BLK:11,SNR1: 2.5057 ,SNR2: 5.1887








2243+394 2025/05/20 21.70UT FUJI -KISO






3C454.3 2025/05/20 21.84UT TOYOKAWA-FUJI








3C454.3 2025/05/20 21.84UT TOYOKAWA-KISO



F20250521064849





BLK:23,SNR1: 2.8825 ,SNR2: 8.8850




Frequency (Hz)

K20250521064846





BLK:23,SNR1: 3.3237 ,SNR2: 10.029





Frequency (Hz)

3C454.3 2025/05/20 21.84UT FUJI -KISO







BLK: 2,SNR1: 0.45607E-01,SNR2: 0.91964





BLK: 2,SNR1: 0.80316 ,SNR2: 6.7329





2259+481 2025/05/20 21.97UT TOYOKAWA-FUJI







BLK: 2, SNR1: 0.45377 , SNR2: 0.63288




BLK: 2, SNR1: 0.78389 , SNR2: 3.3342




2259+481 2025/05/20 21.97UT TOYOKAWA-KISO




F20250521065632




BLK: 3,SNR1: 0.73857E-01,SNR2: 2.5613




K20250521065628









BLK: 3,SNR1: 0.31490 ,SNR2: 4.0672







2259+481 2025/05/20 21.97UT FUJI -KISO













3C459 2025/05/20 22.22UT FUJI -KISO





T20250521074510




BLK:18,SNR1: 5.1290 ,SNR2: 11.773




F20250521074510





BLK:18,SNR1: 8.1842 ,SNR2: 12.848




2347-02 2025/05/20 22.78UT TOYOKAWA-FUJI




T20250521074510




BLK:24,SNR1: 9.7825 ,SNR2: 13.110




K20250521074507




BLK:24,SNR1: 9.9331 ,SNR2: 21.712




2347-02 2025/05/20 22.78UT TOYOKAWA-KISO





F20250521074510




BLK:16,SNR1: 8.2176 ,SNR2: 12.907




K20250521074507







BLK:16,SNR1: 14.310 ,SNR2: 32.115





2347-02 2025/05/20 22.78UT FUJI -KISO









BLK: 2,SNR1: 0.71771E-01,SNR2: 0.55135




BLK: 2,SNR1: 0.51566 ,SNR2: 1.9758




2354+14 2025/05/20 22.90UT TOYOKAWA-KISO




F20250521075203




BLK: 2,SNR1: -0.11434E-02,SNR2: 1.0369




K20250521075200




BLK: 2,SNR1: 0.39749 ,SNR2: 1.6404




2354+14 2025/05/20 22.90UT FUJI -KISO





T20250521080106




BLK: 5, SNR1: 0.37747 , SNR2: 1.9750




F20250521080107




BLK: 5, SNR1: 2.7836 , SNR2: 8.7304





3C2 2025/05/20 23.05UT TOYOKAWA-FUJI












BLK:14,SNR1: 0.58653 ,SNR2: 2.7267




BLK:14,SNR1: 1.9770 ,SNR2: 6.4675







T20250521080828




BLK: 7, SNR1: 1.0359 , SNR2: 2.4590




F20250521080829




BLK: 7, SNR1: 1.9366 , SNR2: 6.0742




0011+344 2025/05/20 23.17UT TOYOKAWA-FUJI




T20250521080828




BLK: 5, SNR1: 0.19436 , SNR2: 1.4232




K20250521080825




BLK: 5, SNR1: 1.1039 , SNR2: 4.2290




0011+344 2025/05/20 23.17UT TOYOKAWA-KISO




F20250521080829




BLK: 8, SNR1: 2.3493 , SNR2: 6.7173




K20250521080825




BLK: 8, SNR1: 2.6875 , SNR2: 5.5952




0011+344 2025/05/20 23.17UT FUJI -KISO




T20250521081705




BLK: 6,SNR1: 0.21781 ,SNR2: 1.7351




F20250521081705












BLK: 6,SNR1: 0.71853 ,SNR2: 3.0488




0019-00 2025/05/20 23.31UT TOYOKAWA-FUJI










0019-00 2025/05/20 23.31UT FUJI -KISO




T20250521082719




BLK:11,SNR1: 0.18683 ,SNR2: 1.8310




F20250521082719




BLK:11,SNR1: 3.6279 ,SNR2: 7.3897




3C12 2025/05/20 23.48UT TOYOKAWA—FUJI





T20250521082719




BLK:12,SNR1: 0.42535 ,SNR2: 2.0009




K20250521082716




BLK:12,SNR1: 11.084 ,SNR2: 21.512




3C12 2025/05/20 23.48UT TOYOKAWA-KISO





F20250521082719




BLK:10,SNR1: 3.8672 ,SNR2: 7.8730




K20250521082716




BLK:10,SNR1: 2.1369 ,SNR2: 7.8417




3C12 2025/05/20 23.48UT FUJI -KISO





T20250521084121




BLK: 8, SNR1: 12.626 , SNR2: 30.836




F20250521084121




BLK: 8, SNR1: 8.3312 , SNR2: 19.892




0044-056 2025/05/20 23.72UT TOYOKAWA-FUJI




T20250521084121




BLK:11,SNR1: 11.619 ,SNR2: 28.370




K20250521084118




BLK:11,SNR1: 9.5805 ,SNR2: 27.326




0044-056 2025/05/20 23.72UT TOYOKAWA-KISO




F20250521084121




BLK: 8, SNR1: 7.5447 , SNR2: 21.910




K20250521084118





BLK: 8, SNR1: 7.9698 , SNR2: 23.036





0044-056 2025/05/20 23.72UT FUJI -KISO







BLK: 9,SNR1: 0.45963E-01,SNR2: 1.3352













BLK: 9,SNR1: 0.14010E-01,SNR2: 2.1780





3C26 2025/05/20 23.84UT TOYOKAWA-FUJI










T20250521085341




BLK: 7, SNR1: 6.5462 , SNR2: 16.384




F20250521085341





BLK: 7, SNR1: 7.3722 , SNR2: 18.846




0056-00 2025/05/20 23.92UT TOYOKAWA-FUJI





T20250521085341




BLK: 5, SNR1: 4.4176 , SNR2: 11.750




K20250521085338





BLK: 5, SNR1: 8.4046 , SNR2: 21.721




0056-00 2025/05/20 23.92UT TOYOKAWA-KISO





F20250521085341




BLK: 7, SNR1: 6.8906 , SNR2: 12.629




K20250521085338





BLK: 7, SNR1: 7.4770 , SNR2: 18.908




0056-00 2025/05/20 23.92UT FUJI -KISO




T20250521090323




BLK: 6, SNR1: 10.893 , SNR2: 26.002




F20250521090323





BLK: 6, SNR1: 9.4454 , SNR2: 22.698




0106+01 2025/05/21 0.08UT TOYOKAWA-FUJI





T20250521090323




BLK: 8, SNR1: 8.4454 , SNR2: 21.678




K20250521090320




BLK: 8, SNR1: 10.043 , SNR2: 22.776




0106+01 2025/05/21 0.08UT TOYOKAWA-KISO





F20250521090323




BLK: 5, SNR1: 5.8065 , SNR2: 15.576




K20250521090320





BLK: 5, SNR1: 13.081 , SNR2: 31.856




0106+01 2025/05/21 0.08UT FUJI -KISO





T20250521091413




BLK: 7, SNR1: 7.5920 , SNR2: 21.600




F20250521091413





BLK: 7, SNR1: 79.734 , SNR2: 77.836




0116+31 2025/05/21 0.27UT TOYOKAWA-FUJI




T20250521091413




BLK:11,SNR1: 7.7387 ,SNR2: 17.785




K20250521091410





BLK:11,SNR1: 15.882 ,SNR2: 38.907




0116+31 2025/05/21 0.27UT TOYOKAWA-KISO




F20250521091413




BLK: 2, SNR1: 7.3560 , SNR2: 21.202




K20250521091410




BLK: 2, SNR1: 7.7693 , SNR2: 21.622




0116+31 2025/05/21 0.27UT FUJI -KISO




T20250521092545




BLK: 5, SNR1: 10.351 , SNR2: 25.546




F20250521092546




BLK: 5, SNR1: 7.1255 , SNR2: 17.305




0128+03 2025/05/21 0.46UT TOYOKAWA-FUJI




T20250521092545




BLK: 9, SNR1: 15.184 , SNR2: 36.011




K20250521092542




BLK: 9, SNR1: 9.9563 , SNR2: 24.860




0128+03 2025/05/21 0.46UT TOYOKAWA-KISO




F20250521092546




BLK: 9, SNR1: 9.6333 , SNR2: 18.238




K20250521092542





BLK: 9, SNR1: 7.1950 , SNR2: 20.555




0128+03 2025/05/21 0.46UT FUJI -KISO





T20250521093219




BLK:23,SNR1: 6.7358 ,SNR2: 56.880




F20250521093219





BLK:23,SNR1: 0.11756 ,SNR2: 2.1617




3C48 2025/05/21 0.57UT TOYOKAWA-FUJI





T20250521093219




BLK:30,SNR1: 6.9945 ,SNR2: 59.081




K20250521093217





BLK:30,SNR1: 0.76602 ,SNR2: 2.7399




3C48 2025/05/21 0.57UT TOYOKAWA-KISO





F20250521093219




BLK:28,SNR1: 0.20699 ,SNR2: 1.4932




K20250521093217




BLK:28,SNR1: 0.81652 ,SNR2: 3.1862




3C48 2025/05/21 0.57UT FUJI -KISO




T20250521095204




BLK: 4, SNR1: 5.4497 , SNR2: 15.520




F20250521095205





BLK: 4, SNR1: 2.3835 , SNR2: 5.9309




0155-109 2025/05/21 0.90UT TOYOKAWA-FUJI





T20250521095204




BLK:10,SNR1: 10.996 ,SNR2: 24.776




K20250521095201







BLK:10,SNR1: 18.969 ,SNR2: 20.924








0155-109 2025/05/21 0.90UT TOYOKAWA-KISO






0155-109 2025/05/21 0.90UT FUJI -KISO








0202+15 2025/05/21 1.01UT TOYOKAWA-FUJI





T20250521095911




BLK: 7, SNR1: 9.6337 , SNR2: 27.893




K20250521095908





BLK: 7, SNR1: 10.141 , SNR2: 29.430




0202+15 2025/05/21 1.01UT TOYOKAWA-KISO





F20250521095912




BLK: 9, SNR1: 7.2401 , SNR2: 20.861




K20250521095908




BLK: 9, SNR1: 9.1373 , SNR2: 26.426




0202+15 2025/05/21 1.01UT FUJI -KISO




T20250521101101




BLK: 6, SNR1: 5.4037 , SNR2: 13.480




F20250521101101




BLK: 6, SNR1: 1.4480 , SNR2: 4.7259




0213+178 2025/05/21 1.21UT TOYOKAWA-FUJI




T20250521101101




BLK: 7, SNR1: 6.3991 , SNR2: 18.279




K20250521101058




BLK: 7, SNR1: 10.958 , SNR2: 27.659




0213+178 2025/05/21 1.21UT TOYOKAWA-KISO




F20250521101101




BLK:14,SNR1: 4.8576 ,SNR2: 13.066




K20250521101058




BLK:14,SNR1: 10.682 ,SNR2: 27.277




0213+178 2025/05/21 1.21UT FUJI -KISO



T20250521101844




BLK:23,SNR1: 4.1448 ,SNR2: 12.410





3C67 2025/05/21 1.34UT TOYOKAWA-FUJI



F20250521101844




BLK:23,SNR1: 1.6244 ,SNR2: 5.1298



T20250521101844





BLK:21,SNR1: 4.1871 ,SNR2: 12.524





3C67 2025/05/21 1.34UT TOYOKAWA-KISO


K20250521101842




BLK:21,SNR1: 7.8702 ,SNR2: 14.729





F20250521101844




BLK:26,SNR1: 1.6023 ,SNR2: 5.0656




K20250521101842




BLK:26,SNR1: 7.8431 ,SNR2: 14.676





3C67 2025/05/21 1.34UT FUJI -KISO









BLK: 8, SNR1: 9.3474 , SNR2: 28.747




BLK: 8, SNR1: 7.4114 , SNR2: 18.805




T20250521103659




BLK: 5, SNR1: 10.939 , SNR2: 29.281




K20250521103657




BLK: 5, SNR1: 7.1938 , SNR2: 18.374




3C71 2025/05/21 1.64UT TOYOKAWA-KISO



F20250521103659




BLK: 5, SNR1: 7.9052 , SNR2: 20.104





3C71 2025/05/21 1.64UT FUJI -KISO



K20250521103657




BLK: 5, SNR1: 5.3378 , SNR2: 13.645





T20250521105614




BLK: 6, SNR1: 10.964 , SNR2: 26.606




F20250521105614





BLK: 6, SNR1: 4.8353 , SNR2: 12.703




0258+350 2025/05/21 1.97UT TOYOKAWA-FUJI





T20250521105614




BLK: 7, SNR1: 10.941 , SNR2: 26.552




K20250521105611




BLK: 7, SNR1: 9.6561 , SNR2: 16.932




0258+350 2025/05/21 1.97UT TOYOKAWA-KISO





F20250521105614




BLK:13,SNR1: 5.9020 ,SNR2: 15.426




K20250521105611





BLK:13,SNR1: 9.2352 ,SNR2: 16.183




0258+350 2025/05/21 1.97UT FUJI -KISO





T20250521110603




BLK:15,SNR1: 0.64658 ,SNR2: 1.5956




F20250521110604





BLK:15,SNR1: 2.2527 ,SNR2: 6.4573




0308+305 2025/05/21 2.13UT TOYOKAWA-FUJI





T20250521110603




BLK:11,SNR1: 0.60459 ,SNR2: 2.4788




K20250521110600





BLK:11,SNR1: 0.50902 ,SNR2: 2.1705




0308+305 2025/05/21 2.13UT TOYOKAWA-KISO





F20250521110604




BLK:12,SNR1: 1.8391 ,SNR2: 4.3564




K20250521110600





BLK:12,SNR1: 0.48197 ,SNR2: 1.8415




0308+305 2025/05/21 2.13UT FUJI -KISO




T20250521111735




BLK:16,SNR1: 3.8395 ,SNR2: 11.025




F20250521111735




BLK:16,SNR1: 0.15649E-01,SNR2: 1.4214




0320+05 2025/05/21 2.32UT TOYOKAWA-FUJI





T20250521111735




BLK:24,SNR1: 3.9234 ,SNR2: 11.235




K20250521111732




BLK:24,SNR1: 2.6432 ,SNR2: 5.3935




0320+05 2025/05/21 2.32UT TOYOKAWA-KISO




F20250521111735




BLK:11,SNR1: 0.20208 ,SNR2: 2.3846




K20250521111732





BLK:11,SNR1: 1.1579 ,SNR2: 4.8838




0320+05 2025/05/21 2.32UT FUJI -KISO





T20250521113056




BLK: 7, SNR1: 5.1414 , SNR2: 13.036




F20250521113057





BLK: 7, SNR1: 8.4485 , SNR2: 21.008




0333+32 2025/05/21 2.54UT TOYOKAWA-FUJI



T20250521113056




BLK: 8,SNR1: 6.2416 ,SNR2: 17.209




0333+32 2025/05/21 2.54UT TOYOKAWA-KISO


K20250521113053





BLK: 8,SNR1: 10.394 ,SNR2: 24.765




Frequency (Hz)




F20250521113057




BLK:11,SNR1: 4.7497 ,SNR2: 12.318




K20250521113053





BLK:11,SNR1: 11.459 ,SNR2: 25.632




0333+32 2025/05/21 2.54UT FUJI -KISO





T20250521114357




BLK:10,SNR1: 0.30007 ,SNR2: 1.3471




F20250521114358





BLK:10,SNR1: 1.9498 ,SNR2: 11.350




0347+05 2025/05/21 2.76UT TOYOKAWA-FUJI





T20250521114357




BLK: 9,SNR1: 0.17799 ,SNR2: 0.85336




K20250521114354





BLK: 9,SNR1: 3.3831 ,SNR2: 13.940




0347+05 2025/05/21 2.76UT TOYOKAWA-KISO




F20250521114358




BLK:11,SNR1: 0.63094 ,SNR2: 6.0508




K20250521114354





BLK:11,SNR1: 1.9068 ,SNR2: 10.826




0347+05 2025/05/21 2.76UT FUJI -KISO





T20250521115932




BLK: 5,SNR1: 0.16453 ,SNR2: 1.4544




F20250521115932





BLK: 5,SNR1:-0.34055 ,SNR2: 0.0000




0403-132 2025/05/21 3.02UT TOYOKAWA-FUJI





T20250521115932




BLK: 5,SNR1: 0.99541 ,SNR2: 1.8457




K20250521115929




BLK: 5,SNR1: 10.293 ,SNR2: 23.226





0403-132 2025/05/21 3.02UT TOYOKAWA-KISO







BLK: 3,SNR1:-0.20474 ,SNR2: 2.8161





BLK: 3,SNR1: 0.41049 ,SNR2: 1.6093




0403-132 2025/05/21 3.02UT FUJI -KISO





T20250521120842




BLK: 6,SNR1: 9.5825 ,SNR2: 24.008




F20250521120843





BLK: 6,SNR1: 4.8741 ,SNR2: 14.387




0411+05 2025/05/21 3.17UT TOYOKAWA-FUJI




T20250521120842




BLK: 7, SNR1: 0.97052 , SNR2: 3.1730




K20250521120840




BLK: 7, SNR1: 5.8073 , SNR2: 17.081




0411+05 2025/05/21 3.17UT TOYOKAWA-KISO




F20250521120843




BLK: 7,SNR1: 8.9089 ,SNR2: 22.878




K20250521120840





BLK: 7,SNR1: 7.4922 ,SNR2: 20.526




0411+05 2025/05/21 3.17UT FUJI -KISO




T20250521121936




BLK:14,SNR1: 6.7063 ,SNR2: 17.929




F20250521121936





BLK:14,SNR1: 6.1297 ,SNR2: 14.086




0422+178 2025/05/21 3.35UT TOYOKAWA-FUJI





T20250521121936




BLK: 5,SNR1: 11.272 ,SNR2: 29.274




K20250521121933




BLK: 5,SNR1: 10.003 ,SNR2: 25.749





0422+178 2025/05/21 3.35UT TOYOKAWA-KISO







BLK: 6,SNR1: 8.4702 ,SNR2: 21.606





BLK: 6,SNR1: 9.4013 ,SNR2: 23.315




0422+178 2025/05/21 3.35UT FUJI -KISO





T20250521122705




BLK:22,SNR1: 5.1256 ,SNR2: 12.379




F20250521122706









BLK:22,SNR1: 1.7562 ,SNR2: 5.1482





3C119 2025/05/21 3.48UT TOYOKAWA-FUJI









BLK:23,SNR1: 1.8479 ,SNR2: 5.4593





BLK:23,SNR1: 4.5638 ,SNR2: 8.0920




3C119 2025/05/21 3.48UT FUJI -KISO





T20250521131511




BLK:18,SNR1: 5.0880 ,SNR2: 13.426




F20250521131511





BLK:18,SNR1: 6.3831 ,SNR2: 15.371




3C138 2025/05/21 4.28UT TOYOKAWA-FUJI




T20250521131511




BLK:17,SNR1: 4.1633 ,SNR2: 25.879




K20250521131508








BLK:17,SNR1: 2.0262 ,SNR2: 4.1465




3C138 2025/05/21 4.28UT TOYOKAWA-KISO







T20250521132845




BLK:22,SNR1: 2.4024 ,SNR2: 9.1341




F20250521132846




BLK:22,SNR1: 0.15461 ,SNR2: 3.1489




0531+194 2025/05/21 4.51UT TOYOKAWA-FUJI




T20250521132845




BLK:24,SNR1: 2.2771 ,SNR2: 8.8493




K20250521132842




BLK:24,SNR1: 0.43559 ,SNR2: 1.9625




0531+194 2025/05/21 4.51UT TOYOKAWA-KISO




F20250521132846




BLK:23,SNR1: 0.32213 ,SNR2: 3.7826




K20250521132842




BLK:23,SNR1: 0.35911 ,SNR2: 2.7067




0531+194 2025/05/21 4.51UT FUJI -KISO





T20250521133705




BLK:29,SNR1: 17.089 ,SNR2: 51.173




F20250521133705




BLK:29,SNR1: 4.8668 ,SNR2: 12.326




3C147 2025/05/21 4.65UT TOYOKAWA-FUJI




T20250521133705




BLK:30,SNR1: 17.059 ,SNR2: 77.146




K20250521133703





BLK:30,SNR1: 3.0096 ,SNR2: 5.9429




3C147 2025/05/21 4.65UT TOYOKAWA-KISO




F20250521133705




BLK:25,SNR1: 3.6726 ,SNR2: 9.8509




K20250521133703





BLK:25,SNR1: 3.1181 ,SNR2: 6.1571




3C147 2025/05/21 4.65UT FUJI -KISO




T20250521134516




BLK:16,SNR1: 0.51034 ,SNR2: 2.1624




F20250521134516





BLK:16,SNR1: 0.59318 ,SNR2: 5.3393




0548+16 2025/05/21 4.78UT TOYOKAWA-FUJI




T20250521134516




BLK:18,SNR1: 0.54586 ,SNR2: 2.2252




K20250521134514




BLK:18,SNR1: 0.31546 ,SNR2: 1.1262




0548+16 2025/05/21 4.78UT TOYOKAWA-KISO





F20250521134516




BLK:12,SNR1: 0.12486 ,SNR2: 2.4064




K20250521134514





BLK:12,SNR1: 0.43802 ,SNR2: 1.7047




0548+16 2025/05/21 4.78UT FUJI -KISO





T20250521134926




BLK:13,SNR1: 18.633 ,SNR2: 114.64




F20250521134927





BLK:13,SNR1: 6.9881 ,SNR2: 18.116




0552+12 2025/05/21 4.85UT TOYOKAWA-FUJI




T20250521134926




BLK:16,SNR1: 18.938 ,SNR2: 52.708




K20250521134924





BLK:16,SNR1: 2.3055 ,SNR2: 7.1869




0552+12 2025/05/21 4.85UT TOYOKAWA-KISO




F20250521134927




BLK: 3,SNR1: 2.4164 ,SNR2: 6.0807




K20250521134924





BLK: 3,SNR1: 0.68304 ,SNR2: 3.0727




0552+12 2025/05/21 4.85UT FUJI -KISO





T20250521135353




BLK: 3,SNR1: 0.35544 ,SNR2: 0.94836




F20250521135353





BLK: 3,SNR1: 3.6958 ,SNR2: 21.068




0556+191 2025/05/21 4.93UT TOYOKAWA-FUJI




T20250521135353




BLK: 4,SNR1:-0.18209E-01,SNR2: 0.72623




K20250521135350




BLK: 4,SNR1: 0.29217 ,SNR2: 3.4593




0556+191 2025/05/21 4.93UT TOYOKAWA-KISO





F20250521135353




BLK: 6,SNR1:-0.18577 ,SNR2: 1.7770




K20250521135350




BLK: 6,SNR1: 0.11208 ,SNR2: 1.4053





0556+191 2025/05/21 4.93UT FUJI -KISO







BLK: 4,SNR1: 0.58986 ,SNR2: 1.7881




BLK: 4,SNR1: 9.6509 ,SNR2: 23.593





0605-08 2025/05/21 5.06UT TOYOKAWA-FUJI







BLK: 9,SNR1: 0.38848 ,SNR2: 2.2843




BLK: 9,SNR1: 1.9085 ,SNR2: 4.0023





0605-08 2025/05/21 5.06UT TOYOKAWA-KISO








BLK: 6,SNR1: 8.1345 ,SNR2: 25.025





BLK: 6,SNR1: 6.5756 ,SNR2: 19.055







BLK: 3,SNR1: 0.43027 ,SNR2: 4.9244




BLK: 3,SNR1: 0.34394 ,SNR2: 1.5618





3C161 2025/05/21 5.37UT TOYOKAWA-FUJI







BLK:12,SNR1: 0.31833 ,SNR2: 2.5072




BLK:12,SNR1: 0.36425 ,SNR2: 1.8260





3C161 2025/05/21 5.37UT TOYOKAWA-KISO







BLK:10,SNR1: 1.1911 ,SNR2: 3.1622





BLK:10,SNR1: 2.7633 ,SNR2: 5.4924




3C161 2025/05/21 5.37UT FUJI -KISO





T20250521144820




BLK: 4,SNR1: 0.19387 ,SNR2: 1.3120




F20250521144820




BLK: 4,SNR1:-0.22796 ,SNR2: 0.78906





0652-130 2025/05/21 5.83UT TOYOKAWA-FUJI







BLK: 6,SNR1: 0.10631 ,SNR2: 0.76117




BLK: 6,SNR1: 0.41598 ,SNR2: 2.9375





0652-130 2025/05/21 5.83UT TOYOKAWA-KISO








BLK: 4,SNR1: 0.17411 ,SNR2: 7.4729





BLK: 4,SNR1: 0.65414 ,SNR2: 6.2617







BLK:12,SNR1: 0.78899E-01,SNR2: 1.6811





BLK:12,SNR1: 1.2673 ,SNR2: 3.9762




0703+138 2025/05/21 6.03UT TOYOKAWA-FUJI





T20250521145956




BLK: 7,SNR1: 0.55536E-01,SNR2: 1.6177




K20250521145953







BLK: 7,SNR1: 0.59644 ,SNR2: 1.8657





0703+138 2025/05/21 6.03UT TOYOKAWA-KISO








T20250521150919




BLK: 4,SNR1: 0.32869E-01,SNR2: 0.39522




F20250521150920




BLK: 4,SNR1: 0.21186E-01,SNR2: 2.1914





0713-024 2025/05/21 6.18UT TOYOKAWA-FUJI







BLK: 2,SNR1: 0.71228E-01,SNR2: 0.78664




BLK: 2,SNR1: 1.4229 ,SNR2: 7.4687





0713-024 2025/05/21 6.18UT TOYOKAWA-KISO








BLK: 6,SNR1:-0.14018 ,SNR2: 1.4047




BLK: 6,SNR1: 0.15200 ,SNR2: 0.60632





T20250521151931




BLK: 6,SNR1:-0.10149 ,SNR2: 0.82080




F20250521151931




BLK: 6,SNR1: 2.7403 ,SNR2: 8.3209





0723+10 2025/05/21 6.35UT TOYOKAWA-FUJI







BLK: 7,SNR1: 0.37880 ,SNR2: 3.3961





BLK: 7,SNR1: 9.4486 ,SNR2: 9.8248




0723+10 2025/05/21 6.35UT TOYOKAWA-KISO





F20250521151931




BLK: 4,SNR1: 2.8968 ,SNR2: 9.5235




K20250521151928




BLK: 4,SNR1: 0.23010 ,SNR2: 2.3417





0723+10 2025/05/21 6.35UT FUJI -KISO







BLK:10,SNR1: 0.47819 ,SNR2: 2.1011




BLK:10,SNR1: 5.3365 ,SNR2: 15.456





0732+33 2025/05/21 6.52UT TOYOKAWA-FUJI







BLK: 9,SNR1: 0.20023 ,SNR2: 1.8223




BLK: 9,SNR1: 5.0203 ,SNR2: 8.5959





0732+33 2025/05/21 6.52UT TOYOKAWA-KISO









BLK: 4,SNR1: 0.80659 ,SNR2: 5.6660




BLK: 4,SNR1:-0.23286 ,SNR2: 1.0300





T20250521153747




BLK: 5,SNR1: 0.14688 ,SNR2: 2.0193




F20250521153747




BLK: 5,SNR1: 0.21640 ,SNR2: 3.6990





0741-06 2025/05/21 6.66UT TOYOKAWA-FUJI







BLK: 7,SNR1: 0.92239E-01,SNR2: 1.2433




BLK: 7,SNR1: 43.857 ,SNR2: 48.928




0741-06 2025/05/21 6.66UT TOYOKAWA-KISO





F20250521153747




BLK: 5,SNR1: 0.33907 ,SNR2: 4.1962




K20250521153744





BLK: 5,SNR1: 2.9636 ,SNR2: 5.5576




0741-06 2025/05/21 6.66UT FUJI -KISO



T20250521154731





BLK: 5, SNR1: 0.76390 , SNR2: 3.9082




Frequency (Hz)

F20250521154731




BLK: 5, SNR1: 0.63668 , SNR2: 2.1929





Frequency (Hz)


0752-200 2025/05/21 6.82UT TOYOKAWA-FUJI





T20250521154731




BLK: 3,SNR1: 0.46831E-02,SNR2: 0.37264E-01




K20250521154728




BLK: 3,SNR1: 5.4528 ,SNR2: 11.785




0752-200 2025/05/21 6.82UT TOYOKAWA-KISO




F20250521154731




BLK:14,SNR1: 0.74508 ,SNR2: 2.5041




K20250521154728




BLK:14,SNR1: 0.63939E-01,SNR2: 3.6555





0752-200 2025/05/21 6.82UT FUJI -KISO







BLK: 6,SNR1: 2.3141 ,SNR2: 34.617




BLK: 6,SNR1: 1.4522 ,SNR2: 3.2063





3C190 2025/05/21 6.95UT TOYOKAWA-FUJI







BLK: 3,SNR1: 4.4664 ,SNR2: 30.772





BLK: 3,SNR1: 16.771 ,SNR2: 23.010




3C190 2025/05/21 6.95UT TOYOKAWA-KISO



F20250521155507





BLK:10,SNR1: 0.77657 ,SNR2: 4.2845




Frequency (Hz)

K20250521155505




BLK:10,SNR1: 1.0629 ,SNR2: 4.0161





Frequency (Hz)


3C190 2025/05/21 6.95UT FUJI -KISO



T20250521160732




BLK: 5,SNR1: 0.45849 ,SNR2: 2.0869




Frequency (Hz)

F20250521160732




BLK: 5,SNR1: 1.5482 ,SNR2: 4.2003





Frequency (Hz)


3C196 2025/05/21 7.15UT TOYOKAWA-FUJI



T20250521160732




BLK: 2,SNR1: 1.3281 ,SNR2: 4.6998




Frequency (Hz)

K20250521160729




BLK: 2,SNR1: 5.8750 ,SNR2: 14.481




Frequency (Hz)


3C196 2025/05/21 7.15UT TOYOKAWA-KISO




F20250521160732




BLK: 4, SNR1: 2.0674 , SNR2: 6.4346




K20250521160729




BLK: 4, SNR1: 19.391 , SNR2: 27.933





3C196 2025/05/21 7.15UT FUJI -KISO







BLK: 6,SNR1: 9.5042 ,SNR2: 17.021




BLK: 6,SNR1: 6.9311 ,SNR2: 12.491





0821+394 2025/05/21 7.34UT TOYOKAWA-FUJI







BLK:16,SNR1: 9.4595 ,SNR2: 16.928




BLK:16,SNR1: 8.7899 ,SNR2: 15.322





0821+394 2025/05/21 7.34UT TOYOKAWA-KISO







BLK:14,SNR1: 8.6977 ,SNR2: 15.208







BLK:14,SNR1: 7.9821 ,SNR2: 20.672





0821+394 2025/05/21 7.34UT FUJI -KISO







0839-071 2025/05/21 7.62UT TOYOKAWA-FUJI







BLK: 4, SNR1: 8.4815 , SNR2: 32.868




BLK: 4, SNR1: 2.2629 , SNR2: 4.5090





0839-071 2025/05/21 7.62UT TOYOKAWA-KISO







BLK: 5,SNR1:-0.26701 ,SNR2: 0.28539







BLK: 5,SNR1: 4.2550 ,SNR2: 11.029








0839-071 2025/05/21 7.62UT FUJI -KISO







3C208 2025/05/21 7.80UT TOYOKAWA-FUJI







3C208 2025/05/21 7.80UT TOYOKAWA-KISO







BLK:19,SNR1: 1.4740 ,SNR2: 3.7646




BLK:19,SNR1: 6.2438 ,SNR2: 10.940





3C208 2025/05/21 7.80UT FUJI -KISO







BLK:30,SNR1: 10.874 ,SNR2: 26.844




BLK:30,SNR1: 8.7435 ,SNR2: 21.156





3C216 2025/05/21 8.08UT TOYOKAWA-FUJI







BLK:30,SNR1: 9.2220 ,SNR2: 23.559




BLK:30,SNR1: 10.701 ,SNR2: 24.839




3C216 2025/05/21 8.08UT TOYOKAWA-KISO



F20250521170309





BLK:25,SNR1: 8.6075 ,SNR2: 20.602




Frequency (Hz)

K20250521170306



BLK:25,SNR1: 8.5034 ,SNR2: 22.859



Frequency (Hz)

3C216 2025/05/21 8.08UT FUJI -KISO

