






T20250525053322




BLK: 9,SNR1: 0.32494 ,SNR2: 1.9106




F20250525053322





BLK: 9,SNR1: 2.5313 ,SNR2: 4.4321




2152+450 2025/05/24 20.58UT TOYOKAWA-FUJI





T20250525053322




BLK:11,SNR1: 0.77303 ,SNR2: 4.5316




K20250525053319




BLK:11,SNR1: 1.4405 ,SNR2: 4.6306





2152+450 2025/05/24 20.58UT TOYOKAWA-KISO









BLK:20,SNR1: 1.8678 ,SNR2: 4.1618





BLK:20,SNR1: 1.3241 ,SNR2: 4.2782




2152+450 2025/05/24 20.58UT FUJI -KISO




T20250525054148




BLK: 4, SNR1: 0.28601 , SNR2: 9.3517




F20250525054149





BLK: 4, SNR1: 1.2585 , SNR2: 6.4337




2200+420 2025/05/24 20.72UT TOYOKAWA-FUJI




T20250525054148




BLK: 6,SNR1: 37.593 ,SNR2: 181.77




K20250525054145




BLK: 6,SNR1: 0.57509 ,SNR2: 6.1052




2200+420 2025/05/24 20.72UT TOYOKAWA-KISO



F20250525054149




BLK: 3,SNR1: 0.50260 ,SNR2: 7.3428





2200+420 2025/05/24 20.72UT FUJI -KISO



K20250525054145




BLK: 3,SNR1: 0.18886 ,SNR2: 2.4356




T20250525054829




BLK: 7,SNR1: 0.14443 ,SNR2: 1.0370




F20250525054830





BLK: 7,SNR1: 0.98246 ,SNR2: 4.5606




2207+374 2025/05/24 20.84UT TOYOKAWA-FUJI





T20250525054829




BLK: 6,SNR1: 0.16994E-01,SNR2: 0.75512




K20250525054826




BLK: 6,SNR1: 0.62395 ,SNR2: 2.2094




2207+374 2025/05/24 20.84UT TOYOKAWA-KISO





F20250525054830




BLK:11,SNR1: 2.1870 ,SNR2: 6.5596




K20250525054826





BLK:11,SNR1: 0.86046 ,SNR2: 2.9364




2207+374 2025/05/24 20.84UT FUJI -KISO





T20250525060825




BLK: 2,SNR1: 0.29131 ,SNR2: 0.71330




F20250525060826



BLK: 2,SNR1: 1.5851 ,SNR2: 4.4072





2227+444 2025/05/24 21.17UT TOYOKAWA-FUJI







T20250525060825




BLK: 3,SNR1:-0.61318E-01,SNR2: 0.26210




K20250525060822





BLK: 3,SNR1: 9.8344 ,SNR2: 19.009




2227+444 2025/05/24 21.17UT TOYOKAWA-KISO




F20250525060826




BLK: 5, SNR1: 1.2785 , SNR2: 4.6981




K20250525060822




BLK: 5, SNR1: 7.9452 , SNR2: 22.905




2227+444 2025/05/24 21.17UT FUJI -KISO




T20250525062034




BLK:10,SNR1: 5.2541 ,SNR2: 14.316




F20250525062035




BLK:10,SNR1: 1.1245 ,SNR2: 3.2752




2239+333 2025/05/24 21.37UT TOYOKAWA-FUJI




T20250525062034




BLK:10,SNR1: 12.445 ,SNR2: 44.364




K20250525062031




BLK:10,SNR1: 0.99618 ,SNR2: 3.1530




2239+333 2025/05/24 21.37UT TOYOKAWA-KISO




F20250525062035




BLK:12,SNR1: 1.0168 ,SNR2: 3.2207




K20250525062031





BLK:12,SNR1: 0.51153 ,SNR2: 1.8524




2239+333 2025/05/24 21.37UT FUJI -KISO




T20250525062451




BLK: 3,SNR1: 0.17014 ,SNR2: 0.95696




F20250525062452





BLK: 3,SNR1: 0.12862 ,SNR2: 2.0869




2243+394 2025/05/24 21.44UT TOYOKAWA-FUJI





T20250525062451




BLK:11,SNR1: 0.85301 ,SNR2: 2.9387




K20250525062448




BLK:11,SNR1: 0.72238 ,SNR2: 2.2173




2243+394 2025/05/24 21.44UT TOYOKAWA-KISO





F20250525062452




BLK: 7,SNR1: 0.30803 ,SNR2: 2.3864




K20250525062448



BLK: 7,SNR1: 0.37611 ,SNR2: 1.4772





2243+394 2025/05/24 21.44UT FUJI -KISO








T20250525063305




BLK: 7,SNR1: 0.21099 ,SNR2: 0.85312




F20250525063305





BLK: 7,SNR1: 1.7199 ,SNR2: 4.9426




3C454.3 2025/05/24 21.58UT TOYOKAWA-FUJI




T20250525063305




BLK:14,SNR1: 0.24652 ,SNR2: 2.5881




K20250525063302





BLK:14,SNR1: 1.9195 ,SNR2: 4.0179




3C454.3 2025/05/24 21.58UT TOYOKAWA-KISO




F20250525063305




BLK: 8, SNR1: 1.7381 , SNR2: 5.2687




K20250525063302





BLK: 8, SNR1: 2.1524 , SNR2: 6.6285




3C454.3 2025/05/24 21.58UT FUJI -KISO





T20250525064048




BLK:10,SNR1: 0.68172 ,SNR2: 2.6866




F20250525064049




BLK:10,SNR1: 6.5770 ,SNR2: 16.683





2259+481 2025/05/24 21.71UT TOYOKAWA-FUJI







BLK: 6,SNR1: 0.45251 ,SNR2: 1.2246




BLK: 6,SNR1: 1.9557 ,SNR2: 6.9738





2259+481 2025/05/24 21.71UT TOYOKAWA-KISO







BLK: 4,SNR1: 0.86994 ,SNR2: 2.4698





BLK: 4,SNR1: 1.6045 ,SNR2: 5.8223




2259+481 2025/05/24 21.71UT FUJI -KISO




T20250525065542




BLK: 5, SNR1: 0.47290 , SNR2: 7.1375




F20250525065542




BLK: 5, SNR1: 0.77445 , SNR2: 4.4479





3C459 2025/05/24 21.96UT TOYOKAWA-FUJI







BLK: 4, SNR1: 20.589 , SNR2: 78.657



BLK: 4, SNR1: 0.59655 , SNR2: 1.9142





3C459 2025/05/24 21.96UT TOYOKAWA-KISO







F20250525065542




BLK: 3,SNR1: 0.81441E-01,SNR2: 0.97833




K20250525065539




BLK: 3,SNR1: 0.20809 ,SNR2: 1.6357





3C459 2025/05/24 21.96UT FUJI -KISO







BLK: 6,SNR1: 0.90892 ,SNR2: 1.7444




BLK: 6,SNR1: 2.6429 ,SNR2: 5.9560





2325+269 2025/05/24 22.15UT TOYOKAWA-FUJI







BLK: 5, SNR1: 1.5874 , SNR2: 4.6845




BLK: 5, SNR1: 3.9990 , SNR2: 11.439




2325+269 2025/05/24 22.15UT TOYOKAWA-KISO




F20250525070702




BLK: 5, SNR1: 1.7468 ,SNR2: 4.1101




K20250525070659







BLK: 5, SNR1: 4.4395 ,SNR2: 12.912




2325+269 2025/05/24 22.15UT FUJI -KISO







2347-02 2025/05/24 22.52UT TOYOKAWA-FUJI



T20250525072927





BLK: 6, SNR1: 2.4188 , SNR2: 5.4492





2347-02 2025/05/24 22.52UT TOYOKAWA-KISO


K20250525072924




BLK: 6, SNR1: 7.1451 , SNR2: 19.574





F20250525072928




BLK: 4, SNR1: 6.6428 , SNR2: 17.965




K20250525072924





BLK: 4, SNR1: 8.9303 , SNR2: 23.576




2347-02 2025/05/24 22.52UT FUJI -KISO





T20250525073620




BLK: 9,SNR1: 2.4877 ,SNR2: 6.3075




F20250525073620



BLK: 9,SNR1: 2.5335 ,SNR2: 7.5719





2354+14 2025/05/24 22.63UT TOYOKAWA-FUJI






T20250525073620




BLK: 6, SNR1: 6.6991 , SNR2: 18.467





2354+14 2025/05/24 22.63UT TOYOKAWA-KISO


K20250525073617




BLK: 6, SNR1: 7.6547 , SNR2: 19.931




F20250525073620




BLK: 5, SNR1: 14.271 , SNR2: 34.692




K20250525073617





BLK: 5, SNR1: 10.876 , SNR2: 26.781




2354+14 2025/05/24 22.63UT FUJI -KISO





T20250525074523




BLK: 6,SNR1: 0.31717 ,SNR2: 1.2830




F20250525074524




BLK: 6,SNR1: 0.83870 ,SNR2: 2.3952




3C2 2025/05/24 22.78UT TOYOKAWA-FUJI





T20250525074523




BLK: 8, SNR1: 0.36993 , SNR2: 1.2447




K20250525074520




BLK: 8, SNR1: 7.9383 , SNR2: 22.959




3C2 2025/05/24 22.78UT TOYOKAWA-KISO





F20250525074524




BLK: 6,SNR1: 1.7712 ,SNR2: 5.5274




K20250525074520




BLK: 6,SNR1: 8.1040 ,SNR2: 23.433




3C2 2025/05/24 22.78UT FUJI -KISO





T20250525075245




BLK:16,SNR1: 0.81597 ,SNR2: 3.1370




F20250525075245




BLK:16,SNR1: 0.81114 ,SNR2: 1.8929




0011+344 2025/05/24 22.91UT TOYOKAWA-FUJI





T20250525075245




BLK:10,SNR1: 0.84991 ,SNR2: 3.7033




K20250525075242




BLK:10,SNR1: 0.62559E-01,SNR2: 1.0350




0011+344 2025/05/24 22.91UT TOYOKAWA-KISO



F20250525075245




BLK:16,SNR1: 1.3940 ,SNR2: 4.6740





0011+344 2025/05/24 22.91UT FUJI -KISO





K20250525075242




BLK:16,SNR1: 0.41164 ,SNR2: 1.8998












0019-00 2025/05/24 23.05UT TOYOKAWA-FUJI








0019-00 2025/05/24 23.05UT TOYOKAWA-KISO





F20250525080121




BLK: 4, SNR1: 11.399 , SNR2: 33.008




K20250525080118







BLK: 4, SNR1: 8.3201 , SNR2: 23.648




0019-00 2025/05/24 23.05UT FUJI -KISO








3C12 2025/05/24 23.22UT TOYOKAWA-FUJI




T20250525081136




BLK: 4, SNR1: 8.1469 , SNR2: 20.825




K20250525081133




BLK: 4, SNR1: 11.084 , SNR2: 35.618




3C12 2025/05/24 23.22UT TOYOKAWA-KISO



F20250525081136




BLK: 4, SNR1: 13.666 , SNR2: 36.768





3C12 2025/05/24 23.22UT FUJI -KISO


K20250525081133




BLK: 4, SNR1: 9.8761 , SNR2: 25.998




T20250525082537




BLK:10,SNR1: 10.001 ,SNR2: 17.780




F20250525082537





BLK:10,SNR1: 3.6317 ,SNR2: 9.7941




0044-056 2025/05/24 23.46UT TOYOKAWA-FUJI





T20250525082537




BLK:12,SNR1: 8.5627 ,SNR2: 22.042




K20250525082534



BLK:12,SNR1: 6.2666 ,SNR2: 14.303





0044-056 2025/05/24 23.46UT TOYOKAWA-KISO








F20250525082537




BLK: 8, SNR1: 6.5245 , SNR2: 18.902




K20250525082534




BLK: 8, SNR1: 6.1992 , SNR2: 14.153




0044-056 2025/05/24 23.46UT FUJI -KISO




T20250525083258




BLK: 9, SNR1: 7.0538 , SNR2: 16.586




F20250525083259












BLK: 9, SNR1: 7.1735 , SNR2: 18.716




3C26 2025/05/24 23.58UT TOYOKAWA-FUJI










3C26 2025/05/24 23.58UT FUJI -KISO









BLK: 8,SNR1: 1.3620 ,SNR2: 3.6278




BLK: 8,SNR1: 0.57730 ,SNR2: 1.6566



T20250525083757




BLK:11,SNR1: 2.7717 ,SNR2: 6.3343









0056-00 2025/05/24 23.66UT TOYOKAWA-KISO

K20250525083755








BLK:11,SNR1: 0.36603 ,SNR2: 1.9870






0056-00 2025/05/24 23.66UT FUJI -KISO






0106+01 2025/05/24 23.82UT TOYOKAWA-FUJI







T20250525084739




BLK: 6, SNR1: 8.3201 , SNR2: 21.093




K20250525084736








BLK: 6, SNR1: 6.7792 , SNR2: 18.360





0106+01 2025/05/24 23.82UT TOYOKAWA-KISO








T20250525091002




BLK: 7, SNR1: 3.8556 , SNR2: 9.9255




F20250525091003




BLK: 7, SNR1: 6.5261 , SNR2: 17.897




0128+03 2025/05/25 0.20UT TOYOKAWA-FUJI




T20250525091002




BLK: 5, SNR1: 3.0964 , SNR2: 8.1327




K20250525090959








BLK: 5, SNR1: 6.4257 , SNR2: 19.229




0128+03 2025/05/25 0.20UT TOYOKAWA-KISO






T20250525091636




BLK:25,SNR1: 3.4106 ,SNR2: 15.961









3C48 2025/05/25 0.30UT TOYOKAWA-FUJI

F20250525091636









BLK:25,SNR1: 0.60792 ,SNR2: 2.6774















3C48 2025/05/25 0.30UT TOYOKAWA-KISO





















0155-109 2025/05/25 0.63UT FUJI -KISO





T20250525094327




BLK: 8, SNR1: 8.7783 , SNR2: 22.404




F20250525094327





BLK: 8, SNR1: 6.8920 , SNR2: 18.887




0202+15 2025/05/25 0.75UT TOYOKAWA-FUJI





T20250525094327




BLK:10,SNR1: 11.565 ,SNR2: 29.128




K20250525094324





BLK:10,SNR1: 8.1024 ,SNR2: 23.433




0202+15 2025/05/25 0.75UT TOYOKAWA-KISO





F20250525094327




BLK: 3, SNR1: 6.7845 , SNR2: 19.595




K20250525094324




BLK: 3, SNR1: 7.8195 , SNR2: 20.412





0202+15 2025/05/25 0.75UT FUJI -KISO







BLK:15,SNR1: 3.2109 ,SNR2: 9.8313




BLK:15,SNR1: 1.9625 ,SNR2: 6.3635





0213+178 2025/05/25 0.95UT TOYOKAWA-FUJI







BLK:17,SNR1: 3.2054 ,SNR2: 9.8117



BLK:17,SNR1: 9.5069 ,SNR2: 21.004





0213+178 2025/05/25 0.95UT TOYOKAWA-KISO








F20250525095518




BLK:24,SNR1: 3.1524 ,SNR2: 9.5793




K20250525095515













BLK:24,SNR1: 9.4832 ,SNR2: 20.948




0213+178 2025/05/25 0.95UT FUJI -KISO










F20250525100301




BLK: 9,SNR1: 0.38592 ,SNR2: 1.6393




K20250525100257




BLK: 9,SNR1: 0.50637 ,SNR2: 2.1165




3C67 2025/05/25 1.08UT FUJI -KISO



T20250525102115




BLK: 9,SNR1: 10.803 ,SNR2: 23.403










3C71 2025/05/25 1.38UT TOYOKAWA-FUJI






F20250525102115







BLK: 9,SNR1: 12.090 ,SNR2: 27.590



















0258+350 2025/05/25 1.70UT TOYOKAWA-FUJI




















0258+350 2025/05/25 1.70UT FUJI -KISO












0308+305 2025/05/25 1.87UT TOYOKAWA-KISO









0308+305 2025/05/25 1.87UT FUJI -KISO




T20250525110151





F20250525110151





0320+05 2025/05/25 2.06UT TOYOKAWA-FUJI







0320+05 2025/05/25 2.06UT TOYOKAWA-KISO







BLK: 6,SNR1: 0.21343 ,SNR2: 2.1398



BLK: 6,SNR1: 4.2821 ,SNR2: 13.376





0320+05 2025/05/25 2.06UT FUJI -KISO







T20250525111512




BLK:24,SNR1: 1.8482 ,SNR2: 3.1664




F20250525111512





BLK:24,SNR1: 2.8668 ,SNR2: 7.0981




0333+32 2025/05/25 2.28UT TOYOKAWA-FUJI





T20250525111512




BLK:24,SNR1: 1.8703 ,SNR2: 3.2281




K20250525111509




BLK:24,SNR1: 3.1514 ,SNR2: 8.0354




0333+32 2025/05/25 2.28UT TOYOKAWA-KISO





F20250525111512




BLK:30,SNR1: 4.0039 ,SNR2: 9.1216




K20250525111509





BLK:30,SNR1: 3.1860 ,SNR2: 11.635




0333+32 2025/05/25 2.28UT FUJI -KISO




T20250525112814




BLK:16,SNR1: 1.8099 ,SNR2: 5.5512




F20250525112814





BLK:16,SNR1: 2.4409 ,SNR2: 6.6098




0347+05 2025/05/25 2.50UT TOYOKAWA-FUJI




T20250525112814




BLK:11,SNR1: 3.6729 ,SNR2: 9.5746




K20250525112811







BLK:11,SNR1: 5.7696 ,SNR2: 14.837








0347+05 2025/05/25 2.50UT TOYOKAWA-KISO







0347+05 2025/05/25 2.50UT FUJI -KISO







0403-132 2025/05/25 2.76UT TOYOKAWA-FUJI







BLK:33,SNR1: 5.0530 ,SNR2: 13.254




BLK:33,SNR1: 1.0496 ,SNR2: 6.1146





0403-132 2025/05/25 2.76UT TOYOKAWA-KISO









BLK: 6,SNR1: -0.69433E-01,SNR2: 1.1332




BLK: 6,SNR1: 0.47988 ,SNR2: 5.3230





0403-132 2025/05/25 2.76UT FUJI -KISO







BLK: 8,SNR1: 0.67279 ,SNR2: 2.9707




BLK: 8,SNR1:-0.11478 ,SNR2: 1.0032





0411+05 2025/05/25 2.91UT TOYOKAWA-FUJI







BLK:12,SNR1: 0.85006 ,SNR2: 2.4225




BLK:12,SNR1: 0.43175 ,SNR2: 1.9936




0411+05 2025/05/25 2.91UT TOYOKAWA-KISO




F20250525115259




BLK: 5,SNR1: -0.34140E-01,SNR2: 0.87316




K20250525115256




BLK: 5,SNR1: 0.23096 ,SNR2: 1.1279




0411+05 2025/05/25 2.91UT FUJI -KISO




T20250525120352




BLK:13,SNR1: 0.27948 ,SNR2: 1.1349




F20250525120352




BLK:13,SNR1: 2.3683 ,SNR2: 6.3733




0422+178 2025/05/25 3.09UT TOYOKAWA-FUJI





T20250525120352




BLK:10,SNR1: 0.32233 ,SNR2: 3.0360




K20250525120349




BLK:10,SNR1: 0.48292 ,SNR2: 1.8472




0422+178 2025/05/25 3.09UT TOYOKAWA-KISO




F20250525120352




BLK:12,SNR1: 2.3268 ,SNR2: 6.3108




K20250525120349




BLK:12,SNR1: 0.26216 ,SNR2: 1.0613




0422+178 2025/05/25 3.09UT FUJI -KISO




T20250525121121




BLK:25,SNR1: 11.814 ,SNR2: 39.303




F20250525121121



BLK:25,SNR1: 0.87918 ,SNR2: 5.9222





3C119 2025/05/25 3.22UT TOYOKAWA-FUJI







T20250525121121




BLK:38,SNR1: 10.772 ,SNR2: 35.824




K20250525121118




BLK:38,SNR1: 2.3266 ,SNR2: 9.2939




3C119 2025/05/25 3.22UT TOYOKAWA-KISO




F20250525121121




BLK:23,SNR1: 0.94519 ,SNR2: 6.0030




K20250525121118




BLK:23,SNR1: 2.3581 ,SNR2: 9.5211





3C119 2025/05/25 3.22UT FUJI -KISO







BLK:21,SNR1: 11.185 ,SNR2: 47.085




BLK:21,SNR1: 0.48075E-02,SNR2: 1.8301





3C138 2025/05/25 4.02UT TOYOKAWA-FUJI







BLK:23,SNR1: 9.5550 ,SNR2: 41.931




BLK:23,SNR1: 0.81284 ,SNR2: 3.4735




3C138 2025/05/25 4.02UT TOYOKAWA-KISO




F20250525125929




BLK:28,SNR1: 0.12515E-01,SNR2: 1.8665




K20250525125925





BLK:28,SNR1: 0.80319 ,SNR2: 3.5820




3C138 2025/05/25 4.02UT FUJI -KISO





T20250525131301




BLK:25,SNR1: 5.1156 ,SNR2: 28.804




F20250525131301




BLK:25,SNR1: 0.18232 ,SNR2: 2.7965





0531+194 2025/05/25 4.25UT TOYOKAWA-FUJI







BLK:29,SNR1: 4.7824 ,SNR2: 27.675




BLK:29,SNR1: 0.65074 ,SNR2: 1.8421




0531+194 2025/05/25 4.25UT TOYOKAWA-KISO





F20250525131301




BLK:28,SNR1: 0.20316 ,SNR2: 2.4704




K20250525131259



BLK:28,SNR1: 0.74062 ,SNR2: 3.1855





0531+194 2025/05/25 4.25UT FUJI -KISO







T20250525132122




BLK:36,SNR1: 11.030 ,SNR2: 68.010




F20250525132122





BLK:36,SNR1: 0.63284 ,SNR2: 7.6059




3C147 2025/05/25 4.38UT TOYOKAWA-FUJI





T20250525132122




BLK:37,SNR1: 11.110 ,SNR2: 68.502




K20250525132119




BLK:37,SNR1: 2.2078 ,SNR2: 15.460




3C147 2025/05/25 4.38UT TOYOKAWA-KISO




F20250525132122




BLK:26,SNR1: 0.66356 ,SNR2: 7.5243




K20250525132119




BLK:26,SNR1: 2.3473 ,SNR2: 15.871





3C147 2025/05/25 4.38UT FUJI -KISO







BLK:11,SNR1: 0.70268 ,SNR2: 2.6381





BLK:11,SNR1: 11.047 ,SNR2: 26.163




0548+16 2025/05/25 4.52UT TOYOKAWA-FUJI




T20250525132932




BLK:10,SNR1: 0.78551 ,SNR2: 3.3919




K20250525132929




BLK:10,SNR1: 0.42498 ,SNR2: 1.7411





0548+16 2025/05/25 4.52UT TOYOKAWA-KISO







BLK: 9,SNR1: 11.384 ,SNR2: 26.962







BLK: 9,SNR1: 0.57498 ,SNR2: 2.2261





0548+16 2025/05/25 4.52UT FUJI -KISO







0552+12 2025/05/25 4.59UT TOYOKAWA-FUJI







BLK:12,SNR1: 7.4297 ,SNR2: 55.990








BLK:12,SNR1: 0.16850E-01,SNR2: 1.1549





0552+12 2025/05/25 4.59UT TOYOKAWA-KISO










T20250525133810




BLK: 4,SNR1: 0.22924 ,SNR2: 2.4780




F20250525133810




BLK: 4,SNR1:-0.11322E-01,SNR2: 1.0772





0556+191 2025/05/25 4.66UT TOYOKAWA-FUJI







BLK: 8,SNR1: 0.29280 ,SNR2: 1.9008





BLK: 8,SNR1: 0.43266 ,SNR2: 3.2183




0556+191 2025/05/25 4.66UT TOYOKAWA-KISO





F20250525133810




BLK: 4,SNR1: 0.64537 ,SNR2: 2.3932




K20250525133808





BLK: 4,SNR1: 0.81382 ,SNR2: 5.1815




0556+191 2025/05/25 4.66UT FUJI -KISO





T20250525134555




BLK: 6,SNR1: 0.57653E-01,SNR2: 1.1159




F20250525134556




BLK: 6,SNR1: 0.74119 ,SNR2: 2.3835





0605-08 2025/05/25 4.79UT TOYOKAWA-FUJI







BLK: 6,SNR1: 0.15461 ,SNR2: 0.53558




BLK: 6,SNR1: 0.91012 ,SNR2: 3.9755





0605-08 2025/05/25 4.79UT TOYOKAWA-KISO








BLK: 6,SNR1: 0.30736 ,SNR2: 3.2618




BLK: 6,SNR1: 0.48975 ,SNR2: 1.9601




T20250525140503




BLK:18,SNR1: 2.5129 ,SNR2: 6.4250




F20250525140503



BLK:18,SNR1: 1.2716 ,SNR2: 3.9708




3C161 2025/05/25 5.11UT TOYOKAWA-FUJI








T20250525140503




BLK:28,SNR1: 1.9251 ,SNR2: 4.6198




K20250525140500




BLK:28,SNR1: 5.6619 ,SNR2: 14.738




3C161 2025/05/25 5.11UT TOYOKAWA-KISO




F20250525140503




BLK:10,SNR1: 1.0925 ,SNR2: 3.4781




K20250525140500




BLK:10,SNR1: 3.4053 ,SNR2: 6.7669





3C161 2025/05/25 5.11UT FUJI -KISO







BLK: 6,SNR1: 6.1712 ,SNR2: 11.117





BLK: 6,SNR1: 3.4446 ,SNR2: 8.0412




0652-130 2025/05/25 5.57UT TOYOKAWA-FUJI



T20250525143236





BLK:14,SNR1: 9.4864 ,SNR2: 16.953




Frequency (Hz)

K20250525143233









BLK:14,SNR1: 7.9368 ,SNR2: 14.185




Frequency (Hz)



0652-130 2025/05/25 5.57UT TOYOKAWA-KISO









BLK:10,SNR1: 3.8101 ,SNR2: 12.564




BLK:10,SNR1: 6.2811 ,SNR2: 20.997





0703+138 2025/05/25 5.77UT TOYOKAWA-FUJI







BLK: 6,SNR1: 16.273 ,SNR2: 26.047




BLK: 6,SNR1: 3.1359 ,SNR2: 9.7258






0703+138 2025/05/25 5.77UT TOYOKAWA-KISO




F20250525144413




K20250525144411





0703+138 2025/05/25 5.77UT FUJI -KISO









BLK: 4,SNR1: 8.4533 ,SNR2: 20.633





BLK: 4,SNR1: 5.4158 ,SNR2: 13.185




0713-024 2025/05/25 5.92UT TOYOKAWA-FUJI





T20250525145335




BLK: 3,SNR1: 7.9164 ,SNR2: 19.692




K20250525145332




BLK: 3,SNR1: 6.7862 ,SNR2: 16.168





0713-024 2025/05/25 5.92UT TOYOKAWA-KISO







BLK: 3,SNR1: 5.4299 ,SNR2: 12.489




BLK: 3,SNR1: 3.1639 ,SNR2: 10.249





0713-024 2025/05/25 5.92UT FUJI -KISO







BLK: 3,SNR1: 6.4416 ,SNR2: 17.557




BLK: 3,SNR1: 12.678 ,SNR2: 22.516





0723+10 2025/05/25 6.09UT TOYOKAWA-FUJI







BLK: 2,SNR1: 1.9085 ,SNR2: 8.1552




BLK: 2,SNR1: 2.1994 ,SNR2: 10.192




0723+10 2025/05/25 6.09UT TOYOKAWA-KISO




F20250525150347




BLK: 6,SNR1: 10.676 ,SNR2: 18.986




K20250525150345




BLK: 6,SNR1: 9.5833 ,SNR2: 17.037





0723+10 2025/05/25 6.09UT FUJI -KISO







BLK:11,SNR1: 8.1863 ,SNR2: 24.917




BLK:11,SNR1: 5.0740 ,SNR2: 14.283





0732+33 2025/05/25 6.26UT TOYOKAWA-FUJI







BLK:18,SNR1: 6.0611 ,SNR2: 10.604




BLK:18,SNR1: 7.3301 ,SNR2: 12.951





0732+33 2025/05/25 6.26UT TOYOKAWA-KISO










BLK:14,SNR1: 5.6287 ,SNR2: 13.757




BLK:14,SNR1: 8.8906 ,SNR2: 15.673




T20250525152203




BLK: 8,SNR1: 0.32322 ,SNR2: 2.0579




F20250525152203





BLK: 8,SNR1: 1.6951 ,SNR2: 4.4236




0741-06 2025/05/25 6.40UT TOYOKAWA-FUJI




T20250525152203




BLK: 6,SNR1: 0.43798 ,SNR2: 2.1963




K20250525152200




BLK: 6,SNR1: 9.5159 ,SNR2: 22.805




0741-06 2025/05/25 6.40UT TOYOKAWA-KISO




F20250525152203




BLK: 2,SNR1: 3.4253 ,SNR2: 6.6649




K20250525152200




BLK: 2,SNR1: 6.1822 ,SNR2: 16.467




0741-06 2025/05/25 6.40UT FUJI -KISO





T20250525153148




BLK: 2,SNR1: 0.15205E-01,SNR2: 1.1511




F20250525153148




BLK: 2,SNR1: 0.39882 ,SNR2: 1.4672





0752-200 2025/05/25 6.56UT TOYOKAWA-FUJI







BLK: 3,SNR1: 0.25474 ,SNR2: 1.1881









BLK: 3,SNR1: 5.6876 ,SNR2: 11.068





0752-200 2025/05/25 6.56UT TOYOKAWA-KISO










BLK: 5,SNR1: 18.679 ,SNR2: 32.801





BLK: 5,SNR1: 8.8224 ,SNR2: 21.751









BLK: 4,SNR1: 11.147 ,SNR2: 27.260









BLK: 4,SNR1: 11.032 ,SNR2: 27.026





3C190 2025/05/25 6.68UT TOYOKAWA-KISO









BLK:23,SNR1: 8.4764 ,SNR2: 25.018




BLK:23,SNR1: 8.7405 ,SNR2: 23.408





3C196 2025/05/25 6.89UT TOYOKAWA-FUJI







BLK:27,SNR1: 7.5128 ,SNR2: 21.528




BLK:27,SNR1: 10.824 ,SNR2: 25.708





3C196 2025/05/25 6.89UT TOYOKAWA-KISO







BLK:28,SNR1: 9.8312 ,SNR2: 24.052




BLK:28,SNR1: 11.345 ,SNR2: 20.158





3C196 2025/05/25 6.89UT FUJI -KISO







BLK: 3,SNR1: 9.9573 ,SNR2: 29.572




BLK: 3,SNR1: 19.772 ,SNR2: 24.865





0821+394 2025/05/25 7.08UT TOYOKAWA-FUJI







BLK: 6, SNR1: 4.4282 , SNR2: 17.099








BLK: 6, SNR1: 15.816 , SNR2: 24.158







0821+394 2025/05/25 7.08UT TOYOKAWA-KISO



















0834-19 2025/05/25 7.27UT TOYOKAWA-FUJI










T20250525161942




BLK:20,SNR1: 6.4126 ,SNR2: 11.384




F20250525161943





BLK:20,SNR1: 6.6398 ,SNR2: 18.065







0839-071 2025/05/25 7.36UT TOYOKAWA-FUJI







0839-071 2025/05/25 7.36UT TOYOKAWA-KISO






T20250525163044





BLK: 9, SNR1: 15.933 , SNR2: 37.724




Frequency (Hz)

F20250525163044





BLK: 9, SNR1: 8.5935 , SNR2: 22.139





Frequency (Hz)

3C208 2025/05/25 7.54UT TOYOKAWA-FUJI







BLK:12,SNR1: 15.201 ,SNR2: 36.430




BLK:12,SNR1: 8.4171 ,SNR2: 22.302





3C208 2025/05/25 7.54UT TOYOKAWA-KISO









BLK: 8,SNR1: 10.045 ,SNR2: 17.587






BLK: 8,SNR1: 8.3370 ,SNR2: 22.090




3C208 2025/05/25 7.54UT FUJI -KISO






T20250525164725




BLK: 2, SNR1: 3.9065 , SNR2: 9.8084




Frequency (Hz)

K20250525164722









BLK: 2, SNR1: 1.4151 , SNR2: 7.5789







Frequency (Hz)


3C216 2025/05/25 7.82UT TOYOKAWA-KISO










0926+117 2025/05/25 8.13UT TOYOKAWA-FUJI







BLK: 5, SNR1: 10.116 , SNR2: 23.357




BLK: 5, SNR1: 10.642 , SNR2: 24.220





0926+117 2025/05/25 8.13UT TOYOKAWA-KISO







BLK: 5, SNR1: 7.3294 , SNR2: 18.579




BLK: 5, SNR1: 10.700 , SNR2: 23.980





0926+117 2025/05/25 8.13UT FUJI -KISO







BLK: 4, SNR1: 0.43408 , SNR2: 2.6220




BLK: 4, SNR1: 3.2759 , SNR2: 13.593





3C236 2025/05/25 8.75UT TOYOKAWA-FUJI









BLK: 4, SNR1: 0.49680 , SNR2: 2.6835




BLK: 4, SNR1: 7.8597 , SNR2: 12.692





3C236 2025/05/25 8.75UT TOYOKAWA-KISO






BLK: 2, SNR1: 3.7431 , SNR2: 17.630



BLK: 2, SNR1: 16.618 , SNR2: 26.633



3C236 2025/05/25 8.75UT FUJI -KISO

