














0552+12 2025/06/02 4.07UT TOYOKAWA-KISO





F20250602130216




BLK: 3, SNR1: 9.2178 , SNR2: 22.735




K20250602130213






BLK: 3, SNR1: 8.8267 , SNR2: 22.069







0552+12 2025/06/02 4.07UT FUJI -KISO















BLK: 4,SNR1: 3.5898 ,SNR2: 16.003





BLK: 4,SNR1: 0.17454 ,SNR2: 1.2890







0556+191 2025/06/02 4.14UT FUJI -KISO







0605-08 2025/06/02 4.27UT TOYOKAWA-FUJI








F20250602131428




BLK: 7, SNR1: 2.1398 , SNR2: 10.062




K20250602131425




BLK: 7, SNR1: 17.022 , SNR2: 29.752




0605-08 2025/06/02 4.27UT FUJI -KISO








BLK: 2, SNR1: 20.425 , SNR2: 47.362




F20250602133336




BLK: 2, SNR1: 9.8865 , SNR2: 30.751






3C161 2025/06/02 4.59UT TOYOKAWA-FUJI







BLK: 3, SNR1: 9.6350 , SNR2: 27.858




BLK: 3, SNR1: 8.8084 , SNR2: 25.279




3C161 2025/06/02 4.59UT TOYOKAWA-KISO





F20250602133336




BLK: 5, SNR1: 11.362 , SNR2: 25.510




K20250602133334








BLK: 5, SNR1: 32.098 , SNR2: 37.039








3C161 2025/06/02 4.59UT FUJI -KISO













F20250602140109




BLK: 5, SNR1: 10.465 ,SNR2: 25.663




K20250602140106





BLK: 5, SNR1: 13.351 ,SNR2: 32.406




0652-130 2025/06/02 5.05UT FUJI -KISO




T20250602141247




BLK: 3,SNR1: 0.29779E-01,SNR2: 0.29541




F20250602141246





BLK: 3,SNR1: 3.4779 ,SNR2: 7.7697




0703+138 2025/06/02 5.24UT TOYOKAWA-FUJI





T20250602141247




BLK: 5, SNR1: -0.24609E-01, SNR2: 0.49249




K20250602141243





BLK: 5, SNR1: 0.98810, SNR2: 6.4491




0703+138 2025/06/02 5.24UT TOYOKAWA-KISO





F20250602141246




BLK: 5, SNR1: 1.1483 , SNR2: 6.6785




K20250602141243







BLK: 5, SNR1: 1.1178 , SNR2: 5.3115




0703+138 2025/06/02 5.24UT FUJI -KISO








0713-024 2025/06/02 5.40UT TOYOKAWA-FUJI





T20250602142209




No.Good Data




K20250602142205





No.Good Data




0713-024 2025/06/02 5.40UT TOYOKAWA-KISO










0713-024 2025/06/02 5.40UT FUJI -KISO







BLK: 9,SNR1: 3.2259 ,SNR2: 5.7011










BLK: 9,SNR1:-0.41076E-01,SNR2: 0.79505




0723+10 2025/06/02 5.57UT TOYOKAWA-FUJI








F20250602143220




BLK:11,SNR1: 0.24124 ,SNR2: 1.4985




K20250602143217




BLK:11,SNR1: 1.4832 ,SNR2: 4.5841





0723+10 2025/06/02 5.57UT FUJI -KISO







BLK: 3,SNR1: 0.69281 ,SNR2: 1.8763







BLK: 3,SNR1: 2.4195 ,SNR2: 6.2977




0732+33 2025/06/02 5.74UT TOYOKAWA-FUJI








0732+33 2025/06/02 5.74UT TOYOKAWA-KISO





F20250602144235




BLK: 2, SNR1: 2.2593 , SNR2: 9.0847




K20250602144232









BLK: 2, SNR1: 0.99602E-01, SNR2: 3.5973




0732+33 2025/06/02 5.74UT FUJI -KISO








0741-06 2025/06/02 5.87UT TOYOKAWA-FUJI









BLK:20,SNR1: 0.59383 ,SNR2: 4.1664




BLK:20,SNR1: 0.11795 ,SNR2: 1.4364





0741-06 2025/06/02 5.87UT TOYOKAWA-KISO







BLK: 4, SNR1: 0.56601 , SNR2: 7.8979








BLK: 4, SNR1: 0.21988 , SNR2: 0.82115





0741-06 2025/06/02 5.87UT FUJI -KISO






T20250602150022





BLK: 5, SNR1: 8.9971 , SNR2: 19.772




Frequency (Hz)

K20250602150018









BLK: 5, SNR1: 11.429 , SNR2: 25.986





Frequency (Hz)

0752-200 2025/06/02 6.03UT TOYOKAWA-KISO








T20250602150757




BLK:15,SNR1: 0.22203 ,SNR2: 1.0177




F20250602150756





BLK:15,SNR1: 7.2965 ,SNR2: 22.906




3C190 2025/06/02 6.16UT TOYOKAWA-FUJI





T20250602150757




BLK:20,SNR1: 0.24953 ,SNR2: 1.4283




K20250602150753




BLK:20,SNR1: 11.366 ,SNR2: 21.391




3C190 2025/06/02 6.16UT TOYOKAWA-KISO





F20250602150756




BLK:17,SNR1: 2.5475 ,SNR2: 6.2902




K20250602150753



BLK:17,SNR1: 4.8952 ,SNR2: 11.773





3C190 2025/06/02 6.16UT FUJI -KISO







T20250602152022




BLK: 9,SNR1: 1.7526 ,SNR2: 4.9161




F20250602152021




BLK: 9,SNR1: 250.16 ,SNR2: 735.94




3C196 2025/06/02 6.37UT TOYOKAWA-FUJI





T20250602152022




BLK:13,SNR1: 1.1791 ,SNR2: 2.2932




K20250602152018




BLK:13,SNR1: 0.52944 ,SNR2: 2.5271





3C196 2025/06/02 6.37UT TOYOKAWA-KISO







BLK: 9, SNR1: 86.092 , SNR2: 239.85





BLK: 9, SNR1: 2.0638 , SNR2: 6.1159




3C196 2025/06/02 6.37UT FUJI -KISO




T20250602153132




BLK:15,SNR1: 0.10773 ,SNR2: 1.4371




F20250602153132





BLK:15,SNR1: 691.32 ,SNR2: 2504.3




0821+394 2025/06/02 6.55UT TOYOKAWA-FUJI




T20250602153132




BLK:10,SNR1: 0.15252 ,SNR2: 0.78359




K20250602153128




BLK:10,SNR1: 1.8508 ,SNR2: 3.8479




0821+394 2025/06/02 6.55UT TOYOKAWA-KISO




F20250602153132




BLK:13,SNR1: 540.86 ,SNR2: 1956.9




K20250602153128




BLK:13,SNR1: 0.73532 ,SNR2: 3.5748




0821+394 2025/06/02 6.55UT FUJI -KISO



T20250602154311





BLK: 7, SNR1: 0.51129 , SNR2: 3.5857









0834-19 2025/06/02 6.75UT TOYOKAWA-FUJI

F20250602154310




BLK: 7, SNR1: 5.1752 , SNR2: 24.972










0834-19 2025/06/02 6.75UT TOYOKAWA-KISO










0834-19 2025/06/02 6.75UT FUJI -KISO







BLK: 9, SNR1: 15.314 , SNR2: 183.41





BLK: 9, SNR1: 4.0139 , SNR2: 17.484




0839-071 2025/06/02 6.83UT TOYOKAWA-FUJI



T20250602154816





BLK: 4, SNR1: 10.329 , SNR2: 98.733





0839-071 2025/06/02 6.83UT TOYOKAWA-KISO


K20250602154812




BLK: 4, SNR1: 0.35015 , SNR2: 0.82065




F20250602154815




BLK: 6,SNR1: 11.051 ,SNR2: 23.308




K20250602154812




BLK: 6,SNR1: 0.53501E-01,SNR2: 1.4466




0839-071 2025/06/02 6.83UT FUJI -KISO




T20250602155918




BLK: 4,SNR1: 0.54376E-01,SNR2: 0.69498




F20250602155918





BLK: 4,SNR1: 0.24501 ,SNR2: 4.8544




3C208 2025/06/02 7.02UT TOYOKAWA-FUJI









3C208 2025/06/02 7.02UT TOYOKAWA-KISO




F20250602155918







K20250602155915




3C208 2025/06/02 7.02UT FUJI -KISO










3C216 2025/06/02 7.29UT TOYOKAWA-FUJI










3C216 2025/06/02 7.29UT TOYOKAWA-KISO







3C216 2025/06/02 7.29UT FUJI -KISO



T20250602162810




BLK: 6,SNR1: 5.6576 ,SNR2: 11.667







0919-142 2025/06/02 7.50UT TOYOKAWA-FUJI

F20250602162809




BLK: 6,SNR1:-0.12015 ,SNR2: 2.1753







0919-142 2025/06/02 7.50UT TOYOKAWA-KISO





F20250602162809




BLK: 9, SNR1: -0.17934 , SNR2: 0.90619




K20250602162806





BLK: 9, SNR1: 1.1486 , SNR2: 3.8976




0919-142 2025/06/02 7.50UT FUJI -KISO





T20250602163449




BLK: 7, SNR1: 0.37954 , SNR2: 2.5370




F20250602163448





BLK: 7, SNR1: 3.3356 , SNR2: 6.1102




0926+117 2025/06/02 7.61UT TOYOKAWA-FUJI



T20250602163449





BLK: 6,SNR1: 2.2774 ,SNR2: 9.3716





0926+117 2025/06/02 7.61UT TOYOKAWA-KISO



K20250602163446




BLK: 6,SNR1: 0.56924 ,SNR2: 2.7434





F20250602163448




BLK: 2,SNR1: 0.68238 ,SNR2: 5.3214




K20250602163446



BLK: 2,SNR1: 0.12244E-01,SNR2: 2.7584





0926+117 2025/06/02 7.61UT FUJI -KISO








T20250602164234




BLK: 3, SNR1: 0.18542 , SNR2: 1.4934




F20250602164233





BLK: 3, SNR1: 6.1378 , SNR2: 22.140




3C222 2025/06/02 7.74UT TOYOKAWA-FUJI



T20250602164234





BLK: 7,SNR1: 0.41159 ,SNR2: 1.0795





3C222 2025/06/02 7.74UT TOYOKAWA-KISO


K20250602164230




BLK: 7,SNR1: 0.86726 ,SNR2: 5.5307





F20250602164233




BLK: 4,SNR1: 0.69972E-01,SNR2: 5.3435




K20250602164230







BLK: 4,SNR1: 0.66966E-01,SNR2: 0.51561









3C222 2025/06/02 7.74UT FUJI -KISO






3C230 2025/06/02 7.99UT TOYOKAWA-FUJI







F20250602165756




BLK:11,SNR1: 0.23588 ,SNR2: 2.0857




K20250602165752




BLK:11,SNR1: 5.9692 ,SNR2: 10.524




3C230 2025/06/02 7.99UT FUJI -KISO




T20250602172754




BLK: 3,SNR1: 0.15194 ,SNR2: 1.5029




F20250602172754




BLK: 3,SNR1: 0.49077E-01,SNR2: 0.98036




3C241 2025/06/02 8.49UT TOYOKAWA-FUJI




T20250602172754




BLK: 2, SNR1: 0.21518 , SNR2: 1.5294




K20250602172750



BLK: 2, SNR1: 0.25405 , SNR2: 1.1604




3C241 2025/06/02 8.49UT TOYOKAWA-KISO








F20250602172754




BLK: 3,SNR1: 0.19870 ,SNR2: 2.0882




K20250602172750





BLK: 3,SNR1: 0.19136 ,SNR2: 1.8800




3C241 2025/06/02 8.49UT FUJI -KISO





T20250602174314




BLK: 1,SNR1:-0.60477E-01,SNR2: 0.50434




F20250602174313





BLK: 1,SNR1: 0.30455 ,SNR2: 3.1128




1034+404 2025/06/02 8.75UT TOYOKAWA-FUJI





T20250602174314




BLK: 6,SNR1: 0.38978E-01,SNR2: 0.48598




K20250602174310





BLK: 6,SNR1: 5.2720 ,SNR2: 8.3485




1034+404 2025/06/02 8.75UT TOYOKAWA-KISO





F20250602174313




BLK: 1, SNR1: 0.87564 , SNR2: 8.8168



K20250602174310



BLK: 1, SNR1: 5.7186 , SNR2: 13.571



1034+404 2025/06/02 8.75UT FUJI -KISO

