




T20250616051418





BLK: 4,SNR1: 0.21549 ,SNR2: 0.40901




Frequency (Hz)

F20250616051418





BLK: 4,SNR1: 0.22750 ,SNR2: 3.6689





Frequency (Hz)

2259+481 2025/06/15 20.27UT TOYOKAWA-FUJI







BLK: 2, SNR1: 55.937 , SNR2: 177.49






BLK: 2, SNR1: 0.26064 , SNR2: 0.45993





2259+481 2025/06/15 20.27UT TOYOKAWA-KISO









T20250616052620




BLK: 3,SNR1: 0.16975 ,SNR2: 0.73192




F20250616052620





BLK: 3,SNR1: 0.20169 ,SNR2: 0.81770




2311+469 2025/06/15 20.47UT TOYOKAWA-FUJI





T20250616052620




BLK: 4,SNR1: 0.38961E-01,SNR2: 0.67214




K20250616052618




BLK: 4,SNR1: 0.13511 ,SNR2: 0.61004




2311+469 2025/06/15 20.47UT TOYOKAWA-KISO




F20250616052620




BLK: 6,SNR1: 0.26499 ,SNR2: 4.8397




K20250616052618





BLK: 6,SNR1: 0.16492 ,SNR2: 0.74609




2311+469 2025/06/15 20.47UT FUJI -KISO




T20250616062615




BLK: 1,SNR1: 0.26731E-01,SNR2: 2.6736




F20250616062616





BLK: 1,SNR1: 0.30522 ,SNR2: 3.0452





0011+344 2025/06/15 21.47UT TOYOKAWA-FUJI







BLK: 1,SNR1: 0.98280E-01,SNR2: 0.49780




BLK: 1,SNR1: 0.81680 ,SNR2: 3.3235




0011+344 2025/06/15 21.47UT TOYOKAWA-KISO





F20250616062616




BLK: 2, SNR1: 10.019 , SNR2: 30.381




K20250616062612





BLK: 2, SNR1: 6.4110 , SNR2: 14.701




0011+344 2025/06/15 21.47UT FUJI -KISO





T20250616064506




BLK: 9,SNR1: 1.4527 ,SNR2: 5.0497




F20250616064507



BLK: 9,SNR1: 13.331 ,SNR2: 15.778





3C12 2025/06/15 21.78UT TOYOKAWA-FUJI








T20250616064506




BLK:12,SNR1: 0.53954 ,SNR2: 1.4867




K20250616064503





BLK:12,SNR1: 6.3103 ,SNR2: 14.697




3C12 2025/06/15 21.78UT TOYOKAWA-KISO





F20250616064507




BLK:13,SNR1: 7.9616 ,SNR2: 14.221




K20250616064503







BLK:13,SNR1: 8.0215 ,SNR2: 17.977





3C12 2025/06/15 21.78UT FUJI -KISO







0038+328 2025/06/15 21.92UT TOYOKAWA-FUJI







BLK:16,SNR1: 1.3775 ,SNR2: 5.1205





BLK:16,SNR1: 0.20187 ,SNR2: 1.9739




0038+328 2025/06/15 21.92UT TOYOKAWA-KISO



F20250616065324





BLK: 9, SNR1: 1.0908 , SNR2: 3.6541




Frequency (Hz)

K20250616065322




BLK: 9, SNR1: 0.37848 , SNR2: 3.2263





Frequency (Hz)


0038+328 2025/06/15 21.92UT FUJI -KISO



T20250616070629





BLK:12,SNR1: 0.21114 ,SNR2: 1.9583





3C26 2025/06/15 22.14UT TOYOKAWA-FUJI



F20250616070629




BLK:12,SNR1: 1.5714 ,SNR2: 7.6849



T20250616070629





BLK: 6, SNR1: 2.6151 , SNR2: 10.110





3C26 2025/06/15 22.14UT TOYOKAWA-KISO



K20250616070626




BLK: 6, SNR1: 3.9816 , SNR2: 7.0066



F20250616070629





BLK: 8, SNR1: 2.3326 , SNR2: 7.0391





3C26 2025/06/15 22.14UT FUJI -KISO


K20250616070626





BLK: 8, SNR1: 8.9589 , SNR2: 16.091









BLK: 9,SNR1: 9.5988 ,SNR2: 17.137




BLK: 9,SNR1: 6.8199 ,SNR2: 17.226





0056-00 2025/06/15 22.22UT TOYOKAWA-FUJI







BLK:11,SNR1: 9.3831 ,SNR2: 16.758





BLK:11,SNR1: 8.7725 ,SNR2: 16.057




0056-00 2025/06/15 22.22UT TOYOKAWA-KISO





F20250616071127




BLK: 7,SNR1: 23.720 ,SNR2: 23.755




K20250616071124




BLK: 7,SNR1: 8.4814 ,SNR2: 15.535





0056-00 2025/06/15 22.22UT FUJI -KISO







BLK: 2,SNR1: 14.725 ,SNR2: 26.470





BLK: 2,SNR1: 2.4094 ,SNR2: 11.235




0106+01 2025/06/15 22.38UT TOYOKAWA-FUJI





T20250616072109




BLK: 2, SNR1: 18.527 , SNR2: 32.953




K20250616072107




BLK: 2, SNR1: 8.4354 , SNR2: 20.867




0106+01 2025/06/15 22.38UT TOYOKAWA-KISO





F20250616072109




BLK: 2, SNR1: 12.032 ,SNR2: 29.382




K20250616072107







BLK: 2, SNR1: 9.5047 ,SNR2: 23.380




0106+01 2025/06/15 22.38UT FUJI -KISO







0115-01 2025/06/15 22.54UT TOYOKAWA-FUJI





T20250616073032




BLK: 1, SNR1: 13.397 ,SNR2: 33.101




K20250616073029



BLK: 1, SNR1: 10.498 ,SNR2: 26.050





0115-01 2025/06/15 22.54UT TOYOKAWA-KISO








F20250616073032




BLK: 3, SNR1: 10.618 , SNR2: 26.067




K20250616073029





BLK: 3, SNR1: 7.5866 , SNR2: 18.887




0115-01 2025/06/15 22.54UT FUJI -KISO




T20250616074332




BLK: 2,SNR1: 11.515 ,SNR2: 27.870




F20250616074332





BLK: 2,SNR1: 9.7005 ,SNR2: 23.853




0128+03 2025/06/15 22.75UT TOYOKAWA-FUJI




T20250616074332




BLK: 4,SNR1: 9.4911 ,SNR2: 23.373




K20250616074329




BLK: 4,SNR1: 6.5461 ,SNR2: 16.736




0128+03 2025/06/15 22.75UT TOYOKAWA-KISO




F20250616074332




BLK: 5, SNR1: 6.3022 , SNR2: 19.272




K20250616074329




BLK: 5, SNR1: 7.0901 , SNR2: 17.658




0128+03 2025/06/15 22.75UT FUJI -KISO





T20250616075006




BLK:14,SNR1: 2.0421 ,SNR2: 17.845




F20250616075006






BLK:14,SNR1: 1.3928 ,SNR2: 4.4028




3C48 2025/06/15 22.86UT TOYOKAWA-FUJI






F20250616075006





BLK: 7, SNR1: 0.90643 , SNR2: 2.8857





3C48 2025/06/15 22.86UT FUJI -KISO


K20250616075004




BLK: 7, SNR1: 0.63703 , SNR2: 2.4210




T20250616080950




BLK: 3, SNR1: 5.4254 , SNR2: 13.363




F20250616080950



BLK: 3, SNR1: 4.6032 , SNR2: 12.501




0155-109 2025/06/15 23.19UT TOYOKAWA-FUJI







T20250616080950




BLK: 8, SNR1: 11.553 ,SNR2: 27.839




K20250616080947




BLK: 8, SNR1: 5.9982 ,SNR2: 14.463




0155-109 2025/06/15 23.19UT TOYOKAWA-KISO




F20250616080950




BLK: 5, SNR1: 14.827 , SNR2: 34.534




K20250616080947













BLK: 5, SNR1: 2.1509 , SNR2: 6.3931




0155-109 2025/06/15 23.19UT FUJI -KISO










F20250616081658




BLK:24,SNR1: 8.8315 ,SNR2: 22.136




K20250616081655





BLK:24,SNR1: 12.508 ,SNR2: 22.389




0202+15 2025/06/15 23.31UT FUJI -KISO



T20250616082848





BLK: 3, SNR1: 12.365 , SNR2: 19.755




Frequency (Hz)

F20250616082848




BLK: 3, SNR1: 2.7881 , SNR2: 8.8632




Frequency (Hz)


0213+178 2025/06/15 23.51UT TOYOKAWA-FUJI




T20250616082848




BLK: 3, SNR1: 12.226 , SNR2: 19.227




K20250616082846




BLK: 3, SNR1: 4.8028 , SNR2: 14.093




0213+178 2025/06/15 23.51UT TOYOKAWA-KISO




F20250616082848




BLK: 7,SNR1: 9.5901 ,SNR2: 17.361




K20250616082846



BLK: 7,SNR1: 2.3827 ,SNR2: 7.7943




0213+178 2025/06/15 23.51UT FUJI -KISO








T20250616083630




BLK: 3,SNR1: 1.1092 ,SNR2: 5.4435




F20250616083630




BLK: 3,SNR1: 2.1000 ,SNR2: 5.4426




3C67 2025/06/15 23.64UT TOYOKAWA-FUJI




T20250616083630




BLK: 1, SNR1: 0.69151 , SNR2: 1.9070




K20250616083627





BLK: 1, SNR1: 0.95008 , SNR2: 6.4053




3C67 2025/06/15 23.64UT TOYOKAWA-KISO




F20250616083630




BLK: 2, SNR1: 0.32659 , SNR2: 2.6032




K20250616083627




BLK: 2, SNR1: 0.46952 , SNR2: 3.8097





3C67 2025/06/15 23.64UT FUJI -KISO







BLK:26,SNR1: 18.929 ,SNR2: 37.417





BLK:26,SNR1: 43.036 ,SNR2: 55.299




0239-070 2025/06/15 23.92UT TOYOKAWA-FUJI





T20250616085340




BLK:25,SNR1: 12.930 ,SNR2: 22.489




K20250616085338




BLK:25,SNR1: 16.223 ,SNR2: 28.287




0239-070 2025/06/15 23.92UT TOYOKAWA-KISO





F20250616085341




BLK:28,SNR1: 56.472 ,SNR2: 70.765




K20250616085338





BLK:28,SNR1: 26.204 ,SNR2: 30.430




0239-070 2025/06/15 23.92UT FUJI -KISO




T20250616091401




BLK: 9, SNR1: 43.483 , SNR2: 54.525




F20250616091401





BLK: 9, SNR1: 35.366 , SNR2: 53.316




0258+350 2025/06/16 0.26UT TOYOKAWA-FUJI




T20250616091401




BLK:12,SNR1: 16.760 ,SNR2: 53.684




K20250616091358



BLK:12,SNR1: 35.144 ,SNR2: 47.923




0258+350 2025/06/16 0.26UT TOYOKAWA-KISO







F20250616091401




BLK: 9, SNR1: 6.6355 , SNR2: 14.880




K20250616091358




BLK: 9, SNR1: 29.029 , SNR2: 35.937





0258+350 2025/06/16 0.26UT FUJI -KISO







BLK: 6,SNR1: 3.5375 ,SNR2: 5.6920







BLK: 6,SNR1: 1.7520 ,SNR2: 8.5976




0308+305 2025/06/16 0.43UT TOYOKAWA-FUJI








0308+305 2025/06/16 0.43UT TOYOKAWA-KISO





F20250616092351




BLK:11,SNR1: 7.6196 ,SNR2: 13.877




K20250616092347





BLK:11,SNR1: 14.240 ,SNR2: 18.544




0308+305 2025/06/16 0.43UT FUJI -KISO





T20250616093210




BLK:23,SNR1: 5.6204 ,SNR2: 13.669




F20250616093211






BLK:23,SNR1: 1.0229 ,SNR2: 3.1257






3C84 2025/06/16 0.56UT TOYOKAWA-FUJI




T20250616093210




K20250616093208




3C84 2025/06/16 0.56UT TOYOKAWA-KISO





F20250616093211




BLK:19,SNR1: 1.4854 ,SNR2: 3.6832




K20250616093208





BLK:19,SNR1: 1.9174 ,SNR2: 8.2110




3C84 2025/06/16 0.56UT FUJI -KISO




T20250616093926




BLK: 5,SNR1:-0.20806E-01,SNR2: 0.52671




F20250616093927



BLK: 5,SNR1: 0.99990 ,SNR2: 2.8110





0324+119 2025/06/16 0.69UT TOYOKAWA-FUJI








T20250616093926




BLK: 2,SNR1:-0.32556E-01,SNR2: 0.27585




K20250616093924




BLK: 2,SNR1: 0.62667 ,SNR2: 4.8218




0324+119 2025/06/16 0.69UT TOYOKAWA-KISO





F20250616093927




BLK: 3,SNR1: 0.88734E-01,SNR2: 1.5971




K20250616093924





BLK: 3,SNR1: 0.39167 ,SNR2: 5.3147




0324+119 2025/06/16 0.69UT FUJI -KISO




T20250616094843




BLK:13,SNR1: 28.218 ,SNR2: 49.783




F20250616094844





BLK:13,SNR1: 12.998 ,SNR2: 23.294




0333+32 2025/06/16 0.84UT TOYOKAWA-FUJI





T20250616094843




BLK:18,SNR1: 7.8310 ,SNR2: 14.541




K20250616094840




BLK:18,SNR1: 7.9023 ,SNR2: 19.836




0333+32 2025/06/16 0.84UT TOYOKAWA-KISO





F20250616094844




BLK:11,SNR1: 3.9502 ,SNR2: 12.280




K20250616094840




BLK:11,SNR1: 11.222 ,SNR2: 20.747





0333+32 2025/06/16 0.84UT FUJI -KISO







BLK:17,SNR1: 6.3159 ,SNR2: 9.9059




BLK:17,SNR1: 16.424 ,SNR2: 54.905





0347+05 2025/06/16 1.06UT TOYOKAWA-FUJI







BLK:17,SNR1: 2.7399 ,SNR2: 9.0194








BLK:17,SNR1: 6.1553 ,SNR2: 11.744




0347+05 2025/06/16 1.06UT TOYOKAWA-KISO













BLK: 2,SNR1:−0.47835E−01,SNR2: 0.74869





BLK: 2,SNR1:−0.39217E−01,SNR2: 2.0687




0403−132 2025/06/16 1.32UT TOYOKAWA−FUJI





T20250616101718




BLK:14,SNR1: 0.23152 ,SNR2: 1.8867




K20250616101716




BLK:14,SNR1: 0.39202 ,SNR2: 1.5477




0403-132 2025/06/16 1.32UT TOYOKAWA-KISO





F20250616101718




BLK: 7,SNR1:-0.10534 ,SNR2: 1.5309




K20250616101716





BLK: 7,SNR1: 0.83479 ,SNR2: 2.5219




0403-132 2025/06/16 1.32UT FUJI -KISO





T20250616102629




BLK: 9, SNR1: 0.39587 , SNR2: 2.6154




F20250616102629




BLK: 9, SNR1: 7.5029 , SNR2: 35.097




0411+05 2025/06/16 1.47UT TOYOKAWA-FUJI





T20250616102629




BLK:10,SNR1: 0.50267 ,SNR2: 1.5138




K20250616102626




BLK:10,SNR1: 0.31067E-01,SNR2: 0.52453




0411+05 2025/06/16 1.47UT TOYOKAWA-KISO





F20250616102629




BLK:11,SNR1: 7.5277 ,SNR2: 35.881




K20250616102626





BLK:11,SNR1: 0.14312 ,SNR2: 0.61406




0411+05 2025/06/16 1.47UT FUJI -KISO





T20250616103323




BLK: 3,SNR1: 0.15637 ,SNR2: 0.96332




F20250616103324




BLK: 3,SNR1: 3.4712 ,SNR2: 14.386




0418+236 2025/06/16 1.58UT TOYOKAWA-FUJI




T20250616103323




BLK:14,SNR1: 0.30213 ,SNR2: 1.6165




K20250616103320



BLK:14,SNR1: 18.515 ,SNR2: 31.634





0418+236 2025/06/16 1.58UT TOYOKAWA-KISO







F20250616103324




BLK:13,SNR1: 3.2380 ,SNR2: 13.378




K20250616103320




BLK:13,SNR1: 16.549 ,SNR2: 27.563




0418+236 2025/06/16 1.58UT FUJI -KISO





T20250616104451




BLK:20,SNR1: 14.055 ,SNR2: 63.318




F20250616104451












BLK:20,SNR1: 2.9609 ,SNR2: 7.1065




3C119 2025/06/16 1.78UT TOYOKAWA-FUJI










3C119 2025/06/16 1.78UT FUJI -KISO




T20250616113258




BLK:22,SNR1: 27.126 ,SNR2: 43.756




F20250616113258







BLK:22,SNR1: 0.88267 ,SNR2: 2.1803




3C138 2025/06/16 2.58UT TOYOKAWA-FUJI







3C138 2025/06/16 2.58UT TOYOKAWA-KISO





F20250616113258




BLK:16,SNR1: 0.28923 ,SNR2: 2.5886




K20250616113255




BLK:16,SNR1: 1.0408 ,SNR2: 4.6437





3C138 2025/06/16 2.58UT FUJI -KISO







BLK:32,SNR1: 38.734 ,SNR2: 77.147



BLK:32,SNR1: 5.9154 ,SNR2: 21.281




0531+194 2025/06/16 2.80UT TOYOKAWA-FUJI







T20250616114631




BLK:33,SNR1: 41.773 ,SNR2: 83.172




K20250616114628







BLK:33,SNR1: 3.5984 ,SNR2: 10.162




0531+194 2025/06/16 2.80UT TOYOKAWA-KISO








0531+194 2025/06/16 2.80UT FUJI -KISO




T20250616115452




BLK:35,SNR1: 26.573 ,SNR2: 93.138




F20250616115452









BLK:35,SNR1: 1.4107 ,SNR2: 10.930





3C147 2025/06/16 2.94UT TOYOKAWA-FUJI









BLK:33,SNR1: 1.5508 ,SNR2: 11.850




BLK:33,SNR1: 31.422 ,SNR2: 59.105




3C147 2025/06/16 2.94UT FUJI -KISO




T20250616120302




BLK:11,SNR1: 25.851 ,SNR2: 40.004




F20250616120302




BLK:11,SNR1: 5.8356 ,SNR2: 10.167




0548+16 2025/06/16 3.08UT TOYOKAWA-FUJI





T20250616120302




BLK:14,SNR1: 11.055 ,SNR2: 25.447




K20250616120259




BLK:14,SNR1: 0.99319 ,SNR2: 4.4670




0548+16 2025/06/16 3.08UT TOYOKAWA-KISO





F20250616120302




BLK: 5,SNR1: 9.7599 ,SNR2: 18.033




K20250616120259



BLK: 5,SNR1: 0.40954 ,SNR2: 1.7489




0548+16 2025/06/16 3.08UT FUJI -KISO







T20250616120713




BLK:10,SNR1: 1.2892 ,SNR2: 4.7152




F20250616120713





BLK:10,SNR1: 0.11358 ,SNR2: 1.7471




0552+12 2025/06/16 3.15UT TOYOKAWA-FUJI





T20250616120713




BLK:18,SNR1: 1.5459 ,SNR2: 7.6504




K20250616120710




BLK:18,SNR1: 0.31957 ,SNR2: 1.1437





0552+12 2025/06/16 3.15UT TOYOKAWA-KISO







BLK: 9,SNR1: 0.10963 ,SNR2: 1.9220





BLK: 9,SNR1: 0.47702 ,SNR2: 1.4838




0552+12 2025/06/16 3.15UT FUJI -KISO





T20250616121140




BLK: 9,SNR1: 7.0484 ,SNR2: 12.571




F20250616121140




BLK: 9,SNR1: 0.50032 ,SNR2: 3.5200





0556+191 2025/06/16 3.22UT TOYOKAWA-FUJI







BLK:10,SNR1: 7.3158 ,SNR2: 13.037




BLK:10,SNR1: 6.1792 ,SNR2: 11.028





0556+191 2025/06/16 3.22UT TOYOKAWA-KISO







BLK:16,SNR1: 2.0920 ,SNR2: 9.8945





BLK:16,SNR1: 4.6959 ,SNR2: 8.4330




0556+191 2025/06/16 3.22UT FUJI -KISO




T20250616121613




BLK:14,SNR1: 0.21155 ,SNR2: 0.99859




F20250616121613





BLK:14,SNR1: 5.9996 ,SNR2: 27.486




3C152 2025/06/16 3.30UT TOYOKAWA-FUJI





T20250616121613




BLK:14,SNR1: 0.27895 ,SNR2: 1.3763




K20250616121610



BLK:14,SNR1: 0.40755 ,SNR2: 1.7700




3C152 2025/06/16 3.30UT TOYOKAWA-KISO








F20250616121613




BLK:16,SNR1: 7.5891 ,SNR2: 20.713




K20250616121610




BLK:16,SNR1: 0.46991 ,SNR2: 1.9407




3C152 2025/06/16 3.30UT FUJI -KISO





T20250616123833




BLK: 8,SNR1: 2.0103 ,SNR2: 6.5383




F20250616123833




BLK: 8,SNR1: 2.2994 ,SNR2: 6.7182





3C161 2025/06/16 3.67UT TOYOKAWA-FUJI







BLK:14,SNR1: 3.1367 ,SNR2: 7.7115




BLK:14,SNR1: 8.5162 ,SNR2: 15.237





3C161 2025/06/16 3.67UT TOYOKAWA-KISO







BLK:11,SNR1: 4.1516 ,SNR2: 10.123




BLK:11,SNR1: 7.0878 ,SNR2: 12.464





3C161 2025/06/16 3.67UT FUJI -KISO







BLK: 9,SNR1: 0.21533 ,SNR2: 1.9568




BLK: 9,SNR1: 1.1970 ,SNR2: 10.197





0652-130 2025/06/16 4.13UT TOYOKAWA-FUJI







BLK:13,SNR1: 8.6050 ,SNR2: 15.380




BLK:13,SNR1: 4.0623 ,SNR2: 9.5829




0652-130 2025/06/16 4.13UT TOYOKAWA-KISO




F20250616130606




BLK:13,SNR1: 0.16099 ,SNR2: 3.4920




K20250616130603





BLK:13,SNR1: 1.0611 ,SNR2: 3.6007




0652-130 2025/06/16 4.13UT FUJI -KISO




T20250616131743




BLK: 8,SNR1: 0.21488 ,SNR2: 0.88250




F20250616131743



BLK: 8,SNR1: 1.8198 ,SNR2: 4.1358





0703+138 2025/06/16 4.32UT TOYOKAWA-FUJI








T20250616131743




BLK: 4,SNR1: 0.40940 ,SNR2: 1.3871




K20250616131740









BLK: 4,SNR1: 0.41498 ,SNR2: 1.8053





0703+138 2025/06/16 4.32UT TOYOKAWA-KISO









BLK: 5,SNR1: 0.98943E-01,SNR2: 1.2674





BLK: 5,SNR1: 0.13702 ,SNR2: 1.9240




0713-024 2025/06/16 4.48UT TOYOKAWA-FUJI





T20250616132705




BLK: 5,SNR1: 0.58262E-01,SNR2: 0.76527




K20250616132702








BLK: 5,SNR1: 0.40109,SNR2: 1.4807





0713-024 2025/06/16 4.48UT TOYOKAWA-KISO







T20250616133717




BLK: 5,SNR1: 0.23381 ,SNR2: 1.4145




F20250616133717





BLK: 5,SNR1: 0.13905 ,SNR2: 3.9350




0723+10 2025/06/16 4.65UT TOYOKAWA-FUJI





T20250616133717




BLK: 8,SNR1: 0.19515 ,SNR2: 1.5602




K20250616133714




BLK: 8,SNR1: 0.58139 ,SNR2: 2.6694




0723+10 2025/06/16 4.65UT TOYOKAWA-KISO





F20250616133717




BLK:10,SNR1: 2.7883 ,SNR2: 5.1326




K20250616133714



BLK:10,SNR1: 0.91769 ,SNR2: 3.0924




0723+10 2025/06/16 4.65UT FUJI -KISO







T20250616134732




BLK:11,SNR1: 2.0473 ,SNR2: 4.3200




F20250616134733




BLK:11,SNR1: 1.7500 ,SNR2: 7.0681




0732+33 2025/06/16 4.82UT TOYOKAWA-FUJI





T20250616134732




BLK:10,SNR1: 0.38984 ,SNR2: 1.2761




K20250616134729





BLK:10,SNR1: 0.21566 ,SNR2: 0.76779




0732+33 2025/06/16 4.82UT TOYOKAWA-KISO





F20250616134733




BLK: 8,SNR1: 1.8560 ,SNR2: 5.1499




K20250616134729





BLK: 8,SNR1: 1.3548 ,SNR2: 8.8322




0732+33 2025/06/16 4.82UT FUJI -KISO





T20250616135534




No.Good Data




F20250616135534





No.Good Data





0741-06 2025/06/16 4.95UT TOYOKAWA-FUJI




T20250616135534





K20250616135531




0741-06 2025/06/16 4.95UT TOYOKAWA-KISO





F20250616135534




No.Good Data




K20250616135531





No.Good Data




0741-06 2025/06/16 4.95UT FUJI -KISO





T20250616140518




BLK: 4,SNR1: 13.646 ,SNR2: 23.354




F20250616140518





BLK: 4,SNR1: 11.471 ,SNR2: 27.741




0752-200 2025/06/16 5.12UT TOYOKAWA-FUJI





T20250616140518




BLK: 2,SNR1: 0.91611 ,SNR2: 3.1732




K20250616140515



BLK: 2,SNR1: 8.1070 ,SNR2: 20.516





0752-200 2025/06/16 5.12UT TOYOKAWA-KISO








F20250616140518




BLK: 1,SNR1: 1.7972 ,SNR2: 9.6738




K20250616140515





BLK: 1,SNR1: 12.979 ,SNR2: 31.704




0752-200 2025/06/16 5.12UT FUJI -KISO




T20250616141253




BLK: 6,SNR1: 0.38440 ,SNR2: 3.2658




F20250616141254





BLK: 6,SNR1: 0.20429E-01,SNR2: 1.4896




3C190 2025/06/16 5.24UT TOYOKAWA-FUJI




T20250616141253




BLK: 6,SNR1: 0.61358 ,SNR2: 4.8328




K20250616141251





BLK: 6,SNR1: 0.18243 ,SNR2: 1.2698




3C190 2025/06/16 5.24UT TOYOKAWA-KISO





F20250616141254




BLK: 4,SNR1: 0.51273E-01,SNR2: 2.4312




K20250616141251




BLK: 4,SNR1: 0.69152E-01,SNR2: 0.81725




3C190 2025/06/16 5.24UT FUJI -KISO




T20250616142519




BLK: 9,SNR1: 6.6353 ,SNR2: 13.687




F20250616142520




BLK: 9,SNR1: 0.14178 ,SNR2: 1.9603




3C196 2025/06/16 5.45UT TOYOKAWA-FUJI




T20250616142519




BLK:14,SNR1: 6.2238 ,SNR2: 12.786




K20250616142516




BLK:14,SNR1: 7.1554 ,SNR2: 14.531




3C196 2025/06/16 5.45UT TOYOKAWA-KISO





F20250616142520




BLK:10,SNR1: 1.4070 ,SNR2: 5.4145




K20250616142516





BLK:10,SNR1: 7.3332 ,SNR2: 15.172




3C196 2025/06/16 5.45UT FUJI -KISO





T20250616143628




BLK: 6,SNR1: 0.29429 ,SNR2: 1.3357




F20250616143629



BLK: 6,SNR1: 0.20377 ,SNR2: 4.1809





0821+394 2025/06/16 5.64UT TOYOKAWA-FUJI








T20250616143628




BLK: 7,SNR1: 0.47207 ,SNR2: 1.6383




K20250616143625




BLK: 7,SNR1: 0.41237 ,SNR2: 2.0246





0821+394 2025/06/16 5.64UT TOYOKAWA-KISO







BLK: 5,SNR1: 1.2274 ,SNR2: 6.6223




BLK: 5,SNR1: 0.26986 ,SNR2: 2.6546





0821+394 2025/06/16 5.64UT FUJI -KISO







BLK: 1,SNR1: 0.59503E-01,SNR2: 1.5196




BLK: 1,SNR1:-0.26906 ,SNR2: 0.98482E-01





0834-19 2025/06/16 5.83UT TOYOKAWA-FUJI







BLK: 3,SNR1: 1.2146 ,SNR2: 4.7387




BLK: 3,SNR1: 0.41600 ,SNR2: 2.6807





0834-19 2025/06/16 5.83UT TOYOKAWA-KISO







BLK: 3,SNR1: 5.1894 ,SNR2: 15.409





BLK: 3,SNR1: 13.060 ,SNR2: 35.978




0834-19 2025/06/16 5.83UT FUJI -KISO




T20250616145313




BLK: 3,SNR1: 10.032 ,SNR2: 24.613




F20250616145313




BLK: 3,SNR1: 11.855 ,SNR2: 29.005





0839-071 2025/06/16 5.92UT TOYOKAWA-FUJI







BLK: 5,SNR1: 10.813 ,SNR2: 26.566




BLK: 5,SNR1: 7.5551 ,SNR2: 19.625





0839-071 2025/06/16 5.92UT TOYOKAWA-KISO







BLK: 2,SNR1: 15.391 ,SNR2: 36.560




BLK: 2,SNR1: 10.993 ,SNR2: 27.294





0839-071 2025/06/16 5.92UT FUJI -KISO










BLK:30,SNR1: 8.4879 ,SNR2: 25.104





BLK:30,SNR1: 11.124 ,SNR2: 26.787







BLK:26,SNR1: 8.7883 ,SNR2: 22.459




BLK:26,SNR1: 8.2784 ,SNR2: 20.551





3C208 2025/06/16 6.10UT TOYOKAWA-KISO








BLK:27,SNR1: 11.232 ,SNR2: 27.020





BLK:27,SNR1: 8.3031 ,SNR2: 20.608







BLK:19,SNR1: 2.9888 ,SNR2: 12.471




BLK:19,SNR1: 6.6224 ,SNR2: 13.552





3C216 2025/06/16 6.38UT TOYOKAWA-FUJI







BLK:25,SNR1: 2.9759 ,SNR2: 12.419




BLK:25,SNR1: 7.6490 ,SNR2: 15.747




3C216 2025/06/16 6.38UT TOYOKAWA-KISO





F20250616152057




BLK:25,SNR1: 6.4344 ,SNR2: 13.165




K20250616152053







BLK:25,SNR1: 7.6491 ,SNR2: 15.747




3C216 2025/06/16 6.38UT FUJI -KISO







0919-142 2025/06/16 6.58UT TOYOKAWA-FUJI




T20250616153306




BLK: 1,SNR1: 0.70343E-01,SNR2: 0.74657




K20250616153303




BLK: 1,SNR1: 0.22269 ,SNR2: 0.74786





0919-142 2025/06/16 6.58UT TOYOKAWA-KISO









BLK: 1,SNR1: 0.33225 ,SNR2: 2.2121





BLK: 1,SNR1: 0.43542 ,SNR2: 2.7974




0919-142 2025/06/16 6.58UT FUJI -KISO





T20250616153946




BLK: 5, SNR1: 3.7521 , SNR2: 7.3138




F20250616153947




BLK: 5, SNR1: 8.3404 , SNR2: 22.701





0926+117 2025/06/16 6.69UT TOYOKAWA-FUJI







BLK: 2, SNR1: 4.4889 , SNR2: 8.8556




BLK: 2, SNR1: 14.206 , SNR2: 35.996





0926+117 2025/06/16 6.69UT TOYOKAWA-KISO







BLK: 8,SNR1: 7.7334 ,SNR2: 18.875









BLK: 8,SNR1: 8.0774 ,SNR2: 20.344





0926+117 2025/06/16 6.69UT FUJI -KISO









BLK: 3,SNR1: 6.9873 ,SNR2: 17.403









BLK: 3,SNR1: 15.900 ,SNR2: 36.535





3C222 2025/06/16 6.82UT TOYOKAWA-KISO









BLK: 4,SNR1: 0.32646 ,SNR2: 1.6942




BLK: 4,SNR1: 2.0167 ,SNR2: 5.6802





0941-08 2025/06/16 6.94UT TOYOKAWA-FUJI









BLK: 2,SNR1: 0.45322 ,SNR2: 2.3343













BLK: 2,SNR1: 4.1187 ,SNR2: 8.1989




0941-08 2025/06/16 6.94UT TOYOKAWA-KISO













BLK: 9,SNR1: 7.5299 ,SNR2: 19.831










BLK: 9,SNR1: 8.0372 ,SNR2: 20.923




3C230 2025/06/16 7.08UT TOYOKAWA-KISO










3C237 2025/06/16 7.34UT TOYOKAWA-FUJI





T20250616161853




BLK: 5,SNR1: 2.3040 ,SNR2: 5.3181




K20250616161850






BLK: 5,SNR1: 0.16542 ,SNR2: 2.0149










3C237 2025/06/16 7.34UT TOYOKAWA-KISO















1011+110 2025/06/16 7.45UT TOYOKAWA-KISO







BLK: 6,SNR1: 9.2575 ,SNR2: 25.358







BLK: 6,SNR1: 13.014 ,SNR2: 32.460








1011+110 2025/06/16 7.45UT FUJI -KISO






3C241 2025/06/16 7.58UT TOYOKAWA-FUJI








3C241 2025/06/16 7.58UT TOYOKAWA-KISO



F20250616163251





BLK: 4, SNR1: 1.6751 , SNR2: 4.8926




Frequency (Hz)

K20250616163247




BLK: 4, SNR1: 11.773 , SNR2: 28.027




Frequency (Hz)


3C241 2025/06/16 7.58UT FUJI -KISO



T20250616174412





BLK: 5, SNR1: 0.25259 , SNR2: 1.2068




Frequency (Hz)

F20250616174413








BLK: 5, SNR1: 1.9617 , SNR2: 4.8030



Frequency (Hz)

1130+335 2025/06/16 8.76UT TOYOKAWA-FUJI





1130+335 2025/06/16 8.76UT TOYOKAWA-KISO

