





T20250617052224




BLK: 6,SNR1: 0.13866 ,SNR2: 1.4599




F20250617052226








BLK: 6,SNR1: 0.39322 ,SNR2: 2.1694







2311+469 2025/06/16 20.40UT TOYOKAWA-FUJI















BLK: 5,SNR1: 7.9643 ,SNR2: 20.033






BLK: 5,SNR1: 0.78503 ,SNR2: 4.6812





0011+344 2025/06/16 21.40UT TOYOKAWA-FUJI






F20250617062221




BLK: 5,SNR1: 1.1075 ,SNR2: 8.1228




Frequency (Hz)

K20250617062216




BLK: 5,SNR1: 0.49029 ,SNR2: 2.8551





Frequency (Hz)


0011+344 2025/06/16 21.40UT FUJI -KISO




T20250617064110




BLK:20,SNR1: 7.4762 ,SNR2: 18.164




F20250617064112







BLK:20,SNR1: 5.0625 ,SNR2: 12.144









3C12 2025/06/16 21.71UT TOYOKAWA-FUJI











3C12 2025/06/16 21.71UT TOYOKAWA-KISO















F20250617064930




BLK: 6,SNR1: 1.2224 ,SNR2: 3.8902




K20250617064925





BLK: 6,SNR1: 0.87118 ,SNR2: 2.8034




0038+328 2025/06/16 21.85UT FUJI -KISO



T20250617070233





BLK: 2,SNR1: 5.9995 ,SNR2: 14.999





3C26 2025/06/16 22.07UT TOYOKAWA-FUJI



F20250617070235




BLK: 2,SNR1: 0.33320 ,SNR2: 7.2254



T20250617070233





No.Good Data




Frequency (Hz)

K20250617070230




No.Good Data





Frequency (Hz)


3C26 2025/06/16 22.07UT TOYOKAWA-KISO





F20250617070235




BLK: 1, SNR1: 0.38468 , SNR2: 2.8600




K20250617070230





BLK: 1, SNR1: 0.35492 , SNR2: 1.2475




3C26 2025/06/16 22.07UT FUJI -KISO




T20250617070731




BLK: 1, SNR1: 2.1330 , SNR2: 4.7399




F20250617070733





BLK: 1, SNR1: 13.726 , SNR2: 26.445




0056-00 2025/06/16 22.15UT TOYOKAWA-FUJI




T20250617070731




BLK: 1,SNR1:-0.28627 ,SNR2: 1.1791




K20250617070728




BLK: 1,SNR1: 0.24448 ,SNR2: 9.2650




0056-00 2025/06/16 22.15UT TOYOKAWA-KISO




F20250617070733




BLK: 4, SNR1: 13.348 , SNR2: 30.622




K20250617070728



BLK: 4, SNR1: 12.944 , SNR2: 16.767





0056-00 2025/06/16 22.15UT FUJI -KISO








T20250617071714




No.Good Data




F20250617071716





No.Good Data




0106+01 2025/06/16 22.32UT TOYOKAWA-FUJI



T20250617071714





No.Good Data




Frequency (Hz)

K20250617071712




No.Good Data





Frequency (Hz)


0106+01 2025/06/16 22.32UT TOYOKAWA-KISO





F20250617071716




BLK: 2, SNR1: 3.9686 , SNR2: 15.705




K20250617071712





BLK: 2, SNR1: 3.6704 , SNR2: 11.321




0106+01 2025/06/16 22.32UT FUJI -KISO





T20250617072636




BLK: 7,SNR1: 2.1037 ,SNR2: 10.115




F20250617072638





BLK: 7,SNR1: 10.777 ,SNR2: 26.437




0115-01 2025/06/16 22.47UT TOYOKAWA-FUJI





T20250617072636




BLK: 1, SNR1: 1.8199 ,SNR2: 9.2353




K20250617072633





BLK: 1, SNR1: 9.1851 ,SNR2: 22.745




0115-01 2025/06/16 22.47UT TOYOKAWA-KISO





F20250617072638




BLK: 4,SNR1: 9.2071 ,SNR2: 22.701




K20250617072633





BLK: 4,SNR1: 9.0293 ,SNR2: 22.000




0115-01 2025/06/16 22.47UT FUJI -KISO




T20250617073936




BLK: 2, SNR1: 8.9031 , SNR2: 21.932




F20250617073938





BLK: 2, SNR1: 3.3069 , SNR2: 14.161




0128+03 2025/06/16 22.69UT TOYOKAWA-FUJI



T20250617073936





BLK: 6,SNR1: 7.4855 ,SNR2: 16.260





0128+03 2025/06/16 22.69UT TOYOKAWA-KISO

K20250617073933




BLK: 6,SNR1: 9.0436 ,SNR2: 16.081








F20250617073938




BLK: 7,SNR1: 17.393 ,SNR2: 31.886




K20250617073933





BLK: 7,SNR1: 11.008 ,SNR2: 24.419




0128+03 2025/06/16 22.69UT FUJI -KISO





T20250617074610




BLK:14,SNR1: 9.3155 ,SNR2: 28.657




F20250617074612





BLK:14,SNR1: 0.79369 ,SNR2: 3.5694




3C48 2025/06/16 22.80UT TOYOKAWA-FUJI





T20250617074610




BLK:19,SNR1: 5.4174 ,SNR2: 12.887




K20250617074607




BLK:19,SNR1: 1.3413 ,SNR2: 5.8343




3C48 2025/06/16 22.80UT TOYOKAWA-KISO





F20250617074612




BLK: 4,SNR1: 1.1900 ,SNR2: 8.7592




K20250617074607





BLK: 4,SNR1: 1.9225 ,SNR2: 7.8293




3C48 2025/06/16 22.80UT FUJI -KISO




T20250617080554




BLK: 7, SNR1: 0.30033 , SNR2: 2.0783




F20250617080556





BLK: 7, SNR1: 0.49627 , SNR2: 4.4447




0155-109 2025/06/16 23.13UT TOYOKAWA-FUJI





T20250617080554




BLK:12,SNR1: 0.29018 ,SNR2: 0.82671




K20250617080551




BLK:12,SNR1: 7.2967 ,SNR2: 18.916




0155-109 2025/06/16 23.13UT TOYOKAWA-KISO





F20250617080556




BLK:17,SNR1: 0.56182 ,SNR2: 5.8484




K20250617080551




BLK:17,SNR1: 7.1059 ,SNR2: 18.424





0155-109 2025/06/16 23.13UT FUJI -KISO







BLK:11,SNR1: 33.602 ,SNR2: 41.646




BLK:11,SNR1: 25.753 ,SNR2: 46.855





0202+15 2025/06/16 23.25UT TOYOKAWA-FUJI









BLK: 7, SNR1: 40.490 , SNR2: 50.169




BLK: 7, SNR1: 9.3936 , SNR2: 21.448




0202+15 2025/06/16 23.25UT TOYOKAWA-KISO




F20250617081304




BLK: 7, SNR1: 48.564 , SNR2: 61.310




K20250617081259





BLK: 7, SNR1: 7.2542 , SNR2: 18.262




0202+15 2025/06/16 23.25UT FUJI -KISO





T20250617082452




BLK:22,SNR1: 18.604 ,SNR2: 24.866




F20250617082454







BLK:22,SNR1: 7.6029 ,SNR2: 21.975




0213+178 2025/06/16 23.44UT TOYOKAWA-FUJI







0213+178 2025/06/16 23.44UT TOYOKAWA-KISO





F20250617082454




BLK:20,SNR1: 19.973 ,SNR2: 36.778




K20250617082449













BLK:20,SNR1: 14.249 ,SNR2: 35.634




0213+178 2025/06/16 23.44UT FUJI -KISO








F20250617083237





BLK:10,SNR1: 2.2462 ,SNR2: 6.7119





3C67 2025/06/16 23.57UT FUJI -KISO

K20250617083232





BLK:10,SNR1: 8.5005 ,SNR2: 18.387








T20250617085049




BLK: 9,SNR1: 25.415 ,SNR2: 42.943




F20250617085051





BLK: 9,SNR1: 23.581 ,SNR2: 40.138




3C71 2025/06/16 23.88UT TOYOKAWA-FUJI



T20250617085049





BLK: 8, SNR1: 30.160 , SNR2: 40.292





3C71 2025/06/16 23.88UT TOYOKAWA-KISO



K20250617085046




BLK: 8, SNR1: 17.597 , SNR2: 28.374



F20250617085051





BLK:10,SNR1: 54.610 ,SNR2: 90.896





3C71 2025/06/16 23.88UT FUJI -KISO



K20250617085046




BLK:10,SNR1: 30.419 ,SNR2: 48.665



T20250617091005





BLK:10,SNR1: 16.098 ,SNR2: 24.665




Frequency (Hz)

F20250617091007




BLK:10,SNR1: 27.931 ,SNR2: 35.256




Frequency (Hz)


0258+350 2025/06/17 0.20UT TOYOKAWA-FUJI





T20250617091005




BLK:21,SNR1: 16.173 ,SNR2: 24.777




K20250617091002




BLK:21,SNR1: 31.947 ,SNR2: 46.992




0258+350 2025/06/17 0.20UT TOYOKAWA-KISO





F20250617091007




BLK:10,SNR1: 32.805 ,SNR2: 41.128




K20250617091002





BLK:10,SNR1: 37.740 ,SNR2: 55.505




0258+350 2025/06/17 0.20UT FUJI -KISO





T20250617091954




BLK: 7,SNR1: 3.0762 ,SNR2: 8.9082




F20250617091956





BLK: 7,SNR1: 5.9521 ,SNR2: 14.778




0308+305 2025/06/17 0.36UT TOYOKAWA-FUJI





T20250617091954




BLK:13,SNR1: 3.0641 ,SNR2: 8.7645




K20250617091951



BLK:13,SNR1: 7.6435 ,SNR2: 16.698





0308+305 2025/06/17 0.36UT TOYOKAWA-KISO








F20250617091956




BLK: 5, SNR1: 3.7704 , SNR2: 9.1725




K20250617091951




BLK: 5, SNR1: 4.6927 , SNR2: 17.765




0308+305 2025/06/17 0.36UT FUJI -KISO




T20250617092814




BLK:10,SNR1: 0.98348 ,SNR2: 3.0317




F20250617092816








BLK:10,SNR1: 1.6948 ,SNR2: 4.0955




3C84 2025/06/17 0.50UT TOYOKAWA-FUJI








F20250617092816




BLK: 8,SNR1: 0.17863 ,SNR2: 1.9725




K20250617092811




BLK: 8,SNR1: 0.52669 ,SNR2: 4.3106




3C84 2025/06/17 0.50UT FUJI -KISO





T20250617093530




BLK:12,SNR1: 2.2444 ,SNR2: 4.4232




F20250617093532




BLK:12,SNR1: 1.9009 ,SNR2: 5.3329




0324+119 2025/06/17 0.62UT TOYOKAWA-FUJI




T20250617093530




BLK:13,SNR1: 1.4226 ,SNR2: 2.7750




K20250617093527





BLK:13,SNR1: 1.9912 ,SNR2: 7.4936




0324+119 2025/06/17 0.62UT TOYOKAWA-KISO





F20250617093532




BLK: 8,SNR1: 2.5363 ,SNR2: 4.8829




K20250617093527





BLK: 8,SNR1: 1.3545 ,SNR2: 5.2171




0324+119 2025/06/17 0.62UT FUJI -KISO





T20250617094447




BLK: 4,SNR1:-0.49784E-01,SNR2: 0.34116




F20250617094449



BLK: 4,SNR1: 2.9443 ,SNR2: 5.3849





0333+32 2025/06/17 0.77UT TOYOKAWA-FUJI








T20250617094447




BLK: 3,SNR1: 0.30125E-01,SNR2: 0.77587




K20250617094444





BLK: 3,SNR1: 1.1779 ,SNR2: 18.395




0333+32 2025/06/17 0.77UT TOYOKAWA-KISO




F20250617094449




BLK: 5, SNR1: 1.0915 , SNR2: 4.8778




K20250617094444





BLK: 5, SNR1: 3.5926 , SNR2: 25.500




0333+32 2025/06/17 0.77UT FUJI -KISO




T20250617095748




BLK: 8,SNR1: 0.32616 ,SNR2: 0.91172




F20250617095750





BLK: 8,SNR1: 0.28243 ,SNR2: 2.2352




0347+05 2025/06/17 0.99UT TOYOKAWA-FUJI



T20250617095748




BLK:10,SNR1: 0.23446 ,SNR2: 1.2118





0347+05 2025/06/17 0.99UT TOYOKAWA-KISO


K20250617095745




BLK:10,SNR1: 4.7742 ,SNR2: 8.6870




F20250617095750




BLK:16,SNR1: 0.65562 ,SNR2: 3.7098




K20250617095745







BLK:16,SNR1: 6.8788 ,SNR2: 12.203









0347+05 2025/06/17 0.99UT FUJI -KISO






0403-132 2025/06/17 1.25UT TOYOKAWA-FUJI








F20250617101324




BLK: 2, SNR1: 0.22372 , SNR2: 6.2496




K20250617101319



BLK: 2, SNR1: 0.12396 , SNR2: 0.64018




0403-132 2025/06/17 1.25UT FUJI -KISO







T20250617102233




BLK: 7,SNR1: 0.57450 ,SNR2: 2.0326




F20250617102235




BLK: 7,SNR1: 0.95660 ,SNR2: 2.2959




0411+05 2025/06/17 1.40UT TOYOKAWA-FUJI




T20250617102233




BLK: 9, SNR1: 0.67639 , SNR2: 2.2339




K20250617102231





BLK: 9, SNR1: 8.4999 , SNR2: 19.039




0411+05 2025/06/17 1.40UT TOYOKAWA-KISO





F20250617102235




BLK: 8, SNR1: 9.3542 , SNR2: 16.760




K20250617102231





BLK: 8, SNR1: 8.1955 , SNR2: 14.502




0411+05 2025/06/17 1.40UT FUJI -KISO





T20250617102928




BLK:15,SNR1: 0.25968 ,SNR2: 1.6418




F20250617102930





BLK:15,SNR1: 48.565 ,SNR2: 75.334




0418+236 2025/06/17 1.52UT TOYOKAWA-FUJI





T20250617102928




BLK:18,SNR1: 0.29798 ,SNR2: 1.6226




K20250617102925




BLK:18,SNR1: 72.323 ,SNR2: 112.07




0418+236 2025/06/17 1.52UT TOYOKAWA-KISO




F20250617102930




BLK:26,SNR1: 24.015 ,SNR2: 43.331




K20250617102925





BLK:26,SNR1: 51.972 ,SNR2: 68.529




0418+236 2025/06/17 1.52UT FUJI -KISO




T20250617104055




BLK:19,SNR1: 10.913 ,SNR2: 46.120




F20250617104057





BLK:19,SNR1: 1.4566 ,SNR2: 4.9489




3C119 2025/06/17 1.71UT TOYOKAWA-FUJI





T20250617104055




BLK:27,SNR1: 9.5572 ,SNR2: 23.917




K20250617104052



BLK:27,SNR1: 1.4567 ,SNR2: 5.7310




3C119 2025/06/17 1.71UT TOYOKAWA-KISO







F20250617104057




BLK:20,SNR1: 1.4242 ,SNR2: 4.9636




K20250617104052








BLK:20,SNR1: 1.2013 ,SNR2: 7.6081





3C119 2025/06/17 1.71UT FUJI -KISO








T20250617112902




BLK:23,SNR1: 7.3054 ,SNR2: 19.746




K20250617112900








BLK:23,SNR1: 0.70789 ,SNR2: 3.0714




3C138 2025/06/17 2.51UT TOYOKAWA-KISO







T20250617114236




BLK:24,SNR1: 1.1119 ,SNR2: 5.2794




F20250617114238




BLK:24,SNR1: 3.4761 ,SNR2: 9.8787




0531+194 2025/06/17 2.74UT TOYOKAWA-FUJI





T20250617114236




BLK:16,SNR1: 0.73438 ,SNR2: 2.3437




K20250617114233




BLK:16,SNR1: 0.36848 ,SNR2: 1.0174




0531+194 2025/06/17 2.74UT TOYOKAWA-KISO




F20250617114238




BLK:10,SNR1: 0.94837 ,SNR2: 2.3382




K20250617114233








BLK:10,SNR1: 0.43510 ,SNR2: 1.2067













0531+194 2025/06/17 2.74UT FUJI -KISO
















T20250617115907




BLK:21,SNR1: 12.474 ,SNR2: 20.945




F20250617115909




BLK:21,SNR1: 1.9134 ,SNR2: 7.5221




0548+16 2025/06/17 3.01UT TOYOKAWA-FUJI





T20250617115907




BLK:14,SNR1: 11.647 ,SNR2: 17.917




K20250617115904





BLK:14,SNR1: 0.30637 ,SNR2: 1.6870




0548+16 2025/06/17 3.01UT TOYOKAWA-KISO





F20250617115909




BLK: 6,SNR1: 0.94327E-01,SNR2: 2.4762




K20250617115904




BLK: 6,SNR1: 0.89035E-01,SNR2: 1.0361




0548+16 2025/06/17 3.01UT FUJI -KISO




T20250617120317




BLK:19,SNR1: 1.6614 ,SNR2: 7.3144




F20250617120319









BLK:19,SNR1: 0.20806 ,SNR2: 1.6425



0552+12 2025/06/17 3.08UT TOYOKAWA-FUJI












T20250617120744




BLK: 8,SNR1: 1.3011 ,SNR2: 6.7987




F20250617120746









BLK: 8,SNR1: 0.71310 ,SNR2: 5.7105




0556+191 2025/06/17 3.16UT TOYOKAWA-FUJI









T20250617121217




BLK:16,SNR1: 1.3808 ,SNR2: 4.2704




F20250617121219









BLK:16,SNR1: 1.3823 ,SNR2: 5.7438




3C152 2025/06/17 3.23UT TOYOKAWA-FUJI









T20250617123437




BLK: 8,SNR1: 1.7454 ,SNR2: 15.113




F20250617123439




BLK: 8,SNR1: 1.9834 ,SNR2: 8.5692




3C161 2025/06/17 3.61UT TOYOKAWA-FUJI




T20250617123437




BLK:13,SNR1: 1.4101 ,SNR2: 10.102




K20250617123434



BLK:13,SNR1: 0.41731 ,SNR2: 1.4986




3C161 2025/06/17 3.61UT TOYOKAWA-KISO







F20250617123439




BLK: 7, SNR1: 4.4747 , SNR2: 8.3235




K20250617123434




BLK: 7, SNR1: 0.47048 , SNR2: 2.9456




3C161 2025/06/17 3.61UT FUJI -KISO




T20250617130210




BLK: 2,SNR1: 0.18013 ,SNR2: 1.6845




F20250617130212




BLK: 2,SNR1: 0.66025 ,SNR2: 2.9038




0652-130 2025/06/17 4.06UT TOYOKAWA-FUJI





T20250617130210




BLK: 4,SNR1:-0.19444E-01,SNR2: 0.95066




K20250617130207




BLK: 4,SNR1: 9.3806 ,SNR2: 20.325




0652-130 2025/06/17 4.06UT TOYOKAWA-KISO




F20250617130212




BLK: 4,SNR1:-0.58494E-02,SNR2: 2.3990




K20250617130207





BLK: 4,SNR1: 2.7789 ,SNR2: 5.5176




0652-130 2025/06/17 4.06UT FUJI -KISO





T20250617131347




BLK: 2,SNR1: 0.62324E-01,SNR2: 0.77464




F20250617131349




BLK: 2,SNR1: 0.57916 ,SNR2: 2.3417




0703+138 2025/06/17 4.26UT TOYOKAWA-FUJI



T20250617131347





BLK: 3,SNR1: 0.25302E-01,SNR2: 0.55459




Frequency (Hz)

K20250617131344








BLK: 3,SNR1: 0.24745 ,SNR2: 1.4464




Frequency (Hz)

0703+138 2025/06/17 4.26UT TOYOKAWA-KISO








0703+138 2025/06/17 4.26UT FUJI -KISO




T20250617132310




BLK: 3,SNR1: 0.11147 ,SNR2: 0.62342




F20250617132312



BLK: 3,SNR1: -0.14093 ,SNR2: 1.4651





0713-024 2025/06/17 4.41UT TOYOKAWA-FUJI








T20250617132310




BLK: 6,SNR1: 0.24364E-01,SNR2: 0.79691




K20250617132307




BLK: 6,SNR1: 0.61979,SNR2: 3.1667




0713-024 2025/06/17 4.41UT TOYOKAWA-KISO





F20250617132312




BLK: 4,SNR1: 0.49250E-01,SNR2: 1.5447




K20250617132307





BLK: 4,SNR1: 0.26700 ,SNR2: 2.2280




0713-024 2025/06/17 4.41UT FUJI -KISO




T20250617133322




BLK:10,SNR1: 0.42540 ,SNR2: 2.8228




F20250617133324




BLK:10,SNR1: 2.5076 ,SNR2: 6.2705





0723+10 2025/06/17 4.58UT TOYOKAWA-FUJI







BLK:21,SNR1: 0.31464 ,SNR2: 2.1650




BLK:21,SNR1: 7.8852 ,SNR2: 20.325




0723+10 2025/06/17 4.58UT TOYOKAWA-KISO




F20250617133324




BLK:22,SNR1: 6.2883 ,SNR2: 14.740




K20250617133320




BLK:22,SNR1: 8.1627 ,SNR2: 21.138




0723+10 2025/06/17 4.58UT FUJI -KISO




T20250617134337




BLK: 9,SNR1: 0.98960 ,SNR2: 3.5364




F20250617134339




BLK: 9,SNR1: 0.49920 ,SNR2: 3.6140




0732+33 2025/06/17 4.76UT TOYOKAWA-FUJI




T20250617134337




BLK: 7,SNR1: 0.15644 ,SNR2: 1.5800




K20250617134335




BLK: 7,SNR1: 0.26132 ,SNR2: 0.81946




0732+33 2025/06/17 4.76UT TOYOKAWA-KISO





F20250617134339




BLK: 7,SNR1: 0.55292 ,SNR2: 2.1159




K20250617134335




BLK: 7,SNR1: 0.23803 ,SNR2: 0.68669





0732+33 2025/06/17 4.76UT FUJI -KISO









BLK: 6,SNR1: 18.840 ,SNR2: 24.762







BLK: 6,SNR1: 10.698 ,SNR2: 26.247





0741-06 2025/06/17 4.89UT TOYOKAWA-FUJI







0741-06 2025/06/17 4.89UT TOYOKAWA-KISO








BLK: 2,SNR1: 13.852 ,SNR2: 25.294





BLK: 2,SNR1: 9.6225 ,SNR2: 23.601







BLK: 5,SNR1: 4.8749 ,SNR2: 18.196




BLK: 5,SNR1: 4.5394 ,SNR2: 16.370





0752-200 2025/06/17 5.05UT TOYOKAWA-FUJI







BLK: 5,SNR1: 3.0149 ,SNR2: 9.8981




BLK: 5,SNR1: 7.6902 ,SNR2: 20.238





0752-200 2025/06/17 5.05UT TOYOKAWA-KISO







BLK: 9,SNR1: 4.5033 ,SNR2: 16.263




BLK: 9,SNR1: 29.821 ,SNR2: 31.712




0752-200 2025/06/17 5.05UT FUJI -KISO





T20250617140857




BLK: 6,SNR1: 0.39332 ,SNR2: 2.3001




F20250617140859




BLK: 6,SNR1: 0.45451 ,SNR2: 2.2728




3C190 2025/06/17 5.18UT TOYOKAWA-FUJI





T20250617140857




BLK:14,SNR1: 0.24361 ,SNR2: 1.7652




K20250617140855



BLK:14,SNR1: 0.53496 ,SNR2: 2.1740




3C190 2025/06/17 5.18UT TOYOKAWA-KISO








F20250617140859




BLK: 1,SNR1: 0.30250 ,SNR2: 0.38718




K20250617140855





BLK: 1,SNR1: 0.79457 ,SNR2: 3.9681




3C190 2025/06/17 5.18UT FUJI -KISO




T20250617142123




BLK: 8,SNR1: 0.49806 ,SNR2: 3.0506




F20250617142125





BLK: 8,SNR1: 2.1824 ,SNR2: 7.2398




3C196 2025/06/17 5.38UT TOYOKAWA-FUJI





T20250617142123




BLK: 5,SNR1: 0.84211 ,SNR2: 4.5045




K20250617142120




BLK: 5,SNR1: 0.96327 ,SNR2: 4.3615




3C196 2025/06/17 5.38UT TOYOKAWA-KISO





F20250617142125




BLK: 2,SNR1: 0.48366 ,SNR2: 2.1540




K20250617142120





BLK: 2,SNR1: 0.42892 ,SNR2: 1.8397





3C196 2025/06/17 5.38UT FUJI -KISO




T20250617143232





F20250617143234




0821+394 2025/06/17 5.57UT TOYOKAWA-FUJI




T20250617143232




BLK: 7,SNR1: 0.85267E-01,SNR2: 0.80215




K20250617143229







BLK: 7,SNR1: 0.53298,SNR2: 2.3742





0821+394 2025/06/17 5.57UT TOYOKAWA-KISO









BLK: 2,SNR1: 5.3697 ,SNR2: 18.717




BLK: 2,SNR1: 11.410 ,SNR2: 20.456





0834-19 2025/06/17 5.76UT TOYOKAWA-FUJI









BLK: 3,SNR1: 0.62424E-01,SNR2: 1.2236




BLK: 3,SNR1: 1.7666 ,SNR2: 15.823





0834-19 2025/06/17 5.76UT TOYOKAWA-KISO









BLK: 2,SNR1: 0.44087 ,SNR2: 4.0132




BLK: 2,SNR1: 0.37621 ,SNR2: 0.81305





T20250617144917




No.Good Data




F20250617144919





No.Good Data




0839-071 2025/06/17 5.85UT TOYOKAWA-FUJI





T20250617144917




BLK: 1,SNR1: 8.2742 ,SNR2: 20.522




K20250617144914





BLK: 1,SNR1: 2.9313 ,SNR2: 13.366




0839-071 2025/06/17 5.85UT TOYOKAWA-KISO





F20250617144919




BLK: 1,SNR1: 0.39594 ,SNR2: 4.4008




K20250617144914




BLK: 1,SNR1: 1.3250 ,SNR2: 8.3021





0839-071 2025/06/17 5.85UT FUJI -KISO







BLK: 1,SNR1: 10.420 ,SNR2: 25.769





BLK: 1,SNR1: 11.077 ,SNR2: 20.122




3C208 2025/06/17 6.03UT TOYOKAWA-FUJI



T20250617150018





No.Good Data




Frequency (Hz)

K20250617150015





No.Good Data





Frequency (Hz)

3C208 2025/06/17 6.03UT TOYOKAWA-KISO







BLK: 2,SNR1: 15.165 ,SNR2: 27.305



BLK: 2,SNR1: 14.541 ,SNR2: 26.277





3C208 2025/06/17 6.03UT FUJI -KISO







T20250617151700




BLK: 4,SNR1: 0.15222 ,SNR2: 1.4555




F20250617151702





BLK: 4,SNR1: 0.45715 ,SNR2: 1.7654




3C216 2025/06/17 6.31UT TOYOKAWA-FUJI



T20250617151700





BLK: 5,SNR1: 4.4214 ,SNR2: 14.037




Frequency (Hz)

K20250617151657





BLK: 5,SNR1: 0.61625 ,SNR2: 2.4325





Frequency (Hz)

3C216 2025/06/17 6.31UT TOYOKAWA-KISO







BLK: 5,SNR1: 1.0392 ,SNR2: 3.8746





BLK: 5,SNR1: 0.26117 ,SNR2: 2.2657




3C216 2025/06/17 6.31UT FUJI -KISO




T20250617152910




BLK: 3,SNR1: 8.6097 ,SNR2: 21.458




F20250617152912




BLK: 3,SNR1: 0.52409 ,SNR2: 3.3555





0919-142 2025/06/17 6.51UT TOYOKAWA-FUJI







BLK: 3,SNR1: 1.1134 ,SNR2: 2.6850




BLK: 3,SNR1: 2.7995 ,SNR2: 9.2249




0919-142 2025/06/17 6.51UT TOYOKAWA-KISO




F20250617152912




BLK: 4,SNR1: 1.6560 ,SNR2: 5.7154




K20250617152907





BLK: 4,SNR1: 8.9059 ,SNR2: 23.386




0919-142 2025/06/17 6.51UT FUJI -KISO





T20250617153550




BLK: 1,SNR1:-0.76545E-02,SNR2: 0.49579




F20250617153552





BLK: 1,SNR1: 8.6317 ,SNR2: 21.645




0926+117 2025/06/17 6.63UT TOYOKAWA-FUJI





T20250617153550




BLK: 3,SNR1: 0.27156 ,SNR2: 1.2428




K20250617153547



BLK: 3,SNR1: 0.81671 ,SNR2: 4.7918





0926+117 2025/06/17 6.63UT TOYOKAWA-KISO








F20250617153552




BLK: 3,SNR1: 1.2462 ,SNR2: 10.244




K20250617153547




BLK: 3,SNR1: 0.36576 ,SNR2: 3.3307





0926+117 2025/06/17 6.63UT FUJI -KISO







BLK: 7,SNR1: 10.806 ,SNR2: 27.215









BLK: 7,SNR1: 4.7556 ,SNR2: 12.701





3C222 2025/06/17 6.75UT TOYOKAWA-FUJI









BLK: 2,SNR1: 5.5717 ,SNR2: 15.270




BLK: 2,SNR1: 6.4373 ,SNR2: 18.885




3C222 2025/06/17 6.75UT FUJI -KISO




T20250617155034




BLK:16,SNR1: 3.7215 ,SNR2: 7.3058




F20250617155036







BLK:16,SNR1: 4.4359 ,SNR2: 9.1934





0941-08 2025/06/17 6.87UT TOYOKAWA-FUJI







0941-08 2025/06/17 6.87UT TOYOKAWA-KISO









BLK:16,SNR1: 4.1883 ,SNR2: 8.7210




BLK:16,SNR1: 7.7705 ,SNR2: 15.178




T20250617155856




BLK: 1,SNR1: 0.35197 ,SNR2: 2.2007




F20250617155858



BLK: 1,SNR1: 1.0380 ,SNR2: 13.900





3C230 2025/06/17 7.01UT TOYOKAWA-FUJI






T20250617155856





No.Good Data




Frequency (Hz)

K20250617155853




No.Good Data




Frequency (Hz)


3C230 2025/06/17 7.01UT TOYOKAWA-KISO





F20250617155858




BLK: 3,SNR1: 0.20175 ,SNR2: 2.6310




K20250617155853




BLK: 3,SNR1: 0.75318 ,SNR2: 3.3315




3C230 2025/06/17 7.01UT FUJI -KISO



T20250617161457




BLK:10,SNR1: 9.7739 ,SNR2: 17.300




Frequency (Hz)

F20250617161459




BLK:10,SNR1: 8.1307 ,SNR2: 23.184




Frequency (Hz)


3C237 2025/06/17 7.28UT TOYOKAWA-FUJI




T20250617161457




BLK: 8,SNR1: 4.2425 ,SNR2: 7.4842




K20250617161454




BLK: 8,SNR1: 9.9141 ,SNR2: 23.994





3C237 2025/06/17 7.28UT TOYOKAWA-KISO







BLK: 9,SNR1: 9.0376 ,SNR2: 22.979





BLK: 9,SNR1: 11.181 ,SNR2: 27.569






3C237 2025/06/17 7.28UT FUJI -KISO








1011+110 2025/06/17 7.38UT TOYOKAWA-FUJI







BLK: 5, SNR1: 0.27234E-01, SNR2: 0.89365








BLK: 5, SNR1: 0.64640 , SNR2: 2.7144




1011+110 2025/06/17 7.38UT TOYOKAWA-KISO













BLK: 7,SNR1: 11.042 ,SNR2: 27.227





BLK: 7,SNR1: 9.3529 ,SNR2: 23.213









3C241 2025/06/17 7.51UT TOYOKAWA-FUJI








3C241 2025/06/17 7.51UT TOYOKAWA-KISO









BLK: 5,SNR1: 0.27670 ,SNR2: 2.4685




BLK: 5,SNR1: 8.4605 ,SNR2: 18.471





1035-058 2025/06/17 7.78UT TOYOKAWA-FUJI







BLK: 7,SNR1: 0.11406 ,SNR2: 1.0871




BLK: 7,SNR1: 0.78110 ,SNR2: 2.6433





1035-058 2025/06/17 7.78UT TOYOKAWA-KISO









BLK:13,SNR1: 6.0445 ,SNR2: 13.239




BLK:13,SNR1: 1.1883 ,SNR2: 4.1087



T20250617165409





BLK: 3,SNR1: 0.19802E-01,SNR2: 0.43626




Frequency (Hz)

F20250617165411




BLK: 3,SNR1:-0.12980 ,SNR2: 0.59997





Frequency (Hz)


1044-008 2025/06/17 7.93UT TOYOKAWA-FUJI




T20250617165409




BLK: 6,SNR1: 0.54352E-01,SNR2: 0.26272




K20250617165406



BLK: 6,SNR1: 0.79836 ,SNR2: 3.6135




1044-008 2025/06/17 7.93UT TOYOKAWA-KISO






F20250617165411




BLK: 4,SNR1:-0.11992E-01,SNR2: 1.6985




Frequency (Hz)

K20250617165406




BLK: 4,SNR1: 0.49980 ,SNR2: 1.5867





Frequency (Hz)


1044-008 2025/06/17 7.93UT FUJI -KISO




T20250617171632




BLK: 3,SNR1:-0.14110E-01,SNR2: 1.4655




F20250617171634




BLK: 3,SNR1:-0.25355E-01,SNR2: 0.60092





1107+109 2025/06/17 8.30UT TOYOKAWA-FUJI







BLK: 2,SNR1: 0.24534 ,SNR2: 0.93808




BLK: 2,SNR1: 0.31289 ,SNR2: 0.75481




1107+109 2025/06/17 8.30UT TOYOKAWA-KISO



F20250617171634





BLK: 7,SNR1: 0.54564 ,SNR2: 3.3190




Frequency (Hz)

K20250617171629







BLK: 7,SNR1: 0.28293 ,SNR2: 1.6005




Frequency (Hz)



1107+109 2025/06/17 8.30UT FUJI -KISO








BLK: 9,SNR1: 0.79500 ,SNR2: 2.5053



BLK: 9,SNR1: 3.2781 ,SNR2: 6.5768



1130+335 2025/06/17 8.70UT TOYOKAWA-KISO

