






T20250618051828




BLK: 3,SNR1: -0.14352E-01,SNR2: 0.65418




F20250618051830




BLK: 3,SNR1: 0.48261E-01,SNR2: 1.5573





2311+469 2025/06/17 20.34UT TOYOKAWA-FUJI







BLK: 2,SNR1: 0.91172E-01,SNR2: 0.37369





BLK: 2,SNR1: 0.27312 ,SNR2: 2.6573




2311+469 2025/06/17 20.34UT TOYOKAWA-KISO










2311+469 2025/06/17 20.34UT FUJI -KISO




T20250618055701




BLK: 3,SNR1: 2.3768 ,SNR2: 7.5898




F20250618055703





BLK: 3,SNR1: 5.2464 ,SNR2: 11.862




2349+327 2025/06/17 20.98UT TOYOKAWA-FUJI




T20250618055701




BLK: 5, SNR1: 1.6565 ,SNR2: 10.849




K20250618055658





BLK: 5, SNR1: 8.1542 ,SNR2: 16.007




2349+327 2025/06/17 20.98UT TOYOKAWA-KISO



F20250618055703





No.Good Data




Frequency (Hz)

K20250618055658




No.Good Data




Frequency (Hz)


2349+327 2025/06/17 20.98UT FUJI -KISO





T20250618061035




BLK: 4,SNR1: 1.1360 ,SNR2: 8.2017




F20250618061037







BLK: 4,SNR1: 1.0853 ,SNR2: 4.0111





0003+313 2025/06/17 21.20UT TOYOKAWA-FUJI









BLK: 2,SNR1: 0.41497 ,SNR2: 1.9355





BLK: 2,SNR1: 0.66181 ,SNR2: 3.2142




0003+313 2025/06/17 21.20UT FUJI -KISO





T20250618061823




BLK: 8, SNR1: 8.7938 , SNR2: 15.758




F20250618061825



BLK: 8, SNR1: 9.3689 , SNR2: 16.768





0011+344 2025/06/17 21.33UT TOYOKAWA-FUJI








T20250618061823




BLK:14,SNR1: 8.7704 ,SNR2: 15.716




K20250618061820





BLK:14,SNR1: 6.6487 ,SNR2: 15.171




0011+344 2025/06/17 21.33UT TOYOKAWA-KISO





F20250618061825




BLK:16,SNR1: 9.3835 ,SNR2: 16.792




K20250618061820





BLK:16,SNR1: 6.7701 ,SNR2: 15.437




0011+344 2025/06/17 21.33UT FUJI -KISO




T20250618063148




BLK: 6, SNR1: 4.6638 , SNR2: 20.569




F20250618063150









BLK: 6, SNR1: 1.0847 , SNR2: 4.2054







0024+125 2025/06/17 21.56UT TOYOKAWA-FUJI













3C12 2025/06/17 21.65UT TOYOKAWA-FUJI







BLK: 3,SNR1: 28.871 ,SNR2: 50.104




BLK: 3,SNR1: 20.771 ,SNR2: 37.258




3C12 2025/06/17 21.65UT TOYOKAWA-KISO




F20250618063716




BLK: 2,SNR1: 8.5078 ,SNR2: 21.050




K20250618063711



BLK: 2,SNR1: 6.4865 ,SNR2: 16.041





3C12 2025/06/17 21.65UT FUJI -KISO








T20250618064532




BLK:27,SNR1: 1.2737 ,SNR2: 2.3896




F20250618064534





BLK:27,SNR1: 6.7108 ,SNR2: 17.477




0038+328 2025/06/17 21.79UT TOYOKAWA-FUJI





T20250618064532




BLK:25,SNR1: 1.5895 ,SNR2: 2.9992




K20250618064529





BLK:25,SNR1: 7.8406 ,SNR2: 20.299




0038+328 2025/06/17 21.79UT TOYOKAWA-KISO





F20250618064534




BLK:35,SNR1: 8.1108 ,SNR2: 14.539




K20250618064529





BLK:35,SNR1: 8.0134 ,SNR2: 20.741




0038+328 2025/06/17 21.79UT FUJI -KISO




T20250618065837




BLK: 1, SNR1: 2.6786 , SNR2: 11.859




F20250618065839





BLK: 1, SNR1: 4.3681 , SNR2: 12.964




3C26 2025/06/17 22.01UT TOYOKAWA-FUJI





T20250618065837




BLK: 1, SNR1: 3.1268 ,SNR2: 9.6781




K20250618065834




BLK: 1, SNR1: 3.5687 ,SNR2: 14.849




3C26 2025/06/17 22.01UT TOYOKAWA-KISO



F20250618065839





BLK: 1, SNR1: 12.368 , SNR2: 19.934





3C26 2025/06/17 22.01UT FUJI -KISO



K20250618065834




BLK: 1, SNR1: 3.5795 , SNR2: 12.263





T20250618070336




BLK: 6,SNR1: 2.8123 ,SNR2: 6.1342




F20250618070338





BLK: 6,SNR1: 12.913 ,SNR2: 31.874




0056-00 2025/06/17 22.09UT TOYOKAWA-FUJI




T20250618070336




BLK: 1, SNR1: 1.1457 , SNR2: 2.6824




K20250618070333



BLK: 1, SNR1: 12.711 , SNR2: 17.084





0056-00 2025/06/17 22.09UT TOYOKAWA-KISO







F20250618070338




BLK: 5, SNR1: 11.838 , SNR2: 26.077




K20250618070333





BLK: 5, SNR1: 8.2456 , SNR2: 14.779




0056-00 2025/06/17 22.09UT FUJI -KISO





T20250618071318




BLK: 3, SNR1: 2.0364 , SNR2: 12.938




F20250618071320





BLK: 3, SNR1: 19.364 , SNR2: 35.048




0106+01 2025/06/17 22.25UT TOYOKAWA-FUJI





T20250618071318




BLK: 2, SNR1: 7.9542 , SNR2: 14.562




K20250618071315




BLK: 2, SNR1: 13.161 , SNR2: 23.890




0106+01 2025/06/17 22.25UT TOYOKAWA-KISO





F20250618071320




BLK: 4,SNR1: 11.318 ,SNR2: 27.684




K20250618071315




BLK: 4,SNR1: 9.2465 ,SNR2: 22.772





0106+01 2025/06/17 22.25UT FUJI -KISO







BLK: 1, SNR1: 3.6706 ,SNR2: 14.928





BLK: 1, SNR1: 15.457 ,SNR2: 24.987




0115-01 2025/06/17 22.41UT TOYOKAWA-FUJI



T20250618072241





No.Good Data




Frequency (Hz)

K20250618072238




No.Good Data




Frequency (Hz)


0115-01 2025/06/17 22.41UT TOYOKAWA-KISO




F20250618072243




BLK: 3, SNR1: 3.5322 , SNR2: 10.860




K20250618072238





BLK: 3, SNR1: 10.172 , SNR2: 16.650




0115-01 2025/06/17 22.41UT FWJ -KISO



T20250618073540





BLK: 1,SNR1: 7.7707 ,SNR2: 19.270





0128+03 2025/06/17 22.62UT TOYOKAWA-FUJI

F20250618073542





BLK: 1,SNR1: 7.4659 ,SNR2: 26.938








T20250618073540




BLK: 1,SNR1: 15.212 ,SNR2: 33.202




K20250618073538




BLK: 1,SNR1: 18.980 ,SNR2: 41.192




0128+03 2025/06/17 22.62UT TOYOKAWA-KISO





F20250618073542




BLK: 2, SNR1: 2.8526 , SNR2: 12.985




K20250618073538




BLK: 2, SNR1: 9.5977 , SNR2: 23.646




0128+03 2025/06/17 22.62UT FUJI -KISO



T20250618074214





BLK:17,SNR1: 12.310 ,SNR2: 28.990





3C48 2025/06/17 22.73UT TOYOKAWA-FUJI


F20250618074216




BLK:17,SNR1: 3.1279 ,SNR2: 7.3098



T20250618074214





BLK:12,SNR1: 1.9179 ,SNR2: 18.629





3C48 2025/06/17 22.73UT TOYOKAWA-KISO


K20250618074211




BLK:12,SNR1: 8.4700 ,SNR2: 15.057



F20250618074216




BLK: 7, SNR1: 6.0880 , SNR2: 10.779









3C48 2025/06/17 22.73UT FUJI -KISO

K20250618074211








BLK: 7, SNR1: 9.0536 , SNR2: 15.780






0155-109 2025/06/17 23.06UT TOYOKAWA-FUJI







0155-109 2025/06/17 23.06UT TOYOKAWA-KISO





F20250618080201




BLK: 7,SNR1: 8.5918 ,SNR2: 20.048




K20250618080157




BLK: 7,SNR1: 7.1944 ,SNR2: 17.058





0155-109 2025/06/17 23.06UT FUJI -KISO









BLK: 2,SNR1: 0.34522E-01,SNR2: 1.9647





BLK: 2,SNR1: 5.0845 ,SNR2: 12.934




0202+15 2025/06/17 23.18UT TOYOKAWA-FUJI





T20250618080906




BLK: 7,SNR1: 0.75786E-01,SNR2: 1.5884




K20250618080904







BLK: 7,SNR1: 13.817 ,SNR2: 29.365




0202+15 2025/06/17 23.18UT TOYOKAWA-KISO








0202+15 2025/06/17 23.18UT FUJI -KISO





T20250618082056




BLK:14,SNR1: 89.404 ,SNR2: 117.08




F20250618082058





BLK:14,SNR1: 147.10 ,SNR2: 229.70




0213+178 2025/06/17 23.38UT TOYOKAWA-FUJI





T20250618082056




BLK:10,SNR1: 62.441 ,SNR2: 77.285




K20250618082053





BLK:10,SNR1: 6.4755 ,SNR2: 40.102




0213+178 2025/06/17 23.38UT TOYOKAWA-KISO




F20250618082058




BLK:12,SNR1: 81.733 ,SNR2: 126.74




K20250618082053





BLK:12,SNR1: 14.593 ,SNR2: 50.815




0213+178 2025/06/17 23.38UT FUJI -KISO




T20250618082839




BLK:17,SNR1: 0.38636 ,SNR2: 1.5555




F20250618082841





BLK:17,SNR1: 13.470 ,SNR2: 17.435




3C67 2025/06/17 23.51UT TOYOKAWA-FUJI




T20250618082839




BLK:23,SNR1: 1.4219 ,SNR2: 2.7983




K20250618082836



BLK:23,SNR1: 4.8624 ,SNR2: 9.5944





3C67 2025/06/17 23.51UT TOYOKAWA-KISO







F20250618082841




BLK:17,SNR1: 4.8542 ,SNR2: 12.276




K20250618082836





BLK:17,SNR1: 4.5335 ,SNR2: 14.179




3C67 2025/06/17 23.51UT FUJI -KISO





T20250618084653




BLK: 8, SNR1: 10.995 , SNR2: 17.861




F20250618084655





BLK: 8, SNR1: 0.18994 , SNR2: 3.6625




3C71 2025/06/17 23.81UT TOYOKAWA-FUJI



T20250618084653





BLK:13,SNR1: 14.005 ,SNR2: 29.326





3C71 2025/06/17 23.81UT TOYOKAWA-KISO



K20250618084650




BLK:13,SNR1: 23.567 ,SNR2: 44.868





F20250618084655




BLK:11,SNR1: 0.37758 ,SNR2: 4.5038




K20250618084650





BLK:11,SNR1: 32.533 ,SNR2: 55.503




3C71 2025/06/17 23.81UT FUJI -KISO




T20250618090609




BLK:18,SNR1: 6.3549 ,SNR2: 17.210




F20250618090611





BLK:18,SNR1: 15.907 ,SNR2: 20.018




0258+350 2025/06/18 0.13UT TOYOKAWA-FUJI





T20250618090609




BLK:23,SNR1: 6.3896 ,SNR2: 17.069




K20250618090606




BLK:23,SNR1: 17.203 ,SNR2: 21.559




0258+350 2025/06/18 0.13UT TOYOKAWA-KISO




F20250618090611




BLK:16,SNR1: 6.7063 ,SNR2: 13.678




K20250618090606





BLK:16,SNR1: 15.929 ,SNR2: 26.325




0258+350 2025/06/18 0.13UT FUJI -KISO



T20250618091558





BLK:21,SNR1: 12.928 ,SNR2: 30.297




Frequency (Hz)

F20250618091600




BLK:21,SNR1: 11.692 ,SNR2: 28.636





Frequency (Hz)

0308+305 2025/06/18 0.29UT TOYOKAWA-FUJI






T20250618091558





BLK:26,SNR1: 12.525 ,SNR2: 29.674




Frequency (Hz)

K20250618091555




BLK:26,SNR1: 33.631 ,SNR2: 54.612




Frequency (Hz)


0308+305 2025/06/18 0.29UT TOYOKAWA-KISO





F20250618091600




BLK:25,SNR1: 22.176 ,SNR2: 39.278




K20250618091555





BLK:25,SNR1: 12.871 ,SNR2: 31.396




0308+305 2025/06/18 0.29UT FUJI -KISO




T20250618092418




BLK:15,SNR1: 0.28584 ,SNR2: 3.3334




F20250618092420




BLK:15,SNR1: 8.8856 ,SNR2: 24.128




3C84 2025/06/18 0.43UT TOYOKAWA-FUJI





T20250618092418




BLK: 9, SNR1: 0.36701 , SNR2: 3.3206




K20250618092415




BLK: 9, SNR1: 1.0469 , SNR2: 3.3160




3C84 2025/06/18 0.43UT TOYOKAWA-KISO



F20250618092420





BLK:16,SNR1: 7.8829 ,SNR2: 21.025





3C84 2025/06/18 0.43UT FUJI -KISO


K20250618092415




BLK:16,SNR1: 0.87164 ,SNR2: 3.2621




T20250618093134




BLK: 5,SNR1: 0.15997 ,SNR2: 1.4044




F20250618093136




BLK: 5,SNR1: 4.2513 ,SNR2: 8.2600





0324+119 2025/06/18 0.55UT TOYOKAWA-FUJI







BLK:10,SNR1: 0.31883 ,SNR2: 1.3434







BLK:10,SNR1: 0.82378 ,SNR2: 3.0599




0324+119 2025/06/18 0.55UT TOYOKAWA-KISO










0324+119 2025/06/18 0.55UT FUJI -KISO












0333+32 2025/06/18 0.71UT TOYOKAWA-FUJI








0333+32 2025/06/18 0.71UT TOYOKAWA-KISO





F20250618094053




BLK:15,SNR1: 1.7474 ,SNR2: 3.5269




K20250618094048





BLK:15,SNR1: 1.2148 ,SNR2: 5.3238




0333+32 2025/06/18 0.71UT FUJI -KISO




T20250618095352




BLK: 4,SNR1: 0.28442E-01,SNR2: 0.59210




F20250618095354





BLK: 4,SNR1: 0.42809 ,SNR2: 2.5926




0347+05 2025/06/18 0.93UT TOYOKAWA-FUJI





T20250618095352




BLK: 6,SNR1: 0.58957E-01,SNR2: 0.50920




K20250618095349




BLK: 6,SNR1: 0.11839 ,SNR2: 0.96002




0347+05 2025/06/18 0.93UT TOYOKAWA-KISO




F20250618095354




BLK: 5, SNR1: 0.42342 , SNR2: 4.1658




K20250618095349




BLK: 5, SNR1: 0.24586 , SNR2: 1.2360




0347+05 2025/06/18 0.93UT FUJI -KISO




T20250618100926




BLK: 7,SNR1: 0.17880 ,SNR2: 0.72252




F20250618100928




BLK: 7,SNR1: 1.9056 ,SNR2: 4.3656




0403-132 2025/06/18 1.19UT TOYOKAWA-FUJI





T20250618100926




BLK: 7,SNR1: 0.25679 ,SNR2: 1.3278




K20250618100924



BLK: 7,SNR1: 0.63543 ,SNR2: 2.5114




0403-132 2025/06/18 1.19UT TOYOKAWA-KISO








F20250618100928




BLK: 9,SNR1: 1.0705 ,SNR2: 5.2926




K20250618100924





BLK: 9,SNR1: 0.75841 ,SNR2: 2.8552




0403-132 2025/06/18 1.19UT FUJI -KISO




T20250618101837




BLK: 9,SNR1: 0.19606 ,SNR2: 0.59867




F20250618101839





BLK: 9,SNR1: 0.15368 ,SNR2: 1.6214




0411+05 2025/06/18 1.34UT TOYOKAWA-FUJI





T20250618101837




BLK: 8,SNR1: 9.8881 ,SNR2: 27.066




K20250618101835




BLK: 8,SNR1: 0.18020 ,SNR2: 1.5497





0411+05 2025/06/18 1.34UT TOYOKAWA-KISO







BLK: 6,SNR1: 0.55127E-01,SNR2: 2.3855




BLK: 6,SNR1: 0.51650 ,SNR2: 1.7763




0411+05 2025/06/18 1.34UT FUJI -KISO




T20250618102532




BLK:16,SNR1: 0.19458 ,SNR2: 1.1564




F20250618102534




BLK:16,SNR1: 9.3429 ,SNR2: 22.958




0418+236 2025/06/18 1.45UT TOYOKAWA-FUJI




T20250618102532




BLK:16,SNR1: 0.16116 ,SNR2: 1.0357




K20250618102529





BLK:16,SNR1: 16.015 ,SNR2: 68.124




0418+236 2025/06/18 1.45UT TOYOKAWA-KISO




F20250618102534




BLK:25,SNR1: 5.5210 ,SNR2: 16.330




K20250618102529




BLK:25,SNR1: 10.725 ,SNR2: 45.725




0418+236 2025/06/18 1.45UT FUJI -KISO




T20250618103659




BLK:19,SNR1: 12.349 ,SNR2: 43.282




F20250618103701



BLK:19,SNR1: 0.78247 ,SNR2: 4.5779





3C119 2025/06/18 1.64UT TOYOKAWA-FUJI








T20250618103659




BLK:33,SNR1: 10.485 ,SNR2: 34.853




K20250618103656




BLK:33,SNR1: 1.4239 ,SNR2: 5.4669




3C119 2025/06/18 1.64UT TOYOKAWA-KISO





F20250618103701




BLK:22,SNR1: 0.85284 ,SNR2: 7.4063




K20250618103656





BLK:22,SNR1: 1.5672 ,SNR2: 5.5371




3C119 2025/06/18 1.64UT FUJI -KISO





T20250618112506




BLK:23,SNR1: 29.924 ,SNR2: 51.912




F20250618112508





BLK:23,SNR1: 11.236 ,SNR2: 24.964




3C138 2025/06/18 2.45UT TOYOKAWA-FUJI




T20250618112506




BLK:24,SNR1: 26.084 ,SNR2: 57.565




K20250618112503





BLK:24,SNR1: 0.88445 ,SNR2: 4.0445




3C138 2025/06/18 2.45UT TOYOKAWA-KISO




F20250618112508




BLK:19,SNR1: 9.1072 ,SNR2: 31.188




K20250618112503








BLK:19,SNR1: 0.93856 ,SNR2: 4.1787





3C138 2025/06/18 2.45UT FUJI -KISO








T20250618113840




BLK:30,SNR1: 7.3488 ,SNR2: 21.166




K20250618113837





BLK:30,SNR1: 0.89407 ,SNR2: 3.9111




0531+194 2025/06/18 2.67UT TOYOKAWA-KISO




F20250618113842




BLK:22,SNR1: 2.6529 ,SNR2: 8.0827




K20250618113837



BLK:22,SNR1: 0.91970 ,SNR2: 4.1965




0531+194 2025/06/18 2.67UT FUJI -KISO








T20250618114700




BLK:27,SNR1: 15.112 ,SNR2: 26.711




F20250618114702





BLK:27,SNR1: 10.440 ,SNR2: 14.037




3C147 2025/06/18 2.81UT TOYOKAWA-FUJI




T20250618114700




BLK:30,SNR1: 15.487 ,SNR2: 27.361




K20250618114657




BLK:30,SNR1: 8.0222 ,SNR2: 14.382





3C147 2025/06/18 2.81UT TOYOKAWA-KISO







BLK:27,SNR1: 6.7814 ,SNR2: 17.673







BLK:27,SNR1: 8.0265 ,SNR2: 14.057








3C147 2025/06/18 2.81UT FUJI -KISO






0548+16 2025/06/18 2.95UT TOYOKAWA-FUJI







0548+16 2025/06/18 2.95UT TOYOKAWA-KISO




F20250618115513




BLK:16,SNR1: 0.22971 ,SNR2: 3.8546




K20250618115508




BLK:16,SNR1: 0.62247 ,SNR2: 2.2607




0548+16 2025/06/18 2.95UT FUJI -KISO




T20250618115921




BLK:26,SNR1: 8.7246 ,SNR2: 27.324




F20250618115923




BLK:26,SNR1: 0.41551 ,SNR2: 1.6609




0552+12 2025/06/18 3.02UT TOYOKAWA-FUJI





T20250618115921




BLK:24,SNR1: 8.8704 ,SNR2: 33.336




K20250618115918



BLK:24,SNR1: 0.29447 ,SNR2: 1.3945




0552+12 2025/06/18 3.02UT TOYOKAWA-KISO








F20250618115923




BLK:20,SNR1: 0.41825 ,SNR2: 1.8518




K20250618115918





BLK:20,SNR1: 0.31439 ,SNR2: 1.8035




0552+12 2025/06/18 3.02UT FUJI -KISO




T20250618120348




BLK:12,SNR1: 2.9986 ,SNR2: 15.285




F20250618120350




BLK:12,SNR1: 5.5636 ,SNR2: 14.479





0556+191 2025/06/18 3.09UT TOYOKAWA-FUJI







BLK:14,SNR1: 0.43759 ,SNR2: 2.5354





BLK:14,SNR1: 0.70539 ,SNR2: 3.2103




0556+191 2025/06/18 3.09UT TOYOKAWA-KISO




F20250618120350




BLK: 8, SNR1: 4.2228 , SNR2: 16.828




K20250618120345





BLK: 8, SNR1: 0.66834 , SNR2: 3.8480




0556+191 2025/06/18 3.09UT FUJI -KISO




T20250618120821




BLK:14,SNR1: 2.7370 ,SNR2: 8.1337




F20250618120823





BLK:14,SNR1: 1.5536 ,SNR2: 6.1910




3C152 2025/06/18 3.17UT TOYOKAWA-FUJI




T20250618120821




BLK:14,SNR1: 2.6150 ,SNR2: 8.5883




K20250618120818




BLK:14,SNR1: 0.56095 ,SNR2: 2.4255




3C152 2025/06/18 3.17UT TOYOKAWA-KISO




F20250618120823




BLK: 4,SNR1: 0.90505 ,SNR2: 3.1204




K20250618120818




BLK: 4,SNR1: 0.38371 ,SNR2: 1.6946




3C152 2025/06/18 3.17UT FUJI -KISO




T20250618123041




BLK:10,SNR1: 1.6213 ,SNR2: 6.7803




F20250618123043




BLK:10,SNR1: 2.2458 ,SNR2: 4.8563





3C161 2025/06/18 3.54UT TOYOKAWA-FUJI









BLK:20,SNR1: 1.5299 ,SNR2: 6.3753




BLK:20,SNR1: 0.55341 ,SNR2: 2.0710




3C161 2025/06/18 3.54UT TOYOKAWA-KISO





F20250618123043




BLK: 7,SNR1: 0.37241 ,SNR2: 2.1867




K20250618123038





BLK: 7,SNR1: 1.6392 ,SNR2: 7.0332




3C161 2025/06/18 3.54UT FUJI -KISO




T20250618125814




BLK: 1,SNR1: 0.61502 ,SNR2: 2.9747




F20250618125816




BLK: 1,SNR1: 0.27808 ,SNR2: 4.9532




0652-130 2025/06/18 4.00UT TOYOKAWA-FUJI





T20250618125814




BLK: 2,SNR1: 0.32024E-01,SNR2: 0.42621




K20250618125811




BLK: 2,SNR1: 0.81037,SNR2: 3.0379





0652-130 2025/06/18 4.00UT TOYOKAWA-KISO









BLK: 2,SNR1: 0.15415 ,SNR2: 1.1401




BLK: 2,SNR1: 0.51387 ,SNR2: 2.0413





T20250618130951




BLK: 8,SNR1: 7.5602 ,SNR2: 13.526




F20250618130953





BLK: 8,SNR1: 2.4440 ,SNR2: 6.9697




0703+138 2025/06/18 4.19UT TOYOKAWA-FUJI





T20250618130951




BLK:14,SNR1: 6.5581 ,SNR2: 11.738




K20250618130948





BLK:14,SNR1: 7.0753 ,SNR2: 12.644




0703+138 2025/06/18 4.19UT TOYOKAWA-KISO





F20250618130953




BLK:11,SNR1: 5.6776 ,SNR2: 14.645




K20250618130948



BLK:11,SNR1: 6.9530 ,SNR2: 12.471





0703+138 2025/06/18 4.19UT FUJI -KISO








T20250618131914




BLK: 3,SNR1: 0.11300 ,SNR2: 0.62662




F20250618131916





BLK: 3,SNR1: 0.67339 ,SNR2: 9.2090




0713-024 2025/06/18 4.35UT TOYOKAWA-FUJI





T20250618131914




BLK: 5,SNR1: 0.12607 ,SNR2: 1.0715




K20250618131911





BLK: 5,SNR1: 0.27050E-01,SNR2: 2.8526




0713-024 2025/06/18 4.35UT TOYOKAWA-KISO





F20250618131916




BLK: 3,SNR1: 0.62380 ,SNR2: 5.5206




K20250618131911









BLK: 3,SNR1: 0.24796 ,SNR2: 0.92807





0713-024 2025/06/18 4.35UT FUJI -KISO









BLK: 6,SNR1: 0.74230 ,SNR2: 4.4270




BLK: 6,SNR1: 0.22442 ,SNR2: 0.95075




0723+10 2025/06/18 4.52UT TOYOKAWA-KISO




F20250618132928




BLK: 5,SNR1: 0.61899 ,SNR2: 1.9216




K20250618132923





BLK: 5,SNR1: 0.37970 ,SNR2: 3.0400




0723+10 2025/06/18 4.52UT FUJI -KISO




T20250618133941




BLK:13,SNR1: 5.4928 ,SNR2: 9.6657




F20250618133943





BLK:13,SNR1: 0.42307 ,SNR2: 2.8962




0732+33 2025/06/18 4.69UT TOYOKAWA-FUJI




T20250618133941




BLK:15,SNR1: 1.1425 ,SNR2: 6.2706




K20250618133938



BLK:15,SNR1: 2.2873 ,SNR2: 4.6386





0732+33 2025/06/18 4.69UT TOYOKAWA-KISO







F20250618133943




BLK:18,SNR1: 0.56464 ,SNR2: 3.2574




K20250618133938




BLK:18,SNR1: 1.1625 ,SNR2: 4.8735





0732+33 2025/06/18 4.69UT FUJI -KISO







BLK: 4,SNR1: 3.7155 ,SNR2: 11.252




BLK: 4,SNR1: 15.725 ,SNR2: 26.240




0741-06 2025/06/18 4.82UT TOYOKAWA-FUJI





T20250618134742




BLK: 1,SNR1: 4.6950 ,SNR2: 21.480




K20250618134739




BLK: 1,SNR1: 0.68262 ,SNR2: 4.8578





0741-06 2025/06/18 4.82UT TOYOKAWA-KISO








BLK: 1,SNR1: 3.0068 ,SNR2: 10.461





BLK: 1,SNR1: 0.52512 ,SNR2: 1.7336







BLK: 4,SNR1: 2.7290 ,SNR2: 12.246






BLK: 4,SNR1: 8.7032 ,SNR2: 21.210





0752-200 2025/06/18 4.99UT TOYOKAWA-FUJI






F20250618135728





BLK: 6,SNR1: 11.040 ,SNR2: 27.067




Frequency (Hz)

K20250618135723









BLK: 6,SNR1: 13.694 ,SNR2: 29.144




Frequency (Hz)

0752-200 2025/06/18 4.99UT FUJI -KISO













BLK:12,SNR1: 0.53654 ,SNR2: 1.7876





BLK:12,SNR1: 1.8253 ,SNR2: 5.8531




3C190 2025/06/18 5.11UT TOYOKAWA-KISO





F20250618140503




BLK: 8,SNR1: 0.63904E-01,SNR2: 2.1644




K20250618140458





BLK: 8,SNR1: 1.0564 ,SNR2: 3.5082




3C190 2025/06/18 5.11UT FUJI -KISO





T20250618141727




BLK: 6,SNR1: 1.5517 ,SNR2: 3.8513




F20250618141729




BLK: 6,SNR1: 2.4837 ,SNR2: 7.7141





3C196 2025/06/18 5.32UT TOYOKAWA-FUJI







BLK:11,SNR1: 2.1711 ,SNR2: 4.2413




BLK:11,SNR1: 2.0031 ,SNR2: 6.4331





3C196 2025/06/18 5.32UT TOYOKAWA-KISO







BLK: 2,SNR1: 2.7008 ,SNR2: 6.5285




BLK: 2,SNR1: 1.9544 ,SNR2: 8.2334





3C196 2025/06/18 5.32UT FUJI -KISO







BLK: 9,SNR1: 2.7988 ,SNR2: 6.8470




BLK: 9,SNR1: 280.12 ,SNR2: 997.02





0821+394 2025/06/18 5.50UT TOYOKAWA-FUJI







BLK: 6,SNR1: 2.5012 ,SNR2: 9.4641




BLK: 6,SNR1: 13.648 ,SNR2: 24.338





0821+394 2025/06/18 5.50UT TOYOKAWA-KISO







BLK:11,SNR1: 303.16 ,SNR2: 706.87




BLK:11,SNR1: 10.396 ,SNR2: 16.928





0821+394 2025/06/18 5.50UT FUJI -KISO









BLK: 2,SNR1: 7.7531 ,SNR2: 14.301




BLK: 2,SNR1: 13.633 ,SNR2: 31.786





0834-19 2025/06/18 5.70UT TOYOKAWA-FUJI







BLK: 1,SNR1: 1.5550 ,SNR2: 5.8009




BLK: 1,SNR1: 8.7736 ,SNR2: 22.703





0834-19 2025/06/18 5.70UT TOYOKAWA-KISO







BLK: 2,SNR1: 8.6715 ,SNR2: 21.010





BLK: 2,SNR1: 9.8724 ,SNR2: 29.455




0834-19 2025/06/18 5.70UT FUJI -KISO




T20250618144521




BLK: 1,SNR1:-0.19311E-01,SNR2: 1.8261




F20250618144523




BLK: 1,SNR1: 0.32562 ,SNR2: 1.8078





0839-071 2025/06/18 5.78UT TOYOKAWA-FUJI







BLK: 2,SNR1: 0.37178 ,SNR2: 1.7131




BLK: 2,SNR1: 0.25128 ,SNR2: 1.5886





0839-071 2025/06/18 5.78UT TOYOKAWA-KISO







BLK: 1,SNR1: 20.170 ,SNR2: 34.637




BLK: 1,SNR1: 2.8374 ,SNR2: 9.7419





0839-071 2025/06/18 5.78UT FUJI -KISO







BLK: 5,SNR1: 3.6373 ,SNR2: 10.713





BLK: 5,SNR1: 8.4662 ,SNR2: 21.138




3C208 2025/06/18 5.97UT TOYOKAWA-FUJI




T20250618145622




BLK: 8, SNR1: 3.6168 , SNR2: 10.654




K20250618145620




BLK: 8, SNR1: 5.2430 , SNR2: 13.463





3C208 2025/06/18 5.97UT TOYOKAWA-KISO









BLK: 6,SNR1:-0.41331 ,SNR2: 0.86965




BLK: 6,SNR1: 3.5635 ,SNR2: 6.4417





3C208 2025/06/18 5.97UT FUJI -KISO







BLK: 8,SNR1: 4.2553 ,SNR2: 11.047




BLK: 8,SNR1: 9.5125 ,SNR2: 27.668





3C216 2025/06/18 6.25UT TOYOKAWA-FUJI







BLK: 5,SNR1: 9.6625 ,SNR2: 27.960









BLK: 5,SNR1: 8.0751 ,SNR2: 20.068





3C216 2025/06/18 6.25UT TOYOKAWA-KISO









BLK: 7,SNR1: 7.8595 ,SNR2: 19.505




BLK: 7,SNR1: 7.6669 ,SNR2: 19.484





0919-142 2025/06/18 6.45UT TOYOKAWA-FUJI







BLK: 9,SNR1: 7.0741 ,SNR2: 18.547




BLK: 9,SNR1: 8.6080 ,SNR2: 21.602





0919-142 2025/06/18 6.45UT TOYOKAWA-KISO







BLK: 7,SNR1: 6.8916 ,SNR2: 19.333




BLK: 7,SNR1: 8.4872 ,SNR2: 21.906




0919-142 2025/06/18 6.45UT FUJI -KISO




T20250618153154




BLK: 4,SNR1: 2.7374 ,SNR2: 6.2744




F20250618153156



BLK: 4,SNR1: 1.1814 ,SNR2: 3.1929





0926+117 2025/06/18 6.56UT TOYOKAWA-FUJI






T20250618153154





BLK: 5, SNR1: 4.9518 , SNR2: 30.514




Frequency (Hz)

K20250618153151




BLK: 5, SNR1: 1.8787 , SNR2: 6.6333





Frequency (Hz)


0926+117 2025/06/18 6.56UT TOYOKAWA-KISO



F20250618153156





BLK: 4, SNR1: 3.1918 , SNR2: 10.120




Frequency (Hz)

K20250618153151




BLK: 4, SNR1: 2.1742 , SNR2: 6.5959





Frequency (Hz)


0926+117 2025/06/18 6.56UT FUJI -KISO




T20250618153938




BLK: 5, SNR1: 0.12516 , SNR2: 0.77479




F20250618153940





BLK: 5, SNR1: 0.98161 , SNR2: 7.7951





3C222 2025/06/18 6.69UT TOYOKAWA-FUJI







3C222 2025/06/18 6.69UT TOYOKAWA-KISO








BLK: 8,SNR1: 0.42384 ,SNR2: 4.2402




BLK: 8,SNR1: 0.60534 ,SNR2: 3.8929




T20250618154638




BLK:11,SNR1: 14.595 ,SNR2: 35.946




F20250618154640




BLK:11,SNR1: 9.1827 ,SNR2: 22.765




0941-08 2025/06/18 6.81UT TOYOKAWA-FUJI




T20250618154638




BLK: 5, SNR1: 10.546 , SNR2: 29.888




K20250618154635




BLK: 5, SNR1: 7.4716 , SNR2: 22.277





0941-08 2025/06/18 6.81UT TOYOKAWA-KISO







BLK: 7,SNR1: 9.7213 ,SNR2: 24.797




BLK: 7,SNR1: 11.977 ,SNR2: 29.378





0941-08 2025/06/18 6.81UT FUJI -KISO









BLK: 4,SNR1: 0.17073 ,SNR2: 0.51606




BLK: 4,SNR1: 1.2695 ,SNR2: 3.2026





3C230 2025/06/18 6.94UT TOYOKAWA-FUJI







BLK: 7, SNR1: 0.41796 , SNR2: 1.9563




BLK: 7, SNR1: 1.0359 , SNR2: 3.6091





3C230 2025/06/18 6.94UT TOYOKAWA-KISO











BLK: 6,SNR1: 0.13036 ,SNR2: 2.2036








BLK: 6,SNR1: 3.5669 ,SNR2: 10.766











3C237 2025/06/18 7.21UT TOYOKAWA-FUJI







3C237 2025/06/18 7.21UT TOYOKAWA-KISO






T20250618161717





BLK:10,SNR1: 1.5066 ,SNR2: 4.9767




Frequency (Hz)

F20250618161719







BLK:10,SNR1: 1.2564 ,SNR2: 3.2736




Frequency (Hz)

1011+110 2025/06/18 7.32UT TOYOKAWA-FUJI













BLK:12,SNR1: 1.9029 ,SNR2: 5.1079





BLK:12,SNR1: 2.0431 ,SNR2: 6.7299






1011+110 2025/06/18 7.32UT FUJI -KISO










3C241 2025/06/18 7.44UT TOYOKAWA-FUJI






3C241 2025/06/18 7.44UT TOYOKAWA-KISO








3C241 2025/06/18 7.44UT FUJI -KISO



T20250618164101





BLK: 8,SNR1: 2.1394 ,SNR2: 5.4309




Frequency (Hz)

F20250618164103




BLK: 8,SNR1: 1.2200 ,SNR2: 4.0586





Frequency (Hz)


1035-058 2025/06/18 7.71UT TOYOKAWA-FUJI



T20250618164101





BLK: 6, SNR1: 0.12921 , SNR2: 1.9435




Frequency (Hz)

K20250618164058





BLK: 6, SNR1: 1.0574 , SNR2: 4.3194





Frequency (Hz)

1035-058 2025/06/18 7.71UT TOYOKAWA-KISO







BLK: 7,SNR1: 0.28031E-01,SNR2: 4.4806





BLK: 7,SNR1: 5.2486 ,SNR2: 12.563




1035-058 2025/06/18 7.71UT FUJI -KISO



T20250618165014




BLK: 2,SNR1: 0.14971 ,SNR2: 1.4931




Frequency (Hz)

F20250618165016




BLK: 2,SNR1:-0.33589 ,SNR2: 0.12382E-01




Frequency (Hz)



1044-008 2025/06/18 7.87UT TOYOKAWA-FUJI









BLK: 3,SNR1: 46.952 ,SNR2: 76.952











BLK: 3,SNR1: 0.25448E-01,SNR2: 0.39499





1044-008 2025/06/18 7.87UT TOYOKAWA-KISO












1055+01 2025/06/18 8.05UT TOYOKAWA-KISO



F20250618170120





BLK: 6,SNR1: 0.17926E-03,SNR2: 3.2221




Frequency (Hz)

K20250618170115








BLK: 6,SNR1: 0.85985 ,SNR2: 2.8177




Frequency (Hz)





1055+01 2025/06/18 8.05UT FUJI -KISO











1107+109 2025/06/18 8.24UT TOYOKAWA-FUJI






1107+109 2025/06/18 8.24UT TOYOKAWA-KISO













BLK: 4, SNR1: 0.18935 , SNR2: 0.74458




BLK: 4, SNR1: 0.94847 , SNR2: 4.7886





1130+335 2025/06/18 8.63UT TOYOKAWA-FUJI







BLK: 8,SNR1: 0.16966 ,SNR2: 1.1185









BLK: 8,SNR1: 0.65203 ,SNR2: 3.1964





1130+335 2025/06/18 8.63UT TOYOKAWA-KISO









BLK: 7,SNR1:-0.21824E-01,SNR2: 0.81615





BLK: 7,SNR1: 2.0791 ,SNR2: 5.2475




1206+439 2025/06/18 9.23UT TOYOKAWA-FUJI



T20250618181152




BLK: 3,SNR1: 0.18051 ,SNR2: 0.37377




Frequency (Hz)

K20250618181150




BLK: 3,SNR1: 1.4080 ,SNR2: 3.2614





Frequency (Hz)


1206+439 2025/06/18 9.23UT TOYOKAWA-KISO



F20250618181154




BLK: 6,SNR1: 3.1993 ,SNR2: 6.3101




Frequency (Hz)

K20250618181150



BLK: 6,SNR1: 0.50425 ,SNR2: 2.1710



Frequency (Hz)

1206+439 2025/06/18 9.23UT FUJI -KISO

