








BLK: 6,SNR1: 16.351 ,SNR2: 39.261




BLK: 6,SNR1: 18.285 ,SNR2: 32.246





2332+489 2025/06/21 20.42UT TOYOKAWA-FUJI







BLK: 4,SNR1: 3.0324 ,SNR2: 13.867



BLK: 4,SNR1: 9.2180 ,SNR2: 22.722





2332+489 2025/06/21 20.42UT TOYOKAWA-KISO







F20250622052340




BLK: 3, SNR1: 20.502 , SNR2: 36.451




K20250622052336





BLK: 3, SNR1: 7.9132 , SNR2: 19.202




2332+489 2025/06/21 20.42UT FUJI -KISO





T20250622054731




BLK: 2, SNR1: 4.2393 , SNR2: 16.670




F20250622054731






BLK: 2, SNR1: 4.8079 , SNR2: 16.942





2356+437 2025/06/21 20.82UT TOYOKAWA-FUJI








F20250622054731




BLK: 6,SNR1: 3.4505 ,SNR2: 12.105




K20250622054728




BLK: 6,SNR1: 9.5844 ,SNR2: 13.006





2356+437 2025/06/21 20.82UT FUJI -KISO







BLK: 4,SNR1: 1.9960 ,SNR2: 4.2898







BLK: 4,SNR1: 11.184 ,SNR2: 13.731





0011+344 2025/06/21 21.07UT TOYOKAWA-FUJI







0011+344 2025/06/21 21.07UT TOYOKAWA-KISO







BLK:15,SNR1: 7.5169 ,SNR2: 12.436





BLK:15,SNR1: 10.404 ,SNR2: 18.167




0011+344 2025/06/21 21.07UT FUJI -KISO




T20250622061014




BLK:14,SNR1: 0.56111 ,SNR2: 5.4297




F20250622061014



BLK:14,SNR1: 11.803 ,SNR2: 21.132





0018+241 2025/06/21 21.20UT TOYOKAWA-FUJI








T20250622061014




BLK:12,SNR1: 0.56082 ,SNR2: 5.5989




K20250622061011





BLK:12,SNR1: 10.674 ,SNR2: 19.049




0018+241 2025/06/21 21.20UT TOYOKAWA-KISO



F20250622061014





BLK: 5,SNR1: 12.272 ,SNR2: 19.091




Frequency (Hz)

K20250622061011




BLK: 5,SNR1: 10.136 ,SNR2: 18.298





Frequency (Hz)


0018+241 2025/06/21 21.20UT FUJI -KISO



T20250622062130





BLK: 8, SNR1: 26.549 , SNR2: 39.625






3C12 2025/06/21 21.39UT TOYOKAWA-FUJI

F20250622062130





BLK: 8, SNR1: 22.994 , SNR2: 34.535







BLK: 5, SNR1: 28.385 , SNR2: 42.089





BLK: 5, SNR1: 0.59395 , SNR2: 4.2785




3C12 2025/06/21 21.39UT TOYOKAWA-KISO





F20250622062130




BLK: 6,SNR1: 14.335 ,SNR2: 21.432




K20250622062127





BLK: 6,SNR1: 24.033 ,SNR2: 31.471




3C12 2025/06/21 21.39UT FUJI -KISO



T20250622062948





BLK: 3,SNR1: 1.7965 ,SNR2: 4.3649




Frequency (Hz)

F20250622062948




BLK: 3,SNR1: 1.3312 ,SNR2: 4.6324




Frequency (Hz)


0038+328 2025/06/21 21.52UT TOYOKAWA-FUJI





T20250622062948




BLK: 8,SNR1: 2.1792 ,SNR2: 5.2909




K20250622062945





BLK: 8,SNR1: 8.2429 ,SNR2: 14.419




0038+328 2025/06/21 21.52UT TOYOKAWA-KISO





F20250622062948




BLK: 8, SNR1: 2.3604 , SNR2: 5.6175




K20250622062945







BLK: 8, SNR1: 8.4454 , SNR2: 15.151




0038+328 2025/06/21 21.52UT FUJI -KISO










0056-00 2025/06/21 21.83UT TOYOKAWA-FUJI



T20250622064752





BLK: 9, SNR1: 8.7552 ,SNR2: 15.661




Frequency (Hz)

K20250622064749




BLK: 9, SNR1: 13.338 ,SNR2: 17.915





Frequency (Hz)


0056-00 2025/06/21 21.83UT TOYOKAWA-KISO





F20250622064752




BLK:14,SNR1: 7.6738 ,SNR2: 16.430




K20250622064749





BLK:14,SNR1: 5.5824 ,SNR2: 11.045




0056-00 2025/06/21 21.83UT FUJI -KISO





T20250622065734




BLK:11,SNR1: 2.9462 ,SNR2: 9.3315




F20250622065734





BLK:11,SNR1: 19.570 ,SNR2: 29.677




0106+01 2025/06/21 21.99UT TOYOKAWA-FUJI





T20250622065734




BLK:18,SNR1: 2.9436 ,SNR2: 9.3229




K20250622065731





BLK:18,SNR1: 8.1649 ,SNR2: 14.733




0106+01 2025/06/21 21.99UT TOYOKAWA-KISO





F20250622065734




BLK:18,SNR1: 19.479 ,SNR2: 29.539




K20250622065731





BLK:18,SNR1: 8.1637 ,SNR2: 14.730




0106+01 2025/06/21 21.99UT FUJI -KISO




T20250622070657




BLK:13,SNR1: 2.9272 ,SNR2: 10.301




F20250622070657





BLK:13,SNR1: 59.552 ,SNR2: 74.204




0115-01 2025/06/21 22.14UT TOYOKAWA-FUJI




T20250622070657




BLK:13,SNR1: 30.997 ,SNR2: 57.727




K20250622070654



BLK:13,SNR1: 43.786 ,SNR2: 81.938




0115-01 2025/06/21 22.14UT TOYOKAWA-KISO







F20250622070657




BLK: 9,SNR1: 47.671 ,SNR2: 78.191




K20250622070654




BLK: 9,SNR1: 84.519 ,SNR2: 130.84




0115-01 2025/06/21 22.14UT FUJI -KISO





T20250622071956




BLK:17,SNR1: 19.816 ,SNR2: 31.671




F20250622071956





BLK:17,SNR1: 23.208 ,SNR2: 34.653




0128+03 2025/06/21 22.36UT TOYOKAWA-FUJI





T20250622071956




BLK:13,SNR1: 20.573 ,SNR2: 33.415




K20250622071953




BLK:13,SNR1: 19.193 ,SNR2: 38.096




0128+03 2025/06/21 22.38UT TOYOKAWA-KISO





F20250622071956




BLK:19,SNR1: 7.3664 ,SNR2: 17.113




K20250622071953












BLK:19,SNR1: 19.358 ,SNR2: 37.685




0128+03 2025/06/21 22.36UT FUJI -KISO









3C48 2025/06/21 22.47UT TOYOKAWA-KISO



F20250622072631




BLK:12,SNR1: 0.74915 ,SNR2: 3.1323





3C48 2025/06/21 22.47UT FUJI -KISO



K20250622072628




BLK:12,SNR1: 0.63405 ,SNR2: 2.9730





T20250622074615




BLK: 4, SNR1: 0.14857 , SNR2: 0.69653




F20250622074615



BLK: 4, SNR1: 4.1247 , SNR2: 16.914





0155-109 2025/06/21 22.80UT TOYOKAWA-FUJI






T20250622074615




BLK: 9,SNR1: 0.12769 ,SNR2: 0.49204





0155-109 2025/06/21 22.80UT TOYOKAWA-KISO


K20250622074612




BLK: 9,SNR1: 8.0083 ,SNR2: 18.023




F20250622074615




BLK:15,SNR1: 2.1003 ,SNR2: 8.9128




K20250622074612




BLK:15,SNR1: 5.1625 ,SNR2: 12.120




0155-109 2025/06/21 22.80UT FUJI -KISO



T20250622075322




BLK:13,SNR1: 18.419 ,SNR2: 35.996





0202+15 2025/06/21 22.92UT TOYOKAWA-FUJI



F20250622075322




BLK:13,SNR1: 0.81912 ,SNR2: 4.5448



T20250622075322




BLK: 9, SNR1: 11.364 , SNR2: 15.854





0202+15 2025/06/21 22.92UT TOYOKAWA-KISO


K20250622075319




BLK: 9, SNR1: 1.4426 , SNR2: 4.9928




F20250622075322




BLK: 2,SNR1: 0.26205 ,SNR2: 3.1287




K20250622075319




BLK: 2,SNR1: 2.0250 ,SNR2: 7.6711




0202+15 2025/06/21 22.92UT FUJI -KISO





T20250622080513




BLK: 5, SNR1: 2.7059 , SNR2: 5.4183




F20250622080514





BLK: 5, SNR1: 0.43791 , SNR2: 4.3648




0213+178 2025/06/21 23.12UT TOYOKAWA-FUJI





T20250622080513




BLK:11,SNR1: 1.9438 ,SNR2: 3.0299




K20250622080510




BLK:11,SNR1: 9.5863 ,SNR2: 14.535




0213+178 2025/06/21 23.12UT TOYOKAWA-KISO





F20250622080514




BLK: 7, SNR1: 0.72105 , SNR2: 6.6496




K20250622080510



BLK: 7, SNR1: 1.2046 , SNR2: 6.9576





0213+178 2025/06/21 23.12UT FUJI -KISO








T20250622081255




BLK: 6,SNR1: 0.26951 ,SNR2: 0.89677




F20250622081255





BLK: 6,SNR1: 13.383 ,SNR2: 31.554




3C67 2025/06/21 23.24UT TOYOKAWA-FUJI



T20250622081255




BLK:12,SNR1: 0.29614 ,SNR2: 2.0149





3C67 2025/06/21 23.24UT TOYOKAWA-KISO



K20250622081252




BLK:12,SNR1: 8.1485 ,SNR2: 9.0543





F20250622081255




BLK: 3, SNR1: 13.462 , SNR2: 31.738




K20250622081252





BLK: 3, SNR1: 1.5440 , SNR2: 13.627




3C67 2025/06/21 23.24UT FUJI -KISO




T20250622083110




BLK: 3,SNR1: 0.34584E-01,SNR2: 0.75407




F20250622083110




BLK: 3,SNR1: 0.16262 ,SNR2: 4.9549





3C71 2025/06/21 23.55UT TOYOKAWA-FUJI







BLK: 5,SNR1: 0.28974E-01,SNR2: 1.7059





BLK: 5,SNR1: 0.25000 ,SNR2: 2.5036




3C71 2025/06/21 23.55UT TOYOKAWA-KISO



F20250622083110





BLK: 3,SNR1: 0.79361 ,SNR2: 3.5227





3C71 2025/06/21 23.55UT FUJI -KISO



K20250622083108




BLK: 3,SNR1: 0.38637 ,SNR2: 4.2421




T20250622085025




BLK: 2,SNR1: 0.56971E-01,SNR2: 0.84021




F20250622085025





BLK: 2,SNR1: 4.9704 ,SNR2: 12.513




0258+350 2025/06/21 23.87UT TOYOKAWA-FUJI



T20250622085025




BLK: 3,SNR1: 0.99505E-01,SNR2: 1.3210





0258+350 2025/06/21 23.87UT TOYOKAWA-KISO

K20250622085022




BLK: 3,SNR1: 0.92346 ,SNR2: 4.2594







F20250622085025




BLK: 2,SNR1: 0.93168 ,SNR2: 4.2446




K20250622085022





BLK: 2,SNR1: 0.53664 ,SNR2: 4.3512




0258+350 2025/06/21 23.87UT FUJI -KISO





T20250622085421




BLK: 3,SNR1:-0.28252E-01,SNR2: 0.17637




F20250622085421





BLK: 3,SNR1: 0.14897 ,SNR2: 2.1681




0302+341 2025/06/21 23.93UT TOYOKAWA-FUJI





T20250622085421




BLK: 6, SNR1: 3.1726 , SNR2: 7.2472




K20250622085418




BLK: 6, SNR1: 46.458 , SNR2: 88.128




0302+341 2025/06/21 23.93UT TOYOKAWA-KISO





F20250622085421




BLK: 5, SNR1: 0.47907 , SNR2: 2.3461




K20250622085418







BLK: 5, SNR1: 0.50033 , SNR2: 1.4897




0302+341 2025/06/21 23.93UT FUJI -KISO








0308+305 2025/06/22 0.03UT TOYOKAWA-FUJI



T20250622090014





BLK: 7,SNR1: 0.20896 ,SNR2: 0.81672





0308+305 2025/06/22 0.03UT TOYOKAWA-KISO



K20250622090011




BLK: 7,SNR1: 8.3339 ,SNR2: 20.066





F20250622090014




BLK:19,SNR1: 17.917 ,SNR2: 32.452




K20250622090011





BLK:19,SNR1: 3.7751 ,SNR2: 11.564




0308+305 2025/06/22 0.03UT FUJI -KISO




T20250622090835




BLK: 9, SNR1: 0.13345 , SNR2: 0.82850




F20250622090835



BLK: 9, SNR1: 1.0366 , SNR2: 5.4567





3C84 2025/06/22 0.17UT TOYOKAWA-FUJI






T20250622090835





BLK:16,SNR1: 0.15790 ,SNR2: 1.0309





3C84 2025/06/22 0.17UT TOYOKAWA-KISO


K20250622090833




BLK:16,SNR1: 2.1994 ,SNR2: 10.210





F20250622090835




BLK: 9,SNR1: 3.7249 ,SNR2: 7.6641




K20250622090833





BLK: 9,SNR1: 0.95486 ,SNR2: 3.2119




3C84 2025/06/22 0.17UT FUJI -KISO





T20250622091551




BLK: 2,SNR1: 0.22731 ,SNR2: 0.76492




F20250622091551




BLK: 2,SNR1: 0.24195 ,SNR2: 1.6551




0324+119 2025/06/22 0.29UT TOYOKAWA-FUJI



T20250622091551




BLK: 5,SNR1: 0.62738 ,SNR2: 1.9037





0324+119 2025/06/22 0.29UT TOYOKAWA-KISO



K20250622091549




BLK: 5,SNR1:-0.19675E-01,SNR2: 0.94773




F20250622091551




BLK: 4, SNR1: 0.10192 , SNR2: 1.1359




K20250622091549




BLK: 4, SNR1: 0.38783 , SNR2: 2.6446




0324+119 2025/06/22 0.29UT FUJI -KISO



T20250622092507




BLK: 2,SNR1:-0.10322 ,SNR2: 0.21152




0333+32 2025/06/22 0.45UT TOYOKAWA-FUJI


F20250622092508





BLK: 2,SNR1:-0.13765 ,SNR2: 0.46642




Frequency (Hz)




T20250622092507




BLK: 1,SNR1: 0.42293E-01,SNR2: 0.96602




K20250622092504





BLK: 1,SNR1: 0.61011 ,SNR2: 1.1234




0333+32 2025/06/22 0.45UT TOYOKAWA-KISO





F20250622092508




BLK: 4,SNR1: 0.56749 ,SNR2: 2.2029




K20250622092504



BLK: 4,SNR1:-0.44762E-01,SNR2: 0.26811





0333+32 2025/06/22 0.45UT FUJI -KISO








T20250622093809




BLK: 3,SNR1:-0.62238E-01,SNR2: 0.34249




F20250622093809





BLK: 3,SNR1: 0.70587 ,SNR2: 2.9034




0347+05 2025/06/22 0.66UT TOYOKAWA-FUJI





T20250622093809




BLK: 3,SNR1: 0.13001 ,SNR2: 0.57851




K20250622093806




BLK: 3,SNR1: 0.37359 ,SNR2: 3.1676




0347+05 2025/06/22 0.66UT TOYOKAWA-KISO





F20250622093809




BLK: 6,SNR1: 3.8130 ,SNR2: 18.515




K20250622093806





BLK: 6,SNR1: 0.33625 ,SNR2: 1.3618




0347+05 2025/06/22 0.66UT FUJI -KISO




T20250622095343




BLK: 1, SNR1: -0.11572 , SNR2: 1.7629




F20250622095343







BLK: 1, SNR1: 0.89126 , SNR2: 3.4749








0403-132 2025/06/22 0.92UT TOYOKAWA-FUJI






0403-132 2025/06/22 0.92UT TOYOKAWA-KISO








0403-132 2025/06/22 0.92UT FUJI -KISO




T20250622100254




BLK: 8,SNR1: 0.23711 ,SNR2: 1.0883




F20250622100254







BLK: 8,SNR1: 6.4647 ,SNR2: 11.561




0411+05 2025/06/22 1.08UT TOYOKAWA-FUJI






0411+05 2025/06/22 1.08UT TOYOKAWA-KISO








F20250622100254




BLK:11,SNR1: 4.2658 ,SNR2: 7.7009




K20250622100251








BLK:11,SNR1: 6.0483 ,SNR2: 14.298





0411+05 2025/06/22 1.08UT FUJI -KISO








T20250622100948




BLK: 3,SNR1: 0.17353 ,SNR2: 1.8158




K20250622100945







BLK: 3,SNR1: 0.20441 ,SNR2: 2.1407




0418+236 2025/06/22 1.19UT TOYOKAWA-KISO








0418+236 2025/06/22 1.19UT FUJI -KISO




T20250622102116




BLK:22,SNR1: 3.3469 ,SNR2: 29.505




F20250622102116




BLK:22,SNR1: 5.9766 ,SNR2: 15.984




3C119 2025/06/22 1.38UT TOYOKAWA-FUJI




T20250622102116




BLK:26,SNR1: 3.6492 ,SNR2: 31.747




K20250622102113




BLK:26,SNR1: 0.53634 ,SNR2: 4.1287




3C119 2025/06/22 1.38UT TOYOKAWA-KISO




F20250622102116




BLK:13,SNR1: 0.69940 ,SNR2: 5.7307




K20250622102113




BLK:13,SNR1: 0.50835 ,SNR2: 2.7342




3C119 2025/06/22 1.38UT FUJI -KISO




T20250622110923




BLK:35,SNR1: 10.664 ,SNR2: 46.991




F20250622110923



BLK:35,SNR1: 0.42102 ,SNR2: 3.5173




3C138 2025/06/22 2.18UT TOYOKAWA-FUJI







T20250622110923




BLK:30,SNR1: 10.805 ,SNR2: 47.555




K20250622110920




BLK:30,SNR1: 1.0960 ,SNR2: 3.2092




3C138 2025/06/22 2.18UT TOYOKAWA-KISO





F20250622110923




BLK:22,SNR1: 0.39851 ,SNR2: 3.4039




K20250622110920







BLK:22,SNR1: 1.2321 ,SNR2: 4.7099









3C138 2025/06/22 2.18UT FUJI -KISO








0531+194 2025/06/22 2.41UT TOYOKAWA-FUJI









BLK:20,SNR1: 5.3077 ,SNR2: 12.528




BLK:20,SNR1: 0.11577 ,SNR2: 6.6680




0531+194 2025/06/22 2.41UT FUJI -KISO




T20250622113116




BLK:27,SNR1: 28.160 ,SNR2: 63.473




F20250622113116





BLK:27,SNR1: 0.60030 ,SNR2: 6.2148




3C147 2025/06/22 2.55UT TOYOKAWA-FUJI



T20250622113116





BLK:39,SNR1: 25.755 ,SNR2: 121.46




Frequency (Hz)

K20250622113113




BLK:39,SNR1: 3.2374 ,SNR2: 23.247




Frequency (Hz)


3C147 2025/06/22 2.55UT TOYOKAWA-KISO





F20250622113116




BLK:31,SNR1: 0.64684 ,SNR2: 6.5410




K20250622113113




BLK:31,SNR1: 3.4266 ,SNR2: 17.324





3C147 2025/06/22 2.55UT FUJI -KISO









BLK: 4, SNR1: 0.95172 , SNR2: 3.0186




BLK: 4, SNR1: 0.26565 , SNR2: 2.0561





0548+16 2025/06/22 2.69UT TOYOKAWA-FUJI







BLK: 6,SNR1: 5.9157 ,SNR2: 10.221




BLK: 6,SNR1: 0.64244 ,SNR2: 3.2023




0548+16 2025/06/22 2.69UT TOYOKAWA-KISO





F20250622113927




BLK: 3,SNR1: 1.2489 ,SNR2: 5.9523




K20250622113924




BLK: 3,SNR1: 7.1743 ,SNR2: 14.160





0548+16 2025/06/22 2.69UT FUJI -KISO







BLK:10,SNR1: 20.151 ,SNR2: 62.043







BLK:10,SNR1: 1.6224 ,SNR2: 4.4222




0552+12 2025/06/22 2.76UT TOYOKAWA-FUJI








0552+12 2025/06/22 2.76UT TOYOKAWA-KISO





F20250622114338




BLK: 2,SNR1: 2.1920 ,SNR2: 9.8104




K20250622114335







BLK: 2,SNR1: 0.10064E-01,SNR2: 1.9155




0552+12 2025/06/22 2.76UT FUJI -KISO








0556+191 2025/06/22 2.83UT TOYOKAWA-FUJI



T20250622114805





BLK:10,SNR1: 1.3093 ,SNR2: 3.6771




Frequency (Hz)

K20250622114802




BLK:10,SNR1: 10.012 ,SNR2: 17.853




Frequency (Hz)



0556+191 2025/06/22 2.83UT TOYOKAWA-KISO









BLK:10,SNR1: 21.165 ,SNR2: 37.276





BLK:10,SNR1: 16.054 ,SNR2: 28.575




0556+191 2025/06/22 2.83UT FUJI -KISO




T20250622115237




BLK:10,SNR1: 0.95944 ,SNR2: 2.4085




F20250622115238





BLK:10,SNR1: 180.20 ,SNR2: 171.76




3C152 2025/06/22 2.91UT TOYOKAWA-FUJI





T20250622115237




BLK:10,SNR1: 0.80724 ,SNR2: 2.2051




K20250622115234




BLK:10,SNR1: 3.2463 ,SNR2: 9.2811





3C152 2025/06/22 2.91UT TOYOKAWA-KISO







BLK:15,SNR1: 139.68 ,SNR2: 133.15




BLK:15,SNR1: 2.3548 ,SNR2: 10.770





3C152 2025/06/22 2.91UT FUJI -KISO







BLK:19,SNR1: 8.0918 ,SNR2: 14.430













BLK:19,SNR1: 7.3995 ,SNR2: 13.360




3C161 2025/06/22 3.28UT TOYOKAWA-FUJI










T20250622124231




BLK: 1,SNR1: 10.829 ,SNR2: 26.603




F20250622124232



BLK: 1,SNR1: 7.0567 ,SNR2: 17.582




0652-130 2025/06/22 3.74UT TOYOKAWA-FUJI








T20250622124231




BLK: 3,SNR1: 7.4200 ,SNR2: 17.120




K20250622124228





BLK: 3,SNR1: 12.748 ,SNR2: 22.964




0652-130 2025/06/22 3.74UT TOYOKAWA-KISO





F20250622124232




BLK: 2,SNR1: 10.080 ,SNR2: 18.073




K20250622124228




BLK: 2,SNR1: 12.332 ,SNR2: 30.204





0652-130 2025/06/22 3.74UT FUJI -KISO







BLK: 1,SNR1:-0.20985 ,SNR2: 0.58626




BLK: 1,SNR1: 0.34330E-01,SNR2: 0.91084





0703+138 2025/06/22 3.93UT TOYOKAWA-FUJI







BLK: 1,SNR1: 22.982 ,SNR2: 28.258






BLK: 1,SNR1: 7.9887 ,SNR2: 21.126





0703+138 2025/06/22 3.93UT TOYOKAWA-KISO







T20250622130330




BLK: 2,SNR1: 7.4420 ,SNR2: 18.693




F20250622130330





BLK: 2,SNR1: 2.1953 ,SNR2: 6.5484




0713-024 2025/06/22 4.09UT TOYOKAWA-FUJI




T20250622130330




BLK: 4,SNR1: 3.4954 ,SNR2: 6.8356




K20250622130327




BLK: 4,SNR1: 9.8913 ,SNR2: 23.682




0713-024 2025/06/22 4.09UT TOYOKAWA-KISO





F20250622130330




BLK: 6,SNR1: 6.8861 ,SNR2: 16.497




K20250622130327








BLK: 6,SNR1: 5.9785 ,SNR2: 11.951




0713-024 2025/06/22 4.09UT FUJI -KISO









T20250622131342




BLK: 3,SNR1: 3.1219 ,SNR2: 7.9333




K20250622131339




BLK: 3,SNR1: 7.9425 ,SNR2: 20.513




0723+10 2025/06/22 4.26UT TOYOKAWA-KISO




F20250622131342




BLK: 2,SNR1: 2.9770 ,SNR2: 9.4251




K20250622131339




BLK: 2,SNR1: 6.6634 ,SNR2: 17.295




0723+10 2025/06/22 4.26UT FUJI -KISO




T20250622132357




BLK: 9,SNR1: 0.69534 ,SNR2: 2.9561




F20250622132358




BLK: 9,SNR1: 5.3393 ,SNR2: 15.366




0732+33 2025/06/22 4.43UT TOYOKAWA-FUJI




T20250622132357




BLK: 9,SNR1: 1.9211 ,SNR2: 5.1049




K20250622132354




BLK: 9,SNR1: 2.7317 ,SNR2: 5.4823




0732+33 2025/06/22 4.43UT TOYOKAWA-KISO




F20250622132358




BLK: 6,SNR1: 5.1135 ,SNR2: 12.134




K20250622132354




BLK: 6,SNR1: 6.0236 ,SNR2: 17.348




0732+33 2025/06/22 4.43UT FUJI -KISO





T20250622133158




BLK: 4,SNR1: 0.27325 ,SNR2: 3.3944




F20250622133158





BLK: 4,SNR1: 9.8523 ,SNR2: 24.300




0741-06 2025/06/22 4.56UT TOYOKAWA-FUJI





T20250622133158




BLK: 5, SNR1: 1.5637 , SNR2: 3.5084




K20250622133155




BLK: 5, SNR1: 5.4487 , SNR2: 13.198





0741-06 2025/06/22 4.56UT TOYOKAWA-KISO











BLK: 3,SNR1: 0.50630 ,SNR2: 5.4397




BLK: 3,SNR1: 12.792 ,SNR2: 31.278








0752-200 2025/06/22 4.72UT TOYOKAWA-FUJI





T20250622134142




BLK: 4,SNR1: 0.78313 ,SNR2: 6.6841




K20250622134139








BLK: 4,SNR1: 5.8193 ,SNR2: 22.031





0752-200 2025/06/22 4.72UT TOYOKAWA-KISO








T20250622134918




BLK: 6,SNR1: 3.7880 ,SNR2: 10.827




F20250622134918





BLK: 6,SNR1: 6.7582 ,SNR2: 19.419




3C190 2025/06/22 4.85UT TOYOKAWA-FUJI





T20250622134918




BLK: 7,SNR1: 9.8006 ,SNR2: 19.002




K20250622134915





BLK: 7,SNR1: 9.9841 ,SNR2: 28.942




3C190 2025/06/22 4.85UT TOYOKAWA-KISO





F20250622134918




BLK: 7,SNR1: 6.9662 ,SNR2: 19.484




K20250622134915





BLK: 7,SNR1: 10.102 ,SNR2: 29.264




3C190 2025/06/22 4.85UT FUJI -KISO




T20250622140143




BLK:16,SNR1: 0.93135 ,SNR2: 2.9431




F20250622140143



BLK:16,SNR1: 1.6576 ,SNR2: 5.1426





3C196 2025/06/22 5.06UT TOYOKAWA-FUJI







T20250622140143




BLK:23,SNR1: 1.3554 ,SNR2: 3.9110




K20250622140140




BLK:23,SNR1: 1.5517 ,SNR2: 6.0912




3C196 2025/06/22 5.06UT TOYOKAWA-KISO





F20250622140143




BLK:19,SNR1: 1.9441 ,SNR2: 5.9640




K20250622140140





BLK:19,SNR1: 1.6162 ,SNR2: 6.5454




3C196 2025/06/22 5.06UT FUJI -KISO




T20250622141253




BLK: 8,SNR1: 0.11858 ,SNR2: 0.87677




F20250622141253





BLK: 8,SNR1: 0.27423 ,SNR2: 3.9041




0821+394 2025/06/22 5.24UT TOYOKAWA-FUJI




T20250622141253




BLK: 4,SNR1: 0.20460 ,SNR2: 1.6330




K20250622141250





BLK: 4,SNR1: 0.63148E-01,SNR2: 1.2883





0821+394 2025/06/22 5.24UT TOYOKAWA-KISO




F20250622141253





K20250622141250




0821+394 2025/06/22 5.24UT FUJI -KISO




T20250622142432




BLK: 7,SNR1: 3.7264 ,SNR2: 8.8705




F20250622142432




BLK: 7,SNR1: 1.7625 ,SNR2: 5.9306





0834-19 2025/06/22 5.44UT TOYOKAWA-FUJI







BLK: 1,SNR1: 0.81650 ,SNR2: 3.7403




BLK: 1,SNR1: 1.3723 ,SNR2: 7.3439





0834-19 2025/06/22 5.44UT TOYOKAWA-KISO







BLK: 2,SNR1: 0.97407 ,SNR2: 6.3619




BLK: 2,SNR1: 1.7575 ,SNR2: 5.6298








T20250622142937




BLK:12,SNR1: 15.551 ,SNR2: 23.450




F20250622142937




BLK:12,SNR1: 3.4284 ,SNR2: 10.372




0839-071 2025/06/22 5.52UT TOYOKAWA-FUJI





T20250622142937




BLK:18,SNR1: 15.469 ,SNR2: 23.315




K20250622142934





BLK:18,SNR1: 10.371 ,SNR2: 25.958




0839-071 2025/06/22 5.52UT TOYOKAWA-KISO





F20250622142937




BLK:12,SNR1: 4.1651 ,SNR2: 11.362




K20250622142934





BLK:12,SNR1: 7.2986 ,SNR2: 19.531




0839-071 2025/06/22 5.52UT FUJI -KISO




T20250622144038




BLK: 2,SNR1: 0.40168 ,SNR2: 1.7295




F20250622144038





BLK: 2,SNR1: 0.14585 ,SNR2: 0.82578




3C208 2025/06/22 5.71UT TOYOKAWA-FUJI




T20250622144038




BLK: 7,SNR1: 0.65251 ,SNR2: 2.2346




K20250622144035




BLK: 7,SNR1: 1.2181 ,SNR2: 2.4542






3C208 2025/06/22 5.71UT TOYOKAWA-KISO




F20250622144038





K20250622144035




3C208 2025/06/22 5.71UT FUJI -KISO





T20250622145720




BLK: 6,SNR1: 0.34453 ,SNR2: 1.2284




F20250622145720




BLK: 6,SNR1: 1.0875 ,SNR2: 3.0443





3C216 2025/06/22 5.98UT TOYOKAWA-FUJI







BLK: 7,SNR1: 0.25028 ,SNR2: 1.4142



BLK: 7,SNR1: 1.7303 ,SNR2: 5.3691




3C216 2025/06/22 5.98UT TOYOKAWA-KISO






F20250622145720




BLK:14,SNR1: 1.2935 ,SNR2: 3.9916




Frequency (Hz)

K20250622145717




BLK:14,SNR1: 1.2708 ,SNR2: 4.0273





Frequency (Hz)


3C216 2025/06/22 5.98UT FUJI -KISO



T20250622150931





BLK: 1,SNR1:-0.97072E-01,SNR2: 1.0058




Frequency (Hz)

F20250622150931





BLK: 1,SNR1:-0.22318 ,SNR2: 0.90023





Frequency (Hz)

0919-142 2025/06/22 6.19UT TOYOKAWA-FUJI







BLK: 7,SNR1: 0.21700 ,SNR2: 0.72972




BLK: 7,SNR1: 0.10206 ,SNR2: 0.40382





0919-142 2025/06/22 6.19UT TOYOKAWA-KISO







BLK: 2,SNR1:-0.91860E-01,SNR2: 1.7160





BLK: 2,SNR1:-0.55274E-01,SNR2: 0.18349




0919-142 2025/06/22 6.19UT FUJI -KISO





T20250622151610




BLK: 4,SNR1: 1.0525 ,SNR2: 3.2004




F20250622151610




BLK: 4,SNR1: 6.1239 ,SNR2: 15.563





0926+117 2025/06/22 6.30UT TOYOKAWA-FUJI







BLK: 4,SNR1: 0.33676 ,SNR2: 0.83478




BLK: 4,SNR1: 10.458 ,SNR2: 26.459





0926+117 2025/06/22 6.30UT TOYOKAWA-KISO







BLK: 6,SNR1: 6.7849 ,SNR2: 19.636




BLK: 6,SNR1: 12.364 ,SNR2: 29.171





0926+117 2025/06/22 6.30UT FUJI -KISO







BLK: 7,SNR1: 0.40279 ,SNR2: 1.3230




BLK: 7,SNR1: 0.83576E-01,SNR2: 1.5280





3C222 2025/06/22 6.43UT TOYOKAWA-FUJI









BLK: 8,SNR1: 0.14931 ,SNR2: 1.6699




BLK: 8,SNR1: 0.90417 ,SNR2: 2.8120





3C222 2025/06/22 6.43UT TOYOKAWA-KISO







BLK: 4,SNR1:-0.87138E-01,SNR2: 2.6430





BLK: 4,SNR1: 0.55614 ,SNR2: 2.2746




3C222 2025/06/22 6.43UT FUJI -KISO



T20250622153055




BLK: 6,SNR1: 0.36930 ,SNR2: 1.1841




Frequency (Hz)

F20250622153055







BLK: 6,SNR1: 0.94046 ,SNR2: 3.5984








Frequency (Hz)



0941-08 2025/06/22 6.54UT TOYOKAWA-FUJI








T20250622153917





BLK:11,SNR1: 5.5353 ,SNR2: 19.480




Frequency (Hz)

F20250622153917





BLK:11,SNR1: 0.93552 ,SNR2: 3.4129





Frequency (Hz)

3C230 2025/06/22 6.68UT TOYOKAWA-FUJI







BLK: 9,SNR1: 7.1510 ,SNR2: 32.174




BLK: 9,SNR1: 3.9432 ,SNR2: 11.283




3C230 2025/06/22 6.68UT TOYOKAWA-KISO



F20250622153917




BLK: 6,SNR1: 0.19529 ,SNR2: 2.3903




Frequency (Hz)

K20250622153914




BLK: 6,SNR1: 5.1415 ,SNR2: 10.091




Frequency (Hz)



3C230 2025/06/22 6.68UT FUJI -KISO









BLK:20,SNR1: 0.66903 ,SNR2: 2.9203




BLK:20,SNR1: 4.0670 ,SNR2: 11.259





3C237 2025/06/22 6.95UT TOYOKAWA-FUJI







BLK:21,SNR1: 0.69123 ,SNR2: 4.0857





BLK:21,SNR1: 3.7116 ,SNR2: 10.369




3C237 2025/06/22 6.95UT TOYOKAWA-KISO



F20250622155517





BLK:28,SNR1: 4.1020 ,SNR2: 11.347




Frequency (Hz)

K20250622155514




BLK:28,SNR1: 3.7193 ,SNR2: 10.387





Frequency (Hz)


3C237 2025/06/22 6.95UT FUJI -KISO



T20250622160134





BLK: 6,SNR1: 0.11193 ,SNR2: 0.57870




Frequency (Hz)

F20250622160134








BLK: 6,SNR1: 3.5246 ,SNR2: 5.5245




Frequency (Hz)

1011+110 2025/06/22 7.05UT TOYOKAWA-FUJI







1011+110 2025/06/22 7.05UT TOYOKAWA-KISO



F20250622160134




BLK: 8, SNR1: 5.4891 , SNR2: 14.210




Frequency (Hz)

K20250622160131




BLK: 8, SNR1: 5.8574 , SNR2: 16.652





Frequency (Hz)


1011+110 2025/06/22 7.05UT FUJI -KISO




T20250622160915




BLK: 6,SNR1: 0.23210 ,SNR2: 1.3720




F20250622160915




BLK: 6,SNR1: 0.33171 ,SNR2: 3.9718





3C241 2025/06/22 7.18UT TOYOKAWA-FUJI







BLK: 4,SNR1: 0.64306 ,SNR2: 2.5758



BLK: 4,SNR1: 0.64196 ,SNR2: 2.1687





3C241 2025/06/22 7.18UT TOYOKAWA-KISO






F20250622160915





BLK: 1,SNR1: 0.55157E-01,SNR2: 0.75074




Frequency (Hz)

K20250622160912




BLK: 1,SNR1: 0.18145 ,SNR2: 1.9130





Frequency (Hz)


3C241 2025/06/22 7.18UT FUJI -KISO



T20250622162044





BLK: 7, SNR1: 0.19810 , SNR2: 1.8114




Frequency (Hz)

F20250622162044







BLK: 7, SNR1: 0.56821 , SNR2: 2.4776




Frequency (Hz)



1031-11 2025/06/22 7.37UT TOYOKAWA-FUJI











BLK:12,SNR1: 0.60986 ,SNR2: 2.4182




BLK:12,SNR1: 0.83444 ,SNR2: 2.8357



T20250622162517





BLK: 9,SNR1: 6.9321 ,SNR2: 70.386




Frequency (Hz)

F20250622162517




BLK: 9,SNR1:-0.14498 ,SNR2: 0.68584





Frequency (Hz)


1035-058 2025/06/22 7.45UT TOYOKAWA-FUJI



T20250622162517




BLK:12,SNR1: 9.8790 ,SNR2: 69.182




Frequency (Hz)

K20250622162514




BLK:12,SNR1: 2.2634 ,SNR2: 4.6244




Frequency (Hz)


1035-058 2025/06/22 7.45UT TOYOKAWA-KISO



F20250622162517




BLK: 5, SNR1: 0.11758 , SNR2: 1.4684




Frequency (Hz)

K20250622162514




BLK: 5, SNR1: 1.5280 , SNR2: 6.0458





Frequency (Hz)


1035-058 2025/06/22 7.45UT FUJI -KISO



T20250622163430





BLK: 5, SNR1: 3.0597 , SNR2: 9.4079




Frequency (Hz)

F20250622163431




BLK: 5, SNR1: 2.2432 , SNR2: 6.3500




Frequency (Hz)



1044-008 2025/06/22 7.60UT TOYOKAWA-FUJI









BLK:10,SNR1: 9.6637 ,SNR2: 20.908




BLK:10,SNR1: 8.0663 ,SNR2: 18.589





1044-008 2025/06/22 7.60UT TOYOKAWA-KISO







BLK: 6,SNR1: 3.6422 ,SNR2: 8.7138







BLK: 6,SNR1: 5.0402 ,SNR2: 13.593




1044-008 2025/06/22 7.60UT FUJI -KISO







1055+01 2025/06/22 7.79UT TOYOKAWA-FUJI



T20250622164534





BLK:11,SNR1: 0.22524 ,SNR2: 1.1566




Frequency (Hz)

K20250622164531








BLK:11,SNR1: 4.4869 ,SNR2: 8.9496




Frequency (Hz)


1055+01 2025/06/22 7.79UT TOYOKAWA-KISO







1055+01 2025/06/22 7.79UT FUJI -KISO







BLK: 5,SNR1: 0.14235E-01,SNR2: 0.53410




BLK: 5,SNR1: 0.36837 ,SNR2: 1.5608





1107+109 2025/06/22 7.98UT TOYOKAWA-FUJI







BLK: 5, SNR1: 0.36684 , SNR2: 2.6023





BLK: 5, SNR1: 0.85166 , SNR2: 1.8458




1107+109 2025/06/22 7.98UT TOYOKAWA-KISO














1107+109 2025/06/22 7.98UT FUJI -KISO













3C263.1 2025/06/22 8.54UT TOYOKAWA-KISO



F20250622173027





BLK: 3,SNR1: 1.9462 ,SNR2: 6.9580




Frequency (Hz)

K20250622173024








BLK: 3,SNR1: 0.60911 ,SNR2: 3.2137




Frequency (Hz)

3C263.1 2025/06/22 8.54UT FUJI -KISO








1206+439 2025/06/22 8.96UT TOYOKAWA-FUJI



T20250622175609





BLK: 2,SNR1: 0.33950 ,SNR2: 1.3811




Frequency (Hz)

K20250622175606









BLK: 2,SNR1: 2.9897 ,SNR2: 8.1210







Frequency (Hz)


1206+439 2025/06/22 8.96UT TOYOKAWA-KISO












1222+423 2025/06/22 9.22UT TOYOKAWA-FUJI









1222+423 2025/06/22 9.22UT TOYOKAWA-KISO







1222+423 2025/06/22 9.22UT FUJI -KISO

