





T20250627052751




BLK:12,SNR1: 11.522 ,SNR2: 22.366




F20250627052751





BLK:12,SNR1: 9.1074 ,SNR2: 15.944




2356+437 2025/06/26 20.49UT TOYOKAWA-FUJI





T20250627052751




BLK: 6, SNR1: 10.979 , SNR2: 21.351




K20250627052748



BLK: 6, SNR1: 18.804 , SNR2: 24.327




2356+437 2025/06/26 20.49UT TOYOKAWA-KISO








F20250627052751




BLK: 7, SNR1: 8.2326 , SNR2: 14.711




K20250627052748




BLK: 7, SNR1: 16.711 , SNR2: 28.247





2356+437 2025/06/26 20.49UT FUJI -KISO







BLK:12,SNR1: 0.29432 ,SNR2: 1.2715




BLK:12,SNR1: 11.828 ,SNR2: 26.445





0038+328 2025/06/26 21.20UT TOYOKAWA-FUJI







BLK:16,SNR1: 0.39032 ,SNR2: 1.4884





BLK:16,SNR1: 4.3711 ,SNR2: 9.9059




0038+328 2025/06/26 21.20UT TOYOKAWA-KISO





F20250627061009




BLK:28,SNR1: 11.609 ,SNR2: 25.960




K20250627061006




BLK:28,SNR1: 6.2132 ,SNR2: 16.793




0038+328 2025/06/26 21.20UT FUJI -KISO





T20250627063157




BLK:14,SNR1: 4.9359 ,SNR2: 14.615




F20250627063158




BLK:14,SNR1: 6.8723 ,SNR2: 16.762




0100+146 2025/06/26 21.56UT TOYOKAWA-FUJI




T20250627063157




BLK:13,SNR1: 6.0268 ,SNR2: 50.763




K20250627063154





BLK:13,SNR1: 4.5410 ,SNR2: 8.9844




0100+146 2025/06/26 21.56UT TOYOKAWA-KISO





F20250627063158




BLK: 5, SNR1: 2.3315 ,SNR2: 5.4325




K20250627063154





BLK: 5, SNR1: 6.0311 ,SNR2: 12.210




0100+146 2025/06/26 21.56UT FUJI -KISO




T20250627064717




BLK: 3, SNR1: 0.24333 , SNR2: 1.2539




F20250627064718






BLK: 3, SNR1: 1.1412 , SNR2: 2.2043






0115-01 2025/06/26 21.82UT TOYOKAWA-FUJI














T20250627070017




BLK: 5, SNR1: 0.16414 , SNR2: 1.1123




F20250627070017




BLK: 5, SNR1: 0.60657 , SNR2: 2.3272




0128+03 2025/06/26 22.03UT TOYOKAWA-FUJI



T20250627070017




BLK: 4,SNR1: 0.42467 ,SNR2: 1.4039




Frequency (Hz)

K20250627070014




BLK: 4,SNR1:-0.14750E-01,SNR2: 1.8662




Frequency (Hz)


0128+03 2025/06/26 22.03UT TOYOKAWA-KISO





F20250627070017




BLK: 5,SNR1: 0.13973 ,SNR2: 1.2395




K20250627070014





BLK: 5,SNR1: 0.40804E-02,SNR2: 0.79692




0128+03 2025/06/26 22.03UT FUJI -KISO




T20250627070651




BLK:10,SNR1: 1.3144 ,SNR2: 5.2990




F20250627070651





BLK:10,SNR1: 6.4045 ,SNR2: 13.760




3C48 2025/06/26 22.14UT TOYOKAWA-FUJI




T20250627070651




BLK:12,SNR1: 1.5127 ,SNR2: 5.6864




K20250627070648




BLK:12,SNR1: 2.0146 ,SNR2: 9.7702





3C48 2025/06/26 22.14UT TOYOKAWA-KISO







BLK: 4,SNR1: 6.6057 ,SNR2: 14.268



BLK: 4,SNR1: 3.8718 ,SNR2: 14.782





3C48 2025/06/26 22.14UT FUJI -KISO








T20250627072635




BLK:12,SNR1: 0.29310 ,SNR2: 3.9806




F20250627072635





BLK:12,SNR1: 0.68482 ,SNR2: 7.6117




0155-109 2025/06/26 22.47UT TOYOKAWA-FUJI





T20250627072635




BLK: 8,SNR1: 0.42684 ,SNR2: 2.1443




K20250627072632




BLK: 8,SNR1: 0.27641 ,SNR2: 2.7577




0155-109 2025/06/26 22.47UT TOYOKAWA-KISO





F20250627072635




BLK: 3,SNR1: 0.10752 ,SNR2: 2.6376




K20250627072632





BLK: 3,SNR1: 0.93735E-01,SNR2: 2.8849






0155-109 2025/06/26 22.47UT FUJI -KISO







BLK: 4,SNR1: 0.22493E-01,SNR2: 1.1110




BLK: 4,SNR1: 0.69996 ,SNR2: 6.4434





0202+15 2025/06/26 22.59UT TOYOKAWA-FUJI







BLK: 5,SNR1: 0.19010E-01,SNR2: 1.1716





BLK: 5,SNR1: 0.80919 ,SNR2: 2.6090




0202+15 2025/06/26 22.59UT TOYOKAWA-KISO





F20250627073343




BLK: 4, SNR1: 0.81531 , SNR2: 2.6626




K20250627073340





BLK: 4, SNR1: 0.59350 , SNR2: 2.7137




0202+15 2025/06/26 22.59UT FUJI -KISO




T20250627074533




BLK: 5,SNR1: 0.66500E-01,SNR2: 0.56178




F20250627074533





BLK: 5,SNR1: 0.18487 ,SNR2: 4.5302




0213+178 2025/06/26 22.79UT TOYOKAWA-FUJI





T20250627074533




BLK: 3,SNR1: 0.44560E-01,SNR2: 1.0749




K20250627074530



BLK: 3,SNR1: 1.3020 ,SNR2: 4.0083




0213+178 2025/06/26 22.79UT TOYOKAWA-KISO







F20250627074533




BLK: 5, SNR1: 0.40515 , SNR2: 5.2944




K20250627074530




BLK: 5, SNR1: 0.79098 , SNR2: 2.6758




0213+178 2025/06/26 22.79UT FUJI -KISO




T20250627075316




BLK:13,SNR1: 0.85483E-01,SNR2: 0.61735




F20250627075316




BLK:13,SNR1: 3.4413 ,SNR2: 10.296




3C67 2025/06/26 22.92UT TOYOKAWA-FUJI





T20250627075316




BLK:11,SNR1: 0.14913 ,SNR2: 0.32249




K20250627075314




BLK:11,SNR1: 2.1460 ,SNR2: 5.4240




3C67 2025/06/26 22.92UT TOYOKAWA-KISO





F20250627075316




BLK:21,SNR1: 2.8415 ,SNR2: 8.7305




K20250627075314




BLK:21,SNR1: 1.4390 ,SNR2: 3.6948





3C67 2025/06/26 22.92UT FUJI -KISO








BLK:14,SNR1: 79.897 ,SNR2: 93.249





BLK:14,SNR1: 1.2831 ,SNR2: 4.4899







BLK: 8,SNR1: 76.963 ,SNR2: 89.822




BLK: 8,SNR1: 33.975 ,SNR2: 53.188




3C71 2025/06/26 23.22UT TOYOKAWA-KISO





F20250627081130




BLK: 4, SNR1: 2.1422 , SNR2: 4.7701




K20250627081127




BLK: 4, SNR1: 6.0703 , SNR2: 30.073




3C71 2025/06/26 23.22UT FUJI -KISO




T20250627083046




BLK: 8,SNR1: 0.85476 ,SNR2: 3.6987




F20250627083046



BLK: 8,SNR1: 0.68854 ,SNR2: 2.1678




0258+350 2025/06/26 23.54UT TOYOKAWA-FUJI








T20250627083046




BLK: 5, SNR1: 0.81987 , SNR2: 4.4286




K20250627083043




BLK: 5, SNR1: 0.72453 , SNR2: 3.2898




0258+350 2025/06/26 23.54UT TOYOKAWA-KISO





F20250627083046




BLK: 8,SNR1: 0.49623 ,SNR2: 4.2063




K20250627083043





BLK: 8,SNR1: 0.52633 ,SNR2: 2.7003




0258+350 2025/06/26 23.54UT FUJI -KISO





T20250627084035




BLK: 7, SNR1: 0.35671 , SNR2: 1.5472




F20250627084035







BLK: 7, SNR1: 1.8759 , SNR2: 6.2855









0308+305 2025/06/26 23.70UT TOYOKAWA-FUJI







0308+305 2025/06/26 23.70UT TOYOKAWA-KISO






T20250627084855




BLK: 9,SNR1: 13.429 ,SNR2: 30.754





3C84 2025/06/26 23.84UT TOYOKAWA-FUJI



F20250627084855




BLK: 9,SNR1: 8.1714 ,SNR2: 19.967





T20250627084855




BLK: 7, SNR1: 0.23026 , SNR2: 1.4914




K20250627084852




BLK: 7, SNR1: 3.4703 , SNR2: 6.3073




3C84 2025/06/26 23.84UT TOYOKAWA-KISO





F20250627084855




BLK: 4,SNR1: 1.7047 ,SNR2: 7.2370




K20250627084852



BLK: 4,SNR1: 0.88966 ,SNR2: 8.6462





3C84 2025/06/26 23.84UT FUJI -KISO








T20250627090528




BLK: 4,SNR1: 0.12447E-01,SNR2: 0.59475




F20250627090528





BLK: 4,SNR1: 2.7930 ,SNR2: 12.886




0333+32 2025/06/27 0.12UT TOYOKAWA-FUJI





T20250627090528




BLK: 4,SNR1: 0.54044E-01,SNR2: 0.98526




K20250627090525





BLK: 4,SNR1: 0.39514 ,SNR2: 3.3060




0333+32 2025/06/27 0.12UT TOYOKAWA-KISO





F20250627090528




BLK: 6, SNR1: 37.473 , SNR2: 81.677




K20250627090525





BLK: 6, SNR1: 3.8685 , SNR2: 8.9466




0333+32 2025/06/27 0.12UT FUJI -KISO




T20250627091829




BLK: 7,SNR1: 0.96089 ,SNR2: 3.0935




F20250627091829





BLK: 7,SNR1: 0.55209 ,SNR2: 2.3692




0347+05 2025/06/27 0.34UT TOYOKAWA-FUJI





T20250627091829




BLK: 5, SNR1: 0.49614 , SNR2: 2.9296




K20250627091826




BLK: 5, SNR1: 0.12770 , SNR2: 0.90848




0347+05 2025/06/27 0.34UT TOYOKAWA-KISO




F20250627091829




BLK: 1, SNR1: 0.40859 , SNR2: 7.3948




K20250627091826




BLK: 1, SNR1: 1.1982 , SNR2: 2.5778




0347+05 2025/06/27 0.34UT FUJI -KISO




T20250627093403




BLK:20,SNR1: 8.8064 ,SNR2: 20.819




F20250627093403




BLK:20,SNR1: 3.5457 ,SNR2: 10.911




0403-132 2025/06/27 0.60UT TOYOKAWA-FUJI




T20250627093403




BLK:23,SNR1: 6.2246 ,SNR2: 14.592




K20250627093400



BLK:23,SNR1: 8.0702 ,SNR2: 22.493




0403-132 2025/06/27 0.60UT TOYOKAWA-KISO







F20250627093403




BLK:20,SNR1: 4.7705 ,SNR2: 14.392




K20250627093400




BLK:20,SNR1: 11.733 ,SNR2: 20.949





0403-132 2025/06/27 0.60UT FUJI -KISO







BLK: 3, SNR1: 0.14393 , SNR2: 1.1887





BLK: 3, SNR1: 1.3103 , SNR2: 5.2975




0411+05 2025/06/27 0.75UT TOYOKAWA-FUJI




T20250627094314




BLK: 1, SNR1: 0.18188 , SNR2: 1.4791




K20250627094311




BLK: 1, SNR1: 0.11085 , SNR2: 3.2616





0411+05 2025/06/27 0.75UT TOYOKAWA-KISO







BLK: 6, SNR1: 3.4090 ,SNR2: 14.441





BLK: 6, SNR1: 2.5156 ,SNR2: 7.6135




0411+05 2025/06/27 0.75UT FUJI -KISO




T20250627095009




BLK: 4,SNR1: 0.56952 ,SNR2: 1.6621




F20250627095009




BLK: 4,SNR1: 0.80083 ,SNR2: 4.9778




0418+236 2025/06/27 0.86UT TOYOKAWA-FUJI





T20250627095009




BLK: 2,SNR1: 0.40632 ,SNR2: 1.7269




K20250627095006





BLK: 2,SNR1:-0.96218E-01,SNR2: 1.1031




0418+236 2025/06/27 0.86UT TOYOKAWA-KISO





F20250627095009




BLK: 8,SNR1: 5.1360 ,SNR2: 7.4717




K20250627095006







BLK: 8,SNR1: 0.20434 ,SNR2: 0.82627




0418+236 2025/06/27 0.86UT FUJI -KISO












3C119 2025/06/27 1.05UT TOYOKAWA-FUJI










F20250627100136




BLK:17,SNR1: 0.19965 ,SNR2: 1.5642




K20250627100133





BLK:17,SNR1: 0.67246 ,SNR2: 2.1212




3C119 2025/06/27 1.05UT FUJI -KISO





T20250627104943




BLK:13,SNR1: 7.2799 ,SNR2: 28.213




F20250627104943





BLK:13,SNR1: 2.2026 ,SNR2: 5.5655




3C138 2025/06/27 1.86UT TOYOKAWA-FUJI





T20250627104943




BLK:15,SNR1: 8.7087 ,SNR2: 22.605




K20250627104940





BLK:15,SNR1: 6.0162 ,SNR2: 15.032




3C138 2025/06/27 1.86UT TOYOKAWA-KISO





F20250627104943




BLK: 3, SNR1: 1.1738 , SNR2: 8.8347




K20250627104940












BLK: 3, SNR1: 3.5066 , SNR2: 9.3660




3C138 2025/06/27 1.86UT FUJI -KISO









0531+194 2025/06/27 2.08UT TOYOKAWA-KISO




F20250627110317




BLK: 6, SNR1: 10.295 , SNR2: 25.280




K20250627110314



BLK: 6, SNR1: 9.7548 , SNR2: 24.022





0531+194 2025/06/27 2.08UT FUJI -KISO






T20250627111137





BLK:22,SNR1: 14.575 ,SNR2: 34.231





3C147 2025/06/27 2.22UT TOYOKAWA-FUJI




F20250627111137



BLK:22,SNR1: 7.7688 ,SNR2: 18.541







T20250627111137





3C147 2025/06/27 2.22UT TOYOKAWA-KISO


K20250627111134



F20250627111137





BLK:27,SNR1: 7.5653 ,SNR2: 18.259










3C147 2025/06/27 2.22UT FUJI -KISO





K20250627111134




BLK:27,SNR1: 107.01 ,SNR2: 113.14









0548+16 2025/06/27 2.36UT TOYOKAWA-KISO




F20250627111948




BLK:11,SNR1: 0.68999 ,SNR2: 3.1438




K20250627111945





BLK:11,SNR1: 0.55180 ,SNR2: 2.6828




0548+16 2025/06/27 2.36UT FUJI -KISO





T20250627112358




BLK: 6, SNR1: 2.7238 , SNR2: 8.4206




F20250627112358





BLK: 6, SNR1: 1.7011 , SNR2: 5.4767




0552+12 2025/06/27 2.43UT TOYOKAWA-FUJI





T20250627112358




BLK:10,SNR1: 2.9811 ,SNR2: 9.1142




K20250627112355



BLK:10,SNR1: 2.3959 ,SNR2: 7.7548





0552+12 2025/06/27 2.43UT TOYOKAWA-KISO








F20250627112358




BLK:13,SNR1: 1.7558 ,SNR2: 5.4817




K20250627112355





BLK:13,SNR1: 9.5060 ,SNR2: 20.777




0552+12 2025/06/27 2.43UT FUJI -KISO




T20250627112825




BLK: 5, SNR1: 2.2588 , SNR2: 5.2574




F20250627112825





BLK: 5, SNR1: 5.6289 , SNR2: 13.746




0556+191 2025/06/27 2.50UT TOYOKAWA-FUJI




T20250627112825




BLK: 9, SNR1: 7.7105 , SNR2: 19.981




K20250627112822




BLK: 9, SNR1: 5.2654 , SNR2: 15.703




0556+191 2025/06/27 2.50UT TOYOKAWA-KISO




F20250627112825




BLK: 3, SNR1: 5.2265 , SNR2: 16.410




K20250627112822





BLK: 3, SNR1: 3.4206 , SNR2: 10.764




0556+191 2025/06/27 2.50UT FUJI -KISO



T20250627113611





BLK: 4, SNR1: 3.4650 , SNR2: 15.947





0605-08 2025/06/27 2.63UT TOYOKAWA-FUJI



F20250627113611




BLK: 4, SNR1: 1.3445 , SNR2: 5.4026





T20250627113611




BLK: 2, SNR1: 9.9634 , SNR2: 24.317




K20250627113608





BLK: 2, SNR1: 12.333 , SNR2: 30.488




0605-08 2025/06/27 2.63UT TOYOKAWA-KISO





F20250627113611




BLK: 4,SNR1: 9.5977 ,SNR2: 23.625




K20250627113608




BLK: 4,SNR1: 10.785 ,SNR2: 26.487





0605-08 2025/06/27 2.63UT FUJI -KISO











BLK:19,SNR1: 3.7032 ,SNR2: 7.7423




BLK:19,SNR1: 0.81534 ,SNR2: 4.1395












3C161 2025/06/27 2.95UT TOYOKAWA-KISO







T20250627122251




BLK: 5, SNR1: 7.8792 , SNR2: 20.289




F20250627122251





BLK: 5, SNR1: 7.1237 , SNR2: 20.557




0652-130 2025/06/27 3.41UT TOYOKAWA-FUJI




T20250627122251




BLK: 5, SNR1: 7.8316 , SNR2: 21.532




K20250627122248




BLK: 5, SNR1: 7.1419 , SNR2: 20.231




0652-130 2025/06/27 3.41UT TOYOKAWA-KISO




F20250627122251




BLK: 7, SNR1: 3.4267 , SNR2: 10.291




K20250627122248




BLK: 7, SNR1: 7.1614 , SNR2: 20.592




0652-130 2025/06/27 3.41UT FUJI -KISO





T20250627123428




BLK: 8, SNR1: 7.4470 , SNR2: 18.736




F20250627123428




BLK: 8, SNR1: 5.7360 , SNR2: 14.616




0703+138 2025/06/27 3.60UT TOYOKAWA-FUJI




T20250627123428




BLK: 9, SNR1: 11.394 , SNR2: 29.022




K20250627123425





BLK: 9, SNR1: 25.804 , SNR2: 50.199




0703+138 2025/06/27 3.60UT TOYOKAWA-KISO




F20250627123428




BLK: 6, SNR1: 6.7790 , SNR2: 20.143




K20250627123425








BLK: 6, SNR1: 69.394 , SNR2: 73.384







0703+138 2025/06/27 3.60UT FUJI -KISO













0713-024 2025/06/27 3.76UT TOYOKAWA-KISO



F20250627124351




BLK: 7,SNR1: 2.7342 ,SNR2: 7.8834




Frequency (Hz)

K20250627124348





BLK: 7,SNR1: 7.7475 ,SNR2: 20.406





Frequency (Hz)

0713-024 2025/06/27 3.76UT FUJI -KISO







BLK: 4,SNR1: 0.85432 ,SNR2: 2.4461




BLK: 4,SNR1: 0.50665 ,SNR2: 1.8244





0723+10 2025/06/27 3.93UT TOYOKAWA-FUJI







BLK:12,SNR1: 0.65812 ,SNR2: 2.6312




BLK:12,SNR1: 0.61522 ,SNR2: 2.3990




0723+10 2025/06/27 3.93UT TOYOKAWA-KISO




F20250627125403




BLK:10,SNR1: 0.41352E-01,SNR2: 1.2957




K20250627125400









BLK:10,SNR1: 1.3919 ,SNR2: 4.2870





0723+10 2025/06/27 3.93UT FUJI -KISO









BLK:21,SNR1: 0.60861 ,SNR2: 2.1430



BLK:21,SNR1: 0.61572 ,SNR2: 2.0422





0732+33 2025/06/27 4.10UT TOYOKAWA-KISO







F20250627130418




BLK:14,SNR1: 2.5917 ,SNR2: 15.519




K20250627130415




BLK:14,SNR1: 0.70609 ,SNR2: 2.3424





0732+33 2025/06/27 4.10UT FUJI -KISO







BLK:16,SNR1: 0.62041 ,SNR2: 4.4802




BLK:16,SNR1: 0.48216 ,SNR2: 2.1761





0741-06 2025/06/27 4.23UT TOYOKAWA-FUJI







BLK:20,SNR1: 0.81756 ,SNR2: 4.8350




BLK:20,SNR1: 2.0637 ,SNR2: 5.5593




0741-06 2025/06/27 4.23UT TOYOKAWA-KISO




F20250627131219




BLK:16,SNR1: 0.32291 ,SNR2: 1.8994




K20250627131216





BLK:16,SNR1: 4.0589 ,SNR2: 10.537




0741-06 2025/06/27 4.23UT FUJI -KISO





T20250627132203




BLK:15,SNR1: 7.5726 ,SNR2: 21.574




F20250627132203





BLK:15,SNR1: 6.4581 ,SNR2: 18.723




0752-200 2025/06/27 4.40UT TOYOKAWA-FUJI




T20250627132203




BLK:10,SNR1: 3.1306 ,SNR2: 6.0640




K20250627132200





BLK:10,SNR1: 11.040 ,SNR2: 27.240




0752-200 2025/06/27 4.40UT TOYOKAWA-KISO





F20250627132203




BLK: 7,SNR1: 6.9304 ,SNR2: 20.069




K20250627132200




BLK: 7,SNR1: 8.7600 ,SNR2: 24.532





0752-200 2025/06/27 4.40UT FUJI -KISO







BLK: 6,SNR1: 0.50304 ,SNR2: 2.5616




BLK: 6,SNR1: 1.3540 ,SNR2: 3.2298





3C190 2025/06/27 4.52UT TOYOKAWA-FUJI









BLK: 7,SNR1: 0.39431 ,SNR2: 1.5468




BLK: 7,SNR1: 11.752 ,SNR2: 22.187




3C190 2025/06/27 4.52UT TOYOKAWA-KISO





F20250627132938




BLK: 4,SNR1: 0.75888 ,SNR2: 3.1540




K20250627132935





BLK: 4,SNR1: 3.0753 ,SNR2: 9.0146




3C190 2025/06/27 4.52UT FUJI -KISO




T20250627134204




BLK:16,SNR1: 1.0735 ,SNR2: 3.1505




F20250627134204




BLK:16,SNR1: 2.7234 ,SNR2: 6.3411




3C196 2025/06/27 4.73UT TOYOKAWA-FUJI




T20250627134204




BLK:18,SNR1: 1.7056 ,SNR2: 3.4430




K20250627134201




BLK:18,SNR1: 3.5928 ,SNR2: 10.472




3C196 2025/06/27 4.73UT TOYOKAWA-KISO




F20250627134204




BLK:10,SNR1: 3.2759 ,SNR2: 7.3289




K20250627134201





BLK:10,SNR1: 3.5969 ,SNR2: 10.529




3C196 2025/06/27 4.73UT FUJI -KISO





T20250627135313




BLK: 9,SNR1: 0.61217 ,SNR2: 1.5793




F20250627135313





BLK: 9,SNR1: 2.1986 ,SNR2: 7.8241




0821+394 2025/06/27 4.92UT TOYOKAWA-FUJI




T20250627135313




BLK: 8,SNR1: 0.19871 ,SNR2: 1.4960




K20250627135310







BLK: 8,SNR1: 2.5409 ,SNR2: 7.0483




0821+394 2025/06/27 4.92UT TOYOKAWA-KISO







0821+394 2025/06/27 4.92UT FUJI -KISO








T20250627140452





F20250627140452




0834-19 2025/06/27 5.11UT TOYOKAWA-FUJI



T20250627140452





BLK:11,SNR1: 0.23886 ,SNR2: 2.7752




Frequency (Hz)

K20250627140449




BLK:11,SNR1: 5.4941 ,SNR2: 15.928





Frequency (Hz)


0834-19 2025/06/27 5.11UT TOYOKAWA-KISO




F20250627140452




BLK: 3,SNR1: 1.0329 ,SNR2: 3.8612




K20250627140449




BLK: 3,SNR1: 8.8643 ,SNR2: 25.190




0834-19 2025/06/27 5.11UT FUJI -KISO





T20250627140958




BLK:10,SNR1: 1.9614 ,SNR2: 5.9367




F20250627140958




BLK:10,SNR1: 0.18345 ,SNR2: 1.4533




0839-071 2025/06/27 5.19UT TOYOKAWA-FUJI




T20250627140958




BLK:15,SNR1: 1.3388 ,SNR2: 4.1326




K20250627140955





BLK:15,SNR1: 3.6584 ,SNR2: 7.8540





0839-071 2025/06/27 5.19UT TOYOKAWA-KISO




F20250627140958




K20250627140955





0839-071 2025/06/27 5.19UT FUJI -KISO







BLK: 4,SNR1: 0.46091 ,SNR2: 3.4690





BLK: 4,SNR1: 0.12433 ,SNR2: 0.67107






3C208 2025/06/27 5.38UT TOYOKAWA-FUJI







BLK: 7,SNR1: 0.22206 ,SNR2: 3.0285



BLK: 7,SNR1: 0.21365 ,SNR2: 1.2554





3C208 2025/06/27 5.38UT TOYOKAWA-KISO








F20250627142059




BLK: 2,SNR1: 0.24756 ,SNR2: 2.2664




K20250627142056




BLK: 2,SNR1: 0.86939 ,SNR2: 1.9873





3C208 2025/06/27 5.38UT FUJI -KISO







BLK:11,SNR1: 0.92842 ,SNR2: 2.2675




BLK:11,SNR1: 12.694 ,SNR2: 14.475





3C216 2025/06/27 5.66UT TOYOKAWA-FUJI







BLK:10,SNR1: 2.3352 ,SNR2: 7.4620




BLK:10,SNR1: 0.79892 ,SNR2: 2.6076





3C216 2025/06/27 5.66UT TOYOKAWA-KISO







BLK: 8,SNR1: 1.7256 ,SNR2: 6.1391




BLK: 8,SNR1: 1.8061 ,SNR2: 5.0008





3C216 2025/06/27 5.66UT FUJI -KISO







BLK: 3,SNR1: 0.31139 ,SNR2: 1.8654




BLK: 3,SNR1: 1.0531 ,SNR2: 3.7455





0919-142 2025/06/27 5.86UT TOYOKAWA-FUJI







BLK: 8,SNR1: 0.82069E-01,SNR2: 1.2631




BLK: 8,SNR1: 4.7839 ,SNR2: 11.077




0919-142 2025/06/27 5.86UT TOYOKAWA-KISO





F20250627144951




BLK:15,SNR1: 4.3471 ,SNR2: 11.985




K20250627144948




BLK:15,SNR1: 2.5932 ,SNR2: 8.2281





0919-142 2025/06/27 5.86UT FUJI -KISO







BLK: 9,SNR1: 0.51965 ,SNR2: 2.7228




BLK: 9,SNR1: 1.1004 ,SNR2: 2.7810





0926+117 2025/06/27 5.97UT TOYOKAWA-FUJI









BLK:13,SNR1: 0.40923 ,SNR2: 1.3391




BLK:13,SNR1: 1.1282 ,SNR2: 3.6836





0926+117 2025/06/27 5.97UT TOYOKAWA-KISO







BLK:15,SNR1: 0.91513 ,SNR2: 2.4141





BLK:15,SNR1: 1.3545 ,SNR2: 4.5381





0926+117 2025/06/27 5.97UT FUJI -KISO




T20250627150415





F20250627150415




3C222 2025/06/27 6.10UT TOYOKAWA-FUJI





T20250627150415




BLK:16,SNR1: 4.6170 ,SNR2: 13.189




K20250627150412




BLK:16,SNR1: 4.0783 ,SNR2: 9.5300




3C222 2025/06/27 6.10UT TOYOKAWA-KISO




F20250627150415




BLK:15,SNR1: 1.1097 ,SNR2: 5.7079




K20250627150412





BLK:15,SNR1: 4.0952 ,SNR2: 10.279




3C222 2025/06/27 6.10UT FUJI -KISO





T20250627151115




BLK: 5,SNR1: 0.14825 ,SNR2: 0.61783




F20250627151115





BLK: 5,SNR1: 0.29541 ,SNR2: 2.6732




0941-08 2025/06/27 6.22UT TOYOKAWA-FUJI





T20250627151115




BLK: 6,SNR1: 0.37030 ,SNR2: 1.9865




K20250627151112





BLK: 6,SNR1: 1.8738 ,SNR2: 5.3568





0941-08 2025/06/27 6.22UT TOYOKAWA-KISO




F20250627151115



K20250627151112





0941-08 2025/06/27 6.22UT FUJI -KISO







T20250627151937




BLK:12,SNR1: 3.0956 ,SNR2: 9.4108




F20250627151937





BLK:12,SNR1: 0.14619 ,SNR2: 2.2578




3C230 2025/06/27 6.36UT TOYOKAWA-FUJI




T20250627151937




BLK:18,SNR1: 3.0616 ,SNR2: 9.3054




K20250627151934




BLK:18,SNR1: 2.8204 ,SNR2: 8.6810




3C230 2025/06/27 6.36UT TOYOKAWA-KISO




F20250627151937




BLK:20,SNR1: 0.17844 ,SNR2: 2.4386




K20250627151934




BLK:20,SNR1: 2.7845 ,SNR2: 8.5861





3C230 2025/06/27 6.36UT FUJI -KISO







BLK:14,SNR1: 0.58103 ,SNR2: 6.1947




BLK:14,SNR1: 0.47388 ,SNR2: 1.8450





3C237 2025/06/27 6.62UT TOYOKAWA-FUJI







BLK:24,SNR1: 0.54775 ,SNR2: 1.4705




BLK:24,SNR1: 125.49 ,SNR2: 121.90




3C237 2025/06/27 6.62UT TOYOKAWA-KISO




F20250627153538




BLK:11,SNR1: 3.0758 ,SNR2: 8.3415




K20250627153535




BLK:11,SNR1: 83.835 ,SNR2: 152.27





3C237 2025/06/27 6.62UT FUJI -KISO







BLK:18,SNR1: 104.33 ,SNR2: 101.34




BLK:18,SNR1: 128.72 ,SNR2: 147.66





1011+110 2025/06/27 6.73UT TOYOKAWA-FUJI







BLK:16,SNR1: 79.393 ,SNR2: 77.866



BLK:16,SNR1: 16.123 ,SNR2: 31.197





1011+110 2025/06/27 6.73UT TOYOKAWA-KISO








F20250627154154




BLK:19,SNR1: 112.92 ,SNR2: 129.54




K20250627154151





BLK:19,SNR1: 15.809 ,SNR2: 48.370




1011+110 2025/06/27 6.73UT FUJI -KISO




T20250627154935




BLK:12,SNR1: 3.6784 ,SNR2: 10.950




F20250627154935




BLK:12,SNR1: 0.78867 ,SNR2: 2.5563





3C241 2025/06/27 6.85UT TOYOKAWA-FUJI







BLK:20,SNR1: 3.6583 ,SNR2: 10.890




BLK:20,SNR1: 3.2424 ,SNR2: 9.7960





3C241 2025/06/27 6.85UT TOYOKAWA-KISO







BLK:18,SNR1: 0.70628 ,SNR2: 3.2312




BLK:18,SNR1: 3.2364 ,SNR2: 9.7805





3C241 2025/06/27 6.85UT FUJI -KISO







BLK: 6,SNR1: 0.28966 ,SNR2: 0.93640






BLK: 6,SNR1: 0.87851 ,SNR2: 4.4682




1031-11 2025/06/27 7.05UT TOYOKAWA-FUJI







F20250627160104




BLK:15,SNR1: 0.46705 ,SNR2: 2.6707




K20250627160101




BLK:15,SNR1: 9.5515 ,SNR2: 14.047





1031-11 2025/06/27 7.05UT FUJI -KISO







BLK: 3,SNR1:-0.89013E-02,SNR2: 0.85558




BLK: 3,SNR1: 2.7217 ,SNR2: 19.193





1035-058 2025/06/27 7.12UT TOYOKAWA-FUJI









BLK: 3,SNR1: 0.97413E-02,SNR2: 1.0626




BLK: 3,SNR1: 0.42036 ,SNR2: 3.4192




1035-058 2025/06/27 7.12UT TOYOKAWA-KISO



F20250627160538





BLK: 4, SNR1: 2.6548 , SNR2: 9.6984




Frequency (Hz)

K20250627160535




BLK: 4, SNR1: 0.28603 , SNR2: 1.7108





Frequency (Hz)


1035-058 2025/06/27 7.12UT FUJI -KISO



T20250627161450





BLK: 6,SNR1: 0.26961 ,SNR2: 0.79209




Frequency (Hz)

F20250627161450




BLK: 6,SNR1:-0.21926 ,SNR2: 0.88955




Frequency (Hz)


1044-008 2025/06/27 7.28UT TOYOKAWA-FUJI



T20250627161450





BLK: 7,SNR1: 0.25779 ,SNR2: 1.0706




Frequency (Hz)

K20250627161447




BLK: 7,SNR1: 1.8256 ,SNR2: 5.6040





Frequency (Hz)


1044-008 2025/06/27 7.28UT TOYOKAWA-KISO



F20250627161450





BLK: 9,SNR1:-0.14691 ,SNR2: 2.4661




Frequency (Hz)

K20250627161447






BLK: 9,SNR1: 1.6700 ,SNR2: 5.1829






Frequency (Hz)

1044-008 2025/06/27 7.28UT FUJI -KISO







BLK: 8, SNR1: 0.57304 , SNR2: 3.8899






BLK: 8, SNR1: 0.88942 , SNR2: 3.7019





1055+01 2025/06/27 7.46UT TOYOKAWA-FUJI






F20250627162555





BLK:15,SNR1: 0.39783 ,SNR2: 2.2157




Frequency (Hz)

K20250627162552




BLK:15,SNR1: 3.7457 ,SNR2: 5.7504





Frequency (Hz)

1055+01 2025/06/27 7.46UT FUJI -KISO






T20250627163713




BLK: 5, SNR1: 0.27977 , SNR2: 1.3057




Frequency (Hz)

F20250627163713




BLK: 5, SNR1: 0.49105 , SNR2: 1.8975





Frequency (Hz)


1107+109 2025/06/27 7.65UT TOYOKAWA-FUJI





T20250627163713




BLK: 3,SNR1: 0.24531 ,SNR2: 0.85588




K20250627163710





BLK: 3,SNR1:-0.48186E-01,SNR2: 0.31743




1107+109 2025/06/27 7.65UT TOYOKAWA-KISO



F20250627163713




BLK: 2,SNR1: 0.90364 ,SNR2: 4.5153




Frequency (Hz)

K20250627163710





BLK: 2,SNR1: 0.96185E-01,SNR2: 0.53996





Frequency (Hz)

1107+109 2025/06/27 7.65UT FUJI -KISO







BLK: 3,SNR1:-0.21010E-01,SNR2: 0.82252




BLK: 3,SNR1: 0.40609 ,SNR2: 2.3276





3C255 2025/06/27 7.81UT TOYOKAWA-FUJI







BLK: 2, SNR1: 0.79428E-01, SNR2: 0.53952









BLK: 2, SNR1: 1.6428 , SNR2: 7.1132





3C255 2025/06/27 7.81UT TOYOKAWA-KISO









BLK:12,SNR1: 1.4880 ,SNR2: 4.6351




BLK:12,SNR1: 0.51929 ,SNR2: 3.1339





3C263.1 2025/06/27 8.21UT TOYOKAWA-FUJI







BLK:13,SNR1: 1.3906 ,SNR2: 4.3908




BLK:13,SNR1: 7.8242 ,SNR2: 17.042





3C263.1 2025/06/27 8.21UT TOYOKAWA-KISO









BLK:19,SNR1: 0.52935 ,SNR2: 3.4562





BLK:19,SNR1: 7.8383 ,SNR2: 17.059




3C263.1 2025/06/27 8.21UT FUJI -KISO





T20250627171715




BLK: 6,SNR1:-0.11623 ,SNR2: 0.40148




F20250627171715




BLK: 6,SNR1: 6.8383 ,SNR2: 17.749





3C267 2025/06/27 8.32UT TOYOKAWA-FUJI







BLK: 6, SNR1: -0.11005 , SNR2: 0.36145







BLK: 6, SNR1: 1.5161 , SNR2: 4.0445




3C267 2025/06/27 8.32UT TOYOKAWA-KISO








3C267 2025/06/27 8.32UT FUJI -KISO



T20250627173629





BLK:10,SNR1: 0.15698 ,SNR2: 0.77972




Frequency (Hz)

F20250627173629




BLK:10,SNR1: 3.1294 ,SNR2: 8.5074





Frequency (Hz)


1206+439 2025/06/27 8.64UT TOYOKAWA-FUJI





T20250627173629




BLK: 8, SNR1: 0.22593 , SNR2: 1.2321




K20250627173626





BLK: 8, SNR1: 0.82919 , SNR2: 3.0981




1206+439 2025/06/27 8.64UT TOYOKAWA-KISO



F20250627173629





BLK:10,SNR1: 10.439 ,SNR2: 23.439




Frequency (Hz)

K20250627173626



BLK:10,SNR1: 0.60389 ,SNR2: 1.8447



Frequency (Hz)

1206+439 2025/06/27 8.64UT FUJI -KISO

