




T20250630054541





BLK: 7, SNR1: 0.17944 , SNR2: 2.7394




Frequency (Hz)

F20250630054541




BLK: 7, SNR1: 5.9050 , SNR2: 14.864





Frequency (Hz)


0025+373 2025/06/29 20.79UT TOYOKAWA-FUJI





T20250630054541




BLK: 8, SNR1: 0.16163 , SNR2: 2.1472




K20250630054538



BLK: 8, SNR1: 5.9371 , SNR2: 15.890





0025+373 2025/06/29 20.79UT TOYOKAWA-KISO








F20250630054541




BLK: 3,SNR1: 2.3830 ,SNR2: 7.8368




K20250630054538




BLK: 3,SNR1: 2.3371 ,SNR2: 5.6651





0025+373 2025/06/29 20.79UT FUJI -KISO







BLK: 7,SNR1: 0.14492 ,SNR2: 0.40370










BLK: 7,SNR1: 9.3011 ,SNR2: 22.969





0038+328 2025/06/29 21.00UT TOYOKAWA-FUJI








F20250630055821




BLK: 2, SNR1: 0.87336 , SNR2: 2.7859




K20250630055818

















BLK: 2, SNR1: 0.53545 , SNR2: 3.5689




0038+328 2025/06/29 21.00UT FUJI -KISO













BLK: 2, SNR1: 3.9615 , SNR2: 10.990






BLK: 2, SNR1: 4.2388 , SNR2: 10.719




0100+146 2025/06/29 21.36UT FUJI -KISO













BLK:15,SNR1: 7.1167 ,SNR2: 12.679





BLK:15,SNR1: 8.4003 ,SNR2: 15.018




0109+416 2025/06/29 21.52UT TOYOKAWA-KISO





F20250630062947




BLK:16,SNR1: 2.8489 ,SNR2: 7.4036




K20250630062943




BLK:16,SNR1: 4.0745 ,SNR2: 9.5362





0109+416 2025/06/29 21.52UT FUJI -KISO







BLK: 5,SNR1:-0.76620E-01,SNR2: 0.82811E-01





BLK: 5,SNR1: 3.2395 ,SNR2: 10.723




0120+405 2025/06/29 21.71UT TOYOKAWA-FUJI





T20250630064051




BLK: 5, SNR1: -0.12234 , SNR2: 0.11888




K20250630064049






BLK: 5, SNR1: 0.81031 , SNR2: 3.9564





0120+405 2025/06/29 21.71UT TOYOKAWA-KISO







T20250630064829




BLK: 5,SNR1: 0.94784E-01,SNR2: 0.55235




F20250630064829






BLK: 5,SNR1: 0.67339 ,SNR2: 4.1200




0128+03 2025/06/29 21.84UT TOYOKAWA-FUJI








F20250630064829




BLK: 4,SNR1: 0.41519 ,SNR2: 2.1871




K20250630064827



BLK: 4,SNR1: 0.11251 ,SNR2: 0.71670





0128+03 2025/06/29 21.84UT FUJI -KISO







T20250630065503




BLK: 9,SNR1: 0.26385 ,SNR2: 2.6615




F20250630065504






BLK: 9,SNR1: 2.7802 ,SNR2: 7.1391





3C48 2025/06/29 21.95UT TOYOKAWA-FUJI






F20250630065504





BLK: 6, SNR1: 0.14178 , SNR2: 4.9385







3C48 2025/06/29 21.95UT FUJI -KISO

K20250630065500





BLK: 6, SNR1: 3.9824 , SNR2: 7.8033







BLK: 6,SNR1: 0.38196 ,SNR2: 5.5434







BLK: 6,SNR1: 8.3997 ,SNR2: 15.245




0155-109 2025/06/29 22.27UT TOYOKAWA-FUJI







0155-109 2025/06/29 22.27UT TOYOKAWA-KISO





F20250630071449




BLK: 2, SNR1: 2.0581 , SNR2: 5.1562




K20250630071445





BLK: 2, SNR1: 0.81195 , SNR2: 3.8562




0155-109 2025/06/29 22.27UT FUJI -KISO




T20250630072155




BLK: 3,SNR1: 0.10211 ,SNR2: 0.82800




F20250630072155





BLK: 3,SNR1: 0.51347 ,SNR2: 2.0821




0202+15 2025/06/29 22.39UT TOYOKAWA-FUJI




T20250630072155




BLK: 7,SNR1: 0.77105E-01,SNR2: 0.69463




K20250630072152



BLK: 7,SNR1: 0.34020 ,SNR2: 1.5452




0202+15 2025/06/29 22.39UT TOYOKAWA-KISO








F20250630072155




BLK: 2,SNR1: 0.49699E-02,SNR2: 2.9158




K20250630072152




BLK: 2,SNR1: 0.25946 ,SNR2: 0.98760




0202+15 2025/06/29 22.39UT FUJI -KISO




T20250630073345




BLK: 1,SNR1: 0.79938E-01,SNR2: 0.31923




F20250630073346







BLK: 1,SNR1: 16.896 ,SNR2: 41.189








0213+178 2025/06/29 22.59UT TOYOKAWA-FUJI






0213+178 2025/06/29 22.59UT TOYOKAWA-KISO







0213+178 2025/06/29 22.59UT FUJI -KISO





T20250630074128




BLK: 4, SNR1: 0.20693 , SNR2: 1.1164




F20250630074128




BLK: 4, SNR1: 3.6266 , SNR2: 7.6546




3C67 2025/06/29 22.72UT TOYOKAWA-FUJI





T20250630074128




BLK: 5, SNR1: 0.27219 , SNR2: 1.8721




K20250630074125





BLK: 5, SNR1: 0.31782 , SNR2: 1.4966




3C67 2025/06/29 22.72UT TOYOKAWA-KISO





F20250630074128




BLK: 3,SNR1: 1.5810 ,SNR2: 4.2286




K20250630074125




BLK: 3,SNR1: 0.48764 ,SNR2: 1.4927




3C67 2025/06/29 22.72UT FUJI -KISO



T20250630075943





BLK: 5, SNR1: 35.318 , SNR2: 320.45





3C71 2025/06/29 23.02UT TOYOKAWA-FUJI


F20250630075944




BLK: 5, SNR1: 3.7615 , SNR2: 8.1813










BLK: 4, SNR1: 56.827 , SNR2: 473.66




3C71 2025/06/29 23.02UT TOYOKAWA-KISO




BLK: 4, SNR1: 9.4767 , SNR2: 21.901




F20250630075944




BLK: 3, SNR1: 6.5718 , SNR2: 16.328




K20250630075940




BLK: 3, SNR1: 8.9404 , SNR2: 22.087





3C71 2025/06/29 23.02UT FUJI -KISO







BLK:15,SNR1: 7.7881 ,SNR2: 13.998




BLK:15,SNR1: 9.5334 ,SNR2: 17.084




0258+350 2025/06/29 23.34UT TOYOKAWA-FUJI





T20250630081858




BLK:16,SNR1: 7.8682 ,SNR2: 14.141




K20250630081855







BLK:16,SNR1: 0.12127 ,SNR2: 6.6904








0258+350 2025/06/29 23.34UT TOYOKAWA-KISO










0258+350 2025/06/29 23.34UT FUJI -KISO






0308+305 2025/06/29 23.51UT TOYOKAWA-FUJI







0308+305 2025/06/29 23.51UT TOYOKAWA-KISO



F20250630082847




BLK: 2,SNR1: 0.33050 ,SNR2: 1.3942




Frequency (Hz)

K20250630082844




BLK: 2,SNR1: 0.29123 ,SNR2: 4.1965





Frequency (Hz)

0308+305 2025/06/29 23.51UT FUJI -KISO







T20250630084019




BLK:10,SNR1: 0.33023 ,SNR2: 1.3334




F20250630084019





BLK:10,SNR1: 0.77637E-02,SNR2: 1.6116




0320+05 2025/06/29 23.70UT TOYOKAWA-FUJI





T20250630084019




BLK:10,SNR1: 0.35644 ,SNR2: 3.2629




K20250630084016




BLK:10,SNR1: 0.21018 ,SNR2: 1.3378




0320+05 2025/06/29 23.70UT TOYOKAWA-KISO





F20250630084019




BLK: 5,SNR1:-0.75565E-01,SNR2: 0.84406




K20250630084016




BLK: 5,SNR1: 0.21727 ,SNR2: 3.4027




0320+05 2025/06/29 23.70UT FUJI -KISO




T20250630085340




BLK: 4, SNR1: 195.26 , SNR2: 203.27




F20250630085340




BLK: 4, SNR1: 2.1838 , SNR2: 5.3926




0333+32 2025/06/29 23.92UT TOYOKAWA-FUJI



T20250630085340





BLK: 7, SNR1: 114.04 , SNR2: 132.29





0333+32 2025/06/29 23.92UT TOYOKAWA-KISO



K20250630085337




BLK: 7, SNR1: 0.89424 , SNR2: 3.7482





F20250630085340




No.Good Data




K20250630085337





No.Good Data




0333+32 2025/06/29 23.92UT FUJI -KISO





T20250630090641




BLK: 2, SNR1: 3.4198 , SNR2: 16.160




F20250630090641





BLK: 2, SNR1: 7.1282 , SNR2: 26.147




0347+05 2025/06/30 0.14UT TOYOKAWA-FUJI





T20250630090641




BLK: 2, SNR1: 3.4198 , SNR2: 16.160




K20250630090638



BLK: 2, SNR1: 8.9381 , SNR2: 21.859





0347+05 2025/06/30 0.14UT TOYOKAWA-KISO








F20250630090641




BLK: 1, SNR1: 11.842 , SNR2: 29.007




K20250630090638




BLK: 1, SNR1: 11.317 , SNR2: 27.777




0347+05 2025/06/30 0.14UT FUJI -KISO





T20250630092215




BLK: 1, SNR1: 8.8778 , SNR2: 22.125




F20250630092215




BLK: 1, SNR1: 11.575 , SNR2: 28.319




0403-132 2025/06/30 0.40UT TOYOKAWA-FUJI





T20250630092215




BLK: 1, SNR1: 0.95971 , SNR2: 5.5137




K20250630092212





BLK: 1, SNR1: 0.86762 , SNR2: 6.6369




0403-132 2025/06/30 0.40UT TOYOKAWA-KISO





F20250630092215




BLK: 2, SNR1: 11.918 , SNR2: 28.799




K20250630092212







BLK: 2, SNR1: 7.9787 , SNR2: 20.030




0403-132 2025/06/30 0.40UT FUJI -KISO







0411+05 2025/06/30 0.55UT TOYOKAWA-FUJI




T20250630093126




BLK: 1, SNR1: 2.2602 , SNR2: 10.832




K20250630093123




BLK: 1, SNR1: 1.6191 , SNR2: 15.810




0411+05 2025/06/30 0.55UT TOYOKAWA-KISO




F20250630093126




BLK: 3, SNR1: 10.002 , SNR2: 24.622




K20250630093123





BLK: 3, SNR1: 2.6404 , SNR2: 12.675




0411+05 2025/06/30 0.55UT FUJI -KISO




T20250630093821




BLK:12,SNR1: 10.714 ,SNR2: 16.906




F20250630093821



BLK:12,SNR1: 10.077 ,SNR2: 21.948





0418+236 2025/06/30 0.67UT TOYOKAWA-FUJI







T20250630093821




BLK:17,SNR1: 3.5699 ,SNR2: 10.651




K20250630093818




BLK:17,SNR1: 8.1205 ,SNR2: 21.036




0418+236 2025/06/30 0.67UT TOYOKAWA-KISO





F20250630093821




BLK:14,SNR1: 8.9114 ,SNR2: 19.424




K20250630093818




BLK:14,SNR1: 8.5924 ,SNR2: 15.006




0418+236 2025/06/30 0.67UT FUJI -KISO




T20250630094949




BLK:23,SNR1: 1.7958 ,SNR2: 6.3072




F20250630094949




BLK:23,SNR1: 1.0274 ,SNR2: 3.4322




3C119 2025/06/30 0.86UT TOYOKAWA-FUJI




T20250630094949




BLK:27,SNR1: 1.7879 ,SNR2: 6.1136




K20250630094946




BLK:27,SNR1: 0.47872 ,SNR2: 1.8527




3C119 2025/06/30 0.86UT TOYOKAWA-KISO





F20250630094949




BLK:20,SNR1: 1.1498 ,SNR2: 3.6970




K20250630094946




BLK:20,SNR1: 0.49740 ,SNR2: 2.4753




3C119 2025/06/30 0.86UT FUJI -KISO




T20250630103755




BLK:16,SNR1: 10.163 ,SNR2: 24.538




F20250630103755




BLK:16,SNR1: 0.88734 ,SNR2: 6.5399




3C138 2025/06/30 1.66UT TOYOKAWA-FUJI




T20250630103755




BLK:13,SNR1: 8.3048 ,SNR2: 21.480




K20250630103752




BLK:13,SNR1: 7.3901 ,SNR2: 12.814




3C138 2025/06/30 1.66UT TOYOKAWA-KISO




F20250630103755




BLK: 7, SNR1: 2.3920 , SNR2: 4.9807




K20250630103752



BLK: 7, SNR1: 6.8754 , SNR2: 9.9837





3C138 2025/06/30 1.66UT FUJI -KISO








T20250630105129




BLK:10,SNR1: 7.7904 ,SNR2: 22.008




F20250630105129








BLK:10,SNR1: 6.8552 ,SNR2: 18.314





0531+194 2025/06/30 1.89UT TOYOKAWA-FUJI








F20250630105129




BLK: 4, SNR1: 5.6068 , SNR2: 16.965




K20250630105126







BLK: 4, SNR1: 6.6832 , SNR2: 19.427








0531+194 2025/06/30 1.89UT FUJI -KISO






3C147 2025/06/30 2.03UT TOYOKAWA-FUJI







3C147 2025/06/30 2.03UT TOYOKAWA-KISO



F20250630105949




BLK:15,SNR1: 2.3493 ,SNR2: 7.2004










3C147 2025/06/30 2.03UT FUJI -KISO

K20250630105946




BLK:15,SNR1: 91.650 ,SNR2: 92.106







T20250630110800




BLK:15,SNR1: 2.6480 ,SNR2: 9.8242




K20250630110757







BLK:15,SNR1: 3.0512 ,SNR2: 8.7928




0548+16 2025/06/30 2.16UT TOYOKAWA-KISO









0548+16 2025/06/30 2.16UT FUJI -KISO




T20250630111210




BLK: 9,SNR1: 8.2952 ,SNR2: 36.525




F20250630111210








BLK: 9,SNR1: 0.71097 ,SNR2: 1.8572





0552+12 2025/06/30 2.23UT TOYOKAWA-FUJI








F20250630111210




BLK: 9,SNR1: 3.2089 ,SNR2: 13.873




K20250630111207







BLK: 9,SNR1: 106.03 ,SNR2: 100.61









0552+12 2025/06/30 2.23UT FUJI -KISO






0556+191 2025/06/30 2.31UT TOYOKAWA-FUJI







F20250630111637




BLK: 3,SNR1: 2.8890 ,SNR2: 8.9504




K20250630111634





BLK: 3,SNR1: 7.0365 ,SNR2: 19.637




0556+191 2025/06/30 2.31UT FUJI -KISO



T20250630112423




No.Good Data




Frequency (Hz)

F20250630112423




No.Good Data




Frequency (Hz)

0605-08 2025/06/30 2.43UT TOYOKAWA-FUJI








T20250630112423




BLK: 2, SNR1: 4.2420 , SNR2: 11.687




K20250630112420




BLK: 2, SNR1: 8.9476 , SNR2: 28.007




0605-08 2025/06/30 2.43UT TOYOKAWA-KISO





F20250630112423




BLK: 5,SNR1: 2.5885 ,SNR2: 6.7697




K20250630112420




BLK: 5,SNR1: 8.8453 ,SNR2: 22.286




0605-08 2025/06/30 2.43UT FUJI -KISO




T20250630114331




BLK:20,SNR1: 1.5447 ,SNR2: 12.385




F20250630114331




BLK:20,SNR1: 0.45907 ,SNR2: 2.4164





3C161 2025/06/30 2.75UT TOYOKAWA-FUJI







BLK:28,SNR1: 1.7640 ,SNR2: 6.3205




BLK:28,SNR1: 0.67318 ,SNR2: 2.6374




3C161 2025/06/30 2.75UT TOYOKAWA-KISO





F20250630114331




BLK:22,SNR1: 0.46594 ,SNR2: 2.3594




K20250630114328




BLK:22,SNR1: 0.77830 ,SNR2: 3.0788




3C161 2025/06/30 2.75UT FUJI -KISO




T20250630121104




BLK: 6,SNR1: 0.97473E-01,SNR2: 2.1085




F20250630121104




BLK: 6,SNR1: 2.4686 ,SNR2: 7.5628




0652-130 2025/06/30 3.21UT TOYOKAWA-FUJI




T20250630121104




BLK: 8, SNR1: 1.5841 , SNR2: 4.1234




K20250630121101




BLK: 8, SNR1: 6.4818 , SNR2: 16.786




0652-130 2025/06/30 3.21UT TOYOKAWA-KISO




F20250630121104




BLK: 3,SNR1: 0.51420 ,SNR2: 4.3596




K20250630121101



BLK: 3,SNR1: 5.6376 ,SNR2: 14.538





0652-130 2025/06/30 3.21UT FUJI -KISO







T20250630122240




BLK: 8, SNR1: 1.0267 , SNR2: 2.4108




F20250630122240





BLK: 8, SNR1: 6.2828 , SNR2: 17.786




0703+138 2025/06/30 3.41UT TOYOKAWA-FUJI




T20250630122240




BLK: 9,SNR1: 3.5134 ,SNR2: 8.7172




K20250630122237




BLK: 9,SNR1: 75.599 ,SNR2: 88.211




0703+138 2025/06/30 3.41UT TOYOKAWA-KISO





F20250630122240




BLK: 9,SNR1: 6.2900 ,SNR2: 17.988




K20250630122237




BLK: 9,SNR1: 23.692 ,SNR2: 49.676




0703+138 2025/06/30 3.41UT FUJI -KISO




T20250630123203




BLK: 7,SNR1: 0.33571 ,SNR2: 1.3734




F20250630123203




BLK: 7,SNR1: 0.12189 ,SNR2: 2.1210




0713-024 2025/06/30 3.56UT TOYOKAWA-FUJI




T20250630123203




BLK:10,SNR1: 0.26311 ,SNR2: 1.2565




K20250630123200




BLK:10,SNR1: 1.8573 ,SNR2: 3.7525




0713-024 2025/06/30 3.56UT TOYOKAWA-KISO





F20250630123203




BLK: 3,SNR1: 0.30250 ,SNR2: 1.2325




K20250630123200




BLK: 3,SNR1: 0.45230 ,SNR2: 2.0256




0713-024 2025/06/30 3.56UT FUJI -KISO




T20250630124215




BLK: 9,SNR1: 0.53554 ,SNR2: 4.1334




F20250630124215




BLK: 9,SNR1: 0.97581 ,SNR2: 2.9915




0723+10 2025/06/30 3.73UT TOYOKAWA-FUJI





T20250630124215




BLK:18,SNR1: 0.70351 ,SNR2: 1.9420




K20250630124212



BLK:18,SNR1: 0.70028 ,SNR2: 2.2855





0723+10 2025/06/30 3.73UT TOYOKAWA-KISO







F20250630124215




BLK:10,SNR1: 0.33679 ,SNR2: 1.8480




K20250630124212




BLK:10,SNR1: 0.65606 ,SNR2: 2.2386





0723+10 2025/06/30 3.73UT FUJI -KISO







BLK:22,SNR1: 2.0808 ,SNR2: 5.6334




BLK:22,SNR1: 1.0605 ,SNR2: 4.3124





0732+33 2025/06/30 3.90UT TOYOKAWA-FUJI







BLK:25,SNR1: 2.0988 ,SNR2: 10.656





BLK:25,SNR1: 0.86698 ,SNR2: 2.6229




0732+33 2025/06/30 3.90UT TOYOKAWA-KISO





F20250630125230




BLK:16,SNR1: 1.0114 ,SNR2: 3.0750




K20250630125227









BLK:16,SNR1: 0.37939 ,SNR2: 1.9971




0732+33 2025/06/30 3.90UT FUJI -KISO










F20250630130031




BLK:12,SNR1: 0.59853 ,SNR2: 2.7068




K20250630130028




BLK:12,SNR1: 0.55536 ,SNR2: 2.2209





0741-06 2025/06/30 4.04UT FUJI -KISO







BLK: 3,SNR1:-0.15532E-01,SNR2: 0.94935




BLK: 3,SNR1: 0.99687 ,SNR2: 3.4562





0752-200 2025/06/30 4.20UT TOYOKAWA-FUJI









BLK: 6,SNR1: 0.52330 ,SNR2: 2.1718




BLK: 6,SNR1: 2.1419 ,SNR2: 4.1148





0752-200 2025/06/30 4.20UT TOYOKAWA-KISO







BLK: 8,SNR1: 6.7657 ,SNR2: 18.126





BLK: 8,SNR1: 1.7283 ,SNR2: 3.4655




0752-200 2025/06/30 4.20UT FUJI -KISO





T20250630131751




BLK: 8,SNR1: 0.93514 ,SNR2: 2.7473




F20250630131751





BLK: 8,SNR1: 0.24656 ,SNR2: 2.2486




3C190 2025/06/30 4.33UT TOYOKAWA-FUJI





T20250630131751




BLK:16,SNR1: 0.57786 ,SNR2: 1.7847




K20250630131748





BLK:16,SNR1: 4.3747 ,SNR2: 19.203




3C190 2025/06/30 4.33UT TOYOKAWA-KISO





F20250630131751




BLK:13,SNR1: 2.5002 ,SNR2: 8.0660




K20250630131748





BLK:13,SNR1: 4.3733 ,SNR2: 19.199




3C190 2025/06/30 4.33UT FUJI -KISO





T20250630133016




BLK:11,SNR1: 0.36938 ,SNR2: 5.5360




F20250630133016





BLK:11,SNR1: 0.51397 ,SNR2: 1.5254




3C196 2025/06/30 4.53UT TOYOKAWA-FUJI





T20250630133016




BLK:12,SNR1: 0.55079 ,SNR2: 2.7848




K20250630133013




BLK:12,SNR1: 0.43007 ,SNR2: 2.0856




3C196 2025/06/30 4.53UT TOYOKAWA-KISO



F20250630133016





BLK: 9,SNR1: 1.0288 ,SNR2: 3.1626




Frequency (Hz)

K20250630133013




BLK: 9,SNR1: 1.3246 ,SNR2: 2.6703





Frequency (Hz)

3C196 2025/06/30 4.53UT FUJI -KISO






T20250630134125





BLK:10,SNR1: 0.35231 ,SNR2: 1.2662




Frequency (Hz)

F20250630134125




BLK:10,SNR1: 1.1507 ,SNR2: 4.1015





Frequency (Hz)


0821+394 2025/06/30 4.72UT TOYOKAWA-FUJI




T20250630134125




BLK:12,SNR1: 0.40093 ,SNR2: 1.9748




K20250630134122




BLK:12,SNR1: 0.70008 ,SNR2: 2.8246





0821+394 2025/06/30 4.72UT TOYOKAWA-KISO







BLK:10,SNR1: 0.92108 ,SNR2: 3.2941




BLK:10,SNR1: 0.87829 ,SNR2: 3.3719





0821+394 2025/06/30 4.72UT FUJI -KISO







BLK: 6,SNR1: 0.40320 ,SNR2: 1.5142







BLK: 6,SNR1: 0.33530 ,SNR2: 2.0684




0834-19 2025/06/30 4.91UT TOYOKAWA-FUJI







0834-19 2025/06/30 4.91UT TOYOKAWA-KISO




F20250630135304




BLK: 9,SNR1: 0.64061 ,SNR2: 2.6192




K20250630135301




BLK: 9,SNR1: 8.5151 ,SNR2: 20.993




0834-19 2025/06/30 4.91UT FUJI -KISO




T20250630135810




BLK: 2,SNR1: 0.10649 ,SNR2: 1.4585




F20250630135810




BLK: 2,SNR1: 0.69566 ,SNR2: 3.2018




0839-071 2025/06/30 5.00UT TOYOKAWA-FUJI





T20250630135810




BLK: 2,SNR1:-0.51697E-01,SNR2: 0.37245




K20250630135807



BLK: 2,SNR1: 0.75043 ,SNR2: 3.7335





0839-071 2025/06/30 5.00UT TOYOKAWA-KISO








F20250630135810




BLK: 3,SNR1: 2.1452 ,SNR2: 5.2967




K20250630135807




BLK: 3,SNR1: 0.31256 ,SNR2: 1.8657





0839-071 2025/06/30 5.00UT FUJI -KISO








BLK: 3,SNR1: 0.41933E-01,SNR2: 1.4216





BLK: 3,SNR1: 0.11498 ,SNR2: 1.1698








BLK: 8,SNR1: 0.82185E-01,SNR2: 1.0710




BLK: 8,SNR1: 4.6851 ,SNR2: 13.581





F20250630140911




BLK: 8,SNR1: 0.24725 ,SNR2: 2.3509




K20250630140908





BLK: 8,SNR1: 0.68401 ,SNR2: 2.2867




3C208 2025/06/30 5.18UT FUJI -KISO





T20250630142553




BLK: 5,SNR1: 0.32968 ,SNR2: 4.3016




F20250630142553





BLK: 5,SNR1:-0.84662E-01,SNR2: 0.81072




3C216 2025/06/30 5.46UT TOYOKAWA-FUJI




T20250630142553




BLK:12,SNR1: 0.18675 ,SNR2: 2.9793




K20250630142550






BLK:12,SNR1: 0.31495 ,SNR2: 1.4863




3C216 2025/06/30 5.46UT TOYOKAWA-KISO









T20250630143804



F20250630143804




0919-142 2025/06/30 5.66UT TOYOKAWA-FUJI









T20250630143804





K20250630143801




0919-142 2025/06/30 5.66UT TOYOKAWA-KISO





F20250630143804




BLK:21,SNR1: 0.25848E-01,SNR2: 1.3600




K20250630143801




BLK:21,SNR1: 1.6204 ,SNR2: 5.1176




0919-142 2025/06/30 5.66UT FUJI -KISO





T20250630144443




BLK: 5,SNR1: 0.57190 ,SNR2: 6.0756




F20250630144443




BLK: 5,SNR1: 0.22172 ,SNR2: 1.0564





0926+117 2025/06/30 5.77UT TOYOKAWA-FUJI







BLK: 3,SNR1: 0.46515 ,SNR2: 6.2995





BLK: 3,SNR1: 0.46185 ,SNR2: 2.1702




0926+117 2025/06/30 5.77UT TOYOKAWA-KISO





F20250630144443




BLK: 3,SNR1: 0.80706E-01,SNR2: 3.0110




K20250630144440




BLK: 3,SNR1: 0.21563 ,SNR2: 2.1506





0926+117 2025/06/30 5.77UT FUJI -KISO







BLK: 7,SNR1: 0.17288 ,SNR2: 2.1657







BLK: 7,SNR1:-0.10655 ,SNR2: 2.5203





3C222 2025/06/30 5.90UT TOYOKAWA-FUJI









BLK: 8,SNR1:-0.12136 ,SNR2: 1.6760



BLK: 8,SNR1: 2.4707 ,SNR2: 3.7054





3C222 2025/06/30 5.90UT FUJI -KISO







T20250630145928




BLK: 5,SNR1: 0.14956 ,SNR2: 1.1362




F20250630145928





BLK: 5,SNR1: 0.28275 ,SNR2: 1.4279




0941-08 2025/06/30 6.02UT TOYOKAWA-FUJI





T20250630145928




BLK: 4,SNR1: 0.28997 ,SNR2: 0.93889




K20250630145925





BLK: 4,SNR1: 0.38062 ,SNR2: 1.2107




0941-08 2025/06/30 6.02UT TOYOKAWA-KISO








0941-08 2025/06/30 6.02UT FUJI -KISO




T20250630150749




BLK: 5,SNR1: 0.35514 ,SNR2: 2.1365




F20250630150749





BLK: 5,SNR1:-0.21237 ,SNR2: 1.3312




3C230 2025/06/30 6.16UT TOYOKAWA-FUJI





T20250630150749




BLK:13,SNR1: 0.19461 ,SNR2: 1.1489




K20250630150746




BLK:13,SNR1: 7.1789 ,SNR2: 10.177




3C230 2025/06/30 6.16UT TOYOKAWA-KISO





F20250630150749




BLK: 8,SNR1: 0.21073 ,SNR2: 1.6028




K20250630150746





BLK: 8,SNR1: 4.5375 ,SNR2: 11.494




3C230 2025/06/30 6.16UT FUJI -KISO




T20250630152350




BLK:16,SNR1: 2.9284 ,SNR2: 8.6946




F20250630152350





BLK:16,SNR1: 3.7218 ,SNR2: 6.6401




3C237 2025/06/30 6.43UT TOYOKAWA-FUJI





T20250630152350




BLK:20,SNR1: 2.7600 ,SNR2: 8.1767




K20250630152347



BLK:20,SNR1: 7.2710 ,SNR2: 12.772




3C237 2025/06/30 6.43UT TOYOKAWA-KISO








F20250630152350




BLK:16,SNR1: 4.6798 ,SNR2: 8.3043




K20250630152347





BLK:16,SNR1: 7.2400 ,SNR2: 12.746




3C237 2025/06/30 6.43UT FUJI -KISO




T20250630153006




BLK: 2,SNR1: 0.18291 ,SNR2: 0.75767




F20250630153006




BLK: 2,SNR1:-0.27917 ,SNR2: 1.1953





1011+110 2025/06/30 6.53UT TOYOKAWA-FUJI







BLK: 1,SNR1: 0.10044 ,SNR2: 0.45262




BLK: 1,SNR1: 8.7808 ,SNR2: 13.110





1011+110 2025/06/30 6.53UT TOYOKAWA-KISO







BLK: 6,SNR1: 0.13380 ,SNR2: 0.97171





BLK: 6,SNR1: 7.9359 ,SNR2: 11.764




1011+110 2025/06/30 6.53UT FUJI -KISO




T20250630153748




BLK:13,SNR1: 0.32748 ,SNR2: 1.9456




F20250630153748





BLK:13,SNR1: 0.12819 ,SNR2: 1.6879




3C241 2025/06/30 6.66UT TOYOKAWA-FUJI



T20250630153748





BLK:13,SNR1: 2.7725 ,SNR2: 8.6902




Frequency (Hz)

K20250630153745




BLK:13,SNR1: 1.4071 ,SNR2: 4.3330




Frequency (Hz)


3C241 2025/06/30 6.66UT TOYOKAWA-KISO



F20250630153748





BLK:17,SNR1: 1.2293 ,SNR2: 4.0532




Frequency (Hz)

K20250630153745




BLK:17,SNR1: 1.4685 ,SNR2: 3.0906





Frequency (Hz)


3C241 2025/06/30 6.66UT FUJI -KISO




T20250630154917




BLK: 4,SNR1: 0.28570 ,SNR2: 0.98077




F20250630154917



BLK: 4,SNR1:-0.15277 ,SNR2: 0.51156





1031-11 2025/06/30 6.85UT TOYOKAWA-FUJI








T20250630154917




BLK: 6,SNR1: 0.12168 ,SNR2: 1.3210




K20250630154914




BLK: 6,SNR1: 0.64343 ,SNR2: 2.7138




1031-11 2025/06/30 6.85UT TOYOKAWA-KISO





F20250630154917




BLK: 2,SNR1:-0.34477 ,SNR2: 0.58471




K20250630154914




BLK: 2,SNR1: 0.49156E-01,SNR2: 0.74366





1031-11 2025/06/30 6.85UT FUJI -KISO







BLK: 9,SNR1: 0.49565 ,SNR2: 2.5489




BLK: 9,SNR1: 0.77907E-01,SNR2: 1.6022





1035-058 2025/06/30 6.93UT TOYOKAWA-FUJI







BLK:18,SNR1: 0.36888 ,SNR2: 2.2943




BLK:18,SNR1: 3.2141 ,SNR2: 4.1081





1035-058 2025/06/30 6.93UT TOYOKAWA-KISO







BLK: 8,SNR1: 0.23380 ,SNR2: 2.6832





BLK: 8,SNR1: 2.4084 ,SNR2: 6.4409




1035-058 2025/06/30 6.93UT FUJI -KISO



T20250630160303





BLK: 9, SNR1: 3.4130 , SNR2: 10.450




Frequency (Hz)

F20250630160303




BLK: 9, SNR1: 2.5262 , SNR2: 7.6996





Frequency (Hz)


1044-008 2025/06/30 7.08UT TOYOKAWA-FUJI



T20250630160303





BLK:17,SNR1: 3.5580 ,SNR2: 10.659




Frequency (Hz)

K20250630160300




BLK:17,SNR1: 8.9058 ,SNR2: 15.709





Frequency (Hz)


1044-008 2025/06/30 7.08UT TOYOKAWA-KISO



F20250630160303





BLK:24,SNR1: 2.0942 ,SNR2: 6.3709




Frequency (Hz)

K20250630160300




BLK:24,SNR1: 8.3327 ,SNR2: 14.569





Frequency (Hz)

1044-008 2025/06/30 7.08UT FUJI -KISO







T20250630161407




BLK: 2, SNR1: 0.45571 , SNR2: 8.4362




F20250630161407




BLK: 2, SNR1: 0.50863 , SNR2: 1.3513





1055+01 2025/06/30 7.26UT TOYOKAWA-FUJI







BLK: 8,SNR1: 2.2357 ,SNR2: 12.952




BLK: 8,SNR1: 0.27796 ,SNR2: 2.0773





1055+01 2025/06/30 7.26UT TOYOKAWA-KISO









BLK: 6,SNR1:-0.46189E-01,SNR2: 1.6832





BLK: 6,SNR1: 0.21592 ,SNR2: 1.8834




T20250630162525





F20250630162525




1107+109 2025/06/30 7.45UT TOYOKAWA-FUJI





T20250630162525




BLK:18,SNR1: 4.5523 ,SNR2: 10.353




K20250630162522




BLK:18,SNR1: 8.1101 ,SNR2: 20.946




1107+109 2025/06/30 7.45UT TOYOKAWA-KISO




F20250630162525




BLK:19,SNR1: 2.5179 ,SNR2: 7.6010




K20250630162522




BLK:19,SNR1: 8.1126 ,SNR2: 20.953





1107+109 2025/06/30 7.45UT FUJI -KISO







BLK:11,SNR1: 0.30276 ,SNR2: 1.2802





BLK:11,SNR1: 3.2269 ,SNR2: 14.156






3C255 2025/06/30 7.61UT TOYOKAWA-FUJI







BLK: 5, SNR1: 0.54123 , SNR2: 2.2042



BLK: 5, SNR1: 0.64723 , SNR2: 3.3840





3C255 2025/06/30 7.61UT TOYOKAWA-KISO






F20250630163502





BLK: 9,SNR1: 1.5463 ,SNR2: 11.726




Frequency (Hz)

K20250630163459





BLK: 9,SNR1: 0.28796 ,SNR2: 1.7670





Frequency (Hz)

3C255 2025/06/30 7.61UT FUJI -KISO







BLK: 3,SNR1: 0.13630 ,SNR2: 1.2231





BLK: 3,SNR1:-0.17867 ,SNR2: 0.98281




3C263.1 2025/06/30 8.01UT TOYOKAWA-FUJI





T20250630165900




BLK: 5, SNR1: 0.17822 , SNR2: 0.80529




K20250630165857




BLK: 5, SNR1: 0.48442 , SNR2: 2.1750





3C263.1 2025/06/30 8.01UT TOYOKAWA-KISO








BLK: 8,SNR1:-0.82162E-01,SNR2: 0.55191





BLK: 8,SNR1: 0.43086 ,SNR2: 1.4905







BLK: 7, SNR1: 1.7994 , SNR2: 5.3616







BLK: 7, SNR1: 13.291 , SNR2: 32.742









3C267 2025/06/30 8.12UT TOYOKAWA-FUJI






3C267 2025/06/30 8.12UT TOYOKAWA-KISO






T20250630172441




BLK: 3,SNR1: 0.35185E-01,SNR2: 1.4290




Frequency (Hz)

F20250630172441




BLK: 3,SNR1: 1.4342 ,SNR2: 4.4860







Frequency (Hz)


1206+439 2025/06/30 8.44UT TOYOKAWA-FUJI










1206+439 2025/06/30 8.44UT TOYOKAWA-KISO



F20250630172441





BLK: 7, SNR1: 2.3569 , SNR2: 5.3841




Frequency (Hz)

K20250630172438









BLK: 7, SNR1: 2.5704 , SNR2: 5.8312





Frequency (Hz)

1206+439 2025/06/30 8.44UT FUJI -KISO






T20250630175429





BLK: 7, SNR1: 0.18548 , SNR2: 0.87680




Frequency (Hz)

K20250630175426






BLK: 7, SNR1: 6.0598 , SNR2: 10.699



Frequency (Hz)

1236+327 2025/06/30 8.94UT TOYOKAWA-KISO





1236+327 2025/06/30 8.94UT FUJI -KISO

