





T20250708055242




BLK: 3,SNR1: 2.1699 ,SNR2: 10.884




F20250708055242









BLK: 3,SNR1: 0.71097 ,SNR2: 4.7649





0103+422 2025/07/07 20.91UT TOYOKAWA-FUJI








T20250708060529





No.Good Data




Frequency (Hz)

F20250708060529




No.Good Data









Frequency (Hz)


0116+31 2025/07/07 21.12UT TOYOKAWA-FUJI















BLK:13,SNR1: 0.80282 ,SNR2: 4.9443









BLK:13,SNR1: 0.40728 ,SNR2: 3.6504




3048 2025/07/07 21.42UT TOYOKAWA-FUJI










T20250708063719




BLK:14,SNR1: 2.8968 ,SNR2: 9.0163




F20250708063719









BLK:14,SNR1: 4.5982 ,SNR2: 13.350



0148+274 2025/07/07 21.65UT TOYOKAWA-FUJI












T20250708065028





BLK: 2, SNR1: 9.3453 , SNR2: 23.059




Frequency (Hz)

F20250708065028







BLK: 2, SNR1: 9.9783 , SNR2: 24.527






Frequency (Hz)



0202+15 2025/07/07 21.87UT TOYOKAWA-FUJI










T20250708070218




BLK: 4, SNR1: 12.411 , SNR2: 30.299




F20250708070218









BLK: 4, SNR1: 18.395 , SNR2: 39.914





0213+178 2025/07/07 22.07UT TOYOKAWA-FUJI













BLK: 3,SNR1: 0.99156E-01,SNR2: 1.5063






BLK: 3,SNR1: 3.7203 ,SNR2: 9.1043






3C67 2025/07/07 22.20UT TOYOKAWA-FUJI












T20250708072815





BLK:14,SNR1: 8.0480 ,SNR2: 14.425








3C71 2025/07/07 22.50UT TOYOKAWA-FUJI




F20250708072815





BLK:14,SNR1: 3.8698 ,SNR2: 10.598










T20250708074731




BLK: 4, SNR1: 11.673 , SNR2: 29.514




F20250708074731









BLK: 4, SNR1: 13.212 , SNR2: 33.071







0258+350 2025/07/07 22.82UT TOYOKAWA-FUJI
















0308+305 2025/07/07 22.98UT TOYOKAWA-FUJI













T20250708080851




BLK: 7, SNR1: 3.0607 ,SNR2: 8.0482




F20250708080851









BLK: 7, SNR1: 10.607 ,SNR2: 30.731







0320+05 2025/07/07 23.18UT TOYOKAWA-FUJI
















0333+32 2025/07/07 23.40UT TOYOKAWA-FUJI












T20250708083514





BLK: 9, SNR1: 7.7587 , SNR2: 22.126








0347+05 2025/07/07 23.62UT TOYOKAWA-FUJI




F20250708083514







BLK: 9, SNR1: 6.4445 , SNR2: 16.881




















0403-132 2025/07/07 23.87UT TOYOKAWA-FUJI













0418+236 2025/07/08 0.14UT TOYOKAWA-FUJI










0418+236 2025/07/08 0.14UT TOYOKAWA-KISO









T20250708091821




BLK:16,SNR1: 1.7031 ,SNR2: 4.9981




F20250708091821









BLK:16,SNR1: 3.2228 ,SNR2: 9.0495







3C119 2025/07/08 0.33UT TOYOKAWA-FUJI

















3C138 2025/07/08 1.14UT TOYOKAWA-FUJI









T20250708102002




BLK:25,SNR1: 2.3827 ,SNR2: 10.126




F20250708102002





BLK:25,SNR1: 0.63379E-01,SNR2: 2.6380




0531+194 2025/07/08 1.36UT TOYOKAWA-FUJI











0531+194 2025/07/08 1.36UT TOYOKAWA-KISO







T20250708102822




BLK:16,SNR1: 23.944 ,SNR2: 59.224




F20250708102822









BLK:16,SNR1: 0.65252 ,SNR2: 2.6870





3C147 2025/07/08 1.50UT TOYOKAWA-FUJI










T20250708103633




BLK:11,SNR1: 0.84542 ,SNR2: 3.9168




F20250708103633









BLK:11,SNR1: 3.0716 ,SNR2: 13.011



0548+16 2025/07/08 1.64UT TOYOKAWA-FUJI













T20250708104043




BLK:13,SNR1: 14.753 ,SNR2: 28.559




F20250708104043









BLK:13,SNR1: 1.7283 ,SNR2: 3.7453







0552+12 2025/07/08 1.71UT TOYOKAWA-FUJI















0556+191 2025/07/08 1.78UT TOYOKAWA-FUJI






0556+191 2025/07/08 1.78UT TOYOKAWA-KISO








0556+191 2025/07/08 1.78UT FUJI -KISO



T20250708105256





BLK: 2,SNR1: 0.25661 ,SNR2: 1.1655








0605-08 2025/07/08 1.91UT TOYOKAWA-FUJI

F20250708105256










BLK: 2,SNR1:-0.21519 ,SNR2: 1.4044



















3C161 2025/07/08 2.23UT TOYOKAWA-FUJI













BLK: 3,SNR1: 0.57263 ,SNR2: 1.4348









BLK: 3,SNR1: -0.29503E-01,SNR2: 1.3116





0652-130 2025/07/08 2.69UT TOYOKAWA-FUJI










T20250708115113





F20250708115113




0703+138 2025/07/08 2.88UT TOYOKAWA-FUJI










0703+138 2025/07/08 2.88UT TOYOKAWA-KISO







0703+138 2025/07/08 2.88UT FUJI -KISO




T20250708120036




BLK: 5, SNR1: 0.15149 , SNR2: 1.9555




F20250708120036





BLK: 5, SNR1: 0.12052 , SNR2: 2.3563






0713-024 2025/07/08 3.04UT TOYOKAWA-FUJI






0713-024 2025/07/08 3.04UT TOYOKAWA-KISO








0713-024 2025/07/08 3.04UT FUJI -KISO



T20250708121048




BLK:11,SNR1: 268.51 ,SNR2: 403.80








0723+10 2025/07/08 3.21UT TOYOKAWA-FUJI




F20250708121048



BLK:11,SNR1: 1.0672 ,SNR2: 3.2047














T20250708122103




BLK:14,SNR1: 1.1286 ,SNR2: 3.3139




F20250708122103









BLK:14,SNR1: 1.1015 ,SNR2: 4.5811







0732+33 2025/07/08 3.38UT TOYOKAWA-FUJI












0741-06 2025/07/08 3.51UT TOYOKAWA-FUJI





T20250708122904




BLK:11,SNR1: 1.0892 ,SNR2: 6.2859




K20250708122901




BLK:11,SNR1: 5.3498 ,SNR2: 14.047




0741-06 2025/07/08 3.51UT TOYOKAWA-KISO





F20250708122904




BLK: 8,SNR1: 3.6132 ,SNR2: 10.286




K20250708122901





BLK: 8,SNR1: 6.1168 ,SNR2: 16.068




0741-06 2025/07/08 3.51UT FUJI -KISO




T20250708123848




BLK: 5,SNR1: 0.18338 ,SNR2: 1.1230




F20250708123848






BLK: 5,SNR1: 0.18315E-01,SNR2: 2.3994







0752-200 2025/07/08 3.67UT TOYOKAWA-FUJI















BLK:13,SNR1: 0.91836 ,SNR2: 5.4266









BLK:13,SNR1: 0.14299 ,SNR2: 0.81571





3C190 2025/07/08 3.80UT TOYOKAWA-FUJI









T20250708125849




BLK:19,SNR1: 1.4468 ,SNR2: 13.677




F20250708125849









BLK:19,SNR1: 0.38074 ,SNR2: 1.9817




3C196 2025/07/08 4.01UT TOYOKAWA-FUJI













BLK:14,SNR1: 0.28444 ,SNR2: 1.1621





BLK:14,SNR1: 0.54741 ,SNR2: 2.3612




0821+394 2025/07/08 4.19UT TOYOKAWA-FUJI












0821+394 2025/07/08 4.19UT TOYOKAWA-KISO








T20250708132137





F20250708132137







0834-19 2025/07/08 4.39UT TOYOKAWA-FUJI







0834-19 2025/07/08 4.39UT TOYOKAWA-KISO







T20250708132643




BLK:12,SNR1: 3.4851 ,SNR2: 10.026




F20250708132643





BLK:12,SNR1: 1.5607 ,SNR2: 4.3524






0839-071 2025/07/08 4.47UT TOYOKAWA-FUJI






0839-071 2025/07/08 4.47UT TOYOKAWA-KISO






0839-071 2025/07/08 4.47UT FUJI -KISO







T20250708133744




BLK: 3,SNR1: 0.34547E-01,SNR2: 1.3017




F20250708133744









BLK: 3,SNR1: 0.96135,SNR2: 2.5694











3C208 2025/07/08 4.66UT TOYOKAWA-FUJI





















T20250708140637




BLK: 6,SNR1: 0.78648E-02,SNR2: 0.69007




F20250708140637





BLK: 6,SNR1: 4.8877 ,SNR2: 19.842




0919-142 2025/07/08 5.14UT TOYOKAWA-FUJI









0919-142 2025/07/08 5.14UT TOYOKAWA-KISO













BLK: 8,SNR1: 2.1744 ,SNR2: 6.2049





BLK: 8,SNR1: 10.010 ,SNR2: 21.213







0926+117 2025/07/08 5.25UT TOYOKAWA-FUJI







0926+117 2025/07/08 5.25UT TOYOKAWA-KISO








T20250708142100




BLK: 6,SNR1: 1.1564 ,SNR2: 3.7339




F20250708142100









BLK: 6,SNR1: 0.51347 ,SNR2: 2.3222




3C222 2025/07/08 5.38UT TOYOKAWA-FUJI













BLK:14,SNR1: 2.0743 ,SNR2: 7.0044




BLK:14,SNR1: 8.8484 ,SNR2: 19.372





0941-08 2025/07/08 5.49UT TOYOKAWA-FUJI









BLK:16,SNR1: 2.6962 ,SNR2: 8.6673





BLK:16,SNR1: 5.1739 ,SNR2: 13.428




0941-08 2025/07/08 5.49UT TOYOKAWA-KISO





F20250708142800




BLK:18,SNR1: 8.3469 ,SNR2: 18.281




K20250708142757




BLK:18,SNR1: 5.0586 ,SNR2: 13.148




0941-08 2025/07/08 5.49UT FUJI -KISO





T20250708143622




BLK: 9,SNR1: 2.5695 ,SNR2: 8.1120




F20250708143622




BLK: 9,SNR1: 4.0271 ,SNR2: 10.962





3C230 2025/07/08 5.63UT TOYOKAWA-FUJI







BLK: 9,SNR1: 1.9636 ,SNR2: 3.8567





BLK: 9,SNR1: 28.559 ,SNR2: 27.887




3C230 2025/07/08 5.63UT TOYOKAWA-KISO





F20250708143622




BLK: 7,SNR1: 9.1355 ,SNR2: 11.865




K20250708143619





BLK: 7,SNR1: 1.7717 ,SNR2: 5.1558




3C230 2025/07/08 5.63UT FUJI -KISO





T20250708145223




BLK:19,SNR1: 1.4459 ,SNR2: 8.5026




F20250708145223





BLK:19,SNR1: 0.20847 ,SNR2: 2.2825




3C237 2025/07/08 5.90UT TOYOKAWA-FUJI





T20250708145223




BLK: 7,SNR1: 1.2239 ,SNR2: 8.0227




K20250708145221




BLK: 7,SNR1: 0.14864 ,SNR2: 1.3605




3C237 2025/07/08 5.90UT TOYOKAWA-KISO





F20250708145223




BLK: 6,SNR1: 0.98440 ,SNR2: 2.7674




K20250708145221



BLK: 6,SNR1: 1.2734 ,SNR2: 3.5572





3C237 2025/07/08 5.90UT FUJI -KISO







T20250708145839




BLK:11,SNR1: 9.1639 ,SNR2: 26.448




F20250708145839





BLK:11,SNR1: 7.1819 ,SNR2: 20.704




1011+110 2025/07/08 6.01UT TOYOKAWA-FUJI





T20250708145839




BLK: 5,SNR1: 8.5665 ,SNR2: 24.870




K20250708145837




BLK: 5,SNR1: 8.9072 ,SNR2: 19.426




1011+110 2025/07/08 6.01UT TOYOKAWA-KISO





F20250708145839




BLK: 7,SNR1: 9.8334 ,SNR2: 24.827




K20250708145837




BLK: 7,SNR1: 9.8213 ,SNR2: 23.606





1011+110 2025/07/08 6.01UT FUJI -KISO







BLK: 8,SNR1: 1.7816 ,SNR2: 5.4974




BLK: 8,SNR1: 4.1749 ,SNR2: 10.232





3C241 2025/07/08 6.13UT TOYOKAWA-FUJI







BLK:10,SNR1: 4.5949 ,SNR2: 11.893




BLK:10,SNR1: 10.109 ,SNR2: 23.487




3C241 2025/07/08 6.13UT TOYOKAWA-KISO





F20250708150620




BLK: 4,SNR1: 4.9021 ,SNR2: 12.941




K20250708150618




BLK: 4,SNR1: 7.5790 ,SNR2: 19.014





3C241 2025/07/08 6.13UT FUJI -KISO







BLK: 8,SNR1: 120.55 ,SNR2: 121.16





BLK: 8,SNR1: 132.98 ,SNR2: 150.80




1031-11 2025/07/08 6.33UT TOYOKAWA-FUJI




T20250708151749




BLK: 5,SNR1: 2.2720 ,SNR2: 5.5121




K20250708151747



BLK: 5,SNR1: 9.1631 ,SNR2: 24.127




1031-11 2025/07/08 6.33UT TOYOKAWA-KISO








F20250708151749




BLK: 6,SNR1: 2.0655 ,SNR2: 5.4712




K20250708151747




BLK: 6,SNR1: 8.0380 ,SNR2: 19.818






1031-11 2025/07/08 6.33UT FUJI -KISO




T20250708152223





F20250708152223




1035-058 2025/07/08 6.40UT TOYOKAWA-FUJI





T20250708152223




BLK: 5, SNR1: 8.9259 , SNR2: 25.801




K20250708152220





BLK: 5, SNR1: 5.6230 , SNR2: 14.106




1035-058 2025/07/08 6.40UT TOYOKAWA-KISO




F20250708152223




BLK: 6,SNR1: 16.801 ,SNR2: 36.554




K20250708152220




BLK: 6,SNR1: 5.6194 ,SNR2: 13.159





1035-058 2025/07/08 6.40UT FUJI -KISO







BLK: 5,SNR1: 12.074 ,SNR2: 29.500




BLK: 5,SNR1: 8.2439 ,SNR2: 17.797





1044-008 2025/07/08 6.55UT TOYOKAWA-FUJI







BLK: 7,SNR1: 10.848 ,SNR2: 26.502




BLK: 7,SNR1: 10.607 ,SNR2: 18.133





1044-008 2025/07/08 6.55UT TOYOKAWA-KISO







BLK: 7,SNR1: 6.9490 ,SNR2: 17.615




BLK: 7,SNR1: 9.5246 ,SNR2: 23.987




1044-008 2025/07/08 6.55UT FUJI -KISO





T20250708154240




BLK: 7, SNR1: 10.920 , SNR2: 32.100




F20250708154240



BLK: 7, SNR1: 7.6633 , SNR2: 18.681




1055+01 2025/07/08 6.74UT TOYOKAWA-FUJI







T20250708154240




BLK:12,SNR1: 10.872 ,SNR2: 31.509




K20250708154238





BLK:12,SNR1: 11.643 ,SNR2: 28.995




1055+01 2025/07/08 6.74UT TOYOKAWA-KISO





F20250708154240




BLK: 4, SNR1: 7.1372 , SNR2: 17.007




K20250708154238







BLK: 4, SNR1: 7.4719 , SNR2: 18.079








1055+01 2025/07/08 6.74UT FUJI -KISO






1107+109 2025/07/08 6.93UT TOYOKAWA-FUJI








1107+109 2025/07/08 6.93UT TOYOKAWA-KISO





F20250708155358




BLK:12,SNR1: 4.2414 ,SNR2: 10.904




K20250708155356





BLK:12,SNR1: 17.814 ,SNR2: 19.541




1107+109 2025/07/08 6.93UT FUJI -KISO



T20250708160335




BLK: 6,SNR1: 6.2630 ,SNR2: 13.070




Frequency (Hz)

F20250708160335





BLK: 6,SNR1: 0.59530 ,SNR2: 3.3686





Frequency (Hz)

3C255 2025/07/08 7.09UT TOYOKAWA-FUJI







BLK: 8,SNR1: 6.7865 ,SNR2: 19.903




BLK: 8,SNR1: 5.1978 ,SNR2: 13.902





3C255 2025/07/08 7.09UT TOYOKAWA-KISO







BLK: 7,SNR1: 4.5790 ,SNR2: 12.435








BLK: 7,SNR1: 7.6451 ,SNR2: 20.632







3C255 2025/07/08 7.09UT FUJI -KISO













1127-14 2025/07/08 7.27UT TOYOKAWA-KISO







BLK: 7,SNR1: 0.84314 ,SNR2: 2.7296





BLK: 7,SNR1: 6.4161 ,SNR2: 16.957




1127-14 2025/07/08 7.27UT FUJI -KISO



T20250708162733





BLK: 7,SNR1: 4.7299 ,SNR2: 8.3824




Frequency (Hz)

F20250708162733





BLK: 7,SNR1: 1.5094 ,SNR2: 4.6273





Frequency (Hz)

3C263.1 2025/07/08 7.49UT TOYOKAWA-FUJI







BLK:14,SNR1: 3.5081 ,SNR2: 6.0475




BLK:14,SNR1: 9.6343 ,SNR2: 21.301




3C263.1 2025/07/08 7.49UT TOYOKAWA-KISO



F20250708162733




BLK:13,SNR1: 1.1299 ,SNR2: 5.6527




Frequency (Hz)

K20250708162730




BLK:13,SNR1: 7.5447 ,SNR2: 17.278




Frequency (Hz)


3C263.1 2025/07/08 7.49UT FUJI -KISO



T20250708163400





BLK: 7, SNR1: 2.5716 , SNR2: 6.5517




Frequency (Hz)

F20250708163400





BLK: 7, SNR1: 2.9643 , SNR2: 8.0851





Frequency (Hz)

3C267 2025/07/08 7.59UT TOYOKAWA-FUJI







BLK: 8,SNR1: 1.5595 ,SNR2: 4.0796




BLK: 8,SNR1: 0.18817 ,SNR2: 3.1824





3C267 2025/07/08 7.59UT TOYOKAWA-KISO









BLK:10,SNR1: 0.21234E-01,SNR2: 1.4887




BLK:10,SNR1: 0.40261 ,SNR2: 4.7841





3C267 2025/07/08 7.59UT FUJI -KISO







BLK: 6,SNR1: 8.9759 ,SNR2: 22.527




BLK: 6,SNR1: 9.9570 ,SNR2: 17.839




1206+439 2025/07/08 7.92UT TOYOKAWA-FUJI



T20250708165314




BLK: 3, SNR1: 16.173 , SNR2: 38.020




Frequency (Hz)

K20250708165311









BLK: 3, SNR1: 10.629 , SNR2: 26.388





Frequency (Hz)

1206+439 2025/07/08 7.92UT TOYOKAWA-KISO






T20250708175952





BLK: 6, SNR1: 11.769 , SNR2: 28.569




Frequency (Hz)

F20250708175952




BLK: 6, SNR1: 11.231 , SNR2: 28.054





Frequency (Hz)


1313+453 2025/07/08 9.03UT TOYOKAWA-FUJI



T20250708175952





No.Good Data




Frequency (Hz)

K20250708175948






No.Good Data




Frequency (Hz)

1313+453 2025/07/08 9.03UT TOYOKAWA-KISO








1313+453 2025/07/08 9.03UT FUJI -KISO



T20250708182111





BLK: 5, SNR1: 1.8798 , SNR2: 4.6568




Frequency (Hz)

F20250708182111




BLK: 5, SNR1: 0.35586 , SNR2: 2.0075





Frequency (Hz)

1335+479 2025/07/08 9.38UT TOYOKAWA-FUJI






T20250708182111





BLK: 5, SNR1: 2.0152 , SNR2: 10.469




Frequency (Hz)

K20250708182108




BLK: 5, SNR1: 0.10606 , SNR2: 1.4076





Frequency (Hz)


1335+479 2025/07/08 9.38UT TOYOKAWA-KISO



F20250708182111





BLK: 4, SNR1: 0.37029 , SNR2: 1.5264




Frequency (Hz)

K20250708182108



BLK: 4, SNR1: 4.2935 , SNR2: 13.845



Frequency (Hz)

1335+479 2025/07/08 9.38UT FUJI -KISO

