








BLK:22,SNR1: 4.7252 ,SNR2: 11.259








BLK:22,SNR1: 5.0584 ,SNR2: 15.698





0103+422 2025/07/08 20.84UT TOYOKAWA-FUJI








F20250709054847




BLK:27,SNR1: 4.5816 ,SNR2: 14.086




K20250709054844





BLK:27,SNR1: 9.1370 ,SNR2: 21.109




0103+422 2025/07/08 20.84UT FUJI -KISO





T20250709060134




BLK: 1, SNR1: 4.1516 , SNR2: 13.044




F20250709060135





BLK: 1, SNR1: 4.3426 , SNR2: 13.594




0116+31 2025/07/08 21.05UT TOYOKAWA-FUJI





T20250709060134




BLK: 1, SNR1: 3.9050 , SNR2: 13.881




K20250709060132





BLK: 1, SNR1: 3.4795 , SNR2: 14.753




0116+31 2025/07/08 21.05UT TOYOKAWA-KISO





F20250709060135




BLK: 3,SNR1: 4.6961 ,SNR2: 16.464




K20250709060132





BLK: 3,SNR1: 18.571 ,SNR2: 23.354




0116+31 2025/07/08 21.05UT FUJI -KISO



T20250709061940





BLK:13,SNR1: 0.55642 ,SNR2: 1.5014





3048 2025/07/08 21.36UT TOYOKAWA-FUJI



F20250709061941




BLK:13,SNR1: 30.914 ,SNR2: 82.753



T20250709061940




BLK:13,SNR1: 0.37199 ,SNR2: 3.1721





3C48 2025/07/08 21.36UT TOYOKAWA-KISO


K20250709061937




BLK:13,SNR1: 0.16889E-01,SNR2: 1.0919



F20250709061941




BLK:10,SNR1: 20.441 ,SNR2: 57.872





3C48 2025/07/08 21.36UT FUJI -KISO



K20250709061937




BLK:10,SNR1: 0.95159 ,SNR2: 1.9414





T20250709063324




No.Good Data




F20250709063324




No.Good Data





0148+274 2025/07/08 21.58UT TOYOKAWA-FUJI







BLK: 3,SNR1: 0.43236 ,SNR2: 4.6542




BLK: 3,SNR1: 1.4984 ,SNR2: 6.5002





0148+274 2025/07/08 21.58UT TOYOKAWA-KISO







BLK: 2,SNR1: 1.6237 ,SNR2: 3.4292





BLK: 2,SNR1: 1.2172 ,SNR2: 4.2994




0148+274 2025/07/08 21.58UT FUJI -KISO





T20250709064632




BLK: 2, SNR1: 23.542 , SNR2: 56.317




F20250709064632





BLK: 2, SNR1: 11.952 , SNR2: 29.234




0202+15 2025/07/08 21.80UT TOYOKAWA-FUJI





T20250709064632




BLK: 2, SNR1: 2.2331 ,SNR2: 10.504




K20250709064629





BLK: 2, SNR1: 8.0080 ,SNR2: 20.086




0202+15 2025/07/08 21.80UT TOYOKAWA-KISO





F20250709064632




BLK: 1, SNR1: 9.4723 , SNR2: 23.332




K20250709064629





BLK: 1, SNR1: 11.696 , SNR2: 28.324




0202+15 2025/07/08 21.80UT FUJI -KISO



T20250709065822




BLK: 7,SNR1: 13.399 ,SNR2: 32.951





0213+178 2025/07/08 22.00UT TOYOKAWA-FUJ



F20250709065822




BLK: 7,SNR1: 2.2800 ,SNR2: 6.8340




T20250709065822




BLK: 5, SNR1: 0.17219 , SNR2: 1.0318




K20250709065820




BLK: 5, SNR1: 10.757 , SNR2: 30.265




0213+178 2025/07/08 22.00UT TOYOKAWA-KISO




F20250709065822




BLK: 5, SNR1: 2.7921 ,SNR2: 6.3159




K20250709065820




BLK: 5, SNR1: 8.8627 ,SNR2: 21.766




0213+178 2025/07/08 22.00UT FUJI -KISO








BLK:12,SNR1: 8.0985 ,SNR2: 20.883




3C67 2025/07/08 22.13UT TOYOKAWA-FUJI





BLK:12,SNR1: 3.1960 ,SNR2: 9.6971







BLK:17,SNR1: 8.6343 ,SNR2: 21.689





BLK:17,SNR1: 8.2387 ,SNR2: 21.339




3C67 2025/07/08 22.13UT TOYOKAWA-KISO



F20250709070605





BLK:17,SNR1: 3.1858 ,SNR2: 9.6661





3C67 2025/07/08 22.13UT FUJI -KISO



K20250709070603




BLK:17,SNR1: 8.0896 ,SNR2: 20.962



T20250709072420




BLK: 6,SNR1: 0.78367E-01,SNR2: 1.8378





3C71 2025/07/08 22.43UT TOYOKAWA-FUJI



F20250709072420




BLK: 6,SNR1: 1.1735 ,SNR2: 4.8448





T20250709072420




BLK: 3,SNR1:-0.27880E-02,SNR2: 0.42778




K20250709072418




BLK: 3,SNR1: 1.0686 ,SNR2: 3.5324




3C71 2025/07/08 22.43UT TOYOKAWA-KISO



F20250709072420





BLK: 3,SNR1:-0.11112 ,SNR2: 2.0225






3C71 2025/07/08 22.43UT FUJI -KISO

K20250709072418





BLK: 3,SNR1: 3.1750 ,SNR2: 5.3878







BLK: 3,SNR1: 0.11231 ,SNR2: 1.2441





BLK: 3,SNR1: 0.96093 ,SNR2: 2.9631




0258+350 2025/07/08 22.75UT TOYOKAWA-FUJI





T20250709074335




BLK: 3, SNR1: 9.3011 , SNR2: 26.799




K20250709074332





BLK: 3, SNR1: 8.3074 , SNR2: 23.362




0258+350 2025/07/08 22.75UT TOYOKAWA-KISO





F20250709074335




BLK: 1,SNR1: 0.18537 ,SNR2: 2.3160




K20250709074332





BLK: 1,SNR1:-0.70125E-01,SNR2: 1.1581




0258+350 2025/07/08 22.75UT FUJI -KISO





T20250709075324




BLK: 3,SNR1: 2.1167 ,SNR2: 6.9904




F20250709075324





BLK: 3,SNR1: 8.6139 ,SNR2: 21.586




0308+305 2025/07/08 22.92UT TOYOKAWA-FUJI





T20250709075324




BLK: 6, SNR1: 6.8925 , SNR2: 18.533




K20250709075321





BLK: 6, SNR1: 12.095 , SNR2: 30.562




0308+305 2025/07/08 22.92UT TOYOKAWA-KISO





F20250709075324




BLK: 7, SNR1: 8.2966 , SNR2: 21.099




K20250709075321







BLK: 7, SNR1: 9.4728 , SNR2: 23.795




0308+305 2025/07/08 22.92UT FUJI -KISO








0320+05 2025/07/08 23.11UT TOYOKAWA-FUJI



T20250709080455




BLK: 3, SNR1: 3.9200 ,SNR2: 11.290









0320+05 2025/07/08 23.11UT TOYOKAWA-KISO

K20250709080452




BLK: 3, SNR1: 19.347 ,SNR2: 45.371








0320+05 2025/07/08 23.11UT FUJI -KISO



T20250709081817





BLK: 6,SNR1:-0.14768 ,SNR2: 0.32022





0333+32 2025/07/08 23.33UT TOYOKAWA-FUJI


F20250709081817




BLK: 6,SNR1: 186.14 ,SNR2: 504.01




T20250709081817




BLK: 5, SNR1: 0.14609 , SNR2: 0.70116




K20250709081814




BLK: 5, SNR1: 17.093 , SNR2: 39.746




0333+32 2025/07/08 23.33UT TOYOKAWA-KISO




F20250709081817




BLK:12,SNR1: 107.49 ,SNR2: 279.83




K20250709081814




BLK:12,SNR1: 10.372 ,SNR2: 25.419




0333+32 2025/07/08 23.33UT FUJI -KISO





T20250709083118




BLK: 6,SNR1: 0.11316 ,SNR2: 0.93161




F20250709083118





BLK: 6,SNR1: 0.98118 ,SNR2: 17.862




0347+05 2025/07/08 23.55UT TOYOKAWA-FUJI




T20250709083118




BLK: 5,SNR1: 0.42255E-01,SNR2: 0.60054




K20250709083115




BLK: 5,SNR1: 1.5062 ,SNR2: 4.5080




0347+05 2025/07/08 23.55UT TOYOKAWA-KISO




F20250709083118




BLK: 7, SNR1: 1.9194 , SNR2: 28.440




K20250709083115







BLK: 7, SNR1: 0.39218 , SNR2: 2.0023








0347+05 2025/07/08 23.55UT FUJI -KISO






0403-132 2025/07/08 23.81UT TOYOKAWA-FUJI







0403-132 2025/07/08 23.81UT TOYOKAWA-KISO





F20250709084652




BLK:16,SNR1: 187.96 ,SNR2: 587.23




K20250709084649







BLK:16,SNR1: 5.4436 ,SNR2: 14.041





0403-132 2025/07/08 23.81UT FUJI -KISO







0409+229 2025/07/08 23.93UT TOYOKAWA-FUJI







BLK:11,SNR1: 0.56875 ,SNR2: 2.4827




BLK:11,SNR1: 20.468 ,SNR2: 21.987





0409+229 2025/07/08 23.93UT TOYOKAWA-KISO







BLK:11,SNR1: 184.45 ,SNR2: 720.33





BLK:11,SNR1: 20.329 ,SNR2: 21.838




0409+229 2025/07/08 23.93UT FUJI -KISO





T20250709090258




BLK: 7, SNR1: 0.10907 , SNR2: 0.36337




F20250709090259





BLK: 7, SNR1: 14.786 , SNR2: 43.107




0418+236 2025/07/09 0.08UT TOYOKAWA-FUJI





T20250709090258




BLK: 6, SNR1: 0.57050 , SNR2: 1.7140




K20250709090255




BLK: 6, SNR1: 8.6262 , SNR2: 22.678




0418+236 2025/07/09 0.08UT TOYOKAWA-KISO





F20250709090259




BLK:10,SNR1: 10.160 ,SNR2: 32.064




K20250709090255







BLK:10,SNR1: 6.3898 ,SNR2: 16.629








0418+236 2025/07/09 0.08UT FUJI -KISO






3C119 2025/07/09 0.27UT TOYOKAWA-FUJI








3C119 2025/07/09 0.27UT TOYOKAWA-KISO



F20250709091426





BLK:11,SNR1: 3.1590 ,SNR2: 7.6148





3C119 2025/07/09 0.27UT FUJI -KISO



K20250709091423




BLK:11,SNR1: 1.2323 ,SNR2: 2.6053




T20250709100232




BLK:25,SNR1: 4.6380 ,SNR2: 10.104




F20250709100232








BLK:25,SNR1:-0.24180E-01,SNR2: 1.5000




3C138 2025/07/09 1.07UT TOYOKAWA-FUJI








F20250709100232




BLK:21,SNR1:-0.18948 ,SNR2: 1.1822




K20250709100230





BLK:21,SNR1: 1.2471 ,SNR2: 3.8696




3C138 2025/07/09 1.07UT FUJI -KISO




T20250709101606




BLK:20,SNR1: 2.0670 ,SNR2: 5.0495




F20250709101606




BLK:20,SNR1: 0.12237 ,SNR2: 2.5521




0531+194 2025/07/09 1.30UT TOYOKAWA-FUJI





T20250709101606




BLK:23,SNR1: 12.191 ,SNR2: 46.346




K20250709101603




BLK:23,SNR1: 0.49618 ,SNR2: 2.2520




0531+194 2025/07/09 1.30UT TOYOKAWA-KISO





F20250709101606




BLK:20,SNR1: 0.20483 ,SNR2: 2.1440




K20250709101603





BLK:20,SNR1: 0.88022 ,SNR2: 4.0754




0531+194 2025/07/09 1.30UT FUJI -KISO




T20250709102426




BLK:26,SNR1: 14.619 ,SNR2: 63.269




F20250709102426





BLK:26,SNR1: 0.16078 ,SNR2: 4.1061




3C147 2025/07/09 1.44UT TOYOKAWA-FUJI





T20250709102426




BLK:30,SNR1: 13.419 ,SNR2: 80.396




K20250709102423




BLK:30,SNR1: 2.1682 ,SNR2: 6.6446




3C147 2025/07/09 1.44UT TOYOKAWA-KISO





F20250709102426




BLK:32,SNR1: 0.22851 ,SNR2: 4.5562




K20250709102423





BLK:32,SNR1: 2.1189 ,SNR2: 14.844




3C147 2025/07/09 1.44UT FUJI -KISO



T20250709103237





BLK:15,SNR1: 10.431 ,SNR2: 16.341





0548+16 2025/07/09 1.57UT TOYOKAWA-FUJI



F20250709103237




BLK:15,SNR1: 19.336 ,SNR2: 21.325





T20250709103237




BLK:19,SNR1: 9.9975 ,SNR2: 15.681




K20250709103234





BLK:19,SNR1: 12.958 ,SNR2: 33.276




0548+16 2025/07/09 1.57UT TOYOKAWA-KISO





F20250709103237




BLK:14,SNR1: 19.359 ,SNR2: 21.350




K20250709103234




BLK:14,SNR1: 11.660 ,SNR2: 29.978




0548+16 2025/07/09 1.57UT FUJI -KISO





T20250709103647




BLK: 7, SNR1: 10.031 , SNR2: 47.870




F20250709103647





BLK: 7, SNR1: 0.82450 , SNR2: 2.3318




0552+12 2025/07/09 1.64UT TOYOKAWA-FUJI





T20250709103647




BLK:12,SNR1: 3.3171 ,SNR2: 16.187




K20250709103644





BLK:12,SNR1: 2.0105 ,SNR2: 6.1961




0552+12 2025/07/09 1.64UT TOYOKAWA-KISO





F20250709103647




BLK:13,SNR1: 1.2866 ,SNR2: 3.1044




K20250709103644




BLK:13,SNR1: 1.9910 ,SNR2: 6.1749




0552+12 2025/07/09 1.64UT FUJI -KISO





T20250709104114




BLK:14,SNR1: 0.22919 ,SNR2: 1.2507




F20250709104114




BLK:14,SNR1: 0.49801 ,SNR2: 2.2021




0556+191 2025/07/09 1.72UT TOYOKAWA-FUJI





T20250709104114




BLK:14,SNR1: 0.36816 ,SNR2: 0.85993




K20250709104111




BLK:14,SNR1: 61.958 ,SNR2: 72.299




0556+191 2025/07/09 1.72UT TOYOKAWA-KISO





F20250709104114




BLK:11,SNR1: 4.0920 ,SNR2: 12.441




K20250709104111




BLK:11,SNR1: 113.99 ,SNR2: 129.99





0556+191 2025/07/09 1.72UT FUJI -KISO







BLK: 3,SNR1: 0.31973 ,SNR2: 1.2651




BLK: 3,SNR1: 0.83691 ,SNR2: 11.968





0605-08 2025/07/09 1.84UT TOYOKAWA-FUJI







BLK: 1,SNR1: 0.10621 ,SNR2: 0.53245




BLK: 1,SNR1: 1.2572 ,SNR2: 8.9505




0605-08 2025/07/09 1.84UT TOYOKAWA-KISO





F20250709104900




BLK: 2,SNR1: 0.42644 ,SNR2: 8.1532




K20250709104857




BLK: 2,SNR1: 0.61354E-01,SNR2: 0.78876




0605-08 2025/07/09 1.84UT FUJI -KISO




T20250709110808




BLK:17,SNR1: 6.6288 ,SNR2: 18.165




F20250709110808




BLK:17,SNR1: 1.4461 ,SNR2: 9.3512




3C161 2025/07/09 2.16UT TOYOKAWA-FUJI



T20250709110808




BLK:35,SNR1: 4.4611 ,SNR2: 12.294





3C161 2025/07/09 2.16UT TOYOKAWA-KISO


K20250709110805




BLK:35,SNR1: 11.116 ,SNR2: 15.887




F20250709110808




BLK:16,SNR1: 0.79916 ,SNR2: 5.6336




K20250709110805







BLK:16,SNR1: 21.260 ,SNR2: 26.980









3C161 2025/07/09 2.16UT FUJI -KISO






0652-130 2025/07/09 2.62UT TOYOKAWA-FUJI







F20250709113540




BLK: 7,SNR1: 0.42487 ,SNR2: 3.1808




K20250709113537




BLK: 7,SNR1: 0.68519 ,SNR2: 2.5647





0652-130 2025/07/09 2.62UT FUJI -KISO







BLK:13,SNR1: 0.24850 ,SNR2: 1.1033








BLK:13,SNR1: 6.1574 ,SNR2: 17.740




0703+138 2025/07/09 2.82UT TOYOKAWA-FUJI







F20250709114717




BLK:13,SNR1: 4.6678 ,SNR2: 12.317




K20250709114714





BLK:13,SNR1: 0.63034 ,SNR2: 2.4178




0703+138 2025/07/09 2.82UT FUJI -KISO





T20250709115640




BLK:15,SNR1: 0.46531 ,SNR2: 2.1751




F20250709115640





BLK:15,SNR1: 1.1773 ,SNR2: 5.1996




0713-024 2025/07/09 2.97UT TOYOKAWA-FUJI





T20250709115640




BLK:16,SNR1: 0.39817 ,SNR2: 1.8947




K20250709115637




BLK:16,SNR1: 1.6263 ,SNR2: 4.9676




0713-024 2025/07/09 2.97UT TOYOKAWA-KISO




F20250709115640




BLK:15,SNR1: 1.2231 ,SNR2: 5.2941




K20250709115637








BLK:15,SNR1: 1.0543 ,SNR2: 3.3818





0713-024 2025/07/09 2.97UT FUJI -KISO








T20250709120652




BLK:17,SNR1: 3.1808 ,SNR2: 9.6238




K20250709120649







BLK:17,SNR1: 3.2109 ,SNR2: 8.2479




0723+10 2025/07/09 3.14UT TOYOKAWA-KISO







0723+10 2025/07/09 3.14UT FUJI -KISO




T20250709121707




BLK:13,SNR1: 0.77253 ,SNR2: 3.9722




F20250709121707




BLK:13,SNR1: 0.27315 ,SNR2: 1.2370




0732+33 2025/07/09 3.31UT TOYOKAWA-FUJI




T20250709121707




BLK:25,SNR1: 0.84354 ,SNR2: 4.0123




K20250709121704




BLK:25,SNR1: 0.13243 ,SNR2: 0.82609




0732+33 2025/07/09 3.31UT TOYOKAWA-KISO




F20250709121707




BLK:13,SNR1: 0.34840 ,SNR2: 1.1544




K20250709121704





BLK:13,SNR1: 0.26531 ,SNR2: 1.3831





0732+33 2025/07/09 3.31UT FUJI -KISO







0741-06 2025/07/09 3.45UT TOYOKAWA-FUJI







BLK:23,SNR1: 2.2591 ,SNR2: 6.6736





BLK:23,SNR1: 7.0698 ,SNR2: 15.654




0741-06 2025/07/09 3.45UT TOYOKAWA-KISO




F20250709122508




BLK:15,SNR1: 3.2299 ,SNR2: 9.8055




K20250709122505





BLK:15,SNR1: 6.4117 ,SNR2: 14.902




0741-06 2025/07/09 3.45UT FUJI -KISO




T20250709123452




BLK:13,SNR1: 4.2157 ,SNR2: 9.6751




F20250709123452





BLK:13,SNR1: 2.6875 ,SNR2: 7.2656




0752-200 2025/07/09 3.61UT TOYOKAWA-FUJI





T20250709123452




BLK:19,SNR1: 27.964 ,SNR2: 56.029




K20250709123449




BLK:19,SNR1: 49.653 ,SNR2: 48.939




0752-200 2025/07/09 3.61UT TOYOKAWA-KISO





F20250709123452




BLK:13,SNR1: 3.6519 ,SNR2: 9.9427




K20250709123449




BLK:13,SNR1: 47.667 ,SNR2: 50.925




0752-200 2025/07/09 3.61UT FUJI -KISO




T20250709124228




BLK:11,SNR1: 0.47440 ,SNR2: 3.9812




F20250709124228





BLK:11,SNR1:-0.27663E-01,SNR2: 0.84187




3C190 2025/07/09 3.74UT TOYOKAWA-FUJI





T20250709124228




BLK:18,SNR1: 0.47878 ,SNR2: 2.3861




K20250709124225





BLK:18,SNR1: 145.60 ,SNR2: 162.41




3C190 2025/07/09 3.74UT TOYOKAWA-KISO







3C190 2025/07/09 3.74UT FUJI -KISO





T20250709125453




BLK:18,SNR1: 3.3969 ,SNR2: 8.8232




F20250709125453





BLK:18,SNR1: 3.5853 ,SNR2: 10.648




3C196 2025/07/09 3.94UT TOYOKAWA-FUJI





T20250709125453




BLK:27,SNR1: 3.0767 ,SNR2: 7.9102




K20250709125450





BLK:27,SNR1: 8.0822 ,SNR2: 20.980




3C196 2025/07/09 3.94UT TOYOKAWA-KISO





F20250709125453




BLK:21,SNR1: 3.6551 ,SNR2: 10.827




K20250709125450





BLK:21,SNR1: 8.0899 ,SNR2: 21.001




3C196 2025/07/09 3.94UT FUJI -KISO





T20250709130602




BLK:11,SNR1: 0.44731 ,SNR2: 4.6369




F20250709130602





BLK:11,SNR1: 1.5572 ,SNR2: 5.2251




0821+394 2025/07/09 4.13UT TOYOKAWA-FUJI




T20250709130602




BLK:12,SNR1: 0.35570 ,SNR2: 2.5058




K20250709130559




BLK:12,SNR1: 0.50667 ,SNR2: 2.0383





0821+394 2025/07/09 4.13UT TOYOKAWA-KISO







BLK: 7,SNR1: 2.8929 ,SNR2: 6.8845





BLK: 7,SNR1: 1.5771 ,SNR2: 4.1465




0821+394 2025/07/09 4.13UT FUJI -KISO





T20250709131741




BLK:12,SNR1: 3.3540 ,SNR2: 5.3474




F20250709131741





BLK:12,SNR1: 3.1520 ,SNR2: 9.2395




0834-19 2025/07/09 4.32UT TOYOKAWA-FUJI





T20250709131741




BLK:19,SNR1: 2.6767 ,SNR2: 4.2611




K20250709131738




BLK:19,SNR1: 4.5387 ,SNR2: 11.924





0834-19 2025/07/09 4.32UT TOYOKAWA-KISO







BLK:10,SNR1: 1.2982 ,SNR2: 3.6347




BLK:10,SNR1: 5.9222 ,SNR2: 15.308





0834-19 2025/07/09 4.32UT FUJI -KISO







BLK:16,SNR1: 4.1559 ,SNR2: 25.046




BLK:16,SNR1: 4.3484 ,SNR2: 29.984





0839-071 2025/07/09 4.41UT TOYOKAWA-FUJI







BLK:12,SNR1: 1.0471 ,SNR2: 4.8296





BLK:12,SNR1: 0.51835 ,SNR2: 1.7338




0839-071 2025/07/09 4.41UT TOYOKAWA-KISO




F20250709132247




BLK:11,SNR1: 8.7637 ,SNR2: 72.658




K20250709132244




BLK:11,SNR1: 0.44604 ,SNR2: 2.1957





0839-071 2025/07/09 4.41UT FUJI -KISO







BLK: 8,SNR1: 0.30087 ,SNR2: 3.2230





BLK: 8,SNR1: 4.0776 ,SNR2: 9.5601




3C208 2025/07/09 4.59UT TOYOKAWA-FUJI







3C208 2025/07/09 4.59UT TOYOKAWA-KISO




F20250709133348




BLK: 7,SNR1: 3.8011 ,SNR2: 8.9836




K20250709133345





BLK: 7,SNR1: 6.2854 ,SNR2: 11.222




3C208 2025/07/09 4.59UT FUJI -KISO





T20250709135030




BLK:14,SNR1: 0.42505 ,SNR2: 1.3606




F20250709135030





BLK:14,SNR1: 2.0910 ,SNR2: 7.6611




3C216 2025/07/09 4.87UT TOYOKAWA-FUJI




T20250709135030




BLK: 8,SNR1: 0.52702 ,SNR2: 2.4142




K20250709135027





BLK: 8,SNR1: 1.0167 ,SNR2: 3.5156




3C216 2025/07/09 4.87UT TOYOKAWA-KISO





F20250709135030




BLK: 8,SNR1: 0.85264 ,SNR2: 3.6255




K20250709135027




BLK: 8,SNR1: 2.5371 ,SNR2: 8.0201




3C216 2025/07/09 4.87UT FUJI -KISO




T20250709140241




BLK:13,SNR1: 5.9321 ,SNR2: 10.626




F20250709140241




BLK:13,SNR1: 8.6546 ,SNR2: 18.957





0919-142 2025/07/09 5.07UT TOYOKAWA-FUJI







BLK:16,SNR1: 7.2717 ,SNR2: 18.896




BLK:16,SNR1: 9.2453 ,SNR2: 20.009




0919-142 2025/07/09 5.07UT TOYOKAWA-KISO





F20250709140241




BLK:15,SNR1: 8.6416 ,SNR2: 19.125




K20250709140238





BLK:15,SNR1: 2.1559 ,SNR2: 7.0773




0919-142 2025/07/09 5.07UT FUJI -KISO





T20250709140920




BLK: 8,SNR1: 1.4741 ,SNR2: 3.4774




F20250709140920





BLK: 8,SNR1: 0.95949 ,SNR2: 3.7334




0926+117 2025/07/09 5.18UT TOYOKAWA-FUJI





T20250709140920




BLK: 5,SNR1: 0.16137 ,SNR2: 0.43865




K20250709140917







BLK: 5,SNR1: 0.55271 ,SNR2: 2.0209





0926+117 2025/07/09 5.18UT TOYOKAWA-KISO









BLK: 6,SNR1: 6.4026 ,SNR2: 12.327







BLK: 6,SNR1: 6.1753 ,SNR2: 16.730





3C222 2025/07/09 5.31UT TOYOKAWA-FUJI







3C222 2025/07/09 5.31UT TOYOKAWA-KISO







BLK: 7,SNR1: 7.3594 ,SNR2: 20.198




BLK: 7,SNR1: 94.065 ,SNR2: 96.442





3C222 2025/07/09 5.31UT FUJI -KISO







BLK: 8,SNR1: 0.17976E-01,SNR2: 0.50704




BLK: 8,SNR1: 0.91541 ,SNR2: 4.5574





0941-08 2025/07/09 5.43UT TOYOKAWA-FUJI







BLK: 7,SNR1: 0.61242 ,SNR2: 2.3789




BLK: 7,SNR1: 5.2527 ,SNR2: 13.677






0941-08 2025/07/09 5.43UT TOYOKAWA-KISO




F20250709142404





K20250709142401




0941-08 2025/07/09 5.43UT FUJI -KISO





T20250709143226




BLK: 2,SNR1: 0.33206 ,SNR2: 4.6312




F20250709143226





BLK: 2,SNR1: 0.18592E-01,SNR2: 1.2655




3C230 2025/07/09 5.57UT TOYOKAWA-FUJI





T20250709143226




BLK: 8,SNR1: 0.12659 ,SNR2: 1.7885




K20250709143223




BLK: 8,SNR1: 0.54350 ,SNR2: 2.6734




3C230 2025/07/09 5.57UT TOYOKAWA-KISO





F20250709143226




BLK: 7,SNR1: 0.87364 ,SNR2: 2.1005




K20250709143223




BLK: 7,SNR1: 0.84605 ,SNR2: 2.7118





3C230 2025/07/09 5.57UT FUJI -KISO







BLK:13,SNR1: 7.1697 ,SNR2: 17.935




BLK:13,SNR1: 9.5669 ,SNR2: 24.380





3C237 2025/07/09 5.84UT TOYOKAWA-FUJI







BLK:11,SNR1: 5.8120 ,SNR2: 14.183




BLK:11,SNR1: 8.2480 ,SNR2: 21.959





3C237 2025/07/09 5.84UT TOYOKAWA-KISO







BLK: 8,SNR1: 13.447 ,SNR2: 31.947




BLK: 8,SNR1: 7.3246 ,SNR2: 18.468





3C237 2025/07/09 5.84UT FUJI -KISO







BLK: 9,SNR1: 0.46565 ,SNR2: 0.93132







BLK: 9,SNR1: 1.1086 ,SNR2: 1.8472




1011+110 2025/07/09 5.94UT TOYOKAWA-FUJI








1011+110 2025/07/09 5.94UT TOYOKAWA-KISO





F20250709145443




BLK:16,SNR1: 1.1189 ,SNR2: 2.5457




K20250709145440




BLK:16,SNR1: 7.7723 ,SNR2: 13.608





1011+110 2025/07/09 5.94UT FUJI -KISO







BLK: 9,SNR1: 7.0375 ,SNR2: 20.293




BLK: 9,SNR1: 5.3999 ,SNR2: 13.593





3C241 2025/07/09 6.07UT TOYOKAWA-FUJI







BLK: 8,SNR1: 0.83461 ,SNR2: 3.8845




BLK: 8,SNR1: 7.2860 ,SNR2: 18.831





3C241 2025/07/09 6.07UT TOYOKAWA-KISO







BLK: 7,SNR1: 8.9377 ,SNR2: 21.505




BLK: 7,SNR1: 8.7826 ,SNR2: 21.966





3C241 2025/07/09 6.07UT FUJI -KISO







BLK: 7,SNR1: 7.7497 ,SNR2: 19.894




BLK: 7,SNR1: 8.0485 ,SNR2: 23.303





1031-11 2025/07/09 6.26UT TOYOKAWA-FUJI







BLK:10,SNR1: 4.6634 ,SNR2: 13.473




BLK:10,SNR1: 2.4855 ,SNR2: 7.2632





1031-11 2025/07/09 6.26UT TOYOKAWA-KISO








BLK:10,SNR1: 10.329 ,SNR2: 24.378





BLK:10,SNR1: 6.8139 ,SNR2: 19.665







BLK: 9,SNR1: 4.2181 ,SNR2: 8.1950





BLK: 9,SNR1: 2.7323 ,SNR2: 6.8035




1035-058 2025/07/09 6.34UT TOYOKAWA-FUJI





T20250709151827




BLK: 6,SNR1: 12.687 ,SNR2: 57.790




K20250709151824




BLK: 6,SNR1: 1.2849 ,SNR2: 3.8762





1035-058 2025/07/09 6.34UT TOYOKAWA-KISO









BLK: 6,SNR1: 0.81091E-01,SNR2: 1.7409




BLK: 6,SNR1: 1.1717 ,SNR2: 2.8013




T20250709152740




BLK: 4,SNR1: 0.84133 ,SNR2: 5.6167




F20250709152740





BLK: 4,SNR1: 1.1667 ,SNR2: 2.6096




1044-008 2025/07/09 6.49UT TOYOKAWA-FUJI





T20250709152740




BLK: 3, SNR1: 0.89735 , SNR2: 3.4654




K20250709152737




BLK: 3, SNR1: 8.1824 , SNR2: 22.393




1044-008 2025/07/09 6.49UT TOYOKAWA-KISO



F20250709152740





BLK: 8,SNR1: 2.1713 ,SNR2: 6.5840




Frequency (Hz)

K20250709152737




BLK: 8,SNR1: 127.61 ,SNR2: 163.97





Frequency (Hz)


1044-008 2025/07/09 6.49UT FUJI -KISO




T20250709153844




BLK:13,SNR1: 1.1925 ,SNR2: 3.6888




F20250709153844




BLK:13,SNR1: 5.9173 ,SNR2: 17.830





1055+01 2025/07/09 6.67UT TOYOKAWA-FUJI







BLK: 6,SNR1: 0.13846 ,SNR2: 1.0609





BLK: 6,SNR1: 25.786 ,SNR2: 47.867




1055+01 2025/07/09 6.67UT TOYOKAWA-KISO



F20250709153844





BLK:15,SNR1: 6.5466 ,SNR2: 19.721




Frequency (Hz)

K20250709153841







BLK:15,SNR1: 78.938 ,SNR2: 86.154







Frequency (Hz)


1055+01 2025/07/09 6.67UT FUJI -KISO









1107+109 2025/07/09 6.86UT TOYOKAWA-KISO



F20250709155002




BLK: 7, SNR1: 2.3062 , SNR2: 5.9763




Frequency (Hz)

K20250709154959




BLK: 7, SNR1: 1.1755 , SNR2: 4.2731





Frequency (Hz)


1107+109 2025/07/09 6.86UT FUJI -KISO



T20250709155939




BLK:14,SNR1: 3.5112 ,SNR2: 10.505




Frequency (Hz)

F20250709155939








BLK:14,SNR1: 0.45826 ,SNR2: 3.3480




Frequency (Hz)


3C255 2025/07/09 7.02UT TOYOKAWA-FUJI







3C255 2025/07/09 7.02UT TOYOKAWA-KISO







BLK:15,SNR1: 0.44089 ,SNR2: 3.2658




BLK:15,SNR1: 9.6872 ,SNR2: 10.648





3C255 2025/07/09 7.02UT FUJI -KISO







BLK: 7, SNR1: 0.12694 , SNR2: 1.4676




BLK: 7, SNR1: 0.67057 , SNR2: 2.8967





1127-14 2025/07/09 7.20UT TOYOKAWA-FUJI







BLK: 7,SNR1: 0.55395 ,SNR2: 0.92842





BLK: 7,SNR1: 1.7872 ,SNR2: 5.4445




1127-14 2025/07/09 7.20UT TOYOKAWA-KISO



F20250709161017




BLK:10,SNR1: 1.0407 ,SNR2: 3.9170




Frequency (Hz)

K20250709161014





BLK:10,SNR1: 1.9164 ,SNR2: 6.0847





Frequency (Hz)

1127-14 2025/07/09 7.20UT FUJI -KISO







BLK:10,SNR1: 7.1796 ,SNR2: 18.456




BLK:10,SNR1: 2.9044 ,SNR2: 8.8072





3C263.1 2025/07/09 7.42UT TOYOKAWA-FUJI







BLK:12,SNR1: 11.557 ,SNR2: 27.154




BLK:12,SNR1: 14.954 ,SNR2: 34.960





3C263.1 2025/07/09 7.42UT TOYOKAWA-KISO







BLK:10,SNR1: 0.48707 ,SNR2: 2.4382





BLK:10,SNR1: 5.4568 ,SNR2: 7.2438




3C263.1 2025/07/09 7.42UT FUJI -KISO




T20250709163004




BLK: 8,SNR1: 0.81074 ,SNR2: 2.7987




F20250709163004




BLK: 8,SNR1: 4.0321 ,SNR2: 5.6700





3C267 2025/07/09 7.53UT TOYOKAWA-FUJI







BLK:17,SNR1: 1.4273 ,SNR2: 4.2926




BLK:17,SNR1: 8.5494 ,SNR2: 20.039





3C267 2025/07/09 7.53UT TOYOKAWA-KISO







BLK:26,SNR1: 2.9501 ,SNR2: 6.9648







BLK:26,SNR1: 8.3883 ,SNR2: 19.664








3C267 2025/07/09 7.53UT FUJI -KISO










1206+439 2025/07/09 7.85UT TOYOKAWA-FUJI







1206+439 2025/07/09 7.85UT TOYOKAWA-KISO







1206+439 2025/07/09 7.85UT FUJI -KISO







BLK: 1,SNR1: 0.41740 ,SNR2: 1.9204




BLK: 1,SNR1: 11.710 ,SNR2: 37.017





1313+453 2025/07/09 8.96UT TOYOKAWA-FUJI







BLK: 7,SNR1: 3.2718 ,SNR2: 9.4483




BLK: 7,SNR1: 0.15227 ,SNR2: 3.4505





1313+453 2025/07/09 8.96UT TOYOKAWA-KISO







BLK: 8,SNR1: 11.644 ,SNR2: 29.675





BLK: 8,SNR1: 0.52979E-01,SNR2: 2.4182




1313+453 2025/07/09 8.96UT FUJI -KISO



T20250709181715





BLK:12,SNR1: 4.4696 ,SNR2: 6.6530




Frequency (Hz)

F20250709181715





BLK:12,SNR1: 5.2407 ,SNR2: 13.218





Frequency (Hz)

1335+479 2025/07/09 9.32UT TOYOKAWA-FUJI






BLK:13,SNR1: 4.7134 ,SNR2: 7.5308



BLK:13,SNR1: 5.3928 ,SNR2: 12.243



1335+479 2025/07/09 9.32UT TOYOKAWA-KISO

