






T20250711054055




BLK:17,SNR1: 3.7689 ,SNR2: 10.761




F20250711054055








BLK:17,SNR1: 0.41922 ,SNR2: 1.6920




0103+422 2025/07/10 20.71UT TOYOKAWA-FUJI













BLK:14,SNR1: 0.55417 ,SNR2: 1.8806





BLK:14,SNR1: 2.4938 ,SNR2: 5.7171




0103+422 2025/07/10 20.71UT FUJI -KISO





T20250711055736




BLK: 1, SNR1: 1.3442 , SNR2: 3.8165




F20250711055736













BLK: 1, SNR1: 0.27916 , SNR2: 1.6193







0120+405 2025/07/10 20.99UT TOYOKAWA-FUJI

















BLK:24,SNR1: 3.0331 ,SNR2: 9.3572




BLK:24,SNR1: 8.1746 ,SNR2: 21.156



F20250711061148





BLK:26,SNR1: 10.287 ,SNR2: 17.909




Frequency (Hz)

3C48 2025/07/10 21.22UT FUJI -KISO


K20250711061145





BLK:26,SNR1: 8.1747 ,SNR2: 21.156




Frequency (Hz)



T20250711062532





BLK: 3,SNR1: 16.367 ,SNR2: 28.797




Frequency (Hz)

F20250711062532




BLK: 3,SNR1: 1.3590 ,SNR2: 10.322





Frequency (Hz)

0148+274 2025/07/10 21.45UT TOYOKAWA-FUJI






T20250711062532





BLK: 3,SNR1: 9.8127 ,SNR2: 24.129




Frequency (Hz)

K20250711062529




BLK: 3,SNR1: 3.5668 ,SNR2: 13.002





Frequency (Hz)


0148+274 2025/07/10 21.45UT TOYOKAWA-KISO





F20250711062532




BLK: 1, SNR1: 2.5066 , SNR2: 5.8441




K20250711062529





BLK: 1, SNR1: 6.0727 , SNR2: 14.566




0148+274 2025/07/10 21.45UT FUJI -KISO




T20250711063840




BLK: 3,SNR1: 2.2049 ,SNR2: 9.3190




F20250711063840





BLK: 3,SNR1: 1.9459 ,SNR2: 6.1951




0202+15 2025/07/10 21.67UT TOYOKAWA-FUJI





T20250711063840




BLK: 5, SNR1: 5.8196 , SNR2: 14.524




K20250711063837




BLK: 5, SNR1: 10.853 , SNR2: 23.691




0202+15 2025/07/10 21.67UT TOYOKAWA-KISO





F20250711063840




BLK: 8, SNR1: 4.3951 , SNR2: 8.1427




K20250711063837





BLK: 8, SNR1: 10.315 , SNR2: 22.538




0202+15 2025/07/10 21.67UT FUJI -KISO





T20250711065030




BLK: 5, SNR1: 5.9963 , SNR2: 17.136




F20250711065030





BLK: 5, SNR1: 34.520 , SNR2: 42.475




0213+178 2025/07/10 21.87UT TOYOKAWA-FUJI





T20250711065030




BLK: 1, SNR1: 3.1585 , SNR2: 11.930




K20250711065027





BLK: 1, SNR1: 10.086 , SNR2: 22.020




0213+178 2025/07/10 21.87UT TOYOKAWA-KISO





F20250711065030




BLK:10,SNR1: 9.2511 ,SNR2: 26.437




K20250711065027



BLK:10,SNR1: 6.8155 ,SNR2: 19.912





0213+178 2025/07/10 21.87UT FUJI -KISO






T20250711065813





No.Good Data




Frequency (Hz)

F20250711065813






No.Good Data




Frequency (Hz)




3C67 2025/07/10 22.00UT TOYOKAWA-FUJI







3C67 2025/07/10 22.00UT TOYOKAWA-KISO






T20250711071628





BLK: 8,SNR1: 8.2113 ,SNR2: 19.995





3C71 2025/07/10 22.30UT TOYOKAWA-FUJI



F20250711071628




BLK: 8,SNR1: 8.8160 ,SNR2: 22.687



T20250711071628





BLK: 8,SNR1: 6.1745 ,SNR2: 15.632





3C71 2025/07/10 22.30UT TOYOKAWA-KISO



K20250711071625




BLK: 8,SNR1: 10.489 ,SNR2: 26.460





F20250711071628




BLK: 4, SNR1: 8.4022 , SNR2: 22.398




K20250711071625





BLK: 4, SNR1: 11.464 , SNR2: 28.850




3C71 2025/07/10 22.30UT FUJI -KISO




T20250711073543




BLK: 8, SNR1: 13.498 , SNR2: 30.916




F20250711073543





BLK: 8, SNR1: 4.9265 , SNR2: 12.986




0258+350 2025/07/10 22.62UT TOYOKAWA-FUJI





T20250711073543




BLK: 7, SNR1: 13.792 , SNR2: 31.604




K20250711073540



BLK: 7, SNR1: 7.0359 , SNR2: 18.027





0258+350 2025/07/10 22.62UT TOYOKAWA-KISO







F20250711073543




BLK: 3, SNR1: 2.7976 , SNR2: 7.3852




K20250711073540





BLK: 3, SNR1: 8.2486 , SNR2: 21.097




0258+350 2025/07/10 22.62UT FUJI -KISO



T20250711074532





BLK: 3,SNR1: 2.1805 ,SNR2: 6.4478




Frequency (Hz)

F20250711074532




BLK: 3,SNR1: 0.29865 ,SNR2: 1.3197




Frequency (Hz)


0308+305 2025/07/10 22.79UT TOYOKAWA-FUJI




T20250711074532




BLK: 5, SNR1: 0.49291 , SNR2: 1.1877




K20250711074529




BLK: 5, SNR1: 2.3910 , SNR2: 6.9333




0308+305 2025/07/10 22.79UT TOYOKAWA-KISO




F20250711074532




BLK: 6,SNR1: 1.2714 ,SNR2: 4.1025




K20250711074529




BLK: 6,SNR1: 1.9417 ,SNR2: 4.7373




0308+305 2025/07/10 22.79UT FUJI -KISO




T20250711075704




BLK: 7, SNR1: 0.59869 , SNR2: 1.5284




F20250711075704







BLK: 7, SNR1: 2.4616 , SNR2: 6.9066




0320+05 2025/07/10 22.98UT TOYOKAWA-FUJI







0320+05 2025/07/10 22.98UT TOYOKAWA-KISO





F20250711075704




BLK: 5, SNR1: 1.1455 , SNR2: 3.3171




K20250711075701




BLK: 5, SNR1: 4.9201 , SNR2: 14.872




0320+05 2025/07/10 22.98UT FUJI -KISO





T20250711081025




BLK: 8, SNR1: 0.85420 , SNR2: 2.5749




F20250711081026



BLK: 8, SNR1: 1.5909 , SNR2: 4.3372




0333+32 2025/07/10 23.20UT TOYOKAWA-FUJI








T20250711081025




BLK: 6, SNR1: 0.21613 , SNR2: 1.4005




K20250711081022




BLK: 6, SNR1: 35.332 , SNR2: 62.551




0333+32 2025/07/10 23.20UT TOYOKAWA-KISO





F20250711081026




BLK: 4, SNR1: 1.2192 , SNR2: 4.1900




K20250711081022




BLK: 4, SNR1: 3.0742 , SNR2: 5.6530




0333+32 2025/07/10 23.20UT FUJI -KISO




T20250711082326




BLK: 3, SNR1: 3.8962 , SNR2: 10.514




F20250711082326




BLK: 3, SNR1: 5.8245 , SNR2: 16.754




0347+05 2025/07/10 23.42UT TOYOKAWA-FUJI




T20250711082326




BLK: 3, SNR1: 0.14277 , SNR2: 0.33266




K20250711082323




BLK: 3, SNR1: 6.4725 , SNR2: 16.124




0347+05 2025/07/10 23.42UT TOYOKAWA-KISO




F20250711082326




BLK: 6, SNR1: 1.9582 , SNR2: 5.9804




K20250711082323




BLK: 6, SNR1: 6.4963 , SNR2: 18.142





0347+05 2025/07/10 23.42UT FUJI -KISO







BLK:16,SNR1: 0.61846E-01,SNR2: 0.48844




BLK:16,SNR1: 4.4092 ,SNR2: 18.095




0403-132 2025/07/10 23.68UT TOYOKAWA-FUJI






BLK: 4,SNR1: 0.16380 ,SNR2: 0.65316




BLK: 4,SNR1: 0.51512 ,SNR2: 2.0550


0403-132 2025/07/10 23.68UT TOYOKAWA-KISO





F20250711083901




BLK:15,SNR1: 7.1706 ,SNR2: 26.698




K20250711083858




BLK:15,SNR1: 0.15190 ,SNR2: 1.6436





0403-132 2025/07/10 23.68UT FUJI -KISO









BLK: 4,SNR1:-0.38292E-01,SNR2: 1.3047




BLK: 4,SNR1: 0.26272 ,SNR2: 1.8439





0411+05 2025/07/10 23.83UT TOYOKAWA-FUJI







BLK: 6,SNR1: 0.22997 ,SNR2: 0.95191










BLK: 6,SNR1: 5.5925 ,SNR2: 13.209




0411+05 2025/07/10 23.83UT TOYOKAWA-KISO










3C119 2025/07/11 0.14UT TOYOKAWA-FUJI




T20250711090634




BLK:20,SNR1: 1.0058 ,SNR2: 7.3285




K20250711090631





BLK:20,SNR1: 0.14564 ,SNR2: 0.97643




3C119 2025/07/11 0.14UT TOYOKAWA-KISO





F20250711090634




BLK:17,SNR1: 1.3217 ,SNR2: 5.9317




K20250711090631













BLK:17,SNR1: 0.25317 ,SNR2: 2.7794



3C119 2025/07/11 0.14UT FUJI -KISO













F20250711095441




BLK:19,SNR1: 0.18595 ,SNR2: 1.9231




K20250711095438




BLK:19,SNR1: 0.43633 ,SNR2: 1.9824





3C138 2025/07/11 0.94UT FUJI -KISO







BLK:29,SNR1: 3.6499 ,SNR2: 10.852







BLK:29,SNR1: 2.8106 ,SNR2: 8.7640




0531+194 2025/07/11 1.17UT TOYOKAWA-FUJI








0531+194 2025/07/11 1.17UT TOYOKAWA-KISO





F202507111100814




BLK:26,SNR1: 2.5668 ,SNR2: 8.1716




K202507111100811





BLK:26,SNR1: 11.968 ,SNR2: 14.138




0531+194 2025/07/11 1.17UT FUJI -KISO




T202507111101634




BLK:27,SNR1: 22.508 ,SNR2: 103.90




F202507111101634





BLK:27,SNR1: 0.57347 ,SNR2: 3.0149




3C147 2025/07/11 1.30UT TOYOKAWA-FUJI




T202507111101634




BLK:32,SNR1: 21.043 ,SNR2: 99.428




K202507111101631




BLK:32,SNR1: 3.4221 ,SNR2: 11.669




3C147 2025/07/11 1.30UT TOYOKAWA-KISO




F202507111101634




BLK:31,SNR1: 0.31233 ,SNR2: 3.2564




K202507111101631





BLK:31,SNR1: 3.0884 ,SNR2: 11.049




3C147 2025/07/11 1.30UT FUJI -KISO





T20250711102445




BLK:15,SNR1: 139.13 ,SNR2: 135.80




F20250711102445



BLK:15,SNR1: 0.38564 ,SNR2: 4.1245





0548+16 2025/07/11 1.44UT TOYOKAWA-FUJI








T20250711102445




BLK:26,SNR1: 164.41 ,SNR2: 159.70




K20250711102442




BLK:26,SNR1: 106.96 ,SNR2: 121.99




0548+16 2025/07/11 1.44UT TOYOKAWA-KISO





F20250711102445




BLK:15,SNR1: 0.39371 ,SNR2: 3.7196




K20250711102442





BLK:15,SNR1: 109.72 ,SNR2: 125.86




0548+16 2025/07/11 1.44UT FUJI -KISO





T20250711102856




BLK: 9,SNR1: 0.78071 ,SNR2: 5.4126




F20250711102856





BLK: 9,SNR1: 0.26737 ,SNR2: 0.84581




0552+12 2025/07/11 1.51UT TOYOKAWA-FUJI





T202507111102856




BLK:14,SNR1: 5.1519 ,SNR2: 33.653




K202507111102853





BLK:14,SNR1: 0.22344 ,SNR2: 0.70520




0552+12 2025/07/11 1.51UT TOYOKAWA-KISO




F202507111102856




BLK: 9,SNR1: 0.74165E-01,SNR2: 1.6715




K202507111102853





BLK: 9,SNR1: 0.27459 ,SNR2: 2.9974




0552+12 2025/07/11 1.51UT FUJI -KISO



T202507111103323





BLK:16,SNR1: 98.905 ,SNR2: 132.08





0556+191 2025/07/11 1.58UT TOYOKAWA-FUJI



F202507111103323




BLK:16,SNR1: 11.509 ,SNR2: 23.107





T202507111103323




BLK:21,SNR1: 98.288 ,SNR2: 131.25




K202507111103320





BLK:21,SNR1: 97.199 ,SNR2: 104.39




0556+191 2025/07/11 1.58UT TOYOKAWA-KISO





F202507111103323




BLK:19,SNR1: 11.963 ,SNR2: 18.781




K202507111103320



BLK:19,SNR1: 97.650 ,SNR2: 104.88




0556+191 2025/07/11 1.58UT FUJI -KISO







T202507111104108




BLK: 2,SNR1: 0.24528 ,SNR2: 0.62093




F202507111104108




BLK: 2,SNR1: 0.11799 ,SNR2: 2.6056




0605-08 2025/07/11 1.71UT TOYOKAWA-FUJI




T202507111104108




BLK: 7,SNR1: 0.16805 ,SNR2: 0.56030




K202507111104105







BLK: 7,SNR1: 0.64375 ,SNR2: 3.0958








0605-08 2025/07/11 1.71UT TOYOKAWA-KISO










0605-08 2025/07/11 1.71UT FUJI -KISO






3C161 2025/07/11 2.03UT TOYOKAWA-FUJI







3C161 2025/07/11 2.03UT TOYOKAWA-KISO




F20250711110016




BLK:19,SNR1: 0.26731 ,SNR2: 2.1169




K20250711110013





BLK:19,SNR1: 1.5480 ,SNR2: 5.5869




3C161 2025/07/11 2.03UT FUJI -KISO





T202507111112749




BLK:12,SNR1: 1.4648 ,SNR2: 4.4850




F202507111112749




BLK:12,SNR1: 0.10859 ,SNR2: 1.4654




0652-130 2025/07/11 2.49UT TOYOKAWA-FUJI





T20250711112749




BLK:20,SNR1: 1.0903 ,SNR2: 3.3637




K20250711112746



BLK:20,SNR1: 3.3640 ,SNR2: 7.7053




0652-130 2025/07/11 2.49UT TOYOKAWA-KISO






F20250711112749




BLK:17,SNR1: 0.13625 ,SNR2: 1.5278





0652-130 2025/07/11 2.49UT FUJI -KISO



K20250711112746




BLK:17,SNR1: 1.8587 ,SNR2: 5.7216





T202507111113925




BLK:16,SNR1: 3.0713 ,SNR2: 9.4376




F202507111113925




BLK:16,SNR1: 8.6597 ,SNR2: 12.289





0703+138 2025/07/11 2.69UT TOYOKAWA-FUJI







BLK:23,SNR1: 3.0365 ,SNR2: 9.3255




BLK:23,SNR1: 9.1937 ,SNR2: 16.062





0703+138 2025/07/11 2.69UT TOYOKAWA-KISO







BLK:25,SNR1: 4.5637 ,SNR2: 12.419





BLK:25,SNR1: 9.1775 ,SNR2: 16.417




0703+138 2025/07/11 2.69UT FUJI -KISO





T202507111114848




BLK: 6,SNR1: 0.23755 ,SNR2: 1.4427




F202507111114848





BLK: 6,SNR1: 0.65571 ,SNR2: 2.1190




0713-024 2025/07/11 2.84UT TOYOKAWA-FUJI





T202507111114848




BLK:13,SNR1: 0.84321 ,SNR2: 3.4089




K202507111114845





BLK:13,SNR1: 0.60094 ,SNR2: 1.9187




0713-024 2025/07/11 2.84UT TOYOKAWA-KISO





F202507111114848




BLK: 6,SNR1: 0.16395 ,SNR2: 1.6746




K202507111114845








BLK: 6,SNR1: 0.73119 ,SNR2: 2.0738








0713-024 2025/07/11 2.84UT FUJI -KISO












F20250711115900




BLK:16,SNR1: 0.73757E-01,SNR2: 2.1562




K20250711115857




BLK:16,SNR1: 2.4692 ,SNR2: 3.9114





0723+10 2025/07/11 3.01UT FUJI -KISO







BLK:23,SNR1: 10.162 ,SNR2: 17.776







BLK:23,SNR1: 2.7873 ,SNR2: 8.7869




0732+33 2025/07/11 3.18UT TOYOKAWA-FUJI








0732+33 2025/07/11 3.18UT TOYOKAWA-KISO





F20250711120915




BLK:28,SNR1: 2.7868 ,SNR2: 8.7851




K20250711120912




BLK:28,SNR1: 7.8486 ,SNR2: 19.956




0732+33 2025/07/11 3.18UT FUJI -KISO




T20250711121716




BLK: 7,SNR1: 2.0520 ,SNR2: 7.2836




F20250711121716




BLK: 7,SNR1:-0.10284 ,SNR2: 1.0067




0741-06 2025/07/11 3.32UT TOYOKAWA-FUJI




T20250711121716




BLK:17,SNR1: 0.98641 ,SNR2: 2.6439




K20250711121713




BLK:17,SNR1: 16.109 ,SNR2: 76.059




0741-06 2025/07/11 3.32UT TOYOKAWA-KISO




F20250711121716




BLK:11,SNR1: 0.31977 ,SNR2: 2.0715




K20250711121713



BLK:11,SNR1: 47.251 ,SNR2: 76.828




0741-06 2025/07/11 3.32UT FUJI -KISO







T202507111122700




BLK:11,SNR1: 5.6421 ,SNR2: 11.891




F202507111122700





BLK:11,SNR1: 0.34471 ,SNR2: 1.7105




0752-200 2025/07/11 3.48UT TOYOKAWA-FUJI




T20250711122700




BLK:17,SNR1: 3.0093 ,SNR2: 8.6287




K20250711122657





BLK:17,SNR1: 3.0959 ,SNR2: 5.4157




0752-200 2025/07/11 3.48UT TOYOKAWA-KISO



F20250711122700





BLK: 7,SNR1: 0.39940 ,SNR2: 1.4814




Frequency (Hz)

K20250711122657





BLK: 7,SNR1: 2.3363 ,SNR2: 4.1772





Frequency (Hz)

0752-200 2025/07/11 3.48UT FUJI -KISO







BLK:22,SNR1: 17.307 ,SNR2: 20.101




BLK:22,SNR1: 4.2327 ,SNR2: 11.745





3C190 2025/07/11 3.60UT TOYOKAWA-FUJI







BLK:24,SNR1: 17.303 ,SNR2: 20.096








BLK:24,SNR1: 12.952 ,SNR2: 33.329




3C190 2025/07/11 3.60UT TOYOKAWA-KISO







T202507111124701




BLK:14,SNR1: 1.1922 ,SNR2: 6.5821




F202507111124701




BLK:14,SNR1: 0.17596 ,SNR2: 2.2366




3C196 2025/07/11 3.81UT TOYOKAWA-FUJI




T202507111124701




BLK:20,SNR1: 0.93362 ,SNR2: 5.3456




K202507111124658



BLK:20,SNR1: 0.14393 ,SNR2: 1.3247




3C196 2025/07/11 3.81UT TOYOKAWA-KISO







F20250711124701




BLK: 8,SNR1: 0.81007 ,SNR2: 3.8816




K20250711124658





BLK: 8,SNR1: 0.10642 ,SNR2: 1.2204




3C196 2025/07/11 3.81UT FUJI -KISO




T20250711125811




BLK:14,SNR1: 0.55773 ,SNR2: 3.8419




F20250711125811




BLK:14,SNR1: 0.20445 ,SNR2: 4.2507





0821+394 2025/07/11 4.00UT TOYOKAWA-FUJI







BLK:20,SNR1: 0.60441 ,SNR2: 3.7600




BLK:20,SNR1: 1.9637 ,SNR2: 4.8952




0821+394 2025/07/11 4.00UT TOYOKAWA-KISO




F20250711125811




BLK:13,SNR1: 0.13825 ,SNR2: 1.5537




K20250711125809








BLK:13,SNR1: 2.4829 ,SNR2: 6.1719




0821+394 2025/07/11 4.00UT FUJI -KISO








T20250711130950




BLK:18,SNR1: 5.2111 ,SNR2: 9.3679




K20250711130947




BLK:18,SNR1: 7.8583 ,SNR2: 20.372





0834-19 2025/07/11 4.19UT TOYOKAWA-KISO







BLK:21,SNR1: 15.252 ,SNR2: 17.513







BLK:21,SNR1: 7.8061 ,SNR2: 19.996




0834-19 2025/07/11 4.19UT FUJI -KISO






0839-071 2025/07/11 4.28UT TOYOKAWA-FUJI









T20250711131455




K20250711131452





0839-071 2025/07/11 4.28UT TOYOKAWA-KISO







BLK: 4,SNR1: 8.8562 ,SNR2: 17.287




BLK: 4,SNR1: 9.4249 ,SNR2: 23.325





0839-071 2025/07/11 4.28UT FUJI -KISO







BLK: 5,SNR1: 1.7927 ,SNR2: 6.2411




BLK: 5,SNR1: 5.8059 ,SNR2: 20.034





3C208 2025/07/11 4.46UT TOYOKAWA-FUJI







BLK:10,SNR1: 8.9924 ,SNR2: 30.083




BLK:10,SNR1: 8.9625 ,SNR2: 29.042





3C208 2025/07/11 4.46UT TOYOKAWA-KISO







BLK: 6, SNR1: 5.8922 , SNR2: 20.324





BLK: 6, SNR1: 7.4932 , SNR2: 25.191




3C208 2025/07/11 4.46UT FUJI -KISO




T20250711134238




BLK: 6,SNR1: 0.11191 ,SNR2: 0.59273




F20250711134239





BLK: 6,SNR1: 0.33609 ,SNR2: 1.9317




3C216 2025/07/11 4.74UT TOYOKAWA-FUJI





T20250711134238




BLK:14,SNR1: 0.21976E-01,SNR2: 1.1020




K20250711134235




BLK:14,SNR1: 0.53007 ,SNR2: 1.7058




3C216 2025/07/11 4.74UT TOYOKAWA-KISO





F20250711134239




BLK:12,SNR1: 0.39659 ,SNR2: 1.2352




K20250711134235




BLK:12,SNR1: 0.61724 ,SNR2: 1.9298





3C216 2025/07/11 4.74UT FUJI -KISO









BLK: 5,SNR1: 0.32484 ,SNR2: 3.1125




BLK: 5,SNR1: -0.11791 ,SNR2: 0.97157





0919-142 2025/07/11 4.94UT TOYOKAWA-FUJI







BLK: 8,SNR1: 0.31917 ,SNR2: 2.4905




BLK: 8,SNR1: 0.60288 ,SNR2: 1.8098




0919-142 2025/07/11 4.94UT TOYOKAWA-KISO





F20250711135449




BLK: 4,SNR1: 0.51037E-02,SNR2: 0.88224




K20250711135446





BLK: 4,SNR1: 0.58925,SNR2: 5.9716




0919-142 2025/07/11 4.94UT FUJI -KISO




T20250711140128




BLK:10,SNR1: 10.602 ,SNR2: 25.857




F20250711140128




BLK:10,SNR1: 7.6158 ,SNR2: 19.857





0926+117 2025/07/11 5.05UT TOYOKAWA-FUJI







BLK:10,SNR1: 10.626 ,SNR2: 25.913




BLK:10,SNR1: 10.600 ,SNR2: 26.918




0926+117 2025/07/11 5.05UT TOYOKAWA-KISO




F20250711140128




BLK:13,SNR1: 7.5021 ,SNR2: 20.509




K20250711140125




BLK:13,SNR1: 9.0444 ,SNR2: 22.518





0926+117 2025/07/11 5.05UT FUJI -KISO







BLK: 6,SNR1: 0.84317 ,SNR2: 1.9477




BLK: 6,SNR1:-0.14116 ,SNR2: 1.2755





3C222 2025/07/11 5.18UT TOYOKAWA-FUJI







BLK: 8,SNR1: 0.49307 ,SNR2: 1.5959




BLK: 8,SNR1: 4.2973 ,SNR2: 12.852





3C222 2025/07/11 5.18UT TOYOKAWA-KISO









BLK: 4,SNR1:-0.42715E-01,SNR2: 2.1555





BLK: 4,SNR1: 8.9337 ,SNR2: 21.175




3C222 2025/07/11 5.18UT FUJI -KISO




T20250711141613




BLK: 7,SNR1: 0.47729 ,SNR2: 2.5466




F20250711141613




BLK: 7,SNR1: 0.12798 ,SNR2: 1.8781





0941-08 2025/07/11 5.30UT TOYOKAWA-FUJI







BLK: 6,SNR1: 1.3484 ,SNR2: 2.6259




BLK: 6,SNR1: 1.7858 ,SNR2: 5.2863




0941-08 2025/07/11 5.30UT TOYOKAWA-KISO





F20250711141613




BLK: 8,SNR1: 0.29484 ,SNR2: 1.7146




K20250711141610




BLK: 8,SNR1: 1.8512 ,SNR2: 4.8979





0941-08 2025/07/11 5.30UT FUJI -KISO







BLK:10,SNR1: 11.156 ,SNR2: 35.874





BLK:10,SNR1: 5.8940 ,SNR2: 16.479




3C230 2025/07/11 5.44UT TOYOKAWA-FUJI





T20250711142435




BLK: 8,SNR1: 7.1555 ,SNR2: 19.494




K20250711142432





BLK: 8,SNR1: 10.412 ,SNR2: 26.521




3C230 2025/07/11 5.44UT TOYOKAWA-KISO





F20250711142435




BLK: 6,SNR1: 9.3780 ,SNR2: 24.008




K20250711142432





BLK: 6,SNR1: 8.0605 ,SNR2: 20.938




3C230 2025/07/11 5.44UT FUJI -KISO





T20250711144035




BLK:16,SNR1: 0.63700 ,SNR2: 2.5507




F20250711144035



BLK:16,SNR1: 2.3787 ,SNR2: 7.6422





3C237 2025/07/11 5.70UT TOYOKAWA-FUJI








T20250711144035




BLK:27,SNR1: 1.2623 ,SNR2: 3.6160




K20250711144032





BLK:27,SNR1: 9.5939 ,SNR2: 24.673




3C237 2025/07/11 5.70UT TOYOKAWA-KISO





F20250711144035




BLK:18,SNR1: 2.3956 ,SNR2: 7.6727




K20250711144032




BLK:18,SNR1: 4.1023 ,SNR2: 5.4115





3C237 2025/07/11 5.70UT FUJI -KISO







BLK: 6,SNR1: 1.0374 ,SNR2: 2.9963




BLK: 6,SNR1: 7.8663 ,SNR2: 23.458





1011+110 2025/07/11 5.81UT TOYOKAWA-FUJI







BLK: 9,SNR1: 2.2353 ,SNR2: 5.4353




BLK: 9,SNR1: 3.2244 ,SNR2: 10.262





1011+110 2025/07/11 5.81UT TOYOKAWA-KISO







BLK:13,SNR1: 6.4229 ,SNR2: 17.478





BLK:13,SNR1: 4.1037 ,SNR2: 10.097




1011+110 2025/07/11 5.81UT FUJI -KISO




T20250711145433




BLK: 5,SNR1: 1.3394 ,SNR2: 4.1301




F20250711145433





BLK: 5,SNR1: 2.7424 ,SNR2: 5.0797




3C241 2025/07/11 5.94UT TOYOKAWA-FUJI





T20250711145433




BLK:10,SNR1: 1.4215 ,SNR2: 3.7534




K20250711145430




BLK:10,SNR1: 3.7770 ,SNR2: 9.5595




3C241 2025/07/11 5.94UT TOYOKAWA-KISO




F20250711145433




BLK:10,SNR1: 1.7661 ,SNR2: 4.5215




K20250711145430



BLK:10,SNR1: 6.0672 ,SNR2: 17.746





3C241 2025/07/11 5.94UT FUJI -KISO








T20250711150602




BLK:14,SNR1: 7.3671 ,SNR2: 16.343




F20250711150602




BLK:14,SNR1: 9.3200 ,SNR2: 28.258





1031-11 2025/07/11 6.13UT TOYOKAWA-FUJI







BLK:13,SNR1: 6.6111 ,SNR2: 14.722




BLK:13,SNR1: 6.5481 ,SNR2: 17.765





1031-11 2025/07/11 6.13UT TOYOKAWA-KISO







BLK:15,SNR1: 9.3075 ,SNR2: 28.219





BLK:15,SNR1: 7.2340 ,SNR2: 18.987




1031-11 2025/07/11 6.13UT FUJI -KISO



T20250711151035




BLK: 5,SNR1: 6.1033 ,SNR2: 11.813




Frequency (Hz)

F20250711151035




BLK: 5,SNR1: 5.7128 ,SNR2: 16.487




Frequency (Hz)


1035-058 2025/07/11 6.20UT TOYOKAWA-FUJI




T20250711151035




BLK:10,SNR1: 7.7540 ,SNR2: 19.869




K20250711151032




BLK:10,SNR1: 8.1074 ,SNR2: 19.343




1035-058 2025/07/11 6.20UT TOYOKAWA-KISO



F20250711151035




BLK: 5,SNR1: 2.9646 ,SNR2: 8.7855




Frequency (Hz)

K20250711151032





BLK: 5,SNR1: 10.960 ,SNR2: 26.086





Frequency (Hz)

1035-058 2025/07/11 6.20UT FUJI -KISO







BLK: 3,SNR1: 8.2527 ,SNR2: 23.292




BLK: 3,SNR1: 5.1866 ,SNR2: 14.829





1044-008 2025/07/11 6.36UT TOYOKAWA-FUJI







BLK: 4,SNR1: 28.895 ,SNR2: 70.955




BLK: 4,SNR1: 11.480 ,SNR2: 28.373





1044-008 2025/07/11 6.36UT TOYOKAWA-KISO









BLK: 2,SNR1: 3.3232 ,SNR2: 10.500





BLK: 2,SNR1: 12.572 ,SNR2: 30.991





1044-008 2025/07/11 6.36UT FUJI -KISO




T20250711153052




F20250711153052




1055+01 2025/07/11 6.54UT TOYOKAWA-FUJI




T20250711153052




BLK: 9, SNR1: 10.708 , SNR2: 26.347




K20250711153049





BLK: 9, SNR1: 6.2121 , SNR2: 16.556




1055+01 2025/07/11 6.54UT TOYOKAWA-KISO



F20250711153052





BLK: 4,SNR1: 8.0514 ,SNR2: 22.623




Frequency (Hz)

K20250711153049







BLK: 4,SNR1: 8.8858 ,SNR2: 22.545









Frequency (Hz)

1055+01 2025/07/11 6.54UT FUJI -KISO













BLK: 2,SNR1: 2.2537 ,SNR2: 10.805




BLK: 2,SNR1: 19.667 ,SNR2: 36.288





1107+109 2025/07/11 6.73UT FUJI -KISO








BLK: 6,SNR1: 4.6987 ,SNR2: 11.536





BLK: 6,SNR1: 0.84329 ,SNR2: 2.7872









BLK:13,SNR1: 11.001 ,SNR2: 27.768












BLK:13,SNR1: 4.1786 ,SNR2: 8.3105




3C255 2025/07/11 6.89UT TOYOKAWA-KISO










1127-14 2025/07/11 7.07UT TOYOKAWA-FUJI







BLK:12,SNR1: 5.8467 ,SNR2: 13.078




BLK:12,SNR1: 14.253 ,SNR2: 15.173





1127-14 2025/07/11 7.07UT TOYOKAWA-KISO







BLK: 9,SNR1: 2.4933 ,SNR2: 7.4342




BLK: 9,SNR1: 6.2720 ,SNR2: 15.687





1127-14 2025/07/11 7.07UT FUJI -KISO







BLK: 2,SNR1: 0.34641 ,SNR2: 0.71731




BLK: 2,SNR1:-0.92498E-01,SNR2: 0.49013





3C263.1 2025/07/11 7.29UT TOYOKAWA-FUJI







BLK: 6,SNR1: 0.63476E-01,SNR2: 1.3550




BLK: 6,SNR1: 1.2988 ,SNR2: 6.3052





3C263.1 2025/07/11 7.29UT TOYOKAWA-KISO







BLK: 2,SNR1:-0.10179 ,SNR2: 0.68078



BLK: 2,SNR1: 0.52957 ,SNR2: 2.6179





3C263.1 2025/07/11 7.29UT FUJI -KISO








T20250711162212




BLK: 3,SNR1: 0.14397 ,SNR2: 0.54967




F20250711162212





BLK: 3,SNR1: 0.71472E-01,SNR2: 3.2566




3C267 2025/07/11 7.40UT TOYOKAWA-FUJI



T20250711162212





BLK:10,SNR1: 0.27025 ,SNR2: 1.0381




Frequency (Hz)

K20250711162209




BLK:10,SNR1: 1.8890 ,SNR2: 3.5015





Frequency (Hz)


3C267 2025/07/11 7.40UT TOYOKAWA-KISO





F20250711162212




BLK: 7,SNR1:-0.79558E-01,SNR2: 0.38475




K20250711162209





BLK: 7,SNR1: 0.81601 ,SNR2: 2.0601




3C267 2025/07/11 7.40UT FUJI -KISO



T20250711164126





BLK: 8, SNR1: 7.2493 , SNR2: 18.575




Frequency (Hz)

F20250711164126




BLK: 8, SNR1: 10.947 , SNR2: 25.835





Frequency (Hz)


1206+439 2025/07/11 7.72UT TOYOKAWA-FUJI



T20250711164126





BLK:10,SNR1: 6.7025 ,SNR2: 19.417




Frequency (Hz)

K20250711164124




BLK:10,SNR1: 4.0888 ,SNR2: 10.315





Frequency (Hz)



1206+439 2025/07/11 7.72UT TOYOKAWA-KISO




F20250711164126




K20250711164124




1206+439 2025/07/11 7.72UT FUJI -KISO



T20250711170117




BLK: 9,SNR1: 9.9725 ,SNR2: 17.567




Frequency (Hz)

F20250711170117




BLK: 9,SNR1: 5.3379 ,SNR2: 16.259





Frequency (Hz)


3C273 2025/07/11 8.05UT TOYOKAWA-FUJI



T20250711170117





BLK:14,SNR1: 8.9381 ,SNR2: 15.769




Frequency (Hz)

K20250711170114




BLK:14,SNR1: 10.009 ,SNR2: 23.301




Frequency (Hz)

3C273 2025/07/11 8.05UT TOYOKAWA-KISO






F20250711170117




BLK:11,SNR1: 6.2011 ,SNR2: 16.358




Frequency (Hz)

K20250711170114




BLK:11,SNR1: 9.6481 ,SNR2: 22.531





Frequency (Hz)


3C273 2025/07/11 8.05UT FUJI -KISO



T20250711174804





BLK: 6,SNR1: 7.5922 ,SNR2: 19.066




Frequency (Hz)

F20250711174804









BLK: 6,SNR1: 6.5192 ,SNR2: 16.673




Frequency (Hz)

1313+453 2025/07/11 8.83UT TOYOKAWA-FUJI






F20250711174804





BLK: 8, SNR1: 6.2397 , SNR2: 16.136




Frequency (Hz)

K20250711174801




BLK: 8, SNR1: -0.34847 , SNR2: 0.51008





Frequency (Hz)


1313+453 2025/07/11 8.83UT FUJI -KISO



T20250711180923





BLK:10,SNR1: 2.0397 ,SNR2: 4.4995




Frequency (Hz)

F20250711180923









BLK:10,SNR1: 2.5086 ,SNR2: 6.6922





Frequency (Hz)

1335+479 2025/07/11 9.18UT TOYOKAWA-FUJI






F20250711180923





BLK:11,SNR1: 1.9550 ,SNR2: 5.8291




Frequency (Hz)

K20250711180920




BLK:11,SNR1:-0.71413E-01,SNR2: 1.5011




Frequency (Hz)


1335+479 2025/07/11 9.18UT FUJI -KISO



T20250711181329





BLK: 4, SNR1: 0.49635 , SNR2: 1.7166




Frequency (Hz)

F20250711181329



BLK: 4, SNR1: 2.3814 , SNR2: 5.2737



Frequency (Hz)

1339+472 2025/07/11 9.25UT TOYOKAWA-FUJI

