








BLK:11,SNR1: 12.898 ,SNR2: 30.315





BLK:11,SNR1: 17.376 ,SNR2: 40.314




0120+405 2025/07/13 20.79UT TOYOKAWA-FUJI





T20250714054549




BLK:15,SNR1: 12.880 ,SNR2: 30.273




K20250714054546





BLK:15,SNR1: 10.095 ,SNR2: 25.223




0120+405 2025/07/13 20.79UT TOYOKAWA-KISO





F20250714054549




BLK:12,SNR1: 18.940 ,SNR2: 43.394




K20250714054546








BLK:12,SNR1: 10.073 ,SNR2: 24.106





0120+405 2025/07/13 20.79UT FUJI -KISO








T20250714060001




BLK:12,SNR1: 0.49919 ,SNR2: 1.7930





3C48 2025/07/13 21.03UT TOYOKAWA-KISO


K20250714055958




BLK:12,SNR1: 0.21321 ,SNR2: 1.5324




F20250714060001




BLK:12,SNR1: 0.64367 ,SNR2: 2.0500




K20250714055958








BLK:12,SNR1: 0.58972 ,SNR2: 1.8884






3C48 2025/07/13 21.03UT FUJI -KISO









BLK:18,SNR1: 1.3043 ,SNR2: 3.5558




BLK:18,SNR1: 8.4935 ,SNR2: 14.823




0148+274 2025/07/13 21.26UT TOYOKAWA-KISO





F20250714061345




BLK:11,SNR1: 2.5055 ,SNR2: 6.4414




K20250714061341





BLK:11,SNR1: 9.6183 ,SNR2: 16.743




0148+274 2025/07/13 21.26UT FUJI -KISO




T20250714062652




BLK: 6,SNR1: 8.5729 ,SNR2: 21.404




F20250714062652




BLK: 6,SNR1: 7.1833 ,SNR2: 18.324





0202+15 2025/07/13 21.48UT TOYOKAWA-FUJI







BLK: 8,SNR1: 4.1795 ,SNR2: 11.507







BLK: 8,SNR1: 6.9205 ,SNR2: 19.626




0202+15 2025/07/13 21.48UT TOYOKAWA-KISO






0202+15 2025/07/13 21.48UT FUJI -KISO








T20250714063843




BLK: 4, SNR1: 2.7647 , SNR2: 6.0523




F20250714063843




BLK: 4, SNR1: 3.0436 , SNR2: 8.5384




0213+178 2025/07/13 21.67UT TOYOKAWA-FUJI





T20250714063843




BLK: 6, SNR1: 2.3717 , SNR2: 6.5562




K20250714063840





BLK: 6, SNR1: 10.735 , SNR2: 26.392




0213+178 2025/07/13 21.67UT TOYOKAWA-KISO





F20250714063843




BLK: 4, SNR1: 2.6551 ,SNR2: 7.6675




K20250714063840




BLK: 4, SNR1: 11.202 ,SNR2: 31.945




0213+178 2025/07/13 21.67UT FUJI -KISO



T20250714064625





BLK:17,SNR1: 116.17 ,SNR2: 351.85





3C67

2025/07/13 21.80UT TOYOKAWA-FUJI



F20250714064625




BLK:17,SNR1: 98.802 ,SNR2: 198.60



T20250714064625





BLK:18,SNR1: 108.06 ,SNR2: 277.66





3C67 2025/07/13 21.80UT TOYOKAWA-KISO



K20250714064622




BLK:18,SNR1: 189.12 ,SNR2: 255.94



F20250714064625




BLK:23,SNR1: 69.689 ,SNR2: 147.44





3C67 2025/07/13 21.80UT FUJI -KISO



K20250714064622




BLK:23,SNR1: 121.90 ,SNR2: 213.42




T20250714070440




BLK: 3,SNR1: 0.85788E-01,SNR2: 0.18975




F20250714070440





BLK: 3,SNR1: 6.9489 ,SNR2: 19.093




3C71 2025/07/13 22.11UT TOYOKAWA-FUJI





T20250714070440




BLK: 3,SNR1:-0.42889E-02,SNR2: 0.30173




K20250714070437



BLK: 3,SNR1: 17.297 ,SNR2: 31.260




3C71 2025/07/13 22.11UT TOYOKAWA-KISO








F20250714070440




BLK: 2,SNR1: 0.78214 ,SNR2: 2.7145




K20250714070437




BLK: 2,SNR1: 19.731 ,SNR2: 35.671




3C71 2025/07/13 22.11UT FUJI -KISO




T20250714072355




BLK: 4,SNR1: 0.98116E-01,SNR2: 0.32448




F20250714072355





BLK: 4,SNR1: 1.5298 ,SNR2: 4.8992




0258+350 2025/07/13 22.43UT TOYOKAWA-FUJI





T20250714072355




BLK: 6, SNR1: 0.18961 , SNR2: 1.6938




K20250714072352




BLK: 6, SNR1: 2.9539 , SNR2: 7.4131




0258+350 2025/07/13 22.43UT TOYOKAWA-KISO





F20250714072355




BLK: 9,SNR1: 0.87721 ,SNR2: 2.9081




K20250714072352




BLK: 9,SNR1: 2.8393 ,SNR2: 7.1395





0258+350 2025/07/13 22.43UT FUJI -KISO







BLK: 1,SNR1: 0.53764E-01,SNR2: 0.85536





BLK: 1,SNR1: 1.0321 ,SNR2: 3.1500




0308+305 2025/07/13 22.59UT TOYOKAWA-FUJI





T20250714073345




BLK: 6,SNR1: 0.22258 ,SNR2: 0.98043




K20250714073342




BLK: 6,SNR1: 2.1528 ,SNR2: 6.9876




0308+305 2025/07/13 22.59UT TOYOKAWA-KISO




F20250714073346




BLK:13,SNR1: 0.51950 ,SNR2: 1.1911




K20250714073342





BLK:13,SNR1: 1.3035 ,SNR2: 3.7511




0308+305 2025/07/13 22.59UT FUJI -KISO



T20250714074516




BLK: 7,SNR1: 0.28112 ,SNR2: 3.1845





0320+05 2025/07/13 22.78UT TOYOKAWA-FUJI

F20250714074517





BLK: 7,SNR1: 0.93140E-01,SNR2: 1.6911







T20250714074516




BLK: 9,SNR1: 0.12256 ,SNR2: 3.1983




K20250714074513




BLK: 9,SNR1: 0.94940 ,SNR2: 2.9690




0320+05 2025/07/13 22.78UT TOYOKAWA-KISO




F20250714074517




BLK: 7,SNR1: 0.24389E-01,SNR2: 1.4960




K20250714074513




BLK: 7,SNR1: 1.7440 ,SNR2: 3.0851




0320+05 2025/07/13 22.78UT FUJI -KISO




T20250714075838




BLK: 5, SNR1: 0.25467 , SNR2: 0.54205




F20250714075838





BLK: 5, SNR1: 0.94537 , SNR2: 5.0392




0333+32 2025/07/13 23.01UT TOYOKAWA-FUJI





T20250714075838




BLK: 1,SNR1: 0.54660E-01,SNR2: 0.55299




K20250714075835




BLK: 1,SNR1: 6.0633 ,SNR2: 17.611




0333+32 2025/07/13 23.01UT TOYOKAWA-KISO





F20250714075838




BLK: 4, SNR1: 1.0704 , SNR2: 5.1069




K20250714075835





BLK: 4, SNR1: 4.0774 , SNR2: 12.218




0333+32 2025/07/13 23.01UT FWJ -KISO





T20250714081139




BLK: 1,SNR1: 0.92555E-02,SNR2: 0.80833




F20250714081140





BLK: 1,SNR1:-0.18030 ,SNR2: 0.84289




0347+05 2025/07/13 23.22UT TOYOKAWA-FUJI



T20250714081139





BLK: 5,SNR1: 0.87189E-01,SNR2: 0.29293





0347+05 2025/07/13 23.22UT TOYOKAWA-KISO


K20250714081136




BLK: 5,SNR1: 6.4186 ,SNR2: 17.390




F20250714081140




BLK: 6,SNR1: 0.64298 ,SNR2: 2.3789




K20250714081136






BLK: 6,SNR1: 1.1491 ,SNR2: 3.3942




0347+05 2025/07/13 23.22UT FUJI -KISO








T20250714082713





BLK: 3,SNR1: 0.68384E-01,SNR2: 1.1031





0403-132 2025/07/13 23.48UT TOYOKAWA-KISO


K20250714082710




BLK: 3,SNR1: 0.46791 ,SNR2: 3.5931




F20250714082713




BLK: 4,SNR1: 0.26436 ,SNR2: 1.5807




K20250714082710





BLK: 4,SNR1:-0.24543E-01,SNR2: 0.27956




0403-132 2025/07/13 23.48UT FUJI -KISO




T20250714083624




BLK: 9,SNR1: 0.39036 ,SNR2: 2.3226




F20250714083624





BLK: 9,SNR1: 0.74067 ,SNR2: 4.0523




0411+05 2025/07/13 23.63UT TOYOKAWA-FUJI




T20250714083624




BLK:11,SNR1: 0.34883 ,SNR2: 2.4589




K20250714083622




BLK:11,SNR1: 2.7658 ,SNR2: 9.4290




0411+05 2025/07/13 23.63UT TOYOKAWA-KISO




F20250714083624




BLK:11,SNR1: 0.34953 ,SNR2: 3.3702




K20250714083622





BLK:11,SNR1: 2.0537 ,SNR2: 5.9215




0411+05 2025/07/13 23.63UT FUJI -KISO




T20250714084318




BLK: 5, SNR1: 0.61491 , SNR2: 2.7373




F20250714084318




BLK: 5, SNR1: 4.6625 , SNR2: 13.316





0418+236 2025/07/13 23.75UT TOYOKAWA-FUJI







BLK: 8,SNR1: 0.78997E-01,SNR2: 0.85906



BLK: 8,SNR1: 2.0431 ,SNR2: 5.6858




0418+236 2025/07/13 23.75UT TOYOKAWA-KISO






F20250714084318




BLK: 7, SNR1: 0.10699 , SNR2: 1.9172




Frequency (Hz)

K20250714084315




BLK: 7, SNR1: 4.9694 , SNR2: 12.028





Frequency (Hz)


0418+236 2025/07/13 23.75UT FUJI -KISO




T20250714085257




BLK: 8,SNR1: 0.20528 ,SNR2: 1.0685




F20250714085258





BLK: 8,SNR1: 0.56903 ,SNR2: 4.1516




0428+20 2025/07/13 23.91UT TOYOKAWA-FUJI





T20250714085257




BLK:11,SNR1: 0.17998 ,SNR2: 1.1933




K20250714085254




BLK:11,SNR1: 7.0302 ,SNR2: 15.271




0428+20 2025/07/13 23.91UT TOYOKAWA-KISO





F20250714085258




BLK:14,SNR1: 0.42878 ,SNR2: 3.3583




K20250714085254





BLK:14,SNR1: 6.6361 ,SNR2: 11.459




0428+20 2025/07/13 23.91UT FUJI -KISO





T20250714094253




BLK:28,SNR1: 17.721 ,SNR2: 20.407




F20250714094253









BLK:28,SNR1: 1.4664 ,SNR2: 4.4035




3C138 2025/07/14 0.74UT TOYOKAWA-FUJI









T20250714095626




BLK:22,SNR1: 1.1047 ,SNR2: 5.5549




F20250714095626






BLK:22,SNR1: 0.22981 ,SNR2: 2.3253






0531+194 2025/07/14 0.97UT TOYOKAWA-FUJI














T20250714100447




BLK:21,SNR1: 249.12 ,SNR2: 274.82




F20250714100447









BLK:21,SNR1: 6.3029 ,SNR2: 20.444











3C147 2025/07/14 1.11UT TOYOKAWA-FUJI

















0548+16 2025/07/14 1.24UT FUJI -KISO







T20250714101708




BLK: 8,SNR1: 5.4269 ,SNR2: 54.961




F20250714101708





BLK: 8,SNR1: 1.9946 ,SNR2: 6.0650







0552+12 2025/07/14 1.31UT TOYOKAWA-FUJI







0552+12 2025/07/14 1.31UT TOYOKAWA-KISO








T20250714102135




BLK:13,SNR1: 4.5615 ,SNR2: 4.4214




F20250714102135





BLK:13,SNR1: 0.67826 ,SNR2: 3.9798







0556+191 2025/07/14 1.39UT TOYOKAWA-FUJI






0556+191 2025/07/14 1.39UT TOYOKAWA-KISO








T20250714102920




BLK: 7, SNR1: 0.36647 , SNR2: 1.4971




F20250714102920





BLK: 7, SNR1: 0.27947 , SNR2: 3.9474




0605-08 2025/07/14 1.52UT TOYOKAWA-FUJI









0605-08 2025/07/14 1.52UT TOYOKAWA-KISO









T20250714104828




BLK:22,SNR1: 3.4006 ,SNR2: 10.217




F20250714104828









BLK:22,SNR1: 6.4118 ,SNR2: 16.687










3C161 2025/07/14 1.84UT TOYOKAWA-FUJI
















0652-130 2025/07/14 2.30UT TOYOKAWA-KISO







T20250714112738




BLK: 4,SNR1:-0.11553 ,SNR2: 2.1167




F20250714112738





BLK: 4,SNR1: 0.12242 ,SNR2: 1.6388




0703+138 2025/07/14 2.49UT TOYOKAWA-FUJI










0703+138 2025/07/14 2.49UT TOYOKAWA-KISO







0703+138 2025/07/14 2.49UT FUJI -KISO




T20250714113700




BLK:14,SNR1: 2.0552 ,SNR2: 8.1577




F20250714113700





BLK:14,SNR1: 0.30717 ,SNR2: 2.8565






0713-024 2025/07/14 2.64UT TOYOKAWA-FUJI






0713-024 2025/07/14 2.64UT TOYOKAWA-KISO







0713-024 2025/07/14 2.64UT FUJI -KISO




T20250714114712




BLK:29,SNR1: 66.068 ,SNR2: 113.70




F20250714114712









BLK:29,SNR1: 3.6241 ,SNR2: 9.8440



0723+10 2025/07/14 2.81UT TOYOKAWA-FUJI












T20250714115727




BLK:14,SNR1: 4.9808 ,SNR2: 12.680




F20250714115727









BLK:14,SNR1: 4.3754 ,SNR2: 10.715











0732+33 2025/07/14 2.99UT TOYOKAWA-FUJI





















T20250714121513




BLK:10,SNR1: 0.31119 ,SNR2: 1.1223




F20250714121513






BLK:10,SNR1: 5.8284 ,SNR2: 14.654






0752-200 2025/07/14 3.28UT TOYOKAWA-FUJI












T20250714122248




BLK:18,SNR1: 1.2817 ,SNR2: 4.9137




F20250714122248









BLK:18,SNR1: 0.11921 ,SNR2: 1.7900





3C190 2025/07/14 3.41UT TOYOKAWA-FUJI










T20250714123513




BLK:16,SNR1: 0.51783 ,SNR2: 4.4226




F20250714123513









BLK:16,SNR1: 1.2784 ,SNR2: 8.2918




3C196 2025/07/14 3.62UT TOYOKAWA-FUJI










T20250714124623




BLK:19,SNR1: 0.35316 ,SNR2: 2.6352




F20250714124623





BLK:19,SNR1: 5.9342 ,SNR2: 10.432




0821+394 2025/07/14 3.80UT TOYOKAWA-FUJI











0821+394 2025/07/14 3.80UT TOYOKAWA-KISO








T20250714125802




BLK:12,SNR1: 1.0678 ,SNR2: 3.1363




F20250714125802









BLK:12,SNR1: 0.41800 ,SNR2: 1.6897





0834-19 2025/07/14 4.00UT TOYOKAWA-FUJI










T20250714130307




BLK:11,SNR1: 10.586 ,SNR2: 26.931




F20250714130307





BLK:11,SNR1: 13.686 ,SNR2: 33.169






0839-071 2025/07/14 4.08UT TOYOKAWA-FUJI






0839-071 2025/07/14 4.08UT TOYOKAWA-KISO








0839-071 2025/07/14 4.08UT FUJI -KISO









BLK:10,SNR1: 11.192 ,SNR2: 27.262









BLK:10,SNR1: 22.779 ,SNR2: 37.172





3C208 2025/07/14 4.26UT TOYOKAWA-FUJI








T20250714133051





BLK:12,SNR1: 0.20896 ,SNR2: 2.1052




Frequency (Hz)

F20250714133051







BLK:12,SNR1: 0.18737 ,SNR2: 3.2365






Frequency (Hz)


3C216 2025/07/14 4.54UT TOYOKAWA-FUJI









T20250714134301




BLK: 5,SNR1: 0.48473 ,SNR2: 2.3682




F20250714134301





BLK: 5,SNR1: 0.22456E-02,SNR2: 1.5929




0919-142 2025/07/14 4.75UT TOYOKAWA-FUJI









0919-142 2025/07/14 4.75UT TOYOKAWA-KISO













BLK: 2,SNR1: 3.2336 ,SNR2: 8.2071





BLK: 2,SNR1: 7.9699 ,SNR2: 22.480







0926+117 2025/07/14 4.86UT TOYOKAWA-FUJI






0926+117 2025/07/14 4.86UT TOYOKAWA-KISO









T20250714135725









F20250714135725




3C222 2025/07/14 4.99UT TOYOKAWA-FUJI













BLK:11,SNR1: 1.6385 ,SNR2: 5.9485





BLK:11,SNR1: 1.3614 ,SNR2: 6.8337




0941-08 2025/07/14 5.10UT TOYOKAWA-FUJI













0941-08 2025/07/14 5.10UT TOYOKAWA-KISO









BLK: 6, SNR1: 7.8991, SNR2: 24.250









BLK: 6, SNR1: 12.859, SNR2: 30.420





3C230 2025/07/14 5.24UT TOYOKAWA-FUJI









T20250714142847




BLK:14,SNR1: 0.27674 ,SNR2: 1.0668




F20250714142847









BLK:14,SNR1: 0.55728 ,SNR2: 4.3526



3C237 2025/07/14 5.51UT TOYOKAWA-FUJI













T20250714143504




BLK: 6,SNR1: 2.1433 ,SNR2: 5.9642




F20250714143504









BLK: 6,SNR1: 5.9981 ,SNR2: 15.445











1011+110 2025/07/14 5.61UT TOYOKAWA-FUJI




















T20250714145414




BLK: 4,SNR1: 0.15912 ,SNR2: 2.5395




F20250714145414






BLK: 4,SNR1:-0.16681 ,SNR2: 2.8749







1031-11 2025/07/14 5.93UT TOYOKAWA-FUJI















BLK:13,SNR1: 3.4679 ,SNR2: 9.2622









BLK:13,SNR1: 1.5016 ,SNR2: 5.2594





1035-058 2025/07/14 6.01UT TOYOKAWA-FUJI









T20250714150800




BLK: 6,SNR1: 12.226 ,SNR2: 27.263




F20250714150800









BLK: 6,SNR1: 7.9330 ,SNR2: 19.855




1044-008 2025/07/14 6.16UT TOYOKAWA-FUJI













BLK: 6,SNR1: 6.4813 ,SNR2: 18.362






BLK: 6,SNR1: 7.4878 ,SNR2: 20.376







1055+01 2025/07/14 6.35UT TOYOKAWA-FUJI















BLK: 3,SNR1: 6.2135 ,SNR2: 17.118





BLK: 3,SNR1: 9.4039 ,SNR2: 26.129







1107+109 2025/07/14 6.53UT TOYOKAWA-FUJI
















1107+109 2025/07/14 6.53UT TOYOKAWA-KISO




















BLK: 2,SNR1: 3.7742 ,SNR2: 7.4531





BLK: 2,SNR1: 0.93989 ,SNR2: 2.3316







1127-14 2025/07/14 6.87UT TOYOKAWA-FUJI










1127-14 2025/07/14 6.87UT TOYOKAWA-KISO














3C263.1 2025/07/14 7.09UT TOYOKAWA-FUJI













BLK: 5,SNR1: 0.48622 ,SNR2: 3.1258






BLK: 5,SNR1: 0.35176 ,SNR2: 3.8500










3C267 2025/07/14 7.20UT TOYOKAWA-FUJI


















1206+439 2025/07/14 7.52UT TOYOKAWA-FUJI








1206+439 2025/07/14 7.52UT TOYOKAWA-KISO









BLK: 9,SNR1: 0.22951 ,SNR2: 0.88363









BLK: 9,SNR1: 1.9203 ,SNR2: 5.4228








3C273 2025/07/14 7.85UT TOYOKAWA-FUJI





















1313+453 2025/07/14 8.63UT TOYOKAWA-KISO








T20250714174623




BLK:10,SNR1: 0.45862 ,SNR2: 1.6626




F20250714174623









BLK:10,SNR1: 12.766 ,SNR2: 29.651





1323+32 2025/07/14 8.80UT TOYOKAWA-FUJI








T20250714175735




BLK:12,SNR1: 0.55489 ,SNR2: 1.8239




Frequency (Hz)

F20250714175735






BLK:12,SNR1: 0.66417 ,SNR2: 2.7689




Frequency (Hz)




1335+479 2025/07/14 8.99UT TOYOKAWA-FUJI












1335+479 2025/07/14 8.99UT TOYOKAWA-KISO











1339+472 2025/07/14 9.06UT TOYOKAWA-KISO

