





T20250719055814




BLK: 7,SNR1: -0.90146E-01,SNR2: 0.10590




F20250719055815






BLK: 7,SNR1: 7.2141 ,SNR2: 19.747





0152+435 2025/07/18 21.00UT TOYOKAWA-FUJI










F20250719055815




BLK:13,SNR1: 8.4672 ,SNR2: 23.191




K20250719055813






BLK:13,SNR1: 0.38124 ,SNR2: 1.4008





0152+435 2025/07/18 21.00UT FUJI -KISO








T20250719061903




BLK:14,SNR1: 0.18009 ,SNR2: 0.70089




K20250719061902






BLK:14,SNR1: 2.2488 ,SNR2: 7.4318





0213+178 2025/07/18 21.35UT TOYOKAWA-KISO






T20250719062646





BLK: 3,SNR1: 0.27527 ,SNR2: 2.9138












3067 2025/07/18 21.47UT TOYOKAWA-FUJI

F20250719062646





BLK: 3,SNR1: 2.0731 ,SNR2: 6.6121






F20250719062646





BLK: 8, SNR1: 1.5455 , SNR2: 4.1362





3C67 2025/07/18 21.47UT FUJI -KISO



K20250719062645




BLK: 8, SNR1: 7.6411 , SNR2: 23.524



T20250719064501




BLK:10,SNR1: 0.67522E-02,SNR2: 0.77864





3071 2025/07/18 21.78UT TOYOKAWA-FUJI



F20250719064501






BLK:10,SNR1: 151.96 ,SNR2: 150.48









BLK: 4,SNR1: 0.27618E-01,SNR2: 0.54964








BLK: 4,SNR1: 1.8073 ,SNR2: 5.6904





3C71 2025/07/18 21.78UT TOYOKAWA-KISO








T20250719070416




BLK:13,SNR1: 3.6279 ,SNR2: 10.815




F20250719070417





BLK:13,SNR1: 11.559 ,SNR2: 19.973




0258+350 2025/07/18 22.10UT TOYOKAWA-FUJI





T20250719070416




BLK:17,SNR1: 11.211 ,SNR2: 23.941




K20250719070415





BLK:17,SNR1: 2.9391 ,SNR2: 8.9924




0258+350 2025/07/18 22.10UT TOYOKAWA-KISO





F20250719070417




BLK:18,SNR1: 10.837 ,SNR2: 18.714




K20250719070415





BLK:18,SNR1: 2.9630 ,SNR2: 9.0766




0258+350 2025/07/18 22.10UT FUJI -KISO





T20250719071405




BLK: 4,SNR1: 0.10406 ,SNR2: 1.0823




F20250719071405





BLK: 4,SNR1: 9.3908 ,SNR2: 16.773




0308+305 2025/07/18 22.26UT TOYOKAWA-FUJI





T20250719071405




BLK:11,SNR1: 0.10889 ,SNR2: 1.0337




K20250719071404





BLK:11,SNR1: 8.0992 ,SNR2: 20.976




0308+305 2025/07/18 22.26UT TOYOKAWA-KISO





F20250719071405




BLK:15,SNR1: 6.8188 ,SNR2: 12.187




K20250719071404



BLK:15,SNR1: 8.0214 ,SNR2: 20.777





0308+305 2025/07/18 22.26UT FUJI -KISO







T20250719072536




BLK: 4,SNR1: 0.38422E-01,SNR2: 1.8743




F20250719072536




BLK: 4,SNR1:-0.25511 ,SNR2: 1.7407




0320+05 2025/07/18 22.45UT TOYOKAWA-FUJI



T20250719072536





BLK: 7,SNR1: 0.12333 ,SNR2: 0.45189




Frequency (Hz)

K20250719072535




BLK: 7,SNR1: 0.39677 ,SNR2: 1.3509




Frequency (Hz)


0320+05 2025/07/18 22.45UT TOYOKAWA-KISO





F20250719072536




BLK: 3,SNR1: 0.43383 ,SNR2: 4.2981




K20250719072535









BLK: 3,SNR1: 0.29332 ,SNR2: 3.4895






0320+05 2025/07/18 22.45UT FUJI -KISO













T20250719075159




BLK: 3,SNR1: 0.10959 ,SNR2: 1.1910




F20250719075159





BLK: 3,SNR1: 1.2596 ,SNR2: 3.0291




0347+05 2025/07/18 22.89UT TOYOKAWA-FUJI





T20250719075159




BLK: 2,SNR1: 0.24589E-01,SNR2: 1.5589




K20250719075158



BLK: 2,SNR1: 1.5476 ,SNR2: 8.0260





0347+05 2025/07/18 22.89UT TOYOKAWA-KISO






F20250719075159





BLK: 3,SNR1:-0.11048 ,SNR2: 0.21642




Frequency (Hz)

K20250719075158




BLK: 3,SNR1:-0.96238E-01,SNR2: 0.24650





Frequency (Hz)


0347+05 2025/07/18 22.89UT FUJI -KISO




T20250719080733




BLK:11,SNR1: 2.7967 ,SNR2: 4.9001




F20250719080733




BLK:11,SNR1: 6.0572 ,SNR2: 27.625




0403-132 2025/07/18 23.15UT TOYOKAWA-FUJI





T20250719080733




BLK:22,SNR1: 3.0683 ,SNR2: 6.7719




K20250719080732





BLK:22,SNR1: 2.3356 ,SNR2: 7.1521




0403-132 2025/07/18 23.15UT TOYOKAWA-KISO





F20250719080733




BLK:12,SNR1: 21.431 ,SNR2: 71.849




K20250719080732




BLK:12,SNR1: 2.1881 ,SNR2: 6.7135





0403-132 2025/07/18 23.15UT FUJI -KISO







BLK: 4,SNR1: 0.60740E-01,SNR2: 0.55661





BLK: 4,SNR1: 1.6045 ,SNR2: 5.4625




0411+05 2025/07/18 23.31UT TOYOKAWA-FUJI




T20250719081644




BLK: 4,SNR1: 0.69342E-01,SNR2: 0.44652




K20250719081643




BLK: 4,SNR1: 1.0573 ,SNR2: 3.7557




0411+05 2025/07/18 23.31UT TOYOKAWA-KISO




F20250719081645




BLK: 2,SNR1:-0.17806E-01,SNR2: 0.76417




K20250719081643




BLK: 2,SNR1: 1.5091 ,SNR2: 3.3911




0411+05 2025/07/18 23.31UT FWJ -KISO





T20250719082339




BLK: 7,SNR1: 0.35949 ,SNR2: 2.0620




F20250719082340



BLK: 7,SNR1:-0.63528E-01,SNR2: 1.3839





0418+236 2025/07/18 23.42UT TOYOKAWA-FUJI








T20250719082339




BLK:11,SNR1: 0.28995 ,SNR2: 1.9007




K20250719082338




BLK:11,SNR1: 1.4370 ,SNR2: 4.2650




0418+236 2025/07/18 23.42UT TOYOKAWA-KISO





F20250719082340




BLK: 7,SNR1: 0.15290 ,SNR2: 3.4659




K20250719082338








BLK: 7,SNR1: 1.1734 ,SNR2: 3.7271




0418+236 2025/07/18 23.42UT FUJI -KISO








T20250719083507




BLK:15,SNR1: 0.68669 ,SNR2: 5.7990




K20250719083506






BLK:15,SNR1:-0.73555E-02,SNR2: 2.0820




3C119 2025/07/18 23.61UT TOYOKAWA-KISO







T20250719085401




BLK: 7, SNR1: 0.80717 , SNR2: 2.7630




F20250719085401




BLK: 7, SNR1: 0.28570 , SNR2: 2.2386




0449-012 2025/07/18 23.93UT TOYOKAWA-FUJI





T20250719085401




BLK:10,SNR1: 0.56736 ,SNR2: 3.1095




K20250719085400





BLK:10,SNR1: 6.3691 ,SNR2: 11.040




0449-012 2025/07/18 23.93UT TOYOKAWA-KISO



F20250719085401





BLK:15,SNR1: 0.99870 ,SNR2: 4.9347




Frequency (Hz)

K20250719085400




BLK:15,SNR1: 6.9365 ,SNR2: 12.105




Frequency (Hz)

0449-012 2025/07/18 23.93UT FUJI -KISO







T20250719092313




BLK:18,SNR1: 1.3602 ,SNR2: 7.7130




F20250719092314





BLK:18,SNR1: 0.76934 ,SNR2: 3.3325




3C138 2025/07/19 0.42UT TOYOKAWA-FUJI




T20250719092313




BLK:15,SNR1: 1.1277 ,SNR2: 3.1633




K20250719092312





BLK:15,SNR1: 5.6336 ,SNR2: 12.373




3C138 2025/07/19 0.42UT TOYOKAWA-KISO




F20250719092314




BLK:15,SNR1: 1.1631 ,SNR2: 4.2960




K20250719092312







BLK:15,SNR1: 1.7041 ,SNR2: 5.6506




3C138 2025/07/19 0.42UT FUJI -KISO







0531+194 2025/07/19 0.64UT TOYOKAWA-FUJI





T20250719093647




BLK:16,SNR1: 0.99050 ,SNR2: 2.8958




K20250719093646




BLK:16,SNR1: 5.9164 ,SNR2: 15.682





0531+194 2025/07/19 0.64UT TOYOKAWA-KISO







BLK: 8, SNR1: 0.19958 , SNR2: 4.0792





BLK: 8, SNR1: 7.3082 , SNR2: 21.063




0531+194 2025/07/19 0.64UT FUJI -KISO




T20250719094507




BLK:24,SNR1: 11.125 ,SNR2: 51.375




F20250719094507




BLK:24,SNR1: 0.88238 ,SNR2: 3.2060




3C147 2025/07/19 0.78UT TOYOKAWA-FUJI





T20250719094507




BLK:35,SNR1: 10.369 ,SNR2: 46.940




K20250719094506



BLK:35,SNR1: 2.2585 ,SNR2: 6.0877




3C147 2025/07/19 0.78UT TOYOKAWA-KISO







F20250719094507





BLK:29,SNR1: 0.97779 ,SNR2: 3.4385





K20250719094506




BLK:29,SNR1: 2.1579 ,SNR2: 5.9465





T20250719095318




BLK: 2,SNR1: 0.30111 ,SNR2: 3.3929




F20250719095318




BLK: 2,SNR1:-0.42106 ,SNR2: 0.0000




0548+16 2025/07/19 0.92UT TOYOKAWA-FUJI



T20250719095318




BLK: 7, SNR1: 0.28028 , SNR2: 1.4914





0548+16 2025/07/19 0.92UT TOYOKAWA-KISO



K20250719095317




BLK: 7, SNR1: 0.29235 , SNR2: 2.8566




F20250719095318




BLK: 6,SNR1:-0.32126 ,SNR2: 1.8180




K20250719095317





BLK: 6,SNR1: 0.16439 ,SNR2: 2.1783




0548+16 2025/07/19 0.92UT FUJI -KISO





T20250719095728




BLK:20,SNR1: 11.479 ,SNR2: 24.720




F20250719095729





BLK:20,SNR1: 11.649 ,SNR2: 28.012




0552+12 2025/07/19 0.99UT TOYOKAWA-FUJI





T20250719095728




BLK:18,SNR1: 10.196 ,SNR2: 22.766




K20250719095727







BLK:18,SNR1: 13.062 ,SNR2: 31.549




0552+12 2025/07/19 0.99UT TOYOKAWA-KISO








0552+12 2025/07/19 0.99UT FUJI -KISO




T20250719100155




BLK: 2,SNR1: 0.97308E-01,SNR2: 0.44020




F20250719100156



BLK: 2,SNR1: 1.0280 ,SNR2: 9.5253





0556+191 2025/07/19 1.06UT TOYOKAWA-FUJI








T20250719100155




BLK: 7,SNR1: 0.15547 ,SNR2: 0.45492




K20250719100154




BLK: 7,SNR1:-0.54075E-01,SNR2: 1.1125




0556+191 2025/07/19 1.06UT TOYOKAWA-KISO





F20250719100156




BLK:12,SNR1: 5.8424 ,SNR2: 23.313




K20250719100154




BLK:12,SNR1: 0.14194E-01,SNR2: 0.32607




0556+191 2025/07/19 1.06UT FUJI -KISO





T20250719100941




BLK:11,SNR1: 2.3792 ,SNR2: 6.6450




F20250719100941









BLK:11,SNR1: 6.9853 ,SNR2: 17.153







0605-08 2025/07/19 1.19UT TOYOKAWA-FUJI















3C161 2025/07/19 1.51UT TOYOKAWA-FUJI







3C161 2025/07/19 1.51UT TOYOKAWA-KISO





F20250719102849




BLK: 8,SNR1: 1.0357 ,SNR2: 8.8486




K20250719102848







BLK: 8,SNR1: 2.2157 ,SNR2: 5.9753




3C161 2025/07/19 1.51UT FUJI -KISO

















0652-130 2025/07/19 1.97UT TOYOKAWA-FUJI














0652-130 2025/07/19 1.97UT FUJI -KISO








T20250719110758




BLK: 6, SNR1: 10.510 , SNR2: 25.205




K20250719110757





BLK: 6, SNR1: 10.549 , SNR2: 27.552




0703+138 2025/07/19 2.16UT TOYOKAWA-KISO





F20250719110758




BLK:13,SNR1: 9.9100 ,SNR2: 25.773




K20250719110757







BLK:13,SNR1: 8.2295 ,SNR2: 21.322




0703+138 2025/07/19 2.16UT FUJI -KISO








0713-024 2025/07/19 2.32UT TOYOKAWA-FUJI





T20250719111721




BLK: 6, SNR1: 12.335 , SNR2: 29.730




K20250719111720



BLK: 6, SNR1: 8.9601 , SNR2: 23.068





0713-024 2025/07/19 2.32UT TOYOKAWA-KISO








F20250719111721




BLK: 7, SNR1: 6.2401 , SNR2: 16.076




K20250719111720





BLK: 7, SNR1: 11.343 , SNR2: 28.149




0713-024 2025/07/19 2.32UT FUJI -KISO





T20250719112733




BLK:14,SNR1: 9.2220 ,SNR2: 22.145




F20250719112733







BLK:14,SNR1: 10.469 ,SNR2: 26.965




0723+10 2025/07/19 2.49UT TOYOKAWA-FUJI








0723+10 2025/07/19 2.49UT TOYOKAWA-KISO





F20250719112733




BLK:13,SNR1: 11.535 ,SNR2: 29.015




K20250719112733





BLK:13,SNR1: 8.7873 ,SNR2: 21.791




0723+10 2025/07/19 2.49UT FUJI -KISO





T20250719113748




BLK:18,SNR1: 2.3155 ,SNR2: 6.1128




F20250719113748





BLK:18,SNR1: 1.6813 ,SNR2: 6.8844




0732+33 2025/07/19 2.66UT TOYOKAWA-FUJI





T20250719113748




BLK:13,SNR1: 1.3513 ,SNR2: 4.2475




K20250719113748




BLK:13,SNR1: 5.5843 ,SNR2: 14.419




0732+33 2025/07/19 2.66UT TOYOKAWA-KISO




F20250719113748




BLK:19,SNR1: 2.9266 ,SNR2: 10.103




K20250719113748





BLK:19,SNR1: 6.3516 ,SNR2: 16.176




0732+33 2025/07/19 2.66UT FUJI -KISO




T20250719114549




BLK:23,SNR1: 7.4109 ,SNR2: 17.414




F20250719114549



BLK:23,SNR1: 0.27813 ,SNR2: 3.9011





0741-06 2025/07/19 2.79UT TOYOKAWA-FUJI







T20250719114549




BLK:31,SNR1: 6.7763 ,SNR2: 16.115




K20250719114549







BLK:31,SNR1: 0.88684 ,SNR2: 3.0564




0741-06 2025/07/19 2.79UT TOYOKAWA-KISO









0741-06 2025/07/19 2.79UT FUJI -KISO




T20250719115533





F20250719115533




0752-200 2025/07/19 2.95UT TOYOKAWA-FUJI




T20250719115533




BLK:24,SNR1: 7.1289 ,SNR2: 16.752




K20250719115533




BLK:24,SNR1: 7.9175 ,SNR2: 20.060





0752-200 2025/07/19 2.95UT TOYOKAWA-KISO







BLK:21,SNR1: 5.1337 ,SNR2: 13.970




BLK:21,SNR1: 6.7173 ,SNR2: 18.348




0752-200 2025/07/19 2.95UT FUJI -KISO




T20250719120309




BLK:23,SNR1: 10.849 ,SNR2: 20.844




F20250719120309




BLK:23,SNR1: 2.6357 ,SNR2: 8.9739




3C190 2025/07/19 3.08UT TOYOKAWA-FUJI




T20250719120309




BLK:17,SNR1: 10.865 ,SNR2: 24.852




K20250719120309





BLK:17,SNR1: 2.1402 ,SNR2: 7.1889




3C190 2025/07/19 3.08UT TOYOKAWA-KISO




F20250719120309




BLK:14,SNR1: 9.1679 ,SNR2: 20.266




K20250719120309



BLK:14,SNR1: 4.3980 ,SNR2: 6.4944




3C190 2025/07/19 3.08UT FUJI -KISO







T20250719121534




BLK:14,SNR1: 2.8876 ,SNR2: 7.2719




F20250719121534




BLK:14,SNR1: 6.5652 ,SNR2: 18.799




3C196 2025/07/19 3.29UT TOYOKAWA-FUJI





T20250719121534




BLK:15,SNR1: 1.0532 ,SNR2: 3.7247




K20250719121534





BLK:15,SNR1: 5.9235 ,SNR2: 16.802




3C196 2025/07/19 3.29UT TOYOKAWA-KISO




F20250719121534




BLK: 6,SNR1: 7.1470 ,SNR2: 20.037




K20250719121534





BLK: 6,SNR1: 4.6221 ,SNR2: 12.465




3C196 2025/07/19 3.29UT FUJI -KISO




T20250719122643




BLK:10,SNR1: 7.5669 ,SNR2: 19.495




F20250719122643




BLK:10,SNR1: 3.7661 ,SNR2: 10.014





0821+394 2025/07/19 3.47UT TOYOKAWA-FUJI







BLK:13,SNR1: 2.6727 ,SNR2: 6.8883




BLK:13,SNR1: 4.6309 ,SNR2: 11.873





0821+394 2025/07/19 3.47UT TOYOKAWA-KISO







BLK: 9,SNR1: 2.6853 ,SNR2: 8.4554





BLK: 9,SNR1: 14.093 ,SNR2: 33.082




0821+394 2025/07/19 3.47UT FUJI -KISO





T20250719123822




BLK: 9,SNR1: 9.3428 ,SNR2: 27.013




F20250719123822





BLK: 9,SNR1: 8.2800 ,SNR2: 23.842




0834-19 2025/07/19 3.67UT TOYOKAWA-FUJI





T20250719123822




BLK: 5,SNR1: 9.1208 ,SNR2: 26.448




K20250719123822



BLK: 5,SNR1: 7.0648 ,SNR2: 18.561





0834-19 2025/07/19 3.67UT TOYOKAWA-KISO








F20250719123822




BLK: 7,SNR1: 7.2861 ,SNR2: 21.379




K20250719123822




BLK: 7,SNR1: 6.2088 ,SNR2: 17.351





0834-19 2025/07/19 3.67UT FUJI -KISO







BLK: 9,SNR1: 2.7334 ,SNR2: 6.8370







BLK: 9,SNR1: 1.1780 ,SNR2: 3.7378




0839-071 2025/07/19 3.75UT TOYOKAWA-FUJI







0839-071 2025/07/19 3.75UT TOYOKAWA-KISO




F20250719124328




BLK: 3,SNR1: 0.66603 ,SNR2: 2.9457




K20250719124328





BLK: 3,SNR1: 1.8396 ,SNR2: 3.9372




0839-071 2025/07/19 3.75UT FUJI -KISO




T20250719125429




BLK: 9,SNR1: 4.9702 ,SNR2: 14.796




F20250719125429




BLK: 9,SNR1: 2.6743 ,SNR2: 8.6749





3C208 2025/07/19 3.94UT TOYOKAWA-FUJI







BLK: 9,SNR1: 3.8198 ,SNR2: 11.337




BLK: 9,SNR1: 5.2592 ,SNR2: 13.639





3C208 2025/07/19 3.94UT TOYOKAWA-KISO







BLK: 5,SNR1: 2.3791 ,SNR2: 7.9922




BLK: 5,SNR1: 4.9936 ,SNR2: 13.327





3C208 2025/07/19 3.94UT FUJI -KISO







BLK: 4,SNR1: 0.15393 ,SNR2: 2.8033



BLK: 4,SNR1: 1.0552 ,SNR2: 3.8492





3C216 2025/07/19 4.21UT TOYOKAWA-FUJI








T20250719131111




BLK: 9,SNR1: 4.4244 ,SNR2: 7.7473




K20250719131111





BLK: 9,SNR1: 6.7459 ,SNR2: 17.075




3C216 2025/07/19 4.21UT TOYOKAWA-KISO





F20250719131111




BLK: 2,SNR1: 0.73689E-01,SNR2: 0.79702




K20250719131111




BLK: 2,SNR1: 1.4421,SNR2: 5.4963




3C216 2025/07/19 4.21UT FUJI -KISO





T20250719132322




BLK: 5,SNR1: 4.0825 ,SNR2: 11.142




F20250719132322




BLK: 5,SNR1: 7.1033 ,SNR2: 20.253




0919-142 2025/07/19 4.42UT TOYOKAWA-FUJI




T20250719132322




BLK: 8,SNR1: 4.5987 ,SNR2: 13.341




K20250719132322





BLK: 8,SNR1: 6.9437 ,SNR2: 20.070




0919-142 2025/07/19 4.42UT TOYOKAWA-KISO




F20250719132322




BLK:11,SNR1: 10.974 ,SNR2: 21.119




K20250719132322




BLK:11,SNR1: 10.411 ,SNR2: 30.186





0919-142 2025/07/19 4.42UT FUJI -KISO







BLK: 4,SNR1: 0.12893 ,SNR2: 2.8321




BLK: 4,SNR1: 0.14985 ,SNR2: 2.3199





0926+117 2025/07/19 4.53UT TOYOKAWA-FUJI







BLK:10,SNR1: 0.17757 ,SNR2: 1.7941





BLK:10,SNR1: 0.81068 ,SNR2: 1.7585




0926+117 2025/07/19 4.53UT TOYOKAWA-KISO




F20250719133001




BLK: 5,SNR1: 0.20877 ,SNR2: 3.0780




K20250719133001



BLK: 5,SNR1: 0.80097 ,SNR2: 2.0263





0926+117 2025/07/19 4.53UT FUJI -KISO








T20250719133745




BLK: 6,SNR1: 5.0596 ,SNR2: 15.170




F20250719133745





BLK: 6,SNR1: 5.7196 ,SNR2: 17.629




3C222 2025/07/19 4.66UT TOYOKAWA-FUJI




T20250719133745




BLK:11,SNR1: 4.4468 ,SNR2: 13.775




K20250719133745




BLK:11,SNR1: 6.7181 ,SNR2: 20.792




3C222 2025/07/19 4.66UT TOYOKAWA-KISO




F20250719133745




BLK: 6,SNR1: 9.2510 ,SNR2: 28.141




K20250719133745




BLK: 6,SNR1: 10.624 ,SNR2: 33.744





3C222 2025/07/19 4.66UT FUJI -KISO







BLK:12,SNR1: 0.43867 ,SNR2: 1.5447





BLK:12,SNR1: 2.3327 ,SNR2: 9.5149




0941-08 2025/07/19 4.77UT TOYOKAWA-FUJI





T20250719134445




BLK:16,SNR1: 0.45486 ,SNR2: 1.4221




K20250719134445




BLK:16,SNR1: 4.0170 ,SNR2: 7.0899




0941-08 2025/07/19 4.77UT TOYOKAWA-KISO





F20250719134445




BLK: 9,SNR1: 2.4662 ,SNR2: 8.2523




K20250719134445




BLK: 9,SNR1: 5.1757 ,SNR2: 9.1380





0941-08 2025/07/19 4.77UT FUJI -KISO







BLK:20,SNR1: 7.7050 ,SNR2: 19.924




BLK:20,SNR1: 30.615 ,SNR2: 30.473





3C230 2025/07/19 4.91UT TOYOKAWA-FUJI







BLK:26,SNR1: 7.8680 ,SNR2: 20.339



BLK:26,SNR1: 7.5990 ,SNR2: 20.002




3C230 2025/07/19 4.91UT TOYOKAWA-KISO







F20250719135307




BLK:20,SNR1: 2.5076 ,SNR2: 7.8076




K20250719135307





BLK:20,SNR1: 9.3849 ,SNR2: 20.521




3C230 2025/07/19 4.91UT FUJI -KISO





T20250719140715




BLK: 6,SNR1: 2.1009 ,SNR2: 5.6404




F20250719140715





BLK: 6,SNR1: 0.42717 ,SNR2: 1.9278




3C236 2025/07/19 5.15UT TOYOKAWA-FUJI




T20250719140715




BLK:15,SNR1: 1.6848 ,SNR2: 4.4405




K20250719140715





BLK:15,SNR1: 0.44440 ,SNR2: 1.4166




3C236 2025/07/19 5.15UT TOYOKAWA-KISO





F20250719140715




BLK: 9,SNR1: 1.0827 ,SNR2: 4.2568




K20250719140715




BLK: 9,SNR1: 1.2157 ,SNR2: 2.4161





3C236 2025/07/19 5.15UT FUJI -KISO







BLK:11,SNR1: 2.2806 ,SNR2: 7.4615




BLK:11,SNR1: 0.84795 ,SNR2: 2.7538





1011+110 2025/07/19 5.28UT TOYOKAWA-FUJI







BLK:13,SNR1: 2.3236 ,SNR2: 7.5766




BLK:13,SNR1: 7.6469 ,SNR2: 19.771




1011+110 2025/07/19 5.28UT TOYOKAWA-KISO





F20250719141524




BLK:19,SNR1: 0.77750 ,SNR2: 2.4763




K20250719141524




BLK:19,SNR1: 7.2482 ,SNR2: 18.737




1011+110 2025/07/19 5.28UT FUJI -KISO




T20250719142305




BLK: 7,SNR1: 7.3549 ,SNR2: 20.829




F20250719142306





BLK: 7,SNR1: 6.4776 ,SNR2: 18.187




3C241 2025/07/19 5.41UT TOYOKAWA-FUJI









3C241 2025/07/19 5.41UT TOYOKAWA-KISO





F20250719142306




BLK: 7, SNR1: 11.995 , SNR2: 22.842




K20250719142305





BLK: 7, SNR1: 6.8646 , SNR2: 20.182




3C241 2025/07/19 5.41UT FUJI -KISO



T20250719143434





BLK: 8,SNR1: 0.47417 ,SNR2: 1.5218




Frequency (Hz)

F20250719143434




BLK: 8,SNR1: 0.42148E-01,SNR2: 2.3470




Frequency (Hz)




1031-11 2025/07/19 5.60UT TOYOKAWA-FUJI




T20250719143434




K20250719143434




1031-11 2025/07/19 5.60UT TOYOKAWA-KISO





F20250719143434




BLK: 7,SNR1: 4.8058 ,SNR2: 16.786




K20250719143434





BLK: 7,SNR1: 4.8642 ,SNR2: 15.262




1031-11 2025/07/19 5.60UT FUJI -KISO




T20250719143908




BLK: 7,SNR1: 1.2443 ,SNR2: 3.7183




F20250719143908





BLK: 7,SNR1:-0.16330 ,SNR2: 1.0929




1035-058 2025/07/19 5.68UT TOYOKAWA-FUJI





T20250719143908




BLK:14,SNR1: 1.1210 ,SNR2: 3.4187




K20250719143908





BLK:14,SNR1: 3.4368 ,SNR2: 6.1030




1035-058 2025/07/19 5.68UT TOYOKAWA-KISO





F20250719143908




BLK:11,SNR1:-0.29250 ,SNR2: 1.1236




K20250719143908



BLK:11,SNR1: 5.0494 ,SNR2: 9.0259





1035-058 2025/07/19 5.68UT FUJI -KISO







T20250719144821




BLK: 3,SNR1: 1.3427 ,SNR2: 3.4951




F20250719144821





BLK: 3,SNR1: 0.45184 ,SNR2: 2.4925




1044-008 2025/07/19 5.83UT TOYOKAWA-FUJI





T20250719144821




BLK: 1,SNR1:-0.13916 ,SNR2: 1.4316




K20250719144821





BLK: 1,SNR1: 0.67667 ,SNR2: 2.4219




1044-008 2025/07/19 5.83UT TOYOKAWA-KISO




F20250719144821




BLK: 5,SNR1: 0.11811 ,SNR2: 1.8789




K20250719144821





BLK: 5,SNR1:-0.50371E-01,SNR2: 1.4734




1044-008 2025/07/19 5.83UT FUJI -KISO








1055+01 2025/07/19 6.02UT TOYOKAWA-FUJI




T20250719145925




BLK: 2,SNR1: 0.36891 ,SNR2: 1.4276




K20250719145925




BLK: 2,SNR1: 1.9323 ,SNR2: 5.3114




1055+01 2025/07/19 6.02UT TOYOKAWA-KISO




F20250719145925




BLK: 3,SNR1: 0.36201 ,SNR2: 1.4002




K20250719145925





BLK: 3,SNR1:-0.56509E-01,SNR2: 0.36258




1055+01 2025/07/19 6.02UT FUJI -KISO





T20250719151043




BLK:19,SNR1: 0.34677 ,SNR2: 1.1561




F20250719151043




BLK:19,SNR1: 7.5590 ,SNR2: 20.378





1107+109 2025/07/19 6.21UT TOYOKAWA-FUJI







BLK:16,SNR1: 0.38003 ,SNR2: 1.3759




BLK:16,SNR1: 8.1439 ,SNR2: 14.531





1107+109 2025/07/19 6.21UT TOYOKAWA-KISO









BLK:17,SNR1: 12.380 ,SNR2: 29.336




BLK:17,SNR1: 2.0390 ,SNR2: 6.9582





1107+109 2025/07/19 6.21UT FUJI -KISO







BLK:13,SNR1: 0.24904 ,SNR2: 1.4534





BLK:13,SNR1: 1.3541 ,SNR2: 4.6875




3C255 2025/07/19 6.37UT TOYOKAWA-FUJI




T20250719152020




BLK:17,SNR1: 0.24745 ,SNR2: 2.2039




K20250719152020




BLK:17,SNR1: 1.5894 ,SNR2: 4.6960





3C255 2025/07/19 6.37UT TOYOKAWA-KISO







BLK: 9,SNR1: 1.4035 ,SNR2: 5.0271








BLK: 9,SNR1: 1.4079 ,SNR2: 3.7076





3C255 2025/07/19 6.37UT FUJI -KISO









BLK: 8,SNR1: 0.26533 ,SNR2: 1.5564




BLK: 8,SNR1: 0.28411 ,SNR2: 1.0384





1127-14 2025/07/19 6.54UT TOYOKAWA-KISO








BLK: 7,SNR1:-0.11440 ,SNR2: 1.9317





BLK: 7,SNR1: 1.0718 ,SNR2: 3.0093







BLK: 6,SNR1: 0.97874E-01,SNR2: 0.42523



BLK: 6,SNR1: 1.2343 ,SNR2: 3.5471





3C263.1 2025/07/19 6.77UT TOYOKAWA-FUJI






T20250719154418





BLK: 5, SNR1: 0.34902E-01, SNR2: 0.60280




Frequency (Hz)

K20250719154418




BLK: 5, SNR1: 0.79324, SNR2: 2.2386




Frequency (Hz)


3C263.1 2025/07/19 6.77UT TOYOKAWA-KISO




F20250719154418




BLK: 3,SNR1: 1.9765 ,SNR2: 11.717




K20250719154418





BLK: 3,SNR1:-0.11180 ,SNR2: 0.33203




3C263.1 2025/07/19 6.77UT FUJI -KISO



T20250719155045





BLK: 7,SNR1: 0.50046 ,SNR2: 1.3279




Frequency (Hz)

F20250719155045





BLK: 7,SNR1: 1.2354 ,SNR2: 3.5086





Frequency (Hz)

3C267 2025/07/19 6.87UT TOYOKAWA-FUJI







BLK:15,SNR1: 1.2920 ,SNR2: 7.4842












BLK:15,SNR1: 2.4067 ,SNR2: 6.7485




3C267 2025/07/19 6.87UT TOYOKAWA-KISO










1213-17 2025/07/19 7.30UT TOYOKAWA-FUJI







BLK: 4,SNR1: 0.74775E-01,SNR2: 1.0772








BLK: 4,SNR1: 0.35987 ,SNR2: 1.0733




1213-17 2025/07/19 7.30UT TOYOKAWA-KISO













BLK:13,SNR1: 1.8688 ,SNR2: 11.671





BLK:13,SNR1:-0.83867E-02,SNR2: 1.3701




3C273 2025/07/19 7.53UT TOYOKAWA-FUJI



T20250719162950




BLK:18,SNR1: 1.7473 ,SNR2: 5.0458




Frequency (Hz)

K20250719162950




BLK:18,SNR1: 5.4055 ,SNR2: 7.8807




Frequency (Hz)


3C273 2025/07/19 7.53UT TOYOKAWA-KISO



F20250719162950





BLK:19,SNR1: 0.94376 ,SNR2: 5.2311




Frequency (Hz)

K20250719162950




BLK:19,SNR1: 1.9713 ,SNR2: 3.0849





Frequency (Hz)


3C273 2025/07/19 7.53UT FUJI -KISO



T20250719164301





BLK:11,SNR1: 0.21901E-01,SNR2: 0.52501




Frequency (Hz)

F20250719164301







BLK:11,SNR1: 3.2402 ,SNR2: 11.302





Frequency (Hz)

3C275 2025/07/19 7.75UT TOYOKAWA-FUJI






F20250719164301





BLK: 6,SNR1: 5.7273 ,SNR2: 10.713




Frequency (Hz)

K20250719164301





BLK: 6,SNR1: 0.33181 ,SNR2: 3.6500





Frequency (Hz)

3C275 2025/07/19 7.75UT FUJI -KISO







BLK: 3,SNR1:-0.17820E-01,SNR2: 0.29696




BLK: 3,SNR1: 0.16847 ,SNR2: 1.2558





1313+453 2025/07/19 8.31UT TOYOKAWA-FUJI







BLK: 3,SNR1: 0.53599E-01,SNR2: 1.0846



BLK: 3,SNR1: 0.33020 ,SNR2: 1.5465




1313+453 2025/07/19 8.31UT TOYOKAWA-KISO







F20250719171637




BLK: 1,SNR1:-0.81043E-01,SNR2: 1.4588




K20250719171637







BLK: 1,SNR1:-0.17641,SNR2: 0.82996E-01






1313+453 2025/07/19 8.31UT FUJI -KISO







1323+32 2025/07/19 8.47UT TOYOKAWA-FUJI







1323+32 2025/07/19 8.47UT TOYOKAWA-KISO







BLK: 5,SNR1: 1.5130 ,SNR2: 4.0587





BLK: 5,SNR1: 4.1874 ,SNR2: 9.0712




1323+32 2025/07/19 8.47UT FUJI -KISO



T20250719173133





BLK:17,SNR1: 0.31686 ,SNR2: 3.0584




Frequency (Hz)

F20250719173133




BLK:17,SNR1: 1.7876 ,SNR2: 5.3424





Frequency (Hz)


3C286 2025/07/19 8.55UT TOYOKAWA-FUJI



T20250719173133





BLK:11,SNR1: 0.35407 ,SNR2: 3.4816




Frequency (Hz)

K20250719173133




BLK:11,SNR1: 2.1431 ,SNR2: 5.6346





Frequency (Hz)


3C286 2025/07/19 8.55UT TOYOKAWA-KISO



F20250719173133





BLK:21,SNR1: 3.0445 ,SNR2: 9.4115




Frequency (Hz)

K20250719173133




BLK:21,SNR1: 7.5536 ,SNR2: 22.527





Frequency (Hz)


3C286 2025/07/19 8.55UT FUJI -KISO



T20250719173756




BLK: 9, SNR1: 0.35727 , SNR2: 1.1123




Frequency (Hz)

F20250719173756




BLK: 9, SNR1: 3.9049 , SNR2: 15.663





Frequency (Hz)

1335+479 2025/07/19 8.66UT TOYOKAWA-FUJI






T20250719173756




BLK: 5, SNR1: 0.25094 , SNR2: 2.6572




Frequency (Hz)

K20250719173756





BLK: 5, SNR1: 1.8898 , SNR2: 4.9742





Frequency (Hz)

1335+479 2025/07/19 8.66UT TOYOKAWA-KISO






BLK: 9, SNR1: 2.1532 , SNR2: 12.509



BLK: 9, SNR1: 2.6488 , SNR2: 3.6717



1335+479 2025/07/19 8.66UT FUJI -KISO

