





















T20250724060706




BLK: 8,SNR1: 0.83422E-01,SNR2: 1.0519




F20250724060706











BLK: 8,SNR1: 3.0026 ,SNR2: 10.697





3C67 2025/07/23 21.15UT TOYOKAWA-FUJI









BLK: 6,SNR1: 4.0984 ,SNR2: 12.198





BLK: 6,SNR1: 0.45832 ,SNR2: 1.8007




3C67 2025/07/23 21.15UT FUJI -KISO




T20250724064436




BLK: 2,SNR1: 0.62924E-01,SNR2: 0.59455




F20250724064436





BLK: 2,SNR1: 1.0046 ,SNR2: 1.6337




0258+350 2025/07/23 21.77UT TOYOKAWA-FUJI




T20250724064436




BLK: 1,SNR1:-0.19099 ,SNR2: 0.33444




K20250724064434





BLK: 1,SNR1: 0.72239 ,SNR2: 2.1637




0258+350 2025/07/23 21.77UT TOYOKAWA-KISO



F20250724064436





BLK:12,SNR1:-0.10752 ,SNR2: 1.6786




Frequency (Hz)

K20250724064434




BLK:12,SNR1: 1.2882 ,SNR2: 2.7081





Frequency (Hz)


0258+350 2025/07/23 21.77UT FUJI -KISO





T20250724065426




BLK: 9,SNR1: 0.73064 ,SNR2: 2.2444




F20250724065426





BLK: 9,SNR1: 7.3947 ,SNR2: 18.729




0308+305 2025/07/23 21.94UT TOYOKAWA-FUJI





T20250724065426




BLK:20,SNR1: 6.4716 ,SNR2: 11.377




K20250724065423







BLK:20,SNR1: 7.9920 ,SNR2: 20.777





0308+305 2025/07/23 21.94UT TOYOKAWA-KISO









BLK: 9,SNR1: 0.84693E-01,SNR2: 0.84951





BLK: 9,SNR1: 9.8368 ,SNR2: 21.963





0320+05 2025/07/23 22.13UT TOYOKAWA-FUJI







BLK: 9,SNR1: 0.83620E-01,SNR2: 0.51889




BLK: 9,SNR1: 2.5002 ,SNR2: 4.8058




0320+05 2025/07/23 22.13UT TOYOKAWA-KISO





F20250724070557




BLK: 8,SNR1: 17.407 ,SNR2: 32.444




K20250724070554





BLK: 8,SNR1: 2.0220 ,SNR2: 5.6040




0320+05 2025/07/23 22.13UT FUJI -KISO



T20250724071919





BLK:19,SNR1: 2.9610 ,SNR2: 9.1713








0333+32 2025/07/23 22.35UT TOYOKAWA-FUJI

F20250724071919





BLK:19,SNR1: 3.0298 ,SNR2: 9.2263






F20250724071919





BLK:21,SNR1: 8.8365 ,SNR2: 15.525





0333+32 2025/07/23 22.35UT FUJI -KISO



K20250724071917




BLK:21,SNR1: 7.9214 ,SNR2: 20.520





T20250724073220




BLK: 2,SNR1: 0.30896 ,SNR2: 0.88255




F20250724073220





BLK: 2,SNR1: 1.3920 ,SNR2: 4.2727




0347+05 2025/07/23 22.57UT TOYOKAWA-FUJI





T20250724073220




BLK: 4, SNR1: 0.11099 , SNR2: 0.35686




K20250724073217




BLK: 4, SNR1: 0.45573 , SNR2: 3.4777





0347+05 2025/07/23 22.57UT TOYOKAWA-KISO







BLK: 2,SNR1: 0.33932 ,SNR2: 2.0811





BLK: 2,SNR1: 0.46166 ,SNR2: 5.1919




0347+05 2025/07/23 22.57UT FUJI -KISO




T20250724074754




BLK: 5,SNR1:-0.20232E-01,SNR2: 0.40715




F20250724074754





BLK: 5,SNR1: 1.9259 ,SNR2: 6.2812




0403-132 2025/07/23 22.83UT TOYOKAWA-FUJI



T20250724074754





BLK:10,SNR1: 0.71668 ,SNR2: 1.4276






0403-132 2025/07/23 22.83UT TOYOKAWA-KISO

K20250724074751





BLK:10,SNR1: 2.1234 ,SNR2: 7.0936







BLK:15,SNR1: 2.1225 ,SNR2: 6.6676






BLK:15,SNR1: 9.6123 ,SNR2: 21.019





0403-132 2025/07/23 22.83UT FUJI -KISO







T20250724075705




BLK: 8,SNR1: 0.21533 ,SNR2: 0.96369




K20250724075702




BLK: 8,SNR1: 1.4991 ,SNR2: 3.9758




0411+05 2025/07/23 22.98UT TOYOKAWA-KISO





F20250724075705




BLK: 4, SNR1: 0.28267 , SNR2: 1.3361




K20250724075702





BLK: 4, SNR1: 0.37853 , SNR2: 2.8380




0411+05 2025/07/23 22.98UT FUJI -KISO





T20250724080359




BLK: 8,SNR1: 2.1106 ,SNR2: 6.0121




F20250724080359





BLK: 8,SNR1: 3.6706 ,SNR2: 10.066




0418+236 2025/07/23 23.09UT TOYOKAWA-FUJI





T20250724080359




BLK: 5, SNR1: 2.6452 ,SNR2: 5.7579




K20250724080356





BLK: 5, SNR1: 10.026 ,SNR2: 27.506




0418+236 2025/07/23 23.09UT TOYOKAWA-KISO





F20250724080359




BLK: 4, SNR1: 10.041 ,SNR2: 21.762




K20250724080356




BLK: 4, SNR1: 10.016 ,SNR2: 27.478





0418+236 2025/07/23 23.09UT FUJI -KISO







BLK:12,SNR1: 10.541 ,SNR2: 23.045







BLK:12,SNR1:-0.17333E-02,SNR2: 0.32384





3C119 2025/07/23 23.29UT TOYOKAWA-FUJI







3C119 2025/07/23 23.29UT TOYOKAWA-KISO







BLK: 7,SNR1: 0.91968 ,SNR2: 3.2628





BLK: 7,SNR1: 5.4408 ,SNR2: 13.220




3C119 2025/07/23 23.29UT FUJI -KISO





T20250724085359




BLK: 4, SNR1: 0.24883 , SNR2: 0.77281




F20250724085359





BLK: 4, SNR1: 2.7662 , SNR2: 7.2935




0508+094 2025/07/23 23.93UT TOYOKAWA-FUJI





T20250724085359




BLK: 8,SNR1: 0.15459 ,SNR2: 0.52560




K20250724085356




BLK: 8,SNR1: 1.1468 ,SNR2: 2.0214




0508+094 2025/07/23 23.93UT TOYOKAWA-KISO





F20250724085359




BLK: 5,SNR1: 1.3401 ,SNR2: 3.5840




K20250724085356





BLK: 5,SNR1: 1.2160 ,SNR2: 3.2581




0508+094 2025/07/23 23.93UT FUJI -KISO




T20250724090334




BLK:20,SNR1: 0.79161 ,SNR2: 7.0078




F20250724090334





BLK:20,SNR1:-0.39924E-01,SNR2: 3.4368




3C138 2025/07/24 0.09UT TOYOKAWA-FUJI





T20250724090334




BLK:17,SNR1: 0.99514 ,SNR2: 7.9889




K20250724090331




BLK:17,SNR1: 0.40368 ,SNR2: 1.7914




3C138 2025/07/24 0.09UT TOYOKAWA-KISO




F20250724090334




BLK: 8,SNR1: 0.63892E-01,SNR2: 1.1918




K20250724090331





BLK: 8,SNR1: 0.45971 ,SNR2: 3.0340




3C138 2025/07/24 0.09UT FUJI -KISO





T20250724091707




BLK:21,SNR1: 10.025 ,SNR2: 18.106




F20250724091707





BLK:21,SNR1: 7.5459 ,SNR2: 19.275




0531+194 2025/07/24 0.31UT TOYOKAWA-FUJI





T20250724091707




BLK:19,SNR1: 9.2520 ,SNR2: 22.980




K20250724091704





BLK:19,SNR1: 8.6453 ,SNR2: 22.309




0531+194 2025/07/24 0.31UT TOYOKAWA-KISO





F20250724091707




BLK:24,SNR1: 7.3753 ,SNR2: 18.856




K20250724091704




BLK:24,SNR1: 8.6426 ,SNR2: 22.302




0531+194 2025/07/24 0.31UT FUJI -KISO




T20250724092528




BLK:23,SNR1: 17.412 ,SNR2: 86.018




F20250724092528




BLK:23,SNR1: 0.32409 ,SNR2: 3.2492




3C147 2025/07/24 0.45UT TOYOKAWA-FUJI





T20250724092528




BLK:25,SNR1: 15.510 ,SNR2: 64.161




K20250724092525




BLK:25,SNR1: 74.753 ,SNR2: 87.761




3C147 2025/07/24 0.45UT TOYOKAWA-KISO




F20250724092528




BLK:26,SNR1: 0.44031 ,SNR2: 3.0093




K20250724092525





BLK:26,SNR1: 50.404 ,SNR2: 86.062




3C147 2025/07/24 0.45UT FUJI -KISO



T20250724093338





BLK: 7, SNR1: 336.21 , SNR2: 775.63





0548+16 2025/07/24 0.59UT TOYOKAWA-FUJI



F20250724093339




BLK: 7, SNR1: 12.482 , SNR2: 29.659




T20250724093338




BLK:15,SNR1: 166.71 ,SNR2: 316.36




K20250724093335





BLK:15,SNR1: 35.691 ,SNR2: 49.658




0548+16 2025/07/24 0.59UT TOYOKAWA-KISO




F20250724093339




BLK:10,SNR1: 7.1446 ,SNR2: 19.090




K20250724093335





BLK:10,SNR1: 57.172 ,SNR2: 76.406




0548+16 2025/07/24 0.59UT FUJI -KISO




T20250724093749




BLK: 9,SNR1: 0.70436E-01,SNR2: 1.1218




F20250724093749




BLK: 9,SNR1: 2.6498 ,SNR2: 11.024




0552+12 2025/07/24 0.66UT TOYOKAWA-FUJI




T20250724093749




BLK: 7, SNR1: 0.87023 , SNR2: 3.4991




K20250724093746





BLK: 7, SNR1: 0.16978 , SNR2: 0.76436




0552+12 2025/07/24 0.66UT TOYOKAWA-KISO





F20250724093749




BLK:10,SNR1: 1.5123 ,SNR2: 4.5565




K20250724093746







BLK:10,SNR1: 0.41434 ,SNR2: 1.7886




0552+12 2025/07/24 0.66UT FUJI -KISO








0556+191 2025/07/24 0.73UT TOYOKAWA-FUJI





T20250724094216




BLK:10,SNR1: 15.685 ,SNR2: 51.566




K20250724094213







BLK:10,SNR1: 8.5792 ,SNR2: 24.381








0556+191 2025/07/24 0.73UT TOYOKAWA-KISO











0556+191 2025/07/24 0.73UT FUJI -KISO






3C152 2025/07/24 0.81UT TOYOKAWA-FUJI







F20250724094648




BLK:18,SNR1: 4.4988 ,SNR2: 10.826




K20250724094645





BLK:18,SNR1: 6.5567 ,SNR2: 16.553




3C152 2025/07/24 0.81UT FUJI -KISO



T20250724100909




BLK:17,SNR1: 0.51290 ,SNR2: 3.5401





3C161 2025/07/24 1.18UT TOYOKAWA-FUJI


F20250724100909




BLK:17,SNR1: 0.81078 ,SNR2: 2.4926




T20250724100909




BLK:19,SNR1: 0.49929 ,SNR2: 3.4313




K20250724100906




BLK:19,SNR1: 0.92752 ,SNR2: 2.7848




3C161 2025/07/24 1.18UT TOYOKAWA-KISO





F20250724100909




BLK:15,SNR1: 0.71997 ,SNR2: 3.0860




K20250724100906




BLK:15,SNR1: 1.1481 ,SNR2: 2.8738




3C161 2025/07/24 1.18UT FUJI -KISO





T20250724103642




BLK:10,SNR1: 9.2296 ,SNR2: 27.123




F20250724103642




BLK:10,SNR1: 10.310 ,SNR2: 29.889




0652-130 2025/07/24 1.64UT TOYOKAWA-FUJI





T20250724103642




BLK: 5, SNR1: 8.4988 , SNR2: 24.093




K20250724103639







BLK: 5, SNR1: 6.8372 , SNR2: 17.802




0652-130 2025/07/24 1.64UT TOYOKAWA-KISO








0652-130 2025/07/24 1.64UT FUJI -KISO





T20250724104819




BLK: 5, SNR1: 11.345 , SNR2: 28.465




F20250724104819





BLK: 5, SNR1: 9.7329 , SNR2: 27.298




0703+138 2025/07/24 1.83UT TOYOKAWA-FUJI





T20250724104819




BLK: 4, SNR1: 10.454 , SNR2: 25.934




K20250724104816







BLK: 4, SNR1: 11.286 , SNR2: 27.432








0703+138 2025/07/24 1.83UT TOYOKAWA-KISO







0703+138 2025/07/24 1.83UT FUJI -KISO







0713-024 2025/07/24 1.99UT TOYOKAWA-FUJI







BLK: 3,SNR1: 0.84644E-01,SNR2: 2.0657





BLK: 3,SNR1: 0.44008 ,SNR2: 2.2166




0713-024 2025/07/24 1.99UT TOYOKAWA-KISO





F20250724105741




BLK: 5,SNR1:-0.36640E-01,SNR2: 2.8310




K20250724105738




BLK: 5,SNR1: 0.34298 ,SNR2: 1.8750




0713-024 2025/07/24 1.99UT FUJI -KISO




T20250724110753




BLK: 9,SNR1: 3.1698 ,SNR2: 6.0997




F20250724110753





BLK: 9,SNR1: 0.88991 ,SNR2: 3.7849




0723+10 2025/07/24 2.16UT TOYOKAWA-FUJI





T20250724110753




BLK: 9, SNR1: 1.4302 , SNR2: 3.3243




K20250724110750





BLK: 9, SNR1: 3.4264 , SNR2: 9.3936




0723+10 2025/07/24 2.16UT TOYOKAWA-KISO





F20250724110753




BLK: 5, SNR1: 0.70701 , SNR2: 1.8681




K20250724110750




BLK: 5, SNR1: 1.4703 , SNR2: 4.9549




0723+10 2025/07/24 2.16UT FUJI -KISO





T20250724111808




BLK:15,SNR1: 0.57714 ,SNR2: 2.3597




F20250724111808




BLK:15,SNR1:-0.33273E-01,SNR2: 0.85012




0732+33 2025/07/24 2.33UT TOYOKAWA-FUJI




T20250724111808




BLK:16,SNR1: 2.6961 ,SNR2: 6.4279




K20250724111806





BLK:16,SNR1: 4.7177 ,SNR2: 6.4179




0732+33 2025/07/24 2.33UT TOYOKAWA-KISO




F20250724111808




BLK:14,SNR1: 1.9103 ,SNR2: 5.0088




K20250724111806





BLK:14,SNR1: 1.8781 ,SNR2: 5.8815




0732+33 2025/07/24 2.33UT FUJI -KISO





T20250724112609




BLK:15,SNR1: 0.85880 ,SNR2: 3.7062




F20250724112609





BLK:15,SNR1: 2.4853 ,SNR2: 6.8996





0741-06 2025/07/24 2.46UT TOYOKAWA-FUJI




T20250724112609




K20250724112606




0741-06 2025/07/24 2.46UT TOYOKAWA-KISO




F20250724112609




BLK:11,SNR1: 4.7679 ,SNR2: 12.634




K20250724112606





BLK:11,SNR1: 1.2033 ,SNR2: 3.8189




0741-06 2025/07/24 2.46UT FUJI -KISO





T20250724113554




BLK: 4, SNR1: 7.6865 , SNR2: 20.224




F20250724113554





BLK: 4, SNR1: 8.5294 , SNR2: 21.514




0752-200 2025/07/24 2.63UT TOYOKAWA-FUJI





T20250724113554




BLK:11,SNR1: 6.5959 ,SNR2: 16.967




K20250724113551





BLK:11,SNR1: 10.326 ,SNR2: 26.303




0752-200 2025/07/24 2.63UT TOYOKAWA-KISO





F20250724113554




BLK: 8,SNR1: 9.3163 ,SNR2: 22.549




K20250724113551




BLK: 8,SNR1: 11.595 ,SNR2: 28.410




0752-200 2025/07/24 2.63UT FUJI -KISO





T20250724114329




BLK: 6,SNR1: 6.9401 ,SNR2: 17.457




F20250724114329




BLK: 6,SNR1: 9.4891 ,SNR2: 23.904




3C190 2025/07/24 2.75UT TOYOKAWA-FUJI




T20250724114329




BLK: 6,SNR1: 10.217 ,SNR2: 25.174




K20250724114326





BLK: 6,SNR1: 17.044 ,SNR2: 32.856




3C190 2025/07/24 2.75UT TOYOKAWA-KISO




F20250724114329




BLK:11,SNR1: 3.8240 ,SNR2: 8.8253




K20250724114326





BLK:11,SNR1: 7.8273 ,SNR2: 19.613




3C190 2025/07/24 2.75UT FUJI -KISO








3C196 2025/07/24 2.96UT TOYOKAWA-FUJI





T20250724115554




BLK:21,SNR1: 11.564 ,SNR2: 28.872




K20250724115552








BLK:21,SNR1: 7.2640 ,SNR2: 18.623





3C196 2025/07/24 2.96UT TOYOKAWA-KISO








T20250724120704




BLK:11,SNR1: 11.670 ,SNR2: 21.155




F20250724120704





BLK:11,SNR1: 3.4635 ,SNR2: 7.0533




0821+394 2025/07/24 3.15UT TOYOKAWA-FUJI




T20250724120704




BLK: 7, SNR1: 9.4681 , SNR2: 17.533




K20250724120701





BLK: 7, SNR1: 0.43012 , SNR2: 3.5011





0821+394 2025/07/24 3.15UT TOYOKAWA-KISO




F20250724120704













K20250724120701





0821+394 2025/07/24 3.15UT FUJI -KISO










F20250724121843




K20250724121840





0834-19 2025/07/24 3.34UT FUJI -KISO







BLK:18,SNR1: 0.68061 ,SNR2: 4.3682





BLK:18,SNR1: 0.37055 ,SNR2: 0.82020




0839-071 2025/07/24 3.42UT TOYOKAWA-FUJI





T20250724122348




BLK:13,SNR1: 0.81496 ,SNR2: 3.3569




K20250724122345







BLK:13,SNR1: 2.2021 ,SNR2: 7.1939




0839-071 2025/07/24 3.42UT TOYOKAWA-KISO








0839-071 2025/07/24 3.42UT FUJI -KISO




T20250724123450




BLK:15,SNR1: 0.38915 ,SNR2: 3.0313




F20250724123450




BLK:15,SNR1: 0.59738 ,SNR2: 2.9629




3C208 2025/07/24 3.61UT TOYOKAWA-FUJI





T20250724123450




BLK:15,SNR1: 0.48078 ,SNR2: 2.8675




K20250724123447





BLK:15,SNR1: 1.0768 ,SNR2: 6.7313




3C208 2025/07/24 3.61UT TOYOKAWA-KISO





F20250724123450




BLK:18,SNR1: 13.927 ,SNR2: 12.868




K20250724123447




BLK:18,SNR1: 0.91347 ,SNR2: 5.8585





3C208 2025/07/24 3.61UT FUJI -KISO







BLK:15,SNR1: 1.4345 ,SNR2: 3.6477




BLK:15,SNR1: 0.30371 ,SNR2: 0.76208




3C216 2025/07/24 3.89UT TOYOKAWA-FUJI





T20250724125132




BLK:13,SNR1: 1.0913 ,SNR2: 3.3570




K20250724125130







BLK:13,SNR1: 0.19448 ,SNR2: 1.1821






3C216 2025/07/24 3.89UT TOYOKAWA-KISO






3C216 2025/07/24 3.89UT FUJI -KISO








0919-142 2025/07/24 4.09UT TOYOKAWA-FUJI





T20250724130342




BLK: 9,SNR1: 1.4400 ,SNR2: 3.8217




K20250724130339





BLK: 9,SNR1: 1.5811 ,SNR2: 2.8288




0919-142 2025/07/24 4.09UT TOYOKAWA-KISO








0919-142 2025/07/24 4.09UT FUJI -KISO




T20250724131021




BLK:19,SNR1: 0.22223 ,SNR2: 1.8138




F20250724131021





BLK:19,SNR1: 2.9849 ,SNR2: 3.9346




0926+117 2025/07/24 4.20UT TOYOKAWA-FUJI





T20250724131021




BLK:12,SNR1: 0.26940 ,SNR2: 1.7829




K20250724131018




BLK:12,SNR1: 1.6231 ,SNR2: 4.3282





0926+117 2025/07/24 4.20UT TOYOKAWA-KISO







BLK:16,SNR1: 0.47361 ,SNR2: 2.8078













BLK:16,SNR1: 2.6428 ,SNR2: 3.7621




0926+117 2025/07/24 4.20UT FUJI -KISO













BLK: 6,SNR1: 1.6797 ,SNR2: 3.5157





BLK: 6,SNR1: 3.8823 ,SNR2: 4.7480




3C222 2025/07/24 4.33UT FUJI -KISO




T20250724132506




BLK:13,SNR1: 0.85462 ,SNR2: 2.7897




F20250724132506





BLK:13,SNR1: 0.18955 ,SNR2: 1.4612




0941-08 2025/07/24 4.45UT TOYOKAWA-FUJI




T20250724132506




BLK:11,SNR1: 0.84658 ,SNR2: 2.2120




K20250724132503




BLK:11,SNR1: 0.64874 ,SNR2: 1.3571




0941-08 2025/07/24 4.45UT TOYOKAWA-KISO




F20250724132506




BLK: 9,SNR1:-0.75262E-01,SNR2: 1.2979




K20250724132503





BLK: 9,SNR1:-0.34025 ,SNR2: 0.31322




0941-08 2025/07/24 4.45UT FUJI -KISO





T20250724133328




BLK:10,SNR1: 0.49613 ,SNR2: 4.4523




F20250724133328




BLK:10,SNR1: 3.0368 ,SNR2: 6.2900





3C230 2025/07/24 4.59UT TOYOKAWA-FUJI







BLK:10,SNR1: 0.71402 ,SNR2: 4.7341





BLK:10,SNR1: 4.9478 ,SNR2: 4.5269





3C230 2025/07/24 4.59UT TOYOKAWA-KISO




F20250724133328




K20250724133325





3C230 2025/07/24 4.59UT FUJI -KISO







BLK:13,SNR1: 0.37092 ,SNR2: 2.4627




BLK:13,SNR1: 3.7180 ,SNR2: 7.9852




3C236 2025/07/24 4.82UT TOYOKAWA-FUJI





T20250724134735




BLK:13,SNR1: 0.54548 ,SNR2: 4.4672




K20250724134732




BLK:13,SNR1: 4.0638 ,SNR2: 6.3351





3C236 2025/07/24 4.82UT TOYOKAWA-KISO







BLK:16,SNR1:-0.18976 ,SNR2: 1.2915




BLK:16,SNR1: 0.27323 ,SNR2: 1.1949





3C236 2025/07/24 4.82UT FUJI -KISO







BLK: 8,SNR1: 0.10530 ,SNR2: 1.7682





BLK: 8,SNR1: 1.7542 ,SNR2: 2.9484




1011+110 2025/07/24 4.96UT TOYOKAWA-FUJI





T20250724135545




BLK:19,SNR1: 0.14412 ,SNR2: 0.51833




K20250724135542






BLK:19,SNR1: 1.0932 ,SNR2: 3.5791





1011+110 2025/07/24 4.96UT TOYOKAWA-KISO








T20250724140326




BLK:10,SNR1: 0.59185 ,SNR2: 1.4904




F20250724140326




BLK:10,SNR1: 0.37422 ,SNR2: 0.63637





3C241 2025/07/24 5.09UT TOYOKAWA-FUJI







BLK:20,SNR1: 0.43801 ,SNR2: 2.1129




BLK:20,SNR1: 1.5899 ,SNR2: 1.7079





3C241 2025/07/24 5.09UT TOYOKAWA-KISO







BLK:16,SNR1: 0.25597 ,SNR2: 0.42691





BLK:16,SNR1: 3.4445 ,SNR2: 5.1058




3C241 2025/07/24 5.09UT FUJI -KISO





T20250724141455




BLK: 9,SNR1: 0.77903 ,SNR2: 2.4348




F20250724141455





BLK: 9,SNR1: 0.70427 ,SNR2: 0.73422




1031-11 2025/07/24 5.28UT TOYOKAWA-FUJI





T20250724141455




BLK:22,SNR1: 0.31790 ,SNR2: 1.0807




K20250724141452





BLK:22,SNR1: 2.3161 ,SNR2: 4.5822




1031-11 2025/07/24 5.28UT TOYOKAWA-KISO





F20250724141455




BLK: 9,SNR1: 1.7167 ,SNR2: 1.6083




K20250724141452




BLK: 9,SNR1: 0.38507 ,SNR2: 0.46828




1031-11 2025/07/24 5.28UT FUJI -KISO





T20250724141928




BLK:12,SNR1: 2.5860 ,SNR2: 10.194




F20250724141928





BLK:12,SNR1: 1.0956 ,SNR2: 1.7493




1035-058 2025/07/24 5.35UT TOYOKAWA-FUJI





T20250724141928




BLK:18,SNR1: 2.1309 ,SNR2: 8.3471




K20250724141925




BLK:18,SNR1: 0.59193 ,SNR2: 1.1676





1035-058 2025/07/24 5.35UT TOYOKAWA-KISO







BLK:12,SNR1: 1.5459 ,SNR2: 1.5008




BLK:12,SNR1: 2.2620 ,SNR2: 4.6633




1035-058 2025/07/24 5.35UT FUJI -KISO




T20250724142841




BLK:11,SNR1: 0.69748 ,SNR2: 3.3938




F20250724142841





BLK:11,SNR1: 6.0564 ,SNR2: 6.4089





1044-008 2025/07/24 5.51UT TOYOKAWA-FUJI




T20250724142841








K20250724142838





1044-008 2025/07/24 5.51UT TOYOKAWA-KISO








T20250724143946




BLK:15,SNR1: 0.52795 ,SNR2: 1.0905




F20250724143946





BLK:15,SNR1: 1.1764 ,SNR2: 2.6181




1055+01 2025/07/24 5.69UT TOYOKAWA-FUJI





T20250724143946




BLK:16,SNR1: 0.55652 ,SNR2: 1.7115




K20250724143943




BLK:16,SNR1: 1.6481 ,SNR2: 3.6817





1055+01 2025/07/24 5.69UT TOYOKAWA-KISO







BLK:14,SNR1: 3.0094 ,SNR2: 6.1267





BLK:14,SNR1: 3.3088 ,SNR2: 3.2196




1055+01 2025/07/24 5.69UT FUJI -KISO





T20250724145103




BLK:12,SNR1: 0.81080 ,SNR2: 2.4906




F20250724145103





BLK:12,SNR1: 4.2823 ,SNR2: 8.0652




1107+109 2025/07/24 5.88UT TOYOKAWA-FUJI





T20250724145103




BLK:15,SNR1: 0.72607 ,SNR2: 2.0169




K20250724145100




BLK:15,SNR1: 1.9444 ,SNR2: 2.3682





1107+109 2025/07/24 5.88UT TOYOKAWA-KISO







BLK:16,SNR1: 0.67449E-01,SNR2: 3.2441




BLK:16,SNR1: 1.2739 ,SNR2: 1.7031





1107+109 2025/07/24 5.88UT FUJI -KISO








BLK:14,SNR1: 1.2791 ,SNR2: 2.0857




BLK:14,SNR1: 3.5069 ,SNR2: 7.0703





T20250724150041




BLK:11,SNR1: 0.80581 ,SNR2: 3.4899




K20250724150038




BLK:11,SNR1: 0.18304 ,SNR2: 0.86932





3C255 2025/07/24 6.04UT TOYOKAWA-KISO







BLK: 5,SNR1: 2.5328 ,SNR2: 7.5334




BLK: 5,SNR1: 0.52871 ,SNR2: 1.0773





3C255 2025/07/24 6.04UT FUJI -KISO







BLK:20,SNR1: 2.9696 ,SNR2: 5.2950




BLK:20,SNR1: 4.2412 ,SNR2: 10.506





1127-14 2025/07/24 6.22UT TOYOKAWA-FUJI







BLK:18,SNR1: 3.1064 ,SNR2: 5.5518




BLK:18,SNR1: 0.39663 ,SNR2: 1.6166





1127-14 2025/07/24 6.22UT TOYOKAWA-KISO








BLK:15,SNR1: 39.264 ,SNR2: 38.345





BLK:15,SNR1: 0.36495 ,SNR2: 1.7874








BLK:11,SNR1: 0.25952 ,SNR2: 2.9893





BLK:11,SNR1:-0.17252 ,SNR2: 1.2016







BLK:13,SNR1: 0.40810 ,SNR2: 1.9158




BLK:13,SNR1: 0.89180 ,SNR2: 2.3340





3C263.1 2025/07/24 6.44UT TOYOKAWA-KISO







BLK:14,SNR1:-0.16568 ,SNR2: 1.1837





BLK:14,SNR1: 2.7609 ,SNR2: 2.7009




3C263.1 2025/07/24 6.44UT FUJI -KISO




T20250724153106




BLK:13,SNR1: 0.49686 ,SNR2: 1.7844




F20250724153106




BLK:13,SNR1:-0.17754 ,SNR2: 1.4374





3C267 2025/07/24 6.55UT TOYOKAWA-FUJI







BLK:10,SNR1: 0.57622 ,SNR2: 2.0820








BLK:10,SNR1: 2.5906 ,SNR2: 3.8504





3C267 2025/07/24 6.55UT TOYOKAWA-KISO






T20250724155653




BLK: 7, SNR1: 1.5713 , SNR2: 3.9735




Frequency (Hz)

F20250724155653




BLK: 7, SNR1: 0.75743 , SNR2: 3.9124




Frequency (Hz)


1213-17 2025/07/24 6.98UT TOYOKAWA-FUJI




T20250724155653




BLK:15,SNR1: 5.5042 ,SNR2: 7.1105




K20250724155650





BLK:15,SNR1: 8.6391 ,SNR2: 10.084




1213-17 2025/07/24 6.98UT TOYOKAWA-KISO



F20250724155653





BLK: 7, SNR1: 6.2241 , SNR2: 13.937




Frequency (Hz)

K20250724155650




BLK: 7, SNR1: 7.0960 , SNR2: 12.362





Frequency (Hz)


1213-17 2025/07/24 6.98UT FUJI -KISO




T20250724161011




BLK:19,SNR1: 1.9803 ,SNR2: 4.7000




F20250724161011




BLK:19,SNR1: 0.22596 ,SNR2: 1.5699





3C273 2025/07/24 7.20UT TOYOKAWA-FUJI







BLK:17,SNR1: 39.093 ,SNR2: 46.396




BLK:17,SNR1: 2.6144 ,SNR2: 7.3263





3C273 2025/07/24 7.20UT TOYOKAWA-KISO







BLK:17,SNR1: 0.16164 ,SNR2: 2.0880





BLK:17,SNR1: 3.1032 ,SNR2: 5.8679




3C273 2025/07/24 7.20UT FUJI -KISO



T2025072416232





BLK:23,SNR1: 8.0204 ,SNR2: 13.758




Frequency (Hz)

3C275 2025/07/24 7.42UT TOYOKAWA-FUJ


F2025072416232





BLK:23,SNR1: 17.383 ,SNR2: 31.500




Frequency (Hz)



T20250724162321




BLK: 9,SNR1: 8.6180 ,SNR2: 15.385




Frequency (Hz)

K20250724162321




BLK: 9,SNR1: 3.5237 ,SNR2: 9.9946





Frequency (Hz)


3C275 2025/07/24 7.42UT TOYOKAWA-KISO



F20250724162321





BLK:13,SNR1: 17.948 ,SNR2: 32.514




Frequency (Hz)

K20250724162321





BLK:13,SNR1: 6.6970 ,SNR2: 10.725





Frequency (Hz)

3C275 2025/07/24 7.42UT FUJI -KISO







BLK:18,SNR1: 2.4509 ,SNR2: 5.7986




BLK:18,SNR1: 3.9330 ,SNR2: 9.3868





1245-19 2025/07/24 7.52UT TOYOKAWA-FUJI







BLK:13,SNR1: 1.1517 ,SNR2: 3.9454




BLK:13,SNR1: 4.8824 ,SNR2: 9.9478





1245-19 2025/07/24 7.52UT TOYOKAWA-KISO







BLK:14,SNR1: 4.1878 ,SNR2: 9.6949




BLK:14,SNR1: 6.5818 ,SNR2: 9.4642





1245-19 2025/07/24 7.52UT FUJI -KISO







BLK: 5,SNR1: 20.571 ,SNR2: 25.802







BLK: 5,SNR1: 4.1077 ,SNR2: 12.622









3C279 2025/07/24 7.65UT TOYOKAWA-FUJI










3C279 2025/07/24 7.65UT TOYOKAWA-KISO










1313+453 2025/07/24 7.98UT TOYOKAWA-FUJI







BLK:12,SNR1: 6.1078 ,SNR2: 18.832







BLK:12,SNR1: 8.8033 ,SNR2: 15.616




1313+453 2025/07/24 7.98UT TOYOKAWA-KISO








1313+453 2025/07/24 7.98UT FUJI -KISO



T20250724170704





BLK: 6, SNR1: 2.7573 , SNR2: 5.5424




Frequency (Hz)

F20250724170704




BLK: 6, SNR1: 0.98370 , SNR2: 4.0513





Frequency (Hz)


1323+32 2025/07/24 8.15UT TOYOKAWA-FUJI



T20250724170704





BLK:20,SNR1: 2.2607 ,SNR2: 3.0961




Frequency (Hz)

K20250724170702




BLK:20,SNR1: 5.1995 ,SNR2: 12.437




Frequency (Hz)


1323+32 2025/07/24 8.15UT TOYOKAWA-KISO



F20250724170704





BLK:11,SNR1: 0.97287 ,SNR2: 4.0094




Frequency (Hz)

K20250724170702









BLK:11,SNR1: 23.858 ,SNR2: 29.205







Frequency (Hz)


1323+32 2025/07/24 8.15UT FUJI -KISO











3C286 2025/07/24 8.23UT TOYOKAWA-KISO





3C286 2025/07/24 8.23UT FUJI -KISO

