




T20250725064041




BLK: 5, SNR1: 1.7618 , SNR2: 5.3435




Frequency (Hz)

F20250725064041







BLK: 5, SNR1: 0.42551 , SNR2: 2.2206






Frequency (Hz)



0258+350 2025/07/24 21.71UT TOYOKAWA-FUJI










T20250725065030




BLK: 4,SNR1: 0.11896 ,SNR2: 1.2849




F20250725065030




BLK: 4,SNR1: 1.2463 ,SNR2: 4.1160





0308+305 2025/07/24 21.87UT TOYOKAWA-FUJI







BLK: 7,SNR1: $-0.94060E-01$,SNR2: 0.12755







BLK: 7,SNR1: 0.35455 ,SNR2: 2.1849





0308+305 2025/07/24 21.87UT TOYOKAWA-KISO









BLK: 4,SNR1: 0.16022 ,SNR2: 1.2437







BLK: 4,SNR1: 0.24862 ,SNR2: 1.9752





0320+05 2025/07/24 22.06UT TOYOKAWA-FUJI









BLK: 4,SNR1: 0.85512 ,SNR2: 2.9328





BLK: 4,SNR1: 0.17907E-01,SNR2: 0.36425




0320+05 2025/07/24 22.06UT FUJI -KISO





T20250725071523




BLK: 6,SNR1: 0.28848 ,SNR2: 0.66208




F20250725071523







BLK: 6,SNR1: 1.2101 ,SNR2: 4.4483





0333+32 2025/07/24 22.28UT TOYOKAWA-FUJI











BLK: 6,SNR1: 0.76975 ,SNR2: 3.7627





BLK: 6,SNR1: 0.98483 ,SNR2: 3.1666







0347+05 2025/07/24 22.50UT TOYOKAWA-FUJI







BLK: 4,SNR1: 0.24582 ,SNR2: 0.78647





BLK: 4,SNR1: 1.5151 ,SNR2: 4.5359




0347+05 2025/07/24 22.50UT TOYOKAWA-KISO








0347+05 2025/07/24 22.50UT FUJI -KISO




T20250725074358




BLK: 6, SNR1: 0.44278 , SNR2: 3.3870




F20250725074358





BLK: 6, SNR1: 0.32142 , SNR2: 2.6246




0403-132 2025/07/24 22.76UT TOYOKAWA-FUJI




T20250725074358




BLK:18,SNR1: 0.25033 ,SNR2: 1.8836




K20250725074355




BLK:18,SNR1: 5.6406 ,SNR2: 9.7996




0403-132 2025/07/24 22.76UT TOYOKAWA-KISO




F20250725074358




BLK: 6,SNR1: 0.22182 ,SNR2: 2.2530




K20250725074355







BLK: 6,SNR1: 2.0925 ,SNR2: 5.4906




0403-132 2025/07/24 22.76UT FUJI -KISO







0411+05 2025/07/24 22.91UT TOYOKAWA-FUJI





T20250725075309




BLK:10,SNR1: 2.4045 ,SNR2: 6.5678




K20250725075306





BLK:10,SNR1: 11.411 ,SNR2: 28.751




0411+05 2025/07/24 22.91UT TOYOKAWA-KISO



F20250725075309





BLK:10,SNR1: 6.9187 ,SNR2: 20.010




Frequency (Hz)

K20250725075306




BLK:10,SNR1: 9.9786 ,SNR2: 25.159





Frequency (Hz)


0411+05 2025/07/24 22.91UT FUJI -KISO




T20250725080003




BLK: 4, SNR1: 0.87242 , SNR2: 3.0259




F20250725080003





BLK: 4, SNR1: 2.9445 , SNR2: 11.634




0418+236 2025/07/24 23.03UT TOYOKAWA-FUJI





T20250725080003




BLK: 7, SNR1: 0.16227 , SNR2: 0.61918




K20250725080000




BLK: 7, SNR1: 0.91028 , SNR2: 2.9887




0418+236 2025/07/24 23.03UT TOYOKAWA-KISO




F20250725080003




BLK: 3,SNR1: 0.40648 ,SNR2: 1.8140




K20250725080000







BLK: 3,SNR1: 0.25146 ,SNR2: 4.7565








0418+236 2025/07/24 23.03UT FUJI -KISO






3C119 2025/07/24 23.22UT TOYOKAWA-FUJI








3C119 2025/07/24 23.22UT TOYOKAWA-KISO




F20250725081131




BLK:14,SNR1: 0.75073 ,SNR2: 2.7889




K20250725081128





BLK:14,SNR1: 0.79993 ,SNR2: 3.0979




3C119 2025/07/24 23.22UT FUJI -KISO



T20250725091311





BLK: 8, SNR1: 10.239 , SNR2: 25.453




Frequency (Hz)

F20250725091311




BLK: 8, SNR1: 6.7308 , SNR2: 19.987





Frequency (Hz)


0531+194 2025/07/25 0.25UT TOYOKAWA-FUJI



T20250725091311





BLK: 7, SNR1: 10.392 , SNR2: 25.908




Frequency (Hz)

K20250725091308




BLK: 7, SNR1: 9.6751 , SNR2: 24.580




Frequency (Hz)


0531+194 2025/07/25 0.25UT TOYOKAWA-KISO




F20250725091311




BLK: 7, SNR1: 12.290 , SNR2: 30.219




K20250725091308




BLK: 7, SNR1: 7.6407 , SNR2: 21.728




0531+194 2025/07/25 0.25UT FUJI -KISO




T20250725092132




BLK:16,SNR1: 7.4130 ,SNR2: 21.535




F20250725092132




BLK:16,SNR1: 4.3768 ,SNR2: 11.188




3C147 2025/07/25 0.39UT TOYOKAWA-FUJI




T20250725092132




BLK:15,SNR1: 8.0163 ,SNR2: 22.933




K20250725092129





BLK:15,SNR1: 5.6930 ,SNR2: 15.145




3C147 2025/07/25 0.39UT TOYOKAWA-KISO



F20250725092132





BLK: 9,SNR1: 6.1461 ,SNR2: 16.924




Frequency (Hz)

K20250725092129




BLK: 9,SNR1: 6.2318 ,SNR2: 16.418





Frequency (Hz)


3C147 2025/07/25 0.39UT FUJI -KISO




T20250725092942




BLK: 9,SNR1: 0.83598E-01,SNR2: 1.4955




F20250725092942





BLK: 9,SNR1:-0.14024 ,SNR2: 1.5790




0548+16 2025/07/25 0.52UT TOYOKAWA-FUJI





T20250725092942




BLK: 3,SNR1: 0.58401E-01,SNR2: 1.1575




K20250725092939




BLK: 3,SNR1: 0.90926 ,SNR2: 2.6463




0548+16 2025/07/25 0.52UT TOYOKAWA-KISO





F20250725092942




BLK: 3,SNR1: 0.84353E-01,SNR2: 1.7211




K20250725092939




BLK: 3,SNR1:-0.94352E-01,SNR2: 0.36349




0548+16 2025/07/25 0.52UT FUJI -KISO




T20250725093353




BLK: 7, SNR1: 10.621 , SNR2: 25.785




F20250725093353





BLK: 7, SNR1: 6.2875 , SNR2: 16.123




0552+12 2025/07/25 0.59UT TOYOKAWA-FUJI




T20250725093353




BLK:10,SNR1: 1.8698 ,SNR2: 5.7494




K20250725093350




BLK:10,SNR1: 9.1185 ,SNR2: 22.591




0552+12 2025/07/25 0.59UT TOYOKAWA-KISO




F20250725093353




BLK: 7, SNR1: 5.3501 ,SNR2: 13.661




K20250725093350





BLK: 7, SNR1: 11.483 ,SNR2: 27.732




0552+12 2025/07/25 0.59UT FUJI -KISO





T20250725093820




BLK: 8,SNR1: 0.63027 ,SNR2: 1.7833




F20250725093820





BLK: 8,SNR1: 0.93325 ,SNR2: 7.2142




0556+191 2025/07/25 0.67UT TOYOKAWA-FUJI



T20250725093820




BLK: 3, SNR1: 1.0044 , SNR2: 3.3971





0556+191 2025/07/25 0.67UT TOYOKAWA-KISO


K20250725093817




BLK: 3, SNR1: 1.6144 , SNR2: 4.4446




F20250725093820




BLK: 8,SNR1: 4.7358 ,SNR2: 12.130




K20250725093817





BLK: 8,SNR1: 2.0307 ,SNR2: 5.7588




0556+191 2025/07/25 0.67UT FUJI -KISO




T20250725094253




BLK: 9,SNR1: 1.9801 ,SNR2: 5.4335




F20250725094253





BLK: 9,SNR1: 2.0462 ,SNR2: 6.0851




3C152 2025/07/25 0.74UT TOYOKAWA-FUJI





T20250725094253




BLK:10,SNR1: 0.65914 ,SNR2: 2.2242




K20250725094250




BLK:10,SNR1: 2.5545 ,SNR2: 6.6343




3C152 2025/07/25 0.74UT TOYOKAWA-KISO





F20250725094253




BLK: 7, SNR1: 1.7544 , SNR2: 4.2992




K20250725094250





BLK: 7, SNR1: 3.3533 , SNR2: 6.0385




3C152 2025/07/25 0.74UT FUJI -KISO




T20250725100513




BLK:22,SNR1: 3.6242 ,SNR2: 7.0095




F20250725100513









BLK:22,SNR1: 1.8775 ,SNR2: 7.1306





3C161 2025/07/25 1.12UT TOYOKAWA-FUJI








T20250725103246





BLK: 2,SNR1: 4.4162 ,SNR2: 13.887




Frequency (Hz)

F20250725103246






BLK: 2,SNR1: 0.88645E-01,SNR2: 1.2471




Frequency (Hz)




0652-130 2025/07/25 1.57UT TOYOKAWA-FUJI






0652-130 2025/07/25 1.57UT TOYOKAWA-KISO








T20250725104423




BLK:10,SNR1: 9.7507 ,SNR2: 28.255




F20250725104423









BLK:10,SNR1: 13.496 ,SNR2: 32.083




0703+138 2025/07/25 1.77UT TOYOKAWA-FUJI









T20250725105345




BLK:13,SNR1: 3.2218 ,SNR2: 8.3000




F20250725105345









BLK:13,SNR1: 8.9444 ,SNR2: 26.692







0713-024 2025/07/25 1.92UT TOYOKAWA-FUJI




















0723+10 2025/07/25 2.09UT TOYOKAWA-FUJI
















0732+33 2025/07/25 2.26UT TOYOKAWA-FUJI







0732+33 2025/07/25 2.26UT TOYOKAWA-KISO








T20250725112214




BLK: 6,SNR1: 0.83709 ,SNR2: 3.3300




F20250725112214









BLK: 6,SNR1: 1.6863 ,SNR2: 5.9623







0741-06 2025/07/25 2.40UT TOYOKAWA-FUJI


















0752-200 2025/07/25 2.56UT TOYOKAWA-FUJI










T20250725113933




BLK:18,SNR1: 5.3288 ,SNR2: 12.495




F20250725113933









BLK:18,SNR1: 8.4718 ,SNR2: 19.167











3C190 2025/07/25 2.69UT TOYOKAWA-FUJI




















T20250725120308




BLK: 7, SNR1: 1.4712 , SNR2: 4.1857




F20250725120308








BLK: 7, SNR1: 5.6183 , SNR2: 16.415




0821+394 2025/07/25 3.08UT TOYOKAWA-FUJI









0821+394 2025/07/25 3.08UT FUJI -KISO




T20250725121447




BLK: 6,SNR1: 0.63166 ,SNR2: 2.1661




F20250725121447








BLK: 6,SNR1: 4.6733 ,SNR2: 9.3175




0834-19 2025/07/25 3.27UT TOYOKAWA-FUJI










0834-19 2025/07/25 3.27UT FUJI -KISO





T20250725121952




BLK:14,SNR1: 6.5868 ,SNR2: 51.627




F20250725121952








BLK:14,SNR1: 1.9998 ,SNR2: 3.5038




0839-071 2025/07/25 3.36UT TOYOKAWA-FUJI



















0839-071 2025/07/25 3.36UT FUJI -KISO















BLK:13,SNR1: 0.15936 ,SNR2: 2.1903









BLK:13,SNR1: 3.5689 ,SNR2: 4.2213




3C216 2025/07/25 3.82UT TOYOKAWA-FUJI













BLK: 8,SNR1: 0.37962 ,SNR2: 1.9938








BLK: 8,SNR1: 0.71577 ,SNR2: 3.5717




0919-142 2025/07/25 4.02UT TOYOKAWA-FUJI










0919-142 2025/07/25 4.02UT FUJI -KISO







BLK: 8,SNR1: 1.7651 ,SNR2: 9.7499









BLK: 8,SNR1: 1.8669 ,SNR2: 3.6302




0926+117 2025/07/25 4.14UT TOYOKAWA-FUJI









T20250725131410




BLK: 9,SNR1: 0.81052 ,SNR2: 3.1106




F20250725131410









BLK: 9,SNR1: 1.8909 ,SNR2: 4.3641





3C222 2025/07/25 4.26UT TOYOKAWA-FUJI









T20250725132110




BLK: 8,SNR1: 0.42332 ,SNR2: 2.4112




F20250725132110









BLK: 8,SNR1: 2.8808 ,SNR2: 5.8666




0941-08 2025/07/25 4.38UT TOYOKAWA-FUJI















BLK:10,SNR1: 0.34773 ,SNR2: 3.0012







BLK:10,SNR1: 1.6596 ,SNR2: 4.0906






3C230 2025/07/25 4.52UT TOYOKAWA-KISO







T20250725134339




BLK:10,SNR1: 0.44363 ,SNR2: 2.4369




F20250725134339









BLK:10,SNR1: 0.52103 ,SNR2: 0.85545





3C236 2025/07/25 4.76UT TOYOKAWA-FUJI


















1011+110 2025/07/25 4.89UT TOYOKAWA-FUJI










T20250725135930




BLK: 9,SNR1: 0.41459 ,SNR2: 3.1213




F20250725135930









BLK: 9,SNR1: 1.0150 ,SNR2: 1.9051





3C241 2025/07/25 5.02UT TOYOKAWA-FUJI










T20250725141059




BLK:10,SNR1: 0.40871 ,SNR2: 3.2834




F20250725141059









BLK:10,SNR1: 2.0220 ,SNR2: 3.5399





1031-11 2025/07/25 5.21UT TOYOKAWA-FUJI









T20250725141533




BLK: 7,SNR1: 0.74540 ,SNR2: 2.4428




F20250725141533





BLK: 7,SNR1: 0.95090 ,SNR2: 1.3534







1035-058 2025/07/25 5.29UT TOYOKAWA-FUJI








1035-058 2025/07/25 5.29UT TOYOKAWA-KISO









BLK: 8,SNR1: 0.12997 ,SNR2: 0.51300





BLK: 8,SNR1: 4.3679 ,SNR2: 6.2834







1044-008 2025/07/25 5.44UT TOYOKAWA-FUJI








1044-008 2025/07/25 5.44UT TOYOKAWA-KISO









BLK:11,SNR1: 0.66629E-02,SNR2: 0.75322









BLK:11,SNR1: 26.868 ,SNR2: 37.599





1055+01 2025/07/25 5.63UT TOYOKAWA-FUJI









T20250725144707




BLK: 8,SNR1: 0.18676 ,SNR2: 1.2640




F20250725144707





BLK: 8,SNR1: 25.980 ,SNR2: 42.551







1107+109 2025/07/25 5.81UT TOYOKAWA-FUJI








1107+109 2025/07/25 5.81UT TOYOKAWA-KISO









BLK:13,SNR1: 0.11694 ,SNR2: 0.91642









BLK:13,SNR1: 0.16519 ,SNR2: 2.8747




3C255 2025/07/25 5.97UT TOYOKAWA-FUJI













BLK:14,SNR1: 1.1939 ,SNR2: 7.9443





BLK:14,SNR1: 16.659 ,SNR2: 15.834







1127-14 2025/07/25 6.15UT TOYOKAWA-FUJI








1127-14 2025/07/25 6.15UT TOYOKAWA-KISO









BLK:14,SNR1: 0.31366 ,SNR2: 2.0414









BLK:14,SNR1: 1.0712 ,SNR2: 6.1235




3C263.1 2025/07/25 6.37UT TOYOKAWA-FUJI










T20250725152710




BLK: 6,SNR1: 0.29560 ,SNR2: 1.1672




F20250725152710









BLK: 6,SNR1: 19.250 ,SNR2: 21.041




3C267 2025/07/25 6.48UT TOYOKAWA-FUJI









T20250725155257




BLK: 6,SNR1: 53.994 ,SNR2: 73.562




F20250725155257









BLK: 6,SNR1: 1.5208 ,SNR2: 3.0230





1213-17 2025/07/25 6.91UT TOYOKAWA-FUJI









T20250725160615




BLK:19,SNR1: 1.0874 ,SNR2: 3.4322




F20250725160615









BLK:19,SNR1: 0.56805 ,SNR2: 3.5986




3C273 2025/07/25 7.13UT TOYOKAWA-FUJI













BLK: 1,SNR1: 0.25206 ,SNR2: 0.51059









BLK: 1,SNR1: 1.3226 ,SNR2: 2.9087







3C275 2025/07/25 7.35UT TOYOKAWA-FUJI

















1245-19 2025/07/25 7.45UT TOYOKAWA-FUJI













BLK:28,SNR1: 7.8983 ,SNR2: 22.887









BLK:28,SNR1: 8.0232 ,SNR2: 23.950







3C279 2025/07/25 7.58UT TOYOKAWA-FUJI
















1313+453 2025/07/25 7.91UT TOYOKAWA-FUJI







1313+453 2025/07/25 7.91UT TOYOKAWA-KISO








T20250725170308





F20250725170308



1323+32 2025/07/25 8.08UT TOYOKAWA-FUJI





1323+32 2025/07/25 8.08UT TOYOKAWA-KISO

