

















BLK: 5,SNR1: 0.15169 ,SNR2: 0.72389



BLK: 5,SNR1: 2.3277 ,SNR2: 5.2984




0244+377 2025/07/31 21.01UT TOYOKAWA-KISO






F20250801055902





BLK: 6,SNR1: 0.86370 ,SNR2: 3.1717




Frequency (Hz)

K20250801055901





BLK: 6,SNR1: 0.95447 ,SNR2: 2.5804





Frequency (Hz)

0244+377 2025/07/31 21.01UT FUJI -KISO







BLK: 3,SNR1: 0.90171 ,SNR2: 7.7909





BLK: 3,SNR1: 19.593 ,SNR2: 44.318




0258+350 2025/07/31 21.25UT TOYOKAWA-FUJI




T20250801061309




BLK: 9, SNR1: 4.6747 , SNR2: 11.342




K20250801061308




BLK: 9, SNR1: 12.671 , SNR2: 28.239





0258+350 2025/07/31 21.25UT TOYOKAWA-KISO







BLK: 7,SNR1: 8.6070 ,SNR2: 20.593





BLK: 7,SNR1: 9.6576 ,SNR2: 21.267




0258+350 2025/07/31 21.25UT FUJI -KISO




T20250801061705




BLK: 8,SNR1: 1.7823 ,SNR2: 5.1609




F20250801061705




BLK: 8,SNR1: 4.9312 ,SNR2: 12.148





0302+341 2025/07/31 21.31UT TOYOKAWA-FUJI







BLK: 4,SNR1:-0.22310E-01,SNR2: 1.7197








BLK: 4,SNR1: 10.499 ,SNR2: 19.508





0302+341 2025/07/31 21.31UT TOYOKAWA-KISO








T20250801062258




BLK: 5, SNR1: 35.316 , SNR2: 47.777




F20250801062259



BLK: 5, SNR1: 3.4984 , SNR2: 8.6869





0308+305 2025/07/31 21.41UT TOYOKAWA-FUJI








T20250801062258




BLK: 3, SNR1: 2.6566 , SNR2: 6.6864




K20250801062257





BLK: 3, SNR1: 7.6317 , SNR2: 16.565




0308+305 2025/07/31 21.41UT TOYOKAWA-KISO





F20250801062259




BLK: 7, SNR1: 3.4962 , SNR2: 8.6817




K20250801062257







BLK: 7, SNR1: 1.4935 , SNR2: 4.6553





0308+305 2025/07/31 21.41UT FUJI -KISO







0324+119 2025/07/31 21.67UT TOYOKAWA-FUJI







BLK:14,SNR1: 12.011 ,SNR2: 33.883





BLK:14,SNR1: 7.5032 ,SNR2: 19.421




0324+119 2025/07/31 21.67UT TOYOKAWA-KISO





F20250801063835




BLK:13,SNR1: 9.8737 ,SNR2: 24.562




K20250801063834





BLK:13,SNR1: 8.3326 ,SNR2: 18.161




0324+119 2025/07/31 21.67UT FUJI -KISO




T20250801064751




BLK: 6,SNR1: 16.042 ,SNR2: 21.435




F20250801064751





BLK: 6,SNR1: 9.1574 ,SNR2: 21.404




0333+32 2025/07/31 21.83UT TOYOKAWA-FUJI




T20250801064751




BLK: 4, SNR1: 21.242 , SNR2: 32.785




K20250801064750




BLK: 4, SNR1: 13.109 , SNR2: 27.329




0333+32 2025/07/31 21.83UT TOYOKAWA-KISO




F20250801064751




BLK: 2, SNR1: 0.41691 , SNR2: 9.2646




K20250801064750





BLK: 2, SNR1: 5.0414 , SNR2: 10.790




0333+32 2025/07/31 21.83UT FUJI -KISO















0347+05 2025/07/31 22.04UT TOYOKAWA-FUJI









BLK: 7,SNR1: 7.7405 ,SNR2: 17.897




BLK: 7,SNR1: 7.7910 ,SNR2: 18.252




0347+05 2025/07/31 22.04UT FUJI -KISO





T20250801071627




BLK:10,SNR1: 0.79862 ,SNR2: 4.7718




F20250801071627







BLK:10,SNR1: 0.35361 ,SNR2: 2.4603





0403-132 2025/07/31 22.30UT TOYOKAWA-FUJI







0403-132 2025/07/31 22.30UT TOYOKAWA-KISO







BLK:11,SNR1: 0.42421E-01,SNR2: 1.7131





BLK:11,SNR1: 5.0657 ,SNR2: 13.229




0403-132 2025/07/31 22.30UT FUJI -KISO





T20250801072538




BLK:11,SNR1: 3.4801 ,SNR2: 8.6513




F20250801072538




BLK:11,SNR1: 5.2813 ,SNR2: 13.249




0411+05 2025/07/31 22.46UT TOYOKAWA-FUJI




T20250801072538




BLK: 7, SNR1: 13.378 , SNR2: 31.338




K20250801072537



BLK: 7, SNR1: 7.0967 , SNR2: 10.828




0411+05 2025/07/31 22.48UT TOYOKAWA-KISO







F20250801072538




BLK:11,SNR1: 6.4152 ,SNR2: 14.563




K20250801072537




BLK:11,SNR1: 6.8451 ,SNR2: 10.450




0411+05 2025/07/31 22.46UT FUJI -KISO




T20250801073232




BLK: 4,SNR1: 0.26601 ,SNR2: 1.0436




F20250801073232




BLK: 4,SNR1: 0.51082 ,SNR2: 2.0934




0418+236 2025/07/31 22.57UT TOYOKAWA-FUJI




T20250801073232




BLK: 6, SNR1: 0.13005 , SNR2: 0.72574




K20250801073231




BLK: 6, SNR1: 1.5971 , SNR2: 3.5588




0418+236 2025/07/31 22.57UT TOYOKAWA-KISO




F20250801073232




BLK: 8, SNR1: 0.62179 , SNR2: 2.3465




K20250801073231





BLK: 8, SNR1: 1.2874 , SNR2: 3.1271




0418+236 2025/07/31 22.57UT FUJI -KISO




T20250801074400




BLK:10,SNR1: 3.3978 ,SNR2: 10.412




F20250801074400











BLK:10,SNR1: 1.8391 ,SNR2: 4.4756




3C119 2025/07/31 22.76UT TOYOKAWA-FUJI













BLK: 6,SNR1: 4.0855 ,SNR2: 9.4674




BLK: 6,SNR1: 14.867 ,SNR2: 20.669





3C138 2025/07/31 23.56UT TOYOKAWA-FUJI









BLK: 5, SNR1: 6.8329 , SNR2: 15.320




BLK: 5, SNR1: 9.5513 , SNR2: 13.978





3C138 2025/07/31 23.56UT TOYOKAWA-KISO







BLK:10,SNR1: 13.565 ,SNR2: 15.238




BLK:10,SNR1: 4.6902 ,SNR2: 11.939




3C138 2025/07/31 23.56UT FUJI -KISO





T20250801084540




BLK:26,SNR1: 10.233 ,SNR2: 20.785




F20250801084540





BLK:26,SNR1: 12.674 ,SNR2: 28.534




0531+194 2025/07/31 23.79UT TOYOKAWA-FUJI





T20250801084540




BLK:18,SNR1: 10.494 ,SNR2: 16.031




K20250801084539












BLK:18,SNR1: 15.307 ,SNR2: 25.535




0531+194 2025/07/31 23.79UT TOYOKAWA-KISO













3C147 2025/07/31 23.93UT TOYOKAWA-FUJI







3C147 2025/07/31 23.93UT TOYOKAWA-KISO







BLK:25,SNR1:-0.71798E-01,SNR2: 1.8324



BLK:25,SNR1: 0.92035 ,SNR2: 4.5325





3C147 2025/07/31 23.93UT FUJI -KISO








T20250801090211




BLK: 5, SNR1: 0.22521 , SNR2: 1.9113




F20250801090211




BLK: 5, SNR1: 2.0649 , SNR2: 15.656




0548+16 2025/08/01 0.06UT TOYOKAWA-FUJI





T20250801090211




BLK:12,SNR1: -0.16214E-01,SNR2: 1.7462




K20250801090210




BLK:12,SNR1: 0.75602 ,SNR2: 2.1327




0548+16 2025/08/01 0.06UT TOYOKAWA-KISO




F20250801090211




BLK: 6, SNR1: 3.1201 , SNR2: 8.2998




K20250801090210







BLK: 6, SNR1: 0.55473 , SNR2: 2.4969








0548+16 2025/08/01 0.06UT FUJI -KISO






0552+12 2025/08/01 0.13UT TOYOKAWA-FUJI








0552+12 2025/08/01 0.13UT TOYOKAWA-KISO





F20250801090622




BLK:19,SNR1: 5.4519 ,SNR2: 12.983




K20250801090621





BLK:19,SNR1: 14.024 ,SNR2: 20.696




0552+12 2025/08/01 0.13UT FUJI -KISO



T20250801091049




BLK: 3,SNR1: 0.88745E-01,SNR2: 1.4854





0556+191 2025/08/01 0.21UT TOYOKAWA-FUJI


F20250801091049




BLK: 3,SNR1: 2.0330 ,SNR2: 5.9291




T20250801091049




BLK:15,SNR1: 0.26177 ,SNR2: 0.75507




K20250801091048








BLK:15,SNR1: 1.5751 ,SNR2: 3.1907





0556+191 2025/08/01 0.21UT TOYOKAWA-KISO









T20250801091521




BLK:12,SNR1: 1.1909 ,SNR2: 2.8790




F20250801091521





BLK:12,SNR1: 0.37531 ,SNR2: 1.9094




3C152 2025/08/01 0.28UT TOYOKAWA-FUJI





T20250801091521




BLK:10,SNR1: 4.1451 ,SNR2: 6.4904




K20250801091520




BLK:10,SNR1: 1.3843 ,SNR2: 2.4173




3C152 2025/08/01 0.28UT TOYOKAWA-KISO





F20250801091521




BLK: 8,SNR1: 0.33913 ,SNR2: 2.0287




K20250801091520




BLK: 8,SNR1: 8.9477 ,SNR2: 11.804




3C152 2025/08/01 0.28UT FUJI -KISO




T20250801093742




BLK:16,SNR1: 2.1523 ,SNR2: 4.1440




F20250801093742




BLK:16,SNR1: 0.14068 ,SNR2: 2.4668




3C161 2025/08/01 0.66UT TOYOKAWA-FUJI





T20250801093742




BLK:25,SNR1: 1.6681 ,SNR2: 3.0417




K20250801093741




BLK:25,SNR1: 2.1781 ,SNR2: 3.1419





3C161 2025/08/01 0.66UT TOYOKAWA-KISO







BLK:16,SNR1: 0.74795E-01,SNR2: 2.1669





BLK:16,SNR1: 3.6712 ,SNR2: 5.1308




3C161 2025/08/01 0.66UT FUJI -KISO





T20250801100515




BLK:10,SNR1: 42.225 ,SNR2: 57.145




F20250801100515



BLK:10,SNR1: 43.420 ,SNR2: 48.425





0652-130 2025/08/01 1.12UT TOYOKAWA-FUJI








T20250801100515




BLK:10,SNR1: 47.482 ,SNR2: 65.131




K20250801100514





BLK:10,SNR1: 4.5609 ,SNR2: 11.588




0652-130 2025/08/01 1.12UT TOYOKAWA-KISO





F20250801100515




BLK:11,SNR1: 4.7854 ,SNR2: 13.571




K20250801100514





BLK:11,SNR1: 5.9622 ,SNR2: 10.801




0652-130 2025/08/01 1.12UT FUJI -KISO





T20250801101652




BLK: 9, SNR1: 0.65396 , SNR2: 2.3225




F20250801101652





BLK: 9, SNR1: 6.6601 , SNR2: 11.370




0703+138 2025/08/01 1.31UT TOYOKAWA-FUJI




T20250801101652




BLK:18,SNR1: 0.50883 ,SNR2: 1.7923




K20250801101651





BLK:18,SNR1: 4.4790 ,SNR2: 6.8870




0703+138 2025/08/01 1.31UT TOYOKAWA-KISO




F20250801101652




BLK:10,SNR1: 6.4487 ,SNR2: 14.521




K20250801101651





BLK:10,SNR1: 8.8835 ,SNR2: 12.660




0703+138 2025/08/01 1.31UT FUJI -KISO





T20250801102614




BLK: 8,SNR1:-0.66551E-01,SNR2: 0.44163




F20250801102614





BLK: 8,SNR1: 1.4994 ,SNR2: 4.5525




0713-024 2025/08/01 1.47UT TOYOKAWA-FUJI




T20250801102614




BLK: 5, SNR1: 3.5863 , SNR2: 10.792




K20250801102613





BLK: 5, SNR1: 3.4931 , SNR2: 5.3085




0713-024 2025/08/01 1.47UT TOYOKAWA-KISO





F20250801102614




BLK: 5, SNR1: 0.89560 , SNR2: 3.1094




K20250801102613



BLK: 5, SNR1: 3.8749 , SNR2: 5.8666




0713-024 2025/08/01 1.47UT FUJI -KISO







T20250801103626




BLK:19,SNR1: 1.1237 ,SNR2: 3.9209




F20250801103626




BLK:19,SNR1: 5.6327 ,SNR2: 7.3349




0723+10 2025/08/01 1.64UT TOYOKAWA-FUJI





T20250801103626




BLK:10,SNR1: 0.72566 ,SNR2: 4.3286




K20250801103625




BLK:10,SNR1: 0.12443 ,SNR2: 1.2503




0723+10 2025/08/01 1.64UT TOYOKAWA-KISO




F20250801103626




BLK: 9, SNR1: 10.386 , SNR2: 15.845




K20250801103625





BLK: 9, SNR1: 0.13464 , SNR2: 1.6194




0723+10 2025/08/01 1.64UT FUJI -KISO




T20250801104641




BLK: 9,SNR1: 0.38349 ,SNR2: 3.0428




F20250801104641




BLK: 9,SNR1: 1.7022 ,SNR2: 2.6277





0732+33 2025/08/01 1.81UT TOYOKAWA-FUJI







BLK:11,SNR1: 0.34586 ,SNR2: 1.4496





BLK:11,SNR1: 6.9479 ,SNR2: 15.798




0732+33 2025/08/01 1.81UT TOYOKAWA-KISO





F20250801104641




BLK:12,SNR1: 3.0830 ,SNR2: 3.6859




K20250801104640




BLK:12,SNR1: 2.4633 ,SNR2: 7.8320




0732+33 2025/08/01 1.81UT FUJI -KISO




T20250801105442




BLK:15,SNR1: 0.82856 ,SNR2: 2.6043




F20250801105442






BLK:15,SNR1:-0.16067 ,SNR2: 1.6072






0741-06 2025/08/01 1.94UT TOYOKAWA-FUJI












T20250801110426




BLK: 8,SNR1: 0.28473 ,SNR2: 2.2526








0752-200 2025/08/01 2.10UT TOYOKAWA-FUJI




F20250801110426





BLK: 8,SNR1: 1.0501 ,SNR2: 2.9580










T20250801111202




BLK:15,SNR1: 0.78538 ,SNR2: 6.8982




F20250801111202









BLK:15,SNR1: 3.3815 ,SNR2: 5.3487




3C190 2025/08/01 2.23UT TOYOKAWA-FUJI










T20250801112427




BLK:15,SNR1: 0.43420 ,SNR2: 2.2486




F20250801112427






BLK:15,SNR1: 5.3312 ,SNR2: 15.115






3C196 2025/08/01 2.44UT TOYOKAWA-FUJI














T20250801113537




BLK:14,SNR1: 0.39054 ,SNR2: 3.5173




F20250801113537









BLK:14,SNR1: 5.1323 ,SNR2: 12.879




0821+394 2025/08/01 2.62UT TOYOKAWA-FUJI













BLK:10,SNR1: 0.46549 ,SNR2: 1.5501









BLK:10,SNR1: 6.1477 ,SNR2: 17.126



0834-19 2025/08/01 2.82UT TOYOKAWA-FUJI













T20250801115221




BLK: 6,SNR1: 0.81648 ,SNR2: 3.4097




F20250801115221





BLK: 6,SNR1: 0.26249 ,SNR2: 2.9135






0839-071 2025/08/01 2.90UT TOYOKAWA-FUJI






0839-071 2025/08/01 2.90UT TOYOKAWA-KISO








0839-071 2025/08/01 2.90UT FUJI -KISO





T20250801120322




BLK:11,SNR1: 0.38217 ,SNR2: 2.1362




F20250801120322









BLK:11,SNR1: 0.56724 ,SNR2: 3.2224











3C208 2025/08/01 3.08UT TOYOKAWA-FUJI






















T20250801123215




BLK: 6,SNR1: 0.16537 ,SNR2: 0.44075




F20250801123215





BLK: 6,SNR1: 0.22305 ,SNR2: 1.6607






0919-142 2025/08/01 3.57UT TOYOKAWA-FUJI







0919-142 2025/08/01 3.57UT TOYOKAWA-KISO







0919-142 2025/08/01 3.57UT FUJI -KISO







BLK: 7,SNR1: 0.33750 ,SNR2: 2.9977





BLK: 7,SNR1: 1.5838 ,SNR2: 4.1726






0926+117 2025/08/01 3.68UT TOYOKAWA-FUJI






0926+117 2025/08/01 3.68UT TOYOKAWA-KISO







0926+117 2025/08/01 3.68UT FUJI -KISO




T20250801124639




BLK:10,SNR1: 1.2559 ,SNR2: 4.9130




F20250801124639






BLK:10,SNR1:-0.10630 ,SNR2: 1.5014








3C222 2025/08/01 3.81UT TOYOKAWA-FUJI


















0941-08 2025/08/01 3.92UT TOYOKAWA-FUJI








0941-08 2025/08/01 3.92UT TOYOKAWA-KISO









BLK:10,SNR1: 9.1308 ,SNR2: 16.356









BLK:10,SNR1: 8.0367 ,SNR2: 18.599



3C230 2025/08/01 4.06UT TOYOKAWA-FUJI













T20250801131608




BLK:11,SNR1: 1.8338 ,SNR2: 4.1785




F20250801131608









BLK:11,SNR1: 2.2892 ,SNR2: 5.4718





3C236 2025/08/01 4.30UT TOYOKAWA-FUJI










T20250801132418




BLK: 7,SNR1: 0.10208 ,SNR2: 0.85937




F20250801132418




BLK: 7,SNR1: 0.31418 ,SNR2: 2.0936




1011+110 2025/08/01 4.43UT TOYOKAWA-FUJI





T20250801132418




BLK: 6,SNR1: 0.14806 ,SNR2: 0.61228




K20250801132417





BLK: 6,SNR1: 2.4226 ,SNR2: 9.8956




1011+110 2025/08/01 4.43UT TOYOKAWA-KISO





F20250801132418




BLK: 8,SNR1: 5.6092 ,SNR2: 9.0803




K20250801132417









BLK: 8,SNR1: 4.8533 ,SNR2: 6.2307





1011+110 2025/08/01 4.43UT FUJI -KISO









BLK:19,SNR1: 0.66341 ,SNR2: 2.2910



BLK:19,SNR1: 0.37641 ,SNR2: 1.1945




3C241 2025/08/01 4.56UT TOYOKAWA-KISO







F20250801133159




BLK: 6,SNR1: 0.52061 ,SNR2: 2.5219




K20250801133158





BLK: 6,SNR1: 0.55534 ,SNR2: 4.8287




3C241 2025/08/01 4.56UT FUJI -KISO





T20250801134328




BLK: 2,SNR1: 6.1205 ,SNR2: 20.530




F20250801134328





BLK: 2,SNR1: 7.4969 ,SNR2: 19.811




1031-11 2025/08/01 4.75UT TOYOKAWA-FUJI





T20250801134328




BLK: 1,SNR1: 10.475 ,SNR2: 26.029




K20250801134327





BLK: 1,SNR1: 12.470 ,SNR2: 30.409




1031-11 2025/08/01 4.75UT TOYOKAWA-KISO





F20250801134328




BLK: 2,SNR1: 21.548 ,SNR2: 38.607




K20250801134327




BLK: 2,SNR1: 12.450 ,SNR2: 30.361





1031-11 2025/08/01 4.75UT FUJI -KISO







BLK: 8,SNR1: 16.800 ,SNR2: 39.482





BLK: 8,SNR1: 17.428 ,SNR2: 31.551




1035-058 2025/08/01 4.83UT TOYOKAWA-FUJI




T20250801134801




BLK:10,SNR1: 9.5935 ,SNR2: 17.130




K20250801134800




BLK:10,SNR1: 8.1634 ,SNR2: 14.297





1035-058 2025/08/01 4.83UT TOYOKAWA-KISO







BLK:12,SNR1: 9.6571 ,SNR2: 17.112





BLK:12,SNR1: 9.1885 ,SNR2: 16.198




1035-058 2025/08/01 4.83UT FUJI -KISO





T20250801135714




BLK:24,SNR1: 7.4058 ,SNR2: 20.017




F20250801135714



BLK:24,SNR1: 22.949 ,SNR2: 26.622





1044-008 2025/08/01 4.98UT TOYOKAWA-FUJI








T20250801135714




BLK:24,SNR1: 7.5710 ,SNR2: 20.490




K20250801135713





BLK:24,SNR1: 8.5424 ,SNR2: 24.848




1044-008 2025/08/01 4.98UT TOYOKAWA-KISO



F20250801135714





BLK:29,SNR1: 21.161 ,SNR2: 27.025




Frequency (Hz)

K20250801135713




BLK:29,SNR1: 8.5267 ,SNR2: 24.801




Frequency (Hz)


1044-008 2025/08/01 4.98UT FUJI -KISO




T20250801140818




BLK: 2,SNR1: 16.018 ,SNR2: 19.607




F20250801140818




BLK: 2,SNR1: 3.7114 ,SNR2: 15.660




1055+01 2025/08/01 5.17UT TOYOKAWA-FUJI




T20250801140818




BLK: 1,SNR1: 3.9097 ,SNR2: 12.153




K20250801140817




BLK: 1,SNR1: 3.3963 ,SNR2: 10.589




1055+01 2025/08/01 5.17UT TOYOKAWA-KISO




F20250801140818




BLK: 4,SNR1: 15.571 ,SNR2: 19.619




K20250801140817




BLK: 4,SNR1: 4.3723 ,SNR2: 16.012





1055+01 2025/08/01 5.17UT FUJI -KISO







BLK: 1,SNR1: 7.1501 ,SNR2: 17.629




BLK: 1,SNR1: 8.7230 ,SNR2: 21.670





1107+109 2025/08/01 5.35UT TOYOKAWA-FUJI







BLK: 3,SNR1: 10.946 ,SNR2: 26.816




BLK: 3,SNR1: 8.1243 ,SNR2: 20.605





1107+109 2025/08/01 5.35UT TOYOKAWA-KISO







BLK: 2,SNR1: 3.1023 ,SNR2: 13.907



BLK: 2,SNR1: 7.7092 ,SNR2: 19.125





1107+109 2025/08/01 5.35UT FUJI -KISO







T20250801142913




BLK: 2,SNR1: 4.1346 ,SNR2: 16.928




F20250801142913





BLK: 2,SNR1: 3.2936 ,SNR2: 13.295




3C255 2025/08/01 5.52UT TOYOKAWA-FUJI





T20250801142913




BLK: 1,SNR1: 7.1213 ,SNR2: 27.390




K20250801142912





BLK: 1,SNR1: 3.8401 ,SNR2: 15.605






3C255 2025/08/01 5.52UT TOYOKAWA-KISO




F20250801142913





K20250801142912







BLK: 2,SNR1: 18.166 ,SNR2: 31.763




BLK: 2,SNR1: 8.7127 ,SNR2: 21.503





1127-14 2025/08/01 5.69UT TOYOKAWA-FUJI







BLK: 2,SNR1: 17.592 ,SNR2: 30.779





BLK: 2,SNR1: 12.295 ,SNR2: 22.760




1127-14 2025/08/01 5.69UT TOYOKAWA-KISO





F20250801143951




BLK: 1,SNR1: 0.14171 ,SNR2: 1.7937




K20250801143950




BLK: 1,SNR1: 9.0157 ,SNR2: 16.362





1127-14 2025/08/01 5.69UT FUJI -KISO







BLK: 2,SNR1: 13.938 ,SNR2: 24.764




BLK: 2,SNR1: 9.7963 ,SNR2: 24.011





3C263.1 2025/08/01 5.91UT TOYOKAWA-FUJI







BLK: 3,SNR1: 9.3976 ,SNR2: 23.449




BLK: 3,SNR1: 17.660 ,SNR2: 31.194





3C263.1 2025/08/01 5.91UT TOYOKAWA-KISO









BLK: 2,SNR1: 1.8896 ,SNR2: 9.3936




BLK: 2,SNR1: 2.0401 ,SNR2: 9.8678




3C263.1 2025/08/01 5.91UT FUJI -KISO



T20250801145938





BLK: 8, SNR1: 8.4961, SNR2: 18.391




Frequency (Hz)

F20250801145938





BLK: 8, SNR1: 14.633, SNR2: 21.686





Frequency (Hz)

3C267 2025/08/01 6.02UT TOYOKAWA-FUJI







BLK:10,SNR1: 8.5828 ,SNR2: 15.146




BLK:10,SNR1: 19.867 ,SNR2: 25.685





3C267 2025/08/01 6.02UT TOYOKAWA-KISO









BLK:10,SNR1: 10.297 ,SNR2: 13.790




BLK:10,SNR1: 8.7817 ,SNR2: 17.199



T20250801152526





BLK: 2, SNR1: 1.6396 , SNR2: 4.3085




Frequency (Hz)

F20250801152526




BLK: 2, SNR1: 0.34840 , SNR2: 3.1328




Frequency (Hz)


1213-17 2025/08/01 6.45UT TOYOKAWA-FUJI





T20250801152526




BLK: 2,SNR1: 1.4583 ,SNR2: 3.8443




K20250801152525




BLK: 2,SNR1: 1.4153 ,SNR2: 5.0213




1213-17 2025/08/01 6.45UT TOYOKAWA-KISO





F20250801152526




BLK: 2,SNR1: 0.34840 ,SNR2: 3.1328




K20250801152525




BLK: 2,SNR1: 5.4434 ,SNR2: 13.540





1213-17 2025/08/01 6.45UT FUJI -KISO







BLK:25,SNR1: 2.8631 ,SNR2: 7.6957




BLK:25,SNR1: 4.6516 ,SNR2: 13.634





3C273 2025/08/01 6.67UT TOYOKAWA-FUJI









BLK:24,SNR1: 2.4172 ,SNR2: 6.3210




BLK:24,SNR1: 18.710 ,SNR2: 35.718




3C273 2025/08/01 6.67UT TOYOKAWA-KISO




F20250801153843




BLK:30,SNR1: 5.4810 ,SNR2: 13.321




K20250801153842




BLK:30,SNR1: 13.199 ,SNR2: 32.167





3C273 2025/08/01 6.67UT FUJI -KISO







BLK: 5,SNR1: 8.3697 ,SNR2: 11.448




BLK: 5,SNR1: 8.7169 ,SNR2: 16.381





3C275 2025/08/01 6.89UT TOYOKAWA-FUJI







BLK: 3,SNR1: 5.0118 ,SNR2: 9.6697










BLK: 3,SNR1: 5.6773 ,SNR2: 11.173




3C275 2025/08/01 6.89UT TOYOKAWA-KISO









1245-19 2025/08/01 6.99UT TOYOKAWA-FUJI



T20250801155759





BLK: 1,SNR1: 9.2332 ,SNR2: 25.201




Frequency (Hz)

K20250801155758







BLK: 1,SNR1: 4.8290 ,SNR2: 16.417








Frequency (Hz)





1245-19 2025/08/01 6.99UT TOYOKAWA-KISO















3C279 2025/08/01 7.12UT TOYOKAWA-KISO







BLK:13,SNR1: 4.6151 ,SNR2: 9.9695




BLK:13,SNR1: 10.770 ,SNR2: 19.212





3C279 2025/08/01 7.12UT FUJI -KISO







BLK: 5,SNR1: 0.29443 ,SNR2: 1.1838





BLK: 5,SNR1: 2.9508 ,SNR2: 6.4289




3C283 2025/08/01 7.38UT TOYOKAWA-FUJI



T20250801162112





BLK: 1,SNR1:-0.71431E-01,SNR2: 0.31590




Frequency (Hz)

3C283 2025/08/01 7.38UT TOYOKAWA-KISO


K20250801162111




BLK: 1,SNR1: 1.2031 ,SNR2: 6.6889





Frequency (Hz)








BLK: 2,SNR1: 0.16137 ,SNR2: 2.3377





BLK: 2,SNR1: 2.1640 ,SNR2: 4.5835







BLK:14,SNR1: 2.4055 ,SNR2: 7.8041







BLK:14,SNR1: 6.3639 ,SNR2: 14.667




1323+32 2025/08/01 7.62UT TOYOKAWA-FUJI








1323+32 2025/08/01 7.62UT TOYOKAWA-KISO














BLK:19,SNR1: 8.2833 ,SNR2: 18.350





BLK:19,SNR1: 6.6681 ,SNR2: 17.887






T20250801164027





BLK:10,SNR1: 1.6835 ,SNR2: 2.7211




Frequency (Hz)

3C286 2025/08/01 7.70UT TOYOKAWA-KISO


K20250801164026





BLK:10,SNR1: 2.5933 ,SNR2: 5.1104




Frequency (Hz)



F20250801164027





BLK: 9, SNR1: 1.7266 , SNR2: 4.3756




Frequency (Hz)

K20250801164026





BLK: 9, SNR1: 5.4339 , SNR2: 9.6138





Frequency (Hz)

3C286 2025/08/01 7.70UT FUJI -KISO







BLK: 3,SNR1: 0.34112 ,SNR2: 0.76085




BLK: 3,SNR1:-0.59777E-01,SNR2: 3.9313





1345+12 2025/08/01 7.98UT TOYOKAWA-FUJI







BLK: 8,SNR1: 0.17167 ,SNR2: 0.74103












BLK: 8,SNR1: 3.6942 ,SNR2: 9.7850




1345+12 2025/08/01 7.98UT TOYOKAWA-KISO










1355+01 2025/08/01 8.15UT TOYOKAWA-FUJI









BLK: 1,SNR1:-0.61695E-01,SNR2: 1.8155





BLK: 1,SNR1: 1.1830 ,SNR2: 11.316




1355+01 2025/08/01 8.15UT TOYOKAWA-KISO



F20250801170715





BLK: 4, SNR1: -0.16420, SNR2: 1.2781




Frequency (Hz)

K20250801170714




BLK: 4, SNR1: -0.19738E-01, SNR2: 1.5456





Frequency (Hz)


1355+01 2025/08/01 8.15UT FUJI -KISO



T20250801180253





BLK:11,SNR1: 0.14973 ,SNR2: 0.44112




Frequency (Hz)

F20250801180253






BLK:11,SNR1: 19.816 ,SNR2: 43.401



Frequency (Hz)

1452+502 2025/08/01 9.08UT TOYOKAWA-FUJI





1452+502 2025/08/01 9.08UT TOYOKAWA-KISO

