






T20250802060913




BLK: 9, SNR1: 1.0095 , SNR2: 2.9525




F20250802060913









BLK: 9, SNR1: 1.2784 , SNR2: 4.5436






0258+350 2025/08/01 21.18UT TOYOKAWA-FUJI













































BLK: 7,SNR1: 12.438 ,SNR2: 42.847









BLK: 7,SNR1: 2.2849 ,SNR2: 6.8798



0324+119 2025/08/01 21.61UT TOYOKAWA-FUJI












T20250802064355





BLK: 1,SNR1:-0.12797 ,SNR2: 0.28785




Frequency (Hz)

F20250802064355






BLK: 1,SNR1:-0.18533 ,SNR2: 1.0551




Frequency (Hz)




0333+32 2025/08/01 21.76UT TOYOKAWA-FUJI







0333+32 2025/08/01 21.76UT TOYOKAWA-KISO







T20250802065657




BLK: 1,SNR1: 0.16260 ,SNR2: 0.24620




F20250802065657









BLK: 1,SNR1: 0.39917 ,SNR2: 4.0848











0347+05 2025/08/01 21.98UT TOYOKAWA-FUJI






















T20250802072142




BLK: 4,SNR1: 0.44176 ,SNR2: 1.3865




F20250802072142









BLK: 4,SNR1: 0.88150 ,SNR2: 2.8259





0411+05 2025/08/01 22.39UT TOYOKAWA-FUJI









T20250802072836




BLK: 2,SNR1: 0.15283 ,SNR2: 0.62791




F20250802072836









BLK: 2,SNR1: 1.0725 ,SNR2: 3.5397





0418+236 2025/08/01 22.50UT TOYOKAWA-FUJI










T20250802074004




BLK: 8,SNR1: 0.18182 ,SNR2: 3.1326




F20250802074004






BLK: 8,SNR1: 0.81532 ,SNR2: 3.1912






3C119 2025/08/01 22.70UT TOYOKAWA-FUJI













T20250802082811




BLK:11,SNR1: 0.84058 ,SNR2: 3.3962




F20250802082811









BLK:11,SNR1: 0.18832E-01,SNR2: 2.2109




3C138 2025/08/01 23.50UT TOYOKAWA-FUJI










T20250802084144




BLK:15,SNR1: 6.6757 ,SNR2: 8.7692




F20250802084144









BLK:15,SNR1: 3.3944 ,SNR2: 6.9837



0531+194 2025/08/01 23.72UT TOYOKAWA-FUJI












T20250802085005




BLK:16,SNR1: 2.9993 ,SNR2: 15.101




F20250802085005









BLK:16,SNR1: 0.19234 ,SNR2: 1.2454





3C147 2025/08/01 23.86UT TOYOKAWA-FUJI








T20250802090226





BLK:18,SNR1: 9.9348 ,SNR2: 21.454








0552+12 2025/08/02 0.07UT TOYOKAWA-FUJI




F20250802090226




BLK:18,SNR1: 8.1299 ,SNR2: 16.838









T20250802090653




BLK:19,SNR1: 55.187 ,SNR2: 56.868




F20250802090653





BLK:19,SNR1: 22.910 ,SNR2: 35.665




0556+191 2025/08/02 0.14UT TOYOKAWA-FUJI










0556+191 2025/08/02 0.14UT TOYOKAWA-KISO










T20250802091125




BLK: 7,SNR1: 0.80099E-01,SNR2: 1.2946




F20250802091125









BLK: 7,SNR1: 3.9266 ,SNR2: 15.710







3C152 2025/08/02 0.22UT TOYOKAWA-FUJI


















3C161 2025/08/02 0.59UT TOYOKAWA-FUJI










T20250802100119




BLK:11,SNR1: 0.67949 ,SNR2: 1.2805




F20250802100119






BLK:11,SNR1: 1.6434 ,SNR2: 11.774






0652-130 2025/08/02 1.05UT TOYOKAWA-FUJI













T20250802101256




BLK: 8, SNR1: 0.73138 , SNR2: 8.4537




F20250802101256





BLK: 8, SNR1: 7.0215 , SNR2: 9.8745







0703+138 2025/08/02 1.24UT TOYOKAWA-FUJI







0703+138 2025/08/02 1.24UT TOYOKAWA-KISO






T20250802102218





BLK: 5, SNR1: 0.20410 , SNR2: 0.62267








0713-024 2025/08/02 1.40UT TOYOKAWA-FUJI




F20250802102218



BLK: 5, SNR1: 1.6835 , SNR2: 5.6661













T20250802103230




BLK: 9,SNR1: 0.48153 ,SNR2: 5.2975




F20250802103230









BLK: 9,SNR1: 0.44619 ,SNR2: 4.3584





0723+10 2025/08/02 1.57UT TOYOKAWA-FUJI










T20250802104245




BLK:10,SNR1: 0.22946 ,SNR2: 3.0030




F20250802104245





BLK:10,SNR1: 2.3483 ,SNR2: 8.6221







0732+33 2025/08/02 1.74UT TOYOKAWA-FUJI






0732+33 2025/08/02 1.74UT TOYOKAWA-KISO







T20250802105046




BLK:16,SNR1: 0.99385 ,SNR2: 6.2811




F20250802105046





BLK:16,SNR1: 0.65169 ,SNR2: 3.9159




0741-06 2025/08/02 1.87UT TOYOKAWA-FUJI










0741-06 2025/08/02 1.87UT TOYOKAWA-KISO









T20250802110030




BLK: 5, SNR1: 0.11771 , SNR2: 2.8582




F20250802110030









BLK: 5, SNR1: 0.59575 , SNR2: 3.0637











0752-200 2025/08/02 2.04UT TOYOKAWA-FUJI



















T20250802112031




BLK:12,SNR1: 0.45223 ,SNR2: 0.95014




F20250802112031






BLK:12,SNR1: 0.38515 ,SNR2: 1.6299






3C196 2025/08/02 2.37UT TOYOKAWA-FUJI














T20250802113141




BLK:11,SNR1: 0.18959 ,SNR2: 0.87563




F20250802113141





BLK:11,SNR1: 0.30318 ,SNR2: 2.5535







0821+394 2025/08/02 2.56UT TOYOKAWA-FUJI








0821+394 2025/08/02 2.56UT TOYOKAWA-KISO









BLK: 8,SNR1: 4.0263 ,SNR2: 7.0645








BLK: 8,SNR1: 4.8767 ,SNR2: 11.216




0834-19 2025/08/02 2.75UT TOYOKAWA-FUJI









0834-19 2025/08/02 2.75UT FUJI -KISO







T20250802114825




BLK: 8,SNR1: 3.2422 ,SNR2: 3.0261




F20250802114825





BLK: 8,SNR1: 0.72489 ,SNR2: 1.6043







0839-071 2025/08/02 2.84UT TOYOKAWA-FUJI








0839-071 2025/08/02 2.84UT TOYOKAWA-KISO









BLK:26,SNR1: 33.556 ,SNR2: 68.143









BLK:26,SNR1: 5.1821 ,SNR2: 10.499





3C208 2025/08/02 3.02UT TOYOKAWA-FUJI








T20250802121608





BLK:18,SNR1: 0.41169 ,SNR2: 1.6064




Frequency (Hz)

F20250802121608







BLK:18,SNR1: 3.0297 ,SNR2: 8.9998






Frequency (Hz)

3C216 2025/08/02 3.30UT TOYOKAWA-FUJI













T20250802122819




BLK: 8,SNR1: 0.13677 ,SNR2: 1.6105




F20250802122819









BLK: 8,SNR1:-0.25470 ,SNR2: 0.97856




0919-142 2025/08/02 3.50UT TOYOKAWA-FUJI













BLK:17,SNR1: 8.7273 ,SNR2: 15.236









BLK:17,SNR1: 9.3944 ,SNR2: 16.094





0926+117 2025/08/02 3.61UT TOYOKAWA-FUJI









T20250802124243




BLK: 6,SNR1: 0.90057 ,SNR2: 5.7358




F20250802124243






BLK: 6,SNR1: 1.1789 ,SNR2: 4.4507






3C222 2025/08/02 3.74UT TOYOKAWA-FUJI













T20250802124943




BLK: 5,SNR1: 0.57282E-01,SNR2: 0.88455




F20250802124943









BLK: 5,SNR1: 0.43588 ,SNR2: 2.0321










0941-08 2025/08/02 3.86UT TOYOKAWA-FUJI
















3C230 2025/08/02 4.00UT TOYOKAWA-KISO













BLK: 8,SNR1: 0.67322 ,SNR2: 3.2424









BLK: 8,SNR1: 0.40182 ,SNR2: 2.0126





3C236 2025/08/02 4.23UT TOYOKAWA-FUJI










T20250802132022




BLK: 2,SNR1: 16.663 ,SNR2: 38.703




F20250802132022









BLK: 2,SNR1: 14.274 ,SNR2: 26.429





1011+110 2025/08/02 4.37UT TOYOKAWA-FUJI










T20250802132803




BLK:10,SNR1: 1.2672 ,SNR2: 4.5375




F20250802132803






BLK:10,SNR1: 15.968 ,SNR2: 21.161







3C241 2025/08/02 4.50UT TOYOKAWA-FUJI















BLK: 1,SNR1: 17.158 ,SNR2: 37.898





BLK: 1,SNR1: 0.95284 ,SNR2: 6.9925







1031-11 2025/08/02 4.69UT TOYOKAWA-FUJI








1031-11 2025/08/02 4.69UT TOYOKAWA-KISO









BLK: 7,SNR1: 0.37436 ,SNR2: 1.6548





BLK: 7,SNR1: 3.2975 ,SNR2: 9.7512







1035-058 2025/08/02 4.76UT TOYOKAWA-FUJI








1035-058 2025/08/02 4.76UT TOYOKAWA-KISO









BLK: 1,SNR1: 2.4401 ,SNR2: 11.243





BLK: 1,SNR1: 6.8932 ,SNR2: 17.142




1044-008 2025/08/02 4.92UT TOYOKAWA-FUJI













1044-008 2025/08/02 4.92UT TOYOKAWA-KISO









BLK:27,SNR1: 7.9546 ,SNR2: 23.384









BLK:27,SNR1: 7.3506 ,SNR2: 21.246




1055+01 2025/08/02 5.10UT TOYOKAWA-FUJI













BLK: 3,SNR1: 3.7891 ,SNR2: 15.646





BLK: 3,SNR1: 3.8342 ,SNR2: 15.875







1107+109 2025/08/02 5.29UT TOYOKAWA-FUJI







1107+109 2025/08/02 5.29UT TOYOKAWA-KISO









T20250802142517




BLK: 6,SNR1: 7.9290 ,SNR2: 19.883




F20250802142517









BLK: 6,SNR1: 17.108 ,SNR2: 25.381




3C255 2025/08/02 5.45UT TOYOKAWA-FUJI













BLK: 8,SNR1: 15.459 ,SNR2: 21.923





BLK: 8,SNR1: 5.0173 ,SNR2: 13.684







1127-14 2025/08/02 5.63UT TOYOKAWA-FUJI








1127-14 2025/08/02 5.63UT TOYOKAWA-KISO









BLK: 2,SNR1: 9.7311 ,SNR2: 28.318






BLK: 2,SNR1: 9.4197 ,SNR2: 15.567






3C263.1 2025/08/02 5.85UT TOYOKAWA-FUJI












T20250802145542




BLK: 8,SNR1: 8.2781 ,SNR2: 14.615




F20250802145542









BLK: 8,SNR1: 6.1905 ,SNR2: 11.406




3C267 2025/08/02 5.96UT TOYOKAWA-FUJI













BLK: 7,SNR1: 16.150 ,SNR2: 21.189









BLK: 7,SNR1: 18.633 ,SNR2: 31.648




1213-17 2025/08/02 6.39UT TOYOKAWA-FUJI













BLK: 6,SNR1: 0.82547 ,SNR2: 3.1436






BLK: 6,SNR1: 4.9260 ,SNR2: 11.015







3C273 2025/08/02 6.61UT TOYOKAWA-FUJI















BLK: 9,SNR1: 0.93751 ,SNR2: 2.4373









BLK: 9,SNR1: 0.62702 ,SNR2: 0.61806





3C275 2025/08/02 6.83UT TOYOKAWA-FUJI








T20250802155403





BLK: 4,SNR1: 0.16893 ,SNR2: 0.94148




Frequency (Hz)

F20250802155403







BLK: 4,SNR1: 17.003 ,SNR2: 23.678






Frequency (Hz)

1245-19 2025/08/02 6.93UT TOYOKAWA-FUJI












T20250802160147





BLK: 6,SNR1: 1.5776 ,SNR2: 3.5191




Frequency (Hz)

F20250802160147







BLK: 6,SNR1:-0.19118 ,SNR2: 0.93567











Frequency (Hz)




3C279 2025/08/02 7.06UT TOYOKAWA-FUJI























BLK: 5, SNR1: 0.19654 , SNR2: 1.3393






BLK: 5, SNR1: 2.4674 , SNR2: 6.5200











1323+32 2025/08/02 7.56UT TOYOKAWA-FUJI




































1345+12 2025/08/02 7.91UT TOYOKAWA-FUJI








T20250802170319




BLK: 4,SNR1: 0.21306 ,SNR2: 1.5871




Frequency (Hz)

F20250802170319




BLK: 4,SNR1: 1.3045 ,SNR2: 2.7424








Frequency (Hz)

1355+01 2025/08/02 8.08UT TOYOKAWA-FUJI









1355+01 2025/08/02 8.08UT FUJI -KISO

