






T20250805063208




BLK: 7,SNR1: 0.33074 ,SNR2: 0.76319




F20250805063208









BLK: 7,SNR1: 1.1359 ,SNR2: 2.0019





0333+32 2025/08/04 21.56UT TOYOKAWA-FUJI









T20250805064509




BLK: 6,SNR1: 0.66371 ,SNR2: 2.1414




F20250805064509






BLK: 6,SNR1: 0.38049E-01,SNR2: 2.4227






0347+05 2025/08/04 21.78UT TOYOKAWA-FUJI













T20250805070043




BLK: 7,SNR1: 14.810 ,SNR2: 34.179




F20250805070043









BLK: 7,SNR1: 12.844 ,SNR2: 31.367







0403-132 2025/08/04 22.04UT TOYOKAWA-FUJI
















0411+05 2025/08/04 22.19UT TOYOKAWA-FUJI














T20250805071648




BLK: 7, SNR1: 2.0036 , SNR2: 5.2947




F20250805071648









BLK: 7, SNR1: 8.8386 , SNR2: 22.460





0418+236 2025/08/04 22.31UT TOYOKAWA-FUJI










T20250805072816




BLK: 6,SNR1: 0.36725 ,SNR2: 2.6366




F20250805072816









BLK: 6,SNR1: 0.99955 ,SNR2: 3.4666





3C119 2025/08/04 22.50UT TOYOKAWA-FUJI








T20250805081623





BLK:17,SNR1: 0.90448 ,SNR2: 2.7513








3C138 2025/08/04 23.30UT TOYOKAWA-FUJI

F20250805081623






BLK:17,SNR1: 2.1259 ,SNR2: 6.7079














T20250805082956




BLK:18,SNR1: 0.62129 ,SNR2: 2.2013




F20250805082956





BLK:18,SNR1: 2.1659 ,SNR2: 6.4329







0531+194 2025/08/04 23.53UT TOYOKAWA-FUJI






0531+194 2025/08/04 23.53UT TOYOKAWA-KISO







T20250805083817




BLK:20,SNR1: 2.5936 ,SNR2: 18.470




F20250805083817









BLK:20,SNR1:-0.14048 ,SNR2: 2.2440




3C147 2025/08/04 23.67UT TOYOKAWA-FUJI













BLK: 8,SNR1: 0.22214 ,SNR2: 0.54853






BLK: 8,SNR1: 1.0329 ,SNR2: 3.1950







0548+16 2025/08/04 23.80UT TOYOKAWA-FUJI















BLK: 7,SNR1: 4.9867 ,SNR2: 68.291









BLK: 7,SNR1: 15.286 ,SNR2: 24.317




0552+12 2025/08/04 23.87UT TOYOKAWA-FUJI









T20250805092158




BLK:15,SNR1: 0.55152 ,SNR2: 7.1558




F20250805092158









BLK:15,SNR1:-0.17133 ,SNR2: 1.4630



3C161 2025/08/05 0.39UT TOYOKAWA-FUJI












T20250805094931




BLK: 7, SNR1: 0.18502 , SNR2: 1.6717




F20250805094931









BLK: 7, SNR1: 1.0383 , SNR2: 3.2577







0652-130 2025/08/05 0.85UT TOYOKAWA-FUJI


















0703+138 2025/08/05 1.05UT TOYOKAWA-FUJI









T20250805101030




BLK: 5, SNR1: 0.27119 , SNR2: 1.1600




F20250805101030






BLK: 5, SNR1: 0.16925 , SNR2: 2.2283






0713-024 2025/08/05 1.20UT TOYOKAWA-FUJI













T20250805102042




BLK:10,SNR1: 0.11288 ,SNR2: 2.1916




F20250805102042









BLK:10,SNR1: 0.20370 ,SNR2: 2.3840




0723+10 2025/08/05 1.37UT TOYOKAWA-FUJI








T20250805103058





BLK:10,SNR1: 0.19081 ,SNR2: 1.7923




Frequency (Hz)

F20250805103058







BLK:10,SNR1: 0.10599 ,SNR2: 0.44181






Frequency (Hz)


0732+33 2025/08/05 1.54UT TOYOKAWA-FUJI









T20250805103859




BLK:10,SNR1: 0.91059 ,SNR2: 2.7387




F20250805103859






BLK:10,SNR1: 5.3624 ,SNR2: 10.852






0741-06 2025/08/05 1.68UT TOYOKAWA-FUJI











T20250805104843




BLK:15,SNR1: 11.064 ,SNR2: 24.400








0752-200 2025/08/05 1.84UT TOYOKAWA-FUJI




F20250805104843





BLK:15,SNR1: 1.3456 ,SNR2: 4.9246









T20250805105618




BLK:16,SNR1: 0.61400 ,SNR2: 3.0725




F20250805105618









BLK:16,SNR1: 1.1186 ,SNR2: 2.8901



3C190 2025/08/05 1.97UT TOYOKAWA-FUJI












T20250805110844





BLK:13,SNR1: 16.535 ,SNR2: 85.978




Frequency (Hz)

F20250805110844







BLK:13,SNR1: 0.16959 ,SNR2: 9.1367






Frequency (Hz)



3C196 2025/08/05 2.17UT TOYOKAWA-FUJI










T20250805111953




BLK: 4,SNR1: 0.27752 ,SNR2: 3.6579




F20250805111953





BLK: 4,SNR1: 0.23742 ,SNR2: 1.4606







0821+394 2025/08/05 2.36UT TOYOKAWA-FUJI






0821+394 2025/08/05 2.36UT TOYOKAWA-KISO







T20250805113132




BLK: 4, SNR1: 3.1899 , SNR2: 8.6649




F20250805113132





BLK: 4, SNR1: 7.8584 , SNR2: 16.443




0834-19 2025/08/05 2.55UT TOYOKAWA-FUJI








0834-19 2025/08/05 2.55UT TOYOKAWA-KISO















0834-19 2025/08/05 2.55UT FUJI -KISO








0839-071 2025/08/05 2.64UT TOYOKAWA-FUJI









0839-071 2025/08/05 2.64UT FUJI -KISO




T20250805114739




BLK:21,SNR1: 18.585 ,SNR2: 38.158




F20250805114739









BLK:21,SNR1: 10.711 ,SNR2: 27.311




3C208 2025/08/05 2.82UT TOYOKAWA-FUJI









T20250805120421




BLK: 2,SNR1: 7.7649 ,SNR2: 13.635




F20250805120421






BLK: 2,SNR1: 2.3308 ,SNR2: 10.784






3C216 2025/08/05 3.10UT TOYOKAWA-FUJI












T20250805121631





BLK: 5, SNR1: 6.8905 , SNR2: 16.533








0919-142 2025/08/05 3.30UT TOYOKAWA-FUJI



F20250805121631




BLK: 5, SNR1: 7.5451 , SNR2: 17.930









0919-142 2025/08/05 3.30UT FUJI -KISO




T20250805122311




BLK: 5, SNR1: 0.75166 , SNR2: 2.5344




F20250805122311









BLK: 5, SNR1: 0.14623 , SNR2: 1.4285



0926+117 2025/08/05 3.41UT TOYOKAWA-FUJI












T20250805123055





BLK:12,SNR1: 2.0974 ,SNR2: 6.3711




Frequency (Hz)

F20250805123055







BLK:12,SNR1: 1.9438 ,SNR2: 7.0903






Frequency (Hz)



3C222 2025/08/05 3.54UT TOYOKAWA-FUJI









T20250805123755




BLK: 2,SNR1: 0.65440 ,SNR2: 5.4800




F20250805123755









BLK: 2,SNR1: 5.6881 ,SNR2: 13.078





0941-08 2025/08/05 3.66UT TOYOKAWA-FUJI










T20250805124617






F20250805124617






3C230 2025/08/05 3.80UT TOYOKAWA-FUJI












T20250805130025




BLK: 5,SNR1: 3.4264 ,SNR2: 7.9567




F20250805130025









BLK: 5,SNR1: 3.8990 ,SNR2: 15.742





3C236 2025/08/05 4.04UT TOYOKAWA-FUJI










T20250805130834




BLK: 6,SNR1: 0.20046 ,SNR2: 0.64196




F20250805130834









BLK: 6,SNR1: 0.60769 ,SNR2: 3.1083




1011+110 2025/08/05 4.17UT TOYOKAWA-FUJI









T20250805131615




BLK: 4,SNR1: 10.606 ,SNR2: 19.490




F20250805131615






BLK: 4,SNR1: 16.108 ,SNR2: 27.370






3C241 2025/08/05 4.30UT TOYOKAWA-FUJI













T20250805132744




BLK:10,SNR1: 19.959 ,SNR2: 23.977




F20250805132744









BLK:10,SNR1: 7.0564 ,SNR2: 15.148




1031-11 2025/08/05 4.49UT TOYOKAWA-FUJI









T20250805133218




BLK: 6,SNR1: 0.60237 ,SNR2: 3.6924




F20250805133218









BLK: 6,SNR1: 0.28208 ,SNR2: 5.7378








1035-058 2025/08/05 4.57UT TOYOKAWA-FUJI


























T20250805135235









F20250805135235











1055+01 2025/08/05 4.90UT TOYOKAWA-FUJI






























1107+109 2025/08/05 5.09UT FUJI -KISO















BLK:13,SNR1: 5.7785 ,SNR2: 9.2374





BLK:13,SNR1: 7.4932 ,SNR2: 17.327







1127-14 2025/08/05 5.43UT TOYOKAWA-FUJI







1127-14 2025/08/05 5.43UT TOYOKAWA-KISO







T20250805143728




BLK: 9,SNR1: 1.5537 ,SNR2: 3.0324




F20250805143728






BLK: 9,SNR1: 2.4494 ,SNR2: 6.5553






3C263.1 2025/08/05 5.65UT TOYOKAWA-FUJI














T20250805144355




BLK: 8,SNR1: 0.28151 ,SNR2: 0.90396




F20250805144355









BLK: 8,SNR1: 3.4903 ,SNR2: 5.7816




3C267 2025/08/05 5.76UT TOYOKAWA-FUJI













BLK: 5,SNR1: 0.62761 ,SNR2: 1.4045









BLK: 5,SNR1: 7.9109 ,SNR2: 24.361




1213-17 2025/08/05 6.19UT TOYOKAWA-FUJI















BLK:23,SNR1: 9.1053 ,SNR2: 21.092




BLK:23,SNR1: 4.7876 ,SNR2: 8.4068





3C273 2025/08/05 6.41UT TOYOKAWA-FUJI







BLK:23,SNR1: 6.6142 ,SNR2: 14.727




BLK:23,SNR1: 8.3228 ,SNR2: 14.549





3C273 2025/08/05 6.41UT TOYOKAWA-KISO







BLK:22,SNR1: 4.8626 ,SNR2: 8.5710




BLK:22,SNR1: 7.9646 ,SNR2: 20.620





3C273 2025/08/05 6.41UT FUJI -KISO







BLK: 7,SNR1: 0.22386E-01,SNR2: 1.0223




BLK: 7,SNR1: 1.1655 ,SNR2: 7.0619





3C275 2025/08/05 6.63UT TOYOKAWA-FUJI







BLK:12,SNR1: 0.76113E-01,SNR2: 1.0180








BLK:12,SNR1: 39.643 ,SNR2: 77.478




3C275 2025/08/05 6.63UT TOYOKAWA-KISO







T20250805154216




BLK:12,SNR1: 2.7998 ,SNR2: 5.0543




F20250805154216




BLK:12,SNR1: 0.34337 ,SNR2: 1.9489




1245-19 2025/08/05 6.73UT TOYOKAWA-FUJI




T20250805154216




BLK:12,SNR1: 1.8096 ,SNR2: 2.8066




K20250805154215



BLK:12,SNR1: 139.15 ,SNR2: 139.84




1245-19 2025/08/05 6.73UT TOYOKAWA-KISO








F20250805154216




BLK:16,SNR1: 0.11247 ,SNR2: 2.2752




K20250805154215





BLK:16,SNR1: 182.92 ,SNR2: 277.08




1245-19 2025/08/05 6.73UT FUJI -KISO




T20250805154959




BLK:13,SNR1: 306.10 ,SNR2: 297.32




F20250805154959




BLK:13,SNR1: 0.16120 ,SNR2: 1.7881





3C279 2025/08/05 6.86UT TOYOKAWA-FUJI







BLK:14,SNR1: 0.47276 ,SNR2: 4.5446




BLK:14,SNR1: 0.56710 ,SNR2: 2.0899





3C279 2025/08/05 6.86UT TOYOKAWA-KISO







BLK: 7,SNR1: 0.19969 ,SNR2: 1.3293




BLK: 7,SNR1: 0.59508 ,SNR2: 3.2667





3C279 2025/08/05 6.86UT FUJI -KISO







BLK:14,SNR1: 0.16271 ,SNR2: 1.3245




BLK:14,SNR1: 2.6162 ,SNR2: 5.8379





3C283 2025/08/05 7.12UT TOYOKAWA-FUJI







BLK:21,SNR1: 0.40454 ,SNR2: 2.4507





BLK:21,SNR1: 1.0568 ,SNR2: 3.5275




3C283 2025/08/05 7.12UT TOYOKAWA-KISO





F20250805160529




BLK:14,SNR1: 3.8348 ,SNR2: 13.980




K20250805160528





BLK:14,SNR1: 1.0623 ,SNR2: 3.6877




3C283 2025/08/05 7.12UT FUJI -KISO



T20250805161953





BLK:11,SNR1: 0.24768 ,SNR2: 1.8747




Frequency (Hz)

F20250805161953




BLK:11,SNR1: 2.7204 ,SNR2: 6.7109





Frequency (Hz)




1323+32 2025/08/05 7.36UT TOYOKAWA-FUJI









BLK:10,SNR1: 0.31683 ,SNR2: 2.0388





BLK:10,SNR1: 0.23209 ,SNR2: 1.7113




1323+32 2025/08/05 7.36UT TOYOKAWA-KISO





F20250805161953




BLK: 9,SNR1: 2.6044 ,SNR2: 6.7513




K20250805161952





BLK: 9,SNR1: 0.21327 ,SNR2: 2.8592




1323+32 2025/08/05 7.36UT FUJI -KISO





T20250805162443




BLK:19,SNR1: 1.4303 ,SNR2: 5.2674




F20250805162443





BLK:19,SNR1: 0.62205 ,SNR2: 1.9713




3C286 2025/08/05 7.44UT TOYOKAWA-FUJI





T20250805162443




BLK:21,SNR1: 1.4482 ,SNR2: 7.0012




K20250805162442





BLK:21,SNR1: 0.42079 ,SNR2: 1.7261




3C286 2025/08/05 7.44UT TOYOKAWA-KISO



F20250805162443





BLK: 7,SNR1: 1.1293 ,SNR2: 5.0894




Frequency (Hz)

K20250805162442




BLK: 7,SNR1: 0.18250 ,SNR2: 1.1155





Frequency (Hz)


3C286 2025/08/05 7.44UT FUJI -KISO



T20250805164110





BLK: 7, SNR1: 0.34083 , SNR2: 1.7575




Frequency (Hz)

F20250805164110




BLK: 7, SNR1: 1.3084 , SNR2: 4.2476





Frequency (Hz)


1345+12 2025/08/05 7.71UT TOYOKAWA-FUJI



T20250805164110





BLK:15,SNR1: 0.59406 ,SNR2: 3.8162




Frequency (Hz)

K20250805164109






BLK:15,SNR1: 0.46552 ,SNR2: 2.7455




Frequency (Hz)

1345+12 2025/08/05 7.71UT TOYOKAWA-KISO






1345+12 2025/08/05 7.71UT FUJI -KISO






T20250805165131





BLK:16,SNR1: 0.35012 ,SNR2: 1.3428




Frequency (Hz)

F20250805165131





BLK:16,SNR1: 2.3193 ,SNR2: 7.7760





Frequency (Hz)

1355+01 2025/08/05 7.89UT TOYOKAWA-FUJI







BLK:10,SNR1: 0.57086 ,SNR2: 2.7947









BLK:10,SNR1: 0.65171 ,SNR2: 2.4787





1355+01 2025/08/05 7.89UT TOYOKAWA-KISO










BLK:11,SNR1: 0.65728 ,SNR2: 2.2075





BLK:11,SNR1: 2.1449 ,SNR2: 5.4360







BLK:18,SNR1: 0.62719 ,SNR2: 5.9952




BLK:18,SNR1: 2.6139 ,SNR2: 6.7379




3C298 2025/08/05 8.24UT TOYOKAWA-KISO



F20250805171242





BLK: 9, SNR1: 2.6549 , SNR2: 5.0869




Frequency (Hz)

K20250805171241



BLK: 9, SNR1: 0.80091 , SNR2: 1.8054



Frequency (Hz)

3C298 2025/08/05 8.24UT FUJI -KISO

