
















0652-130 2025/09/23 21.58UT TOYOKAWA-FUJI










T20250924064433




BLK: 1, SNR1: 10.480 , SNR2: 26.157




F20250924064435






BLK: 1, SNR1: 12.260 , SNR2: 29.980







0703+138 2025/09/23 21.77UT TOYOKAWA-FUJI















BLK: 8,SNR1: 8.4314 ,SNR2: 24.690









BLK: 8,SNR1: 8.9124 ,SNR2: 25.728





0713-024 2025/09/23 21.93UT TOYOKAWA-FUJI










T20250924070407




BLK: 2, SNR1: 7.3526 , SNR2: 16.451




F20250924070409









BLK: 2, SNR1: 13.778 , SNR2: 24.987




0723+10 2025/09/23 22.10UT TOYOKAWA-FUJI















BLK: 1, SNR1: 0.93314 , SNR2: 5.9268








BLK: 1, SNR1: 8.3008 , SNR2: 18.953




0732+33 2025/09/23 22.27UT TOYOKAWA-FUJI



















0732+33 2025/09/23 22.27UT FUJI -KISO












T20250924073208




BLK: 7,SNR1: 4.2194 ,SNR2: 8.7331




F20250924073210






BLK: 7,SNR1: 1.6098 ,SNR2: 7.4736







0752-200 2025/09/23 22.56UT TOYOKAWA-FUJI















BLK: 2,SNR1: 37.363 ,SNR2: 65.480









BLK: 2,SNR1: 16.752 ,SNR2: 29.477





3C190 2025/09/23 22.69UT TOYOKAWA-FUJI








T20250924075209





BLK: 1, SNR1: 14.817 , SNR2: 26.152




Frequency (Hz)

F20250924075211







BLK: 1, SNR1: 13.923 , SNR2: 25.014









Frequency (Hz)

3C196 2025/09/23 22.90UT TOYOKAWA-FUJI




























BLK: 5, SNR1: 3.6034 , SNR2: 10.743









BLK: 5, SNR1: 2.1966 , SNR2: 5.8159







0834-19 2025/09/23 23.28UT TOYOKAWA-FUJI
















0839-071 2025/09/23 23.36UT TOYOKAWA-FUJI













T20250924083104




BLK:17,SNR1: 2.0876 ,SNR2: 6.0286




F20250924083106









BLK:17,SNR1: 1.8821 ,SNR2: 6.5267





3C208 2025/09/23 23.55UT TOYOKAWA-FUJI









T20250924084746




BLK: 3, SNR1: 6.5612 , SNR2: 16.003




F20250924084748









BLK: 3, SNR1: 14.171 , SNR2: 34.388




3C216 2025/09/23 23.82UT TOYOKAWA-FUJI













BLK:20,SNR1: 3.3473 ,SNR2: 10.154






BLK:20,SNR1: 8.7016 ,SNR2: 15.122






0926+117 2025/09/24 0.14UT TOYOKAWA-FUJI














T20250924091420




BLK: 9,SNR1: 0.19874 ,SNR2: 1.2876




F20250924091422









BLK: 9,SNR1:-0.14315 ,SNR2: 2.3866











3C222 2025/09/24 0.27UT TOYOKAWA-FUJI



















T20250924092942




BLK:12,SNR1: 1.1856 ,SNR2: 6.6658




F20250924092944






BLK:12,SNR1:-0.83424E-01,SNR2: 3.0363






3C230 2025/09/24 0.52UT TOYOKAWA-FUJI













T20250924094543




BLK:18,SNR1: 4.3593 ,SNR2: 12.708




F20250924094545









BLK:18,SNR1: 2.0495 ,SNR2: 5.5651







3C237 2025/09/24 0.79UT TOYOKAWA-FUJI
















1011+110 2025/09/24 0.89UT TOYOKAWA-FUJI













T20250924095940




BLK: 7, SNR1: 1.9970 , SNR2: 5.0473




F20250924095942









BLK: 7, SNR1: 0.15242 , SNR2: 0.97765





3C241 2025/09/24 1.02UT TOYOKAWA-FUJI









T20250924101109




BLK: 7,SNR1: 0.37276 ,SNR2: 1.9067




F20250924101111









BLK: 7,SNR1:-0.60476E-01,SNR2: 1.5494




1031-11 2025/09/24 1.21UT TOYOKAWA-FUJI









T20250924101543




BLK:11,SNR1: 6.7031 ,SNR2: 18.893




F20250924101545





BLK:11,SNR1: 6.1482 ,SNR2: 17.845




1035-058 2025/09/24 1.29UT TOYOKAWA-FUJI









1035-058 2025/09/24 1.29UT TOYOKAWA-KISO









T20250924102455




BLK:10,SNR1: 0.76349 ,SNR2: 1.4290




F20250924102457









BLK:10,SNR1: 0.44660 ,SNR2: 4.9606







1044-008 2025/09/24 1.44UT TOYOKAWA-FUJI
















1055+01 2025/09/24 1.63UT TOYOKAWA-FUJI













1055+01 2025/09/24 1.63UT TOYOKAWA-KISO





















T20250924105655




BLK:19,SNR1: 3.1239 ,SNR2: 16.100




F20250924105657








BLK:19,SNR1: 46.649 ,SNR2: 63.523




3C255 2025/09/24 1.98UT TOYOKAWA-FUJI


















3C255 2025/09/24 1.98UT FUJI -KISO














T20250924112053




BLK:10,SNR1: 1.5370 ,SNR2: 4.8254




F20250924112055









BLK:10,SNR1: 0.36769 ,SNR2: 1.6851











3C263.1 2025/09/24 2.38UT TOYOKAWA-FUJI


















T20250924115307





No. Good Data




Frequency (Hz)

F20250924115309







No. Good Data






Frequency (Hz)

1213-17 2025/09/24 2.91UT TOYOKAWA-FUJI












T20250924120625




BLK:10,SNR1: 12.075 ,SNR2: 23.187




F20250924120627









BLK:10,SNR1: 2.1895 ,SNR2: 9.0075





3C273 2025/09/24 3.14UT TOYOKAWA-FUJI









T20250924121936




BLK:15,SNR1: 0.50455 ,SNR2: 3.5180




F20250924121938









BLK:15,SNR1:-0.62661E-01,SNR2: 1.3128




3C275 2025/09/24 3.35UT TOYOKAWA-FUJI













BLK:19,SNR1: 1.0556 ,SNR2: 7.0903






BLK:19,SNR1:-0.91860E-01,SNR2: 1.0096






1245-19 2025/09/24 3.46UT TOYOKAWA-FUJI














T20250924123324




BLK:11,SNR1: 282.08 ,SNR2: 707.28




F20250924123326









BLK:11,SNR1: 264.64 ,SNR2: 757.07





3C279 2025/09/24 3.58UT TOYOKAWA-FUJI









T20250924124854




BLK:17,SNR1: 0.99418 ,SNR2: 2.6948




F20250924124856





BLK:17,SNR1: 1.0905 ,SNR2: 3.4920







3C283 2025/09/24 3.84UT TOYOKAWA-FUJI






3C283 2025/09/24 3.84UT TOYOKAWA-KISO













BLK:18,SNR1: 0.44010 ,SNR2: 1.3476









BLK:18,SNR1: 1.2609 ,SNR2: 3.4315




1323+32 2025/09/24 4.08UT TOYOKAWA-FUJI













BLK:13,SNR1: 9.1076 ,SNR2: 23.149









BLK:13,SNR1: 5.6674 ,SNR2: 14.142




3C286 2025/09/24 4.16UT TOYOKAWA-FUJI










T20250924132435




BLK:23,SNR1: 3.5953 ,SNR2: 8.0322




F20250924132437





BLK:23,SNR1: 0.47601 ,SNR2: 1.5149




1345+12 2025/09/24 4.44UT TOYOKAWA-FUJI










1345+12 2025/09/24 4.44UT TOYOKAWA-KISO









T20250924133456




BLK:14,SNR1: 0.34072 ,SNR2: 1.3402




F20250924133458





BLK:14,SNR1: 2.8272 ,SNR2: 14.388







1355+01 2025/09/24 4.61UT TOYOKAWA-FUJI
















1355+01 2025/09/24 4.61UT TOYOKAWA-KISO


















BLK:11,SNR1: 0.10475 ,SNR2: 0.84209





BLK:11,SNR1: 0.36441 ,SNR2: 4.7412




1428-03 2025/09/24 5.16UT TOYOKAWA-FUJI













1428-03 2025/09/24 5.16UT TOYOKAWA-KISO









BLK:10,SNR1: 0.17238 ,SNR2: 1.6682





BLK:10,SNR1: 0.98716 ,SNR2: 6.6823







1436-16 2025/09/24 5.30UT TOYOKAWA-FUJI







1436-16 2025/09/24 5.30UT TOYOKAWA-KISO







T20250924143255




BLK: 2,SNR1: 2.2903 ,SNR2: 8.3163




F20250924143257





BLK: 2,SNR1: 0.29374E-01,SNR2: 1.9255







1453-10 2025/09/24 5.58UT TOYOKAWA-FUJI






1453-10 2025/09/24 5.58UT TOYOKAWA-KISO













BLK: 4,SNR1: 0.17725 ,SNR2: 1.5925









BLK: 4,SNR1:-0.11576 ,SNR2: 1.6177




1508-05 2025/09/24 5.82UT TOYOKAWA-FUJI













BLK: 4,SNR1: 0.11111 ,SNR2: 2.1309









BLK: 4,SNR1: 0.22339E-01,SNR2: 2.0379





3C318 2025/09/24 5.97UT TOYOKAWA-FUJI










T20250924150234




BLK: 6,SNR1:-0.54037E-01,SNR2: 0.18827




F20250924150236





BLK: 6,SNR1: 0.11848 ,SNR2: 1.7246




1523+03 2025/09/24 6.07UT TOYOKAWA-FUJI










1523+03 2025/09/24 6.07UT TOYOKAWA-KISO

















1535+139 2025/09/24 6.27UT TOYOKAWA-FUJI













BLK: 6,SNR1: 0.26524 ,SNR2: 2.8413









BLK: 6,SNR1: 0.50455 ,SNR2: 2.8282





1545-12 2025/09/24 6.44UT TOYOKAWA-FUJI









T20250924154540




BLK: 3,SNR1: 0.55604E-01,SNR2: 0.46620




F20250924154542




BLK: 3,SNR1: 0.62577E-01,SNR2: 1.4140





1607+26 2025/09/24 6.79UT TOYOKAWA-FUJI









BLK: 3,SNR1: 0.77662E-01,SNR2: 0.63210




BLK: 3,SNR1: 0.27764 ,SNR2: 0.95574





1607+26 2025/09/24 6.79UT TOYOKAWA-KISO







BLK: 1,SNR1: 0.30872 ,SNR2: 1.5628









BLK: 1,SNR1: 0.85032 ,SNR2: 4.5366





1607+26 2025/09/24 6.79UT FUJI -KISO









BLK:10,SNR1:-0.10112E-01,SNR2: 0.66205





BLK:10,SNR1: 1.7322 ,SNR2: 4.7900




1623-228 2025/09/24 7.08UT TOYOKAWA-KISO



F20250924160313





BLK:12,SNR1: 0.96531 ,SNR2: 2.7981




Frequency (Hz)

K20250924160310





BLK:12,SNR1: 1.3700 ,SNR2: 2.4380





Frequency (Hz)

1623-228 2025/09/24 7.08UT FUJI -KISO







BLK: 8,SNR1: 0.29321 ,SNR2: 1.0475




BLK: 8,SNR1: 7.1617 ,SNR2: 16.326





1631-222 2025/09/24 7.22UT TOYOKAWA-FUJI







BLK: 3,SNR1:-0.66326E-02,SNR2: 0.68897





BLK: 3,SNR1: 1.4803 ,SNR2: 5.0084




1631-222 2025/09/24 7.22UT TOYOKAWA-KISO



F20250924161144




BLK: 9, SNR1: 10.074 , SNR2: 23.216




Frequency (Hz)

K20250924161144




BLK: 9, SNR1: 0.37458 , SNR2: 1.7220





Frequency (Hz)

1631-222 2025/09/24 7.22UT FUJI -KISO








T20250924161718




BLK: 6,SNR1: 0.25215 ,SNR2: 0.80328




F20250924161720





BLK: 6,SNR1: 1.1799 ,SNR2: 2.8146




1638-025 2025/09/24 7.32UT TOYOKAWA-FUJI





T20250924161718




BLK: 1,SNR1:-0.17204 ,SNR2: 0.26604




K20250924161717





BLK: 1,SNR1: 2.3387 ,SNR2: 11.287




1638-025 2025/09/24 7.32UT TOYOKAWA-KISO



F20250924161720





BLK: 3,SNR1: 0.18597 ,SNR2: 3.0540




Frequency (Hz)

K20250924161717






BLK: 3,SNR1: 0.74426 ,SNR2: 4.4636




Frequency (Hz)




1638-025 2025/09/24 7.32UT FUJI -KISO












1644-106 2025/09/24 7.43UT TOYOKAWA-FUJI
















1650+004 2025/09/24 7.52UT TOYOKAWA-FUJI












T20250924163505




BLK: 8, SNR1: 4.8960 , SNR2: 8.6489




Frequency (Hz)

F20250924163507






BLK: 8, SNR1: 0.16797 , SNR2: 2.0298




Frequency (Hz)




1656+053 2025/09/24 7.61UT TOYOKAWA-FUJI










1656+053 2025/09/24 7.61UT TOYOKAWA-KISO









1712-033 2025/09/24 7.89UT TOYOKAWA-KISO

