






T20250926061958




BLK: 6, SNR1: 3.3170 , SNR2: 27.865




F20250926062000





BLK: 6, SNR1: 3.0076 , SNR2: 11.271




0647-185 2025/09/25 21.36UT TOYOKAWA-FUJI





T20250926061958




BLK: 5, SNR1: 3.4641 , SNR2: 24.894




K20250926061957



BLK: 5, SNR1: 0.80197E-01, SNR2: 0.61174





0647-185 2025/09/25 21.36UT TOYOKAWA-KISO








F20250926062000




BLK: 5,SNR1: 2.8703 ,SNR2: 11.869




K20250926061957




BLK: 5,SNR1: 0.11908 ,SNR2: 0.99146





0647-185 2025/09/25 21.36UT FUJI -KISO







BLK: 6,SNR1: 4.1579 ,SNR2: 12.051




BLK: 6,SNR1: 15.461 ,SNR2: 24.033





0652-130 2025/09/25 21.45UT TOYOKAWA-FUJI







BLK: 4,SNR1: 16.086 ,SNR2: 20.183




BLK: 4,SNR1: 17.767 ,SNR2: 31.124





0652-130 2025/09/25 21.45UT TOYOKAWA-KISO







BLK: 4,SNR1: 14.337 ,SNR2: 25.217










BLK: 4,SNR1: 10.427 ,SNR2: 18.134




0652-130 2025/09/25 21.45UT FUJI -KISO










0703+138 2025/09/25 21.64UT TOYOKAWA-KISO







BLK: 2,SNR1: 18.658 ,SNR2: 42.248




BLK: 2,SNR1: 11.689 ,SNR2: 28.604





0703+138 2025/09/25 21.64UT FUJI -KISO







BLK: 3, SNR1: 6.2806 , SNR2: 18.999








BLK: 3, SNR1: 5.9515 , SNR2: 20.663





0713-024 2025/09/25 21.80UT TOYOKAWA-FUJI










F20250926064606




BLK: 4, SNR1: 6.2535 , SNR2: 21.629




K20250926064603









BLK: 4, SNR1: 6.6444 , SNR2: 22.919





0713-024 2025/09/25 21.80UT FUJI -KISO









BLK: 3,SNR1: 9.8034 ,SNR2: 21.699





BLK: 3,SNR1: 7.9903 ,SNR2: 12.911




0723+10 2025/09/25 21.97UT TOYOKAWA-KISO





F20250926065618




BLK: 3,SNR1: 1.0876 ,SNR2: 4.7120




K20250926065615





BLK: 3,SNR1: 2.0668 ,SNR2: 6.3797




0723+10 2025/09/25 21.97UT FUJI -KISO





T20250926070631




BLK: 3,SNR1: 5.9553 ,SNR2: 10.274




F20250926070633





BLK: 3,SNR1: 8.2935 ,SNR2: 17.502




0732+33 2025/09/25 22.14UT TOYOKAWA-FUJI





T20250926070631




BLK: 3, SNR1: 19.102 , SNR2: 21.323




K20250926070630





BLK: 3, SNR1: 7.1115 , SNR2: 13.889




0732+33 2025/09/25 22.14UT TOYOKAWA-KISO





F20250926070633




BLK: 2, SNR1: 8.8663 , SNR2: 18.726




K20250926070630



BLK: 2, SNR1: 7.4037 , SNR2: 14.455





0732+33 2025/09/25 22.14UT FUJI -KISO








T20250926071432




BLK: 6,SNR1: 0.13242 ,SNR2: 1.7594




F20250926071434




BLK: 6,SNR1: 0.67896 ,SNR2: 3.4513




0741-06 2025/09/25 22.27UT TOYOKAWA-FUJI




T20250926071432




BLK: 7,SNR1: 0.28151E-01,SNR2: 1.1553




K20250926071431




BLK: 7,SNR1: 0.22173 ,SNR2: 0.94912




0741-06 2025/09/25 22.27UT TOYOKAWA-KISO





F20250926071434




BLK: 3,SNR1: 0.37673 ,SNR2: 6.0238




K20250926071431





BLK: 3,SNR1: 0.86094E-01,SNR2: 1.6594




0741-06 2025/09/25 22.27UT FUJI -KISO





T20250926072416




BLK:13,SNR1: 8.9704 ,SNR2: 25.894




F20250926072418





BLK:13,SNR1: 9.0092 ,SNR2: 25.696




0752-200 2025/09/25 22.43UT TOYOKAWA-FUJI



T20250926072416





BLK:10,SNR1: 8.9846 ,SNR2: 25.962




Frequency (Hz)

K20250926072415








BLK:10,SNR1: 7.9777 ,SNR2: 22.432




Frequency (Hz)

0752-200 2025/09/25 22.43UT TOYOKAWA-KISO








0752-200 2025/09/25 22.43UT FUJI -KISO



T20250926073151





BLK: 4, SNR1: 6.4813 ,SNR2: 15.723




Frequency (Hz)

F20250926073153




BLK: 4, SNR1: 3.8931 ,SNR2: 10.041





Frequency (Hz)


3C190 2025/09/25 22.56UT TOYOKAWA-FUJI





T20250926073151




BLK: 9, SNR1: 24.659 , SNR2: 35.916




K20250926073150



BLK: 9, SNR1: 4.7295 , SNR2: 10.228





3C190 2025/09/25 22.56UT TOYOKAWA-KISO








F20250926073153




BLK: 4, SNR1: 2.6104 , SNR2: 7.5604




K20250926073150




BLK: 4, SNR1: 7.4756 , SNR2: 13.959




3C190 2025/09/25 22.56UT FUJI -KISO




T20250926074417




BLK: 2, SNR1: 2.6175 , SNR2: 6.5263




F20250926074419







BLK: 2, SNR1: 1.7286 , SNR2: 5.7854




3C196 2025/09/25 22.77UT TOYOKAWA-FUJI







3C196 2025/09/25 22.77UT TOYOKAWA-KISO




F20250926074419




BLK: 2, SNR1: 7.5009 , SNR2: 21.658




K20250926074416







BLK: 2, SNR1: 5.5974 , SNR2: 14.349








3C196 2025/09/25 22.77UT FUJI -KISO






0821+394 2025/09/25 22.95UT TOYOKAWA-FUJI







0821+394 2025/09/25 22.95UT TOYOKAWA-KISO




F20250926075528




BLK: 4, SNR1: 4.9514 , SNR2: 13.341




K20250926075525







BLK: 4, SNR1: 9.8366 , SNR2: 23.632




0821+394 2025/09/25 22.95UT FUJI -KISO










0834-19 2025/09/25 23.15UT TOYOKAWA-FUJI









0834-19 2025/09/25 23.15UT TOYOKAWA-KISO





F20250926080707




BLK: 5,SNR1: 6.8173 ,SNR2: 19.527




K20250926080704




BLK: 5,SNR1: 8.8426 ,SNR2: 26.374




0834-19 2025/09/25 23.15UT FUJI -KISO




T20250926081211




BLK: 3,SNR1: 0.21394 ,SNR2: 2.3242




F20250926081213







BLK: 3,SNR1:-0.18921 ,SNR2: 0.48522





0839-071 2025/09/25 23.23UT TOYOKAWA-FUJI







0839-071 2025/09/25 23.23UT TOYOKAWA-KISO







BLK: 2,SNR1: 0.19891 ,SNR2: 6.6082




BLK: 2,SNR1: 0.82302 ,SNR2: 5.8267




0839-071 2025/09/25 23.23UT FUJI -KISO




T20250926082312




BLK: 3,SNR1: 0.51975 ,SNR2: 1.5151




F20250926082314





BLK: 3,SNR1: 0.58028 ,SNR2: 2.0594




3C208 2025/09/25 23.41UT TOYOKAWA-FUJI





T20250926082312




BLK: 5, SNR1: 0.35456 , SNR2: 1.0837




K20250926082311




BLK: 5, SNR1: 0.44386 , SNR2: 1.7604




3C208 2025/09/25 23.41UT TOYOKAWA-KISO





F20250926082314




BLK: 5,SNR1: 0.26756E-01,SNR2: 2.6075




K20250926082311








BLK: 5,SNR1: 0.91674 ,SNR2: 3.1022







3C208 2025/09/25 23.41UT FUJI -KISO













3C216 2025/09/25 23.69UT TOYOKAWA-KISO





F20250926083956




BLK: 6, SNR1: 7.2962 , SNR2: 19.927




K20250926083953







BLK: 6, SNR1: 12.561 , SNR2: 30.830




3C216 2025/09/25 23.69UT FUJI -KISO







0919-142 2025/09/25 23.90UT TOYOKAWA-FUJI





T20250926085204




BLK: 7, SNR1: 12.943 , SNR2: 31.148




K20250926085203




BLK: 7, SNR1: 11.870 , SNR2: 29.572




0919-142 2025/09/25 23.90UT TOYOKAWA-KISO




F20250926085206




BLK:10,SNR1: 8.0034 ,SNR2: 20.914




K20250926085203







BLK:10,SNR1: 8.5636 ,SNR2: 21.842








0919-142 2025/09/25 23.90UT FUJI -KISO






3C222 2025/09/26 0.14UT TOYOKAWA-FUJI







3C222 2025/09/26 0.14UT TOYOKAWA-KISO








F20250926090630




K20250926090627




3C222 2025/09/26 0.14UT FUJI -KISO




T20250926091328




BLK:11,SNR1: 8.2122 ,SNR2: 23.676




F20250926091330





BLK:11,SNR1: 8.7645 ,SNR2: 23.621




0941-08 2025/09/26 0.25UT TOYOKAWA-FUJI





T20250926091328




BLK:10,SNR1: 8.1771 ,SNR2: 23.574




K20250926091327







BLK:10,SNR1: 10.978 ,SNR2: 31.617




0941-08 2025/09/26 0.25UT TOYOKAWA-KISO








0941-08 2025/09/26 0.25UT FUJI -KISO




T20250926092150




BLK:11,SNR1: 0.43410 ,SNR2: 1.6006




F20250926092152





BLK:11,SNR1: 0.20289 ,SNR2: 2.7633




3C230 2025/09/26 0.39UT TOYOKAWA-FUJI





T20250926092150




BLK:13,SNR1: 5.5574 ,SNR2: 9.8404




K20250926092149




BLK:13,SNR1: 3.7088 ,SNR2: 8.5790




3C230 2025/09/26 0.39UT TOYOKAWA-KISO





F20250926092152




BLK:15,SNR1: 0.17177 ,SNR2: 2.7189




K20250926092149




BLK:15,SNR1: 7.7838 ,SNR2: 20.154




3C230 2025/09/26 0.39UT FUJI -KISO




T20250926093751




BLK:14,SNR1: 5.9385 ,SNR2: 17.092




F20250926093753



BLK:14,SNR1: 4.2700 ,SNR2: 11.117




3C237 2025/09/26 0.66UT TOYOKAWA-FUJI








T20250926093751




BLK:20,SNR1: 4.5876 ,SNR2: 13.087




K20250926093750




BLK:20,SNR1: 9.7767 ,SNR2: 21.144




3C237 2025/09/26 0.66UT TOYOKAWA-KISO





F20250926093753




BLK:16,SNR1: 2.8690 ,SNR2: 7.0563




K20250926093750





BLK:16,SNR1: 9.6729 ,SNR2: 20.919




3C237 2025/09/26 0.66UT FUJI -KISO




T20250926094407




BLK:13,SNR1: 9.5756 ,SNR2: 29.585




F20250926094409





BLK:13,SNR1: 1.4506 ,SNR2: 4.3414




1011+110 2025/09/26 0.76UT TOYOKAWA-FUJI




T20250926094407




BLK:12,SNR1: 4.3309 ,SNR2: 10.936




K20250926094406




BLK:12,SNR1: 7.3196 ,SNR2: 19.155




1011+110 2025/09/26 0.76UT TOYOKAWA-KISO




F20250926094409




BLK:15,SNR1: 1.7477 ,SNR2: 4.8457




K20250926094406




BLK:15,SNR1: 6.9470 ,SNR2: 18.175




1011+110 2025/09/26 0.76UT FUJI -KISO




T20250926095148




BLK: 9,SNR1: 0.49952 ,SNR2: 2.0578




F20250926095150




BLK: 9,SNR1: 0.54030 ,SNR2: 3.0895




3C241 2025/09/26 0.89UT TOYOKAWA-FUJI




T20250926095148




BLK: 7, SNR1: 0.41821 , SNR2: 1.9275




K20250926095147




BLK: 7, SNR1: 6.4185 , SNR2: 16.560




3C241 2025/09/26 0.89UT TOYOKAWA-KISO





F20250926095150




BLK:13,SNR1: 0.97771 ,SNR2: 2.6510




K20250926095147



BLK:13,SNR1: 5.1660 ,SNR2: 13.181





3C241 2025/09/26 0.89UT FUJI -KISO






T20250926100317





BLK: 7,SNR1: 0.19879 ,SNR2: 2.6944





1031-11 2025/09/26 1.08UT TOYOKAWA-FUJI



F20250926100319




BLK: 7,SNR1:-0.23571 ,SNR2: 1.8079





T20250926100317




BLK:12,SNR1: 2.1103 ,SNR2: 4.1088




K20250926100316





BLK:12,SNR1: 2.1821 ,SNR2: 6.3448




1031-11 2025/09/26 1.08UT TOYOKAWA-KISO





F20250926100319




BLK: 7, SNR1: -0.58439E-01, SNR2: 4.0551




K20250926100316





BLK: 7, SNR1: 5.1317, SNR2: 13.194




1031-11 2025/09/26 1.08UT FUJI -KISO




T20250926100751




BLK: 4, SNR1: 5.5029 , SNR2: 13.779




F20250926100753




BLK: 4, SNR1: 10.944 , SNR2: 26.407




1035-058 2025/09/26 1.16UT TOYOKAWA-FUJI





T20250926100751




BLK: 8, SNR1: 15.769 , SNR2: 36.683




K20250926100750





BLK: 8, SNR1: 8.1142 , SNR2: 21.235




1035-058 2025/09/26 1.16UT TOYOKAWA-KISO



F20250926100753





BLK: 3, SNR1: 9.9651 , SNR2: 24.382





1035-058 2025/09/26 1.16UT FUJI -KISO


K20250926100750




BLK: 3, SNR1: 7.7860 , SNR2: 20.718




T20250926101703




BLK: 6,SNR1: 7.4698 ,SNR2: 19.181




F20250926101705




BLK: 6,SNR1: 9.5559 ,SNR2: 24.390




1044-008 2025/09/26 1.31UT TOYOKAWA-FUJI





T20250926101703




BLK: 7, SNR1: 6.6530 ,SNR2: 16.902




K20250926101702



BLK: 7, SNR1: 10.219 ,SNR2: 25.490





1044-008 2025/09/26 1.31UT TOYOKAWA-KISO








F20250926101705




BLK: 7, SNR1: 6.4792 , SNR2: 16.125




K20250926101702




BLK: 7, SNR1: 14.650 , SNR2: 44.159




1044-008 2025/09/26 1.31UT FUJI -KISO





T20250926102808




BLK: 4,SNR1: 16.539 ,SNR2: 30.553




F20250926102810




BLK: 4,SNR1: 10.235 ,SNR2: 25.484




1055+01 2025/09/26 1.50UT TOYOKAWA-FUJI





T20250926102808




BLK: 6,SNR1: 16.146 ,SNR2: 29.813




K20250926102807





BLK: 6,SNR1: 1.5470 ,SNR2: 10.266




1055+01 2025/09/26 1.50UT TOYOKAWA-KISO





F20250926102810




BLK: 7, SNR1: 10.702 , SNR2: 26.317




K20250926102807







BLK: 7, SNR1: 11.173 , SNR2: 27.462





1055+01 2025/09/26 1.50UT FUJI -KISO







1107+109 2025/09/26 1.69UT TOYOKAWA-FUJI











BLK: 4, SNR1: 10.952 , SNR2: 26.783









BLK: 4, SNR1: 10.749 , SNR2: 26.324









1107+109 2025/09/26 1.69UT FUJI -KISO
















3C255 2025/09/26 1.85UT TOYOKAWA-KISO







T20250926105941




BLK:12,SNR1: 0.44655 ,SNR2: 3.1816




F20250926105943





BLK:12,SNR1:-0.20194 ,SNR2: 0.80899





1127-14 2025/09/26 2.02UT TOYOKAWA-FUJI




T20250926105941





K20250926105940








1127-14 2025/09/26 2.02UT TOYOKAWA-KISO










1127-14 2025/09/26 2.02UT FUJI -KISO










3C263.1 2025/09/26 2.25UT TOYOKAWA-FUJI






3C263.1 2025/09/26 2.25UT TOYOKAWA-KISO









3C263.1 2025/09/26 2.25UT FUJI -KISO













BLK:21,SNR1: 0.30377 ,SNR2: 3.8075




BLK:21,SNR1: 0.24720 ,SNR2: 0.95202




3C267 2025/09/26 2.35UT TOYOKAWA-KISO





F20250926111930




BLK: 4,SNR1:-0.16934 ,SNR2: 0.68948




K20250926111927





BLK: 4,SNR1: 0.63777 ,SNR2: 3.1777





3C267 2025/09/26 2.35UT FUJI -KISO




T20250926114516




F20250926114518




1213-17 2025/09/26 2.78UT TOYOKAWA-FUJI





T20250926114516




BLK: 6,SNR1: 5.3007 ,SNR2: 13.339




K20250926114515




BLK: 6,SNR1: 8.0755 ,SNR2: 21.224




1213-17 2025/09/26 2.78UT TOYOKAWA-KISO





F20250926114518




BLK: 8, SNR1: 5.7385 , SNR2: 15.456




K20250926114515




BLK: 8, SNR1: 9.3602 , SNR2: 23.667





1213-17 2025/09/26 2.78UT FUJI -KISO







BLK: 7,SNR1: 7.1288 ,SNR2: 20.969




BLK: 7,SNR1: 8.6186 ,SNR2: 21.682





3C273 2025/09/26 3.00UT TOYOKAWA-FUJI







BLK: 7,SNR1: 8.2572 ,SNR2: 24.205



BLK: 7,SNR1: 10.416 ,SNR2: 26.333





3C273 2025/09/26 3.00UT TOYOKAWA-KISO







F20250926115835




BLK:12,SNR1: 6.8126 ,SNR2: 20.257




K20250926115832





BLK:12,SNR1: 9.4992 ,SNR2: 23.969




3C273 2025/09/26 3.00UT FUJI -KISO





T20250926121144




BLK:11,SNR1: 12.985 ,SNR2: 28.915




F20250926121146





BLK:11,SNR1: 20.587 ,SNR2: 35.784




3C275 2025/09/26 3.22UT TOYOKAWA-FUJI




T20250926121144




BLK:11,SNR1: 3.9668 ,SNR2: 11.581




K20250926121143





BLK:11,SNR1: 3.0359 ,SNR2: 9.2378




3C275 2025/09/26 3.22UT TOYOKAWA-KISO



F20250926121146




BLK: 9, SNR1: 9.0100 , SNR2: 19.633





3C275 2025/09/26 3.22UT FUJI -KISO



K20250926121143




BLK: 9, SNR1: 2.9669 , SNR2: 9.0585




T20250926121749




BLK:12,SNR1: 0.31792 ,SNR2: 2.3293




F20250926121751





BLK:12,SNR1: 0.26061 ,SNR2: 2.8804




1245-19 2025/09/26 3.33UT TOYOKAWA-FUJI





T20250926121749




BLK:18,SNR1: 0.18045 ,SNR2: 2.4821




K20250926121748




BLK:18,SNR1: 1.0393 ,SNR2: 1.8278




1245-19 2025/09/26 3.33UT TOYOKAWA-KISO





F20250926121751




BLK:13,SNR1: 0.52369E-01,SNR2: 2.0357




K20250926121748




BLK:13,SNR1: 1.3435 ,SNR2: 2.1332





1245-19 2025/09/26 3.33UT FUJI -KISO







BLK:14,SNR1: 4.5627 ,SNR2: 16.901



BLK:14,SNR1:-0.34746 ,SNR2: 0.26709E-01





3C279 2025/09/26 3.45UT TOYOKAWA-FUJI








T20250926122532




BLK:19,SNR1: 4.0626 ,SNR2: 10.651




K20250926122531




BLK:19,SNR1: 1.0861 ,SNR2: 2.2126





3C279 2025/09/26 3.45UT TOYOKAWA-KISO







BLK:20,SNR1:-0.34773 ,SNR2: 0.47424





BLK:20,SNR1: 2.0608 ,SNR2: 4.1374




3C279 2025/09/26 3.45UT FUJI -KISO




T20250926124102




BLK:23,SNR1: 0.50470 ,SNR2: 3.5526




F20250926124104





BLK:23,SNR1: 0.25504 ,SNR2: 4.2273




3C283 2025/09/26 3.71UT TOYOKAWA-FUJI




T20250926124102




BLK:31,SNR1: 0.51319 ,SNR2: 3.5229




K20250926124101








BLK:31,SNR1: 0.38509 ,SNR2: 1.7491





3C283 2025/09/26 3.71UT TOYOKAWA-KISO








T20250926125526




BLK:13,SNR1: 0.45176 ,SNR2: 1.8157




F20250926125528




BLK:13,SNR1: 10.921 ,SNR2: 25.509





1323+32 2025/09/26 3.95UT TOYOKAWA-FUJI







BLK:16,SNR1: 0.41550 ,SNR2: 2.6071








BLK:16,SNR1: 2.7779 ,SNR2: 7.9249




1323+32 2025/09/26 3.95UT TOYOKAWA-KISO













BLK:21,SNR1: 4.5537 ,SNR2: 11.785




BLK:21,SNR1: 1.6156 ,SNR2: 3.6968





3C286 2025/09/26 4.03UT TOYOKAWA-FUJI







BLK:22,SNR1: 4.4658 ,SNR2: 11.432




BLK:22,SNR1: 2.7895 ,SNR2: 4.3927





3C286 2025/09/26 4.03UT TOYOKAWA-KISO







BLK:22,SNR1: 1.2042 ,SNR2: 3.3013




BLK:22,SNR1: 6.4744 ,SNR2: 15.287





3C286 2025/09/26 4.03UT FUJI -KISO







BLK:16,SNR1: 0.82103 ,SNR2: 5.7593




BLK:16,SNR1: 1.5586 ,SNR2: 4.1892




1345+12 2025/09/26 4.31UT TOYOKAWA-FUJI





T20250926131644




BLK:16,SNR1: 0.81560 ,SNR2: 2.7778




K20250926131643








BLK:16,SNR1: 0.60875 ,SNR2: 2.4241





1345+12 2025/09/26 4.31UT TOYOKAWA-KISO







T20250926132704




BLK:13,SNR1: 0.63142 ,SNR2: 1.9565




F20250926132706




BLK:13,SNR1: 1.0442 ,SNR2: 5.7610




1355+01 2025/09/26 4.48UT TOYOKAWA-FUJI





T20250926132704




BLK:14,SNR1: 0.81179 ,SNR2: 2.3913




K20250926132703



BLK:14,SNR1: 2.6132 ,SNR2: 6.7332




1355+01 2025/09/26 4.48UT TOYOKAWA-KISO








F20250926132706




BLK:13,SNR1: 1.2617 ,SNR2: 4.1995




K20250926132703





BLK:13,SNR1: 2.2155 ,SNR2: 7.0583




1355+01 2025/09/26 4.48UT FUJI -KISO




T20250926134815




BLK:19,SNR1: 1.4688 ,SNR2: 9.4008




F20250926134817




BLK:19,SNR1: 0.59907 ,SNR2: 1.8237




3C298 2025/09/26 4.83UT TOYOKAWA-FUJI





T20250926134815




BLK:22,SNR1: 1.3169 ,SNR2: 4.9928




K20250926134814







BLK:22,SNR1: 14.488 ,SNR2: 22.629





3C298 2025/09/26 4.83UT TOYOKAWA-KISO







3C298 2025/09/26 4.83UT FUJI -KISO







BLK: 2,SNR1: 0.64097 ,SNR2: 4.8038




BLK: 2,SNR1:-0.24385 ,SNR2: 0.65839





1428-03 2025/09/26 5.03UT TOYOKAWA-FUJI







BLK: 4,SNR1: 0.11912 ,SNR2: 1.0535





BLK: 4,SNR1: 0.78121 ,SNR2: 3.2485




1428-03 2025/09/26 5.03UT TOYOKAWA-KISO




F20250926140000




BLK: 7,SNR1:-0.20646 ,SNR2: 0.55762




K20250926135957





BLK: 7,SNR1: 0.41071 ,SNR2: 3.0736




1428-03 2025/09/26 5.03UT FUJI -KISO





T20250926140601




BLK: 4,SNR1: 0.70278E-01,SNR2: 0.30765




F20250926140603



BLK: 4,SNR1: 4.4898 ,SNR2: 8.0510





1434+03 2025/09/26 5.13UT TOYOKAWA-FUJI








T20250926140601




BLK: 7,SNR1: 0.16206 ,SNR2: 0.38242




K20250926140600




BLK: 7,SNR1: 0.28339 ,SNR2: 1.3749






1434+03 2025/09/26 5.13UT TOYOKAWA-KISO




F20250926140603




K20250926140600





1434+03 2025/09/26 5.13UT FUJI -KISO







BLK: 5,SNR1: 0.45885 ,SNR2: 1.2209




BLK: 5,SNR1: -0.28252 ,SNR2: 1.0565





1453-10 2025/09/26 5.45UT TOYOKAWA-FUJI







BLK: 6,SNR1: 0.48004 ,SNR2: 2.5838




BLK: 6,SNR1: 0.79106 ,SNR2: 2.9975





1453-10 2025/09/26 5.45UT TOYOKAWA-KISO









BLK: 2,SNR1: 0.51330 ,SNR2: 1.4565




BLK: 2,SNR1: 0.41820 ,SNR2: 1.2750




T20250926143955




BLK:11,SNR1: 0.23811 ,SNR2: 2.4300




F20250926143957





BLK:11,SNR1:-0.30229 ,SNR2: 0.88115




1508-05 2025/09/26 5.69UT TOYOKAWA-FUJI





T20250926143955




BLK:10,SNR1: 0.20602 ,SNR2: 2.2289




K20250926143954




BLK:10,SNR1: 0.71849 ,SNR2: 2.6822




1508-05 2025/09/26 5.69UT TOYOKAWA-KISO





F20250926143957




BLK:12,SNR1:-0.10899 ,SNR2: 1.4637




K20250926143954




BLK:12,SNR1: 0.42329 ,SNR2: 2.2534





1508-05 2025/09/26 5.69UT FUJI -KISO









BLK: 9,SNR1: 0.21309 ,SNR2: 1.3092




BLK: 9,SNR1: 2.2541 ,SNR2: 7.9957





3C318 2025/09/26 5.84UT TOYOKAWA-FUJI







BLK: 8,SNR1: 0.14514 ,SNR2: 1.2846





BLK: 8,SNR1: 4.9882 ,SNR2: 8.8306




3C318 2025/09/26 5.84UT TOYOKAWA-KISO





F20250926144857




BLK:13,SNR1: 1.1396 ,SNR2: 4.8686




K20250926144854





BLK:13,SNR1: 4.5003 ,SNR2: 7.9675




3C318 2025/09/26 5.84UT FUJI -KISO




T20250926145442




BLK: 9,SNR1: 0.34853 ,SNR2: 1.0558




F20250926145444





BLK: 9,SNR1: 0.37455 ,SNR2: 2.3390




1523+03 2025/09/26 5.94UT TOYOKAWA-FUJI





T20250926145442




BLK:12,SNR1: 0.27966 ,SNR2: 0.95088




K20250926145441




BLK:12,SNR1: 0.32274 ,SNR2: 2.4724





1523+03 2025/09/26 5.94UT TOYOKAWA-KISO







BLK: 5,SNR1: 0.52177 ,SNR2: 2.8505





BLK: 5,SNR1: 0.70915E-01,SNR2: 1.1198




1523+03 2025/09/26 5.94UT FUJI -KISO




T20250926150621




BLK: 4,SNR1: 0.25196 ,SNR2: 0.56586




F20250926150623




BLK: 4,SNR1: 1.0467 ,SNR2: 9.2711





1535+139 2025/09/26 6.13UT TOYOKAWA-FUJI







BLK: 2,SNR1: 0.85302E-01,SNR2: 0.71226



BLK: 2,SNR1: 49.346 ,SNR2: 82.282





1535+139 2025/09/26 6.13UT TOYOKAWA-KISO








F20250926150623




BLK: 2,SNR1: 0.24822 ,SNR2: 1.2864




K20250926150620




BLK: 2,SNR1: 27.884 ,SNR2: 51.256





1535+139 2025/09/26 6.13UT FUJI -KISO







BLK: 4,SNR1: 0.32731E-01,SNR2: 0.70237




BLK: 4,SNR1: 76.107 ,SNR2: 76.864





1545-12 2025/09/26 6.31UT TOYOKAWA-FUJI







BLK: 7,SNR1: 0.22040 ,SNR2: 0.79348




BLK: 7,SNR1: 0.35401 ,SNR2: 1.8330





1545-12 2025/09/26 6.31UT TOYOKAWA-KISO










BLK: 4,SNR1: 47.162 ,SNR2: 61.783





BLK: 4,SNR1: 0.42663 ,SNR2: 1.3877






T20250926153748





BLK:15,SNR1: 10.317 ,SNR2: 17.931




Frequency (Hz)

K20250926153747




BLK:15,SNR1: 8.7695 ,SNR2: 15.451




Frequency (Hz)


1607+26 2025/09/26 6.66UT TOYOKAWA-KISO



F20250926153750





BLK:13,SNR1: 0.58542 ,SNR2: 1.8857




Frequency (Hz)

K20250926153747




BLK:13,SNR1: 7.1855 ,SNR2: 18.559





Frequency (Hz)


1607+26 2025/09/26 6.66UT FUJI -KISO





T20250926155520




BLK: 8,SNR1: 0.43389 ,SNR2: 3.4829




F20250926155522



BLK: 8,SNR1: 6.1282 ,SNR2: 16.479





1623-228 2025/09/26 6.95UT TOYOKAWA-FUJI






T20250926155520





BLK:12,SNR1: 0.46091 ,SNR2: 1.4521




Frequency (Hz)

K20250926155519




BLK:12,SNR1: 6.6478 ,SNR2: 18.076




Frequency (Hz)


1623-228 2025/09/26 6.95UT TOYOKAWA-KISO





F20250926155522




BLK: 5, SNR1: 0.82730 , SNR2: 5.3197




K20250926155519










BLK: 5, SNR1: 5.7162 , SNR2: 14.745




1623-228 2025/09/26 6.95UT FUJI -KISO










1631-222 2025/09/26 7.09UT TOYOKAWA-KISO







BLK:12,SNR1: 0.29036 ,SNR2: 0.68187




BLK:12,SNR1: 3.3240 ,SNR2: 7.5632





1631-222 2025/09/26 7.09UT FUJI -KISO







BLK: 8,SNR1: 7.9352 ,SNR2: 20.613







BLK: 8,SNR1:-0.88406E-03,SNR2: 1.8707




1638-025 2025/09/26 7.19UT TOYOKAWA-FUJI







1638-025 2025/09/26 7.19UT TOYOKAWA-KISO



F20250926160929





BLK:25,SNR1: 0.17154 ,SNR2: 2.9533




Frequency (Hz)

K20250926160926




BLK:25,SNR1: 5.2988 ,SNR2: 9.2576





Frequency (Hz)

1638-025 2025/09/26 7.19UT FUJI -KISO






T20250926161621





BLK: 4, SNR1: 0.18734 , SNR2: 2.4782




Frequency (Hz)

F20250926161623




BLK: 4, SNR1: 2.5663 , SNR2: 11.492





Frequency (Hz)


1644-106 2025/09/26 7.30UT TOYOKAWA-FUJI



T20250926161621





BLK: 2, SNR1: 0.24838 , SNR2: 2.1885




Frequency (Hz)

K20250926161620







BLK: 2, SNR1: 5.9771 , SNR2: 11.585




Frequency (Hz)



1644-106 2025/09/26 7.30UT TOYOKAWA-KISO









BLK: 7, SNR1: 2.3168 , SNR2: 10.879




BLK: 7, SNR1: 7.3918 , SNR2: 18.307





1650+004 2025/09/26 7.39UT TOYOKAWA-FUJI







BLK: 2,SNR1: 2.3531 ,SNR2: 11.016








BLK: 2,SNR1: 7.2149 ,SNR2: 17.934





1650+004 2025/09/26 7.39UT TOYOKAWA-KISO






T20250926162713




BLK:13,SNR1: 0.93083 ,SNR2: 2.5514




Frequency (Hz)

F20250926162715









BLK:13,SNR1: 0.94767 ,SNR2: 4.7917



Frequency (Hz)



1656+053 2025/09/26 7.48UT TOYOKAWA-FUJI








F20250926162715





BLK:25,SNR1: 0.55029 ,SNR2: 3.2320




Frequency (Hz)

K20250926162712







BLK:25,SNR1: 4.0145 ,SNR2: 11.113




Frequency (Hz)



1656+053 2025/09/26 7.48UT FUJI -KISO









BLK: 1, SNR1: 15.576 , SNR2: 19.991







BLK: 1, SNR1: 4.3358 , SNR2: 17.735




1712-033 2025/09/26 7.76UT TOYOKAWA-KISO








1712-033 2025/09/26 7.76UT FUJI -KISO





T20250926170146




BLK: 4, SNR1: 5.0792 , SNR2: 9.3219




F20250926170148





BLK: 4, SNR1: 8.2136 , SNR2: 18.996




1730-13 2025/09/26 8.06UT TOYOKAWA-FUJI



T20250926170146





BLK: 9, SNR1: 3.8493 , SNR2: 6.9501




Frequency (Hz)

K20250926170145




BLK: 9, SNR1: 8.4157 , SNR2: 21.812





Frequency (Hz)


1730-13 2025/09/26 8.06UT TOYOKAWA-KISO





F20250926170148




BLK: 9, SNR1: 8.1833 , SNR2: 21.213



K20250926170145



BLK: 9, SNR1: 8.4275 , SNR2: 21.842



1730-13 2025/09/26 8.06UT FUJI -KISO

