









BLK: 1,SNR1: 0.11233 ,SNR2: 1.0086





BLK: 1,SNR1: -0.87788E-01,SNR2: 0.47999E-01







BLK: 1,SNR1:-0.10913 ,SNR2: 0.58735



BLK: 1,SNR1: 1.2119 ,SNR2: 8.0108





0652-130 2025/09/26 21.38UT TOYOKAWA-KISO








F20250927062110




No.Good Data




K20250927062107









No.Good Data





0652-130 2025/09/26 21.38UT FUJI -KISO









F20250927063247




BLK: 4, SNR1: 0.69145 , SNR2: 5.4689




K20250927063244







BLK: 4, SNR1: 0.39356 , SNR2: 3.4635








0703+138 2025/09/26 21.57UT FUJI -KISO






0713-024 2025/09/26 21.73UT TOYOKAWA-FUJI







0713-024 2025/09/26 21.73UT TOYOKAWA-KISO





F20250927064210




BLK: 3, SNR1: 0.19433 , SNR2: 5.2053




K20250927064207




BLK: 3, SNR1: 5.1148 , SNR2: 8.8146





0713-024 2025/09/26 21.73UT FUJI -KISO







BLK: 4,SNR1: 5.1104 ,SNR2: 11.969



BLK: 4,SNR1: 2.7318 ,SNR2: 6.7498





0723+10 2025/09/26 21.90UT TOYOKAWA-FUJI






T20250927065220





BLK: 6, SNR1: 3.5269 , SNR2: 7.8738




Frequency (Hz)

K20250927065219





BLK: 6, SNR1: 8.6256 , SNR2: 16.110





Frequency (Hz)

0723+10 2025/09/26 21.90UT TOYOKAWA-KISO







BLK: 8,SNR1: 1.7664 ,SNR2: 4.4807




BLK: 8,SNR1: 9.2100 ,SNR2: 16.495





0723+10 2025/09/26 21.90UT FUJI -KISO







BLK: 1, SNR1: 2.1708 , SNR2: 6.6550







BLK: 1, SNR1: 9.0371 , SNR2: 21.757





0732+33 2025/09/26 22.07UT TOYOKAWA-FUJI







0732+33 2025/09/26 22.07UT TOYOKAWA-KISO







BLK: 2,SNR1: 7.2011 ,SNR2: 20.605




BLK: 2,SNR1: 9.8724 ,SNR2: 24.554




0732+33 2025/09/26 22.07UT FUJI -KISO




T20250927071036




BLK:10,SNR1: 5.2400 ,SNR2: 19.086




F20250927071038




BLK:10,SNR1: 1.7735 ,SNR2: 7.2305




0741-06 2025/09/26 22.20UT TOYOKAWA-FUJI





T20250927071036




BLK:18,SNR1: 3.9008 ,SNR2: 14.825




K20250927071035




BLK:18,SNR1: 3.2072 ,SNR2: 6.1205




0741-06 2025/09/26 22.20UT TOYOKAWA-KISO





F20250927071038




BLK:11,SNR1: 2.3332 ,SNR2: 9.2465




K20250927071035







BLK:11,SNR1: 3.1070 ,SNR2: 11.294




0741-06 2025/09/26 22.20UT FUJI -KISO










0752-200 2025/09/26 22.37UT TOYOKAWA-FUJI







BLK:18,SNR1: 3.0019 ,SNR2: 9.0608





BLK:18,SNR1: 8.6993 ,SNR2: 15.282




0752-200 2025/09/26 22.37UT TOYOKAWA-KISO




F20250927072022




BLK:19,SNR1: 3.6166 ,SNR2: 10.634




K20250927072019





BLK:19,SNR1: 7.8404 ,SNR2: 13.733




0752-200 2025/09/26 22.37UT FUJI -KISO





T20250927072756




BLK: 9,SNR1: 2.5178 ,SNR2: 6.0747




F20250927072758





BLK: 9,SNR1: 5.0193 ,SNR2: 15.399




3C190 2025/09/26 22.49UT TOYOKAWA-FUJI





T20250927072756




No.Good Data




K20250927072755




No.Good Data




3C190 2025/09/26 22.49UT TOYOKAWA-KISO





F20250927072758




BLK: 5,SNR1: 15.690 ,SNR2: 27.691




K20250927072755




BLK: 5,SNR1: 2.7346 ,SNR2: 6.9361





3C190 2025/09/26 22.49UT FUJI -KISO







BLK: 6,SNR1: 1.0191 ,SNR2: 3.9892





BLK: 6,SNR1: 1.2913 ,SNR2: 3.0170




3C196 2025/09/26 22.70UT TOYOKAWA-FUJI





T20250927074021




BLK: 5, SNR1: 1.4344 , SNR2: 4.1998




K20250927074020



BLK: 5, SNR1: 2.8542 , SNR2: 6.9774





3C196 2025/09/26 22.70UT TOYOKAWA-KISO








F20250927074023




BLK: 5, SNR1: 1.4612 , SNR2: 4.3084




K20250927074020





BLK: 5, SNR1: 0.27985 , SNR2: 2.9751




3C196 2025/09/26 22.70UT FUJI -KISO





T20250927075130




BLK: 3,SNR1: 12.265 ,SNR2: 29.521




F20250927075132




BLK: 3,SNR1: 2.3423 ,SNR2: 8.0056




0821+394 2025/09/26 22.89UT TOYOKAWA-FUJI




T20250927075130




BLK: 7,SNR1: 9.1522 ,SNR2: 22.333




K20250927075129





BLK: 7,SNR1: 9.4943 ,SNR2: 16.785




0821+394 2025/09/26 22.89UT TOYOKAWA-KISO




F20250927075132




BLK:11,SNR1: 1.3360 ,SNR2: 4.8795




K20250927075129




BLK:11,SNR1: 7.1908 ,SNR2: 16.591




0821+394 2025/09/26 22.89UT FUJI -KISO



T20250927080309





BLK: 7, SNR1: 0.64271 , SNR2: 3.7372





0834-19 2025/09/26 23.08UT TOYOKAWA-FUJI



F20250927080311




BLK: 7, SNR1: 0.78424 , SNR2: 2.7035



T20250927080309




BLK:15,SNR1: 2.2110 ,SNR2: 6.5645





0834-19 2025/09/26 23.08UT TOYOKAWA-KISO


K20250927080308




BLK:15,SNR1: 2.0042 ,SNR2: 6.2016





F20250927080311




BLK:11,SNR1: 2.1964 ,SNR2: 5.7595




K20250927080308





BLK:11,SNR1: 1.5081 ,SNR2: 4.7988




0834-19 2025/09/26 23.08UT FUJI -KISO





T20250927080815




BLK: 3, SNR1: 2.7696 , SNR2: 7.0164




F20250927080817



BLK: 3, SNR1: 11.884 , SNR2: 27.628





0839-071 2025/09/26 23.17UT TOYOKAWA-FUJI








T20250927080815




BLK: 5, SNR1: 10.592 ,SNR2: 26.102




K20250927080814





BLK: 5, SNR1: 9.0995 ,SNR2: 22.214




0839-071 2025/09/26 23.17UT TOYOKAWA-KISO




F20250927080817




BLK: 8, SNR1: 10.335 ,SNR2: 24.167




K20250927080814




BLK: 8, SNR1: 12.483 ,SNR2: 30.362





0839-071 2025/09/26 23.17UT FUJI -KISO







BLK:11,SNR1: 2.2381 ,SNR2: 7.3818








BLK:11,SNR1: 129.30 ,SNR2: 150.03




3C208 2025/09/26 23.35UT TOYOKAWA-FUJI






F20250927081918





BLK:15,SNR1: 137.62 ,SNR2: 144.01





3C208 2025/09/26 23.35UT FUJI -KISO



K20250927081915




BLK:15,SNR1: 7.4397 ,SNR2: 19.257




T20250927083558




BLK: 3,SNR1: 0.27034E-01,SNR2: 0.60957




F20250927083600




BLK: 3,SNR1: 4.3592 ,SNR2: 10.579




3C216 2025/09/26 23.63UT TOYOKAWA-FUJI





T20250927083558




BLK: 6, SNR1: 0.75221 , SNR2: 3.1954




K20250927083557




BLK: 6, SNR1: 8.1207 , SNR2: 22.819




3C216 2025/09/26 23.63UT TOYOKAWA-KISO





F20250927083600




BLK: 5, SNR1: 4.3904 , SNR2: 12.146




K20250927083557



BLK: 5, SNR1: 7.3846 , SNR2: 20.725




3C216 2025/09/26 23.63UT FUJI -KISO







T20250927085320




BLK: 8, SNR1: 7.8572 , SNR2: 21.717




F20250927085322





BLK: 8, SNR1: 7.0753 , SNR2: 17.971





0923+392 2025/09/26 23.92UT TOYOKAWA-FUJI




T20250927085320




K20250927085319




0923+392 2025/09/26 23.92UT TOYOKAWA-KISO





F20250927085322




BLK:11,SNR1: 3.5897 ,SNR2: 10.446




K20250927085319





BLK:11,SNR1: 9.3520 ,SNR2: 23.629




0923+392 2025/09/26 23.92UT FUJI -KISO





T20250927090232




BLK: 8,SNR1: 1.1551 ,SNR2: 3.1016




F20250927090234









BLK: 8,SNR1:-0.17676 ,SNR2: 1.9093





3C222 2025/09/27 0.07UT TOYOKAWA-FUJI









BLK: 5,SNR1: 0.75889E-01,SNR2: 2.2545





BLK: 5,SNR1: 2.1824 ,SNR2: 6.2347




3C222 2025/09/27 0.07UT FUJI -KISO



T20250927090932





BLK:14,SNR1: 3.2821 ,SNR2: 7.5284




Frequency (Hz)

F20250927090934




BLK:14,SNR1: 0.53625 ,SNR2: 2.6829





Frequency (Hz)


0941-08 2025/09/27 0.19UT TOYOKAWA-FUJI





T20250927090932




BLK:18,SNR1: 6.5295 ,SNR2: 14.222




K20250927090931



BLK:18,SNR1: 9.2041 ,SNR2: 19.703




0941-08 2025/09/27 0.19UT TOYOKAWA-KISO








F20250927090934




BLK:20,SNR1: 0.90140 ,SNR2: 3.7386




K20250927090931







BLK:20,SNR1: 8.0658 ,SNR2: 17.845









0941-08 2025/09/27 0.19UT FUJI -KISO








3C230 2025/09/27 0.33UT TOYOKAWA-FUJI









BLK: 9,SNR1: 5.2260 ,SNR2: 15.149




BLK: 9,SNR1: 8.6224 ,SNR2: 22.017




3C230 2025/09/27 0.33UT FUJI -KISO





T20250927093355




BLK:23,SNR1: 1.7637 ,SNR2: 9.0875




F20250927093357







BLK:23,SNR1: 1.3485 ,SNR2: 5.4554








3C237 2025/09/27 0.59UT TOYOKAWA-FUJI






3C237 2025/09/27 0.59UT TOYOKAWA-KISO








3C237 2025/09/27 0.59UT FUJI -KISO





T20250927094011




BLK: 6,SNR1: 0.20721E-01,SNR2: 0.77940




F20250927094013







BLK: 6,SNR1: 1.6975 ,SNR2: 4.1380




1011+110 2025/09/27 0.70UT TOYOKAWA-FUJI










1011+110 2025/09/27 0.70UT TOYOKAWA-KISO




F20250927094013




BLK: 6, SNR1: 4.2403 , SNR2: 9.9338




K20250927094010





BLK: 6, SNR1: 7.6845 , SNR2: 22.155




1011+110 2025/09/27 0.70UT FUJI -KISO





T20250927094752




BLK:17,SNR1: 8.2768 ,SNR2: 14.461




F20250927094754





BLK:17,SNR1: 20.052 ,SNR2: 21.620




3C241 2025/09/27 0.83UT TOYOKAWA-FUJI





T20250927094752




BLK:17,SNR1: 8.4014 ,SNR2: 14.677




K20250927094751





BLK:17,SNR1: 8.2893 ,SNR2: 14.891




3C241 2025/09/27 0.83UT TOYOKAWA-KISO





F20250927094754




BLK:19,SNR1: 9.2893 ,SNR2: 16.247




K20250927094751





BLK:19,SNR1: 8.2429 ,SNR2: 14.809




3C241 2025/09/27 0.83UT FUJI -KISO



T20250927095921




BLK: 4, SNR1: 0.25369 , SNR2: 0.84449




Frequency (Hz)

1031-11 2025/09/27 1.02UT TOYOKAWA-FUJI


F20250927095923





BLK: 4, SNR1: -0.15343 , SNR2: 2.3783




Frequency (Hz)





T20250927095921




BLK: 5, SNR1: 0.17114 , SNR2: 2.4057




K20250927095920




BLK: 5, SNR1: 0.98075 , SNR2: 4.3750




1031-11 2025/09/27 1.02UT TOYOKAWA-KISO




F20250927095923




BLK: 7, SNR1: -0.37403 , SNR2: 0.13134




K20250927095920



BLK: 7, SNR1: 1.2760 , SNR2: 2.5250




1031-11 2025/09/27 1.02UT FUJI -KISO








T20250927100355




BLK: 7, SNR1: 10.112 , SNR2: 29.083




F20250927100357




BLK: 7, SNR1: 4.8054 , SNR2: 12.112




1035-058 2025/09/27 1.09UT TOYOKAWA-FUJI





T20250927100355




BLK:11,SNR1: 9.3878 ,SNR2: 24.260




K20250927100354







BLK:11,SNR1: 8.8617 ,SNR2: 21.507




1035-058 2025/09/27 1.09UT TOYOKAWA-KISO








1035-058 2025/09/27 1.09UT FUJI -KISO





T20250927101308




BLK: 9, SNR1: 9.8058 , SNR2: 17.505




F20250927101310





BLK: 9, SNR1: 0.16766 , SNR2: 3.0327




1044-008 2025/09/27 1.25UT TOYOKAWA-FUJI



T20250927101308





BLK:12,SNR1: 9.4484 ,SNR2: 16.887










1044-008 2025/09/27 1.25UT TOYOKAWA-KISO





K20250927101307




BLK:12,SNR1: 8.0177 ,SNR2: 20.748












1055+01 2025/09/27 1.43UT TOYOKAWA-FUJI







1055+01 2025/09/27 1.43UT TOYOKAWA-KISO








F20250927102414




BLK:18,SNR1: 9.3217 ,SNR2: 19.327




K20250927102411




BLK:18,SNR1: 3.8944 ,SNR2: 11.304




1055+01 2025/09/27 1.43UT FUJI -KISO





T20250927103530




BLK: 1, SNR1: 0.38304 , SNR2: 3.5207




F20250927103532





BLK: 1, SNR1: 1.3072 , SNR2: 7.5235




1107+109 2025/09/27 1.62UT TOYOKAWA-FUJI





T20250927103530




BLK: 3,SNR1: 0.31326 ,SNR2: 2.8759




K20250927103529





BLK: 3,SNR1: 1.7455 ,SNR2: 5.8865




1107+109 2025/09/27 1.62UT TOYOKAWA-KISO





F20250927103532




BLK: 5, SNR1: 0.91224 , SNR2: 3.8548




K20250927103529




BLK: 5, SNR1: 1.5859 , SNR2: 5.7480




1107+109 2025/09/27 1.62UT FUJI -KISO





T20250927104507




BLK:25,SNR1: 3.4583 ,SNR2: 10.288




F20250927104509




BLK:25,SNR1: 0.35944 ,SNR2: 4.1160




3C255 2025/09/27 1.78UT TOYOKAWA-FUJI



T20250927104507




BLK:23,SNR1: 2.1282 ,SNR2: 8.6217





3C255 2025/09/27 1.78UT TOYOKAWA-KISO


K20250927104506




BLK:23,SNR1: 1.3477 ,SNR2: 3.7970





F20250927104509




BLK:20,SNR1: 0.60954 ,SNR2: 5.9341




K20250927104506








BLK:20,SNR1: 1.6130 ,SNR2: 4.4487




3C255 2025/09/27 1.78UT FUJI -KISO













BLK:22,SNR1: 0.79054 ,SNR2: 2.9932




BLK:22,SNR1: 0.18208 ,SNR2: 1.0478




1127-14 2025/09/27 1.96UT TOYOKAWA-KISO




F20250927105547




BLK:10,SNR1:-0.14179 ,SNR2: 1.3045




K20250927105544





BLK:10,SNR1: 0.12441 ,SNR2: 1.9045




1127-14 2025/09/27 1.96UT FUJI -KISO



T20250927110905





BLK: 8,SNR1: 3.2501 ,SNR2: 19.226




Frequency (Hz)

F20250927110907




BLK: 8,SNR1: 1.1178 ,SNR2: 4.9203




Frequency (Hz)


3C263.1 2025/09/27 2.18UT TOYOKAWA-FUJI





T20250927110905




BLK:14,SNR1: 4.5339 ,SNR2: 54.157




K20250927110904




BLK:14,SNR1: 0.43751 ,SNR2: 1.4611




3C263.1 2025/09/27 2.18UT TOYOKAWA-KISO





F20250927110907




BLK: 8,SNR1: 0.56384 ,SNR2: 5.1478




K20250927110904




BLK: 8,SNR1: 1.0126 ,SNR2: 2.6684




3C263.1 2025/09/27 2.18UT FUJI -KISO




T20250927111532




BLK:12,SNR1: 2.3968 ,SNR2: 7.4631




F20250927111534





BLK:12,SNR1: 1.5918 ,SNR2: 4.3813




3C267 2025/09/27 2.29UT TOYOKAWA-FUJI




T20250927111532




BLK:19,SNR1: 9.6086 ,SNR2: 20.123




K20250927111531





BLK:19,SNR1: 5.8560 ,SNR2: 15.187




3C267 2025/09/27 2.29UT TOYOKAWA-KISO





F20250927111534




BLK:24,SNR1: 0.72727 ,SNR2: 2.4850




K20250927111531








BLK:24,SNR1: 6.6381 ,SNR2: 11.709




3C267 2025/09/27 2.29UT FUJI -KISO













BLK:23,SNR1: 3.5590 ,SNR2: 10.559




BLK:23,SNR1: 2.7067 ,SNR2: 8.3207





1213-17 2025/09/27 2.72UT TOYOKAWA-KISO







BLK:21,SNR1: 7.8320 ,SNR2: 12.305




BLK:21,SNR1: 7.5559 ,SNR2: 13.443




1213-17 2025/09/27 2.72UT FUJI -KISO




T20250927115437




BLK:12,SNR1: 7.3496 ,SNR2: 8.4473




F20250927115439




BLK:12,SNR1: 0.11597 ,SNR2: 1.8468




3C273 2025/09/27 2.94UT TOYOKAWA-FUJI





T20250927115437




BLK:11,SNR1: 5.9045 ,SNR2: 9.6821




K20250927115436




BLK:11,SNR1: 4.6435 ,SNR2: 7.9523




3C273 2025/09/27 2.94UT TOYOKAWA-KISO





F20250927115439




BLK:13,SNR1: 0.14723 ,SNR2: 1.9973




K20250927115436




BLK:13,SNR1: 4.1447 ,SNR2: 8.1965





3C273 2025/09/27 2.94UT FUJI -KISO







BLK:10,SNR1: 1.4431 ,SNR2: 4.0651




BLK:10,SNR1: 1.3301 ,SNR2: 4.5452





3C275 2025/09/27 3.16UT TOYOKAWA-FUJI







BLK:16,SNR1: 1.0472 ,SNR2: 3.3348



BLK:16,SNR1: 3.0060 ,SNR2: 6.0300




3C275 2025/09/27 3.16UT TOYOKAWA-KISO







F20250927120750




BLK: 4,SNR1: 2.8377 ,SNR2: 8.6136




K20250927120747




BLK: 4,SNR1: 0.90277 ,SNR2: 3.6080





3C275 2025/09/27 3.16UT FUJI -KISO







BLK:13,SNR1: 1.4704 ,SNR2: 4.4296




BLK:13,SNR1: 4.9328 ,SNR2: 11.582





1245-19 2025/09/27 3.26UT TOYOKAWA-FUJI







BLK:22,SNR1: 2.5867 ,SNR2: 7.5830




BLK:22,SNR1: 12.231 ,SNR2: 17.868




1245-19 2025/09/27 3.26UT TOYOKAWA-KISO




F20250927121355




BLK:24,SNR1: 7.0808 ,SNR2: 10.812




K20250927121352









BLK:24,SNR1: 9.2474 ,SNR2: 20.419





1245-19 2025/09/27 3.26UT FUJI -KISO









BLK:15,SNR1: 4.2315 ,SNR2: 9.8423




BLK:15,SNR1: 8.5482 ,SNR2: 20.429





3C279 2025/09/27 3.39UT TOYOKAWA-KISO







BLK: 9,SNR1: 5.9685 ,SNR2: 14.596




BLK: 9,SNR1: 8.5131 ,SNR2: 20.361





3C279 2025/09/27 3.39UT FUJI -KISO








BLK:24,SNR1: 1.2972 ,SNR2: 5.0387





BLK:24,SNR1: 0.58158 ,SNR2: 5.9073









BLK:26,SNR1: 1.0781 ,SNR2: 7.1242




BLK:26,SNR1: 0.82258 ,SNR2: 2.5863





3C283 2025/09/27 3.65UT TOYOKAWA-KISO







BLK:29,SNR1: 0.24065 ,SNR2: 3.5073





BLK:29,SNR1: 0.77042 ,SNR2: 3.5915




3C283 2025/09/27 3.65UT FUJI -KISO





T20250927125130




BLK:15,SNR1: 0.35408 ,SNR2: 3.9703




F20250927125132





BLK:15,SNR1:-0.20676E-01,SNR2: 1.1087




1323+32 2025/09/27 3.89UT TOYOKAWA-FUJI





T20250927125130




BLK:19,SNR1: 0.43816 ,SNR2: 3.4801




K20250927125129





BLK:19,SNR1: 0.22899 ,SNR2: 2.3548




1323+32 2025/09/27 3.89UT TOYOKAWA-KISO




F20250927125132




BLK:11,SNR1: 0.56554 ,SNR2: 1.7646




K20250927125129




BLK:11,SNR1: 0.30197 ,SNR2: 3.3840





1323+32 2025/09/27 3.89UT FUJI -KISO









BLK:32,SNR1: 3.8194 ,SNR2: 22.906




BLK:32,SNR1: 0.30891 ,SNR2: 1.5685





T20250927125620




BLK:28,SNR1: 4.5084 ,SNR2: 27.853




K20250927125619




BLK:28,SNR1: 0.69492 ,SNR2: 2.0604





3C286 2025/09/27 3.97UT TOYOKAWA-KISO







BLK:22,SNR1: 0.35461 ,SNR2: 1.3277



BLK:22,SNR1: 0.72762 ,SNR2: 2.1320




3C286 2025/09/27 3.97UT FUJI -KISO








T20250927131248




BLK:26,SNR1: 2.8978 ,SNR2: 10.003




F20250927131250





BLK:26,SNR1: 0.38431 ,SNR2: 1.8557




1345+12 2025/09/27 4.24UT TOYOKAWA-FUJI




T20250927131248




BLK:30,SNR1: 2.5531 ,SNR2: 9.1192




K20250927131247




BLK:30,SNR1: 0.46369 ,SNR2: 3.2562




1345+12 2025/09/27 4.24UT TOYOKAWA-KISO





F20250927131250




BLK:23,SNR1: 0.41604 ,SNR2: 1.9339




K20250927131247





BLK:23,SNR1: 0.62689 ,SNR2: 3.2424




1345+12 2025/09/27 4.24UT FUJI -KISO




T20250927132308




BLK:13,SNR1: 0.75138 ,SNR2: 2.1464




F20250927132310





BLK:13,SNR1: 1.4559 ,SNR2: 11.077




1355+01 2025/09/27 4.41UT TOYOKAWA-FUJI





T20250927132308




BLK:17,SNR1: 0.99069 ,SNR2: 4.1939




K20250927132307




BLK:17,SNR1: 3.0351 ,SNR2: 7.8580







1355+01 2025/09/27 4.41UT TOYOKAWA-KISO




F20250927132310






K20250927132307




T20250927134419




F20250927134421





3C298 2025/09/27 4.77UT TOYOKAWA-FUJI







BLK:32,SNR1: 2.9787 ,SNR2: 17.223



BLK:32,SNR1: 0.44470 ,SNR2: 1.6681





3C298 2025/09/27 4.77UT TOYOKAWA-KISO








F20250927134421




BLK:19,SNR1: 0.26325 ,SNR2: 2.9472




K20250927134418





BLK:19,SNR1: 0.48448 ,SNR2: 2.0314





3C298 2025/09/27 4.77UT FUJI -KISO







1428-03 2025/09/27 4.96UT TOYOKAWA-FUJI







BLK:10,SNR1: 0.10465 ,SNR2: 1.1567





BLK:10,SNR1: 8.7861 ,SNR2: 15.692




1428-03 2025/09/27 4.96UT TOYOKAWA-KISO





F20250927135604




BLK:16,SNR1: 1.0514 ,SNR2: 5.5081




K20250927135601








BLK:16,SNR1: 8.2821 ,SNR2: 18.279





1428-03 2025/09/27 4.96UT FUJI -KISO








T20250927140205




BLK: 5,SNR1: 0.11604 ,SNR2: 1.1487




K20250927140204




BLK: 5,SNR1: 4.8120 ,SNR2: 15.010





1434+03 2025/09/27 5.06UT TOYOKAWA-KISO









BLK: 4,SNR1: 2.0360 ,SNR2: 5.6469




BLK: 4,SNR1: 1.1317 ,SNR2: 5.2655





T20250927142107




BLK: 7,SNR1: 0.28663 ,SNR2: 1.5337




F20250927142109




BLK: 7,SNR1: 0.91929E-01,SNR2: 2.7201





1453-10 2025/09/27 5.38UT TOYOKAWA-FUJI









BLK:11,SNR1: 0.13722 ,SNR2: 1.0476




BLK:11,SNR1: 1.5031 ,SNR2: 5.0424





1453-10 2025/09/27 5.38UT TOYOKAWA-KISO








BLK: 9,SNR1: 1.2598 ,SNR2: 4.5877





BLK: 9,SNR1: 5.8663 ,SNR2: 14.102







BLK: 7,SNR1: 0.15533E-01,SNR2: 0.80331




BLK: 7,SNR1: 1.9832 ,SNR2: 9.3985





1508-05 2025/09/27 5.63UT TOYOKAWA-FUJI







BLK: 4,SNR1: 0.10742 ,SNR2: 0.27884




BLK: 4,SNR1: 4.2275 ,SNR2: 11.731





1508-05 2025/09/27 5.63UT TOYOKAWA-KISO







BLK: 4,SNR1: 3.3232 ,SNR2: 16.248




BLK: 4,SNR1: 1.1524 ,SNR2: 3.0068





1508-05 2025/09/27 5.63UT FUJI -KISO







BLK:11,SNR1: 0.17641 ,SNR2: 1.3405




BLK:11,SNR1: 0.47431 ,SNR2: 2.9228





3C318 2025/09/27 5.78UT TOYOKAWA-FUJI







BLK:11,SNR1: 0.15148 ,SNR2: 1.6560




BLK:11,SNR1: 0.79930 ,SNR2: 2.3079





3C318 2025/09/27 5.78UT TOYOKAWA-KISO







BLK:11,SNR1: 0.31555 ,SNR2: 4.2607



BLK:11,SNR1: 0.88069 ,SNR2: 1.7597





3C318 2025/09/27 5.78UT FUJI -KISO








T20250927145046




BLK: 7,SNR1: 0.45513 ,SNR2: 1.6706




F20250927145048





BLK: 7,SNR1: 0.60916 ,SNR2: 3.4775




1523+03 2025/09/27 5.87UT TOYOKAWA-FUJI





T20250927145046




BLK:10,SNR1: 0.41001 ,SNR2: 1.0606




K20250927145045





BLK:10,SNR1: 1.0506 ,SNR2: 2.7226




1523+03 2025/09/27 5.87UT TOYOKAWA-KISO









1523+03 2025/09/27 5.87UT FUJI -KISO




T20250927150225





F20250927150227




1535+139 2025/09/27 6.07UT TOYOKAWA-FUJI





T20250927150225




BLK: 6,SNR1: 2.4940 ,SNR2: 7.9127




K20250927150224




BLK: 6,SNR1: 1.6540 ,SNR2: 3.9713




1535+139 2025/09/27 6.07UT TOYOKAWA-KISO




F20250927150227




BLK:14,SNR1: 1.4332 ,SNR2: 3.2212




K20250927150224




BLK:14,SNR1: 0.66087 ,SNR2: 1.3953





1535+139 2025/09/27 6.07UT FUJI -KISO







BLK: 6,SNR1: 5.3594 ,SNR2: 13.990




BLK: 6,SNR1:-0.77538E-01,SNR2: 1.7811





1545-12 2025/09/27 6.24UT TOYOKAWA-FUJI







BLK:18,SNR1: 4.8263 ,SNR2: 8.7243








BLK:18,SNR1: 7.8848 ,SNR2: 20.449





1545-12 2025/09/27 6.24UT TOYOKAWA-KISO








T20250927153352





BLK: 1,SNR1: 0.15238E-01,SNR2: 0.70891




Frequency (Hz)

F20250927153354




BLK: 1,SNR1: 6.9399 ,SNR2: 20.770





Frequency (Hz)


1607+26 2025/09/27 6.59UT TOYOKAWA-FUJI




T20250927153352




BLK: 3,SNR1: 0.11679 ,SNR2: 0.49226




K20250927153351




BLK: 3,SNR1: 4.8560 ,SNR2: 14.707




1607+26 2025/09/27 6.59UT TOYOKAWA-KISO




F20250927153354




BLK: 1,SNR1: 6.9397 ,SNR2: 20.770




K20250927153351




BLK: 1,SNR1: 1.6979 ,SNR2: 4.6249




1607+26 2025/09/27 6.59UT FUJI -KISO



T20250927155124





BLK: 3,SNR1: 0.21159 ,SNR2: 0.77362




Frequency (Hz)

F20250927155126








BLK: 3,SNR1: 3.6089 ,SNR2: 12.546




Frequency (Hz)






1623-228 2025/09/27 6.88UT TOYOKAWA-FUJI








1623-228 2025/09/27 6.88UT TOYOKAWA-KISO









BLK: 2,SNR1: 8.9082 ,SNR2: 22.250



BLK: 2,SNR1: 8.2488 ,SNR2: 20.095




1631-222 2025/09/27 7.03UT TOYOKAWA-FUJI







T20250927155954




BLK: 2,SNR1: 0.50388 ,SNR2: 2.9374




K20250927155953




BLK: 2,SNR1: 0.44636 ,SNR2: 3.4561





1631-222 2025/09/27 7.03UT TOYOKAWA-KISO







BLK: 5,SNR1: 13.096 ,SNR2: 28.682




BLK: 5,SNR1: 14.626 ,SNR2: 30.603





1631-222 2025/09/27 7.03UT FUJI -KISO







BLK:11,SNR1: 0.58350 ,SNR2: 2.0860




BLK:11,SNR1: 6.0829 ,SNR2: 17.363





1638-025 2025/09/27 7.12UT TOYOKAWA-FUJI







BLK:15,SNR1: 0.51934 ,SNR2: 2.7965












BLK:15,SNR1: 3.1123 ,SNR2: 5.0247




1638-025 2025/09/27 7.12UT TOYOKAWA-KISO

















1644-106 2025/09/27 7.24UT TOYOKAWA-FUJI







1644-106 2025/09/27 7.24UT TOYOKAWA-KISO








T20250927161746





BLK: 3, SNR1: 0.14002 , SNR2: 0.61696




Frequency (Hz)

F20250927161748




BLK: 3, SNR1: -0.24799 , SNR2: 0.13603





Frequency (Hz)


1650+004 2025/09/27 7.32UT TOYOKAWA-FUJI



T20250927161746




BLK: 4, SNR1: 0.12767 , SNR2: 0.90799




Frequency (Hz)

K20250927161745




BLK: 4, SNR1: 1.1069 , SNR2: 3.3734





Frequency (Hz)


1650+004 2025/09/27 7.32UT TOYOKAWA-KISO



F20250927161748




BLK: 3, SNR1: -0.18483 , SNR2: 2.6889




Frequency (Hz)

K20250927161745





BLK: 3, SNR1: 0.18552 , SNR2: 3.5914





Frequency (Hz)

1650+004 2025/09/27 7.32UT FUJI -KISO







BLK: 5,SNR1:-0.18748E-03,SNR2: 0.12461





BLK: 5,SNR1: 4.3789 ,SNR2: 33.543




1656+053 2025/09/27 7.42UT TOYOKAWA-FUJI





T20250927162317




BLK: 3,SNR1:-0.84913E-01,SNR2: 0.0000




K20250927162316





BLK: 3,SNR1: 1.4198 ,SNR2: 4.6940




1656+053 2025/09/27 7.42UT TOYOKAWA-KISO





F20250927162319




BLK: 6,SNR1: 2.5555 ,SNR2: 15.429




K20250927162316







BLK: 6,SNR1: 0.46073E-01,SNR2: 0.31707





1656+053 2025/09/27 7.42UT FUJI -KISO







1712-033 2025/09/27 7.69UT TOYOKAWA-FUJI







BLK:27,SNR1: 10.282 ,SNR2: 18.235




BLK:27,SNR1: 8.0201 ,SNR2: 25.128





1712-033 2025/09/27 7.69UT TOYOKAWA-KISO









BLK:19,SNR1: 7.6718 ,SNR2: 23.681





BLK:19,SNR1: 8.0869 ,SNR2: 25.330




1712-033 2025/09/27 7.69UT FUJI -KISO



T20250927165750





BLK: 3,SNR1: 1.5696 ,SNR2: 4.8340




Frequency (Hz)

F20250927165752





BLK: 3,SNR1: 7.7308 ,SNR2: 13.938





Frequency (Hz)

1730-13 2025/09/27 7.99UT TOYOKAWA-FUJI







BLK: 3,SNR1: 1.6714 ,SNR2: 5.0650




BLK: 3,SNR1: 2.6440 ,SNR2: 8.0524





1730-13 2025/09/27 7.99UT TOYOKAWA-KISO





BLK: 4, SNR1: 7.3067 , SNR2: 13.185



BLK: 4, SNR1: 2.8152 , SNR2: 8.5164

