




T20251007063117




BLK: 3, SNR1: 0.16728 , SNR2: 1.9734




F20251007063119




BLK: 3, SNR1: 1.3767 , SNR2: 3.9811




0741-06 2025/10/06 21.55UT TOYOKAWA-FUJI





T20251007063117




BLK: 2,SNR1: 0.67381E-01,SNR2: 1.4120




K20251007063114




BLK: 2,SNR1: 2.3071 ,SNR2: 5.9915




0741-06 2025/10/06 21.55UT TOYOKAWA-KISO




F20251007063119




BLK: 3,SNR1: 4.0116 ,SNR2: 9.4753




K20251007063114





BLK: 3,SNR1: 6.3317 ,SNR2: 18.644




0741-06 2025/10/06 21.55UT FUJI -KISO




T20251007064101




BLK: 8,SNR1:-0.72275E-01,SNR2: 1.4065




F20251007064103





BLK: 8,SNR1: 2.7161 ,SNR2: 7.3716




0752-200 2025/10/06 21.71UT TOYOKAWA-FUJI





T20251007064101




BLK: 6,SNR1:-0.41220E-01,SNR2: 1.2595




K20251007064058




BLK: 6,SNR1: 3.9127 ,SNR2: 10.375




0752-200 2025/10/06 21.71UT TOYOKAWA-KISO





F20251007064103




BLK: 7,SNR1: 1.7996 ,SNR2: 6.4265




K20251007064058





BLK: 7,SNR1: 3.7874 ,SNR2: 9.1583




0752-200 2025/10/06 21.71UT FUJI -KISO





T20251007064837




BLK: 9,SNR1: 9.7266 ,SNR2: 24.645




F20251007064839




BLK: 9,SNR1: 7.5860 ,SNR2: 20.405





3C190 2025/10/06 21.84UT TOYOKAWA-FUJI







BLK: 3,SNR1: -0.56115×10^{-2} ,SNR2: 0.70074





BLK: 3,SNR1: 7.7791 ,SNR2: 19.850




3C190 2025/10/06 21.84UT TOYOKAWA-KISO





F20251007064839




BLK: 8, SNR1: 11.173 , SNR2: 26.451




K20251007064834










BLK: 8, SNR1: 10.663 , SNR2: 25.756




3C190 2025/10/06 21.84UT FUJI -KISO










3C196 2025/10/06 22.05UT TOYOKAWA-KISO







BLK: 4,SNR1: 7.3372 ,SNR2: 20.632







BLK: 4,SNR1: 4.6626 ,SNR2: 11.926




3C196 2025/10/06 22.05UT FUJI -KISO








0821+394 2025/10/06 22.23UT TOYOKAWA-FUJI





T20251007071211




BLK: 7, SNR1: 0.78451 , SNR2: 3.2705




K20251007071208








BLK: 7, SNR1: 8.0708 , SNR2: 20.894





0821+394 2025/10/06 22.23UT TOYOKAWA-KISO







T20251007072350




BLK: 6,SNR1: 0.82957E-01,SNR2: 1.6903




F20251007072352





BLK: 6,SNR1: 0.44581 ,SNR2: 5.5274




0834-19 2025/10/06 22.43UT TOYOKAWA-FUJI





T20251007072350




BLK: 2,SNR1: 4.6927 ,SNR2: 13.918




K20251007072347




BLK: 2,SNR1: 5.1635 ,SNR2: 12.605




0834-19 2025/10/06 22.43UT TOYOKAWA-KISO





F20251007072352




BLK: 2,SNR1: 0.25504 ,SNR2: 3.5683




K20251007072347




BLK: 2,SNR1: 1.5999 ,SNR2: 5.0448




0834-19 2025/10/06 22.43UT FUJI -KISO





T20251007072856




BLK:14,SNR1: 8.3651 ,SNR2: 20.930




F20251007072858




BLK:14,SNR1: 7.7951 ,SNR2: 20.562




0839-071 2025/10/06 22.51UT TOYOKAWA-FUJI





T20251007072856




BLK:10,SNR1: 4.8842 ,SNR2: 12.765




K20251007072853




BLK:10,SNR1: 10.601 ,SNR2: 26.151




0839-071 2025/10/06 22.51UT TOYOKAWA-KISO





F20251007072858




BLK: 7, SNR1: 9.1271 ,SNR2: 24.092




K20251007072853







BLK: 7, SNR1: 11.300 ,SNR2: 27.548









0839-071 2025/10/06 22:51UT FUJI -KISO






3C208 2025/10/06 22.69UT TOYOKAWA-FUJI







F20251007073959




BLK: 7,SNR1: 0.86306 ,SNR2: 2.8945




K20251007073954





BLK: 7,SNR1: 6.1568 ,SNR2: 15.644




3C208 2025/10/06 22.69UT FUJI -KISO




T20251007075639




BLK: 6,SNR1: 0.77920E-01,SNR2: 0.57034




F20251007075641





BLK: 6,SNR1: 0.67873 ,SNR2: 3.1209




3C216 2025/10/06 22.97UT TOYOKAWA-FUJI





T20251007075639




No.Good Data




K20251007075636





No.Good Data




3C216 2025/10/06 22.97UT TOYOKAWA-KISO




F20251007075641




BLK: 3,SNR1: 0.27888 ,SNR2: 2.1448




K20251007075636





BLK: 3,SNR1: 0.21575 ,SNR2: 0.96813




3C216 2025/10/06 22.97UT FUJI -KISO




T20251007080849




BLK: 5,SNR1: 0.13291 ,SNR2: 0.81215




F20251007080851





BLK: 5,SNR1: 0.81984E-01,SNR2: 2.4129




0919-142 2025/10/06 23.18UT TOYOKAWA-FUJI




T20251007080849




BLK: 9,SNR1: 0.68649E-04,SNR2: 0.82813




K20251007080846




BLK: 9,SNR1: 1.4020 ,SNR2: 4.9056




0919-142 2025/10/06 23.18UT TOYOKAWA-KISO




F20251007080851




BLK: 9,SNR1: 0.82934 ,SNR2: 3.2709




K20251007080846





BLK: 9,SNR1: 1.7646 ,SNR2: 4.5725




0919-142 2025/10/06 23.18UT FUJI -KISO




T20251007081529




BLK: 9, SNR1: 1.9608 , SNR2: 6.5143




F20251007081531





BLK: 9, SNR1: 10.076 , SNR2: 22.732




0926+117 2025/10/06 23.29UT TOYOKAWA-FUJI





T20251007081529




BLK:10,SNR1: 1.6066 ,SNR2: 4.3388




K20251007081526




BLK:10,SNR1: 2.7846 ,SNR2: 8.6043




0926+117 2025/10/06 23.29UT TOYOKAWA-KISO





F20251007081531




BLK:19,SNR1: 9.9443 ,SNR2: 22.456




K20251007081526





BLK:19,SNR1: 2.7948 ,SNR2: 8.6262




0926+117 2025/10/06 23.29UT FUJI -KISO




T20251007082313




BLK: 2, SNR1: 4.0010 , SNR2: 25.597




F20251007082315




BLK: 2, SNR1: -0.14069 , SNR2: 0.39937





3C222 2025/10/06 23.42UT TOYOKAWA-FUJI







BLK: 7,SNR1: 0.39760E-01,SNR2: 0.73178






BLK: 7,SNR1: 0.62357 ,SNR2: 2.1084





3C222 2025/10/06 23.42UT TOYOKAWA-KISO








T20251007083013




BLK: 5, SNR1: 0.38411 , SNR2: 2.9723




F20251007083015





BLK: 5, SNR1: 2.4395 , SNR2: 6.2787




0941-08 2025/10/06 23.53UT TOYOKAWA-FUJI




T20251007083013




BLK:12,SNR1: 0.53793 ,SNR2: 2.1821




K20251007083010




BLK:12,SNR1: 8.5334 ,SNR2: 20.996




0941-08 2025/10/06 23.53UT TOYOKAWA-KISO




F20251007083015




BLK:12,SNR1: 5.6744 ,SNR2: 16.713




K20251007083010









BLK:12,SNR1: 7.4199 ,SNR2: 21.435





0941-08 2025/10/06 23.53UT FUJI -KISO









BLK: 1, SNR1: 0.60186 , SNR2: 1.6507




BLK: 1, SNR1: 6.5712 , SNR2: 17.813




3C230 2025/10/06 23.67UT TOYOKAWA-KISO




F20251007083837




BLK: 3,SNR1: 6.7160 ,SNR2: 19.991




K20251007083832




BLK: 3,SNR1: 8.1182 ,SNR2: 20.448





3C230 2025/10/06 23.67UT FUJI -KISO







BLK:14,SNR1: 0.32177 ,SNR2: 2.1813








BLK:14,SNR1: 5.3478 ,SNR2: 13.630





3C236 2025/10/06 23.91UT TOYOKAWA-FUJI







F20251007085245




BLK:15,SNR1: 3.9130 ,SNR2: 9.4923




K20251007085240





BLK:15,SNR1: 5.4430 ,SNR2: 14.016




3C236 2025/10/06 23.91UT FUJI -KISO




T20251007090052




BLK: 3, SNR1: 13.676 , SNR2: 29.805




F20251007090054





BLK: 3, SNR1: 6.9810 , SNR2: 17.139




1011+110 2025/10/07 0.04UT TOYOKAWA-FUJI





T20251007090052




BLK: 2,SNR1: 3.0580 ,SNR2: 10.665




K20251007090049







BLK: 2,SNR1: 0.58926E-01,SNR2: 3.3055








1011+110 2025/10/07 0.04UT TOYOKAWA-KISO






1011+110 2025/10/07 0.04UT FUJI -KISO







3C241 2025/10/07 0.17UT TOYOKAWA-FUJI





T20251007090833




BLK: 4, SNR1: 0.25003 , SNR2: 1.9096




K20251007090830







BLK: 4, SNR1: 3.3114 , SNR2: 7.6024




3C241 2025/10/07 0.17UT TOYOKAWA-KISO







3C241 2025/10/07 0.17UT FUJI -KISO





T20251007092002




BLK: 2, SNR1: 5.9668 , SNR2: 15.370




F20251007092004




BLK: 2, SNR1: 5.9855 , SNR2: 15.286




1031-11 2025/10/07 0.36UT TOYOKAWA-FUJI




T20251007092002




BLK: 1, SNR1: 29.646 , SNR2: 35.049




K20251007091959




BLK: 1, SNR1: 52.130 , SNR2: 54.584




1031-11 2025/10/07 0.36UT TOYOKAWA-KISO




F20251007092004




BLK: 1, SNR1: 20.822 , SNR2: 33.950




K20251007091959





BLK: 1, SNR1: 5.0502 , SNR2: 17.937




1031-11 2025/10/07 0.36UT FUJI -KISO




T20251007092436




BLK:13,SNR1: 3.1074 ,SNR2: 9.8031




F20251007092436





BLK:13,SNR1: 17.437 ,SNR2: 38.265




1035-058 2025/10/07 0.44UT TOYOKAWA-FUJI



T20251007092436




BLK:13,SNR1: 32.587 ,SNR2: 63.012





1035-058 2025/10/07 0.44UT TOYOKAWA-KISO


K20251007092433




BLK:13,SNR1: 40.293 ,SNR2: 46.522




F20251007092438




BLK:15,SNR1: 26.110 ,SNR2: 29.313




K20251007092433




BLK:15,SNR1: 8.2318 ,SNR2: 21.255




1035-058 2025/10/07 0.44UT FUJI -KISO




T20251007093349




BLK: 1, SNR1: 6.2746 , SNR2: 16.246




F20251007093351




BLK: 1, SNR1: 2.0011 , SNR2: 6.6222




1044-008 2025/10/07 0.59UT TOYOKAWA-FUJI





T20251007093349




BLK: 8, SNR1: 11.824 , SNR2: 25.877




K20251007093346




BLK: 8, SNR1: 46.938 , SNR2: 53.232




1044-008 2025/10/07 0.59UT TOYOKAWA-KISO





F20251007093351




BLK: 3, SNR1: 41.411 , SNR2: 47.283




K20251007093346





BLK: 3, SNR1: 5.4059 , SNR2: 19.276




1044-008 2025/10/07 0.59UT FUJI -KISO



T20251007094453





BLK: 2, SNR1: 12.636 , SNR2: 21.448





1055+01 2025/10/07 0.78UT TOYOKAWA-FUJI



F20251007094455




BLK: 2, SNR1: 16.190 , SNR2: 27.357




T20251007094453




BLK: 4, SNR1: 15.279 , SNR2: 25.858




K20251007094450





BLK: 4, SNR1: 14.901 , SNR2: 24.257




1055+01 2025/10/07 0.78UT TOYOKAWA-KISO



F20251007094455




BLK: 1, SNR1: 15.177 , SNR2: 32.704





1055+01 2025/10/07 0.78UT FUJI -KISO



K20251007094450




BLK: 1, SNR1: 5.5894 , SNR2: 18.979





T20251007095611




BLK: 7, SNR1: 3.3420 , SNR2: 16.004




F20251007095613








BLK: 7, SNR1: 7.3704 , SNR2: 19.820





1107+109 2025/10/07 0.96UT TOYOKAWA-FUJI








F20251007095613




BLK:18,SNR1: 1.3498 ,SNR2: 3.6352




K20251007095608







BLK:18,SNR1: 5.4859 ,SNR2: 11.943








1107+109 2025/10/07 0.96UT FUJI -KISO











3C255 2025/10/07 1.12UT TOYOKAWA-FUJI








3C255 2025/10/07 1.12UT TOYOKAWA-KISO

















1127-14 2025/10/07 1.30UT TOYOKAWA-FUJI
















1127-14 2025/10/07 1.30UT FUJI -KISO






3C263.1 2025/10/07 1.52UT TOYOKAWA-FUJI







3C263.1 2025/10/07 1.52UT TOYOKAWA-KISO




F20251007102948




BLK: 7, SNR1: 9.5561 , SNR2: 20.727




K20251007102944





BLK: 7, SNR1: 9.3964 , SNR2: 25.017




3C263.1 2025/10/07 1.52UT FUJI -KISO





T20251007103613




BLK: 8, SNR1: 0.41111 , SNR2: 2.7719




F20251007103615





BLK: 8, SNR1: 2.7686 , SNR2: 5.0334




3C267 2025/10/07 1.63UT TOYOKAWA-FUJI





T20251007103613




No. Good Data




K20251007103611





No. Good Data




3C267 2025/10/07 1.63UT TOYOKAWA-KISO



F20251007103615




BLK: 3,SNR1: 0.75120 ,SNR2: 4.7443








3C267 2025/10/07 1.63UT FUJI -KISO






K20251007103611




BLK: 3,SNR1: 0.40985E-02,SNR2: 1.3263









F20251007110203




BLK: 3,SNR1: 20.899 ,SNR2: 44.245




K20251007110158




BLK: 3,SNR1: 14.219 ,SNR2: 23.660




1213-17 2025/10/07 2.06UT FUJI -KISO




T20251007111518




BLK: 8,SNR1: 25.812 ,SNR2: 47.110




F20251007111518




BLK: 8,SNR1: 8.0828 ,SNR2: 16.688




3C273 2025/10/07 2.28UT TOYOKAWA-FUJI




T20251007111518




BLK:15,SNR1: 31.073 ,SNR2: 84.309




K20251007111515




BLK:15,SNR1: 15.278 ,SNR2: 31.415




3C273 2025/10/07 2.28UT TOYOKAWA-KISO




F20251007111518




BLK: 5, SNR1: 8.7370 , SNR2: 17.722




K20251007111515








BLK: 5, SNR1: 17.395 , SNR2: 36.366





3C273 2025/10/07 2.28UT FUJI -KISO







T20251007113434




BLK:30,SNR1: 82.287 ,SNR2: 150.46




K20251007113431







BLK:30,SNR1: 15.748 ,SNR2: 28.123





1245-19 2025/10/07 2.60UT TOYOKAWA-KISO







1245-19 2025/10/07 2.60UT FUJI -KISO







BLK: 6,SNR1: 2.7559 ,SNR2: 7.9790





BLK: 6,SNR1: 3.5423 ,SNR2: 11.750




3C283 2025/10/07 2.99UT TOYOKAWA-FUJI




T20251007115747




BLK:10,SNR1: 2.1329 ,SNR2: 6.0223




K20251007115744




BLK:10,SNR1: 3.9364 ,SNR2: 17.493




3C283 2025/10/07 2.99UT TOYOKAWA-KISO



F20251007115747




BLK: 6, SNR1: 0.58621 , SNR2: 3.6667





3C283 2025/10/07 2.99UT FUJI -KISO


K20251007115744




BLK: 6, SNR1: 2.2856 , SNR2: 6.0870





T20251007121211




BLK: 8,SNR1: 10.043 ,SNR2: 17.392




F20251007121211








BLK: 8,SNR1: 8.7850 ,SNR2: 22.427





1323+32 2025/10/07 3.23UT TOYOKAWA-FUJI






F20251007121211




BLK: 6, SNR1: 3.0729 , SNR2: 9.3385





1323+32 2025/10/07 3.23UT FUJI -KISO



K20251007121208




BLK: 6, SNR1: 16.223 , SNR2: 28.579





T20251007121701




BLK:24,SNR1: 3.7475 ,SNR2: 15.631




F20251007121701





BLK:24,SNR1: 4.0159 ,SNR2: 10.507




3C286 2025/10/07 3.31UT TOYOKAWA-FUJI




T20251007121701




BLK:12,SNR1: 3.7542 ,SNR2: 10.961




K20251007121658




BLK:12,SNR1: 4.1683 ,SNR2: 10.783




3C286 2025/10/07 3.31UT TOYOKAWA-KISO




F20251007121701




BLK: 7,SNR1: 2.7283 ,SNR2: 8.4663




K20251007121658




BLK: 7,SNR1: 5.6858 ,SNR2: 14.477




3C286 2025/10/07 3.31UT FUJI -KISO




T20251007123329




BLK: 5, SNR1: 16.077 , SNR2: 28.170




F20251007123329




BLK: 5, SNR1: 9.1383 , SNR2: 22.485




1345+12 2025/10/07 3.59UT TOYOKAWA-FUJI




T20251007123329




BLK: 3,SNR1: 6.7199 ,SNR2: 16.771




K20251007123326




BLK: 3,SNR1: 19.668 ,SNR2: 34.655




1345+12 2025/10/07 3.59UT TOYOKAWA-KISO




F20251007123329




BLK: 1, SNR1: 9.4012 , SNR2: 23.395




K20251007123326




BLK: 1, SNR1: 10.805 , SNR2: 26.489





1345+12 2025/10/07 3.59UT FUJI -KISO







BLK: 3,SNR1: 11.723 ,SNR2: 28.350





BLK: 3,SNR1: 18.755 ,SNR2: 33.611




1355+01 2025/10/07 3.76UT TOYOKAWA-FUJI



T20251007124349





No.Good Data




Frequency (Hz)

K20251007124346




No.Good Data





Frequency (Hz)


1355+01 2025/10/07 3.76UT TOYOKAWA-KISO





F20251007124350




No.Good Data




K20251007124346




No.Good Data




1355+01 2025/10/07 3.76UT FUJI -KISO




T20251007130500




BLK:26,SNR1: 5.0747 ,SNR2: 38.354




F20251007130501









BLK:26,SNR1: 0.97310 ,SNR2: 8.3084





3C298 2025/10/07 4.11UT TOYOKAWA-FUJI








T20251007131643





BLK: 2,SNR1: 22.551 ,SNR2: 40.299




Frequency (Hz)

F20251007131643







BLK: 2,SNR1: 14.109 ,SNR2: 25.259






Frequency (Hz)


1428-03 2025/10/07 4.31UT TOYOKAWA-FUJI










T20251007132246




BLK:11,SNR1: 8.5644 ,SNR2: 22.009




F20251007132247









BLK:11,SNR1: 15.510 ,SNR2: 37.533




1434+03 2025/10/07 4.41UT TOYOKAWA-FUJI









T20251007134148




BLK: 2,SNR1: 3.5480 ,SNR2: 15.078




F20251007134148









BLK: 2,SNR1: 37.377 ,SNR2: 42.169











1453-10 2025/10/07 4.72UT TOYOKAWA-FUJI























BLK: 2,SNR1: 7.8154 ,SNR2: 19.749









BLK: 2,SNR1: 6.5009 ,SNR2: 16.349





3C318 2025/10/07 5.12UT TOYOKAWA-FUJI









T20251007141127




BLK: 3,SNR1: 1.1132 ,SNR2: 6.0627




F20251007141127









BLK: 3,SNR1: 5.6045 ,SNR2: 19.918








1523+03 2025/10/07 5.22UT TOYOKAWA-FUJI

















1535+139 2025/10/07 5.41UT TOYOKAWA-KISO








T20251007143612




BLK: 3,SNR1: 0.15461 ,SNR2: 0.49862




F20251007143612









BLK: 3,SNR1: 3.0265 ,SNR2: 15.657





1548+05 2025/10/07 5.63UT TOYOKAWA-FUJI









T20251007145433




BLK: 4,SNR1: 1.7510 ,SNR2: 4.5572




F20251007145433









BLK: 4,SNR1: 2.9170 ,SNR2: 9.1014




1607+26 2025/10/07 5.94UT TOYOKAWA-FUJI













BLK: 9,SNR1: 2.0797 ,SNR2: 4.6479









BLK: 9,SNR1: 1.6081 ,SNR2: 6.6663





1623-228 2025/10/07 6.23UT TOYOKAWA-FUJI










T20251007152035




BLK:13,SNR1: 49.302 ,SNR2: 75.915




F20251007152035









BLK:13,SNR1: 41.517 ,SNR2: 79.737




1631-222 2025/10/07 6.37UT TOYOKAWA-FUJI













BLK: 2,SNR1: 24.547 ,SNR2: 77.274









BLK: 2,SNR1: 1.4068 ,SNR2: 8.5763





1638-025 2025/10/07 6.46UT TOYOKAWA-FUJI










T20251007153306




BLK: 5,SNR1: 0.96710 ,SNR2: 7.5186




F20251007153306









BLK: 5,SNR1: 4.1093 ,SNR2: 14.370





1644-106 2025/10/07 6.58UT TOYOKAWA-FUJI








T20251007153827





BLK: 2,SNR1: 38.296 ,SNR2: 70.131




Frequency (Hz)

F20251007153827







BLK: 2,SNR1: 3.4964 ,SNR2: 16.536







Frequency (Hz)

1650+004 2025/10/07 6.67UT TOYOKAWA-FUJI













BLK: 2,SNR1: 0.42739 ,SNR2: 1.5209









BLK: 2,SNR1: 0.61867 ,SNR2: 1.6091









1656+053 2025/10/07 6.76UT TOYOKAWA-FUJI



















T20251007161831





BLK: 3,SNR1: 0.10544 ,SNR2: 0.44662




Frequency (Hz)

F20251007161831







BLK: 3,SNR1: 0.41348 ,SNR2: 3.2218











Frequency (Hz)




1730-13 2025/10/07 7.34UT TOYOKAWA-FUJI






















BLK: 2,SNR1: 0.72817E-01,SNR2: 0.54765



Frequency (Hz)



BLK: 2,SNR1: 2.1743 ,SNR2: 5.4202



Frequency (Hz)

1759+13 2025/10/07 7.81UT TOYOKAWA-FUJI

