

















BLK: 4, SNR1: 1.2310 , SNR2: 4.3673








BLK: 4, SNR1: 5.5204 , SNR2: 13.632





0727-115 2025/10/09 21.12UT TOYOKAWA-KISO










T20251010061929




BLK: 8,SNR1: 8.7651 ,SNR2: 25.013




F20251010061929





BLK: 8,SNR1: 10.639 ,SNR2: 26.645




0741-06 2025/10/09 21.35UT TOYOKAWA-FUJI




T20251010061929




BLK: 2, SNR1: 7.5538 , SNR2: 21.859




K20251010061927





BLK: 2, SNR1: 8.0274 , SNR2: 20.535




0741-06 2025/10/09 21.35UT TOYOKAWA-KISO




F20251010061929




BLK: 8, SNR1: 10.687 , SNR2: 26.767




K20251010061927




BLK: 8, SNR1: 9.0839 , SNR2: 22.677





0741-06 2025/10/09 21.35UT FUJI -KISO







BLK:11,SNR1: 2.8894 ,SNR2: 3.8841




BLK:11,SNR1: 0.44282 ,SNR2: 2.6475





0752-200 2025/10/09 21.52UT TOYOKAWA-FUJI







BLK: 9,SNR1: 2.3762 ,SNR2: 13.063







BLK: 9,SNR1: 6.2930 ,SNR2: 14.767






0752-200 2025/10/09 21.52UT TOYOKAWA-KISO







0752-200 2025/10/09 21.52UT FUJI -KISO







BLK: 8, SNR1: 3.2695 , SNR2: 8.9814







BLK: 8, SNR1: 1.4144 , SNR2: 4.2329




3C190 2025/10/09 21.64UT TOYOKAWA-FUJI
















3C190 2025/10/09 21.64UT TOYOKAWA-KISO









3C190 2025/10/09 21.64UT FUJI -KISO










0806-103 2025/10/09 21.76UT TOYOKAWA-FUJI










T20251010070024




BLK: 6,SNR1: 0.61941 ,SNR2: 3.5242




F20251010070025





BLK: 6,SNR1: 0.91219 ,SNR2: 3.3596




0821+394 2025/10/09 22.03UT TOYOKAWA-FUJI





T20251010070024




BLK: 4,SNR1: 0.68652E-01,SNR2: 0.46350




K20251010070022






BLK: 4,SNR1: 2.5150 ,SNR2: 7.5637





0821+394 2025/10/09 22.03UT TOYOKAWA-KISO













BLK: 7,SNR1: 0.46987E-01,SNR2: 1.4525





BLK: 7,SNR1: 0.41847E-01,SNR2: 0.78641






0834-19 2025/10/09 22.23UT TOYOKAWA-FUJI







BLK: 5, SNR1: 0.23505E-01, SNR2: 1.2335




BLK: 5, SNR1: 1.0619, SNR2: 3.4902






0834-19 2025/10/09 22.23UT TOYOKAWA-KISO







BLK: 5, SNR1: 0.63091 , SNR2: 1.6299




BLK: 5, SNR1: 1.0679 , SNR2: 4.1922




0834-19 2025/10/09 22.23UT FUJI -KISO





T20251010071708




BLK:13,SNR1: 2.1044 ,SNR2: 7.7087




F20251010071708




BLK:13,SNR1: 7.7869 ,SNR2: 24.272




0839-071 2025/10/09 22.31UT TOYOKAWA-FUJI




T20251010071708




BLK:11,SNR1: 9.8797 ,SNR2: 24.777




K20251010071705







BLK:11,SNR1: 8.4219 ,SNR2: 21.972






0839-071 2025/10/09 22.31UT TOYOKAWA-KISO








0839-071 2025/10/09 22.31UT FUJI -KISO







BLK: 4,SNR1: 0.23192 ,SNR2: 1.2290




BLK: 4,SNR1: 7.6342 ,SNR2: 19.410





3C208 2025/10/09 22.50UT TOYOKAWA-FUJI







BLK: 7, SNR1: 0.14725 , SNR2: 0.96604







BLK: 7, SNR1: 9.2060 , SNR2: 23.234




3C208 2025/10/09 22.50UT TOYOKAWA-KISO










3C208 2025/10/09 22.50UT FUJI -KISO





T20251010074451




BLK:11,SNR1: 0.20015 ,SNR2: 1.0504




F20251010074451





BLK:11,SNR1: 7.2304 ,SNR2: 14.778




3C216 2025/10/09 22.78UT TOYOKAWA-FUJI





T20251010074451




BLK:10,SNR1: 0.45278 ,SNR2: 1.2690




K20251010074448





BLK:10,SNR1: 9.9470 ,SNR2: 21.465




3C216 2025/10/09 22.78UT TOYOKAWA-KISO





F20251010074451




BLK: 8, SNR1: 6.1939 ,SNR2: 13.186




K20251010074448





BLK: 8, SNR1: 10.102 ,SNR2: 21.789







3C216 2025/10/09 22.78UT FUJI -KISO






0923+392 2025/10/09 23.07UT TOYOKAWA-FUJI







F20251010080214




BLK: 2, SNR1: 5.6871 , SNR2: 15.798




K20251010080212




BLK: 2, SNR1: 8.2440 , SNR2: 21.082





0923+392 2025/10/09 23.07UT FUJI -KISO







BLK: 5, SNR1: 20.383 , SNR2: 65.411



BLK: 5, SNR1: 23.216 , SNR2: 26.711




3C222 2025/10/09 23.22UT TOYOKAWA-FUJI







T20251010081126




No.Good Data




K20251010081123





No.Good Data




3C222 2025/10/09 23.22UT TOYOKAWA-KISO



F20251010081126





BLK: 1,SNR1: 0.39903 ,SNR2: 4.2615




Frequency (Hz)

3C222 2025/10/09 23.22UT FUJI -KISO


K20251010081123





BLK: 1,SNR1: 2.4902 ,SNR2: 6.5395




Frequency (Hz)





T20251010081826




BLK: 7,SNR1: 27.293 ,SNR2: 56.131




F20251010081826





BLK: 7,SNR1: 4.1037 ,SNR2: 7.2074




0941-08 2025/10/09 23.34UT TOYOKAWA-FUJI





T20251010081826




BLK: 9,SNR1: 55.675 ,SNR2: 67.304




K20251010081823




BLK: 9,SNR1: 9.9445 ,SNR2: 15.293




0941-08 2025/10/09 23.34UT TOYOKAWA-KISO




F20251010081826




BLK: 2, SNR1: 3.4428 , SNR2: 6.0819




K20251010081823








BLK: 2, SNR1: 2.7808 , SNR2: 8.4069





0941-08 2025/10/09 23.34UT FUJI -KISO






T20251010082648




BLK: 2, SNR1: 31.761 , SNR2: 53.395









3C230 2025/10/09 23.47UT TOYOKAWA-KISO

K20251010082645




BLK: 2, SNR1: 0.28985 , SNR2: 1.9696










3C230 2025/10/09 23.47UT FUJI -KISO










3C237 2025/10/09 23.74UT TOYOKAWA-FUJI





T20251010084248




BLK: 1, SNR1: 3.9459 , SNR2: 11.849




K20251010084246





BLK: 1, SNR1: 3.9150 , SNR2: 13.691




3C237 2025/10/09 23.74UT TOYOKAWA-KISO





F20251010084248




BLK: 1, SNR1: 7.7379 , SNR2: 17.752




K20251010084246





BLK: 1, SNR1: 4.3951 , SNR2: 14.883




3C237 2025/10/09 23.74UT FUJI -KISO




T20251010084905




BLK: 5,SNR1: 0.73606E-01,SNR2: 1.4413




F20251010084906





BLK: 5,SNR1: 1.5815 ,SNR2: 4.9719




1011+110 2025/10/09 23.85UT TOYOKAWA-FUJI




T20251010084905




BLK: 1,SNR1: 0.24440 ,SNR2: 0.54806




K20251010084902




BLK: 1,SNR1: 8.4705 ,SNR2: 14.199




1011+110 2025/10/09 23.85UT TOYOKAWA-KISO




F20251010084906




BLK: 1,SNR1:-0.66513E-01,SNR2: 1.0009




K20251010084902





BLK: 1,SNR1:-0.35924E-02,SNR2: 1.1097




1011+110 2025/10/09 23.85UT FUJI -KISO





T20251010090815




BLK: 1, SNR1: 21.129 ,SNR2: 35.655




F20251010090815





BLK: 1, SNR1: 21.286 ,SNR2: 34.408




1031-11 2025/10/10 0.17UT TOYOKAWA-FUJI




T20251010090815




BLK: 1, SNR1: 6.2558 , SNR2: 21.406




K20251010090813



BLK: 1, SNR1: 12.873 , SNR2: 28.061




1031-11 2025/10/10 0.17UT TOYOKAWA-KISO







F20251010090815




BLK: 1, SNR1: 9.9951 ,SNR2: 21.897




K20251010090813




BLK: 1, SNR1: 11.734 ,SNR2: 25.654





1031-11 2025/10/10 0.17UT FUJI -KISO








BLK: 8,SNR1: 19.376 ,SNR2: 56.463




BLK: 8,SNR1: 6.7339 ,SNR2: 9.6779





T20251010091248




BLK:13,SNR1: 3.8253 ,SNR2: 11.428




K20251010091246








BLK:13,SNR1: 2.1602 ,SNR2: 4.7111





1035-058 2025/10/10 0.24UT TOYOKAWA-KISO







T20251010092201




BLK: 4,SNR1: 47.176 ,SNR2: 66.139




F20251010092201




BLK: 4,SNR1: 25.340 ,SNR2: 41.234





1044-008 2025/10/10 0.40UT TOYOKAWA-FUJI







BLK: 5, SNR1: 57.105 , SNR2: 82.881




BLK: 5, SNR1: 28.556 , SNR2: 59.632




1044-008 2025/10/10 0.40UT TOYOKAWA-KISO



F20251010092201





BLK: 4, SNR1: 2.5785 , SNR2: 7.2153





1044-008 2025/10/10 0.40UT FUJI -KISO



K20251010092158




BLK: 4, SNR1: 60.153 , SNR2: 97.123




T20251010093305




BLK: 6,SNR1: 0.55164 ,SNR2: 2.4764




F20251010093306



BLK: 6,SNR1: 3.6289 ,SNR2: 8.7054





1055+01 2025/10/10 0.58UT TOYOKAWA-FUJI








T20251010093305




BLK: 9, SNR1: 0.50869 , SNR2: 2.2992




K20251010093302




BLK: 9, SNR1: 9.3915 , SNR2: 16.536




1055+01 2025/10/10 0.58UT TOYOKAWA-KISO





F20251010093306




BLK: 6, SNR1: 10.308 , SNR2: 18.204




K20251010093302




BLK: 6, SNR1: 6.9847 , SNR2: 15.959




1055+01 2025/10/10 0.58UT FUJI -KISO





T20251010094423




BLK: 8, SNR1: 76.690 , SNR2: 94.924




F20251010094423








BLK: 8, SNR1: 24.268 , SNR2: 24.888





1107+109 2025/10/10 0.77UT TOYOKAWA-FUJI







F20251010094423




BLK: 5, SNR1: 46.348 , SNR2: 75.950




K20251010094421







BLK: 5, SNR1: 10.198 , SNR2: 20.943





1107+109 2025/10/10 0.77UT FUJI -KISO







3C255 2025/10/10 0.93UT TOYOKAWA-FUJI







BLK: 3, SNR1: 2.1748 , SNR2: 5.6087





BLK: 3, SNR1: 5.1119 , SNR2: 12.809




3C255 2025/10/10 0.93UT TOYOKAWA-KISO



F20251010095401





BLK: 2, SNR1: 18.673 ,SNR2: 51.675





3C255 2025/10/10 0.93UT FUJI -KISO

K20251010095358





BLK: 2, SNR1: 2.2475 ,SNR2: 10.329







T20251010100438




BLK: 3, SNR1: 0.51962 , SNR2: 4.9418




F20251010100438





BLK: 3, SNR1: 11.109 , SNR2: 27.179




1127-14 2025/10/10 1.11UT TOYOKAWA-FUJI





T20251010100438




BLK: 2, SNR1: 0.65130 , SNR2: 2.9465




K20251010100435




BLK: 2, SNR1: 15.898 , SNR2: 27.549




1127-14 2025/10/10 1.11UT TOYOKAWA-KISO





F20251010100438




BLK: 4, SNR1: 6.0387 , SNR2: 18.443




K20251010100435







BLK: 4, SNR1: 7.2822 , SNR2: 17.911





1127-14 2025/10/10 1.11UT FUJI -KISO







3C263.1 2025/10/10 1.33UT TOYOKAWA-FUJI







BLK:12,SNR1: 1.0562 ,SNR2: 3.1759







BLK:12,SNR1: 11.873 ,SNR2: 30.887








3C263.1 2025/10/10 1.33UT TOYOKAWA-KISO











3C263.1 2025/10/10 1.33UT FUJI -KISO









3C267 2025/10/10 1.44UT TOYOKAWA-FUJI












3C267 2025/10/10 1.44UT FUJI -KISO



T20251010105013




BLK: 1, SNR1: 2.2998 , SNR2: 6.3854










1213-17 2025/10/10 1.87UT TOYOKAWA-FUJI

F20251010105013




BLK: 1, SNR1: 5.4859 , SNR2: 21.209








F20251010105013




BLK: 3, SNR1: 7.7558 , SNR2: 19.137




K20251010105010













BLK: 3, SNR1: 8.8024 , SNR2: 22.017




1213-17 2025/10/10 1.87UT FUJI -KISO









F20251010110331




BLK: 7, SNR1: 7.6078 , SNR2: 18.723




K20251010110327








BLK: 7, SNR1: 21.572 , SNR2: 38.245




3C273 2025/10/10 2.09UT FUJI -KISO













BLK: 7, SNR1: 64.660 , SNR2: 87.565




BLK: 7, SNR1: 23.868 , SNR2: 25.517




3C275 2025/10/10 2.31UT TOYOKAWA-KISO




F20251010111641




BLK: 3,SNR1: 9.7162 ,SNR2: 16.543




K20251010111638





BLK: 3,SNR1: 6.2984 ,SNR2: 24.094









3C275 2025/10/10 2.31UT FUJI -KISO










1245-19 2025/10/10 2.41UT TOYOKAWA-FUJI










1245-19 2025/10/10 2.41UT FUJI -KISO









BLK:19,SNR1: 1.0078 ,SNR2: 9.1398





BLK:19,SNR1: 8.7470 ,SNR2: 21.536




T20251010114559







K20251010114556




3C283 2025/10/10 2.79UT TOYOKAWA-KISO










3C283 2025/10/10 2.79UT FUJI -KISO












1323+32 2025/10/10 3.03UT TOYOKAWA-FUJI







1323+32 2025/10/10 3.03UT TOYOKAWA-KISO




F20251010120023




BLK: 2, SNR1: 8.8386 , SNR2: 21.930




K20251010120020




BLK: 2, SNR1: 11.177 , SNR2: 26.272





1323+32 2025/10/10 3.03UT FUJI -KISO







BLK:17,SNR1: 7.7872 ,SNR2: 13.865








BLK:17,SNR1: 0.41029 ,SNR2: 2.6397





3C286 2025/10/10 3.12UT TOYOKAWA-FUJI








F20251010120514




BLK:20,SNR1: 0.53155 ,SNR2: 3.0773




K20251010120511













BLK:20,SNR1: 3.3975 ,SNR2: 5.9175



3C286 2025/10/10 3.12UT FUJI -KISO













F20251010122141




BLK:19,SNR1: 8.3733 ,SNR2: 23.884




K20251010122138





BLK:19,SNR1: 9.0731 ,SNR2: 23.995




1345+12 2025/10/10 3.39UT FUJI -KISO





T20251010123201




No.Good Data




F20251010123202





No.Good Data




1355+01 2025/10/10 3.56UT TOYOKAWA-FUJI





T20251010123201




BLK: 2,SNR1: 10.052 ,SNR2: 17.232




K20251010123158




BLK: 2,SNR1: 9.7248 ,SNR2: 17.383




1355+01 2025/10/10 3.56UT TOYOKAWA-KISO





F20251010123202




BLK: 7, SNR1: 7.8565 , SNR2: 18.332




K20251010123158





BLK: 7, SNR1: 8.3332 , SNR2: 14.582




1355+01 2025/10/10 3.56UT FUJI -KISO



T20251010125312





BLK:20,SNR1: 21.208 ,SNR2: 48.780




Frequency (Hz)

F20251010125312





BLK:20,SNR1: 7.2630 ,SNR2: 18.118





Frequency (Hz)

3C298 2025/10/10 3.91UT TOYOKAWA-FUJI







BLK:15,SNR1: 6.2712 ,SNR2: 23.201





BLK:15,SNR1: 3.7217 ,SNR2: 10.622




3C298 2025/10/10 3.91UT TOYOKAWA-KISO





F20251010125312




BLK: 4,SNR1: 5.7296 ,SNR2: 14.476




K20251010125309






BLK: 4,SNR1: 1.9927 ,SNR2: 6.9646




3C298 2025/10/10 3.91UT FUJI -KISO













BLK: 1,SNR1: 0.31647 ,SNR2: 2.5853








BLK: 1,SNR1: 1.6060 ,SNR2: 4.8852





1428-03 2025/10/10 4.11UT TOYOKAWA-KISO








T20251010131058




BLK: 5,SNR1: 12.320 ,SNR2: 29.886




F20251010131059




BLK: 5,SNR1: 6.0162 ,SNR2: 15.283





1434+03 2025/10/10 4.21UT TOYOKAWA-FUJI







BLK: 4,SNR1: 12.112 ,SNR2: 29.758




BLK: 4,SNR1: 8.1843 ,SNR2: 20.282





1434+03 2025/10/10 4.21UT TOYOKAWA-KISO







BLK: 3,SNR1: 6.9510 ,SNR2: 18.284




BLK: 3,SNR1: 7.0359 ,SNR2: 18.224





1434+03 2025/10/10 4.21UT FUJI -KISO







BLK: 9,SNR1: 1.0418 ,SNR2: 3.2520




BLK: 9,SNR1: 0.21936 ,SNR2: 4.1544





1453-10 2025/10/10 4.53UT TOYOKAWA-FUJI







BLK:18,SNR1: 0.77805 ,SNR2: 2.4215




BLK:18,SNR1: 9.6384 ,SNR2: 16.665





1453-10 2025/10/10 4.53UT TOYOKAWA-KISO







BLK:15,SNR1: 0.65608E-01,SNR2: 2.4144




BLK:15,SNR1: 9.7807 ,SNR2: 16.915





1453-10 2025/10/10 4.53UT FUJI -KISO









BLK: 6,SNR1: 9.1075 ,SNR2: 26.807




BLK: 6,SNR1:-0.51598E-01,SNR2: 1.4167





1508-05 2025/10/10 4.78UT TOYOKAWA-FUJI







BLK: 9,SNR1: 9.0936 ,SNR2: 26.760





BLK: 9,SNR1: 9.3072 ,SNR2: 27.274




1508-05 2025/10/10 4.78UT TOYOKAWA-KISO





F20251010134453




BLK: 5,SNR1:-0.33947E-01,SNR2: 1.6604




K20251010134450





BLK: 5,SNR1: 9.6057 ,SNR2: 28.150




1508-05 2025/10/10 4.78UT FUJI -KISO





T20251010135352




BLK: 7,SNR1: 3.1292 ,SNR2: 8.5203




F20251010135352





BLK: 7,SNR1: 26.830 ,SNR2: 32.197




3C318 2025/10/10 4.93UT TOYOKAWA-FUJI




T20251010135352




BLK: 4,SNR1: 2.9553 ,SNR2: 9.3421




K20251010135349








BLK: 4,SNR1: 6.6916 ,SNR2: 17.501





3C318 2025/10/10 4.93UT TOYOKAWA-KISO








T20251010135939




BLK:12,SNR1: 1.1672 ,SNR2: 4.4373




F20251010135939





BLK:12,SNR1: 2.6198 ,SNR2: 6.6634




1523+03 2025/10/10 5.02UT TOYOKAWA-FUJI




T20251010135939




BLK:14,SNR1: 1.0910 ,SNR2: 2.9975




K20251010135936




BLK:14,SNR1: 2.9825 ,SNR2: 5.2900





1523+03 2025/10/10 5.02UT TOYOKAWA-KISO









BLK: 8,SNR1: 1.1741 ,SNR2: 4.3950





BLK: 8,SNR1: 4.2784 ,SNR2: 7.6039





1523+03 2025/10/10 5.02UT FUJI -KISO




T20251010141119





F20251010141119




1535+139 2025/10/10 5.22UT TOYOKAWA-FUJI



T20251010141119





No.Good Data




Frequency (Hz)

K20251010141116





No.Good Data





Frequency (Hz)

1535+139 2025/10/10 5.22UT TOYOKAWA-KISO








BLK: 2,SNR1: 4.7054 ,SNR2: 11.517




BLK: 2,SNR1: 0.52289 ,SNR2: 1.7206




T20251010142425




BLK: 5,SNR1: 131.05 ,SNR2: 136.44




F20251010142426




BLK: 5,SNR1: 13.402 ,SNR2: 24.077





1548+05 2025/10/10 5.44UT TOYOKAWA-FUJI







BLK: 4,SNR1: 13.897 ,SNR2: 40.015




BLK: 4,SNR1: 0.10744 ,SNR2: 3.5772





1548+05 2025/10/10 5.44UT TOYOKAWA-KISO







BLK: 3,SNR1: 0.12950 ,SNR2: 3.6751




BLK: 3,SNR1: 8.7812 ,SNR2: 15.026





1548+05 2025/10/10 5.44UT FUJI -KISO







BLK: 3,SNR1:-0.16334 ,SNR2: 0.22312




BLK: 3,SNR1: 0.25958 ,SNR2: 1.8735





1607+26 2025/10/10 5.74UT TOYOKAWA-FUJI









BLK: 4,SNR1:-0.45687E-01,SNR2: 0.78262





BLK: 4,SNR1: 0.10896 ,SNR2: 2.1133




1607+26 2025/10/10 5.74UT TOYOKAWA-KISO



F20251010144246





BLK: 4,SNR1: 0.39954 ,SNR2: 1.4104




Frequency (Hz)

K20251010144244







BLK: 4,SNR1: 0.76921 ,SNR2: 6.9101




Frequency (Hz)



1607+26 2025/10/10 5.74UT FUJI -KISO









BLK: 3,SNR1: 6.4202 ,SNR2: 15.513






BLK: 3,SNR1: 9.0842 ,SNR2: 22.697





1623-228 2025/10/10 6.03UT TOYOKAWA-KISO








T20251010150847




BLK: 4,SNR1: 4.7647 ,SNR2: 8.6374




F20251010150847




BLK: 4,SNR1: 16.173 ,SNR2: 28.299





1631-222 2025/10/10 6.17UT TOYOKAWA-FUJI







BLK: 8,SNR1: 229.75 ,SNR2: 256.30




BLK: 8,SNR1: 19.146 ,SNR2: 34.095





1631-222 2025/10/10 6.17UT TOYOKAWA-KISO







BLK: 5,SNR1: 9.0433 ,SNR2: 22.599








BLK: 5,SNR1: 10.239 ,SNR2: 25.157




1631-222 2025/10/10 6.17UT FUJI -KISO













BLK: 5,SNR1: 172.10 ,SNR2: 239.27





BLK: 5,SNR1: 0.67174 ,SNR2: 5.0785




1638-025 2025/10/10 6.27UT TOYOKAWA-KISO





F20251010151424




BLK: 8,SNR1: 0.16463 ,SNR2: 2.4505




K20251010151422






BLK: 8,SNR1: 0.41906 ,SNR2: 2.9988




1638-025 2025/10/10 6.27UT FUJI -KISO







T20251010152119




BLK: 3,SNR1: 9.3707 ,SNR2: 23.105




K20251010152117




BLK: 3,SNR1: 9.0099 ,SNR2: 22.152





1644-106 2025/10/10 6.38UT TOYOKAWA-KISO








BLK: 4,SNR1: 10.926 ,SNR2: 26.832





BLK: 4,SNR1: 8.7228 ,SNR2: 21.821







BLK: 1,SNR1: 0.22047E-01,SNR2: 0.44840





BLK: 1,SNR1: 0.56020E-01,SNR2: 4.1726






1650+004 2025/10/10 6.47UT TOYOKAWA-FUJI







BLK: 3,SNR1: 0.86107E-01,SNR2: 0.68402




BLK: 3,SNR1: 0.58100 ,SNR2: 2.4308





1650+004 2025/10/10 6.47UT TOYOKAWA-KISO













BLK: 5,SNR1: 0.29056E-01,SNR2: 0.91122





BLK: 5,SNR1: 0.30424 ,SNR2: 2.3539









BLK: 2,SNR1: 13.079 ,SNR2: 31.868





BLK: 2,SNR1: 1.6369 ,SNR2: 8.3233




1656+053 2025/10/10 6.56UT TOYOKAWA-KISO



F20251010153212





BLK: 3,SNR1: 12.373 ,SNR2: 30.203




Frequency (Hz)

K20251010153209




BLK: 3,SNR1: 10.086 ,SNR2: 24.766




Frequency (Hz)


1656+053 2025/10/10 6.56UT FUJI -KISO




T20251010154841




BLK: 7,SNR1: 22.587 ,SNR2: 57.371




F20251010154842







BLK: 7,SNR1: 0.26946E-01,SNR2: 1.8930




1712-033 2025/10/10 6.84UT TOYOKAWA-FUJI








1712-033 2025/10/10 6.84UT TOYOKAWA-KISO



F20251010154842





BLK: 9,SNR1: 0.67074 ,SNR2: 2.7603




Frequency (Hz)

K20251010154839





BLK: 9,SNR1: 0.75029 ,SNR2: 2.2395





Frequency (Hz)

1712-033 2025/10/10 6.84UT FUJI -KISO







BLK: 2,SNR1: 11.833 ,SNR2: 28.906







BLK: 2,SNR1: 7.6319 ,SNR2: 19.393




1730-13 2025/10/10 7.14UT TOYOKAWA-FUJI















1730-13 2025/10/10 7.14UT TOYOKAWA-KISO









BLK: 1,SNR1: 0.26792 ,SNR2: 0.39449





BLK: 1,SNR1:-0.36545 ,SNR2: 1.3746






1748+031 2025/10/10 7.43UT TOYOKAWA-FUJI







BLK: 1,SNR1: 0.12967E-01,SNR2: 0.85144




BLK: 1,SNR1:-0.42115E-01,SNR2: 1.1847





1748+031 2025/10/10 7.43UT TOYOKAWA-KISO







BLK: 2,SNR1: 0.23115E-01,SNR2: 1.4016




BLK: 2,SNR1:-0.13451E-01,SNR2: 0.96559





1748+031 2025/10/10 7.43UT FUJI -KISO







BLK: 1,SNR1: 0.26379 ,SNR2: 1.5729







BLK: 1,SNR1:-0.59506E-01,SNR2: 2.6075





1759+13 2025/10/10 7.61UT TOYOKAWA-FUJI







1759+13 2025/10/10 7.61UT TOYOKAWA-KISO







BLK: 3, SNR1: 0.64322 , SNR2: 2.0617








BLK: 3, SNR1: 1.2982 , SNR2: 3.5990







1759+13 2025/10/10 7.61UT FUJI -KISO















BLK: 3, SNR1: -0.16396 , SNR2: 1.1443





BLK: 3, SNR1: 0.31849 , SNR2: 3.1547




1819-096 2025/10/10 7.96UT FUJI -KISO



T20251010170717





BLK:14,SNR1: 2.6414 ,SNR2: 8.3528




Frequency (Hz)

F20251010170717




BLK:14,SNR1: 9.6917 ,SNR2: 20.753





Frequency (Hz)


1830-210 2025/10/10 8.15UT TOYOKAWA-FUJI



T20251010170717





BLK:18,SNR1: 2.6370 ,SNR2: 8.3403




Frequency (Hz)

K20251010170715




BLK:18,SNR1: 8.6233 ,SNR2: 15.227





Frequency (Hz)


1830-210 2025/10/10 8.15UT TOYOKAWA-KISO



F20251010170717





BLK:14,SNR1: 9.3835 ,SNR2: 20.119




Frequency (Hz)

K20251010170715



BLK:14,SNR1: 8.6232 ,SNR2: 15.227



Frequency (Hz)

1830-210 2025/10/10 8.15UT FUJI -KISO

