





T20251022060253




BLK: 1, SNR1: -0.17884 , SNR2: 0.69737




F20251022060254





BLK: 1, SNR1: 1.5777 , SNR2: 5.5483




0812-184 2025/10/21 21.08UT TOYOKAWA-FUJI



T20251022060253





No.Good Data




Frequency (Hz)

K20251022060251




No.Good Data





Frequency (Hz)

0812-184 2025/10/21 21.08UT TOYOKAWA-KISO








F20251022060254




No.Good Data




K20251022060251




No.Good Data





0812-184 2025/10/21 21.08UT FUJI -KISO







BLK:12,SNR1: 8.9064 ,SNR2: 11.462





BLK:12,SNR1: 9.6820 ,SNR2: 12.946




0825-202 2025/10/21 21.28UT TOYOKAWA-FUJI




T20251022061500




BLK: 6,SNR1: 2.9995 ,SNR2: 8.0865




K20251022061458




BLK: 6,SNR1: 15.556 ,SNR2: 27.156





0825-202 2025/10/21 21.28UT TOYOKAWA-KISO







BLK: 3, SNR1: 3.8550 , SNR2: 12.804




BLK: 3, SNR1: 19.604 , SNR2: 26.172





0825-202 2025/10/21 21.28UT FUJI -KISO







BLK: 4,SNR1: 0.14689 ,SNR2: 1.2639




BLK: 4,SNR1: 2.4837 ,SNR2: 6.9547





0830-118 2025/10/21 21.37UT TOYOKAWA-FUJI







BLK: 2,SNR1: 0.39117 ,SNR2: 2.3347





BLK: 2,SNR1: 7.9755 ,SNR2: 14.311




0830-118 2025/10/21 21.37UT TOYOKAWA-KISO





F20251022062015




BLK: 4, SNR1: 2.0988 , SNR2: 6.0340




K20251022062012





BLK: 4, SNR1: 3.0227 , SNR2: 8.0963




0830-118 2025/10/21 21.37UT FUJI -KISO




T20251022062452




BLK: 1, SNR1: 0.16061 , SNR2: 3.6013




F20251022062452



BLK: 1, SNR1: 1.6330 , SNR2: 5.9080





0834-19 2025/10/21 21.44UT TOYOKAWA-FUJI








T20251022062452




BLK: 1, SNR1: 0.16059 , SNR2: 3.6012




K20251022062450




BLK: 1, SNR1: 10.142 , SNR2: 27.061




0834-19 2025/10/21 21.44UT TOYOKAWA-KISO





F20251022062452




No.Good Data




K20251022062450





No.Good Data




0834-19 2025/10/21 21.44UT FUJI -KISO



T20251022062957





BLK: 4, SNR1: 1.3918 , SNR2: 6.1135




Frequency (Hz)

F20251022062957




BLK: 4, SNR1: 7.5752 , SNR2: 19.888





Frequency (Hz)


0839-071 2025/10/21 21.53UT TOYOKAWA-FUJI





T20251022062957




No.Good Data




K20251022062954




No.Good Data




0839-071 2025/10/21 21.53UT TOYOKAWA-KISO





F20251022062957




BLK: 7, SNR1: 8.6186 , SNR2: 18.468




K20251022062954




BLK: 7, SNR1: 9.0481 , SNR2: 23.362





0839-071 2025/10/21 21.53UT FUJI -KISO







BLK: 1,SNR1: 4.4542 ,SNR2: 14.651





BLK: 1,SNR1: 16.482 ,SNR2: 24.373




3C208 2025/10/21 21.71UT TOYOKAWA-FUJI



T20251022064059




No.Good Data




Frequency (Hz)

K20251022064057






No.Good Data




Frequency (Hz)

3C208 2025/10/21 21.71UT TOYOKAWA-KISO







3C208 2025/10/21 21.71UT FUJI -KISO






T20251022070224





BLK: 4, SNR1: 2.4184 , SNR2: 11.106




Frequency (Hz)

F20251022070224





BLK: 4, SNR1: 11.437 , SNR2: 27.672





Frequency (Hz)

0912-132 2025/10/21 22.07UT TOYOKAWA-FUJI







BLK: 4, SNR1: 2.4152 , SNR2: 11.095





BLK: 4, SNR1: 8.4197 , SNR2: 20.858




0912-132 2025/10/21 22.07UT TOYOKAWA-KISO



F20251022070224





BLK: 1, SNR1: 2.5184 ,SNR2: 11.698




Frequency (Hz)

K20251022070222






BLK: 1, SNR1: 8.9605 ,SNR2: 22.165




Frequency (Hz)


0912-132 2025/10/21 22.07UT FUJI -KISO







0919-142 2025/10/21 22.19UT TOYOKAWA-FUJI







BLK: 7,SNR1: 0.85085E-01,SNR2: 2.1808







BLK: 7,SNR1: 4.5979 ,SNR2: 7.5300




0919-142 2025/10/21 22.19UT TOYOKAWA-KISO








0919-142 2025/10/21 22.19UT FUJI -KISO




T20251022072415




BLK: 8,SNR1: 0.26356 ,SNR2: 1.8202




F20251022072416





BLK: 8,SNR1: 5.0626 ,SNR2: 9.0263




3C222 2025/10/21 22.43UT TOYOKAWA-FUJI





T20251022072415




BLK: 7,SNR1: 0.18626 ,SNR2: 1.7270




K20251022072413




BLK: 7,SNR1: 2.2281 ,SNR2: 6.9231





3C222 2025/10/21 22.43UT TOYOKAWA-KISO









BLK: 7,SNR1: 1.2698 ,SNR2: 6.6313




BLK: 7,SNR1: 2.4827 ,SNR2: 7.5525




3C222 2025/10/21 22.43UT FUJI -KISO



T20251022073115




BLK:12,SNR1: 10.159 ,SNR2: 18.026





0941-08 2025/10/21 22.55UT TOYOKAWA-FUJI


F20251022073115




BLK:12,SNR1: 9.0341 ,SNR2: 23.250





T20251022073115




BLK: 8, SNR1: 10.013 ,SNR2: 17.674




K20251022073113




BLK: 8, SNR1: 11.305 ,SNR2: 28.407




0941-08 2025/10/21 22.55UT TOYOKAWA-KISO





F20251022073115




BLK: 5, SNR1: 8.4954 , SNR2: 22.015




K20251022073113





BLK: 5, SNR1: 12.443 , SNR2: 30.974




0941-08 2025/10/21 22.55UT FUJI -KISO





T20251022073937




BLK: 2, SNR1: 0.34441 , SNR2: 1.1160




F20251022073938





BLK: 2, SNR1: 4.7623 , SNR2: 12.808




3C230 2025/10/21 22.69UT TOYOKAWA-FUJI




T20251022073937




BLK: 1,SNR1: 0.27119 ,SNR2: 1.2500




K20251022073935




BLK: 1,SNR1: 10.501 ,SNR2: 26.554




3C230 2025/10/21 22.69UT TOYOKAWA-KISO



F20251022073938




BLK: 1, SNR1: 1.8515 ,SNR2: 6.6090





3C230 2025/10/21 22.69UT FUJI -KISO


K20251022073935




BLK: 1, SNR1: 10.501 ,SNR2: 26.554





T20251022075537




BLK: 4, SNR1: 19.615 , SNR2: 21.523




F20251022075537



BLK: 4, SNR1: 10.376 , SNR2: 19.205




3C237 2025/10/21 22.96UT TOYOKAWA-FUJI







T20251022075537




BLK: 6, SNR1: 10.621 , SNR2: 24.540




K20251022075535







BLK: 6, SNR1: 11.049 , SNR2: 25.109









3C237 2025/10/21 22.96UT TOYOKAWA-KISO










3C237 2025/10/21 22.96UT FUJI -KISO

















1011+110 2025/10/21 23.06UT TOYOKAWA-KISO










1011+110 2025/10/21 23.06UT FUJI -KISO










F20251022080935




No.Good Data




K20251022080933



No.Good Data





3C241 2025/10/21 23.19UT FUJI -KISO






T20251022082104




BLK: 1,SNR1: 4.4037 ,SNR2: 18.300









1031-11 2025/10/21 23.38UT TOYOKAWA-FUJI

F20251022082105




BLK: 1,SNR1: 3.0306 ,SNR2: 10.947







1031-11 2025/10/21 23.38UT TOYOKAWA-KISO




F20251022082105




BLK: 9,SNR1: 9.4335 ,SNR2: 21.094




K20251022082102





BLK: 9,SNR1: 7.0637 ,SNR2: 18.361




1031-11 2025/10/21 23.38UT FUJI -KISO



T20251022082537




BLK: 9, SNR1: 11.588 ,SNR2: 28.203





1035-058 2025/10/21 23.46UT TOYOKAWA-FUJI



F20251022082537




BLK: 9, SNR1: 11.778 ,SNR2: 28.770




T20251022082537




BLK:13,SNR1: 9.6995 ,SNR2: 23.526




K20251022082535




BLK:13,SNR1: 15.060 ,SNR2: 36.135




1035-058 2025/10/21 23.46UT TOYOKAWA-KISO




F20251022082537




BLK: 3, SNR1: 7.1385 , SNR2: 19.071




K20251022082535





BLK: 3, SNR1: 16.287 , SNR2: 40.365




1035-058 2025/10/21 23.46UT FUJI -KISO



T20251022083450





BLK: 4, SNR1: 12.603 , SNR2: 60.627




Frequency (Hz)

F20251022083450




BLK: 4, SNR1: 8.4337 , SNR2: 20.794




Frequency (Hz)


1044-008 2025/10/21 23.61UT TOYOKAWA-FUJI





T20251022083450




BLK: 5, SNR1: 15.519 ,SNR2: 73.605




K20251022083448







BLK: 5, SNR1: 18.293 ,SNR2: 31.300




1044-008 2025/10/21 23.61UT TOYOKAWA-KISO













1044-008 2025/10/21 23.61UT FUJI -KISO












BLK: 3, SNR1: 0.10410 , SNR2: 1.1004





BLK: 3, SNR1: 2.4352 , SNR2: 11.522







T20251022085358




BLK:20,SNR1: 9.3672 ,SNR2: 25.358




F20251022085358





BLK:20,SNR1: 4.6926 ,SNR2: 12.009




1103-006 2025/10/21 23.93UT TOYOKAWA-FUJI





T20251022085358




BLK:22,SNR1: 9.1661 ,SNR2: 15.418




K20251022085356




BLK:22,SNR1: 9.0514 ,SNR2: 15.059




1103-006 2025/10/21 23.93UT TOYOKAWA-KISO




F20251022085358




BLK:11,SNR1: 6.8628 ,SNR2: 11.301




K20251022085356







BLK:11,SNR1: 21.830 ,SNR2: 25.311




1103-006 2025/10/21 23.93UT FUJI -KISO










3C255 2025/10/22 0.14UT TOYOKAWA-FUJI

















3C255 2025/10/22 0.14UT TOYOKAWA-KISO













1127-14 2025/10/22 0.32UT TOYOKAWA-FUJI







F20251022091728




BLK: 3, SNR1: 18.599 ,SNR2: 27.837




K20251022091725





BLK: 3, SNR1: 2.1665 ,SNR2: 10.360




1127-14 2025/10/22 0.32UT FUJI -KISO





T20251022093048




BLK:16,SNR1: 13.758 ,SNR2: 25.124




F20251022093049





BLK:16,SNR1: 96.654 ,SNR2: 106.64




3C263.1 2025/10/22 0.54UT TOYOKAWA-FUJI





T20251022093048




BLK:17,SNR1: 13.287 ,SNR2: 24.303




K20251022093046





BLK:17,SNR1: 65.185 ,SNR2: 70.771




3C263.1 2025/10/22 0.54UT TOYOKAWA-KISO





F20251022093049




BLK:31,SNR1: 97.755 ,SNR2: 107.27




K20251022093046




BLK:31,SNR1: 64.297 ,SNR2: 69.807





3C263.1 2025/10/22 0.54UT FUJI -KISO









BLK: 7, SNR1: 6.0613 ,SNR2: 9.8508




BLK: 7, SNR1: 3.6023 ,SNR2: 6.8719




3C267 2025/10/22 0.65UT TOYOKAWA-FUJI




T20251022093714




BLK:13,SNR1: 7.2382 ,SNR2: 12.895




K20251022093711







BLK:13,SNR1: 7.6559 ,SNR2: 13.651




3C267 2025/10/22 0.65UT TOYOKAWA-KISO







3C267 2025/10/22 0.65UT FUJI -KISO





T20251022100302




BLK: 4, SNR1: 3.1717 , SNR2: 8.4337




F20251022100303




BLK: 4, SNR1: 10.453 , SNR2: 22.296




1213-17 2025/10/22 1.08UT TOYOKAWA-FUJI



T20251022100302




BLK: 3,SNR1: 17.358 ,SNR2: 27.769






1213-17 2025/10/22 1.08UT TOYOKAWA-KISO

K20251022100259





BLK: 3,SNR1: 25.200 ,SNR2: 43.777







BLK: 1, SNR1: 4.3418 , SNR2: 12.787







BLK: 1, SNR1: 4.3379 , SNR2: 11.250








1213-17 2025/10/22 1.08UT FUJI -KISO






3C273 2025/10/22 1.30UT TOYOKAWA-FUJI










3C273 2025/10/22 1.30UT TOYOKAWA-KISO



















3C273 2025/10/22 1.30UT FUJI -KISO










F20251022102930




BLK: 8, SNR1: 0.43256 , SNR2: 2.3838




K20251022102927





BLK: 8, SNR1: 0.64393 , SNR2: 2.3695




3C275 2025/10/22 1.52UT FUJI -KISO




T20251022103535




BLK: 4, SNR1: 1.2716 , SNR2: 5.4857




F20251022103535




BLK: 4, SNR1: 23.064 , SNR2: 31.088




1245-19 2025/10/22 1.62UT TOYOKAWA-FUJI




T20251022103535




BLK: 2, SNR1: 2.0204 , SNR2: 17.287




K20251022103532




BLK: 2, SNR1: 2.9466 , SNR2: 13.671




1245-19 2025/10/22 1.62UT TOYOKAWA-KISO



F20251022103535




BLK: 3,SNR1: 27.357 ,SNR2: 36.606










1245-19 2025/10/22 1.62UT FUJI -KISO

K20251022103532




BLK: 3,SNR1: 28.577 ,SNR2: 39.449













BLK:16,SNR1: 4.2159 ,SNR2: 18.999





BLK:16,SNR1: 0.76410 ,SNR2: 1.3702




3C279 2025/10/22 1.75UT TOYOKAWA-KISO







3C279 2025/10/22 1.75UT FUJI -KISO




T20251022105849




BLK: 1, SNR1: 0.28126 , SNR2: 3.7498




F20251022105850




BLK: 1, SNR1: 21.534 , SNR2: 39.578




3C283 2025/10/22 2.01UT TOYOKAWA-FUJI




T20251022105849




BLK: 4, SNR1: 10.639 ,SNR2: 19.145




K20251022105846




BLK: 4, SNR1: 13.617 ,SNR2: 24.711




3C283 2025/10/22 2.01UT TOYOKAWA-KISO



F20251022105850




BLK: 3, SNR1: 15.273 , SNR2: 26.745










3C283 2025/10/22 2.01UT FUJI -KISO


K20251022105846





BLK: 3, SNR1: 19.556 , SNR2: 34.744









BLK:11,SNR1: 0.34160 ,SNR2: 3.0915





BLK:11,SNR1: 2.4854 ,SNR2: 6.0539




1323+32 2025/10/22 2.25UT TOYOKAWA-KISO
















1323+32 2025/10/22 2.25UT FUJI -KISO















BLK:10,SNR1: 0.84193 ,SNR2: 2.9324




BLK:10,SNR1: 7.0474 ,SNR2: 12.365





3C286 2025/10/22 2.33UT FUJI -KISO







BLK: 2,SNR1: 7.6058 ,SNR2: 19.135





BLK: 2,SNR1: 19.049 ,SNR2: 33.875




1345+12 2025/10/22 2.60UT TOYOKAWA-FUJI




T20251022113430




BLK: 3, SNR1: 10.095 , SNR2: 21.988




K20251022113427




BLK: 3, SNR1: 27.443 , SNR2: 46.308




1345+12 2025/10/22 2.60UT TOYOKAWA-KISO





F20251022113430




BLK: 3,SNR1: 2.5507 ,SNR2: 11.607




K20251022113427








BLK: 3,SNR1: 0.56563 ,SNR2: 4.2923




1345+12 2025/10/22 2.60UT FUJI -KISO







T20251022114451




BLK: 9,SNR1: 10.345 ,SNR2: 25.413




K20251022114448



BLK: 9,SNR1: 17.703 ,SNR2: 31.399




1355+01 2025/10/22 2.78UT TOYOKAWA-KISO







F20251022114451




BLK: 4,SNR1: 10.764 ,SNR2: 26.392




K20251022114448




BLK: 4,SNR1: 12.060 ,SNR2: 29.460





1355+01 2025/10/22 2.78UT FUJI -KISO







BLK: 7,SNR1: 7.1654 ,SNR2: 17.712




BLK: 7,SNR1: 15.351 ,SNR2: 27.043





3C298 2025/10/22 3.13UT TOYOKAWA-FUJI







BLK:14,SNR1: 2.4553 ,SNR2: 11.395





BLK:14,SNR1: 8.5301 ,SNR2: 21.097




3C298 2025/10/22 3.13UT TOYOKAWA-KISO





F20251022120601




BLK: 1,SNR1: 7.6940 ,SNR2: 18.078




K20251022120558





BLK: 1,SNR1: 0.28976 ,SNR2: 5.9474




3C298 2025/10/22 3.13UT FUJI -KISO




T20251022121745




BLK: 1,SNR1: 21.438 ,SNR2: 38.178




F20251022121745




BLK: 1,SNR1: 8.0749 ,SNR2: 20.385





1428-03 2025/10/22 3.32UT TOYOKAWA-FUJI







BLK: 1,SNR1: 0.73958 ,SNR2: 5.2106





BLK: 1,SNR1: 22.977 ,SNR2: 58.282




1428-03 2025/10/22 3.32UT TOYOKAWA-KISO



F20251022121745





No.Good Data




Frequency (Hz)

K20251022121742





No.Good Data





Frequency (Hz)

1428-03 2025/10/22 3.32UT FUJI -KISO







BLK: 4,SNR1: 23.728 ,SNR2: 41.829



BLK: 4,SNR1: 10.873 ,SNR2: 19.053





1434+03 2025/10/22 3.42UT TOYOKAWA-FUJI







T20251022122347




BLK: 1,SNR1: 24.805 ,SNR2: 43.734




K20251022122344




BLK: 1,SNR1: 0.64061 ,SNR2: 6.7914





1434+03 2025/10/22 3.42UT TOYOKAWA-KISO







BLK: 3,SNR1: 10.870 ,SNR2: 26.925




BLK: 3,SNR1: 10.525 ,SNR2: 18.498





1434+03 2025/10/22 3.42UT FUJI -KISO







BLK: 4,SNR1: 10.555 ,SNR2: 18.655




BLK: 4,SNR1: 14.753 ,SNR2: 23.592




1453-10 2025/10/22 3.74UT TOYOKAWA-FUJI





T20251022124250




BLK: 5, SNR1: 11.114 , SNR2: 19.640




K20251022124247




BLK: 5, SNR1: 180.94 , SNR2: 175.75





1453-10 2025/10/22 3.74UT TOYOKAWA-KISO







BLK: 7, SNR1: 15.250 , SNR2: 26.945





BLK: 7, SNR1: 123.65 , SNR2: 120.69




1453-10 2025/10/22 3.74UT FUJI -KISO





T20251022125742




BLK: 5,SNR1: 9.9816 ,SNR2: 17.055




F20251022125742




BLK: 5,SNR1: 10.368 ,SNR2: 22.298




1508-05 2025/10/22 3.99UT TOYOKAWA-FUJI




T20251022125742




BLK: 4,SNR1: 23.888 ,SNR2: 30.727




K20251022125739




BLK: 4,SNR1: 15.088 ,SNR2: 26.411




1508-05 2025/10/22 3.99UT TOYOKAWA-KISO




F20251022125742




BLK: 3,SNR1: 10.677 ,SNR2: 18.894




K20251022125739




BLK: 3,SNR1: 7.6127 ,SNR2: 18.698





1508-05 2025/10/22 3.99UT FUJI -KISO









BLK:12,SNR1: 81.026 ,SNR2: 79.472




BLK:12,SNR1: 21.314 ,SNR2: 39.112





3C318 2025/10/22 4.14UT TOYOKAWA-FUJI







BLK:20,SNR1: 112.57 ,SNR2: 107.29




BLK:20,SNR1: 89.241 ,SNR2: 83.110





3C318 2025/10/22 4.14UT TOYOKAWA-KISO







BLK: 7,SNR1: 24.722 ,SNR2: 46.003





BLK: 7,SNR1: 75.138 ,SNR2: 79.030




3C318 2025/10/22 4.14UT FUJI -KISO





T20251022131229




BLK: 2,SNR1: 1.2815 ,SNR2: 5.0485




F20251022131229




BLK: 2,SNR1: 10.795 ,SNR2: 18.624





1523+03 2025/10/22 4.24UT TOYOKAWA-FUJI







BLK: 8,SNR1: 2.3997 ,SNR2: 7.2882




BLK: 8,SNR1: 10.403 ,SNR2: 19.301





1523+03 2025/10/22 4.24UT TOYOKAWA-KISO







BLK: 5,SNR1: 11.319 ,SNR2: 19.654




BLK: 5,SNR1: 10.376 ,SNR2: 18.560





1523+03 2025/10/22 4.24UT FUJI -KISO







BLK: 2,SNR1: 72.197 ,SNR2: 111.86





BLK: 2,SNR1: 8.2970 ,SNR2: 15.472




1535+139 2025/10/22 4.43UT TOYOKAWA-FUJI





T20251022132408




BLK: 3, SNR1: 75.474 , SNR2: 116.94




K20251022132405








BLK: 3, SNR1: 17.445 , SNR2: 29.547




1535+139 2025/10/22 4.43UT TOYOKAWA-KISO













BLK: 2,SNR1: 6.0677 ,SNR2: 23.032








BLK: 2,SNR1: 2.4220 ,SNR2: 11.116





1548+05 2025/10/22 4.65UT TOYOKAWA-FUJI








F20251022133714




BLK: 2,SNR1: 2.3031 ,SNR2: 10.919




K20251022133711





BLK: 2,SNR1: 16.397 ,SNR2: 28.914




1548+05 2025/10/22 4.65UT FUJI -KISO




T20251022135535




BLK: 2,SNR1: 15.478 ,SNR2: 26.061




F20251022135535





BLK: 2,SNR1: 12.983 ,SNR2: 23.548




1607+26 2025/10/22 4.95UT TOYOKAWA-FUJI




T20251022135535




BLK: 2, SNR1: 15.477 , SNR2: 26.061




K20251022135532




BLK: 2, SNR1: 6.5350 , SNR2: 21.160





1607+26 2025/10/22 4.95UT TOYOKAWA-KISO







BLK: 4,SNR1: 10.397 ,SNR2: 26.748




BLK: 4,SNR1: 15.837 ,SNR2: 27.909





1607+26 2025/10/22 4.95UT FUJI -KISO







BLK: 6,SNR1:-0.18744 ,SNR2: 1.1164




BLK: 6,SNR1: 0.13785 ,SNR2: 2.2152





1623-228 2025/10/22 5.25UT TOYOKAWA-FUJI









BLK: 3,SNR1: 0.79526 ,SNR2: 4.8027




BLK: 3,SNR1: 2.8494 ,SNR2: 9.0511





1623-228 2025/10/22 5.25UT TOYOKAWA-KISO







BLK: 8,SNR1: 1.9284 ,SNR2: 6.8140




BLK: 8,SNR1: 2.2555 ,SNR2: 7.1985





1623-228 2025/10/22 5.25UT FUJI -KISO







BLK: 1,SNR1: 14.429 ,SNR2: 26.157




BLK: 1,SNR1: 6.1830 ,SNR2: 16.529





1631-222 2025/10/22 5.39UT TOYOKAWA-FUJI







BLK: 2,SNR1: 16.550 ,SNR2: 29.230




BLK: 2,SNR1: 2.0621 ,SNR2: 9.9583




1631-222 2025/10/22 5.39UT TOYOKAWA-KISO




F20251022142136




BLK: 1,SNR1: 13.274 ,SNR2: 32.173




K20251022142133




BLK: 1,SNR1: 11.738 ,SNR2: 28.479




1631-222 2025/10/22 5.39UT FUJI -KISO





T20251022142713




BLK: 1,SNR1: 0.92007 ,SNR2: 6.5094




F20251022142714





BLK: 1,SNR1: 5.3107 ,SNR2: 13.576





1638-025 2025/10/22 5.48UT TOYOKAWA-FUJI







1638-025 2025/10/22 5.48UT TOYOKAWA-KISO







BLK: 6,SNR1: 11.463 ,SNR2: 19.357



BLK: 6,SNR1: 10.775 ,SNR2: 23.362





1638-025 2025/10/22 5.48UT FUJI -KISO








T20251022143408




BLK:26,SNR1: 11.888 ,SNR2: 27.839




F20251022143409





BLK:26,SNR1: 13.989 ,SNR2: 32.471




1644-106 2025/10/22 5.60UT TOYOKAWA-FUJI





T20251022143408




BLK:30,SNR1: 11.536 ,SNR2: 27.031




K20251022143405




BLK:30,SNR1: 12.770 ,SNR2: 23.639





1644-106 2025/10/22 5.60UT TOYOKAWA-KISO









BLK:24,SNR1: 33.751 ,SNR2: 44.226




BLK:24,SNR1: 12.956 ,SNR2: 23.990





T20251022143928




BLK:15,SNR1: 10.010 ,SNR2: 18.781




F20251022143928




BLK:15,SNR1: 14.306 ,SNR2: 18.103





1650+004 2025/10/22 5.69UT TOYOKAWA-FUJI







BLK:14,SNR1: 10.869 ,SNR2: 20.406





BLK:14,SNR1: 10.696 ,SNR2: 22.607




1650+004 2025/10/22 5.69UT TOYOKAWA-KISO



F20251022143928





BLK:11,SNR1: 10.843 ,SNR2: 19.294




Frequency (Hz)

K20251022143925







BLK:11,SNR1: 18.401 ,SNR2: 23.125







Frequency (Hz)


1650+004 2025/10/22 5.69UT FUJI -KISO











1656+053 2025/10/22 5.78UT TOYOKAWA-KISO













BLK: 7,SNR1: 4.1095 ,SNR2: 7.9617




BLK: 7,SNR1: 7.2883 ,SNR2: 12.784





1712-033 2025/10/22 6.05UT TOYOKAWA-FUJI







BLK: 4,SNR1: 7.9701 ,SNR2: 14.253




BLK: 4,SNR1: 9.8182 ,SNR2: 21.487





1712-033 2025/10/22 6.05UT TOYOKAWA-KISO







BLK: 3,SNR1: 14.424 ,SNR2: 26.971





BLK: 3,SNR1: 14.755 ,SNR2: 26.597




1712-033 2025/10/22 6.05UT FUJI -KISO



T20251022151932




BLK: 2,SNR1: 12.222 ,SNR2: 21.871




Frequency (Hz)

F20251022151933




BLK: 2,SNR1: 1.5042 ,SNR2: 4.6487




Frequency (Hz)


1730-13 2025/10/22 6.35UT TOYOKAWA-FUJI




T20251022151932




BLK: 3,SNR1: 9.9624 ,SNR2: 24.131




K20251022151929




BLK: 3,SNR1: 18.829 ,SNR2: 33.468





1730-13 2025/10/22 6.35UT TOYOKAWA-KISO











BLK: 2,SNR1: 5.7756 ,SNR2: 12.903




BLK: 2,SNR1: 9.0673 ,SNR2: 22.322










1748+031 2025/10/22 6.64UT TOYOKAWA-FUJI














1748+031 2025/10/22 6.64UT TOYOKAWA-KISO






T20251022154750





BLK: 9, SNR1: 9.6010 , SNR2: 28.260




Frequency (Hz)

F20251022154750




BLK: 9, SNR1: 6.2673 , SNR2: 16.296





Frequency (Hz)


1759+13 2025/10/22 6.83UT TOYOKAWA-FUJI





T20251022154750




BLK: 7, SNR1: 4.0237 , SNR2: 11.969




K20251022154748




BLK: 7, SNR1: 10.151 , SNR2: 29.684





1759+13 2025/10/22 6.83UT TOYOKAWA-KISO







BLK:12,SNR1: 10.539 ,SNR2: 30.531




BLK:12,SNR1: 8.7243 ,SNR2: 21.947





1759+13 2025/10/22 6.83UT FUJI -KISO







BLK: 8,SNR1: 0.80390E-01,SNR2: 0.33626













BLK: 8,SNR1: 1.6128 ,SNR2: 9.9510




1819-096 2025/10/22 7.18UT TOYOKAWA-FUJI















BLK:15,SNR1: 3.5252 ,SNR2: 10.512







BLK:15,SNR1: 4.5714 ,SNR2: 9.8984




1830-210 2025/10/22 7.36UT TOYOKAWA-FUJI







1830-210 2025/10/22 7.36UT TOYOKAWA-KISO



F20251022162007




BLK:23,SNR1: 4.3883 ,SNR2: 7.8457




Frequency (Hz)

K20251022162004





BLK:23,SNR1: 8.9988 ,SNR2: 15.748





Frequency (Hz)

1830-210 2025/10/22 7.36UT FUJI -KISO







BLK:22,SNR1: 1.0264 ,SNR2: 8.0799







BLK:22,SNR1: 14.028 ,SNR2: 33.217




1908-20 2025/10/22 7.98UT TOYOKAWA-FUJI








1908-20 2025/10/22 7.98UT TOYOKAWA-KISO



F20251022165716





BLK:14,SNR1: 13.921 ,SNR2: 33.329




Frequency (Hz)

K20251022165712





BLK:14,SNR1: 51.388 ,SNR2: 100.56





Frequency (Hz)

1908-20 2025/10/22 7.98UT FUJI -KISO








BLK:11,SNR1: 0.23261 ,SNR2: 2.0420





BLK:11,SNR1: 0.18226 ,SNR2: 3.2152







BLK: 5, SNR1: 0.31604 , SNR2: 1.6668




BLK: 5, SNR1: 0.35279 , SNR2: 1.0383





1915-121 2025/10/22 8.10UT TOYOKAWA-KISO







BLK: 6,SNR1: 0.20670 ,SNR2: 4.1332



BLK: 6,SNR1: 2.4660 ,SNR2: 11.137

