








BLK:10,SNR1: 6.4601 ,SNR2: 15.875




BLK:10,SNR1: 5.5282 ,SNR2: 13.775





0830-118 2025/10/26 21.04UT TOYOKAWA-FUJI







BLK:15,SNR1: 8.9797 ,SNR2: 16.063



BLK:15,SNR1: 9.0098 ,SNR2: 16.124





0830-118 2025/10/26 21.04UT TOYOKAWA-KISO








F20251027060034




BLK:10,SNR1: 9.2126 ,SNR2: 19.119




K20251027060033





BLK:10,SNR1: 8.7024 ,SNR2: 15.572




0830-118 2025/10/26 21.04UT FUJI -KISO





T20251027060512




BLK: 1, SNR1: 7.3966 , SNR2: 18.587




F20251027060513





BLK: 1, SNR1: 7.3822 , SNR2: 18.134




0834-19 2025/10/26 21.11UT TOYOKAWA-FUJI




T20251027060512




BLK: 1, SNR1: 13.665 , SNR2: 32.649




K20251027060511




BLK: 1, SNR1: 15.603 , SNR2: 37.305




0834-19 2025/10/26 21.11UT TOYOKAWA-KISO




F20251027060513




BLK: 1, SNR1: 18.388 , SNR2: 44.348




K20251027060511





BLK: 1, SNR1: 12.012 , SNR2: 29.303




0834-19 2025/10/26 21.11UT FUJI -KISO





T20251027061018




BLK: 6,SNR1: 12.657 ,SNR2: 30.081




F20251027061019





BLK: 6,SNR1: 8.7966 ,SNR2: 22.085




0839-071 2025/10/26 21.20UT TOYOKAWA-FUJI





T20251027061018




BLK: 4, SNR1: 10.721 , SNR2: 27.053




K20251027061017





BLK: 4, SNR1: 12.590 , SNR2: 29.988




0839-071 2025/10/26 21.20UT TOYOKAWA-KISO




F20251027061019




BLK:12,SNR1: 10.262 ,SNR2: 25.361




K20251027061017





BLK:12,SNR1: 6.8830 ,SNR2: 16.328




0839-071 2025/10/26 21.20UT FUJI -KISO





T20251027062119




BLK: 3,SNR1: 0.48273E-01,SNR2: 0.27321




F20251027062120






BLK: 3,SNR1: 2.9137 ,SNR2: 9.1415





3C208 2025/10/26 21.38UT TOYOKAWA-FUJI













3C208 2025/10/26 21.38UT FUJI -KISO



T20251027064244





BLK: 5, SNR1: 8.3595 ,SNR2: 24.155




Frequency (Hz)

F20251027064244




BLK: 5, SNR1: 12.209 ,SNR2: 29.657





Frequency (Hz)


0912-132 2025/10/26 21.74UT TOYOKAWA-FUJI




T20251027064244




BLK: 3, SNR1: 7.3077 , SNR2: 18.899




K20251027064243




BLK: 3, SNR1: 6.9376 , SNR2: 19.765




0912-132 2025/10/26 21.74UT TOYOKAWA-KISO





F20251027064244




BLK: 8, SNR1: 9.4345 , SNR2: 23.965




K20251027064243




BLK: 8, SNR1: 8.1738 , SNR2: 21.002





0912-132 2025/10/26 21.74UT FUJI -KISO







BLK: 2,SNR1: 14.448 ,SNR2: 34.292




BLK: 2,SNR1: 10.019 ,SNR2: 25.731





0919-142 2025/10/26 21.86UT TOYOKAWA-FUJI







BLK: 1,SNR1: 12.136 ,SNR2: 30.539





BLK: 1,SNR1: 11.422 ,SNR2: 26.972




0919-142 2025/10/26 21.86UT TOYOKAWA-KISO





F20251027065012




No.Good Data




K20251027065010








No.Good Data





0919-142 2025/10/26 21.86UT FUJI -KISO










T20251027070435




BLK: 6,SNR1:-0.92390E-02,SNR2: 1.1964




K20251027070434








BLK: 6,SNR1: 7.8431 ,SNR2: 14.095





3C222 2025/10/26 22.10UT TOYOKAWA-KISO








T20251027071135




BLK: 2,SNR1: 1.9076 ,SNR2: 8.6354




F20251027071136





BLK: 2,SNR1: 2.3011 ,SNR2: 9.9512




0941-08 2025/10/26 22.22UT TOYOKAWA-FUJI




T20251027071135




BLK: 1, SNR1: 1.2543 ,SNR2: 4.7977




K20251027071134





BLK: 1, SNR1: 10.858 ,SNR2: 31.809




0941-08 2025/10/26 22.22UT TOYOKAWA-KISO



F20251027071136





No.Good Data




Frequency (Hz)

K20251027071134




No.Good Data





Frequency (Hz)


0941-08 2025/10/26 22.22UT FUJI -KISO




T20251027071957




BLK: 3, SNR1: 0.35762 , SNR2: 1.6256




F20251027071957





BLK: 3, SNR1: 0.28357 , SNR2: 2.0398




3C230 2025/10/26 22.36UT TOYOKAWA-FUJI





T20251027071957




BLK: 7, SNR1: 0.19654 , SNR2: 1.0169




K20251027071956



BLK: 7, SNR1: 5.9030 , SNR2: 13.370




3C230 2025/10/26 22.36UT TOYOKAWA-KISO








F20251027071957




BLK: 3, SNR1: 0.54270 , SNR2: 3.1810




K20251027071956




BLK: 3, SNR1: 5.9490 , SNR2: 10.076




3C230 2025/10/26 22.36UT FUJI -KISO




T20251027073558




BLK: 2,SNR1: 11.955 ,SNR2: 29.305




F20251027073559




BLK: 2,SNR1: 9.8460 ,SNR2: 23.805




3C237 2025/10/26 22.63UT TOYOKAWA-FUJI




T20251027073558




BLK: 1, SNR1: 8.7269 , SNR2: 22.001




K20251027073557





BLK: 1, SNR1: 8.6705 , SNR2: 15.277




3C237 2025/10/26 22.63UT TOYOKAWA-KISO





F20251027073559




No. Good Data




K20251027073557





No. Good Data




3C237 2025/10/26 22.63UT FUJI -KISO





T20251027074214




BLK: 7,SNR1: -0.34807E-01,SNR2: 1.7976




F20251027074215





BLK: 7,SNR1: 0.52942 ,SNR2: 5.9070




1011+110 2025/10/26 22.73UT TOYOKAWA-FUJI





T20251027074214




BLK: 6, SNR1: 0.24151 , SNR2: 0.68497




K20251027074213





BLK: 6, SNR1: 2.4750 , SNR2: 5.8781




1011+110 2025/10/26 22.73UT TOYOKAWA-KISO





F20251027074215




BLK: 3,SNR1: 1.1708 ,SNR2: 3.9809




K20251027074213








BLK: 3,SNR1: 1.2810 ,SNR2: 4.3200








1011+110 2025/10/26 22.73UT FUJI -KISO













F20251027074955




BLK: 3,SNR1: 6.3262 ,SNR2: 19.483




K20251027074954





BLK: 3,SNR1: 7.6618 ,SNR2: 19.131




3C241 2025/10/26 22.86UT FUJI -KISO



T20251027080124





BLK: 2, SNR1: 0.53496 , SNR2: 3.0639




Frequency (Hz)

F20251027080125




BLK: 2, SNR1: 5.6610 , SNR2: 14.225





Frequency (Hz)


1031-11 2025/10/26 23.05UT TOYOKAWA-FUJI



T20251027080124





BLK: 3, SNR1: 0.59019 , SNR2: 2.9972




Frequency (Hz)

K20251027080123




BLK: 3, SNR1: 7.9418 , SNR2: 14.929




Frequency (Hz)


1031-11 2025/10/26 23.05UT TOYOKAWA-KISO




F20251027080125




BLK: 3, SNR1: 3.1427 , SNR2: 11.028




K20251027080123







BLK: 3, SNR1: 11.731 , SNR2: 21.736









1031-11 2025/10/26 23.05UT FUJI -KISO






1035-058 2025/10/26 23.13UT TOYOKAWA-FUJI







F20251027080558




BLK: 3, SNR1: 3.3729 , SNR2: 7.3776




K20251027080557



BLK: 3, SNR1: 5.4770 , SNR2: 12.407





1035-058 2025/10/26 23.13UT FUJI -KISO







T20251027081511




BLK: 3,SNR1: 0.24856 ,SNR2: 1.3467




F20251027081511





BLK: 3,SNR1: 0.54467 ,SNR2: 6.1611




1044-008 2025/10/26 23.28UT TOYOKAWA-FUJI




T20251027081511




BLK: 7, SNR1: 1.2912 , SNR2: 9.9701




K20251027081510







BLK: 7, SNR1: 2.2072 , SNR2: 8.3042




1044-008 2025/10/26 23.28UT TOYOKAWA-KISO








1044-008 2025/10/26 23.28UT FUJI -KISO




T20251027082615




BLK: 5,SNR1: 0.31276 ,SNR2: 1.7559




F20251027082615








BLK: 5,SNR1: 0.64681 ,SNR2: 1.9301




1055+01 2025/10/26 23.47UT TOYOKAWA-FUJI








F20251027082615




BLK: 2, SNR1: 1.5244 , SNR2: 3.7296




K20251027082614








BLK: 2, SNR1: 0.53149 , SNR2: 2.1243





1055+01 2025/10/26 23.47UT FUJI -KISO








T20251027083733




BLK: 2, SNR1: 0.66842 , SNR2: 2.9588




K20251027083732




BLK: 2, SNR1: 0.24938 , SNR2: 0.66454





1107+109 2025/10/26 23.65UT TOYOKAWA-KISO









BLK: 2, SNR1: 2.5550 ,SNR2: 5.6140




BLK: 2, SNR1: 0.52017 ,SNR2: 1.9537




1107+109 2025/10/26 23.65UT FUJI -KISO




T20251027084710




BLK: 6,SNR1: 5.4108 ,SNR2: 11.969




F20251027084710




BLK: 6,SNR1: 20.211 ,SNR2: 36.528




3C255 2025/10/26 23.81UT TOYOKAWA-FUJI




T20251027084710




BLK: 7, SNR1: 5.9805 , SNR2: 14.715




K20251027084709




BLK: 7, SNR1: 2.5816 , SNR2: 11.932




3C255 2025/10/26 23.81UT TOYOKAWA-KISO




F20251027084710




BLK: 3,SNR1: 11.009 ,SNR2: 27.107




K20251027084709






BLK: 3,SNR1: 2.7089 ,SNR2: 12.462





3C255 2025/10/26 23.81UT FUJI -KISO








T20251027085412




BLK: 1, SNR1: 1.5188 , SNR2: 4.8576




K20251027085411






BLK: 1, SNR1: 2.1665 , SNR2: 10.547





1123+126 2025/10/26 23.93UT TOYOKAWA-KISO








T20251027091108




BLK: 5, SNR1: 10.158 , SNR2: 22.697




F20251027091108



BLK: 5, SNR1: 2.0107 , SNR2: 13.067




3C263.1 2025/10/27 0.21UT TOYOKAWA-FUJI








T20251027091108




BLK: 7, SNR1: 3.0990 , SNR2: 12.386




K20251027091107





BLK: 7, SNR1: 6.1362 , SNR2: 10.915




3C263.1 2025/10/27 0.21UT TOYOKAWA-KISO





F20251027091108




BLK: 7, SNR1: 3.9706 , SNR2: 10.557




K20251027091107





BLK: 7, SNR1: 0.68068 , SNR2: 2.5779




3C263.1 2025/10/27 0.21UT FUJI -KISO





T20251027091735




BLK: 2, SNR1: 2.4826 , SNR2: 11.338




F20251027091736





BLK: 2, SNR1: 2.4231 , SNR2: 11.104




3C267 2025/10/27 0.32UT TOYOKAWA-FUJI





T20251027091735




BLK: 1, SNR1: 10.696 , SNR2: 26.264




K20251027091734




BLK: 1, SNR1: 9.5104 , SNR2: 23.393




3C267 2025/10/27 0.32UT TOYOKAWA-KISO





F20251027091736




BLK: 1, SNR1: 9.8900 , SNR2: 24.623




K20251027091734




BLK: 1, SNR1: 11.491 , SNR2: 28.484




3C267 2025/10/27 0.32UT FUJI -KISO





T20251027094323




BLK: 3, SNR1: 73.291 , SNR2: 216.01




F20251027094323





BLK: 3, SNR1: 10.173 , SNR2: 24.983




1213-17 2025/10/27 0.75UT TOYOKAWA-FUJI





T20251027094323




BLK: 7, SNR1: 12.379 , SNR2: 30.619




K20251027094322





BLK: 7, SNR1: 8.7946 , SNR2: 21.679




1213-17 2025/10/27 0.75UT TOYOKAWA-KISO





F20251027094323




BLK: 4, SNR1: 10.431 , SNR2: 25.276




K20251027094322



BLK: 4, SNR1: 9.3134 , SNR2: 22.915





1213-17 2025/10/27 0.75UT FUJI -KISO







T20251027095640




BLK: 7, SNR1: 19.611 , SNR2: 36.388




F20251027095640







BLK: 7, SNR1: 4.1299 , SNR2: 10.502








3C273 2025/10/27 0.97UT TOYOKAWA-FUJI






3C273 2025/10/27 0.97UT TOYOKAWA-KISO








3C273 2025/10/27 0.97UT FUJI -KISO




T20251027100951




BLK: 5, SNR1: 2.8091 , SNR2: 8.7070




F20251027100951





BLK: 5, SNR1: 8.6203 , SNR2: 20.480




3C275 2025/10/27 1.19UT TOYOKAWA-FUJI



T20251027100951




BLK:12,SNR1: 8.3706 ,SNR2: 14.844





3C275 2025/10/27 1.19UT TOYOKAWA-KISO


K20251027100950




BLK:12,SNR1: 9.8159 ,SNR2: 17.306




F20251027100951




BLK:10,SNR1: 8.0617 ,SNR2: 14.326




K20251027100950







BLK:10,SNR1: 10.248 ,SNR2: 18.196





3C275 2025/10/27 1.19UT FUJI -KISO







1245-19 2025/10/27 1.29UT TOYOKAWA-FUJI







BLK:11,SNR1: 299.89 ,SNR2: 312.19



BLK:11,SNR1: 121.86 ,SNR2: 152.70





1245-19 2025/10/27 1.29UT TOYOKAWA-KISO








F20251027101556




BLK: 6, SNR1: 32.106 , SNR2: 53.538




K20251027101555




BLK: 6, SNR1: 45.786 , SNR2: 63.666




1245-19 2025/10/27 1.29UT FUJI -KISO




T20251027102339




BLK:14,SNR1: 42.636 ,SNR2: 56.207




F20251027102339





BLK:14,SNR1: 2.9885 ,SNR2: 12.645




3C279 2025/10/27 1.42UT TOYOKAWA-FUJI





T20251027102339




BLK:17,SNR1: 61.345 ,SNR2: 73.692




K20251027102338




BLK:17,SNR1: 57.515 ,SNR2: 92.020




3C279 2025/10/27 1.42UT TOYOKAWA-KISO





F20251027102339




BLK: 9, SNR1: 2.8044 , SNR2: 11.917




K20251027102338












BLK: 9, SNR1: 57.361 , SNR2: 91.773




3C279 2025/10/27 1.42UT FUJI -KISO










3C283 2025/10/27 1.68UT TOYOKAWA-KISO




F20251027103909




BLK: 5, SNR1: 18.157 , SNR2: 43.619




K20251027103908








BLK: 5, SNR1: 10.270 , SNR2: 25.395





3C283 2025/10/27 1.68UT FUJI -KISO









T20251027105333




BLK: 2, SNR1: 1.2800 , SNR2: 19.255




K20251027105332







BLK: 2, SNR1: 17.530 , SNR2: 39.699





1323+32 2025/10/27 1.92UT TOYOKAWA-KISO







1323+32 2025/10/27 1.92UT FUJI -KISO







BLK: 7, SNR1: 3.5319 , SNR2: 9.2273





BLK: 7, SNR1: 8.0065 , SNR2: 13.132




3C286 2025/10/27 2.00UT TOYOKAWA-FUJI





T20251027105823




BLK:11,SNR1: 6.9867 ,SNR2: 17.111




K20251027105822













BLK:11,SNR1: 9.8111 ,SNR2: 15.212





3C286 2025/10/27 2.00UT TOYOKAWA-KISO










T20251027111451




BLK: 4, SNR1: 10.646 ,SNR2: 24.435




K20251027111450





BLK: 4, SNR1: 10.422 ,SNR2: 23.752




1345+12 2025/10/27 2.28UT TOYOKAWA-KISO





F20251027111451




BLK: 6,SNR1: 7.5690 ,SNR2: 21.353




K20251027111450




BLK: 6,SNR1: 5.7868 ,SNR2: 13.406





1345+12 2025/10/27 2.28UT FUJI -KISO









BLK: 1,SNR1: 2.3622 ,SNR2: 4.5598




BLK: 1,SNR1: -0.98746E-03,SNR2: 4.4655





1355+01 2025/10/27 2.45UT TOYOKAWA-FUJI







BLK: 2,SNR1: 27.253 ,SNR2: 41.165





BLK: 2,SNR1: 10.563 ,SNR2: 26.302




1355+01 2025/10/27 2.45UT TOYOKAWA-KISO



F20251027112511





BLK: 2,SNR1: 9.8977 ,SNR2: 24.731





1355+01 2025/10/27 2.45UT FUJI -KISO


K20251027112510




BLK: 2,SNR1: 10.275 ,SNR2: 25.574




T20251027114622




BLK: 5, SNR1: 12.330 ,SNR2: 38.280




F20251027114622




BLK: 5, SNR1: 11.077 ,SNR2: 27.602




3C298 2025/10/27 2.80UT TOYOKAWA-FUJI





T20251027114622




BLK: 7, SNR1: 16.842 , SNR2: 22.225




K20251027114621




BLK: 7, SNR1: 6.3360 , SNR2: 15.863




3C298 2025/10/27 2.80UT TOYOKAWA-KISO



F20251027114622





BLK: 3,SNR1: 10.750 ,SNR2: 26.515





3C298 2025/10/27 2.80UT FUJI -KISO


K20251027114621




BLK: 3,SNR1: 9.7279 ,SNR2: 24.123




T20251027115805




BLK: 1, SNR1: 29.728 , SNR2: 37.304




F20251027115806




BLK: 1, SNR1: 31.118 , SNR2: 40.536




1428-03 2025/10/27 3.00UT TOYOKAWA-FUJI





T20251027115805




BLK: 3, SNR1: 11.701 , SNR2: 20.806




K20251027115804



BLK: 3, SNR1: 23.495 , SNR2: 30.520





1428-03 2025/10/27 3.00UT TOYOKAWA-KISO








F20251027115806




BLK: 3, SNR1: 7.1622 , SNR2: 17.650




K20251027115804





BLK: 3, SNR1: 10.414 , SNR2: 18.229




1428-03 2025/10/27 3.00UT FUJI -KISO




T20251027120408




BLK:11,SNR1: 10.145 ,SNR2: 17.937




F20251027120408





BLK:11,SNR1: 22.765 ,SNR2: 25.695




1434+03 2025/10/27 3.10UT TOYOKAWA-FUJI





T20251027120408




BLK:14,SNR1: 9.2166 ,SNR2: 22.569




K20251027120407




BLK:14,SNR1: 18.172 ,SNR2: 32.936




1434+03 2025/10/27 3.10UT TOYOKAWA-KISO




F20251027120408




BLK:12,SNR1: 5.2865 ,SNR2: 13.643




K20251027120407





BLK:12,SNR1: 14.821 ,SNR2: 26.199




1434+03 2025/10/27 3.10UT FUJI -KISO




T20251027122310




BLK: 7, SNR1: 5.6475 , SNR2: 17.324




F20251027122310





BLK: 7, SNR1: 28.128 , SNR2: 36.862




1453-10 2025/10/27 3.41UT TOYOKAWA-FUJI




T20251027122310




BLK: 6,SNR1: 42.030 ,SNR2: 50.529




K20251027122309





BLK: 6,SNR1: 10.743 ,SNR2: 19.179




1453-10 2025/10/27 3.41UT TOYOKAWA-KISO



F20251027122310





BLK: 3,SNR1: 34.609 ,SNR2: 45.342




Frequency (Hz)

K20251027122309




BLK: 3,SNR1: 20.870 ,SNR2: 31.594




Frequency (Hz)


1453-10 2025/10/27 3.41UT FUJI -KISO





T20251027123802




BLK: 3,SNR1: 0.13027 ,SNR2: 2.3322




F20251027123802



BLK: 3,SNR1: 9.4594 ,SNR2: 24.018





1508-05 2025/10/27 3.66UT TOYOKAWA-FUJI








T20251027123802




BLK: 2,SNR1: 0.15202 ,SNR2: 2.0168




K20251027123801






BLK: 2,SNR1: 1.0945 ,SNR2: 10.593





1508-05 2025/10/27 3.66UT TOYOKAWA-KISO








T20251027124702




BLK: 5, SNR1: 1.0042 , SNR2: 2.6151




F20251027124702





BLK: 5, SNR1: 10.246 , SNR2: 25.689




3C318 2025/10/27 3.81UT TOYOKAWA-FUJI





T20251027124702




BLK: 3,SNR1: 3.3562 ,SNR2: 10.218




K20251027124701




BLK: 3,SNR1: 30.355 ,SNR2: 48.861




3C318 2025/10/27 3.81UT TOYOKAWA-KISO




F20251027124702




BLK: 1,SNR1: 4.2853 ,SNR2: 10.548




K20251027124701







BLK: 1,SNR1: 1.6512 ,SNR2: 12.665





3C318 2025/10/27 3.81UT FUJI -KISO









BLK: 1,SNR1: 8.3667 ,SNR2: 20.708




BLK: 1,SNR1: 12.394 ,SNR2: 30.224





1523+03 2025/10/27 3.91UT TOYOKAWA-KISO







BLK: 1,SNR1: 7.7784 ,SNR2: 18.847



BLK: 1,SNR1: 7.5507 ,SNR2: 17.993





1523+03 2025/10/27 3.91UT FUJI -KISO






T20251027130428





BLK: 1,SNR1: 0.18598 ,SNR2: 0.73189




Frequency (Hz)

F20251027130428




BLK: 1,SNR1: 2.9770 ,SNR2: 8.7204





Frequency (Hz)


1535+139 2025/10/27 4.10UT TOYOKAWA-FUJI





T20251027130428




BLK: 3,SNR1: 8.5116 ,SNR2: 21.306




K20251027130427







BLK: 3,SNR1: 9.8864 ,SNR2: 24.341





1535+139 2025/10/27 4.10UT TOYOKAWA-KISO









BLK:10,SNR1: 9.5738 ,SNR2: 17.151








BLK:10,SNR1: 8.1591 ,SNR2: 21.079





1548+05 2025/10/27 4.32UT TOYOKAWA-FUJI








F20251027131734




BLK:14,SNR1: 8.0797 ,SNR2: 20.878




K20251027131733




BLK:14,SNR1: 7.7134 ,SNR2: 20.266





1548+05 2025/10/27 4.32UT FUJI -KISO







BLK: 1,SNR1: 13.780 ,SNR2: 26.755








BLK: 1,SNR1: 7.4796 ,SNR2: 19.037




1607+26 2025/10/27 4.63UT TOYOKAWA-FUJI













BLK: 5,SNR1: 7.8682 ,SNR2: 19.062





BLK: 5,SNR1: 10.761 ,SNR2: 30.672




1607+26 2025/10/27 4.63UT FUJI -KISO





T20251027135327




BLK: 4,SNR1: 5.2892 ,SNR2: 8.2138




F20251027135328





BLK: 4,SNR1: 5.5919 ,SNR2: 14.372




1623-228 2025/10/27 4.92UT TOYOKAWA-FUJI





T20251027135327




BLK: 5, SNR1: 4.3302 , SNR2: 5.7754




K20251027135326





BLK: 5, SNR1: 5.1503 , SNR2: 10.954




1623-228 2025/10/27 4.92UT TOYOKAWA-KISO





F20251027135328




No.Good Data




K20251027135326




No.Good Data





1623-228 2025/10/27 4.92UT FUJI -KISO







BLK: 4,SNR1: 1.4344 ,SNR2: 8.3003




BLK: 4,SNR1: 1.8495 ,SNR2: 7.1320





1631-222 2025/10/27 5.06UT TOYOKAWA-FUJI







BLK: 3,SNR1: 0.46374 ,SNR2: 2.4566




BLK: 3,SNR1: 8.2775 ,SNR2: 21.349





1631-222 2025/10/27 5.06UT TOYOKAWA-KISO








BLK: 5,SNR1: 4.0054 ,SNR2: 11.742





BLK: 5,SNR1: 5.3364 ,SNR2: 15.478







BLK:19,SNR1: 20.306 ,SNR2: 42.586



BLK:19,SNR1: 13.252 ,SNR2: 28.518




1638-025 2025/10/27 5.15UT TOYOKAWA-FUJI








T20251027140734




BLK:21,SNR1: 20.535 ,SNR2: 43.046




K20251027140733




BLK:21,SNR1: 11.544 ,SNR2: 20.442





1638-025 2025/10/27 5.15UT TOYOKAWA-KISO











BLK:20,SNR1: 9.7301 ,SNR2: 20.563








BLK:20,SNR1: 10.255 ,SNR2: 22.158







1644-106 2025/10/27 5.27UT TOYOKAWA-FUJI







1644-106 2025/10/27 5.27UT TOYOKAWA-KISO








BLK: 8,SNR1: 6.2330 ,SNR2: 15.207





BLK: 8,SNR1: 5.2224 ,SNR2: 12.038







BLK:24,SNR1: 107.87 ,SNR2: 159.82




BLK:24,SNR1: 120.01 ,SNR2: 124.93





1650+004 2025/10/27 5.36UT TOYOKAWA-FUJI







BLK:20,SNR1: 105.77 ,SNR2: 156.72




BLK:20,SNR1: 18.376 ,SNR2: 59.031





1650+004 2025/10/27 5.36UT TOYOKAWA-KISO








BLK:24,SNR1: 119.80 ,SNR2: 124.72





BLK:24,SNR1: 18.439 ,SNR2: 59.218









BLK: 9,SNR1: 0.39927E-01,SNR2: 0.44444




BLK: 9,SNR1: 1.6739 ,SNR2: 13.854





1656+053 2025/10/27 5.45UT TOYOKAWA-FUJI







BLK: 1,SNR1:-0.99989E-02,SNR2: 0.59362




BLK: 1,SNR1: 0.20544 ,SNR2: 1.1310





1656+053 2025/10/27 5.45UT TOYOKAWA-KISO








BLK: 5,SNR1: 1.0619 ,SNR2: 10.053





BLK: 5,SNR1: 0.58795 ,SNR2: 1.6202







BLK:15,SNR1: 5.5138 ,SNR2: 11.321




BLK:15,SNR1: 12.212 ,SNR2: 26.810





1712-033 2025/10/27 5.73UT TOYOKAWA-FUJI







BLK:12,SNR1: 2.9544 ,SNR2: 7.8890




BLK:12,SNR1: 15.704 ,SNR2: 33.700





1712-033 2025/10/27 5.73UT TOYOKAWA-KISO







BLK: 8,SNR1: 8.0715 ,SNR2: 14.427




BLK: 8,SNR1: 28.650 ,SNR2: 62.135





1712-033 2025/10/27 5.73UT FUJI -KISO







BLK:13,SNR1: 33.713 ,SNR2: 40.993




BLK:13,SNR1: 4.3446 ,SNR2: 9.4706





1730-13 2025/10/27 6.03UT TOYOKAWA-FUJI







BLK:18,SNR1: 3.6795 ,SNR2: 8.5548








BLK:18,SNR1: 14.964 ,SNR2: 21.545




1730-13 2025/10/27 6.03UT TOYOKAWA-KISO













BLK: 6,SNR1: 385.05 ,SNR2: 374.01




BLK: 6,SNR1: 1.3855 ,SNR2: 6.6742





1748+031 2025/10/27 6.32UT TOYOKAWA-FUJI







BLK:14,SNR1: 370.01 ,SNR2: 359.40




BLK:14,SNR1: 71.212 ,SNR2: 158.92





1748+031 2025/10/27 6.32UT TOYOKAWA-KISO







BLK: 6,SNR1: 1.1447 ,SNR2: 6.2303




BLK: 6,SNR1: 71.873 ,SNR2: 162.18





1748+031 2025/10/27 6.32UT FUJI -KISO







BLK: 9,SNR1: 0.32520 ,SNR2: 1.1554




BLK: 9,SNR1: 2.5290 ,SNR2: 6.2602





1759+13 2025/10/27 6.50UT TOYOKAWA-FUJI







BLK:15,SNR1: 0.54896 ,SNR2: 1.6501





BLK:15,SNR1: 7.4448 ,SNR2: 13.164




1759+13 2025/10/27 6.50UT TOYOKAWA-KISO



F20251027152810





BLK:11,SNR1: 3.7221 ,SNR2: 8.4120




Frequency (Hz)

K20251027152809




BLK:11,SNR1: 4.2602 ,SNR2: 11.213





Frequency (Hz)


1759+13 2025/10/27 6.50UT FUJI -KISO





T20251027154911




BLK:12,SNR1: 0.18244 ,SNR2: 1.4145




F20251027154911



BLK:12,SNR1: 4.4381 ,SNR2: 10.475





1819-096 2025/10/27 6.85UT TOYOKAWA-FUJI






T20251027154911




BLK:10,SNR1: 0.27842 ,SNR2: 1.6156




Frequency (Hz)

K20251027154910









BLK:10,SNR1: 1.9629 ,SNR2: 7.9639




Frequency (Hz)



1819-096 2025/10/27 6.85UT TOYOKAWA-KISO









BLK:10,SNR1: 0.66572 ,SNR2: 1.8255







BLK:10,SNR1: 9.4844 ,SNR2: 23.222









1830-210 2025/10/27 7.04UT TOYOKAWA-FUJI










1830-210 2025/10/27 7.04UT TOYOKAWA-KISO










1858+171 2025/10/27 7.48UT TOYOKAWA-FUJI







BLK:10,SNR1: 0.15134 ,SNR2: 0.50310








BLK:10,SNR1: 8.0194 ,SNR2: 17.841





1858+171 2025/10/27 7.48UT TOYOKAWA-KISO








T20251027163736





BLK: 3,SNR1: 0.24326 ,SNR2: 1.5386




Frequency (Hz)

F20251027163737





BLK: 3,SNR1: 1.0056 ,SNR2: 7.8873





Frequency (Hz)

1908-20 2025/10/27 7.65UT TOYOKAWA-FUJI







BLK: 7, SNR1: 0.40904 , SNR2: 2.2073




BLK: 7, SNR1: 3.8278 , SNR2: 9.8914





1908-20 2025/10/27 7.65UT TOYOKAWA-KISO







BLK: 6,SNR1:-0.65451E-02,SNR2: 1.1961







BLK: 6,SNR1: 1.0233 ,SNR2: 4.7257








1908-20 2025/10/27 7.65UT FUJI -KISO







1915-121 2025/10/27 7.77UT TOYOKAWA-FUJI







1915-121 2025/10/27 7.77UT TOYOKAWA-KISO







BLK: 3, SNR1: 10.243 , SNR2: 15.480




BLK: 3, SNR1: 12.647 , SNR2: 22.882





1915-121 2025/10/27 7.77UT FUJI -KISO







BLK: 2,SNR1: 1.5403 ,SNR2: 7.9030




BLK: 2,SNR1: 8.0448 ,SNR2: 20.982





1928-142 2025/10/27 8.00UT TOYOKAWA-FUJI







BLK: 1, SNR1: 0.99857 , SNR2: 4.3832



BLK: 1, SNR1: 1.7970 , SNR2: 7.4106




1928-142 2025/10/27 8.00UT TOYOKAWA-KISO






F20251027165809




BLK: 3, SNR1: 7.2109 , SNR2: 13.000




Frequency (Hz)

K20251027165807





BLK: 3, SNR1: 13.128 , SNR2: 23.234





Frequency (Hz)

1928-142 2025/10/27 8.00UT FUJI -KISO







BLK: 5, SNR1: 13.115 , SNR2: 17.292




BLK: 5, SNR1: 20.616 , SNR2: 26.864





1938-15 2025/10/27 8.16UT TOYOKAWA-FUJI







BLK: 1,SNR1: 0.95419E-01,SNR2: 1.8016




BLK: 1,SNR1: 0.97370 ,SNR2: 5.6151





1938-15 2025/10/27 8.16UT TOYOKAWA-KISO







BLK: 6, SNR1: 0.74734E-01, SNR2: 8.3018




BLK: 6, SNR1: 13.157, SNR2: 25.983




1938-15 2025/10/27 8.16UT FUJI -KISO



T20251027171948





BLK: 1, SNR1: 8.1797 , SNR2: 15.206




Frequency (Hz)

F20251027171949




BLK: 1, SNR1: 11.210 , SNR2: 27.078




Frequency (Hz)


1950-213 2025/10/27 8.36UT TOYOKAWA-FUJI




T20251027171948




BLK: 2, SNR1: 5.1466 , SNR2: 12.878




K20251027171947




BLK: 2, SNR1: 7.1122 , SNR2: 18.036





1950-213 2025/10/27 8.36UT TOYOKAWA-KISO






BLK: 1, SNR1: 11.898 , SNR2: 20.858



BLK: 1, SNR1: 4.7279 , SNR2: 12.204



1950-213 2025/10/27 8.36UT FUJI -KISO

