

























0830-118 2025/10/27 20.97UT FUJI -KISO








T20251028060116




BLK: 9, SNR1: 7.9236 , SNR2: 8.7890




K20251028060115







BLK: 9, SNR1: 9.4030 , SNR2: 20.545




0834-19 2025/10/27 21.05UT TOYOKAWA-KISO







0834-19 2025/10/27 21.05UT FUJI -KISO




T20251028060622




BLK: 7,SNR1: 10.374 ,SNR2: 25.762




F20251028060622




BLK: 7,SNR1: 13.530 ,SNR2: 31.668




0839-071 2025/10/27 21.13UT TOYOKAWA-FUJI





T20251028060622




BLK: 7,SNR1: 11.889 ,SNR2: 28.922




K20251028060621




BLK: 7,SNR1: 14.264 ,SNR2: 33.727




0839-071 2025/10/27 21.13UT TOYOKAWA-KISO





F20251028060622




BLK: 9, SNR1: 8.5780 , SNR2: 21.644




K20251028060621







BLK: 9, SNR1: 13.129 , SNR2: 31.504




0839-071 2025/10/27 21.13UT FUJI -KISO







0857-191 2025/10/27 21.42UT TOYOKAWA-FUJI








T20251028062343




BLK: 1, SNR1: 0.70307 , SNR2: 6.2483




K20251028062342





BLK: 1, SNR1: 8.9171 , SNR2: 22.265






0857-191 2025/10/27 21.42UT TOYOKAWA-KISO







BLK: 1, SNR1: -0.19728 , SNR2: 1.6988





BLK: 1, SNR1: 2.2688 , SNR2: 7.0992




0857-191 2025/10/27 21.42UT FUJI -KISO





T20251028063848




BLK: 4, SNR1: 10.188 , SNR2: 24.387




F20251028063849





BLK: 4, SNR1: 8.5961 , SNR2: 21.347




0912-132 2025/10/27 21.67UT TOYOKAWA-FUJI





T20251028063848




BLK: 9, SNR1: 9.0332 , SNR2: 24.381




K20251028063847




BLK: 9, SNR1: 15.515 , SNR2: 36.375




0912-132 2025/10/27 21.67UT TOYOKAWA-KISO




F20251028063849




BLK: 6,SNR1: 10.097 ,SNR2: 27.000




K20251028063847




BLK: 6,SNR1: 13.981 ,SNR2: 33.209





0912-132 2025/10/27 21.67UT FUJI -KISO







BLK: 4,SNR1: 0.95901E-01,SNR2: 1.1657





BLK: 4,SNR1: 0.40288 ,SNR2: 2.4679




0919-142 2025/10/27 21.80UT TOYOKAWA-FUJI





T20251028064616




BLK: 2,SNR1: 0.13578E-01,SNR2: 0.47450




K20251028064615





BLK: 2,SNR1: 3.2976 ,SNR2: 8.2985




0919-142 2025/10/27 21.80UT TOYOKAWA-KISO










0919-142 2025/10/27 21.80UT FUJI -KISO














3C222 2025/10/27 22.04UT TOYOKAWA-FUJI








F20251028070039




BLK: 2, SNR1: 4.1446 , SNR2: 10.307




K20251028070038







BLK: 2, SNR1: 6.3129 , SNR2: 14.225








3C222 2025/10/27 22.04UT FUJI -KISO







0941-08 2025/10/27 22.16UT TOYOKAWA-FUJI







0941-08 2025/10/27 22.16UT TOYOKAWA-KISO







BLK: 3,SNR1: 1.2689 ,SNR2: 6.1974





BLK: 3,SNR1: 12.372 ,SNR2: 22.899




0941-08 2025/10/27 22.16UT FUJI -KISO




T20251028071601




BLK: 6,SNR1: 0.41338 ,SNR2: 2.3675




F20251028071602




BLK: 6,SNR1: 0.81382 ,SNR2: 6.9182





3C230 2025/10/27 22.30UT TOYOKAWA-FUJI







BLK: 5, SNR1: 0.20024 , SNR2: 1.9361



BLK: 5, SNR1: 10.593 , SNR2: 18.812




3C230 2025/10/27 22.30UT TOYOKAWA-KISO







F20251028071602




BLK: 6, SNR1: 1.4612 , SNR2: 6.7373




K20251028071600




BLK: 6, SNR1: 4.2567 , SNR2: 10.193





3C230 2025/10/27 22.30UT FUJI -KISO







BLK: 2,SNR1: 0.46136 ,SNR2: 3.4083




BLK: 2,SNR1: 0.97337 ,SNR2: 9.0755





3C237 2025/10/27 22.56UT TOYOKAWA-FUJI







BLK: 5, SNR1: 0.45610 , SNR2: 3.8589




BLK: 5, SNR1: 5.1335 , SNR2: 11.091




3C237 2025/10/27 22.56UT TOYOKAWA-KISO





F20251028073203




BLK: 4, SNR1: 0.72314 , SNR2: 2.5256




K20251028073201







BLK: 4, SNR1: 4.8493 , SNR2: 10.042





3C237 2025/10/27 22.56UT FUJI -KISO









BLK: 1,SNR1: 0.51187 ,SNR2: 2.4179




BLK: 1,SNR1: 1.8085 ,SNR2: 9.0352




1011+110 2025/10/27 22.67UT TOYOKAWA-KISO





F20251028073818




BLK: 2,SNR1: 10.933 ,SNR2: 27.139




K20251028073817






BLK: 2,SNR1: 11.644 ,SNR2: 26.214





1011+110 2025/10/27 22.67UT FUJI -KISO










T20251028074559




BLK: 2, SNR1: -0.83561E-01, SNR2: 0.78986




K20251028074558







BLK: 2, SNR1: 7.5284, SNR2: 13.084




3C241 2025/10/27 22.79UT TOYOKAWA-KISO







3C241 2025/10/27 22.79UT FUJI -KISO



T20251028075728




BLK: 2, SNR1: 1.4970 , SNR2: 7.0856





1031-11 2025/10/27 22.99UT TOYOKAWA-FUJI


F20251028075728




BLK: 2, SNR1: 2.3570 , SNR2: 10.884



T20251028075728




BLK: 4, SNR1: 0.96652 , SNR2: 10.887





1031-11 2025/10/27 22.99UT TOYOKAWA-KISO


K20251028075727




BLK: 4, SNR1: 11.441 , SNR2: 20.547




F20251028075728




BLK: 2,SNR1: 0.70046E-01,SNR2: 3.0077




K20251028075727




BLK: 2,SNR1: 12.348 ,SNR2: 27.893





1031-11 2025/10/27 22.99UT FUJI -KISO







BLK: 4,SNR1: 23.368 ,SNR2: 87.981




BLK: 4,SNR1: 15.463 ,SNR2: 20.455





1035-058 2025/10/27 23.06UT TOYOKAWA-FUJI







BLK: 8,SNR1: 14.269 ,SNR2: 32.576





BLK: 8,SNR1: 5.8397 ,SNR2: 21.311




1035-058 2025/10/27 23.06UT TOYOKAWA-KISO



F20251028080203





BLK: 4, SNR1: 9.5735 , SNR2: 23.594




Frequency (Hz)

K20251028080201




BLK: 4, SNR1: 16.478 , SNR2: 29.066




Frequency (Hz)

1035-058 2025/10/27 23.06UT FUJI -KISO







T20251028081115




BLK: 5, SNR1: 0.45465 , SNR2: 1.7285




F20251028081116




BLK: 5, SNR1: 0.23297 , SNR2: 5.8086





1044-008 2025/10/27 23.22UT TOYOKAWA-FUJI







BLK: 5, SNR1: 0.46539 , SNR2: 1.7034





BLK: 5, SNR1: 15.786 , SNR2: 24.477




1044-008 2025/10/27 23.22UT TOYOKAWA-KISO








1044-008 2025/10/27 23.22UT FUJI -KISO





T20251028082219




BLK: 2, SNR1: 0.38164 , SNR2: 2.1343




F20251028082220





BLK: 2, SNR1: 5.8397 , SNR2: 27.399




1055+01 2025/10/27 23.40UT TOYOKAWA-FUJI





T20251028082219




BLK: 3, SNR1: 0.49747 , SNR2: 4.3478




K20251028082218





BLK: 3, SNR1: 19.022 , SNR2: 39.975




1055+01 2025/10/27 23.40UT TOYOKAWA-KISO





F20251028082220




BLK: 3,SNR1: 2.5623 ,SNR2: 12.761




K20251028082218





BLK: 3,SNR1: 8.5288 ,SNR2: 13.902




1055+01 2025/10/27 23.40UT FUJI -KISO




T20251028083337




BLK: 8, SNR1: 9.8940 , SNR2: 22.201




F20251028083338




BLK: 8, SNR1: 12.711 , SNR2: 28.491





1107+109 2025/10/27 23.59UT TOYOKAWA-FUJI







BLK:13,SNR1: 0.63527 ,SNR2: 1.3333







BLK:13,SNR1: 12.910 ,SNR2: 22.099




1107+109 2025/10/27 23.59UT TOYOKAWA-KISO









1107+109 2025/10/27 23.59UT FUJI -KISO





T20251028084314




BLK: 6, SNR1: 0.72254 , SNR2: 4.6115




F20251028084314




BLK: 6, SNR1: 10.390 , SNR2: 24.729




3C255 2025/10/27 23.75UT TOYOKAWA-FUJI




T20251028084314




BLK:13,SNR1: 1.5507 ,SNR2: 5.7147




K20251028084313




BLK:13,SNR1: 2.5940 ,SNR2: 4.4118




3C255 2025/10/27 23.75UT TOYOKAWA-KISO





F20251028084314




BLK: 3, SNR1: 3.1033 , SNR2: 8.3898




K20251028084313




BLK: 3, SNR1: 0.74459 , SNR2: 3.8855





3C255 2025/10/27 23.75UT FUJI -KISO







BLK: 4,SNR1: 0.20881 ,SNR2: 3.4803












BLK: 4,SNR1: 0.36275 ,SNR2: 4.1817




1127-14 2025/10/27 23.93UT TOYOKAWA-FUJI










1127-14 2025/10/27 23.93UT FUJI -KISO




T20251028090712




BLK: 7, SNR1: 1.2161 , SNR2: 11.050




F20251028090713



BLK: 7, SNR1: 0.43763 , SNR2: 2.5343





3C263.1 2025/10/28 0.15UT TOYOKAWA-FUJI







T20251028090712




BLK:11,SNR1: 0.95856 ,SNR2: 5.6752




K20251028090711




BLK:11,SNR1: 0.86584 ,SNR2: 3.4820





3C263.1 2025/10/28 0.15UT TOYOKAWA-KISO







BLK: 3, SNR1: 0.84166 , SNR2: 3.8413




BLK: 3, SNR1: 0.70376 , SNR2: 3.9765




3C263.1 2025/10/28 0.15UT FUJI -KISO





T20251028091339




BLK: 6,SNR1: 0.40316 ,SNR2: 1.1650




F20251028091340





BLK: 6,SNR1: 3.7849 ,SNR2: 6.6059




3C267 2025/10/28 0.26UT TOYOKAWA-FUJI





T20251028091339




BLK: 7, SNR1: 0.38735 , SNR2: 1.2754




K20251028091338





BLK: 7, SNR1: 8.9260 , SNR2: 15.881




3C267 2025/10/28 0.26UT TOYOKAWA-KISO





F20251028091340




BLK: 8, SNR1: 3.7770 , SNR2: 9.0569




K20251028091338







BLK: 8, SNR1: 8.9086 , SNR2: 15.853









3C267 2025/10/28 0.26UT FUJI -KISO






1213-17 2025/10/28 0.69UT TOYOKAWA-FUJI







F20251028093927




BLK: 1, SNR1: 11.689 , SNR2: 28.609




K20251028093926







BLK: 1, SNR1: 4.6995 , SNR2: 11.603




1213-17 2025/10/28 0.69UT FUJI -KISO










3C273 2025/10/28 0.91UT TOYOKAWA-FUJI




T20251028095244




BLK:22,SNR1: 19.011 ,SNR2: 26.235




K20251028095243







BLK:22,SNR1: 5.7000 ,SNR2: 12.772




3C273 2025/10/28 0.91UT TOYOKAWA-KISO







3C273 2025/10/28 0.91UT FUJI -KISO





T20251028100555




BLK:13,SNR1: 25.023 ,SNR2: 39.049




F20251028100556




BLK:13,SNR1: 66.663 ,SNR2: 103.49




3C275 2025/10/28 1.13UT TOYOKAWA-FUJI





T20251028100555




BLK:13,SNR1: 25.142 ,SNR2: 34.746




K20251028100554













BLK:13,SNR1: 12.981 ,SNR2: 31.767




3C275 2025/10/28 1.13UT TOYOKAWA-KISO










T20251028101200




BLK: 9, SNR1: 8.8192 , SNR2: 15.589




K20251028101159







BLK: 9, SNR1: 1.9162 , SNR2: 8.7981




1245-19 2025/10/28 1.23UT TOYOKAWA-KISO
















1245-19 2025/10/28 1.23UT FUJI -KISO










3C279 2025/10/28 1.36UT TOYOKAWA-FUJI










3C279 2025/10/28 1.36UT TOYOKAWA-KISO











3C279 2025/10/28 1.36UT FUJI -KISO







3C283 2025/10/28 1.62UT TOYOKAWA-FUJI






F20251028103513





BLK:13,SNR1: 8.0132 ,SNR2: 14.197





3C283 2025/10/28 1.62UT FUJI -KISO


K20251028103512




BLK:13,SNR1: 9.7894 ,SNR2: 17.345




T20251028104937




BLK: 4,SNR1: 1.2492 ,SNR2: 3.3271




F20251028104938



BLK: 4,SNR1: 0.96316 ,SNR2: 5.6107





1323+32 2025/10/28 1.86UT TOYOKAWA-FUJI







T20251028104937




BLK: 6,SNR1: 0.85709 ,SNR2: 4.3818




K20251028104936





BLK: 6,SNR1: 1.8618 ,SNR2: 4.0023




1323+32 2025/10/28 1.86UT TOYOKAWA-KISO





F20251028104938




BLK: 2,SNR1: 2.4597 ,SNR2: 10.339




K20251028104936












BLK: 2,SNR1: 1.7807 ,SNR2: 7.8655




1323+32 2025/10/28 1.86UT FUJI -KISO










3C286 2025/10/28 1.94UT TOYOKAWA-KISO





F20251028105427




BLK: 1,SNR1: 9.3197 ,SNR2: 20.825




K20251028105426




BLK: 1,SNR1: 8.0856 ,SNR2: 18.610





3C286 2025/10/28 1.94UT FUJI -KISO







BLK: 2, SNR1: 2.2090 , SNR2: 7.1841




BLK: 2, SNR1: 3.2951 , SNR2: 14.973




1345+12 2025/10/28 2.21UT TOYOKAWA-FUJI




T20251028111055




BLK: 3, SNR1: 3.6875 , SNR2: 6.4542




K20251028111054





BLK: 3, SNR1: 3.2558 , SNR2: 14.414




1345+12 2025/10/28 2.21UT TOYOKAWA-KISO




F20251028111055




BLK: 2,SNR1: 7.6090 ,SNR2: 13.475




K20251028111054



BLK: 2,SNR1: 3.1921 ,SNR2: 9.9492





1345+12 2025/10/28 2.21UT FUJI -KISO







T20251028112115




BLK: 4,SNR1: 9.0177 ,SNR2: 22.174




F20251028112116





BLK: 4,SNR1: 16.336 ,SNR2: 30.189




1355+01 2025/10/28 2.38UT TOYOKAWA-FUJI




T20251028112115




BLK: 2,SNR1: 7.6897 ,SNR2: 24.481




K20251028112114




BLK: 2,SNR1: 13.973 ,SNR2: 29.931




1355+01 2025/10/28 2.38UT TOYOKAWA-KISO




F20251028112116




BLK: 4,SNR1: 23.249 ,SNR2: 54.448




K20251028112114





BLK: 4,SNR1: 18.083 ,SNR2: 31.866




1355+01 2025/10/28 2.38UT FUJI -KISO



T20251028114226





BLK:12,SNR1: 9.9815 ,SNR2: 31.745




Frequency (Hz)

F20251028114226




BLK:12,SNR1: 18.385 ,SNR2: 25.714





Frequency (Hz)


3C298 2025/10/28 2.74UT TOYOKAWA-FUJI



T20251028114226





BLK:16,SNR1: 8.4361 ,SNR2: 25.786




Frequency (Hz)

K20251028114225





BLK:16,SNR1: 5.2284 ,SNR2: 16.384





Frequency (Hz)

3C298 2025/10/28 2.74UT TOYOKAWA-KISO







BLK: 8,SNR1: 15.633 ,SNR2: 23.281





BLK: 8,SNR1: 6.4917 ,SNR2: 19.446




3C298 2025/10/28 2.74UT FUJI -KISO





T20251028115409




BLK: 6,SNR1: 11.042 ,SNR2: 19.758




F20251028115409





BLK: 6,SNR1: 11.006 ,SNR2: 19.683




1428-03 2025/10/28 2.93UT TOYOKAWA-FUJI





T20251028115409




BLK: 3,SNR1:-0.11349 ,SNR2: 5.2859




K20251028115408



BLK: 3,SNR1: 9.8906 ,SNR2: 19.309




1428-03 2025/10/28 2.93UT TOYOKAWA-KISO








F20251028115409




BLK: 2, SNR1: 15.418 , SNR2: 27.448




K20251028115408




BLK: 2, SNR1: 1.4782 , SNR2: 12.324





1428-03 2025/10/28 2.93UT FUJI -KISO







BLK: 2,SNR1: 18.550 ,SNR2: 28.339




BLK: 2,SNR1: 16.885 ,SNR2: 22.166





1434+03 2025/10/28 3.03UT TOYOKAWA-FUJI







BLK: 2,SNR1: 2.5421 ,SNR2: 6.4315








BLK: 2,SNR1: 9.2228 ,SNR2: 20.560





1434+03 2025/10/28 3.03UT TOYOKAWA-KISO






T20251028121914





BLK:23,SNR1: 7.1686 ,SNR2: 18.601




Frequency (Hz)

F20251028121914




BLK:23,SNR1: 10.584 ,SNR2: 24.705




Frequency (Hz)


1453-10 2025/10/28 3.35UT TOYOKAWA-FUJI





T20251028121914




BLK:30,SNR1: 7.9590 ,SNR2: 20.377




K20251028121913




BLK:30,SNR1: 10.368 ,SNR2: 19.452




1453-10 2025/10/28 3.35UT TOYOKAWA-KISO





F20251028121914




BLK:30,SNR1: 11.777 ,SNR2: 21.987




K20251028121913








BLK:30,SNR1: 10.073 ,SNR2: 18.722





1453-10 2025/10/28 3.35UT FUJI -KISO










T20251028123406




BLK: 1,SNR1: 0.39538 ,SNR2: 2.7252




K20251028123405




BLK: 1,SNR1: 3.7904 ,SNR2: 13.012




1508-05 2025/10/28 3.60UT TOYOKAWA-KISO





F20251028123407




BLK: 1, SNR1: 1.9365 , SNR2: 14.820




K20251028123405








BLK: 1, SNR1: 3.5563 , SNR2: 10.392




1508-05 2025/10/28 3.60UT FUJI -KISO








T20251028124306




BLK:10,SNR1: 10.502 ,SNR2: 25.025




K20251028124305




BLK:10,SNR1: 425.40 ,SNR2: 496.30





3C318 2025/10/28 3.75UT TOYOKAWA-KISO







BLK: 4,SNR1: 7.7873 ,SNR2: 18.264





BLK: 4,SNR1: 239.39 ,SNR2: 259.88




3C318 2025/10/28 3.75UT FUJI -KISO





T20251028124853




BLK: 7,SNR1: 2.8898 ,SNR2: 6.3101




F20251028124853




BLK: 7,SNR1: 27.008 ,SNR2: 30.491




1523+03 2025/10/28 3.84UT TOYOKAWA-FUJI




T20251028124853




BLK: 8,SNR1: 7.6859 ,SNR2: 13.415




K20251028124852




BLK: 8,SNR1: 9.8935 ,SNR2: 17.302




1523+03 2025/10/28 3.84UT TOYOKAWA-KISO





F20251028124853




BLK: 2,SNR1: 0.59353 ,SNR2: 6.6782




K20251028124852




BLK: 2,SNR1: 0.73526E-01,SNR2: 4.3416





1523+03 2025/10/28 3.84UT FUJI -KISO









BLK: 3,SNR1: 15.048 ,SNR2: 22.730




BLK: 3,SNR1: 16.709 ,SNR2: 30.446





1535+139 2025/10/28 4.04UT TOYOKAWA-FUJI







BLK: 1,SNR1: 1.3739 ,SNR2: 6.1912





BLK: 1,SNR1: 8.1427 ,SNR2: 24.060




1535+139 2025/10/28 4.04UT TOYOKAWA-KISO





F20251028130034




No.Good Data




K20251028130032




No.Good Data





1535+139 2025/10/28 4.04UT FUJI -KISO







BLK: 2,SNR1: 11.129 ,SNR2: 27.644





BLK: 2,SNR1: 8.0591 ,SNR2: 20.628




1548+05 2025/10/28 4.26UT TOYOKAWA-FUJI





T20251028131338




BLK: 2,SNR1: 11.822 ,SNR2: 29.608




K20251028131337





BLK: 2,SNR1: 11.402 ,SNR2: 27.232




1548+05 2025/10/28 4.26UT TOYOKAWA-KISO





F20251028131339




BLK: 9,SNR1: 7.5534 ,SNR2: 19.585




K20251028131337





BLK: 9,SNR1: 8.8068 ,SNR2: 22.191




1548+05 2025/10/28 4.26UT FUJI -KISO




T20251028133159




BLK: 6,SNR1: 0.61692 ,SNR2: 2.2480




F20251028133159




BLK: 6,SNR1: 5.3079 ,SNR2: 9.4496





1607+26 2025/10/28 4.56UT TOYOKAWA-FUJI







BLK: 6,SNR1: 0.35320 ,SNR2: 1.4251








BLK: 6,SNR1: 6.1795 ,SNR2: 12.684




1607+26 2025/10/28 4.56UT TOYOKAWA-KISO









T20251028134931




BLK: 3,SNR1: 7.4054 ,SNR2: 18.407




F20251028134931




BLK: 3,SNR1: 6.8853 ,SNR2: 19.270




1623-228 2025/10/28 4.85UT TOYOKAWA-FUJI





T20251028134931




BLK: 3,SNR1: 11.099 ,SNR2: 20.363




K20251028134930




BLK: 3,SNR1: 13.886 ,SNR2: 32.667





1623-228 2025/10/28 4.85UT TOYOKAWA-KISO







BLK: 4,SNR1: 8.5187 ,SNR2: 23.015





BLK: 4,SNR1: 10.801 ,SNR2: 29.649




1623-228 2025/10/28 4.85UT FUJI -KISO





T20251028135801




BLK:19,SNR1: 78.090 ,SNR2: 107.12




F20251028135801




BLK:19,SNR1: 12.101 ,SNR2: 25.379





1631-222 2025/10/28 5.00UT TOYOKAWA-FUJI







BLK:18,SNR1: 29.460 ,SNR2: 65.237




BLK:18,SNR1: 22.024 ,SNR2: 46.766





1631-222 2025/10/28 5.00UT TOYOKAWA-KISO









BLK:11,SNR1: 13.823 ,SNR2: 29.363




BLK:11,SNR1: 22.731 ,SNR2: 48.241




T20251028140338




BLK:11,SNR1: 1.8182 ,SNR2: 10.046




F20251028140338




BLK:11,SNR1: 0.64220 ,SNR2: 3.1950





1638-025 2025/10/28 5.09UT TOYOKAWA-FUJI









BLK:18,SNR1: 0.57071 ,SNR2: 2.5089




BLK:18,SNR1: 4.4693 ,SNR2: 10.468





1638-025 2025/10/28 5.09UT TOYOKAWA-KISO








BLK: 9,SNR1: 1.4933 ,SNR2: 9.8693





BLK: 9,SNR1: 5.5866 ,SNR2: 14.570







BLK:15,SNR1: 9.3006 ,SNR2: 23.508




BLK:15,SNR1: 0.92527 ,SNR2: 7.5222





1644-106 2025/10/28 5.20UT TOYOKAWA-FUJI







BLK:15,SNR1: 9.4042 ,SNR2: 23.748




BLK:15,SNR1: 30.685 ,SNR2: 68.604





1644-106 2025/10/28 5.20UT TOYOKAWA-KISO











BLK:17,SNR1: 4.6065 ,SNR2: 14.197





BLK:17,SNR1: 34.047 ,SNR2: 74.441









BLK: 7,SNR1: 0.16073 ,SNR2: 1.3166




BLK: 7,SNR1: 0.22922 ,SNR2: 2.6878




1650+004 2025/10/28 5.29UT TOYOKAWA-KISO




F20251028141554




BLK: 7,SNR1: 29.497 ,SNR2: 53.943




K20251028141552




BLK: 7,SNR1: 0.10126 ,SNR2: 2.2132





1650+004 2025/10/28 5.29UT FUJI -KISO









BLK:14,SNR1: 1.0292 ,SNR2: 4.3217




BLK:14,SNR1: 0.64535 ,SNR2: 6.9519




1656+053 2025/10/28 5.38UT TOYOKAWA-FUJI





T20251028142124




BLK:10,SNR1: 1.0621 ,SNR2: 7.4014




K20251028142123





BLK:10,SNR1: 20.149 ,SNR2: 42.666





1656+053 2025/10/28 5.38UT TOYOKAWA-KISO






BLK:10,SNR1: 0.54729 ,SNR2: 6.0644



BLK:10,SNR1: 20.691 ,SNR2: 43.892




1656+053 2025/10/28 5.38UT FUJI -KISO





T20251028143754




BLK:14,SNR1: 2.7278 ,SNR2: 8.6230




F20251028143754





BLK:14,SNR1: 0.38655 ,SNR2: 3.1959




1712-033 2025/10/28 5.66UT TOYOKAWA-FUJI




T20251028143754




BLK:18,SNR1: 2.7213 ,SNR2: 8.6009




K20251028143753




BLK:18,SNR1: 7.5894 ,SNR2: 13.218




1712-033 2025/10/28 5.66UT TOYOKAWA-KISO




F20251028143754




BLK:25,SNR1: 0.23288 ,SNR2: 2.4554




K20251028143753





BLK:25,SNR1: 7.5487 ,SNR2: 13.004




1712-033 2025/10/28 5.66UT FUJI -KISO





T20251028145557




BLK:10,SNR1: 3.3537 ,SNR2: 8.3764




F20251028145557





BLK:10,SNR1: 0.77593 ,SNR2: 5.0164




1730-13 2025/10/28 5.96UT TOYOKAWA-FUJI





T20251028145557




BLK:14,SNR1: 1.9003 ,SNR2: 7.0719




K20251028145556



BLK:14,SNR1: 10.250 ,SNR2: 22.201





1730-13 2025/10/28 5.96UT TOYOKAWA-KISO








F20251028145557




BLK: 6,SNR1: 0.74601 ,SNR2: 4.9310




K20251028145556




BLK: 6,SNR1: 9.8287 ,SNR2: 22.339





1730-13 2025/10/28 5.96UT FUJI -KISO







BLK: 5,SNR1: 1.0148 ,SNR2: 2.5858




BLK: 5,SNR1:-0.16476 ,SNR2: 3.4033





1748+031 2025/10/28 6.25UT TOYOKAWA-FUJI







BLK: 4,SNR1: 0.52158 ,SNR2: 0.91744




BLK: 4,SNR1: 2.0131 ,SNR2: 7.7694





1748+031 2025/10/28 6.25UT TOYOKAWA-KISO







BLK: 6,SNR1: 2.8792 ,SNR2: 6.3970




BLK: 6,SNR1: 0.79010 ,SNR2: 3.2585





1748+031 2025/10/28 6.25UT FUJI -KISO







BLK:10,SNR1: 0.38392 ,SNR2: 2.2890




BLK:10,SNR1: 1.7913 ,SNR2: 6.0802





1759+13 2025/10/28 6.43UT TOYOKAWA-FUJI







BLK:10,SNR1: 1.1343 ,SNR2: 1.6699







BLK:10,SNR1: 3.4441 ,SNR2: 7.5275




1759+13 2025/10/28 6.43UT TOYOKAWA-KISO








1759+13 2025/10/28 6.43UT FUJI -KISO



T20251028154515




BLK: 4,SNR1: 0.13809 ,SNR2: 0.45143




Frequency (Hz)

F20251028154515




BLK: 4,SNR1:-0.19134 ,SNR2: 1.3461





Frequency (Hz)

1819-096 2025/10/28 6.78UT TOYOKAWA-FUJI






T20251028154515





BLK: 5, SNR1: 0.60175E-02, SNR2: 0.27749




Frequency (Hz)

K20251028154514




BLK: 5, SNR1: 28.218, SNR2: 50.910




Frequency (Hz)


1819-096 2025/10/28 6.78UT TOYOKAWA-KISO



F20251028154515





BLK: 7,SNR1:-0.22341E-01,SNR2: 3.2551




Frequency (Hz)

K20251028154514




BLK: 7,SNR1: 65.228 ,SNR2: 75.259





Frequency (Hz)


1819-096 2025/10/28 6.78UT FUJI -KISO



T20251028155630





BLK:18,SNR1: 16.668 ,SNR2: 21.700




Frequency (Hz)

F20251028155630





BLK:18,SNR1: 100.38 ,SNR2: 88.989





Frequency (Hz)

1830-210 2025/10/28 6.97UT TOYOKAWA-FUJI







BLK:16,SNR1: 11.243 ,SNR2: 24.418




BLK:16,SNR1: 8.2523 ,SNR2: 18.188





1830-210 2025/10/28 6.97UT TOYOKAWA-KISO







BLK:15,SNR1: 99.135 ,SNR2: 87.883







BLK:15,SNR1: 5.1685 ,SNR2: 11.457





1830-210 2025/10/28 6.97UT FUJI -KISO







1858+171 2025/10/28 7.41UT TOYOKAWA-FUJI







BLK: 4,SNR1: 0.18751E-01,SNR2: 0.46963








BLK: 4,SNR1: 5.9568 ,SNR2: 18.306







1858+171 2025/10/28 7.41UT TOYOKAWA-KISO













1908-20 2025/10/28 7.59UT TOYOKAWA-FUJI







BLK: 1, SNR1: 1.1420 , SNR2: 5.5372





BLK: 1, SNR1: 4.0610 , SNR2: 13.073




1908-20 2025/10/28 7.59UT TOYOKAWA-KISO



F20251028163341





BLK: 5, SNR1: 4.5459 , SNR2: 11.555




Frequency (Hz)

K20251028163339





BLK: 5, SNR1: 5.2620 , SNR2: 13.354





Frequency (Hz)

1908-20 2025/10/28 7.59UT FUJI -KISO







BLK: 7, SNR1: 8.8129 , SNR2: 18.891





BLK: 7, SNR1: 1.6925 , SNR2: 8.0518




1915-121 2025/10/28 7.70UT TOYOKAWA-FUJI



T20251028164030





BLK: 5, SNR1: 0.83676 , SNR2: 3.1565




Frequency (Hz)

K20251028164029








BLK: 5, SNR1: 14.549 , SNR2: 33.594




Frequency (Hz)


1915-121 2025/10/28 7.70UT TOYOKAWA-KISO







1915-121 2025/10/28 7.70UT FUJI -KISO







BLK: 6, SNR1: 0.54192 , SNR2: 5.1474




BLK: 6, SNR1: 0.28427 , SNR2: 2.2947





1928-142 2025/10/28 7.93UT TOYOKAWA-FUJI







BLK: 7, SNR1: 0.53076 , SNR2: 4.6034



BLK: 7, SNR1: 3.2028 , SNR2: 7.0070




1928-142 2025/10/28 7.93UT TOYOKAWA-KISO






F20251028165412





BLK: 3,SNR1:-0.21201 ,SNR2: 0.38928E-01




Frequency (Hz)

K20251028165411





BLK: 3,SNR1: 7.7092 ,SNR2: 17.223





Frequency (Hz)

1928-142 2025/10/28 7.93UT FUJI -KISO







BLK:10,SNR1: 5.4727 ,SNR2: 13.141




BLK:10,SNR1: 7.4287 ,SNR2: 12.724





1938-15 2025/10/28 8.09UT TOYOKAWA-FUJI







BLK: 9, SNR1: 4.6481 , SNR2: 8.9647







BLK: 9, SNR1: 6.8470 , SNR2: 11.341



1938-15 2025/10/28 8.09UT TOYOKAWA-KISO





1938-15 2025/10/28 8.09UT FUJI -KISO

