




T20251030055324





BLK: 4, SNR1: 2.1939 , SNR2: 6.6359





0834-19 2025/10/29 20.92UT TOYOKAWA-FUJI



F20251030055324




BLK: 4, SNR1: 6.1546 , SNR2: 14.470




T20251030055324




BLK: 7, SNR1: 7.4147 , SNR2: 18.376




K20251030055323



BLK: 7, SNR1: 11.247 , SNR2: 25.627





0834-19 2025/10/29 20.92UT TOYOKAWA-KISO








F20251030055324




BLK:11,SNR1: 9.5382 ,SNR2: 21.701




K20251030055323







BLK:11,SNR1: 10.603 ,SNR2: 18.047





0834-19 2025/10/29 20.92UT FUJI -KISO









BLK: 1,SNR1: 0.12377 ,SNR2: 1.0566




BLK: 1,SNR1: 0.19555 ,SNR2: 2.8284






0839-071 2025/10/29 21.00UT TOYOKAWA-KISO







BLK: 2,SNR1: 0.24312 ,SNR2: 6.2986




BLK: 2,SNR1: 0.44122E-01,SNR2: 0.60951





0839-071 2025/10/29 21.00UT FUJI -KISO







BLK: 1,SNR1: 10.946 ,SNR2: 39.448









BLK: 1,SNR1: 25.412 ,SNR2: 56.696





0857-191 2025/10/29 21.29UT TOYOKAWA-FUJI













0912-132 2025/10/29 21.54UT TOYOKAWA-FUJI









BLK:10,SNR1: 0.66017E-01,SNR2: 0.60189





BLK:10,SNR1: 7.6572 ,SNR2: 13.647




0912-132 2025/10/29 21.54UT TOYOKAWA-KISO








0912-132 2025/10/29 21:54UT FUJI -KISO





T20251030063824




No.Good Data




F20251030063824




No.Good Data





0919-142 2025/10/29 21.67UT TOYOKAWA-FUJI







BLK: 2,SNR1: 5.5750 ,SNR2: 10.791





BLK: 2,SNR1: 9.6432 ,SNR2: 30.133




0919-142 2025/10/29 21.67UT TOYOKAWA-KISO




F20251030063824




BLK: 2, SNR1: 3.8711 , SNR2: 11.188




K20251030063823









BLK: 2, SNR1: 12.076 , SNR2: 36.691





0919-142 2025/10/29 21.67UT FUJI -KISO









F20251030064504




BLK: 6, SNR1: 13.289 , SNR2: 16.463




K20251030064502







BLK: 6, SNR1: 12.431 , SNR2: 16.606




0926+117 2025/10/29 21.78UT FUJI -KISO











3C222 2025/10/29 21.91UT TOYOKAWA-FUJI








F20251030065249




BLK: 1,SNR1:-0.22660 ,SNR2: 0.68622




K20251030065247












BLK: 1,SNR1:-0.94647E-02,SNR2: 1.1069




3C222 2025/10/29 21.91UT FUJI -KISO

















0941-08 2025/10/29 22.02UT TOYOKAWA-KISO






0941-08 2025/10/29 22.02UT FUJI -KISO








T20251030070810




BLK: 3, SNR1: 3.4664 , SNR2: 10.995




K20251030070809







BLK: 3, SNR1: 11.082 , SNR2: 22.610




3C230 2025/10/29 22.16UT TOYOKAWA-KISO









3C230 2025/10/29 22.16UT FUJI -KISO




T20251030072410




BLK: 9, SNR1: 3.2313 , SNR2: 7.3984




F20251030072411




BLK: 9, SNR1: 28.530 , SNR2: 37.600




3C237 2025/10/29 22.43UT TOYOKAWA-FUJI





T20251030072410




BLK: 8, SNR1: 3.9476 , SNR2: 6.0113




K20251030072409







BLK: 8, SNR1: 21.390 , SNR2: 35.544





3C237 2025/10/29 22.43UT TOYOKAWA-KISO







3C237 2025/10/29 22.43UT FUJI -KISO







BLK: 4, SNR1: 0.14387E-01, SNR2: 0.84296





BLK: 4, SNR1: 3.3020 ,SNR2: 6.5458




1011+110 2025/10/29 22.54UT TOYOKAWA-FUJI





T20251030073027




BLK: 3, SNR1: 1.5820 , SNR2: 17.369




K20251030073026





BLK: 3, SNR1: 10.359 , SNR2: 18.351




1011+110 2025/10/29 22.54UT TOYOKAWA-KISO





F20251030073028




BLK: 5, SNR1: 1.6649 ,SNR2: 4.4316




K20251030073026




BLK: 5, SNR1: 2.2267 ,SNR2: 4.9299





1011+110 2025/10/29 22.54UT FUJI -KISO








BLK: 4,SNR1: 0.22092 ,SNR2: 1.3821





BLK: 4,SNR1: 0.68843E-02,SNR2: 1.3593










BLK: 5,SNR1: 0.26818 ,SNR2: 1.0421




BLK: 5,SNR1: 0.14828E-01,SNR2: 1.8126





F20251030073808




BLK: 5,SNR1: 0.34759 ,SNR2: 2.9262




K20251030073807




BLK: 5,SNR1: 0.14353 ,SNR2: 1.7893





3C241 2025/10/29 22.66UT FUJI -KISO







BLK: 4, SNR1: 0.28568 , SNR2: 1.1621




BLK: 4, SNR1: -0.33747 , SNR2: 1.0516





1031-11 2025/10/29 22.86UT TOYOKAWA-FUJI











BLK: 1,SNR1: 0.32475 ,SNR2: 2.1498





BLK: 1,SNR1: 0.23773 ,SNR2: 2.2405







1031-11 2025/10/29 22.86UT FUJI -KISO







BLK: 7,SNR1: 0.98712 ,SNR2: 8.5277




BLK: 7,SNR1: 1.1987 ,SNR2: 7.7932





1035-058 2025/10/29 22.93UT TOYOKAWA-FUJI








BLK: 5,SNR1: 4.2812 ,SNR2: 27.078




BLK: 5,SNR1: 1.6969 ,SNR2: 9.0234




F20251030075410




BLK: 5, SNR1: 7.0991 , SNR2: 15.710




K20251030075409








BLK: 5, SNR1: 16.076 , SNR2: 28.857












1035-058 2025/10/29 22.93UT FUJI -KISO


















1044-008 2025/10/29 23.08UT FUJI -KISO







1055+01 2025/10/29 23.27UT TOYOKAWA-FUJI











BLK: 5,SNR1:-0.20704E-01,SNR2: 1.5230




BLK: 5,SNR1: 0.94332 ,SNR2: 5.1649








1055+01 2025/10/29 23.27UT FUJI -KISO





T20251030082545




BLK: 7, SNR1: 0.11239 , SNR2: 1.0530




F20251030082545




BLK: 7, SNR1: 5.9457 , SNR2: 11.470




1107+109 2025/10/29 23.46UT TOYOKAWA-FUJI




T20251030082545




BLK: 6, SNR1: 0.17765 , SNR2: 0.59360




K20251030082544







BLK: 6, SNR1: 3.7970 , SNR2: 6.8499




1107+109 2025/10/29 23.46UT TOYOKAWA-KISO










1107+109 2025/10/29 23.46UT FUJI -KISO




T20251030083522




BLK: 3, SNR1: 0.69906 , SNR2: 2.2278




F20251030083523





BLK: 3, SNR1: 1.1288 , SNR2: 4.0881




3C255 2025/10/29 23.62UT TOYOKAWA-FUJI





T20251030083522




BLK: 5, SNR1: 0.50456 , SNR2: 5.3363




K20251030083521







BLK: 5, SNR1: 3.0457 , SNR2: 7.8224




3C255 2025/10/29 23.62UT TOYOKAWA-KISO








3C255 2025/10/29 23.62UT FUJI -KISO





T20251030084600




BLK: 5, SNR1: 35.117 , SNR2: 49.950




F20251030084600





BLK: 5, SNR1: 19.604 , SNR2: 33.436




1127-14 2025/10/29 23.79UT TOYOKAWA-FUJI





T20251030084600




BLK: 4, SNR1: 42.431 , SNR2: 68.520




K20251030084559




BLK: 4, SNR1: 37.394 , SNR2: 60.318




1127-14 2025/10/29 23.79UT TOYOKAWA-KISO





F20251030084600




BLK: 3, SNR1: 32.510 , SNR2: 45.357




K20251030084559







BLK: 3, SNR1: 14.704 , SNR2: 31.959




1127-14 2025/10/29 23.79UT FUJI -KISO







3C267 2025/10/30 0.12UT TOYOKAWA-FUJI








T20251030090547




BLK: 8,SNR1: 9.7852 ,SNR2: 20.415




K20251030090546




BLK: 8,SNR1: 18.331 ,SNR2: 24.505




3C267 2025/10/30 0.12UT TOYOKAWA-KISO





F20251030090547




BLK: 6, SNR1: 20.969 , SNR2: 34.709




K20251030090546







BLK: 6, SNR1: 18.544 , SNR2: 25.280








3C267 2025/10/30 0.12UT FUJI -KISO






1213-17 2025/10/30 0.55UT TOYOKAWA-FUJI







1213-17 2025/10/30 0.55UT TOYOKAWA-KISO





F20251030093136




BLK: 2, SNR1: 2.1958 ,SNR2: 7.3054




K20251030093134







BLK: 2, SNR1: 2.4490 ,SNR2: 6.4328









1213-17 2025/10/30 0.55UT FUJI -KISO






3C273 2025/10/30 0.78UT TOYOKAWA-FUJI








F20251030094453




BLK:15,SNR1:-0.55094E-01,SNR2: 2.8052




K20251030094451





BLK:15,SNR1: 5.4806 ,SNR2: 13.013




3C273 2025/10/30 0.78UT FUJI -KISO














3C275 2025/10/30 1.00UT TOYOKAWA-FUJI






F20251030095803





No. Good Data




Frequency (Hz)

K20251030095802





No. Good Data





Frequency (Hz)

3C275 2025/10/30 1.00UT FUJI -KISO







BLK: 1,SNR1: 14.785 ,SNR2: 35.566







BLK: 1,SNR1: 23.474 ,SNR2: 43.109








1245-19 2025/10/30 1.10UT TOYOKAWA-FUJI








1245-19 2025/10/30 1.10UT TOYOKAWA-KISO










1245-19 2025/10/30 1.10UT FUJI -KISO






3C279 2025/10/30 1.23UT TOYOKAWA-FUJI








3C279 2025/10/30 1.23UT TOYOKAWA-KISO


























3C279 2025/10/30 1.23UT FUJI -KISO






















1323+32 2025/10/30 1.72UT TOYOKAWA-FUJI









1323+32 2025/10/30 1.72UT FUJI -KISO





T20251030104636




BLK: 2,SNR1: 17.406 ,SNR2: 31.489




F20251030104636



BLK: 2,SNR1: 11.172 ,SNR2: 35.528




3C286 2025/10/30 1.80UT TOYOKAWA-FUJI








T20251030104636




BLK: 1, SNR1: 18.528 , SNR2: 33.513




K20251030104635







BLK: 1, SNR1: 15.263 , SNR2: 27.250









3C286 2025/10/30 1.80UT TOYOKAWA-KISO











3C286 2025/10/30 1.80UT FUJI -KISO













BLK:11,SNR1: 3.0323 ,SNR2: 11.311





BLK:11,SNR1: 25.993 ,SNR2: 67.822




1345+12 2025/10/30 2.08UT FUJI -KISO





T20251030111323




BLK: 8, SNR1: 17.955 , SNR2: 23.418




F20251030111324





BLK: 8, SNR1: 5.6511 , SNR2: 10.286




1355+01 2025/10/30 2.25UT TOYOKAWA-FUJI





T20251030111323




BLK: 9, SNR1: 3.1613 , SNR2: 8.1696




K20251030111322





BLK: 9, SNR1: 7.0400 , SNR2: 17.070




1355+01 2025/10/30 2.25UT TOYOKAWA-KISO





F20251030111324




BLK: 6,SNR1: 6.0811 ,SNR2: 15.081




K20251030111322








BLK: 6,SNR1: 8.0478 ,SNR2: 13.827







1355+01 2025/10/30 2.25UT FUJI -KISO












3C298 2025/10/30 2.60UT TOYOKAWA-KISO




F20251030113434




BLK: 8,SNR1: 18.097 ,SNR2: 31.820




K20251030113433





BLK: 8,SNR1: 17.149 ,SNR2: 30.741




3C298 2025/10/30 2.60UT FUJI -KISO



T20251030114618





BLK: 1, SNR1: 0.22537E-01, SNR2: 1.2560




Frequency (Hz)

F20251030114619




BLK: 1, SNR1: 8.1803, SNR2: 13.899





Frequency (Hz)


1428-03 2025/10/30 2.80UT TOYOKAWA-FUJI



T20251030114618





No. Good Data




Frequency (Hz)

K20251030114617




No. Good Data




Frequency (Hz)


1428-03 2025/10/30 2.80UT TOYOKAWA-KISO




F20251030114619




BLK: 3,SNR1: 7.6129 ,SNR2: 23.744




K20251030114617





BLK: 3,SNR1: 9.2271 ,SNR2: 22.893




1428-03 2025/10/30 2.80UT FUJI -KISO





T20251030115220




BLK: 2,SNR1: 9.4005 ,SNR2: 23.117




F20251030115221




BLK: 2,SNR1: 7.9192 ,SNR2: 19.652




1434+03 2025/10/30 2.90UT TOYOKAWA-FUJI





T20251030115220




BLK: 2,SNR1: 1.9651 ,SNR2: 9.5528




K20251030115219



BLK: 2,SNR1: 11.925 ,SNR2: 28.932





1434+03 2025/10/30 2.90UT TOYOKAWA-KISO








F20251030115221




BLK: 2,SNR1: 7.5713 ,SNR2: 18.431




K20251030115219




BLK: 2,SNR1: 10.799 ,SNR2: 30.718




1434+03 2025/10/30 2.90UT FUJI -KISO




T20251030121122




BLK: 5,SNR1: 13.355 ,SNR2: 37.839




F20251030121123




BLK: 5,SNR1: 7.1180 ,SNR2: 20.116




1453-10 2025/10/30 3.22UT TOYOKAWA-FUJI





T20251030121122




BLK: 7,SNR1: 8.1158 ,SNR2: 23.438




K20251030121121




BLK: 7,SNR1: 9.4357 ,SNR2: 23.721




1453-10 2025/10/30 3.22UT TOYOKAWA-KISO





F20251030121123




BLK: 5, SNR1: 6.4562 , SNR2: 17.019




K20251030121121





BLK: 5, SNR1: 10.905 , SNR2: 25.694




1453-10 2025/10/30 3.22UT FUJI -KISO





T20251030122615




BLK:16,SNR1: 9.4132 ,SNR2: 16.307




F20251030122615





BLK:16,SNR1: 8.4735 ,SNR2: 15.167




1508-05 2025/10/30 3.47UT TOYOKAWA-FUJI





T20251030122615




BLK:13,SNR1: 9.5110 ,SNR2: 16.466




K20251030122614





BLK:13,SNR1: 7.5956 ,SNR2: 13.837




1508-05 2025/10/30 3.47UT TOYOKAWA-KISO





F20251030122615




BLK:16,SNR1: 8.3433 ,SNR2: 14.964




K20251030122614




BLK:16,SNR1: 7.5955 ,SNR2: 13.837





1508-05 2025/10/30 3.47UT FUJI -KISO







BLK: 9,SNR1: 6.9321 ,SNR2: 19.952







BLK: 9,SNR1: 8.7015 ,SNR2: 24.810




3C318 2025/10/30 3.62UT TOYOKAWA-FUJI










3C318 2025/10/30 3.62UT TOYOKAWA-KISO







BLK: 5,SNR1: 7.9056 ,SNR2: 20.804




BLK: 5,SNR1: 8.1617 ,SNR2: 23.967




3C318 2025/10/30 3.62UT FUJI -KISO




T20251030124101




BLK:12,SNR1: 1.3232 ,SNR2: 4.5847




F20251030124102




BLK:12,SNR1: 0.75320 ,SNR2: 3.3513




1523+03 2025/10/30 3.71UT TOYOKAWA-FUJI





T20251030124101




BLK:10,SNR1: 2.7967 ,SNR2: 7.1717




K20251030124100




BLK:10,SNR1: 11.246 ,SNR2: 63.173




1523+03 2025/10/30 3.71UT TOYOKAWA-KISO





F20251030124102




BLK: 7, SNR1: 0.86832 , SNR2: 3.6898




K20251030124100





BLK: 7, SNR1: 3.8448 , SNR2: 19.348




1523+03 2025/10/30 3.71UT FUJI -KISO





T20251030125241




BLK: 4,SNR1: 0.78040 ,SNR2: 2.5616




F20251030125242







BLK: 4,SNR1: 7.1061 ,SNR2: 10.110




1535+139 2025/10/30 3.91UT TOYOKAWA-FUJI







1535+139 2025/10/30 3.91UT TOYOKAWA-KISO





F20251030125242




BLK: 8,SNR1: 5.2318 ,SNR2: 9.0131




K20251030125240




BLK: 8,SNR1: 17.344 ,SNR2: 25.926





1535+139 2025/10/30 3.91UT FUJI -KISO









BLK: 6,SNR1: 6.8806 ,SNR2: 16.556




BLK: 6,SNR1: 14.176 ,SNR2: 25.120





1548+05 2025/10/30 4.12UT TOYOKAWA-FUJI







BLK: 7,SNR1: 6.4139 ,SNR2: 15.637




BLK: 7,SNR1: 7.9563 ,SNR2: 23.351




1548+05 2025/10/30 4.12UT TOYOKAWA-KISO




F20251030130547




BLK: 4,SNR1: 6.2558 ,SNR2: 19.263




K20251030130546









BLK: 4,SNR1: 10.261 ,SNR2: 30.830





1548+05 2025/10/30 4.12UT FUJI -KISO









BLK: 9,SNR1: 0.29052 ,SNR2: 1.7564




BLK: 9,SNR1: 1.3744 ,SNR2: 7.0501





1607+26 2025/10/30 4.43UT TOYOKAWA-KISO







BLK:10,SNR1: 3.4737 ,SNR2: 8.6365




BLK:10,SNR1: 1.3430 ,SNR2: 4.4735






1607+26 2025/10/30 4.43UT FUJI -KISO




T20251030134139







F20251030134140




1623-228 2025/10/30 4.72UT TOYOKAWA-FUJI








1623-228 2025/10/30 4.72UT TOYOKAWA-KISO









BLK:11,SNR1: 6.4406 ,SNR2: 15.491




BLK:11,SNR1: 18.235 ,SNR2: 38.776





1623-228 2025/10/30 4.72UT FUJI -KISO







BLK:12,SNR1: 2.2443 ,SNR2: 3.3228





BLK:12,SNR1: 2.9868 ,SNR2: 7.9671




1631-222 2025/10/30 4.86UT TOYOKAWA-FUJI





T20251030135009




BLK:15,SNR1: 0.41553 ,SNR2: 1.2516




K20251030135008









BLK:15,SNR1: 4.4542 ,SNR2: 8.5172





1631-222 2025/10/30 4.86UT TOYOKAWA-KISO









BLK: 7,SNR1: 0.42336 ,SNR2: 1.9453





BLK: 7,SNR1: 2.6459 ,SNR2: 7.9691




1638-025 2025/10/30 4.96UT TOYOKAWA-FUJI





T20251030135546




BLK:13,SNR1: 1.6073 ,SNR2: 3.6849




K20251030135545









BLK:13,SNR1: 7.8394 ,SNR2: 22.937





1638-025 2025/10/30 4.96UT TOYOKAWA-KISO









BLK:13,SNR1: 1.1579 ,SNR2: 2.0729




BLK:13,SNR1: 1.3429 ,SNR2: 5.3744





1644-106 2025/10/30 5.07UT TOYOKAWA-FUJI









BLK:11,SNR1: 0.45975 ,SNR2: 1.9367




BLK:11,SNR1: 3.7079 ,SNR2: 7.0637





1644-106 2025/10/30 5.07UT TOYOKAWA-KISO








BLK: 9,SNR1: 2.1523 ,SNR2: 10.776





BLK: 9,SNR1: 4.9614 ,SNR2: 9.9770







BLK: 9,SNR1: 2.6645 ,SNR2: 8.4022




BLK: 9,SNR1: 0.63271E-01,SNR2: 2.1875





1650+004 2025/10/30 5.16UT TOYOKAWA-FUJI







BLK:19,SNR1: 2.4810 ,SNR2: 7.8097




BLK:19,SNR1: 8.6399 ,SNR2: 15.104





1650+004 2025/10/30 5.16UT TOYOKAWA-KISO







BLK:17,SNR1: 0.14960 ,SNR2: 2.1812




BLK:17,SNR1: 8.6225 ,SNR2: 15.076





1650+004 2025/10/30 5.16UT FUJI -KISO







BLK: 9,SNR1: 0.50647 ,SNR2: 1.2787




BLK: 9,SNR1: 0.48688 ,SNR2: 5.5875





1656+053 2025/10/30 5.25UT TOYOKAWA-FUJI







BLK:12,SNR1: 0.45969 ,SNR2: 1.6595




BLK:12,SNR1: 5.6621 ,SNR2: 7.4124





1656+053 2025/10/30 5.25UT TOYOKAWA-KISO







BLK:13,SNR1: 1.0905 ,SNR2: 4.4256





BLK:13,SNR1: 4.3205 ,SNR2: 8.3097







T20251030143003




BLK: 9,SNR1: 0.79736E-01,SNR2: 0.50813




F20251030143003





BLK: 9,SNR1: 0.52129 ,SNR2: 4.7989




1712-033 2025/10/30 5.53UT TOYOKAWA-FUJI





T20251030143003




BLK:11,SNR1:-0.15075E-02,SNR2: 0.29219




K20251030143002





BLK:11,SNR1: 1.1053 ,SNR2: 1.9455




1712-033 2025/10/30 5.53UT TOYOKAWA-KISO





F20251030143003




BLK: 9,SNR1: 5.6926 ,SNR2: 16.479




K20251030143002





BLK: 9,SNR1: 1.1503 ,SNR2: 2.3606




1712-033 2025/10/30 5.53UT FUJI -KISO




T20251030144805




BLK: 5,SNR1: 0.43690 ,SNR2: 1.5559




F20251030144805





BLK: 5,SNR1: 0.37992 ,SNR2: 4.4877




1730-13 2025/10/30 5.83UT TOYOKAWA-FUJI





T20251030144805




BLK: 6,SNR1: 0.46885 ,SNR2: 1.8848




K20251030144804




BLK: 6,SNR1: 5.7707 ,SNR2: 11.490




1730-13 2025/10/30 5.83UT TOYOKAWA-KISO





F20251030144805




BLK: 7, SNR1: 0.15574 , SNR2: 4.9745




K20251030144804




BLK: 7, SNR1: 5.0944 , SNR2: 12.496





1730-13 2025/10/30 5.83UT FUJI -KISO







BLK: 6, SNR1: 3.3027 , SNR2: 6.9409




BLK: 6, SNR1: 0.92908 , SNR2: 8.7980





1748+031 2025/10/30 6.12UT TOYOKAWA-FUJI







BLK: 8,SNR1: 1.7049 ,SNR2: 4.9802








BLK: 8,SNR1: 3.9696 ,SNR2: 7.0045




1748+031 2025/10/30 6.12UT TOYOKAWA-KISO













BLK: 3,SNR1:-0.10723 ,SNR2: 0.26043







BLK: 3,SNR1: 0.46529 ,SNR2: 1.8247





1759+13 2025/10/30 6.30UT TOYOKAWA-FUJI







1759+13 2025/10/30 6.30UT TOYOKAWA-KISO














BLK: 2,SNR1:-0.26844 ,SNR2: 0.86631




BLK: 2,SNR1: 0.22851 ,SNR2: 1.3413










1819-096 2025/10/30 6.65UT TOYOKAWA-KISO



F20251030153723




BLK: 5, SNR1: 0.19111 , SNR2: 3.6096




Frequency (Hz)

K20251030153722




BLK: 5, SNR1: 1.4013 , SNR2: 4.1192





Frequency (Hz)


1819-096 2025/10/30 6.65UT FUJI -KISO



T20251030154839





BLK:13,SNR1: 5.6654 ,SNR2: 9.7397




Frequency (Hz)

F20251030154839




BLK:13,SNR1: 15.196 ,SNR2: 19.381





Frequency (Hz)

1830-210 2025/10/30 6.84UT TOYOKAWA-FUJI






T20251030154839





BLK: 6,SNR1: 6.9266 ,SNR2: 11.833




Frequency (Hz)

K20251030154838





BLK: 6,SNR1: 5.3840 ,SNR2: 9.5418





Frequency (Hz)

1830-210 2025/10/30 6.84UT TOYOKAWA-KISO











BLK:18,SNR1: 10.438 ,SNR2: 11.426





BLK:18,SNR1: 11.575 ,SNR2: 20.406







1858+171 2025/10/30 7.28UT TOYOKAWA-FUJI







BLK: 3,SNR1: 3.0075 ,SNR2: 9.1603




BLK: 3,SNR1: 9.4366 ,SNR2: 19.769





1858+171 2025/10/30 7.28UT TOYOKAWA-KISO








BLK: 6,SNR1: 3.1504 ,SNR2: 11.762





BLK: 6,SNR1: 13.300 ,SNR2: 23.981







BLK: 5, SNR1: 2.1757 , SNR2: 4.3525




BLK: 5, SNR1: 13.849 , SNR2: 10.902





1908-20 2025/10/30 7.46UT TOYOKAWA-FUJI







BLK: 5, SNR1: 8.7695 , SNR2: 20.047








BLK: 5, SNR1: 10.245 , SNR2: 21.928





1908-20 2025/10/30 7.46UT TOYOKAWA-KISO








T20251030163238





BLK: 2,SNR1: 0.98648E-01,SNR2: 2.1975




Frequency (Hz)

F20251030163239





BLK: 2,SNR1: 0.78746E-01,SNR2: 1.0391





Frequency (Hz)

1915-121 2025/10/30 7.57UT TOYOKAWA-FUJI







BLK: 8,SNR1: 0.53240 ,SNR2: 1.5901




BLK: 8,SNR1: 0.82703 ,SNR2: 4.5657





1915-121 2025/10/30 7.57UT TOYOKAWA-KISO







BLK: 1, SNR1: 2.8982 , SNR2: 5.2387




BLK: 1, SNR1: 0.18362 , SNR2: 1.0476





1915-121 2025/10/30 7.57UT FUJI -KISO







BLK: 5, SNR1: 3.3528 , SNR2: 8.9914




BLK: 5, SNR1: 2.2240 , SNR2: 3.0458





1928-142 2025/10/30 7.80UT TOYOKAWA-FUJI







BLK:11,SNR1: 2.5010 ,SNR2: 6.8319





BLK:11,SNR1: 3.9894 ,SNR2: 16.790




1928-142 2025/10/30 7.80UT TOYOKAWA-KISO



F20251030164621





BLK: 5, SNR1: 2.7658 , SNR2: 3.4227




Frequency (Hz)

K20251030164619







BLK: 5, SNR1: 4.0040 , SNR2: 16.848




Frequency (Hz)



1928-142 2025/10/30 7.80UT FUJI -KISO








BLK: 4, SNR1: 1.4238 , SNR2: 6.2473



BLK: 4, SNR1: 2.0088 , SNR2: 5.1995



1938-15 2025/10/30 7.96UT TOYOKAWA-KISO

