








BLK:18,SNR1: 7.9830 ,SNR2: 20.741




BLK:18,SNR1: 9.3008 ,SNR2: 20.141





0919-142 2025/11/10 20.88UT TOYOKAWA-FUJI







BLK:20,SNR1: 7.8229 ,SNR2: 20.337



BLK:20,SNR1: 8.4085 ,SNR2: 18.624





0919-142 2025/11/10 20.88UT TOYOKAWA-KISO






F20251111055113





BLK:22,SNR1: 9.3116 ,SNR2: 20.161








0919-142 2025/11/10 20.88UT FUJI -KISO


K20251111055112





BLK:22,SNR1: 8.4381 ,SNR2: 18.689









BLK: 6, SNR1: 0.52769 , SNR2: 6.1710





BLK: 6, SNR1: 1.8157 , SNR2: 4.8057




0928-179 2025/11/10 21.02UT TOYOKAWA-KISO




F20251111055947




BLK: 8,SNR1:-0.12700 ,SNR2: 1.3815




K20251111055945





BLK: 8,SNR1: 3.4003 ,SNR2: 12.212






0928-179 2025/11/10 21.02UT FUJI -KISO







0941-08 2025/11/10 21.24UT TOYOKAWA-FUJI







0941-08 2025/11/10 21.24UT TOYOKAWA-KISO







BLK: 4,SNR1:-0.18078 ,SNR2: 1.9725




BLK: 4,SNR1: 0.61313 ,SNR2: 2.0160





0941-08 2025/11/10 21.24UT FUJI -KISO







BLK:12,SNR1: 6.2425 ,SNR2: 19.135




BLK:12,SNR1: 8.8098 ,SNR2: 26.010





3C230 2025/11/10 21.38UT TOYOKAWA-FUJI









BLK:13,SNR1: 7.0275 ,SNR2: 21.426




BLK:13,SNR1: 7.8448 ,SNR2: 20.105





3C230 2025/11/10 21.38UT TOYOKAWA-KISO







BLK:12,SNR1: 8.1616 ,SNR2: 24.146












BLK:12,SNR1: 7.9431 ,SNR2: 20.405




3C230 2025/11/10 21.38UT FUJI -KISO









3C237 2025/11/10 21.64UT TOYOKAWA-KISO








BLK: 7,SNR1: 11.078 ,SNR2: 26.974




3C237 2025/11/10 21.64UT FUJI -KISO





BLK: 7,SNR1: 10.688 ,SNR2: 25.769







BLK: 2,SNR1: 16.920 ,SNR2: 30.144




BLK: 2,SNR1: 9.3527 ,SNR2: 23.054




1011+110 2025/11/10 21.75UT TOYOKAWA-FUJI




T20251111064316




BLK: 2, SNR1: 14.107 , SNR2: 42.675




K20251111064315





BLK: 2, SNR1: 8.9280 , SNR2: 22.289




1011+110 2025/11/10 21.75UT TOYOKAWA-KISO





F20251111064316




No.Good Data




K20251111064315



No.Good Data





1011+110 2025/11/10 21.75UT FUJI -KISO






T20251111065057




BLK: 5, SNR1: 0.21089 , SNR2: 1.1955





3C241 2025/11/10 21.88UT TOYOKAWA-FUJI



F20251111065058




BLK: 5, SNR1: 1.8554 , SNR2: 5.6214





T20251111065057




BLK: 3, SNR1: 0.55280 , SNR2: 2.2642




K20251111065056





BLK: 3, SNR1: 1.5032 , SNR2: 4.9501




3C241 2025/11/10 21.88UT TOYOKAWA-KISO





F20251111065058




BLK: 3,SNR1: 2.0677 ,SNR2: 6.6921




K20251111065056





BLK: 3,SNR1: 3.4885 ,SNR2: 8.7844




3C241 2025/11/10 21.88UT FUJI -KISO




T20251111070226




BLK: 2, SNR1: 0.51046 , SNR2: 4.0186




F20251111070227





BLK: 2, SNR1: 0.33451E-01, SNR2: 2.7100




1031-11 2025/11/10 22.07UT TOYOKAWA-FUJI





T20251111070226




BLK: 1, SNR1: 0.67600 , SNR2: 3.7210




K20251111070225




BLK: 1, SNR1: 1.7702 , SNR2: 9.8232




1031-11 2025/11/10 22.07UT TOYOKAWA-KISO





F20251111070227




BLK: 3, SNR1: 1.6346 , SNR2: 14.270




K20251111070225





BLK: 3, SNR1: 2.6587 , SNR2: 7.2287








1031-11 2025/11/10 22.07UT FUJI -KISO






1035-058 2025/11/10 22.14UT TOYOKAWA-FUJI






1035-058 2025/11/10 22.14UT TOYOKAWA-KISO







F20251111070700




BLK: 3,SNR1: 19.119 ,SNR2: 34.590




K20251111070658





BLK: 3,SNR1: 8.2200 ,SNR2: 20.586




1035-058 2025/11/10 22.14UT FUJI -KISO





T20251111071502




No.Good Data




F20251111071502





No.Good Data




1043+158 2025/11/10 22.28UT TOYOKAWA-FUJI





T20251111071502




No.Good Data




K20251111071501





No.Good Data




1043+158 2025/11/10 22.28UT TOYOKAWA-KISO





F20251111071502




No.Good Data




K20251111071501




No.Good Data




1043+158 2025/11/10 22.28UT FUJI -KISO





T20251111072717




BLK: 2, SNR1: 2.9769 , SNR2: 9.4291




F20251111072718




BLK: 2, SNR1: 4.0334 , SNR2: 9.8485




1055+01 2025/11/10 22.48UT TOYOKAWA-FUJI





T20251111072717




BLK: 3, SNR1: 0.30781 , SNR2: 5.4621




K20251111072716




BLK: 3, SNR1: 13.839 , SNR2: 25.320




1055+01 2025/11/10 22.48UT TOYOKAWA-KISO





F20251111072718




BLK: 5, SNR1: 4.6161 ,SNR2: 11.521




K20251111072716




BLK: 5, SNR1: 12.180 ,SNR2: 21.039





1055+01 2025/11/10 22.48UT FUJII -KISO







BLK: 7, SNR1: 7.0702 , SNR2: 12.637



BLK: 7, SNR1: 6.6093 , SNR2: 15.191





1107+109 2025/11/10 22.67UT TOYOKAWA-FUJI








T20251111073834




BLK:16,SNR1: 5.3413 ,SNR2: 9.5525




K20251111073833




BLK:16,SNR1: 2.1614 ,SNR2: 7.0718





1107+109 2025/11/10 22.67UT TOYOKAWA-KISO







BLK:12,SNR1: 6.3743 ,SNR2: 14.640







BLK:12,SNR1: 2.1720 ,SNR2: 7.1000








1107+109 2025/11/10 22.67UT FUJI -KISO






3C255 2025/11/10 22.83UT TOYOKAWA-FUJI







3C255 2025/11/10 22.83UT TOYOKAWA-KISO




F20251111074812




BLK: 5, SNR1: 8.9928 , SNR2: 27.553




K20251111074810





BLK: 5, SNR1: 14.472 , SNR2: 43.024




3C255 2025/11/10 22.83UT FUJI -KISO





T20251111075849




BLK: 6, SNR1: 12.335 ,SNR2: 30.340




F20251111075849




BLK: 6, SNR1: 10.136 ,SNR2: 24.471




1127-14 2025/11/10 23.01UT TOYOKAWA-FUJI



T20251111075849





BLK: 9, SNR1: 11.129 , SNR2: 23.950





1127-14 2025/11/10 23.01UT TOYOKAWA-KISO



K20251111075848




BLK: 9, SNR1: 10.376 , SNR2: 24.715



F20251111075849





BLK: 7, SNR1: 7.7156 , SNR2: 19.533





1127-14 2025/11/10 23.01UT FUJI -KISO

K20251111075848




BLK: 7, SNR1: 9.6731 , SNR2: 23.791








T20251111081209




BLK: 6, SNR1: 6.5931 , SNR2: 20.694




F20251111081210




BLK: 6, SNR1: 11.954 , SNR2: 21.259




3C263.1 2025/11/10 23.23UT TOYOKAWA-FUJI





T20251111081209




BLK: 9, SNR1: 28.076 , SNR2: 49.162




K20251111081208





BLK: 9, SNR1: 8.5308 , SNR2: 21.138








3C263.1 2025/11/10 23.23UT TOYOKAWA-KISO










3C263.1 2025/11/10 23.23UT FUJI -KISO






3C267 2025/11/10 23.34UT TOYOKAWA-FUJI







3C267 2025/11/10 23.34UT TOYOKAWA-KISO




F20251111081836




BLK: 2, SNR1: 7.4889 , SNR2: 20.789




K20251111081835





BLK: 2, SNR1: 6.6309 , SNR2: 19.176




3C267 2025/11/10 23.34UT FUJI -KISO





T20251111084424




BLK:13,SNR1: 1.9780 ,SNR2: 8.5533




F20251111084425





BLK:13,SNR1: 14.454 ,SNR2: 34.740




1213-17 2025/11/10 23.77UT TOYOKAWA-FUJI





T20251111084424




BLK: 9, SNR1: 7.3872 , SNR2: 19.915




K20251111084423



BLK: 9, SNR1: 11.862 , SNR2: 29.114





1213-17 2025/11/10 23.77UT TOYOKAWA-KISO








F20251111084425




BLK: 8,SNR1: 50.440 ,SNR2: 47.866




K20251111084423







BLK: 8,SNR1: 1.1972 ,SNR2: 4.2235








1213-17 2025/11/10 23.77UT FUJI -KISO






1222+216 2025/11/10 23.92UT TOYOKAWA-FUJI







1222+216 2025/11/10 23.92UT TOYOKAWA-KISO




F20251111085329




BLK:13,SNR1: 8.1243 ,SNR2: 21.002




K20251111085328





BLK:13,SNR1: 8.8712 ,SNR2: 23.148




1222+216 2025/11/10 23.92UT FUJI -KISO



T20251111091052





BLK: 5, SNR1: 2.5346 , SNR2: 9.7968





3C275 2025/11/11 0.21UT TOYOKAWA-FUJI



F20251111091053




BLK: 5, SNR1: 5.4359 , SNR2: 13.048




T20251111091052




BLK: 9, SNR1: 3.9368 ,SNR2: 25.894




K20251111091051





BLK: 9, SNR1: 6.4623 ,SNR2: 16.056




3C275 2025/11/11 0.21UT TOYOKAWA-KISO




F20251111091053




BLK: 4, SNR1: 2.7271 , SNR2: 8.6367




K20251111091051




BLK: 4, SNR1: 9.0253 , SNR2: 16.036




3C275 2025/11/11 0.21UT FUJI -KISO





T20251111091657




BLK:18,SNR1: 0.83250 ,SNR2: 2.3913




F20251111091658



BLK:18,SNR1: 9.4682 ,SNR2: 12.250





1245-19 2025/11/11 0.31UT TOYOKAWA-FUJI






T20251111091657





BLK:22,SNR1: 1.2028 ,SNR2: 8.2013





1245-19 2025/11/11 0.31UT TOYOKAWA-KISO


K20251111091656




BLK:22,SNR1: 10.614 ,SNR2: 23.703




F20251111091658




BLK:16,SNR1: 6.9690 ,SNR2: 17.969




K20251111091656







BLK:16,SNR1: 9.5965 ,SNR2: 21.453




1245-19 2025/11/11 0.31UT FUJI -KISO







3C279 2025/11/11 0.44UT TOYOKAWA-FUJI




T20251111092441




BLK:23,SNR1: 1.8546 ,SNR2: 3.3217




K20251111092440




BLK:23,SNR1: 9.3883 ,SNR2: 16.182





3C279 2025/11/11 0.44UT TOYOKAWA-KISO







BLK:12,SNR1:-0.48128E-01,SNR2: 1.7081




BLK:12,SNR1: 3.7067 ,SNR2: 8.7226




3C279 2025/11/11 0.44UT FUJI -KISO





T20251111094011




BLK:18,SNR1: 2.3837 ,SNR2: 3.7909




F20251111094012




BLK:18,SNR1: 12.771 ,SNR2: 29.833




3C283 2025/11/11 0.70UT TOYOKAWA-FUJI





T20251111094011




BLK:25,SNR1: 1.9350 ,SNR2: 2.5914




K20251111094010





BLK:25,SNR1: 14.231 ,SNR2: 27.658




3C283 2025/11/11 0.70UT TOYOKAWA-KISO





F20251111094012




BLK:19,SNR1: 12.600 ,SNR2: 29.440




K20251111094010







BLK:19,SNR1: 9.2060 ,SNR2: 25.172




3C283 2025/11/11 0.70UT FUJI -KISO









1323+32 2025/11/11 0.94UT TOYOKAWA-FUJI





T20251111095434




BLK: 7,SNR1: 0.94921E-01,SNR2: 1.6850




K20251111095433




BLK: 7,SNR1: 2.7935 ,SNR2: 8.0630





1323+32 2025/11/11 0.94UT TOYOKAWA-KISO







BLK: 8, SNR1: 1.6857 , SNR2: 4.9539




BLK: 8, SNR1: 1.8777 , SNR2: 9.5974




1323+32 2025/11/11 0.94UT FUJI -KISO





T20251111095925




BLK:11,SNR1: 0.74373 ,SNR2: 4.0583




F20251111095925













BLK:11,SNR1: 7.1450 ,SNR2: 13.428





3C286 2025/11/11 1.02UT TOYOKAWA-FUJI










T20251111101552




BLK:12,SNR1: 0.69842 ,SNR2: 5.2035




F20251111101552





BLK:12,SNR1: 0.11002 ,SNR2: 1.4550




1345+12 2025/11/11 1.29UT TOYOKAWA-FUJI





T20251111101552




BLK:10,SNR1: 0.60270 ,SNR2: 1.8870




K20251111101551







BLK:10,SNR1: 2.1979 ,SNR2: 5.6752




1345+12 2025/11/11 1.29UT TOYOKAWA-KISO










1345+12 2025/11/11 1.29UT FUJI -KISO





T20251111102613




BLK:13,SNR1: 0.93620 ,SNR2: 3.4280




F20251111102614




BLK:13,SNR1:-0.13139 ,SNR2: 2.6925




1355+01 2025/11/11 1.47UT TOYOKAWA-FUJI





T20251111102613




BLK:15,SNR1: 0.88886 ,SNR2: 4.0747




K20251111102612




BLK:15,SNR1: 0.66083E-02,SNR2: 1.8195




1355+01 2025/11/11 1.47UT TOYOKAWA-KISO



F20251111102614




BLK:11,SNR1:-0.11686 ,SNR2: 2.8581





1355+01 2025/11/11 1.47UT FUJI -KISO


K20251111102612




BLK:11,SNR1: 0.23749 ,SNR2: 1.7745





T202511111104723




BLK:11,SNR1: 2.6693 ,SNR2: 13.791




F202511111104724




BLK:11,SNR1: 0.78886E-01,SNR2: 1.9332




3C298 2025/11/11 1.82UT TOYOKAWA-FUJI



T202511111104723




BLK:23,SNR1: 2.0921 ,SNR2: 17.265










3C298 2025/11/11 1.82UT TOYOKAWA-KISO

K202511111104722




BLK:23,SNR1: 2.2788 ,SNR2: 4.3070







T20251111105907




BLK:10,SNR1: 0.36266 ,SNR2: 3.8647




F20251111105908



BLK:10,SNR1: 0.37275E-01,SNR2: 5.3192




1428-03 2025/11/11 2.01UT TOYOKAWA-FUJI







T20251111105907




BLK:10,SNR1: 0.33171 ,SNR2: 3.5100




K20251111105906




BLK:10,SNR1: 0.61873 ,SNR2: 1.2758




1428-03 2025/11/11 2.01UT TOYOKAWA-KISO



F20251111105908




BLK: 5, SNR1: -0.67558E-01, SNR2: 2.4573






1428-03 2025/11/11 2.01UT FUJI -KISO

K20251111105906





BLK: 5, SNR1: 0.80370, SNR2: 2.4706







BLK:11,SNR1: 0.83532 ,SNR2: 3.2264




BLK:11,SNR1: 0.13752 ,SNR2: 3.7964





1434+03 2025/11/11 2.11UT TOYOKAWA-FUJI







BLK:17,SNR1: 0.84055 ,SNR2: 3.5943




BLK:17,SNR1: 69.343 ,SNR2: 114.45




1434+03 2025/11/11 2.11UT TOYOKAWA-KISO



F20251111110510





BLK:10,SNR1: 0.28025 ,SNR2: 5.0007









1434+03 2025/11/11 2.11UT FUJI -KISO

K20251111110508








BLK:10,SNR1: 195.10 ,SNR2: 215.23






1453-10 2025/11/11 2.43UT TOYOKAWA-FUJI








1453-10 2025/11/11 2.43UT TOYOKAWA-KISO





F20251111112412




BLK:13,SNR1: 4.0984 ,SNR2: 9.8958




K20251111112411



BLK:13,SNR1: 33.595 ,SNR2: 58.483




1453-10 2025/11/11 2.43UT FUJI -KISO







T20251111113904




BLK:21,SNR1: 35.917 ,SNR2: 61.275




F20251111113905




BLK:21,SNR1:-0.26879 ,SNR2: 1.8424




1508-05 2025/11/11 2.68UT TOYOKAWA-FUJI




T20251111113904




BLK:23,SNR1: 37.541 ,SNR2: 53.293




K20251111113903




BLK:23,SNR1: 1.7469 ,SNR2: 4.4584




1508-05 2025/11/11 2.68UT TOYOKAWA-KISO




F20251111113905




BLK:10,SNR1: 0.13515 ,SNR2: 3.4407




K20251111113903









BLK:10,SNR1: 1.3075 ,SNR2: 2.9686





1508-05 2025/11/11 2.68UT FUJI -KISO









BLK: 4, SNR1: 2.5013 , SNR2: 5.1884




BLK: 4, SNR1: 8.9989 , SNR2: 21.755





3C318 2025/11/11 2.83UT TOYOKAWA-KISO







BLK: 3,SNR1: 10.559 ,SNR2: 18.920









BLK: 3,SNR1: 18.672 ,SNR2: 33.803






3C318 2025/11/11 2.83UT FUJI -KISO


















BLK:16,SNR1: 1.9823 ,SNR2: 3.8268









BLK:16,SNR1: 1.8552 ,SNR2: 5.0364




1535+139 2025/11/11 3.12UT TOYOKAWA-FUJI













BLK:16,SNR1: 2.8610 ,SNR2: 8.9067









BLK:16,SNR1:-0.20851 ,SNR2: 0.92859




1545-12 2025/11/11 3.29UT TOYOKAWA-FUJI













BLK: 1,SNR1: 0.89297 ,SNR2: 9.0187




BLK: 1,SNR1: 2.9650 ,SNR2: 13.813





1607+26 2025/11/11 3.64UT TOYOKAWA-FUJI









BLK: 2,SNR1: 0.19675 ,SNR2: 1.9277




BLK: 2,SNR1: 0.83598 ,SNR2: 3.6110





1607+26 2025/11/11 3.64UT TOYOKAWA-KISO







BLK: 2,SNR1: 10.734 ,SNR2: 26.722





BLK: 2,SNR1: 12.361 ,SNR2: 21.683




1607+26 2025/11/11 3.64UT FUJI -KISO





T20251111125201




BLK: 9,SNR1: 0.99517 ,SNR2: 1.9978




F20251111125202





BLK: 9,SNR1: 18.699 ,SNR2: 41.691




1621-11 2025/11/11 3.90UT TOYOKAWA-FUJI





T20251111125201




BLK: 3, SNR1: 0.25354 , SNR2: 1.8948




K20251111125200




BLK: 3, SNR1: 1.9333 , SNR2: 5.2702




1621-11 2025/11/11 3.90UT TOYOKAWA-KISO




F20251111125202




BLK: 7,SNR1: 153.71 ,SNR2: 150.77




K20251111125200





BLK: 7,SNR1: 1.2944 ,SNR2: 4.2466




1621-11 2025/11/11 3.90UT FUJI -KISO




T20251111130258




BLK: 2,SNR1: 18.623 ,SNR2: 32.998




F20251111130258





BLK: 2,SNR1: 11.625 ,SNR2: 28.915




1631-222 2025/11/11 4.08UT TOYOKAWA-FUJI





T20251111130258




BLK: 6,SNR1: 100.86 ,SNR2: 99.408




K20251111130257





BLK: 6,SNR1: 12.148 ,SNR2: 29.780




1631-222 2025/11/11 4.08UT TOYOKAWA-KISO





F20251111130258




BLK: 2,SNR1: 11.578 ,SNR2: 28.471




K20251111130257




BLK: 2,SNR1: 10.978 ,SNR2: 26.961





1631-222 2025/11/11 4.08UT FUJI -KISO









BLK: 4,SNR1: 10.146 ,SNR2: 18.917




BLK: 4,SNR1: 7.7964 ,SNR2: 19.277





1638-025 2025/11/11 4.17UT TOYOKAWA-FUJI







BLK: 2,SNR1: 10.881 ,SNR2: 25.819




BLK: 2,SNR1: 10.265 ,SNR2: 24.420





1638-025 2025/11/11 4.17UT TOYOKAWA-KISO







BLK: 4,SNR1: 10.706 ,SNR2: 19.824




BLK: 4,SNR1: 11.505 ,SNR2: 21.220






1638-025 2025/11/11 4.17UT FUJI -KISO




T20251111131530





F20251111131531




1644-106 2025/11/11 4.29UT TOYOKAWA-FUJI





T20251111131530




BLK:23,SNR1: 7.5061 ,SNR2: 16.958




K20251111131529




BLK:23,SNR1: 33.556 ,SNR2: 35.496




1644-106 2025/11/11 4.29UT TOYOKAWA-KISO





F20251111131531




BLK:10,SNR1: 10.397 ,SNR2: 16.378




K20251111131529





BLK:10,SNR1: 51.389 ,SNR2: 70.050




1644-106 2025/11/11 4.29UT FUJI -KISO





T20251111132050




BLK: 5,SNR1: 1.5920 ,SNR2: 3.7691




F20251111132051





BLK: 5,SNR1: 0.24699 ,SNR2: 1.3814




1650+004 2025/11/11 4.38UT TOYOKAWA-FUJI




T20251111132050




BLK:11,SNR1: 13.254 ,SNR2: 21.599




K20251111132049



BLK:11,SNR1: 4.0644 ,SNR2: 8.9686




1650+004 2025/11/11 4.38UT TOYOKAWA-KISO







F20251111132051




BLK: 7,SNR1:-0.74433E-01,SNR2: 1.6578




K20251111132049





BLK: 7,SNR1: 3.1099 ,SNR2: 6.4418




1650+004 2025/11/11 4.38UT FUJI -KISO





T20251111132622




BLK: 1,SNR1: 2.4066 ,SNR2: 6.9699




F20251111132622




BLK: 1,SNR1: 8.2309 ,SNR2: 20.437




1656+053 2025/11/11 4.47UT TOYOKAWA-FUJI





T20251111132622




BLK: 5,SNR1: 5.7226 ,SNR2: 14.493




K20251111132621





BLK: 5,SNR1: 5.6950 ,SNR2: 14.308




1656+053 2025/11/11 4.47UT TOYOKAWA-KISO





F20251111132622




BLK: 2,SNR1: 10.141 ,SNR2: 25.006




K20251111132621





BLK: 2,SNR1: 6.7316 ,SNR2: 16.692




1656+053 2025/11/11 4.47UT FUJI -KISO





T20251111134252




BLK: 6,SNR1: 3.9111 ,SNR2: 11.535




F20251111134252




BLK: 6,SNR1: 4.9427 ,SNR2: 11.011





1712-033 2025/11/11 4.74UT TOYOKAWA-FUJI







BLK: 9,SNR1: 3.7788 ,SNR2: 11.274





BLK: 9,SNR1: 3.1333 ,SNR2: 9.5072




1712-033 2025/11/11 4.74UT TOYOKAWA-KISO




F20251111134252




BLK: 9,SNR1: 4.7131 ,SNR2: 10.479




K20251111134251





BLK: 9,SNR1: 10.491 ,SNR2: 18.473




1712-033 2025/11/11 4.74UT FUJI -KISO




T20251111140054




BLK: 5, SNR1: 0.18597 , SNR2: 2.0249




F20251111140055



BLK: 5, SNR1: 0.47595 , SNR2: 4.8075





1730-13 2025/11/11 5.04UT TOYOKAWA-FUJI








T20251111140054




BLK:12,SNR1: 1.1832 ,SNR2: 3.5456




K20251111140053




BLK:12,SNR1: 5.8839 ,SNR2: 17.396





1730-13 2025/11/11 5.04UT TOYOKAWA-KISO









BLK:19,SNR1: 0.49494E-01,SNR2: 2.2737




BLK:19,SNR1: 4.8679 ,SNR2: 14.836





T20251111141819




BLK: 9,SNR1: 0.95047 ,SNR2: 5.6381




F20251111141820




BLK: 9,SNR1: 16.995 ,SNR2: 30.132





1748+031 2025/11/11 5.33UT TOYOKAWA-FUJI







BLK: 6,SNR1: 0.95265 ,SNR2: 5.7204




BLK: 6,SNR1: 6.8469 ,SNR2: 20.116





1748+031 2025/11/11 5.33UT TOYOKAWA-KISO







BLK: 6,SNR1: 11.704 ,SNR2: 24.587




BLK: 6,SNR1: 3.8968 ,SNR2: 10.572





1748+031 2025/11/11 5.33UT FUJI -KISO







BLK: 7,SNR1: 4.4386 ,SNR2: 16.794




BLK: 7,SNR1: 7.9003 ,SNR2: 14.429





1759+13 2025/11/11 5.51UT TOYOKAWA-FUJI







BLK: 4,SNR1: 7.2641 ,SNR2: 25.655




BLK: 4,SNR1: 14.387 ,SNR2: 25.578





1759+13 2025/11/11 5.51UT TOYOKAWA-KISO








BLK: 5,SNR1: 20.360 ,SNR2: 36.020





BLK: 5,SNR1: 21.712 ,SNR2: 45.613









BLK: 9,SNR1: 9.3995 ,SNR2: 17.018




BLK: 9,SNR1: 8.8358 ,SNR2: 18.760





1819-096 2025/11/11 5.86UT TOYOKAWA-FUJI







BLK: 3,SNR1: 10.458 ,SNR2: 17.013




BLK: 3,SNR1: 10.547 ,SNR2: 22.400





1819-096 2025/11/11 5.86UT TOYOKAWA-KISO







BLK: 5,SNR1: 10.638 ,SNR2: 17.340




BLK: 5,SNR1: 10.160 ,SNR2: 16.748





1819-096 2025/11/11 5.86UT FUJI -KISO







BLK: 4,SNR1: 12.269 ,SNR2: 21.144




BLK: 4,SNR1: 9.9379 ,SNR2: 17.656





1830-210 2025/11/11 6.05UT TOYOKAWA-FUJI







BLK: 6,SNR1: 4.7449 ,SNR2: 10.825




BLK: 6,SNR1: 12.064 ,SNR2: 22.014





1830-210 2025/11/11 6.05UT TOYOKAWA-KISO









BLK: 4,SNR1: 0.86436 ,SNR2: 4.4353




BLK: 4,SNR1: 20.329 ,SNR2: 27.204





T20251111152751




BLK: 2,SNR1: 0.40156 ,SNR2: 3.1757




F20251111152751




BLK: 2,SNR1: 4.9589 ,SNR2: 20.380





1858+171 2025/11/11 6.49UT TOYOKAWA-FUJI







BLK: 1,SNR1: 0.15409E-01,SNR2: 1.9092




BLK: 1,SNR1: 1.0065 ,SNR2: 4.8174





1858+171 2025/11/11 6.49UT TOYOKAWA-KISO









BLK: 2,SNR1: 14.788 ,SNR2: 27.025





BLK: 2,SNR1: 4.0990 ,SNR2: 13.811




1858+171 2025/11/11 6.49UT FUJI -KISO



T20251111153837





BLK:17,SNR1: 3.6859 ,SNR2: 10.951




Frequency (Hz)

F20251111153838




BLK:17,SNR1: 5.7894 ,SNR2: 16.858





Frequency (Hz)


1908-20 2025/11/11 6.67UT TOYOKAWA-FUJI




T20251111153837




BLK:10,SNR1: 3.8453 ,SNR2: 11.359




K20251111153836





BLK:10,SNR1: 20.007 ,SNR2: 26.713




1908-20 2025/11/11 6.67UT TOYOKAWA-KISO



F20251111153838





BLK:11,SNR1: 14.658 ,SNR2: 18.960




Frequency (Hz)

K20251111153836





BLK:11,SNR1: 15.252 ,SNR2: 26.706





Frequency (Hz)

1908-20 2025/11/11 6.67UT FUJI -KISO







BLK: 4,SNR1: 3.8822 ,SNR2: 7.1611





BLK: 4,SNR1: 2.9888 ,SNR2: 18.521




1915-121 2025/11/11 6.79UT TOYOKAWA-FUJI



T20251111154527





BLK: 9, SNR1: 9.0538 , SNR2: 14.880




Frequency (Hz)

K20251111154526





BLK: 9, SNR1: 10.127 , SNR2: 18.284





Frequency (Hz)

1915-121 2025/11/11 6.79UT TOYOKAWA-KISO







BLK: 5,SNR1: 7.5615 ,SNR2: 18.151








BLK: 5,SNR1: 6.9939 ,SNR2: 14.988




1915-121 2025/11/11 6.79UT FUJI -KISO













BLK:12,SNR1: 8.3537 ,SNR2: 14.839





BLK:12,SNR1: 26.169 ,SNR2: 50.911




1928-142 2025/11/11 7.01UT TOYOKAWA-KISO



F20251111155910





BLK: 8,SNR1: 45.165 ,SNR2: 84.998




Frequency (Hz)

K20251111155908





BLK: 8,SNR1: 27.122 ,SNR2: 52.767





Frequency (Hz)

1928-142 2025/11/11 7.01UT FUJI -KISO







BLK:12,SNR1: 3.5849 ,SNR2: 10.691




BLK:12,SNR1: 4.8273 ,SNR2: 8.8497





1938-15 2025/11/11 7.17UT TOYOKAWA-FUJI







BLK:11,SNR1: 2.1561 ,SNR2: 6.7231





BLK:11,SNR1: 8.6949 ,SNR2: 15.392




1938-15 2025/11/11 7.17UT TOYOKAWA-KISO



F20251111160848





BLK: 9, SNR1: 2.5267 , SNR2: 7.8575




Frequency (Hz)

K20251111160847





BLK: 9, SNR1: 8.4118 , SNR2: 14.920





Frequency (Hz)

1938-15 2025/11/11 7.17UT FUJI -KISO







BLK: 5,SNR1: 12.406 ,SNR2: 29.464




BLK: 5,SNR1: 9.1185 ,SNR2: 23.055





2053-201 2025/11/11 8.42UT TOYOKAWA-FUJI






BLK: 6,SNR1: 8.1246 ,SNR2: 20.719



BLK: 6,SNR1: 7.1348 ,SNR2: 21.338



2053-201 2025/11/11 8.42UT TOYOKAWA-KISO

