








BLK: 1, SNR1: 1.3638 , SNR2: 3.9345








BLK: 1, SNR1: 0.40889 , SNR2: 2.0041





0928-179 2025/11/15 20.70UT TOYOKAWA-FUJI










F20251116054006




BLK: 5, SNR1: 10.050 ,SNR2: 25.607




K20251116054005





BLK: 5, SNR1: 15.701 ,SNR2: 38.195




0928-179 2025/11/15 20.70UT FUJI -KISO




T20251116055257




BLK: 6,SNR1: 11.451 ,SNR2: 28.908




F20251116055257





BLK: 6,SNR1: 9.9518 ,SNR2: 25.426




0941-08 2025/11/15 20.91UT TOYOKAWA-FUJI




T20251116055257




BLK: 3, SNR1: 13.897 , SNR2: 33.423




K20251116055256




BLK: 3, SNR1: 7.7271 , SNR2: 23.401




0941-08 2025/11/15 20.91UT TOYOKAWA-KISO




F20251116055257




BLK: 5, SNR1: 10.520 ,SNR2: 26.414




K20251116055256





BLK: 5, SNR1: 7.5614 ,SNR2: 22.935




0941-08 2025/11/15 20.91UT FUJI -KISO





T20251116060119




BLK: 7, SNR1: 11.422 , SNR2: 28.361




F20251116060119





BLK: 7, SNR1: 9.5509 , SNR2: 24.641




3C230 2025/11/15 21.05UT TOYOKAWA-FUJI





T20251116060119




BLK: 5, SNR1: 10.267 , SNR2: 24.301




K20251116060118





BLK: 5, SNR1: 8.8400 , SNR2: 22.745




3C230 2025/11/15 21.05UT TOYOKAWA-KISO





F20251116060119




BLK: 5, SNR1: 9.4925 ,SNR2: 24.211




K20251116060118





BLK: 5, SNR1: 10.734 ,SNR2: 27.000




3C230 2025/11/15 21.05UT FUJI -KISO





T20251116061042




BLK: 2,SNR1: 5.2654 ,SNR2: 15.240




F20251116061043



BLK: 2,SNR1:-0.56946E-02,SNR2: 1.0549





0958-001 2025/11/15 21.21UT TOYOKAWA-FUJI








T20251116061042




BLK: 4, SNR1: 5.2601 , SNR2: 15.250




K20251116061041





BLK: 4, SNR1: 8.8990 , SNR2: 15.799




0958-001 2025/11/15 21.21UT TOYOKAWA-KISO





F20251116061043




BLK: 2, SNR1: 0.28923 , SNR2: 1.6321




K20251116061041





BLK: 2, SNR1: 6.2867 , SNR2: 15.965




0958-001 2025/11/15 21.21UT FUJI -KISO



T20251116061720





No.Good Data




Frequency (Hz)

F20251116061720




No.Good Data





Frequency (Hz)


3C237 2025/11/15 21.32UT TOYOKAWA-FUJI



T20251116061720





BLK: 1, SNR1: 7.4764 , SNR2: 20.244




Frequency (Hz)

K20251116061719




BLK: 1, SNR1: 16.741 , SNR2: 50.303





Frequency (Hz)


3C237 2025/11/15 21.32UT TOYOKAWA-KISO




F20251116061720




BLK: 2, SNR1: 5.8214 , SNR2: 14.857




K20251116061719





BLK: 2, SNR1: 8.8291 , SNR2: 21.887




3C237 2025/11/15 21.32UT FUJI -KISO



T20251116062336





BLK: 6, SNR1: 9.1242 , SNR2: 27.644




Frequency (Hz)

F20251116062337




BLK: 6, SNR1: 5.9927 , SNR2: 17.131





Frequency (Hz)


1011+110 2025/11/15 21.42UT TOYOKAWA-FUJI



T20251116062336





BLK:12,SNR1: 9.0918 ,SNR2: 27.547




Frequency (Hz)

K20251116062335




BLK:12,SNR1: 10.258 ,SNR2: 25.854





Frequency (Hz)


1011+110 2025/11/15 21.42UT TOYOKAWA-KISO





F20251116062337




BLK: 8,SNR1: 6.5934 ,SNR2: 17.557




K20251116062335







BLK: 8,SNR1: 6.2483 ,SNR2: 16.999




1011+110 2025/11/15 21.42UT FUJI -KISO













1031-11 2025/11/15 21.74UT TOYOKAWA-FUJI








F20251116064246




BLK: 3,SNR1:-0.24599 ,SNR2: 0.0000




K20251116064245







BLK: 3,SNR1: 4.3956 ,SNR2: 9.8091








1031-11 2025/11/15 21.74UT FUJI -KISO






1035-058 2025/11/15 21.82UT TOYOKAWA-FUJI







1035-058 2025/11/15 21.82UT TOYOKAWA-KISO




F20251116064721




BLK:13,SNR1: 3.6608 ,SNR2: 9.6391




K20251116064719





BLK:13,SNR1: 8.8232 ,SNR2: 18.682




1035-058 2025/11/15 21.82UT FUJI -KISO




T20251116065522




BLK: 3, SNR1: 0.72276 , SNR2: 2.3752




F20251116065522





BLK: 3, SNR1: 0.43149 , SNR2: 1.3885




1043+158 2025/11/15 21.95UT TOYOKAWA-FUJI





T20251116065522




BLK: 2, SNR1: 0.46024 , SNR2: 1.7989




K20251116065521



BLK: 2, SNR1: 2.4097 , SNR2: 7.8362




1043+158 2025/11/15 21.95UT TOYOKAWA-KISO








F20251116065522




BLK: 2,SNR1: 0.18075 ,SNR2: 1.1933




K20251116065521




BLK: 2,SNR1: 1.4598 ,SNR2: 4.0444





1043+158 2025/11/15 21.95UT FUJI -KISO








BLK:19,SNR1: 3.0853 ,SNR2: 9.4346




BLK:19,SNR1: 3.4466 ,SNR2: 10.313








BLK:26,SNR1: 3.0846 ,SNR2: 9.4327





1055+01 2025/11/15 22.18UT TOYOKAWA-KISO




BLK:26,SNR1: 3.0273 ,SNR2: 9.1723



F20251116070738





BLK:28,SNR1: 3.4317 ,SNR2: 10.269




Frequency (Hz)

K20251116070736




BLK:28,SNR1: 3.0221 ,SNR2: 9.1596





Frequency (Hz)


1055+01 2025/11/15 22.16UT FUJI -KISO





T20251116071855




BLK: 9,SNR1: 0.84581E-02,SNR2: 1.0205




F20251116071856




BLK: 9,SNR1: 0.99265 ,SNR2: 2.6527





1107+109 2025/11/15 22.34UT TOYOKAWA-FUJI







BLK: 7, SNR1: 0.88231 , SNR2: 2.3570




BLK: 7, SNR1: 1.0141 , SNR2: 2.8230





1107+109 2025/11/15 22.34UT TOYOKAWA-KISO







BLK: 7, SNR1: 0.38740 , SNR2: 1.8299






BLK: 7, SNR1: 0.48480 , SNR2: 1.9157




1107+109 2025/11/15 22.34UT FUJI -KISO
















BLK: 7, SNR1: 0.24834 , SNR2: 2.0023




BLK: 7, SNR1: 0.22734 , SNR2: 1.0690








T20251116073910




BLK:11,SNR1: 0.50259 ,SNR2: 2.6929




F20251116073911









BLK:11,SNR1:-0.29846 ,SNR2: 0.34070







1127-14 2025/11/15 22.68UT TOYOKAWA-FUJI





















3C263.1 2025/11/15 22.90UT TOYOKAWA-FUJI

























T20251116082445




BLK: 5, SNR1: 0.28447 , SNR2: 1.1067




F20251116082445





BLK: 5, SNR1: -0.27677 , SNR2: 0.59563




1213-17 2025/11/15 23.44UT TOYOKAWA-FUJI





T20251116082445




BLK: 6, SNR1: 0.29632 , SNR2: 1.0654




K20251116082444




BLK: 6, SNR1: 0.71880 , SNR2: 2.3972




1213-17 2025/11/15 23.44UT TOYOKAWA-KISO





F20251116082445




BLK: 8,SNR1:-0.18914 ,SNR2: 0.85915




K20251116082444













BLK: 8,SNR1: 4.1283 ,SNR2: 7.4402







1213-17 2025/11/15 23.44UT FUJI -KISO















3C273 2025/11/15 23.66UT FUJI -KISO




T20251116085113




BLK: 9,SNR1: 0.17231 ,SNR2: 1.8744




F20251116085114





BLK: 9,SNR1:-0.21278E-01,SNR2: 1.5978




3C275 2025/11/15 23.88UT TOYOKAWA-FUJI




T20251116085113




BLK:10,SNR1: 0.40649 ,SNR2: 3.7659




K20251116085112




BLK:10,SNR1: 2.9700 ,SNR2: 7.9305




3C275 2025/11/15 23.88UT TOYOKAWA-KISO




F20251116085114




BLK: 4, SNR1: 0.38996 , SNR2: 1.4636




K20251116085112







BLK: 4, SNR1: 7.0572 , SNR2: 14.472









3C275 2025/11/15 23.88UT FUJI -KISO






3C279 2025/11/16 0.11UT TOYOKAWA-FUJI








F20251116090501




BLK: 4, SNR1: 2.2408 , SNR2: 9.5545




K20251116090500





BLK: 4, SNR1: 1.5461 , SNR2: 3.6832




3C279 2025/11/16 0.11UT FUJI -KISO





T20251116092031




BLK:20,SNR1: 0.36022 ,SNR2: 2.3294




F20251116092032



BLK:20,SNR1: 0.23797 ,SNR2: 2.9356





3C283 2025/11/16 0.37UT TOYOKAWA-FUJI








T20251116092031




BLK:22,SNR1: 0.25106 ,SNR2: 1.2695




K20251116092030





BLK:22,SNR1: 5.8328 ,SNR2: 11.086




3C283 2025/11/16 0.37UT TOYOKAWA-KISO





F20251116092032




BLK:14,SNR1: 0.66555E-01,SNR2: 1.8508




K20251116092030





BLK:14,SNR1: 6.8772 ,SNR2: 20.527




3C283 2025/11/16 0.37UT FUJI -KISO





T20251116093455




BLK:10,SNR1: 0.13814 ,SNR2: 0.64810




F20251116093456




BLK:10,SNR1: 1.5528 ,SNR2: 3.0705




1323+32 2025/11/16 0.61UT TOYOKAWA-FUJI





T20251116093455




BLK: 8, SNR1: 0.18069 , SNR2: 1.2736




K20251116093454







BLK: 8, SNR1: 0.20734 , SNR2: 1.5341








1323+32 2025/11/16 0.61UT TOYOKAWA-KISO










1323+32 2025/11/16 0.61UT FUJI -KISO








3C286 2025/11/16 0.69UT TOYOKAWA-FUJI






3C286 2025/11/16 0.69UT TOYOKAWA-KISO







3C286 2025/11/16 0.69UT FUJI -KISO








T20251116095613




BLK:10,SNR1: 0.74589 ,SNR2: 2.4621




F20251116095614




BLK:10,SNR1: 0.11055 ,SNR2: 1.4802




1345+12 2025/11/16 0.97UT TOYOKAWA-FUJI





T20251116095613




BLK:15,SNR1: 0.42762 ,SNR2: 1.8231




K20251116095612




BLK:15,SNR1: 0.13697E-01,SNR2: 0.73075




1345+12 2025/11/16 0.97UT TOYOKAWA-KISO




F20251116095614




BLK: 7,SNR1: 0.32530E-01,SNR2: 0.92497




K20251116095612




BLK: 7,SNR1: 0.71496E-01,SNR2: 0.61352




1345+12 2025/11/16 0.97UT FUJI -KISO





T20251116100633




BLK:11,SNR1: 0.24359 ,SNR2: 2.1766




F20251116100633




BLK:11,SNR1: -0.30504E-01,SNR2: 4.2706




1355+01 2025/11/16 1.14UT TOYOKAWA-FUJI




T20251116100633




BLK:13,SNR1: 0.17289 ,SNR2: 3.0306




K20251116100632





BLK:13,SNR1: 1.0469 ,SNR2: 3.4754




1355+01 2025/11/16 1.14UT TOYOKAWA-KISO





F20251116100633




BLK:11,SNR1: 0.85267 ,SNR2: 7.9138




K20251116100632







BLK:11,SNR1: 1.1030 ,SNR2: 3.1330









1355+01 2025/11/16 1.14UT FUJI -KISO







3C298 2025/11/16 1.49UT TOYOKAWA-FUJI













3C298 2025/11/16 1.49UT FUJI -KISO





T20251116103927




BLK: 5,SNR1: 0.25571 ,SNR2: 2.9903




F20251116103928





BLK: 5,SNR1:-0.11756 ,SNR2: 1.2535




1428-03 2025/11/16 1.69UT TOYOKAWA-FUJI





T20251116103927




BLK: 9,SNR1: 0.33559 ,SNR2: 2.6714




K20251116103926




BLK: 9,SNR1: 0.13460 ,SNR2: 0.75942




1428-03 2025/11/16 1.69UT TOYOKAWA-KISO





F20251116103928




BLK: 4, SNR1: -0.23450 , SNR2: 1.6861




K20251116103926




BLK: 4, SNR1: 0.14253 , SNR2: 0.42608





1428-03 2025/11/16 1.69UT FUJI -KISO







BLK: 3, SNR1: 0.41089 , SNR2: 1.7574




BLK: 3, SNR1: -0.29703 , SNR2: 1.4102





1434+03 2025/11/16 1.79UT TOYOKAWA-FUJI







BLK: 8,SNR1: 0.53410 ,SNR2: 1.4109




BLK: 8,SNR1: 3.1781 ,SNR2: 8.0541




1434+03 2025/11/16 1.79UT TOYOKAWA-KISO



F20251116104530





BLK: 8,SNR1: 0.56890E-01,SNR2: 1.6443





1434+03 2025/11/16 1.79UT FUJI -KISO



K20251116104529




BLK: 8,SNR1: 3.8573 ,SNR2: 10.167



T20251116110432




BLK:10,SNR1: 6.7373 ,SNR2: 16.953





1453-10 2025/11/16 2.10UT TOYOKAWA-FUJI

F20251116110433




BLK:10,SNR1: 0.55270 ,SNR2: 7.7865







T20251116110432




BLK:12,SNR1: 0.59398 ,SNR2: 4.7016




K20251116110431




BLK:12,SNR1: 0.77015 ,SNR2: 1.4821




1453-10 2025/11/16 2.10UT TOYOKAWA-KISO




F20251116110433




BLK: 2,SNR1: 4.9952 ,SNR2: 20.301




K20251116110431





BLK: 2,SNR1: 0.12899 ,SNR2: 1.7926




1453-10 2025/11/16 2.10UT FUJI -KISO




T20251116111924




BLK: 4,SNR1: 0.64319E-01,SNR2: 1.7171




F20251116111924




BLK: 4,SNR1:-0.10608 ,SNR2: 1.2865




1508-05 2025/11/16 2.35UT TOYOKAWA-FUJI




T20251116111924




BLK: 9, SNR1: 0.33175 , SNR2: 2.2397




K20251116111923




BLK: 9, SNR1: 5.6311 , SNR2: 15.969




1508-05 2025/11/16 2.35UT TOYOKAWA-KISO





F20251116111924




BLK: 8,SNR1:-0.24970 ,SNR2: 1.5650




K20251116111923








BLK: 8,SNR1: 3.4071 ,SNR2: 9.8778





1508-05 2025/11/16 2.35UT FUJI -KISO







T20251116112824




BLK:12,SNR1: 7.8935 ,SNR2: 13.866




K20251116112823




BLK:12,SNR1: 8.3907 ,SNR2: 14.734




3C318 2025/11/16 2.50UT TOYOKAWA-KISO



F20251116112824




BLK: 8,SNR1: 8.2509 ,SNR2: 14.687





3C318 2025/11/16 2.50UT FUJI -KISO

K20251116112823





BLK: 8,SNR1: 8.8517 ,SNR2: 15.633







T20251116113411




BLK:11,SNR1: 0.74081 ,SNR2: 3.7129




F20251116113412





BLK:11,SNR1: 0.20993 ,SNR2: 3.5325




1523+03 2025/11/16 2.60UT TOYOKAWA-FUJI



T20251116113411





BLK:17,SNR1: 0.65117 ,SNR2: 2.0138




Frequency (Hz)

K20251116113410




BLK:17,SNR1: 2.9711 ,SNR2: 5.7710




Frequency (Hz)


1523+03 2025/11/16 2.60UT TOYOKAWA-KISO




F20251116113412




BLK: 4,SNR1: 0.90882 ,SNR2: 8.3870




K20251116113410









BLK: 4,SNR1: 3.5054 ,SNR2: 12.127





1523+03 2025/11/16 2.60UT FUJI -KISO


















1535+139 2025/11/16 2.79UT FUJI -KISO









BLK:16,SNR1: 3.3633 ,SNR2: 10.150



BLK:16,SNR1: 2.8318 ,SNR2: 8.5767




1545-12 2025/11/16 2.97UT TOYOKAWA-KISO






F20251116115615




BLK:13,SNR1: 0.13598 ,SNR2: 2.3863







1545-12 2025/11/16 2.97UT FUJI -KISO

K20251116115614




BLK:13,SNR1: 6.6919 ,SNR2: 11.695








1607+26 2025/11/16 3.32UT TOYOKAWA-FUJI




T20251116121717




BLK:14,SNR1: 0.72896 ,SNR2: 3.8897




K20251116121716







BLK:14,SNR1: 7.5864 ,SNR2: 11.902




1607+26 2025/11/16 3.32UT TOYOKAWA-KISO








1607+26 2025/11/16 3.32UT FUJI -KISO



T20251116123222





No.Good Data




Frequency (Hz)

F20251116123222




No.Good Data





Frequency (Hz)


1621-11 2025/11/16 3.57UT TOYOKAWA-FUJI





T20251116123222




BLK: 2,SNR1: 1.5615 ,SNR2: 4.5935




K20251116123221





BLK: 2,SNR1: 1.2049 ,SNR2: 2.4420




1621-11 2025/11/16 3.57UT TOYOKAWA-KISO





F20251116123222




BLK: 3,SNR1: 8.7948 ,SNR2: 21.697




K20251116123221





BLK: 3,SNR1: 8.1832 ,SNR2: 20.512




1621-11 2025/11/16 3.57UT FUJI -KISO





T20251116124319




BLK: 4,SNR1: 0.28818 ,SNR2: 2.2775




F20251116124319



BLK: 4,SNR1: 0.32889 ,SNR2: 2.7941





1631-222 2025/11/16 3.75UT TOYOKAWA-FUJI








T20251116124319




BLK: 1, SNR1: 0.16398 , SNR2: 1.0929




K20251116124318





BLK: 1, SNR1: 0.94319 , SNR2: 3.9706




1631-222 2025/11/16 3.75UT TOYOKAWA-KISO





F20251116124319




BLK: 4,SNR1: 1.6073 ,SNR2: 4.2041




K20251116124318




BLK: 4,SNR1: 7.3466 ,SNR2: 13.529





1631-222 2025/11/16 3.75UT FUJI -KISO







BLK: 2,SNR1: 7.5010 ,SNR2: 20.601




BLK: 2,SNR1: 6.9941 ,SNR2: 20.110





1638-025 2025/11/16 3.84UT TOYOKAWA-FUJI







BLK: 4,SNR1: 6.9930 ,SNR2: 19.872




BLK: 4,SNR1: 7.8949 ,SNR2: 19.993





1638-025 2025/11/16 3.84UT TOYOKAWA-KISO







BLK: 1,SNR1: 20.385 ,SNR2: 27.292




BLK: 1,SNR1: 14.786 ,SNR2: 26.214





1638-025 2025/11/16 3.84UT FUJI -KISO







BLK: 2,SNR1: 0.50763 ,SNR2: 7.3779




BLK: 2,SNR1: 13.458 ,SNR2: 17.715





1644-106 2025/11/16 3.96UT TOYOKAWA-FUJI







BLK: 3,SNR1: 0.50690 ,SNR2: 7.3726





BLK: 3,SNR1: 20.237 ,SNR2: 28.220




1644-106 2025/11/16 3.96UT TOYOKAWA-KISO





F20251116125551




No. Good Data




K20251116125549



No. Good Data





1644-106 2025/11/16 3.96UT FUJI -KISO







T20251116130111




BLK: 4,SNR1: 10.945 ,SNR2: 29.870




F20251116130112




BLK: 4,SNR1: 6.6582 ,SNR2: 18.942





1650+004 2025/11/16 4.05UT TOYOKAWA-FUJI







BLK: 7,SNR1: 16.179 ,SNR2: 37.886




BLK: 7,SNR1: 8.7030 ,SNR2: 21.868





1650+004 2025/11/16 4.05UT TOYOKAWA-KISO







BLK:10,SNR1: 6.8876 ,SNR2: 17.686




BLK:10,SNR1: 7.9924 ,SNR2: 19.889




1650+004 2025/11/16 4.05UT FUJI -KISO





T20251116130642




BLK: 4,SNR1: 4.5759 ,SNR2: 11.777




F20251116130642




BLK: 4,SNR1: 20.827 ,SNR2: 45.622




1656+053 2025/11/16 4.14UT TOYOKAWA-FUJI





T20251116130642




BLK: 2,SNR1: 8.7603 ,SNR2: 15.990




K20251116130641





BLK: 2,SNR1: 8.7689 ,SNR2: 22.687





1656+053 2025/11/16 4.14UT TOYOKAWA-KISO




F20251116130642




K20251116130641





1656+053 2025/11/16 4.14UT FUJI -KISO







BLK: 2,SNR1: 10.425 ,SNR2: 26.850




BLK: 2,SNR1: 8.5454 ,SNR2: 20.605





1712-033 2025/11/16 4.41UT TOYOKAWA-FUJI







BLK: 4,SNR1: 8.2822 ,SNR2: 23.495








BLK: 4,SNR1: 11.535 ,SNR2: 28.464




1712-033 2025/11/16 4.41UT TOYOKAWA-KISO













BLK: 1,SNR1: 6.1632 ,SNR2: 19.097







BLK: 1,SNR1: 0.17864 ,SNR2: 3.1728





1730-13 2025/11/16 4.72UT TOYOKAWA-FUJI









BLK: 2,SNR1: 8.0777 ,SNR2: 17.253




BLK: 2,SNR1: 17.416 ,SNR2: 30.732




1730-13 2025/11/16 4.72UT FUJI -KISO




T20251116135839




BLK: 3,SNR1: 9.8377 ,SNR2: 21.012




F20251116135840




BLK: 3,SNR1: 8.1006 ,SNR2: 24.628




1748+031 2025/11/16 5.01UT TOYOKAWA-FUJI




T20251116135839




BLK: 6,SNR1: 7.7544 ,SNR2: 20.995




K20251116135838





BLK: 6,SNR1: 9.5696 ,SNR2: 24.182




1748+031 2025/11/16 5.01UT TOYOKAWA-KISO





F20251116135840




BLK: 3,SNR1:-0.13071 ,SNR2: 1.5428




K20251116135838




BLK: 3,SNR1: 10.689 ,SNR2: 26.989





1748+031 2025/11/16 5.01UT FUJI -KISO







BLK: 5,SNR1: 6.8495 ,SNR2: 10.824




BLK: 5,SNR1: 6.2655 ,SNR2: 9.8621





1759+13 2025/11/16 5.19UT TOYOKAWA-FUJI









BLK: 8,SNR1: 2.6118 ,SNR2: 7.8520




BLK: 8,SNR1: 19.960 ,SNR2: 21.393




1759+13 2025/11/16 5.19UT TOYOKAWA-KISO




F20251116140932




BLK: 7,SNR1: 4.3639 ,SNR2: 9.4344




K20251116140931




BLK: 7,SNR1: 20.011 ,SNR2: 21.323





1759+13 2025/11/16 5.19UT FUJI -KISO







BLK: 3,SNR1: 2.5676 ,SNR2: 7.5474





BLK: 3,SNR1: 0.58709 ,SNR2: 5.1960




1819-096 2025/11/16 5.54UT TOYOKAWA-FUJI





T20251116143033




BLK: 4,SNR1: 3.7352 ,SNR2: 10.681




K20251116143032





BLK: 4,SNR1: 3.9446 ,SNR2: 8.3780




1819-096 2025/11/16 5.54UT TOYOKAWA-KISO





F20251116143034




BLK: 3,SNR1:-0.15583 ,SNR2: 1.5779




K20251116143032




BLK: 3,SNR1: 5.9656 ,SNR2: 17.138





1819-096 2025/11/16 5.54UT FUJI -KISO







BLK: 5, SNR1: 2.7108 , SNR2: 5.2982





BLK: 5, SNR1: 0.64900 , SNR2: 4.6352




1830-210 2025/11/16 5.72UT TOYOKAWA-FUJI





T20251116144148




BLK: 3, SNR1: 0.41574E-02, SNR2: 1.7305




K20251116144147




BLK: 3, SNR1: 0.46933, SNR2: 3.7419





1830-210 2025/11/16 5.72UT TOYOKAWA-KISO







BLK: 4,SNR1: 2.0737 ,SNR2: 5.2256




BLK: 4,SNR1: 10.467 ,SNR2: 18.517





1830-210 2025/11/16 5.72UT FUJI -KISO









BLK: 4,SNR1: 5.0497 ,SNR2: 14.255




BLK: 4,SNR1: 10.336 ,SNR2: 29.928





1858+171 2025/11/16 6.16UT TOYOKAWA-FUJI







BLK: 2,SNR1: 0.92357 ,SNR2: 3.8243







BLK: 2,SNR1: 3.4192 ,SNR2: 9.7757





1858+171 2025/11/16 6.16UT TOYOKAWA-KISO










BLK: 3,SNR1: 0.43542E-01,SNR2: 2.7309





BLK: 3,SNR1: 0.36996 ,SNR2: 3.8292







BLK: 9,SNR1: 1.3607 ,SNR2: 3.9584




BLK: 9,SNR1: 8.2788 ,SNR2: 17.692





1908-20 2025/11/16 6.34UT TOYOKAWA-KISO








BLK: 7,SNR1: 0.34943 ,SNR2: 3.5149





BLK: 7,SNR1: 2.2118 ,SNR2: 7.3371







BLK: 7,SNR1: 11.536 ,SNR2: 27.332







BLK: 7,SNR1: 6.1529 ,SNR2: 14.047




1915-121 2025/11/16 6.46UT TOYOKAWA-FUJI








1915-121 2025/11/16 6.46UT TOYOKAWA-KISO










BLK: 4, SNR1: 4.1712 , SNR2: 12.665





BLK: 4, SNR1: 5.1999 , SNR2: 12.330







BLK: 8,SNR1: 10.438 ,SNR2: 25.411




BLK: 8,SNR1: 9.2296 ,SNR2: 22.643





1928-142 2025/11/16 6.69UT TOYOKAWA-FUJI







BLK: 5, SNR1: 10.948 , SNR2: 26.909




BLK: 5, SNR1: 7.6677 , SNR2: 20.464





1928-142 2025/11/16 6.69UT TOYOKAWA-KISO







BLK: 2,SNR1: 13.339 ,SNR2: 32.400







BLK: 2,SNR1: 10.383 ,SNR2: 24.991








1928-142 2025/11/16 6.69UT FUJI -KISO






1938-15 2025/11/16 6.85UT TOYOKAWA-FUJI








1938-15 2025/11/16 6.85UT TOYOKAWA-KISO



F20251116154909





BLK: 4,SNR1: 8.3302 ,SNR2: 24.523




Frequency (Hz)

K20251116154908





BLK: 4,SNR1: 8.0275 ,SNR2: 23.219





Frequency (Hz)

1938-15 2025/11/16 6.85UT FUJI -KISO







BLK:10,SNR1: 5.1053 ,SNR2: 7.7739




BLK:10,SNR1: 13.198 ,SNR2: 17.291





3C422 2025/11/16 7.94UT TOYOKAWA-FUJI









BLK:16,SNR1: 1.7476 ,SNR2: 5.2939





BLK:16,SNR1: 7.9697 ,SNR2: 16.894




3C422 2025/11/16 7.94UT TOYOKAWA-KISO



F20251116165442





BLK:13,SNR1: 10.074 ,SNR2: 21.058




Frequency (Hz)

K20251116165440





BLK:13,SNR1: 7.7659 ,SNR2: 16.471





Frequency (Hz)

3C422 2025/11/16 7.94UT FUJI -KISO







BLK: 3,SNR1: 2.6432 ,SNR2: 5.2814




BLK: 3,SNR1: 0.63665 ,SNR2: 3.2926





2059-127 2025/11/16 8.19UT TOYOKAWA-FUJI







BLK: 1,SNR1: 6.2272 ,SNR2: 17.812




BLK: 1,SNR1: 10.123 ,SNR2: 23.266





2059-127 2025/11/16 8.19UT TOYOKAWA-KISO






BLK: 2, SNR1: 0.99926E-01, SNR2: 3.8498



BLK: 2, SNR1: 6.8096, SNR2: 17.810



2059-127 2025/11/16 8.19UT FUJI -KISO

