













BLK:16,SNR1: 0.19678 ,SNR2: 0.72682



BLK:16,SNR1: 15.223 ,SNR2: 29.068





0952-224 2025/11/23 20.57UT TOYOKAWA-KISO






F20251124053225




BLK:14,SNR1: 2.9772 ,SNR2: 6.0830










0952-224 2025/11/23 20.57UT FUJI -KISO








K20251124053224





BLK:14,SNR1: 13.101 ,SNR2: 25.093








F20251124054255





No.Good Data




Frequency (Hz)

K20251124054253




No.Good Data





Frequency (Hz)


1002-216 2025/11/23 20.74UT FUJI -KISO




T20251124061119




BLK: 5, SNR1: 1.7419 , SNR2: 14.315




F20251124061120





BLK: 5, SNR1: -0.17737 , SNR2: 0.0000




1031-11 2025/11/23 21.22UT TOYOKAWA-FUJI





T20251124061119




BLK:12,SNR1: 39.147 ,SNR2: 248.36




K20251124061118




BLK:12,SNR1: 0.54966 ,SNR2: 1.9321




1031-11 2025/11/23 21.22UT TOYOKAWA-KISO





F20251124061120




BLK: 6,SNR1:-0.28216 ,SNR2: 0.0000




K20251124061118





BLK: 6,SNR1: 8.4281 ,SNR2: 13.246




1031-11 2025/11/23 21.22UT FUJI -KISO




T20251124061553




BLK: 4,SNR1: 18.108 ,SNR2: 101.85




F20251124061553



BLK: 4,SNR1: 0.45240E-01,SNR2: 2.0998





1035-058 2025/11/23 21.29UT TOYOKAWA-FUJI








T20251124061553




BLK:12,SNR1: 11.405 ,SNR2: 59.286




K20251124061552




BLK:12,SNR1: 12.856 ,SNR2: 15.999




1035-058 2025/11/23 21.29UT TOYOKAWA-KISO





F20251124061553




BLK: 4,SNR1: 0.75962E-01,SNR2: 0.81979




K20251124061552









BLK: 4,SNR1: 3.1086 ,SNR2: 8.5459





1035-058 2025/11/23 21.29UT FUJI -KISO









BLK: 3,SNR1: 0.18692E-01,SNR2: 1.6352










BLK: 3,SNR1: 1.2365 ,SNR2: 3.4706




1055+01 2025/11/23 21.63UT TOYOKAWA-KISO










1107+109 2025/11/23 21.82UT TOYOKAWA-FUJI





T20251124064727




BLK:10,SNR1: 0.54081 ,SNR2: 1.7033




K20251124064726








BLK:10,SNR1: 7.9723 ,SNR2: 20.671





1107+109 2025/11/23 21.82UT TOYOKAWA-KISO









T20251124065705




BLK: 5, SNR1: 0.17562 , SNR2: 3.8465




F20251124065706





BLK: 5, SNR1: 0.22634 , SNR2: 3.2500




3C255 2025/11/23 21.98UT TOYOKAWA-FUJI





T20251124065705




BLK: 4, SNR1: 0.60239 , SNR2: 2.2929




K20251124065704








BLK: 4, SNR1: 12.335 , SNR2: 17.608




3C255 2025/11/23 21.98UT TOYOKAWA-KISO








T20251124070742




BLK: 2, SNR1: 5.2585 , SNR2: 17.430




F20251124070742




BLK: 2, SNR1: 9.6639 , SNR2: 21.322




1127-14 2025/11/23 22.16UT TOYOKAWA-FUJI




T20251124070742




BLK: 3,SNR1: 19.730 ,SNR2: 45.096




K20251124070741





BLK: 3,SNR1: 19.357 ,SNR2: 35.575




1127-14 2025/11/23 22.16UT TOYOKAWA-KISO




F20251124070742




BLK: 2, SNR1: 11.902 , SNR2: 21.350




K20251124070741




BLK: 2, SNR1: 18.219 , SNR2: 31.529




1127-14 2025/11/23 22.16UT FUJI -KISO





T20251124072103




BLK: 7, SNR1: 12.931 ,SNR2: 69.317




F20251124072104




BLK: 7, SNR1: 5.0170 ,SNR2: 12.586




3C263.1 2025/11/23 22.38UT TOYOKAWA-FUJI





T20251124072103




BLK: 8, SNR1: 30.143 , SNR2: 109.43




K20251124072102



BLK: 8, SNR1: 8.1703 , SNR2: 20.525





3C263.1 2025/11/23 22.38UT TOYOKAWA-KISO








F20251124072104




BLK: 2,SNR1:-0.20729 ,SNR2: 1.1514




K20251124072102





BLK: 2,SNR1: 1.2377 ,SNR2: 8.6019








3C263.1 2025/11/23 22.38UT FUJI -KISO






3C267 2025/11/23 22.49UT TOYOKAWA-FUJI







3C267 2025/11/23 22.49UT TOYOKAWA-KISO





F20251124072730




BLK: 2, SNR1: 0.64403E-01, SNR2: 3.5062




K20251124072729







BLK: 2, SNR1: 0.51564, SNR2: 4.0031






3C267 2025/11/23 22.49UT FUJI -KISO








1213-17 2025/11/23 22.92UT TOYOKAWA-FUJI







BLK:10,SNR1: 0.17424 ,SNR2: 1.3042





BLK:10,SNR1: 0.60252 ,SNR2: 3.3095









1213-17 2025/11/23 22.92UT TOYOKAWA-KISO






1213-17 2025/11/23 22.92UT FUJI -KISO













BLK: 9, SNR1: 0.77722 , SNR2: 3.8279




BLK: 9, SNR1: 0.84356 , SNR2: 2.5322




3C273 2025/11/23 23.14UT TOYOKAWA-KISO





F20251124080636




BLK: 6,SNR1: 0.67444E-01,SNR2: 5.0951




K20251124080634












BLK: 6,SNR1: 8.3700 ,SNR2: 19.014




3C273 2025/11/23 23.14UT FUJI -KISO












3C275 2025/11/23 23.36UT TOYOKAWA-KISO








3C275 2025/11/23 23.36UT FUJI -KISO





T20251124082551




BLK:15,SNR1: 7.5949 ,SNR2: 13.284




F20251124082551





BLK:15,SNR1: 16.033 ,SNR2: 23.105




1245-19 2025/11/23 23.46UT TOYOKAWA-FUJI





T20251124082551




BLK:18,SNR1: 6.6800 ,SNR2: 19.024




K20251124082550




BLK:18,SNR1: 11.033 ,SNR2: 19.404




1245-19 2025/11/23 23.46UT TOYOKAWA-KISO





F20251124082551




BLK:22,SNR1: 9.1732 ,SNR2: 14.397




K20251124082550



BLK:22,SNR1: 11.163 ,SNR2: 24.646





1245-19 2025/11/23 23.46UT FUJI -KISO







T20251124083334




BLK: 2, SNR1: 5.0342 , SNR2: 11.234




F20251124083334





BLK: 2, SNR1: 5.2556 , SNR2: 11.855




3C279 2025/11/23 23.59UT TOYOKAWA-FUJI




T20251124083334




BLK: 2, SNR1: 7.6597 , SNR2: 14.634




K20251124083333




BLK: 2, SNR1: 5.3416 , SNR2: 15.753




3C279 2025/11/23 23.59UT TOYOKAWA-KISO




F20251124083334




BLK: 3, SNR1: 5.9772 , SNR2: 9.9218




K20251124083333





BLK: 3, SNR1: 5.5336 , SNR2: 16.041




3C279 2025/11/23 23.59UT FUJI -KISO





T20251124084904




No. Good Data




F20251124084904




No. Good Data




3C283 2025/11/23 23.85UT TOYOKAWA-FUJI





T20251124084904




BLK: 1, SNR1: 15.011 , SNR2: 34.956




K20251124084903







BLK: 1, SNR1: 11.738 , SNR2: 26.778




3C283 2025/11/23 23.85UT TOYOKAWA-KISO








3C283 2025/11/23 23.85UT FUJI -KISO



T20251124090328





BLK: 2,SNR1: 0.67398 ,SNR2: 1.6105





1323+32 2025/11/24 0.09UT TOYOKAWA-FUJI



F20251124090328




BLK: 2,SNR1: 0.48061 ,SNR2: 0.93744




T20251124090328




BLK: 7, SNR1: 1.3607 , SNR2: 3.9639




K20251124090327




BLK: 7, SNR1: 8.9288 , SNR2: 18.990





1323+32 2025/11/24 0.09UT TOYOKAWA-KISO









BLK: 8, SNR1: 2.0624 , SNR2: 5.7993





BLK: 8, SNR1: 6.4141 , SNR2: 16.524




1323+32 2025/11/24 0.09UT FUJI -KISO



T20251124090818





BLK: 2, SNR1: 0.43887 , SNR2: 3.2945




Frequency (Hz)

F20251124090818




BLK: 2, SNR1: 6.4260 , SNR2: 16.013





Frequency (Hz)


3C286 2025/11/24 0.17UT TOYOKAWA-FUJI





T20251124090818




No. Good Data




K20251124090817







No. Good Data









3C286 2025/11/24 0.17UT TOYOKAWA-KISO












3C286 2025/11/24 0.17UT FUJI -KISO










F20251124092445




BLK: 3, SNR1: 0.17235 , SNR2: 4.8525




K20251124092444







BLK: 3, SNR1: 0.84231 , SNR2: 3.2705




1345+12 2025/11/24 0.44UT FUJI -KISO










1355+01 2025/11/24 0.61UT TOYOKAWA-FUJI










1355+01 2025/11/24 0.61UT TOYOKAWA-KISO





F20251124093507




BLK:10,SNR1: 0.64527 ,SNR2: 3.9670




K20251124093505




BLK:10,SNR1: 4.7426 ,SNR2: 7.4171




1355+01 2025/11/24 0.61UT FUJI -KISO





T20251124095617




BLK:13,SNR1: 8.8654 ,SNR2: 22.512




F20251124095618







BLK:13,SNR1: 6.8995 ,SNR2: 17.511








3C298 2025/11/24 0.97UT TOYOKAWA-FUJI






3C298 2025/11/24 0.97UT TOYOKAWA-KISO








3C298 2025/11/24 0.97UT FUJI -KISO



T20251124100800




BLK: 2, SNR1: 10.365 , SNR2: 22.596





1428-03 2025/11/24 1.16UT TOYOKAWA-FUJI



F20251124100800




BLK: 2, SNR1: 9.3320 , SNR2: 20.331





T20251124100800




BLK: 1, SNR1: 9.3700 , SNR2: 20.410




K20251124100759




BLK: 1, SNR1: 8.4258 , SNR2: 18.388




1428-03 2025/11/24 1.16UT TOYOKAWA-KISO





F20251124100800




BLK: 1, SNR1: 8.9113 ,SNR2: 19.490




K20251124100759







BLK: 1, SNR1: 9.7593 ,SNR2: 21.398




1428-03 2025/11/24 1.16UT FUJI -KISO












1436-16 2025/11/24 1.31UT TOYOKAWA-FUJI







1436-16 2025/11/24 1.31UT TOYOKAWA-KISO





F20251124101643




BLK: 9, SNR1: 13.239 , SNR2: 32.505




K20251124101641





BLK: 9, SNR1: 11.517 , SNR2: 29.058




1436-16 2025/11/24 1.31UT FUJI -KISO





T20251124103305




BLK: 6,SNR1: 0.82199 ,SNR2: 4.3386




F20251124103306





BLK: 6,SNR1: -0.13993E-01,SNR2: 1.2091




1453-10 2025/11/24 1.58UT TOYOKAWA-FUJI





T20251124103305




BLK: 3,SNR1: 1.1705 ,SNR2: 4.0480




K20251124103304




BLK: 3,SNR1: 2.1395 ,SNR2: 8.5273




1453-10 2025/11/24 1.58UT TOYOKAWA-KISO





F20251124103306




BLK: 1,SNR1:-0.58894E-01,SNR2: 1.0654




K20251124103304





BLK: 1,SNR1: 3.3986 ,SNR2: 8.4611




1453-10 2025/11/24 1.58UT FUJI -KISO



T20251124104757





BLK:10,SNR1: 6.0763 ,SNR2: 17.824





1508-05 2025/11/24 1.83UT TOYOKAWA-FUJI



F20251124104757




BLK:10,SNR1: 8.1393 ,SNR2: 20.256





T20251124104757




BLK: 5, SNR1: 6.0833 , SNR2: 17.845




K20251124104756



BLK: 5, SNR1: 9.6346 , SNR2: 24.859





1508-05 2025/11/24 1.83UT TOYOKAWA-KISO






F20251124104757





BLK: 6, SNR1: 4.3928 , SNR2: 12.618










1508-05 2025/11/24 1.83UT FUJI -KISO

K20251124104756




BLK: 6, SNR1: 11.197 , SNR2: 28.814









T20251124105657








K20251124105656





3C318 2025/11/24 1.98UT TOYOKAWA-KISO







T20251124110244




BLK:12,SNR1: 0.56820 ,SNR2: 1.7034




F20251124110245





BLK:12,SNR1: 0.10657 ,SNR2: 2.6265




1523+03 2025/11/24 2.07UT TOYOKAWA-FUJI





T20251124110244




BLK:10,SNR1: 0.43051 ,SNR2: 2.6617




K20251124110243




BLK:10,SNR1: 2.8385 ,SNR2: 5.2579




1523+03 2025/11/24 2.07UT TOYOKAWA-KISO





F20251124110245




BLK: 3, SNR1: 0.28130 , SNR2: 7.0560




K20251124110243








BLK: 3, SNR1: 2.1741 , SNR2: 6.5291




1523+03 2025/11/24 2.07UT FUJI -KISO













BLK: 4,SNR1: 0.27192 ,SNR2: 1.2242




BLK: 4,SNR1: 1.2224 ,SNR2: 5.2794





1535+139 2025/11/24 2.27UT TOYOKAWA-KISO







BLK:10,SNR1: 21.792 ,SNR2: 28.189





BLK:10,SNR1: 2.8873 ,SNR2: 6.7358




1535+139 2025/11/24 2.27UT FUJI -KISO





T20251124112448




BLK:11,SNR1: 1.9675 ,SNR2: 4.4534




F20251124112449




BLK:11,SNR1: 0.94727 ,SNR2: 3.6380




1545-12 2025/11/24 2.44UT TOYOKAWA-FUJI





T20251124112448




BLK:16,SNR1: 1.1700 ,SNR2: 3.6492




K20251124112447




BLK:16,SNR1: 6.4687 ,SNR2: 14.303




1545-12 2025/11/24 2.44UT TOYOKAWA-KISO





F20251124112449




BLK:15,SNR1: 2.5342 ,SNR2: 6.9930




K20251124112447





BLK:15,SNR1: 12.729 ,SNR2: 28.899




1545-12 2025/11/24 2.44UT FUJI -KISO




T20251124114550




BLK:14,SNR1: 2.2491 ,SNR2: 5.7934




F20251124114551









BLK:14,SNR1: 6.6152 ,SNR2: 14.598





1607+26 2025/11/24 2.79UT TOYOKAWA-FUJI









BLK:20,SNR1: 2.2682 ,SNR2: 6.8993



BLK:20,SNR1: 2.4847 ,SNR2: 7.8619





1607+26 2025/11/24 2.79UT FUJI -KISO







T20251124120055




BLK: 9, SNR1: 3.9200 , SNR2: 31.022




F20251124120055





BLK: 9, SNR1: 0.28504 , SNR2: 1.6168




1621-11 2025/11/24 3.04UT TOYOKAWA-FUJI




T20251124120055




BLK:13,SNR1: 0.21867 ,SNR2: 1.6805




K20251124120054




BLK:13,SNR1: 1.5388 ,SNR2: 4.2799




1621-11 2025/11/24 3.04UT TOYOKAWA-KISO




F20251124120055




BLK:13,SNR1: 0.42402E-01,SNR2: 1.1103




K20251124120054





BLK:13,SNR1: 1.3789 ,SNR2: 2.8896




1621-11 2025/11/24 3.04UT FUJI -KISO





T20251124121152




BLK:23,SNR1: 3.7178 ,SNR2: 8.0537




F20251124121152





BLK:23,SNR1: 4.3420 ,SNR2: 11.284




1631-222 2025/11/24 3.23UT TOYOKAWA-FUJI





T20251124121152




BLK:15,SNR1: 4.2423 ,SNR2: 9.1566




K20251124121151




BLK:15,SNR1: 9.4819 ,SNR2: 20.529




1631-222 2025/11/24 3.23UT TOYOKAWA-KISO





F20251124121152




BLK:21,SNR1: 3.1232 ,SNR2: 8.1449




K20251124121151







BLK:21,SNR1: 9.3565 ,SNR2: 20.256




1631-222 2025/11/24 3.23UT FUJI -KISO








1638-025 2025/11/24 3.32UT TOYOKAWA-FUJI




T20251124121728




BLK: 6,SNR1: 8.0229 ,SNR2: 20.235




K20251124121727



BLK: 6,SNR1: 12.698 ,SNR2: 30.913




1638-025 2025/11/24 3.32UT TOYOKAWA-KISO








F20251124121728




BLK: 4,SNR1: 8.0776 ,SNR2: 20.475




K20251124121727




BLK: 4,SNR1: 13.645 ,SNR2: 31.343





1638-025 2025/11/24 3.32UT FUJI -KISO







BLK:12,SNR1: 0.36306 ,SNR2: 2.3766




BLK:12,SNR1: -0.52261E-01,SNR2: 2.1936





1644-106 2025/11/24 3.43UT TOYOKAWA-FUJI







BLK:17,SNR1: 0.38798 ,SNR2: 2.5075




BLK:17,SNR1: 6.4906 ,SNR2: 14.939





1644-106 2025/11/24 3.43UT TOYOKAWA-KISO







BLK:10,SNR1:-0.77251E-01,SNR2: 2.2392





BLK:10,SNR1: 6.8329 ,SNR2: 15.707




1644-106 2025/11/24 3.43UT FUJI -KISO




T20251124122943




BLK: 7,SNR1: 0.31160 ,SNR2: 1.3739




F20251124122944





BLK: 7,SNR1: -0.20186 ,SNR2: 1.5258




1650+004 2025/11/24 3.52UT TOYOKAWA-FUJI





T20251124122943




BLK:23,SNR1: 0.30743 ,SNR2: 1.1482




K20251124122942




BLK:23,SNR1: 1.1569 ,SNR2: 3.6942




1650+004 2025/11/24 3.52UT TOYOKAWA-KISO




F20251124122944




BLK:16,SNR1:-0.22350 ,SNR2: 1.1944




K20251124122942





BLK:16,SNR1: 1.5399 ,SNR2: 4.9298




1650+004 2025/11/24 3.52UT FUJI -KISO





T20251124123515




BLK: 6,SNR1: 0.90943 ,SNR2: 2.9846




F20251124123515



BLK: 6,SNR1: 0.90347 ,SNR2: 7.6906





1656+053 2025/11/24 3.62UT TOYOKAWA-FUJI








T20251124123515




BLK:10,SNR1: 0.59587 ,SNR2: 3.4189




K20251124123514





BLK:10,SNR1: 0.15838 ,SNR2: 0.86555




1656+053 2025/11/24 3.62UT TOYOKAWA-KISO





F20251124123515




BLK:11,SNR1: 1.6779 ,SNR2: 8.2455




K20251124123514







BLK:11,SNR1: 0.89774 ,SNR2: 2.8797





1656+053 2025/11/24 3.62UT FUJI -KISO







1712-033 2025/11/24 3.89UT TOYOKAWA-FUJI







BLK: 5,SNR1: 9.0816 ,SNR2: 22.331




BLK: 5,SNR1: 9.8015 ,SNR2: 24.615




1712-033 2025/11/24 3.89UT TOYOKAWA-KISO





F20251124125145




BLK: 5, SNR1: 8.4247 , SNR2: 20.850




K20251124125144





BLK: 5, SNR1: 15.021 , SNR2: 36.508




1712-033 2025/11/24 3.89UT FUJI -KISO





T20251124130948




BLK: 7,SNR1: 0.62926 ,SNR2: 6.5476




F20251124130949




BLK: 7,SNR1: 0.84456E-01,SNR2: 6.1013





1730-13 2025/11/24 4.19UT TOYOKAWA-FUJI







BLK:13,SNR1: 0.72755 ,SNR2: 4.6492





BLK:13,SNR1: 0.10190 ,SNR2: 1.2493




1730-13 2025/11/24 4.19UT TOYOKAWA-KISO





F20251124130949




BLK: 6,SNR1: 0.81165 ,SNR2: 9.3538




K20251124130947



BLK: 6,SNR1: 0.27774 ,SNR2: 0.80666





1730-13 2025/11/24 4.19UT FUJI -KISO







T20251124132712




BLK: 4,SNR1: 0.27626 ,SNR2: 0.82452




F20251124132713





BLK: 4,SNR1: 0.14267 ,SNR2: 1.7897




1748+031 2025/11/24 4.48UT TOYOKAWA-FUJI





T20251124132712




BLK: 2, SNR1: 0.18474 , SNR2: 2.5881




K20251124132711




BLK: 2, SNR1: 0.48367 , SNR2: 4.4435





1748+031 2025/11/24 4.48UT TOYOKAWA-KISO







BLK: 3,SNR1:-0.30507 ,SNR2: 0.66452





BLK: 3,SNR1: 0.10730 ,SNR2: 0.90548




1748+031 2025/11/24 4.48UT FUJI -KISO




T20251124133805




BLK:12,SNR1: 0.77722 ,SNR2: 4.1166




F20251124133806




BLK:12,SNR1: 1.8879 ,SNR2: 9.5265





1759+13 2025/11/24 4.66UT TOYOKAWA-FUJI







BLK: 9,SNR1: 0.20302 ,SNR2: 2.2187





BLK: 9,SNR1: 1.0752 ,SNR2: 8.9121





1759+13 2025/11/24 4.66UT TOYOKAWA-KISO




F20251124133806




K20251124133804





1759+13 2025/11/24 4.66UT FUJI -KISO







BLK: 3,SNR1: 1.1683 ,SNR2: 2.7187





BLK: 3,SNR1: 3.1315 ,SNR2: 9.3210




1819-096 2025/11/24 5.01UT TOYOKAWA-FUJI




T20251124135905




BLK: 3, SNR1: 5.3191, SNR2: 15.260




K20251124135904



BLK: 3, SNR1: 6.4820, SNR2: 16.927




1819-096 2025/11/24 5.01UT TOYOKAWA-KISO







F20251124135905




BLK: 8, SNR1: 10.875 , SNR2: 24.183




K20251124135904




BLK: 8, SNR1: 9.3343 , SNR2: 22.724





1819-096 2025/11/24 5.01UT FUJI -KISO







BLK:13,SNR1: 0.13341 ,SNR2: 0.79830




BLK:13,SNR1:-0.13884 ,SNR2: 1.6121





1835+134 2025/11/24 5.26UT TOYOKAWA-FUJI







BLK:15,SNR1: 0.14701 ,SNR2: 0.74017




BLK:15,SNR1: 1.0140 ,SNR2: 3.5465




1835+134 2025/11/24 5.26UT TOYOKAWA-KISO





F20251124141349




BLK:17,SNR1: 0.19591 ,SNR2: 1.3410




K20251124141348




BLK:17,SNR1: 1.0742 ,SNR2: 3.6893





1835+134 2025/11/24 5.26UT FUJI -KISO







BLK: 6,SNR1: 0.26214 ,SNR2: 1.0562





BLK: 6,SNR1: 9.5036 ,SNR2: 23.058




1858+171 2025/11/24 5.64UT TOYOKAWA-FUJI





T20251124143645




BLK: 2,SNR1: 3.3298 ,SNR2: 9.0194




K20251124143644




BLK: 2,SNR1: 9.3475 ,SNR2: 24.074





1858+171 2025/11/24 5.64UT TOYOKAWA-KISO







BLK: 2, SNR1: 9.7985 , SNR2: 23.767





BLK: 2, SNR1: 3.2236 , SNR2: 6.3743




1858+171 2025/11/24 5.64UT FUJI -KISO





T20251124144730




BLK: 6,SNR1: 4.0492 ,SNR2: 5.3335




F20251124144731



BLK: 6,SNR1: 2.5210 ,SNR2: 6.0089





1908-20 2025/11/24 5.82UT TOYOKAWA-FUJI








T20251124144730




BLK: 8,SNR1: 2.6701 ,SNR2: 4.2279




K20251124144729




BLK: 8,SNR1: 1.7315 ,SNR2: 4.9020




1908-20 2025/11/24 5.82UT TOYOKAWA-KISO





F20251124144731




BLK: 2,SNR1: 2.1161 ,SNR2: 5.9136




K20251124144729





BLK: 2,SNR1: 2.3353 ,SNR2: 6.3203




1908-20 2025/11/24 5.82UT FUJI -KISO



T20251124145421




No. Good Data




Frequency (Hz)

F20251124145421




No. Good Data





Frequency (Hz)


1915-121 2025/11/24 5.93UT TOYOKAWA-FUJI



T20251124145421





No. Good Data




Frequency (Hz)

K20251124145420





No. Good Data





Frequency (Hz)

1915-121 2025/11/24 5.93UT TOYOKAWA-KISO







BLK: 2,SNR1:-0.56331E-01,SNR2: 1.6679




BLK: 2,SNR1: 4.9293 ,SNR2: 12.253




1915-121 2025/11/24 5.93UT FUJI -KISO





T20251124150803




BLK: 3,SNR1: 10.032 ,SNR2: 24.681




F20251124150804




BLK: 3,SNR1: 2.4463 ,SNR2: 11.189




1928-142 2025/11/24 6.16UT TOYOKAWA-FUJI





T20251124150803




BLK: 3,SNR1: 8.0707 ,SNR2: 14.437




K20251124150802




BLK: 3,SNR1: 2.6268 ,SNR2: 11.925





1928-142 2025/11/24 6.16UT TOYOKAWA-KISO








BLK: 3,SNR1: 10.055 ,SNR2: 24.715





BLK: 3,SNR1: 7.4467 ,SNR2: 18.769









BLK: 2,SNR1: 8.7895 ,SNR2: 21.994




BLK: 2,SNR1: 10.126 ,SNR2: 24.901





1938-15 2025/11/24 6.32UT TOYOKAWA-FUJI







BLK: 1,SNR1: 11.112 ,SNR2: 27.259






BLK: 1,SNR1: 8.8273 ,SNR2: 22.425





1938-15 2025/11/24 6.32UT TOYOKAWA-KISO








T20251124155237




BLK: 6,SNR1: 0.27540 ,SNR2: 0.94438




F20251124155237





BLK: 6,SNR1: 3.0761 ,SNR2: 6.4243




2014+358 2025/11/24 6.91UT TOYOKAWA-FUJI





T20251124155237




BLK: 1, SNR1: 0.59636 , SNR2: 1.5680




K20251124155236




BLK: 1, SNR1: 0.48658 , SNR2: 1.6814





2014+358 2025/11/24 6.91UT TOYOKAWA-KISO







BLK: 1,SNR1: 3.0446 ,SNR2: 32.099




BLK: 1,SNR1: 0.25174 ,SNR2: 0.93977





2014+358 2025/11/24 6.91UT FUJI -KISO








BLK: 4,SNR1: 6.1507 ,SNR2: 15.835





BLK: 4,SNR1: 6.0061 ,SNR2: 14.440







BLK: 5, SNR1: 8.6429 , SNR2: 20.394




BLK: 5, SNR1: 10.863 , SNR2: 25.980





3C422 2025/11/24 7.42UT TOYOKAWA-KISO









BLK: 7,SNR1: 6.9614 ,SNR2: 12.635




BLK: 7,SNR1: 9.9134 ,SNR2: 24.398




3C422 2025/11/24 7.42UT FUJI -KISO




T20251124164352




BLK: 1,SNR1: 0.75302 ,SNR2: 7.7989




F20251124164352





BLK: 1,SNR1:-0.29861 ,SNR2: 1.3194




2105-072 2025/11/24 7.76UT TOYOKAWA-FUJI





T20251124164352




No.Good Data




K20251124164351







No.Good Data





2105-072 2025/11/24 7.76UT TOYOKAWA-KISO









BLK: 4,SNR1: 8.2976 ,SNR2: 20.240




BLK: 4,SNR1: 9.7409 ,SNR2: 28.266





2121-014 2025/11/24 8.02UT TOYOKAWA-FUJI







BLK: 7, SNR1: 7.9787 , SNR2: 19.511












BLK: 7, SNR1: 8.7789 , SNR2: 21.240




2121-014 2025/11/24 8.02UT TOYOKAWA-KISO











2135-209 2025/11/24 8.26UT TOYOKAWA-FUJI







2135-209 2025/11/24 8.26UT TOYOKAWA-KISO

