






T20251203054317




BLK: 4, SNR1: 0.33808 ,SNR2: 1.2543




F20251203054318





BLK: 4, SNR1: 2.0283 ,SNR2: 7.3906




1038-191 2025/12/02 20.75UT TOYOKAWA-FUJI




T20251203054317




BLK: 8, SNR1: 0.18414E-01, SNR2: 2.0814




K20251203054316



BLK: 8, SNR1: 3.0341, SNR2: 9.3210





1038-191 2025/12/02 20.75UT TOYOKAWA-KISO







F20251203054318




BLK: 6, SNR1: 0.31500 , SNR2: 2.9713




K20251203054316






BLK: 6, SNR1: 3.0502 , SNR2: 9.3797





1038-191 2025/12/02 20.75UT FUJI -KISO








T20251203055350




BLK: 6,SNR1: 0.91961E-01,SNR2: 1.1899




K20251203055349




BLK: 6,SNR1: 2.4372 ,SNR2: 6.4879






1048-090 2025/12/02 20.93UT TOYOKAWA-KISO







BLK: 1, SNR1: 0.67575 , SNR2: 5.2780





BLK: 1, SNR1: 11.316 , SNR2: 29.444




1048-090 2025/12/02 20.93UT FUJI -KISO





T20251203060423




BLK: 5, SNR1: 10.129 ,SNR2: 33.160




F20251203060423










BLK: 5, SNR1: 1.4806 ,SNR2: 6.1673





1059-010 2025/12/02 21.10UT TOYOKAWA-FUJI








F20251203060423




BLK: 2, SNR1: 7.3475 , SNR2: 25.162




K20251203060422




BLK: 2, SNR1: 1.9029 , SNR2: 6.0520





1059-010 2025/12/02 21.10UT FUJI -KISO







BLK: 6,SNR1: 2.5746 ,SNR2: 12.456




BLK: 6,SNR1: 9.3550 ,SNR2: 23.218





1107+045 2025/12/02 21.24UT TOYOKAWA-FUJI









BLK: 5,SNR1: 7.6033 ,SNR2: 18.939




BLK: 5,SNR1: 6.0629 ,SNR2: 21.573




1107+045 2025/12/02 21.24UT TOYOKAWA-KISO




F20251203061231




BLK: 4, SNR1: 9.1625 , SNR2: 22.538




K20251203061229





BLK: 4, SNR1: 7.4795 , SNR2: 20.164




1107+045 2025/12/02 21.24UT FUJI -KISO





T20251203062142




BLK: 1, SNR1: 7.1524 , SNR2: 18.108




F20251203062142





BLK: 1, SNR1: 16.491 , SNR2: 29.075




3C255 2025/12/02 21.39UT TOYOKAWA-FUJI



T20251203062142





No.Good Data




Frequency (Hz)

K20251203062141




No.Good Data





Frequency (Hz)


3C255 2025/12/02 21.39UT TOYOKAWA-KISO





F20251203062142




BLK: 1, SNR1: 6.8495 , SNR2: 18.641




K20251203062141




BLK: 1, SNR1: 8.6145 , SNR2: 21.170





3C255 2025/12/02 21.39UT FUJI -KISO







BLK: 6,SNR1: 13.313 ,SNR2: 23.694




BLK: 6,SNR1: 10.444 ,SNR2: 24.616





1127-14 2025/12/02 21.57UT TOYOKAWA-FUJI









BLK: 5,SNR1: 6.5916 ,SNR2: 16.483




BLK: 5,SNR1: 4.8046 ,SNR2: 12.343



F20251203063220





BLK: 5, SNR1: 10.351 ,SNR2: 17.301




Frequency (Hz)

K20251203063218




BLK: 5, SNR1: 24.465 ,SNR2: 28.150





Frequency (Hz)

1127-14 2025/12/02 21:57UT FUJI -KISO








T20251203063636




BLK: 4, SNR1: 4.7529 ,SNR2: 11.476




F20251203063637





BLK: 4, SNR1: 12.355 ,SNR2: 30.045




1131-171 2025/12/02 21.64UT TOYOKAWA-FUJI



T20251203063636





BLK: 1,SNR1: 2.0563 ,SNR2: 7.0965




Frequency (Hz)

K20251203063635




BLK: 1,SNR1: 13.715 ,SNR2: 33.693




Frequency (Hz)


1131-171 2025/12/02 21.64UT TOYOKAWA-KISO





F20251203063637




BLK: 2, SNR1: 15.529 , SNR2: 44.838




K20251203063635




BLK: 2, SNR1: 9.2148 , SNR2: 26.310





1131-171 2025/12/02 21.64UT FUJI -KISO







BLK: 4,SNR1: 58.365 ,SNR2: 103.22




BLK: 4,SNR1: 9.5772 ,SNR2: 23.815





3C263.1 2025/12/02 21.79UT TOYOKAWA-FUJI







BLK: 1,SNR1: 17.387 ,SNR2: 54.744




BLK: 1,SNR1: 16.067 ,SNR2: 45.445




3C263.1 2025/12/02 21.79UT TOYOKAWA-KISO




F20251203064540




BLK: 1, SNR1: 17.951 ,SNR2: 32.065




K20251203064539




BLK: 1, SNR1: 6.9779 ,SNR2: 25.800





3C263.1 2025/12/02 21.79UT FUJI -KISO







BLK: 7, SNR1: 2.4742 , SNR2: 7.9101





BLK: 7, SNR1: 2.1311 , SNR2: 5.3701




3C267 2025/12/02 21.90UT TOYOKAWA-FUJI




T20251203065207




BLK: 9, SNR1: 2.7163 , SNR2: 8.5455




K20251203065206








BLK: 9, SNR1: 8.5454 , SNR2: 15.317




3C267 2025/12/02 21.90UT TOYOKAWA-KISO










T20251203071754




BLK: 2, SNR1: 12.538 , SNR2: 30.732




F20251203071755




BLK: 2, SNR1: 7.7708 , SNR2: 21.071




1213-17 2025/12/02 22.33UT TOYOKAWA-FUJI





T20251203071754




BLK: 4, SNR1: 10.179 , SNR2: 18.135




K20251203071753




BLK: 4, SNR1: 8.6687 , SNR2: 22.343




1213-17 2025/12/02 22.33UT TOYOKAWA-KISO





F20251203071755




BLK: 4, SNR1: 6.6375 , SNR2: 16.094




K20251203071753







BLK: 4, SNR1: 16.773 , SNR2: 36.453




1213-17 2025/12/02 22.33UT FUJI -KISO







3C273 2025/12/02 22.55UT TOYOKAWA-FUJI




T20251203073112




BLK: 2, SNR1: 7.5470 , SNR2: 19.420




K20251203073111




BLK: 2, SNR1: 10.366 , SNR2: 26.144




3C273 2025/12/02 22.55UT TOYOKAWA-KISO




F20251203073113




BLK: 3, SNR1: 8.0311 , SNR2: 19.832




K20251203073111





BLK: 3, SNR1: 7.5917 , SNR2: 20.814




3C273 2025/12/02 22.55UT FUJI -KISO




T20251203074422




BLK: 2,SNR1: 13.629 ,SNR2: 49.165




F20251203074422



BLK: 2,SNR1: 16.620 ,SNR2: 28.919





3C275 2025/12/02 22.77UT TOYOKAWA-FUJI







T20251203074422




BLK: 2, SNR1: 21.467 , SNR2: 40.887




K20251203074421




BLK: 2, SNR1: 14.946 , SNR2: 36.390




3C275 2025/12/02 22.77UT TOYOKAWA-KISO



F20251203074422




BLK: 5, SNR1: 8.4220 , SNR2: 20.759





3C275 2025/12/02 22.77UT FUJI -KISO



K20251203074421




BLK: 5, SNR1: 30.279 , SNR2: 58.752



T20251203075028




BLK:13,SNR1: 3.9845 ,SNR2: 11.730





1245-19 2025/12/02 22.87UT TOYOKAWA-FUJI



F20251203075029




BLK:13,SNR1: 2.3491 ,SNR2: 7.3781





T20251203075028




BLK:13,SNR1: 4.0374 ,SNR2: 11.872




K20251203075027




BLK:13,SNR1: 9.8955 ,SNR2: 22.820




1245-19 2025/12/02 22.87UT TOYOKAWA-KISO





F20251203075029




BLK:18,SNR1: 2.3211 ,SNR2: 7.1605




K20251203075027





BLK:18,SNR1: 8.4495 ,SNR2: 21.560




1245-19 2025/12/02 22.87UT FUJI -KISO




T20251203075811




BLK: 5, SNR1: 0.12685 , SNR2: 1.6502




F20251203075812




BLK: 5, SNR1: 0.52097E-01, SNR2: 1.4543




3C279 2025/12/02 23.00UT TOYOKAWA-FUJI




T20251203075811




BLK: 9, SNR1: 0.19792 , SNR2: 1.8602




K20251203075810







BLK: 9, SNR1: 7.9560 , SNR2: 14.740




3C279 2025/12/02 23.00UT TOYOKAWA-KISO














3C279 2025/12/02 23.00UT FUJI -KISO



















3C283 2025/12/02 23.26UT TOYOKAWA-KISO






3C283 2025/12/02 23.26UT FUJI -KISO








1323+32 2025/12/02 23.50UT TOYOKAWA-FUJI





T20251203082805




BLK: 3, SNR1: 0.41391 , SNR2: 1.9744




K20251203082804







BLK: 3, SNR1: 4.0372 , SNR2: 10.551









1323+32 2025/12/02 23.50UT TOYOKAWA-KISO











1323+32 2025/12/02 23.50UT FUJI -KISO















BLK: 2, SNR1: 1.9685 , SNR2: 5.5464







BLK: 2, SNR1: 7.1065 , SNR2: 11.491





3C286 2025/12/02 23.58UT FUJI -KISO









BLK: 1, SNR1: 0.41024 , SNR2: 0.97034




BLK: 1, SNR1: 8.8070 , SNR2: 20.113




1345+12 2025/12/02 23.85UT TOYOKAWA-KISO




F20251203084923




BLK: 1, SNR1: 9.7844 , SNR2: 20.748




K20251203084921





BLK: 1, SNR1: 10.174 , SNR2: 22.408




1345+12 2025/12/02 23.85UT FUJI -KISO




T20251203092053




BLK: 4, SNR1: 10.045 , SNR2: 24.049




F20251203092053





BLK: 4, SNR1: 11.757 , SNR2: 27.351




3C298 2025/12/03 0.38UT TOYOKAWA-FUJI




T20251203092053




BLK: 7, SNR1: 6.2727 , SNR2: 17.063




K20251203092052




BLK: 7, SNR1: 8.2870 , SNR2: 20.905




3C298 2025/12/03 0.38UT TOYOKAWA-KISO




F20251203092053




BLK:10,SNR1: 12.234 ,SNR2: 28.507




K20251203092052





BLK:10,SNR1: 8.6251 ,SNR2: 21.560




3C298 2025/12/03 0.38UT FUJI -KISO




T20251203093237




BLK: 4, SNR1: 2.0901 , SNR2: 9.9186




F20251203093238



BLK: 4, SNR1: 7.5161 , SNR2: 18.740





1428-03 2025/12/03 0.57UT TOYOKAWA-FUJI







T20251203093237




BLK: 7, SNR1: 1.9354 , SNR2: 9.3345




K20251203093236




BLK: 7, SNR1: 8.8588 , SNR2: 21.693




1428-03 2025/12/03 0.57UT TOYOKAWA-KISO




F20251203093238




BLK: 5, SNR1: 7.2564 , SNR2: 18.137




K20251203093236




BLK: 5, SNR1: 7.9279 , SNR2: 19.596




1428-03 2025/12/03 0.57UT FUJI -KISO



T20251203094118




BLK: 3, SNR1: 10.713 , SNR2: 27.096





1436-16 2025/12/03 0.72UT TOYOKAWA-FUJI


F20251203094118




BLK: 3, SNR1: 10.549 , SNR2: 25.793




T20251203094118




BLK:10,SNR1: 12.864 ,SNR2: 30.486




K20251203094117




BLK:10,SNR1: 11.098 ,SNR2: 26.998




1436-16 2025/12/03 0.72UT TOYOKAWA-KISO




F20251203094118




BLK: 8, SNR1: 8.8291 , SNR2: 21.727




K20251203094117





BLK: 8, SNR1: 8.8483 , SNR2: 21.992




1436-16 2025/12/03 0.72UT FUJI -KISO





T20251203095742




BLK:13,SNR1: 3.8347 ,SNR2: 11.068




F20251203095743




BLK:13,SNR1: 9.6973 ,SNR2: 16.357




1453-10 2025/12/03 0.99UT TOYOKAWA-FUJI



T20251203095742




BLK:12,SNR1: 4.4637 ,SNR2: 12.926




1453-10 2025/12/03 0.99UT TOYOKAWA-KISO


K20251203095741




BLK:12,SNR1: 11.854 ,SNR2: 34.042




Frequency (Hz)




F20251203095743




BLK: 8, SNR1: 4.3861 , SNR2: 10.639




K20251203095741







BLK: 8, SNR1: 12.918 , SNR2: 37.019




1453-10 2025/12/03 0.99UT FUJI -KISO










1508-05 2025/12/03 1.24UT TOYOKAWA-FUJI







BLK:16,SNR1: 0.30304 ,SNR2: 2.4363








BLK:16,SNR1: 6.2271 ,SNR2: 11.548





1508-05 2025/12/03 1.24UT TOYOKAWA-KISO






T20251203102133




BLK: 8, SNR1: 0.18448 , SNR2: 1.0913









3C318 2025/12/03 1.39UT TOYOKAWA-FUJI

F20251203102134





BLK: 8, SNR1: 0.61468 , SNR2: 3.8789







3C318 2025/12/03 1.39UT TOYOKAWA-KISO







BLK: 2, SNR1: 0.86800 , SNR2: 5.8534








BLK: 2, SNR1: 2.9308 , SNR2: 9.1184





3C318 2025/12/03 1.39UT FUJI -KISO







T20251203102721




BLK:23,SNR1: 9.8512 ,SNR2: 18.981




K20251203102720








BLK:23,SNR1: 52.038 ,SNR2: 97.928







1523+03 2025/12/03 1.48UT TOYOKAWA-KISO

















1535+139 2025/12/03 1.68UT TOYOKAWA-FUJI








F20251203103901




BLK:13,SNR1: 48.163 ,SNR2: 60.027




K20251203103859




BLK:13,SNR1: 83.263 ,SNR2: 152.38





1535+139 2025/12/03 1.68UT FUJI -KISO








BLK:16,SNR1: 98.087 ,SNR2: 349.37





BLK:16,SNR1: 185.90 ,SNR2: 182.32









BLK:10,SNR1: 152.68 ,SNR2: 378.05




BLK:10,SNR1: 258.29 ,SNR2: 647.35




F20251203105206




BLK:17,SNR1: 173.50 ,SNR2: 170.16




K20251203105205





BLK:17,SNR1: 133.81 ,SNR2: 323.53




1548+05 2025/12/03 1.90UT FUJI -KISO




T20251203111027




BLK: 8, SNR1: 0.60971 , SNR2: 1.9652




F20251203111028



BLK: 8, SNR1: 3.3588 , SNR2: 6.2958





1607+26 2025/12/03 2.20UT TOYOKAWA-FUJI








T20251203111027




BLK: 5, SNR1: 5.2720 , SNR2: 13.141




K20251203111026





BLK: 5, SNR1: 5.3345 , SNR2: 10.261




1607+26 2025/12/03 2.20UT TOYOKAWA-KISO





F20251203111028




BLK:14,SNR1: 2.6338 ,SNR2: 9.2536




K20251203111026




BLK:14,SNR1: 4.9099 ,SNR2: 9.1722




1607+26 2025/12/03 2.20UT FUJI -KISO





T20251203112532




BLK: 7, SNR1: 5.4250 ,SNR2: 11.414




F20251203112533




BLK: 7, SNR1: 9.7234 ,SNR2: 30.034




1621-11 2025/12/03 2.45UT TOYOKAWA-FUJI



T20251203112532




BLK: 6,SNR1: 5.1076 ,SNR2: 10.829





1621-11 2025/12/03 2.45UT TOYOKAWA-KISO



K20251203112531




BLK: 6,SNR1: 11.056 ,SNR2: 27.403




F20251203112533




BLK: 5, SNR1: 0.78647 , SNR2: 10.819




K20251203112531





BLK: 5, SNR1: 10.186 , SNR2: 24.945




1621-11 2025/12/03 2.45UT FUJI -KISO



T20251203114205





BLK:13,SNR1: 3.2352 ,SNR2: 9.6941




Frequency (Hz)

F20251203114206




BLK:13,SNR1: 2.6472 ,SNR2: 8.1235





Frequency (Hz)


1638-025 2025/12/03 2.73UT TOYOKAWA-FUJI




T20251203114205




BLK:21,SNR1: 3.1800 ,SNR2: 9.5164




K20251203114204




BLK:21,SNR1: 11.132 ,SNR2: 19.527





1638-025 2025/12/03 2.73UT TOYOKAWA-KISO







BLK: 8,SNR1: 2.7498 ,SNR2: 8.4443




BLK: 8,SNR1: 10.246 ,SNR2: 17.984





1638-025 2025/12/03 2.73UT FUJI -KISO









BLK: 1,SNR1: 4.6539 ,SNR2: 17.486






BLK: 1,SNR1: 5.4393 ,SNR2: 15.261





1644-106 2025/12/03 2.84UT TOYOKAWA-FUJI







F20251203114901




BLK: 2,SNR1: 6.8431 ,SNR2: 17.081




K20251203114859




BLK: 2,SNR1: 18.921 ,SNR2: 33.400




1644-106 2025/12/03 2.84UT FUJI -KISO




T20251203115420




BLK: 9,SNR1: 1.9129 ,SNR2: 9.8455




F20251203115421




BLK: 9,SNR1: 3.2952 ,SNR2: 7.2471




1650+004 2025/12/03 2.93UT TOYOKAWA-FUJI




T20251203115420




BLK: 4, SNR1: 4.0295 , SNR2: 10.394




K20251203115419




BLK: 4, SNR1: 6.4967 , SNR2: 11.456





1650+004 2025/12/03 2.93UT TOYOKAWA-KISO







BLK: 1,SNR1: 1.7977 ,SNR2: 11.954




BLK: 1,SNR1: 17.191 ,SNR2: 34.011





1650+004 2025/12/03 2.93UT FUJI -KISO







BLK: 2,SNR1: 2.2988 ,SNR2: 10.726




BLK: 2,SNR1: 9.4271 ,SNR2: 23.245





1656+053 2025/12/03 3.03UT TOYOKAWA-FUJI







BLK: 2,SNR1: 2.5030 ,SNR2: 6.9643



BLK: 2,SNR1: 17.360 ,SNR2: 31.110





1656+053 2025/12/03 3.03UT TOYOKAWA-KISO







F20251203115953




BLK: 1,SNR1: 2.9351 ,SNR2: 14.003




K20251203115951




BLK: 1,SNR1: 13.168 ,SNR2: 32.142




1656+053 2025/12/03 3.03UT FUJI -KISO




T20251203121622




BLK: 1,SNR1: 4.1974 ,SNR2: 12.012




F20251203121623





BLK: 1,SNR1: 14.479 ,SNR2: 45.541




1712-033 2025/12/03 3.30UT TOYOKAWA-FUJI



T20251203121622





No.Good Data




Frequency (Hz)

K20251203121621





No.Good Data





Frequency (Hz)

1712-033 2025/12/03 3.30UT TOYOKAWA-KISO







BLK: 1,SNR1: 1.0508 ,SNR2: 6.1365




BLK: 1,SNR1: 7.2533 ,SNR2: 18.521





1712-033 2025/12/03 3.30UT FUJI -KISO







BLK: 1,SNR1: 8.5575 ,SNR2: 20.970




BLK: 1,SNR1: 7.3546 ,SNR2: 18.077




1730-13 2025/12/03 3.60UT TOYOKAWA-FUJI




T20251203123425




BLK: 2,SNR1: 9.4390 ,SNR2: 23.339




K20251203123424




BLK: 2,SNR1: 9.2330 ,SNR2: 22.803




1730-13 2025/12/03 3.60UT TOYOKAWA-KISO





F20251203123426




BLK: 4,SNR1: 10.868 ,SNR2: 26.299




K20251203123424








BLK: 4,SNR1: 10.658 ,SNR2: 18.646




1730-13 2025/12/03 3.60UT FUJI -KISO













BLK: 3,SNR1: 0.85786 ,SNR2: 2.7324




BLK: 3,SNR1: 1.8383 ,SNR2: 9.0050





1748+031 2025/12/03 3.89UT TOYOKAWA-KISO







BLK: 1,SNR1: 0.79264 ,SNR2: 6.8384




BLK: 1,SNR1: 2.5267 ,SNR2: 8.0096




1748+031 2025/12/03 3.89UT FUJI -KISO





T20251203130242




BLK: 7,SNR1: 9.2335 ,SNR2: 22.210




F20251203130242








BLK: 7,SNR1: 12.989 ,SNR2: 23.071





1759+13 2025/12/03 4.07UT TOYOKAWA-FUJI








F20251203130242




BLK: 6,SNR1: 8.1964 ,SNR2: 19.996




K20251203130241




BLK: 6,SNR1: 24.595 ,SNR2: 43.606





1759+13 2025/12/03 4.07UT FUJI -KISO







BLK: 3,SNR1: 2.3794 ,SNR2: 11.192




BLK: 3,SNR1: 18.112 ,SNR2: 32.787





1819-096 2025/12/03 4.42UT TOYOKAWA-FUJI







BLK: 4,SNR1: 10.570 ,SNR2: 25.636




BLK: 4,SNR1: 10.251 ,SNR2: 25.179





1819-096 2025/12/03 4.42UT TOYOKAWA-KISO







BLK: 6,SNR1: 12.899 ,SNR2: 21.897






BLK: 6,SNR1: 16.290 ,SNR2: 28.780











1819-096 2025/12/03 4.42UT FUJI -KISO















T20251203133826




BLK: 9,SNR1: 27.096 ,SNR2: 39.350




F20251203133826





BLK: 9,SNR1: 4.2301 ,SNR2: 9.0189




1835+134 2025/12/03 4.67UT TOYOKAWA-FUJI





T20251203133826




BLK: 5, SNR1: 34.398 , SNR2: 49.968




K20251203133825




BLK: 5, SNR1: 5.3712 , SNR2: 11.801






1835+134 2025/12/03 4.67UT TOYOKAWA-KISO




F20251203133826





K20251203133825




1835+134 2025/12/03 4.67UT FUJI -KISO




T20251203140122




BLK: 4,SNR1: 0.45040 ,SNR2: 0.98420




F20251203140123




BLK: 4,SNR1: 1.8684 ,SNR2: 3.7816





1858+171 2025/12/03 5.05UT TOYOKAWA-FUJI







BLK: 6,SNR1: 0.33805 ,SNR2: 1.8492




BLK: 6,SNR1: 0.65535 ,SNR2: 2.3863





1858+171 2025/12/03 5.05UT TOYOKAWA-KISO











BLK: 4,SNR1: 1.3168 ,SNR2: 5.1732




BLK: 4,SNR1: 2.3797 ,SNR2: 5.0130




T20251203141207




No.Good Data




F20251203141207





No.Good Data




1908-20 2025/12/03 5.23UT TOYOKAWA-FUJI




T20251203141207




BLK: 2,SNR1: 3.1810 ,SNR2: 9.7349




K20251203141206





BLK: 2,SNR1: 12.330 ,SNR2: 21.770




1908-20 2025/12/03 5.23UT TOYOKAWA-KISO



F20251203141207





No. Good Data




Frequency (Hz)

K20251203141206




No. Good Data





Frequency (Hz)


1908-20 2025/12/03 5.23UT FUJI -KISO





T20251203141858




BLK: 4,SNR1: 1.3125 ,SNR2: 13.879




F20251203141858





BLK: 4,SNR1: 16.792 ,SNR2: 29.832




1915-121 2025/12/03 5.34UT TOYOKAWA-FUJI





T20251203141858




BLK: 5,SNR1: 8.6756 ,SNR2: 21.498




K20251203141857





BLK: 5,SNR1: 8.3843 ,SNR2: 20.777




1915-121 2025/12/03 5.34UT TOYOKAWA-KISO



F20251203141858





No.Good Data




Frequency (Hz)

K20251203141857





No.Good Data





Frequency (Hz)

1915-121 2025/12/03 5.34UT FUJI -KISO







BLK: 5,SNR1: 6.3952 ,SNR2: 20.285




BLK: 5,SNR1: 8.7268 ,SNR2: 21.898





1928-142 2025/12/03 5.57UT TOYOKAWA-FUJI









BLK: 2,SNR1: 10.971 ,SNR2: 26.949





BLK: 2,SNR1: 9.1938 ,SNR2: 22.627




1928-142 2025/12/03 5.57UT TOYOKAWA-KISO



F20251203143239





BLK: 1,SNR1: 14.883 ,SNR2: 32.030




Frequency (Hz)

K20251203143238




BLK: 1,SNR1: 14.302 ,SNR2: 24.620




Frequency (Hz)


1928-142 2025/12/03 5.57UT FUJI -KISO




T20251203144219




No.Good Data




F20251203144219





No.Good Data




1938-15 2025/12/03 5.73UT TOYOKAWA-FUJI





T20251203144219




BLK: 1,SNR1: 9.0094 ,SNR2: 28.883




K20251203144218





BLK: 1,SNR1: 2.6967 ,SNR2: 12.522




1938-15 2025/12/03 5.73UT TOYOKAWA-KISO



F20251203144219





No.Good Data




Frequency (Hz)

K20251203144218





No.Good Data





Frequency (Hz)

1938-15 2025/12/03 5.73UT FUJI -KISO







BLK: 3,SNR1: 1.9056 ,SNR2: 6.0603




BLK: 3,SNR1: 4.8191 ,SNR2: 10.668





2014+358 2025/12/03 6.32UT TOYOKAWA-FUJI







BLK: 4, SNR1: 1.7712 , SNR2: 5.5955





BLK: 4, SNR1: 6.9165 , SNR2: 15.961




2014+358 2025/12/03 6.32UT TOYOKAWA-KISO





F20251203151715




BLK: 6,SNR1: 7.8358 ,SNR2: 20.337




K20251203151713



BLK: 6,SNR1: 7.9023 ,SNR2: 20.434




2014+358 2025/12/03 6.32UT FUJI -KISO







T20251203154751




BLK: 6,SNR1: 1.6115 ,SNR2: 4.6065




F20251203154752




BLK: 6,SNR1: 10.040 ,SNR2: 23.618




3C422 2025/12/03 6.83UT TOYOKAWA-FUJI





T20251203154751




BLK: 5, SNR1: 5.1002 , SNR2: 13.915




K20251203154750




BLK: 5, SNR1: 9.5986 , SNR2: 25.404




3C422 2025/12/03 6.83UT TOYOKAWA-KISO




F20251203154752




BLK: 6,SNR1: 9.0789 ,SNR2: 23.088




K20251203154750




BLK: 6,SNR1: 9.7848 ,SNR2: 27.656





3C422 2025/12/03 6.83UT FUJI -KISO







BLK: 7,SNR1: 49.814 ,SNR2: 121.29




BLK: 7,SNR1: 11.988 ,SNR2: 28.094





2105-072 2025/12/03 7.17UT TOYOKAWA-FUJI







BLK: 6,SNR1: 62.085 ,SNR2: 151.30




BLK: 6,SNR1: 26.851 ,SNR2: 62.572





2105-072 2025/12/03 7.17UT TOYOKAWA-KISO







BLK: 7,SNR1: 12.128 ,SNR2: 30.099





BLK: 7,SNR1: 25.882 ,SNR2: 61.798




2105-072 2025/12/03 7.17UT FUJI -KISO




T20251203162417




BLK: 1, SNR1: 13.722 , SNR2: 63.881




F20251203162418






BLK: 1, SNR1: 0.84909E-01, SNR2: 2.6740






2121-014 2025/12/03 7.43UT TOYOKAWA-FUJI




T20251203162417






K20251203162416





2121-014 2025/12/03 7.43UT TOYOKAWA-KISO








T20251203163833





BLK: 5, SNR1: 6.4119 , SNR2: 14.776




Frequency (Hz)

F20251203163833





BLK: 5, SNR1: 11.907 , SNR2: 20.897





Frequency (Hz)

2135-209 2025/12/03 7.67UT TOYOKAWA-FUJI







BLK: 9,SNR1: 6.4104 ,SNR2: 14.773





BLK: 9,SNR1: 9.7667 ,SNR2: 20.862




2135-209 2025/12/03 7.67UT TOYOKAWA-KISO



F20251203163833





BLK: 4, SNR1: 11.338 , SNR2: 19.911




Frequency (Hz)

K20251203163832









BLK: 4, SNR1: 8.3110 , SNR2: 14.556





Frequency (Hz)

2135-209 2025/12/03 7.67UT FUJI -KISO






T20251203165956





BLK: 2, SNR1: 0.30791 , SNR2: 2.2662




Frequency (Hz)

K20251203165955









BLK: 2, SNR1: 1.2659 , SNR2: 7.8655




Frequency (Hz)



2156-043 2025/12/03 8.03UT TOYOKAWA-KISO









BLK: 7,SNR1: 10.268 ,SNR2: 25.291







BLK: 7,SNR1: 8.8533 ,SNR2: 25.623



2203-18 2025/12/03 8.14UT TOYOKAWA-FUJI







2203-18 2025/12/03 8.14UT TOYOKAWA-KISO

