






T20251206054304




BLK:20,SNR1: 96.355 ,SNR2: 105.77




F20251206054305





BLK:20,SNR1: 66.185 ,SNR2: 81.936




1050-184 2025/12/05 20.75UT TOYOKAWA-FUJI





T20251206054304




BLK:17,SNR1: 18.795 ,SNR2: 36.618




K20251206054303



BLK:17,SNR1: 18.810 ,SNR2: 44.177





1050-184 2025/12/05 20.75UT TOYOKAWA-KISO








F20251206054305




BLK:12,SNR1: 39.599 ,SNR2: 50.637




K20251206054303





BLK:12,SNR1: 17.690 ,SNR2: 34.516




1050-184 2025/12/05 20.75UT FUJI -KISO





T20251206055301




BLK: 2,SNR1: 9.2142 ,SNR2: 32.000




F20251206055301





BLK: 2,SNR1: 1.6621 ,SNR2: 5.3063




1100-094 2025/12/05 20.91UT TOYOKAWA-FUJI




T20251206055301




BLK: 4, SNR1: 4.4388 , SNR2: 20.784




K20251206055300





BLK: 4, SNR1: 12.052 , SNR2: 21.297




1100-094 2025/12/05 20.91UT TOYOKAWA-KISO




F20251206055301




BLK: 2, SNR1: 2.3827 , SNR2: 10.979




K20251206055300




BLK: 2, SNR1: 8.2979 , SNR2: 20.638





1100-094 2025/12/05 20.91UT FUJI -KISO







BLK:12,SNR1: 33.843 ,SNR2: 67.289




BLK:12,SNR1: 10.100 ,SNR2: 26.047





1110-217 2025/12/05 21.08UT TOYOKAWA-FUJI







BLK: 9,SNR1: 65.788 ,SNR2: 102.03





BLK: 9,SNR1: 39.710 ,SNR2: 44.823




1110-217 2025/12/05 21.08UT TOYOKAWA-KISO





F20251206060318




BLK:16,SNR1: 63.041 ,SNR2: 94.213




K20251206060316





BLK:16,SNR1: 63.751 ,SNR2: 98.155




1110-217 2025/12/05 21.08UT FUJI -KISO





T20251206060954




BLK: 6, SNR1: 8.7977 , SNR2: 22.422




F20251206060955








BLK: 6, SNR1: 9.4422 , SNR2: 23.597





3C255 2025/12/05 21.19UT TOYOKAWA-FUJI










F20251206060955




BLK: 7, SNR1: 3.3282 , SNR2: 9.7835




K20251206060953





BLK: 7, SNR1: 11.537 , SNR2: 28.381




3C255 2025/12/05 21.19UT FUJI -KISO





T20251206062032




BLK: 4, SNR1: 7.6835 , SNR2: 22.196




F20251206062033





BLK: 4, SNR1: 7.2973 , SNR2: 20.774




1127-14 2025/12/05 21.37UT TOYOKAWA-FUJI




T20251206062032




BLK: 1, SNR1: 7.7095 , SNR2: 19.359




K20251206062031





BLK: 1, SNR1: 10.780 , SNR2: 25.562




1127-14 2025/12/05 21.37UT TOYOKAWA-KISO





F20251206062033




BLK: 4, SNR1: 9.4913 , SNR2: 24.609




K20251206062031





BLK: 4, SNR1: 8.2206 , SNR2: 23.791




1127-14 2025/12/05 21.37UT FUJI -KISO




T20251206062449




BLK: 2, SNR1: 10.227 , SNR2: 27.285




F20251206062450





BLK: 2, SNR1: 5.1969 , SNR2: 14.179




1131-171 2025/12/05 21.44UT TOYOKAWA-FUJI





T20251206062449




BLK: 3,SNR1: 31.747 ,SNR2: 99.406




K20251206062448





BLK: 3,SNR1: 2.9007 ,SNR2: 8.1948




1131-171 2025/12/05 21.44UT TOYOKAWA-KISO



F20251206062450





No.Good Data




Frequency (Hz)

K20251206062448




No.Good Data




Frequency (Hz)



1131-171 2025/12/05 21.44UT FUJI -KISO









BLK: 7,SNR1: 4.1954 ,SNR2: 12.260







BLK: 7,SNR1: 9.6484 ,SNR2: 26.506




1136-13 2025/12/05 21.52UT TOYOKAWA-FUJI








1136-13 2025/12/05 21.52UT TOYOKAWA-KISO





F20251206062936




BLK: 5, SNR1: 9.8979 , SNR2: 17.291




K20251206062934




BLK: 5, SNR1: 15.787 , SNR2: 32.102




1136-13 2025/12/05 21:52UT FUJI -KISO








BLK: 4, SNR1: 9.6176 , SNR2: 22.729




3C267 2025/12/05 21.70UT TOYOKAWA-FUJI





BLK: 4, SNR1: 11.497 , SNR2: 24.411







BLK: 3,SNR1: 14.822 ,SNR2: 51.632





BLK: 3,SNR1: 6.3191 ,SNR2: 14.469




3C267 2025/12/05 21.70UT TOYOKAWA-KISO




F20251206064020




BLK: 2,SNR1: 15.218 ,SNR2: 27.276




K20251206064018





BLK: 2,SNR1: 17.534 ,SNR2: 29.391




3C267 2025/12/05 21.70UT FUJI -KISO




T20251206070607




BLK: 1, SNR1: 0.13879 , SNR2: 2.4550




F20251206070608





BLK: 1, SNR1: 4.3255 , SNR2: 32.167




1213-17 2025/12/05 22.13UT TOYOKAWA-FUJI





T20251206070607




No.Good Data




K20251206070606



No.Good Data





1213-17 2025/12/05 22.13UT TOYOKAWA-KISO







F20251206070608




BLK: 3, SNR1: 2.2375 ,SNR2: 5.5659




K20251206070606




BLK: 3, SNR1: 16.307 ,SNR2: 31.100





1213-17 2025/12/05 22.13UT FUJI -KISO












BLK: 6,SNR1: 1.3246 ,SNR2: 3.1970




BLK: 6,SNR1:-0.21232 ,SNR2: 0.72167E-01








F20251206071925




BLK: 2, SNR1: 0.43435 , SNR2: 2.7694




K20251206071923





BLK: 2, SNR1: 1.8498 , SNR2: 5.1656




3C273 2025/12/05 22.35UT FUJI -KISO







3C275 2025/12/05 22.57UT TOYOKAWA-FUJI





T20251206073235




BLK: 9, SNR1: 0.15632 , SNR2: 2.1754




K20251206073234




BLK: 9, SNR1: 1.9242 , SNR2: 4.4325




3C275 2025/12/05 22.57UT TOYOKAWA-KISO



F20251206073235





BLK:11,SNR1: 0.48481 ,SNR2: 1.2300









3C275 2025/12/05 22.57UT FUJI -KISO

K20251206073234




BLK:11,SNR1: 3.7846 ,SNR2: 8.8156










1245-19 2025/12/05 22.67UT TOYOKAWA-FUJI










1245-19 2025/12/05 22.67UT TOYOKAWA-KISO




F20251206073841




BLK:10,SNR1: 9.4987 ,SNR2: 15.489




K20251206073839




BLK:10,SNR1: 14.794 ,SNR2: 23.974




1245-19 2025/12/05 22.67UT FUJI -KISO





T20251206074623




BLK: 4,SNR1: 13.409 ,SNR2: 31.443




F20251206074623




BLK: 4,SNR1: 11.317 ,SNR2: 27.116




3C279 2025/12/05 22.80UT TOYOKAWA-FUJI




T20251206074623




BLK: 1, SNR1: 11.995 , SNR2: 30.649




K20251206074622




BLK: 1, SNR1: 14.265 , SNR2: 35.288




3C279 2025/12/05 22.80UT TOYOKAWA-KISO




F20251206074623




BLK: 3, SNR1: 10.480 , SNR2: 25.678




K20251206074622




BLK: 3, SNR1: 9.9260 , SNR2: 28.661




3C279 2025/12/05 22.80UT FUJI -KISO





T20251206080153




BLK:13,SNR1: 1.5128 ,SNR2: 5.0049




F20251206080153




BLK:13,SNR1: 6.1913 ,SNR2: 15.671




3C283 2025/12/05 23.06UT TOYOKAWA-FUJI




T20251206080153




BLK: 6,SNR1: 1.8109 ,SNR2: 6.0255




K20251206080152







BLK: 6,SNR1: 8.8599 ,SNR2: 15.432




3C283 2025/12/05 23.06UT TOYOKAWA-KISO







3C283 2025/12/05 23.06UT FUJI -KISO






T20251206081617





BLK: 7, SNR1: 5.8412 , SNR2: 14.473





1323+32 2025/12/05 23.30UT TOYOKAWA-FUJI



F20251206081618




BLK: 7, SNR1: 5.4959 , SNR2: 14.545



T20251206081617





BLK: 8, SNR1: 1.9930 , SNR2: 4.9010





1323+32 2025/12/05 23.30UT TOYOKAWA-KISO



K20251206081616




BLK: 8, SNR1: 3.7402 , SNR2: 10.627





F20251206081618




BLK: 9, SNR1: 14.468 , SNR2: 32.536




K20251206081616




BLK: 9, SNR1: 9.2889 , SNR2: 23.623




1323+32 2025/12/05 23.30UT FUJI -KISO





T20251206082107




BLK: 8, SNR1: 1.9379 , SNR2: 5.5636




F20251206082107





BLK: 8, SNR1: 12.704 , SNR2: 36.284




3C286 2025/12/05 23.38UT TOYOKAWA-FUJI





T20251206082107




BLK:10,SNR1: 0.64317 ,SNR2: 2.0823




K20251206082106





BLK:10,SNR1: 7.9734 ,SNR2: 23.124




3C286 2025/12/05 23.38UT TOYOKAWA-KISO



F20251206082107




BLK: 9, SNR1: 12.416 , SNR2: 35.423









3C286 2025/12/05 23.38UT FUJI -KISO

K20251206082106




BLK: 9, SNR1: 9.1381 , SNR2: 24.971







1345+12 2025/12/05 23.65UT TOYOKAWA-FUJI



T20251206083735




BLK: 8, SNR1: 0.26172 , SNR2: 2.1152





1345+12 2025/12/05 23.65UT TOYOKAWA-KISO





K20251206083734




BLK: 8, SNR1: 9.1429 , SNR2: 16.103


















1345+12 2025/12/05 23.65UT FUJI -KISO









F20251206084756




BLK: 8, SNR1: 0.46426 , SNR2: 3.9811




K20251206084754





BLK: 8, SNR1: 2.5818 , SNR2: 9.4616




1355+01 2025/12/05 23.83UT FUJI -KISO




T20251206085404




BLK:21,SNR1: 40.913 ,SNR2: 68.832




F20251206085404





BLK:21,SNR1: 82.138 ,SNR2: 86.408




1401-043 2025/12/05 23.93UT TOYOKAWA-FUJI





T20251206085404




BLK:21,SNR1: 41.993 ,SNR2: 68.366




K20251206085403





BLK:21,SNR1: 112.62 ,SNR2: 121.61




1401-043 2025/12/05 23.93UT TOYOKAWA-KISO





F20251206085404




BLK:17,SNR1: 46.021 ,SNR2: 83.565




K20251206085403







BLK:17,SNR1: 53.962 ,SNR2: 98.842




1401-043 2025/12/05 23.93UT FUJI -KISO











3C298 2025/12/06 0.18UT TOYOKAWA-FUJI













BLK: 2, SNR1: 2.0901 , SNR2: 7.4234




BLK: 2, SNR1: 8.2430 , SNR2: 15.059




3C298 2025/12/06 0.18UT FUJI -KISO



T20251206092049





BLK:14,SNR1: 0.13328 ,SNR2: 1.5990





1428-03 2025/12/06 0.38UT TOYOKAWA-FUJI


F20251206092050




BLK:14,SNR1: 8.6234 ,SNR2: 25.450




T20251206092049




BLK: 6, SNR1: 0.62158E-01, SNR2: 1.1536




K20251206092048





BLK: 6, SNR1: 7.3188, SNR2: 15.830




1428-03 2025/12/06 0.38UT TOYOKAWA-KISO



F20251206092050




BLK: 4, SNR1: 0.93180 , SNR2: 5.1804





1428-03 2025/12/06 0.38UT FUJI -KISO



K20251206092048




BLK: 4, SNR1: 4.3412 , SNR2: 9.3997




T20251206092931




BLK:12,SNR1: 21.851 ,SNR2: 38.693




F20251206092932





BLK:12,SNR1: 3.0726 ,SNR2: 9.6134




1436-16 2025/12/06 0.52UT TOYOKAWA-FUJI



T20251206092931





BLK:12,SNR1: 6.8774 ,SNR2: 17.368




1436-16 2025/12/06 0.52UT TOYOKAWA-KISO


K20251206092930





BLK:12,SNR1: 39.046 ,SNR2: 73.471




Frequency (Hz)




F20251206092932




BLK:14,SNR1: 26.399 ,SNR2: 55.351




K20251206092930







BLK:14,SNR1: 41.943 ,SNR2: 78.855




1436-16 2025/12/06 0.52UT FUJI -KISO












1453-10 2025/12/06 0.79UT TOYOKAWA-FUJI







1453-10 2025/12/06 0.79UT TOYOKAWA-KISO





F20251206094555




BLK: 4, SNR1: 0.21954 , SNR2: 2.0683




K20251206094553













BLK: 4, SNR1: 1.5910 , SNR2: 10.390




1453-10 2025/12/06 0.79UT FUJI -KISO









F20251206100046




BLK:13,SNR1: 5.4786 ,SNR2: 18.480




K20251206100045







BLK:13,SNR1: 16.579 ,SNR2: 49.137





1508-05 2025/12/06 1.04UT FUJI -KISO







3C318 2025/12/06 1.19UT TOYOKAWA-FUJI







BLK: 5, SNR1: 0.62364 , SNR2: 4.2076








BLK: 5, SNR1: 1.2724 , SNR2: 6.0634







3C318 2025/12/06 1.19UT TOYOKAWA-KISO




















1523+03 2025/12/06 1.29UT TOYOKAWA-FUJI


















1523+03 2025/12/06 1.29UT FUJI -KISO













BLK: 5, SNR1: 9.0407 , SNR2: 16.198







BLK: 5, SNR1: 3.0865 , SNR2: 9.3924




1535+139 2025/12/06 1.48UT FUJI -KISO











1548+05 2025/12/06 1.70UT TOYOKAWA-FUJI









F20251206104018




BLK: 3,SNR1: 5.2735 ,SNR2: 20.973




K20251206104017












BLK: 3,SNR1: 9.7756 ,SNR2: 23.011




1548+05 2025/12/06 1.70UT FUJI -KISO

















1607+26 2025/12/06 2.01UT TOYOKAWA-KISO











1607+26 2025/12/06 2.01UT FUJI -KISO









F20251206111345




BLK: 4,SNR1:-0.28353 ,SNR2: 0.0000




K20251206111343







BLK: 4,SNR1: 4.1633 ,SNR2: 11.066




1621-11 2025/12/06 2.26UT FUJI -KISO












1631-222 2025/12/06 2.44UT TOYOKAWA-FUJI







1631-222 2025/12/06 2.44UT TOYOKAWA-KISO




F20251206112442




BLK:16,SNR1: 18.054 ,SNR2: 32.227




K20251206112440




BLK:16,SNR1: 49.472 ,SNR2: 86.797




1631-222 2025/12/06 2.44UT FUJI -KISO





T20251206113018




BLK: 6, SNR1: 12.157 , SNR2: 21.568




F20251206113018





BLK: 6, SNR1: 11.087 , SNR2: 19.652




1638-025 2025/12/06 2.53UT TOYOKAWA-FUJI



T20251206113018





BLK: 2,SNR1: 11.162 ,SNR2: 20.518




Frequency (Hz)

K20251206113017




BLK: 2,SNR1: 9.3684 ,SNR2: 20.620





Frequency (Hz)


1638-025 2025/12/06 2.53UT TOYOKAWA-KISO





F20251206113018




BLK: 1,SNR1: 8.9407 ,SNR2: 21.670




K20251206113017




BLK: 1,SNR1: 5.2761 ,SNR2: 13.612




1638-025 2025/12/06 2.53UT FUJI -KISO




T20251206113712




BLK: 4,SNR1: 7.4705 ,SNR2: 14.791




F20251206113713




BLK: 4,SNR1: 3.2010 ,SNR2: 11.393




1644-106 2025/12/06 2.65UT TOYOKAWA-FUJI





T20251206113712




BLK: 3, SNR1: 1.5239 , SNR2: 7.3944




K20251206113711



BLK: 3, SNR1: 19.032 , SNR2: 42.623





1644-106 2025/12/06 2.65UT TOYOKAWA-KISO








F20251206113713




No. Good Data




K20251206113711





No. Good Data




1644-106 2025/12/06 2.65UT FUJI -KISO




T20251206114233




BLK: 3,SNR1: 6.6755 ,SNR2: 21.987




F20251206114234





BLK: 3,SNR1: 16.545 ,SNR2: 30.764




1650+004 2025/12/06 2.74UT TOYOKAWA-FUJI




T20251206114233




BLK: 3, SNR1: 14.798 , SNR2: 35.522




K20251206114232




BLK: 3, SNR1: 5.8974 , SNR2: 19.269




1650+004 2025/12/06 2.74UT TOYOKAWA-KISO




F20251206114234




BLK: 5,SNR1: 11.354 ,SNR2: 27.598




K20251206114232




BLK: 5,SNR1: 6.1306 ,SNR2: 20.272




1650+004 2025/12/06 2.74UT FUJI -KISO




T20251206114804




BLK: 1,SNR1: 9.8830 ,SNR2: 24.213




F20251206114805





BLK: 1,SNR1: 1.1375 ,SNR2: 7.7952




1656+053 2025/12/06 2.83UT TOYOKAWA-FUJI



T20251206114804





No. Good Data




Frequency (Hz)

K20251206114803





No. Good Data





Frequency (Hz)

1656+053 2025/12/06 2.83UT TOYOKAWA-KISO







BLK: 3,SNR1: 7.1427 ,SNR2: 17.650





BLK: 3,SNR1: 19.472 ,SNR2: 34.640




1656+053 2025/12/06 2.83UT FUJI -KISO





T20251206120434




BLK: 5,SNR1: 3.9680 ,SNR2: 16.864




F20251206120435



BLK: 5,SNR1: 5.6361 ,SNR2: 16.422





1712-033 2025/12/06 3.10UT TOYOKAWA-FUJI








T20251206120434




BLK: 2, SNR1: 3.2590 , SNR2: 11.719




K20251206120433




BLK: 2, SNR1: 8.0843 , SNR2: 14.654




1712-033 2025/12/06 3.10UT TOYOKAWA-KISO





F20251206120435




BLK: 4,SNR1: 18.787 ,SNR2: 29.374




K20251206120433




BLK: 4,SNR1: 16.379 ,SNR2: 29.189




1712-033 2025/12/06 3.10UT FUJI -KISO




T20251206122237




BLK:11,SNR1: 39.148 ,SNR2: 39.745




F20251206122237




BLK:11,SNR1: 73.758 ,SNR2: 126.88




1730-13 2025/12/06 3.41UT TOYOKAWA-FUJI




T20251206122237




BLK: 3,SNR1: 29.970 ,SNR2: 55.049




K20251206122236




BLK: 3,SNR1: 68.318 ,SNR2: 98.420




1730-13 2025/12/06 3.41UT TOYOKAWA-KISO




F20251206122237




BLK: 8,SNR1: 83.245 ,SNR2: 104.36




K20251206122236





BLK: 8,SNR1: 85.418 ,SNR2: 110.46




1730-13 2025/12/06 3.41UT FUJI -KISO





T20251206124001




BLK: 5,SNR1: 4.7594 ,SNR2: 8.9392




F20251206124002





BLK: 5,SNR1: 7.7897 ,SNR2: 15.706




1748+031 2025/12/06 3.70UT TOYOKAWA-FUJI





T20251206124001




BLK: 3,SNR1: 1.6810 ,SNR2: 7.5064




K20251206124000




BLK: 3,SNR1: 23.679 ,SNR2: 43.497





1748+031 2025/12/06 3.70UT TOYOKAWA-KISO







BLK: 6,SNR1: 1.8515 ,SNR2: 8.6809




BLK: 6,SNR1: 10.643 ,SNR2: 21.548





1748+031 2025/12/06 3.70UT FUJI -KISO









BLK:10,SNR1: 15.398 ,SNR2: 33.414




BLK:10,SNR1: 12.895 ,SNR2: 27.669





1759+13 2025/12/06 3.88UT TOYOKAWA-FUJI







BLK:14,SNR1: 10.294 ,SNR2: 23.698





BLK:14,SNR1: 16.831 ,SNR2: 38.352




1759+13 2025/12/06 3.88UT TOYOKAWA-KISO





F20251206125055




BLK:13,SNR1: 12.734 ,SNR2: 28.784




K20251206125053





BLK:13,SNR1: 10.203 ,SNR2: 25.801




1759+13 2025/12/06 3.88UT FUJI -KISO




T20251206131155




BLK: 5,SNR1: 1.4151 ,SNR2: 3.0228




F20251206131156



BLK: 5,SNR1: 1.5778 ,SNR2: 6.8345




1819-096 2025/12/06 4.23UT TOYOKAWA-FUJI








F20251206131156




BLK: 4,SNR1:-0.16876E-01,SNR2: 1.8008




K20251206131154







BLK: 4,SNR1: 4.6839 ,SNR2: 17.498





1819-096 2025/12/06 4.23UT FUJI -KISO







1829+29 2025/12/06 4.37UT TOYOKAWA-FUJI







BLK: 1,SNR1: 0.27470 ,SNR2: 1.3164






BLK: 1,SNR1: 5.3267 ,SNR2: 18.822




1829+29 2025/12/06 4.37UT TOYOKAWA-KISO










T20251206132638




BLK:14,SNR1: 16.335 ,SNR2: 20.534




F20251206132639




BLK:14,SNR1: 11.363 ,SNR2: 24.176




1835+134 2025/12/06 4.47UT TOYOKAWA-FUJI





T20251206132638




BLK:21,SNR1: 9.7643 ,SNR2: 17.423




K20251206132637




BLK:21,SNR1: 9.4594 ,SNR2: 17.149





1835+134 2025/12/06 4.47UT TOYOKAWA-KISO









BLK:13,SNR1: 7.7022 ,SNR2: 18.359




BLK:13,SNR1: 9.0234 ,SNR2: 16.266





T20251206134934




BLK: 2,SNR1: 5.4437 ,SNR2: 12.404




F20251206134935





BLK: 2,SNR1: 3.6161 ,SNR2: 33.320




1858+171 2025/12/06 4.85UT TOYOKAWA-FUJI





T20251206134934




BLK: 7,SNR1: 4.9579 ,SNR2: 18.604




K20251206134933




BLK: 7,SNR1: 2.3067 ,SNR2: 11.111





1858+171 2025/12/06 4.85UT TOYOKAWA-KISO









BLK: 2,SNR1: 12.294 ,SNR2: 29.018




BLK: 2,SNR1: 11.477 ,SNR2: 27.956





T20251206140020




BLK: 4,SNR1: 2.8491 ,SNR2: 6.3252




F20251206140021



BLK: 4,SNR1: 6.4731 ,SNR2: 16.098





1908-20 2025/12/06 5.03UT TOYOKAWA-FUJI







T20251206140020




BLK: 2, SNR1: 2.5640 , SNR2: 8.5472




K20251206140019





BLK: 2, SNR1: 8.2818 , SNR2: 23.132




1908-20 2025/12/06 5.03UT TOYOKAWA-KISO




F20251206140021




BLK: 3,SNR1: 29.243 ,SNR2: 65.973




K20251206140019




BLK: 3,SNR1: 9.0068 ,SNR2: 21.288





1908-20 2025/12/06 5.03UT FUJI -KISO







BLK: 4,SNR1: 2.2359 ,SNR2: 10.623




BLK: 4,SNR1: 18.541 ,SNR2: 33.538





1915-121 2025/12/06 5.15UT TOYOKAWA-FUJI







BLK: 4,SNR1: 16.788 ,SNR2: 33.667




BLK: 4,SNR1: 15.103 ,SNR2: 35.071




1915-121 2025/12/06 5.15UT TOYOKAWA-KISO




F20251206140711




BLK: 5,SNR1: 18.269 ,SNR2: 33.044




K20251206140709




BLK: 5,SNR1: 20.825 ,SNR2: 36.378





1915-121 2025/12/06 5.15UT FUJI -KISO







BLK:22,SNR1: 12.350 ,SNR2: 21.826




BLK:22,SNR1: 11.005 ,SNR2: 19.755





1928-142 2025/12/06 5.38UT TOYOKAWA-FUJI







BLK:26,SNR1: 11.947 ,SNR2: 21.140




BLK:26,SNR1: 12.527 ,SNR2: 22.624





1928-142 2025/12/06 5.38UT TOYOKAWA-KISO








BLK:26,SNR1: 11.460 ,SNR2: 20.377





BLK:26,SNR1: 13.591 ,SNR2: 24.755









BLK: 1,SNR1: 25.124 ,SNR2: 37.008









BLK: 1,SNR1: 3.1546 ,SNR2: 10.227









1938-15 2025/12/06 5.54UT TOYOKAWA-FUJI














F20251206150527




BLK: 1,SNR1: 16.762 ,SNR2: 41.793




K20251206150525




BLK: 1,SNR1: 9.3139 ,SNR2: 26.766





2014+358 2025/12/06 6.12UT FUJI -KISO







BLK: 6,SNR1: 13.100 ,SNR2: 12.623




BLK: 6,SNR1: 3.3299 ,SNR2: 9.2223





3C422 2025/12/06 6.63UT TOYOKAWA-FUJI







BLK: 7, SNR1: 12.938 , SNR2: 12.468




BLK: 7, SNR1: 7.5077 , SNR2: 13.471





3C422 2025/12/06 6.63UT TOYOKAWA-KISO










BLK:11,SNR1: 3.3569 ,SNR2: 9.2908





BLK:11,SNR1: 7.5082 ,SNR2: 13.369







BLK:13,SNR1: 12.567 ,SNR2: 29.218




BLK:13,SNR1: 12.329 ,SNR2: 28.390





2105-072 2025/12/06 6.97UT TOYOKAWA-FUJI







BLK: 9,SNR1: 9.4512 ,SNR2: 23.471




BLK: 9,SNR1: 13.488 ,SNR2: 31.796





2105-072 2025/12/06 6.97UT TOYOKAWA-KISO







BLK: 9,SNR1: 9.2019 ,SNR2: 23.594




BLK: 9,SNR1: 13.647 ,SNR2: 32.248





2105-072 2025/12/06 6.97UT FUJI -KISO







BLK: 3,SNR1: 0.34798 ,SNR2: 1.2625




BLK: 3,SNR1:-0.83694E-02,SNR2: 1.8957





2121-014 2025/12/06 7.24UT TOYOKAWA-FUJI







BLK: 3,SNR1: 0.28784 ,SNR2: 1.8195




BLK: 3,SNR1: 1.5473 ,SNR2: 5.7081





2121-014 2025/12/06 7.24UT TOYOKAWA-KISO







BLK: 2,SNR1:-0.14078 ,SNR2: 1.1561




BLK: 2,SNR1: 2.2958 ,SNR2: 10.391





2121-014 2025/12/06 7.24UT FUJI -KISO







BLK: 9,SNR1: 3.2332 ,SNR2: 7.7711




BLK: 9,SNR1: 2.8454 ,SNR2: 6.7230





2135-209 2025/12/06 7.47UT TOYOKAWA-FUJI









BLK:10,SNR1: 3.1791 ,SNR2: 4.9122







BLK:10,SNR1: 6.1386 ,SNR2: 14.825








2135-209 2025/12/06 7.47UT TOYOKAWA-KISO










2135-209 2025/12/06 7.47UT FUJI -KISO











2147+145 2025/12/06 7.68UT TOYOKAWA-FUJI
















2147+145 2025/12/06 7.68UT TOYOKAWA-KISO




















BLK: 5,SNR1: 0.47171 ,SNR2: 1.8624







BLK: 5,SNR1: 1.3366 ,SNR2: 5.4227




2203-18 2025/12/06 7.94UT TOYOKAWA-FUJI








2203-18 2025/12/06 7.94UT TOYOKAWA-KISO





F20251206165458




BLK: 3,SNR1: 7.1633 ,SNR2: 15.608




K20251206165456





BLK: 3,SNR1: 1.8290 ,SNR2: 9.0172




2203-18 2025/12/06 7.94UT FUJI -KISO



T20251206170119





BLK: 7, SNR1: 1.3300 , SNR2: 4.8767




Frequency (Hz)

F20251206170119




BLK: 7, SNR1: 4.2130 , SNR2: 9.2444





Frequency (Hz)


2210+016 2025/12/06 8.05UT TOYOKAWA-FUJI



T20251206170119





BLK: 7, SNR1: 5.6557 , SNR2: 10.453




Frequency (Hz)

K20251206170118




BLK: 7, SNR1: 9.5540 , SNR2: 17.033





Frequency (Hz)


2210+016 2025/12/06 8.05UT TOYOKAWA-KISO



F20251206170119





BLK: 4, SNR1: 6.8210 , SNR2: 14.563




Frequency (Hz)

K20251206170118








BLK: 4, SNR1: 10.087 , SNR2: 17.232




Frequency (Hz)





2210+016 2025/12/06 8.05UT FUJI -KISO






3C446 2025/12/06 8.27UT TOYOKAWA-FUJI










3C446 2025/12/06 8.27UT TOYOKAWA-KISO










3C446 2025/12/06 8.27UT FUJI -KISO





T20251206172113




BLK: 3,SNR1: 0.22753 ,SNR2: 3.5437




F20251206172113





BLK: 3,SNR1: 2.5765 ,SNR2: 6.4046




2229-093 2025/12/06 8.38UT TOYOKAWA-FUJI



T20251206172113





BLK: 8, SNR1: 0.74563 , SNR2: 11.869




Frequency (Hz)

K20251206172112




BLK: 8, SNR1: 3.0904 , SNR2: 7.9355




Frequency (Hz)


2229-093 2025/12/06 8.38UT TOYOKAWA-KISO



F20251206172113





BLK: 7, SNR1: -0.31244 , SNR2: 0.80900




Frequency (Hz)

K20251206172112








BLK: 7, SNR1: 2.0295 , SNR2: 9.5285




Frequency (Hz)


2229-093 2025/12/06 8.38UT FUJI -KISO







2238-113 2025/12/06 8.52UT TOYOKAWA-FUJI







BLK: 3,SNR1: 1.1250 ,SNR2: 3.2053




BLK: 3,SNR1: 4.3011 ,SNR2: 10.099





2238-113 2025/12/06 8.52UT TOYOKAWA-KISO







BLK: 4, SNR1: 0.25511 , SNR2: 1.8806








BLK: 4, SNR1: 5.7345 , SNR2: 9.0449





2238-113 2025/12/06 8.52UT FUJI -KISO








T20251206173910




BLK: 2, SNR1: 4.3403 , SNR2: 30.955




Frequency (Hz)

K20251206173909








BLK: 2, SNR1: 0.76699 , SNR2: 4.3659




Frequency (Hz)

2247-232 2025/12/06 8.68UT TOYOKAWA-KISO








2247-232 2025/12/06 8.68UT FUJI -KISO



T20251206174619





BLK: 5, SNR1: 0.60937 , SNR2: 3.1805




Frequency (Hz)

F20251206174620






BLK: 5, SNR1: 8.9978 , SNR2: 15.899



Frequency (Hz)

2254-248 2025/12/06 8.80UT TOYOKAWA-FUJI





2254-248 2025/12/06 8.80UT TOYOKAWA-KISO

