















BLK: 5, SNR1: 1.2472 , SNR2: 3.5403



BLK: 5, SNR1: 7.9282 , SNR2: 22.534




1050-184 2025/12/06 20.68UT TOYOKAWA-KISO







F20251207053909




BLK:13,SNR1: 12.985 ,SNR2: 32.240




K20251207053907




BLK:13,SNR1: 8.5963 ,SNR2: 23.561





1050-184 2025/12/06 20.68UT FUJI -KISO







BLK: 6,SNR1: 7.8222 ,SNR2: 19.812




BLK: 6,SNR1: 2.4214 ,SNR2: 7.6282





1103-208 2025/12/06 20.91UT TOYOKAWA-FUJI







BLK: 7,SNR1: 9.1801 ,SNR2: 26.323








BLK: 7,SNR1: 2.7133 ,SNR2: 5.3283





1103-208 2025/12/06 20.91UT TOYOKAWA-KISO








T20251207055922




BLK: 5, SNR1: 13.550 ,SNR2: 33.013




F20251207055923





BLK: 5, SNR1: 6.5316 ,SNR2: 17.464




1110-217 2025/12/06 21.02UT TOYOKAWA-FUJI





T20251207055922




BLK: 5, SNR1: 7.5143 , SNR2: 22.435




K20251207055921





BLK: 5, SNR1: 9.0528 , SNR2: 26.181




1110-217 2025/12/06 21.02UT TOYOKAWA-KISO




F20251207055923




BLK: 5, SNR1: 11.231 ,SNR2: 29.910




K20251207055921





BLK: 5, SNR1: 18.969 ,SNR2: 47.875




1110-217 2025/12/06 21.02UT FUJI -KISO




T20251207060558




BLK: 8, SNR1: 2.1779 , SNR2: 5.4691




F20251207060559



BLK: 8, SNR1: 2.0950 , SNR2: 4.3473





3C255 2025/12/06 21.13UT TOYOKAWA-FUJI






T20251207060558





BLK:11,SNR1: 7.8133 ,SNR2: 12.256






3C255 2025/12/06 21.13UT TOYOKAWA-KISO

K20251207060557





BLK:11,SNR1: 3.1931 ,SNR2: 9.7964







BLK:11,SNR1: 4.7811 ,SNR2: 10.653




BLK:11,SNR1: 13.701 ,SNR2: 20.510




3C255 2025/12/06 21.13UT FUJI -KISO





T20251207061636




BLK: 5, SNR1: 10.712 , SNR2: 23.115




F20251207061637




BLK: 5, SNR1: 10.076 , SNR2: 22.005




1127-14 2025/12/06 21.30UT TOYOKAWA-FUJI





T20251207061636




BLK: 5, SNR1: 1.3655 , SNR2: 5.7285




K20251207061635





BLK: 5, SNR1: 2.0891 , SNR2: 8.1262




1127-14 2025/12/06 21.30UT TOYOKAWA-KISO





F20251207061637




BLK: 5, SNR1: 8.5466 , SNR2: 24.926




K20251207061635




BLK: 5, SNR1: 7.4186 , SNR2: 22.078




1127-14 2025/12/06 21.30UT FUJI -KISO




T20251207062053




BLK: 9, SNR1: 8.5078 , SNR2: 22.039




F20251207062054








BLK: 9, SNR1: 8.4664 , SNR2: 24.514





1131-171 2025/12/06 21.38UT TOYOKAWA-FUJI






F20251207062054





BLK: 4, SNR1: 9.8036 , SNR2: 24.435




Frequency (Hz)

K20251207062052




BLK: 4, SNR1: 9.5118 , SNR2: 27.992








Frequency (Hz)


1131-171 2025/12/06 21.38UT FUJI -KISO









T20251207062539




BLK:12,SNR1: 0.76044 ,SNR2: 3.7741




K20251207062538




BLK:12,SNR1: 1.2180 ,SNR2: 4.2777





1136-13 2025/12/06 21.46UT TOYOKAWA-KISO







BLK: 9,SNR1: 0.88674E-01,SNR2: 0.77433




BLK: 9,SNR1: 3.8386 ,SNR2: 7.4047




1136-13 2025/12/06 21.46UT FUJI -KISO



T20251207063623





BLK: 9,SNR1: 0.84143 ,SNR2: 7.5337





3C267 2025/12/06 21.63UT TOYOKAWA-FUJI


F20251207063624




BLK: 9,SNR1: 1.4242 ,SNR2: 2.3946



T20251207063623





BLK: 8, SNR1: 1.8511 ,SNR2: 6.6072





3C267 2025/12/06 21.63UT TOYOKAWA-KISO



K20251207063622




BLK: 8, SNR1: 3.1396 ,SNR2: 8.6316





F20251207063624




BLK: 5, SNR1: 2.0964 , SNR2: 6.7809




K20251207063622





BLK: 5, SNR1: 4.7944 , SNR2: 12.852




3C267 2025/12/06 21.63UT FUJI -KISO








1213-17 2025/12/06 22.06UT TOYOKAWA-FUJI





T20251207070211




BLK:14,SNR1: 0.27217 ,SNR2: 1.2238




K20251207070210




BLK:14,SNR1: 2.3227 ,SNR2: 4.5415






1213-17 2025/12/06 22.08UT TOYOKAWA-KISO









BLK: 5, SNR1: 0.66232E-01, SNR2: 5.1848





BLK: 5, SNR1: 1.2645 ,SNR2: 5.8764




1213-17 2025/12/06 22.06UT FUJI -KISO





T20251207071528




BLK:13,SNR1: 1.6947 ,SNR2: 5.2118




F20251207071529





BLK:13,SNR1: 14.269 ,SNR2: 28.245




3C273 2025/12/06 22.29UT TOYOKAWA-FUJI




T20251207071528




BLK:19,SNR1: 1.8288 ,SNR2: 4.4141




K20251207071527




BLK:19,SNR1: 8.2563 ,SNR2: 10.431




3C273 2025/12/06 22.29UT TOYOKAWA-KISO





F20251207071529




BLK:15,SNR1: 16.835 ,SNR2: 32.722




K20251207071527




BLK:15,SNR1: 8.8404 ,SNR2: 16.236




3C273 2025/12/06 22.29UT FUJI -KISO





T20251207072839




BLK:11,SNR1: 11.989 ,SNR2: 29.087




F20251207072840




BLK:11,SNR1: 8.5713 ,SNR2: 21.536




3C275 2025/12/06 22.51UT TOYOKAWA-FUJI





T20251207072839




BLK:11,SNR1: 11.037 ,SNR2: 27.854




K20251207072838





BLK:11,SNR1: 10.055 ,SNR2: 24.764




3C275 2025/12/06 22.51UT TOYOKAWA-KISO





F20251207072840




BLK: 7, SNR1: 15.502 ,SNR2: 37.110




K20251207072838




BLK: 7, SNR1: 7.9885 ,SNR2: 20.565




3C275 2025/12/06 22.51UT FUJI -KISO





T20251207073444




BLK:11,SNR1: 2.1271 ,SNR2: 6.9702




F20251207073445



BLK:11,SNR1: 2.1818 ,SNR2: 7.3099





1245-19 2025/12/06 22.61UT TOYOKAWA-FUJI






T20251207073444





BLK:18,SNR1: 2.0264 ,SNR2: 6.7184





1245-19 2025/12/06 22.61UT TOYOKAWA-KISO



K20251207073443




BLK:18,SNR1: 4.7652 ,SNR2: 8.4744





F20251207073445




BLK:26,SNR1: 2.1134 ,SNR2: 7.0972




K20251207073443





BLK:26,SNR1: 6.3455 ,SNR2: 14.642




1245-19 2025/12/06 22.61UT FUJI -KISO




T20251207074227




BLK:10,SNR1: 11.046 ,SNR2: 26.356




F20251207074228




BLK:10,SNR1: 10.224 ,SNR2: 24.815




3C279 2025/12/06 22.74UT TOYOKAWA-FUJI




T20251207074227




BLK: 8, SNR1: 11.127 , SNR2: 26.530




K20251207074226




BLK: 8, SNR1: 10.058 , SNR2: 24.374




3C279 2025/12/06 22.74UT TOYOKAWA-KISO




F20251207074228




BLK: 7, SNR1: 9.5933 , SNR2: 23.305




K20251207074226





BLK: 7, SNR1: 9.9599 , SNR2: 24.159




3C279 2025/12/06 22.74UT FUJI -KISO



T20251207075757




BLK:25,SNR1: 6.7168 ,SNR2: 11.440





3C283 2025/12/06 22.99UT TOYOKAWA-FUJI



F20251207075758




BLK:25,SNR1: 3.1909 ,SNR2: 6.3990





T20251207075757




BLK:18,SNR1: 0.71301 ,SNR2: 3.0947




K20251207075756




BLK:18,SNR1: 14.991 ,SNR2: 17.818




3C283 2025/12/06 22.99UT TOYOKAWA-KISO




F20251207075758




BLK:22,SNR1: 4.7977 ,SNR2: 11.029




K20251207075756



BLK:22,SNR1: 8.8928 ,SNR2: 20.119





3C283 2025/12/06 22.99UT FUJI -KISO






T20251207081221





BLK:20,SNR1: 5.5700 ,SNR2: 10.439





1323+32 2025/12/06 23.23UT TOYOKAWA-FUJI



F20251207081222




BLK:20,SNR1: 12.062 ,SNR2: 26.408



T20251207081221





BLK:17,SNR1: 1.6229 ,SNR2: 5.7541




Frequency (Hz)

K20251207081220








BLK:17,SNR1: 12.003 ,SNR2: 22.241




Frequency (Hz)

1323+32 2025/12/06 23.23UT TOYOKAWA-KISO








1323+32 2025/12/06 23.23UT FUJI -KISO




T20251207081711




BLK:17,SNR1: 57.715 ,SNR2: 108.62




F20251207081712





BLK:17,SNR1: 41.426 ,SNR2: 78.008




3C286 2025/12/06 23.31UT TOYOKAWA-FUJI





T20251207081711




BLK:15,SNR1: 52.823 ,SNR2: 66.222




K20251207081710




BLK:15,SNR1: 103.99 ,SNR2: 128.72




3C286 2025/12/06 23.31UT TOYOKAWA-KISO




F20251207081712




BLK:16,SNR1: 57.029 ,SNR2: 70.595




K20251207081710





BLK:16,SNR1: 44.532 ,SNR2: 74.860




3C286 2025/12/06 23.31UT FUJI -KISO



T20251207083339





BLK:15,SNR1: 9.8505 ,SNR2: 17.052





1345+12 2025/12/06 23.59UT TOYOKAWA-FUJI



F20251207083340




BLK:15,SNR1: 12.403 ,SNR2: 21.509



T20251207083339





BLK:17,SNR1: 9.2255 ,SNR2: 15.959





1345+12 2025/12/06 23.59UT TOYOKAWA-KISO

K20251207083338




BLK:17,SNR1: 10.580 ,SNR2: 18.789








F20251207083340




BLK:17,SNR1: 15.955 ,SNR2: 27.609




K20251207083338




BLK:17,SNR1: 12.813 ,SNR2: 21.959




1345+12 2025/12/06 23.59UT FUJI -KISO



T20251207084359





BLK: 6, SNR1: 0.38573 , SNR2: 3.7696










1355+01 2025/12/06 23.76UT TOYOKAWA-FUJI






F20251207084359





BLK: 6, SNR1: 0.47328 , SNR2: 2.4594










T20251207085419




BLK: 7, SNR1: 2.4187 , SNR2: 8.0488




F20251207085420













BLK: 7, SNR1: 5.0126 , SNR2: 13.477







1406+240 2025/12/06 23.93UT TOYOKAWA-FUJI















3C298 2025/12/07 0.11UT TOYOKAWA-FUJI









3C298 2025/12/07 0.11UT TOYOKAWA-KISO





F20251207090511




BLK: 5, SNR1: 0.10879 , SNR2: 3.4523




K20251207090509







BLK: 5, SNR1: 0.67865 , SNR2: 1.9893





3C298 2025/12/07 0.11UT FUJI -KISO







1428-03 2025/12/07 0.31UT TOYOKAWA-FUJI







BLK: 6,SNR1: 0.75667E-01,SNR2: 1.4016





BLK: 6,SNR1: 5.9199 ,SNR2: 14.816




1428-03 2025/12/07 0.31UT TOYOKAWA-KISO





F20251207091654




BLK: 6, SNR1: 0.26976 , SNR2: 2.7772




K20251207091652





BLK: 6, SNR1: 2.7428 , SNR2: 8.6060




1428-03 2025/12/07 0.31UT FUJI -KISO




T20251207092535




BLK:12,SNR1: 16.380 ,SNR2: 30.601




F20251207092536





BLK:12,SNR1: 11.060 ,SNR2: 20.920




1436-16 2025/12/07 0.45UT TOYOKAWA-FUJI




T20251207092535




BLK:15,SNR1: 14.045 ,SNR2: 27.820




K20251207092534




BLK:15,SNR1: 18.828 ,SNR2: 42.712




1436-16 2025/12/07 0.45UT TOYOKAWA-KISO




F20251207092536




BLK:13,SNR1: 8.5559 ,SNR2: 25.210




K20251207092534



BLK:13,SNR1: 9.2409 ,SNR2: 25.059




1436-16 2025/12/07 0.45UT FUJI -KISO






T20251207094158




BLK:15,SNR1: 0.40353 ,SNR2: 1.8501









1453-10 2025/12/07 0.73UT TOYOKAWA-FUJI

F20251207094159








BLK:15,SNR1: 118.73 ,SNR2: 116.44










1453-10 2025/12/07 0.73UT TOYOKAWA-KISO










1453-10 2025/12/07 0.73UT FUJI -KISO






1508-05 2025/12/07 0.98UT TOYOKAWA-FUJI








1508-05 2025/12/07 0.98UT TOYOKAWA-KISO





F20251207095651




BLK: 1, SNR1: 0.71597 , SNR2: 10.229




K20251207095649












BLK: 1, SNR1: 8.5537 , SNR2: 21.172




1508-05 2025/12/07 0.98UT FUJI -KISO












3C318 2025/12/07 1.13UT TOYOKAWA-KISO











3C318 2025/12/07 1.13UT FUJI -KISO







BLK: 1,SNR1: 0.46827 ,SNR2: 1.1883








BLK: 1,SNR1: 0.29247 ,SNR2: 1.6449





1523+03 2025/12/07 1.22UT TOYOKAWA-FUJI








F20251207101138




BLK: 1,SNR1: 0.29249 ,SNR2: 1.6450




K20251207101136




BLK: 1,SNR1: 0.50079 ,SNR2: 2.6322





1523+03 2025/12/07 1.22UT FUJI -KISO







BLK: 8,SNR1: 0.42610 ,SNR2: 1.3270




BLK: 8,SNR1: 1.1985 ,SNR2: 3.9305





1535+139 2025/12/07 1.42UT TOYOKAWA-FUJI







BLK:16,SNR1: 0.34398 ,SNR2: 0.97336





BLK:16,SNR1: 4.4223 ,SNR2: 7.7046




1535+139 2025/12/07 1.42UT TOYOKAWA-KISO




F20251207102317




BLK:16,SNR1: 2.6195 ,SNR2: 3.1121




K20251207102315





BLK:16,SNR1: 2.6526 ,SNR2: 6.6744




1535+139 2025/12/07 1.42UT FUJI -KISO



T20251207103622




BLK:15,SNR1: 0.19432 ,SNR2: 2.3146





1548+05 2025/12/07 1.63UT TOYOKAWA-FUJI

F20251207103623




BLK:15,SNR1: 72.698 ,SNR2: 70.960







T20251207103622




BLK: 5, SNR1: 0.80843 , SNR2: 3.1360




K20251207103621





BLK: 5, SNR1: 3.6728 , SNR2: 11.911




1548+05 2025/12/07 1.63UT TOYOKAWA-KISO



F20251207103623





BLK:14,SNR1: 6.7395 ,SNR2: 26.625





1548+05 2025/12/07 1.63UT FUJI -KISO



K20251207103621




BLK:14,SNR1: 1.5896 ,SNR2: 6.8167





T20251207105443




BLK: 1,SNR1: 0.13637 ,SNR2: 1.3854




F20251207105444





BLK: 1,SNR1: 2.8148 ,SNR2: 7.5385




1607+26 2025/12/07 1.94UT TOYOKAWA-FUJI



T20251207105443





BLK: 1,SNR1: 17.028 ,SNR2: 30.403




Frequency (Hz)

K20251207105442




BLK: 1,SNR1: 11.594 ,SNR2: 21.613





Frequency (Hz)


1607+26 2025/12/07 1.94UT TOYOKAWA-KISO





F20251207105444




BLK: 3,SNR1: 9.7924 ,SNR2: 17.594




K20251207105442





BLK: 3,SNR1: 10.412 ,SNR2: 18.497




1607+26 2025/12/07 1.94UT FUJI -KISO



T20251207110948





BLK: 4,SNR1: 0.23130 ,SNR2: 0.93868




Frequency (Hz)

F20251207110949




BLK: 4,SNR1: 1.4362 ,SNR2: 15.924





Frequency (Hz)


1621-11 2025/12/07 2.19UT TOYOKAWA-FUJI




T20251207110948




BLK: 6,SNR1: 0.18577 ,SNR2: 0.50394




K20251207110947





BLK: 6,SNR1: 5.1498 ,SNR2: 7.9279




1621-11 2025/12/07 2.19UT TOYOKAWA-KISO




F20251207110949




BLK: 2, SNR1: -0.85278E-02, SNR2: 2.4052




K20251207110947








BLK: 2, SNR1: 15.438, SNR2: 32.933









1621-11 2025/12/07 2.19UT FUJI -KISO















BLK:22,SNR1: 8.1421 ,SNR2: 7.9580




BLK:22,SNR1: 18.105 ,SNR2: 38.098




1631-222 2025/12/07 2.37UT FUJI -KISO




T20251207112622




BLK: 4,SNR1: 15.612 ,SNR2: 31.110




F20251207112623




BLK: 4,SNR1: 16.869 ,SNR2: 35.755




1638-025 2025/12/07 2.47UT TOYOKAWA-FUJI




T20251207112622




BLK: 6,SNR1: 20.410 ,SNR2: 35.465




K20251207112621




BLK: 6,SNR1: 20.093 ,SNR2: 34.394




1638-025 2025/12/07 2.47UT TOYOKAWA-KISO




F20251207112623




BLK: 2,SNR1: 17.666 ,SNR2: 31.245




K20251207112621





BLK: 2,SNR1: 29.211 ,SNR2: 51.548




1638-025 2025/12/07 2.47UT FUJI -KISO




T20251207113316




BLK:12,SNR1: 1.2363 ,SNR2: 3.0401




F20251207113317




BLK:12,SNR1: 110.28 ,SNR2: 108.16





1644-106 2025/12/07 2.58UT TOYOKAWA-FUJI







BLK:10,SNR1: 0.83194 ,SNR2: 3.7093



BLK:10,SNR1: 1.1345 ,SNR2: 3.9524





1644-106 2025/12/07 2.58UT TOYOKAWA-KISO






F20251207113317





BLK:13,SNR1: 73.588 ,SNR2: 72.877




Frequency (Hz)

K20251207113315




BLK:13,SNR1: 2.1582 ,SNR2: 3.3198





Frequency (Hz)


1644-106 2025/12/07 2.58UT FUJI -KISO





T20251207113837




BLK: 3,SNR1: 8.8305 ,SNR2: 22.041




F20251207113838




BLK: 3,SNR1: 15.704 ,SNR2: 37.675




1650+004 2025/12/07 2.67UT TOYOKAWA-FUJI




T20251207113837




BLK: 5, SNR1: 9.5471 , SNR2: 23.552




K20251207113836




BLK: 5, SNR1: 10.395 , SNR2: 25.502




1650+004 2025/12/07 2.67UT TOYOKAWA-KISO




F20251207113838




BLK: 3,SNR1: 9.1735 ,SNR2: 22.069




K20251207113836





BLK: 3,SNR1: 7.9784 ,SNR2: 20.022




1650+004 2025/12/07 2.67UT FUJI -KISO




T20251207114408




BLK:10,SNR1: 0.51487 ,SNR2: 2.4848




F20251207114409




BLK:10,SNR1: 1.0438 ,SNR2: 4.5191




1656+053 2025/12/07 2.76UT TOYOKAWA-FUJI





T20251207114408




BLK:10,SNR1: 0.42732 ,SNR2: 2.2055




K20251207114407




BLK:10,SNR1: 3.9646 ,SNR2: 9.9983




1656+053 2025/12/07 2.76UT TOYOKAWA-KISO




F20251207114409




BLK: 6,SNR1: 0.81569 ,SNR2: 4.7194




K20251207114407




BLK: 6,SNR1: 5.3608 ,SNR2: 13.398





1656+053 2025/12/07 2.76UT FUJI -KISO







BLK: 7,SNR1: 21.334 ,SNR2: 51.601




BLK: 7,SNR1: 10.129 ,SNR2: 25.015





1712-033 2025/12/07 3.04UT TOYOKAWA-FUJI









BLK: 2,SNR1: 7.7343 ,SNR2: 19.434




BLK: 2,SNR1: 13.037 ,SNR2: 31.894





1712-033 2025/12/07 3.04UT TOYOKAWA-KISO







BLK: 3,SNR1: 24.202 ,SNR2: 43.095




BLK: 3,SNR1: 14.762 ,SNR2: 35.968





1712-033 2025/12/07 3.04UT FUJI -KISO







BLK: 9,SNR1: 0.79961 ,SNR2: 3.2220




BLK: 9,SNR1: -0.19416E-01,SNR2: 1.0698





1730-13 2025/12/07 3.34UT TOYOKAWA-FUJI







BLK:20,SNR1: 0.92113 ,SNR2: 3.6668




BLK:20,SNR1: 2.6101 ,SNR2: 5.1439




1730-13 2025/12/07 3.34UT TOYOKAWA-KISO





F20251207121842




BLK:11,SNR1:-0.32055E-01,SNR2: 1.2567




K20251207121840





BLK:11,SNR1: 1.0724 ,SNR2: 3.2522




1730-13 2025/12/07 3.34UT FUJI -KISO




T20251207123605




BLK: 1,SNR1: 23.908 ,SNR2: 42.370




F20251207123606





BLK: 1,SNR1: 31.664 ,SNR2: 54.236




1748+031 2025/12/07 3.63UT TOYOKAWA-FUJI





T20251207123605




BLK: 6,SNR1: 59.112 ,SNR2: 112.47




K20251207123604





BLK: 6,SNR1: 49.740 ,SNR2: 53.155




1748+031 2025/12/07 3.63UT TOYOKAWA-KISO





F20251207123606




BLK: 8,SNR1: 83.733 ,SNR2: 90.439




K20251207123604



BLK: 8,SNR1: 10.880 ,SNR2: 28.015





1748+031 2025/12/07 3.63UT FUJI -KISO








T20251207124658




No.Good Data




F20251207124659




No.Good Data




1759+13 2025/12/07 3.81UT TOYOKAWA-FUJI




T20251207124658




BLK: 2,SNR1: 12.389 ,SNR2: 30.264




K20251207124657




BLK: 2,SNR1: 2.3004 ,SNR2: 10.880





1759+13 2025/12/07 3.81UT TOYOKAWA-KISO







BLK: 6,SNR1: 20.138 ,SNR2: 36.071




BLK: 6,SNR1: 16.580 ,SNR2: 29.413




1759+13 2025/12/07 3.81UT FUJI -KISO




T20251207130759




No.Good Data




F20251207130800




No.Good Data





1819-096 2025/12/07 4.16UT TOYOKAWA-FUJI







BLK: 1,SNR1: 10.241 ,SNR2: 22.728




BLK: 1,SNR1: 10.445 ,SNR2: 26.573





1819-096 2025/12/07 4.16UT TOYOKAWA-KISO







BLK: 1,SNR1: 8.4016 ,SNR2: 16.070




BLK: 1,SNR1: 8.4291 ,SNR2: 21.868




1819-096 2025/12/07 4.16UT FUJI -KISO




T20251207131619




BLK: 6,SNR1: 9.6278 ,SNR2: 23.638




F20251207131620





BLK: 6,SNR1: 16.055 ,SNR2: 37.391




1829+29 2025/12/07 4.30UT TOYOKAWA-FUJI



T20251207131619





No.Good Data




Frequency (Hz)

K20251207131618




No.Good Data




Frequency (Hz)

1829+29 2025/12/07 4.30UT TOYOKAWA-KISO






F20251207131620





BLK: 4,SNR1: 16.374 ,SNR2: 34.525




Frequency (Hz)

K20251207131618




BLK: 4,SNR1: 9.9849 ,SNR2: 24.492





Frequency (Hz)


1829+29 2025/12/07 4.30UT FUJI -KISO




T20251207132242




No. Good Data




F20251207132243





No. Good Data




1835+134 2025/12/07 4.41UT TOYOKAWA-FUJI





T20251207132242




No.Good Data




K20251207132241





No.Good Data




1835+134 2025/12/07 4.41UT TOYOKAWA-KISO



F20251207132243





BLK: 3,SNR1: 8.3827 ,SNR2: 20.962




Frequency (Hz)

K20251207132241




BLK: 3,SNR1: 5.6566 ,SNR2: 14.511




Frequency (Hz)


1835+134 2025/12/07 4.41UT FUJI -KISO




T20251207134538




BLK: 1,SNR1: 4.1646 ,SNR2: 13.010




F20251207134539




BLK: 1,SNR1: 8.4322 ,SNR2: 18.172




1858+171 2025/12/07 4.79UT TOYOKAWA-FUJI



T20251207134538




BLK: 3,SNR1: 4.9203 ,SNR2: 13.212




Frequency (Hz)

K20251207134537




BLK: 3,SNR1: 16.434 ,SNR2: 35.592





Frequency (Hz)


1858+171 2025/12/07 4.79UT TOYOKAWA-KISO



F20251207134539





No. Good Data




Frequency (Hz)

K20251207134537




No. Good Data




Frequency (Hz)


1858+171 2025/12/07 4.79UT FUJI -KISO





T20251207135624




BLK: 2,SNR1: 3.3837 ,SNR2: 8.7840




F20251207135625



BLK: 2,SNR1: 19.937 ,SNR2: 47.080




1908-20 2025/12/07 4.97UT TOYOKAWA-FUJI







T20251207135624




BLK: 5,SNR1: 4.4076 ,SNR2: 8.3702




K20251207135623




BLK: 5,SNR1: 13.136 ,SNR2: 30.985





1908-20 2025/12/07 4.97UT TOYOKAWA-KISO







BLK: 7,SNR1: 8.5939 ,SNR2: 21.605





BLK: 7,SNR1: 12.954 ,SNR2: 30.545




1908-20 2025/12/07 4.97UT FUJI -KISO





T20251207140314




BLK: 3,SNR1: 0.89767E-01,SNR2: 0.36807




F20251207140315





BLK: 3,SNR1:-0.28700,SNR2: 0.41973




1915-121 2025/12/07 5.08UT TOYOKAWA-FUJI





T20251207140314




BLK: 3,SNR1: 0.11437 ,SNR2: 0.55726




K20251207140313




BLK: 3,SNR1: 0.85586 ,SNR2: 2.8873




1915-121 2025/12/07 5.08UT TOYOKAWA-KISO





F20251207140315




BLK: 4,SNR1:-0.27096E-01,SNR2: 2.1975




K20251207140313




BLK: 4,SNR1: 1.0937 ,SNR2: 5.5409





1915-121 2025/12/07 5.08UT FUJI -KISO







BLK: 1,SNR1: 0.36200 ,SNR2: 2.0434







BLK: 1,SNR1:-0.51600E-02,SNR2: 4.2117




1928-142 2025/12/07 5.31UT TOYOKAWA-FUJI








1928-142 2025/12/07 5.31UT TOYOKAWA-KISO





F20251207141657




BLK: 3,SNR1: 5.3669 ,SNR2: 10.248




K20251207141655




BLK: 3,SNR1: 18.330 ,SNR2: 32.631





1928-142 2025/12/07 5.31UT FUJI -KISO









BLK: 7,SNR1: 75.680 ,SNR2: 98.508




BLK: 7,SNR1: 78.542 ,SNR2: 78.157





1938-15 2025/12/07 5.47UT TOYOKAWA-FUJI







BLK: 8,SNR1: 74.267 ,SNR2: 97.287





BLK: 8,SNR1: 27.085 ,SNR2: 57.405




1938-15 2025/12/07 5.47UT TOYOKAWA-KISO





F20251207142636




BLK: 3,SNR1: 69.379 ,SNR2: 71.482




K20251207142634




BLK: 3,SNR1: 21.832 ,SNR2: 46.274






1938-15 2025/12/07 5.47UT FUJI -KISO




T20251207150130




F20251207150131






2014+358 2025/12/07 6.05UT TOYOKAWA-FUJI




T20251207150130





K20251207150129




2014+358 2025/12/07 6.05UT TOYOKAWA-KISO





F20251207150131




BLK: 4,SNR1: 10.247 ,SNR2: 25.264




K20251207150129





BLK: 4,SNR1: 7.7368 ,SNR2: 19.070




2014+358 2025/12/07 6.05UT FUJI -KISO



T20251207153207





No.Good Data




Frequency (Hz)

F20251207153207




No.Good Data





Frequency (Hz)


3C422 2025/12/07 6.56UT TOYOKAWA-FUJI



T20251207153207





No.Good Data




Frequency (Hz)

K20251207153206




No.Good Data




Frequency (Hz)



3C422 2025/12/07 6.56UT TOYOKAWA-KISO











BLK: 4, SNR1: 6.0311 , SNR2: 11.599




BLK: 4, SNR1: 8.3543 , SNR2: 20.848








2105-072 2025/12/07 6.91UT TOYOKAWA-FUJI




T20251207155245




BLK: 1,SNR1: 104.23 ,SNR2: 184.30




K20251207155244










BLK: 1,SNR1: 10.471 ,SNR2: 25.907




2105-072 2025/12/07 6.91UT TOYOKAWA-KISO












2121-014 2025/12/07 7.17UT TOYOKAWA-FUJI







2121-014 2025/12/07 7.17UT TOYOKAWA-KISO



F20251207160834





BLK: 4, SNR1: 3.5182 , SNR2: 12.085




Frequency (Hz)

K20251207160832








BLK: 4, SNR1: 5.4321 , SNR2: 15.697




Frequency (Hz)

2121-014 2025/12/07 7.17UT FUJI -KISO










2135-209 2025/12/07 7.41UT TOYOKAWA-FUJI









2135-209 2025/12/07 7.41UT TOYOKAWA-KISO



F20251207162249





BLK: 5, SNR1: 7.0148 , SNR2: 9.2210




Frequency (Hz)

K20251207162248




BLK: 5, SNR1: 11.648 , SNR2: 24.625





Frequency (Hz)



2135-209 2025/12/07 7.41UT FUJI -KISO




T20251207163508




F20251207163508




2147+145 2025/12/07 7.61UT TOYOKAWA-FUJI




T20251207163508




BLK: 1, SNR1: 11.674 , SNR2: 19.891




K20251207163507





BLK: 1, SNR1: 9.9568 , SNR2: 25.683




2147+145 2025/12/07 7.61UT TOYOKAWA-KISO



F20251207163508




BLK: 2, SNR1: 44.376 , SNR2: 59.320




Frequency (Hz)

K20251207163507




BLK: 2, SNR1: 11.809 , SNR2: 25.953





Frequency (Hz)


2147+145 2025/12/07 7.61UT FUJI -KISO



T20251207164413





BLK: 7, SNR1: 2.3256 , SNR2: 5.9364




Frequency (Hz)

F20251207164413




BLK: 7, SNR1: 2.2364 , SNR2: 10.433





Frequency (Hz)


2156-043 2025/12/07 7.77UT TOYOKAWA-FUJI





T20251207164413




BLK: 3, SNR1: 1.3137 , SNR2: 2.7408




K20251207164412





BLK: 3, SNR1: 4.1720 , SNR2: 10.790




2156-043 2025/12/07 7.77UT TOYOKAWA-KISO



F20251207164413





BLK: 9, SNR1: 2.6818 , SNR2: 7.0813




Frequency (Hz)

K20251207164412




BLK: 9, SNR1: 9.6055 , SNR2: 17.823





Frequency (Hz)

2156-043 2025/12/07 7.77UT FUJI -KISO







T20251207165101




BLK: 4, SNR1: 0.15622 , SNR2: 1.2664




F20251207165102




BLK: 4, SNR1: 0.58617 , SNR2: 3.3406





2203-18 2025/12/07 7.88UT TOYOKAWA-FUJI







BLK: 5,SNR1: 0.81927E-01,SNR2: 1.4893




BLK: 5,SNR1: 4.8562 ,SNR2: 13.408





2203-18 2025/12/07 7.88UT TOYOKAWA-KISO







BLK: 4, SNR1: 1.0070 , SNR2: 2.6700




BLK: 4, SNR1: 3.8330 , SNR2: 14.685




2203-18 2025/12/07 7.88UT FUJI -KISO



T20251207165723





BLK: 3, SNR1: 8.5460 , SNR2: 15.096




Frequency (Hz)

F20251207165724




BLK: 3, SNR1: 2.1188 , SNR2: 11.887




Frequency (Hz)


2210+016 2025/12/07 7.98UT TOYOKAWA-FUJI



T20251207165723





BLK: 2, SNR1: 2.4415 , SNR2: 5.2151




Frequency (Hz)

K20251207165722








BLK: 2, SNR1: 13.302 , SNR2: 23.931




Frequency (Hz)


2210+016 2025/12/07 7.98UT TOYOKAWA-KISO







2210+016 2025/12/07 7.98UT FUJI -KISO







BLK: 3, SNR1: 1.0278 , SNR2: 6.7264




BLK: 3, SNR1: 10.222 , SNR2: 16.758





3C446 2025/12/07 8.20UT TOYOKAWA-FUJI







BLK: 3, SNR1: 1.4763 , SNR2: 4.2462








BLK: 3, SNR1: 1.8184 , SNR2: 9.8304




3C446 2025/12/07 8.20UT TOYOKAWA-KISO













BLK: 4,SNR1: 0.19839 ,SNR2: 1.8715




BLK: 4,SNR1: 9.8574 ,SNR2: 23.795





2229-093 2025/12/07 8.32UT TOYOKAWA-FUJI







BLK: 2, SNR1: 0.14521 , SNR2: 1.2374





BLK: 2, SNR1: 19.120 , SNR2: 33.942




2229-093 2025/12/07 8.32UT TOYOKAWA-KISO



F20251207171718





BLK: 1, SNR1: 5.1987 , SNR2: 13.300




Frequency (Hz)

K20251207171716




BLK: 1, SNR1: 15.852 , SNR2: 34.431





Frequency (Hz)


2229-093 2025/12/07 8.32UT FUJI -KISO




T20251207172544




BLK: 2,SNR1: 0.25973 ,SNR2: 1.5907




F20251207172544







BLK: 2,SNR1: 0.65180E-01,SNR2: 1.0963









2238-113 2025/12/07 8.46UT TOYOKAWA-FUJI






2238-113 2025/12/07 8.46UT TOYOKAWA-KISO






T20251207173101





BLK: 3, SNR1: 16.915 , SNR2: 30.103




Frequency (Hz)

F20251207173102




BLK: 3, SNR1: 23.800 , SNR2: 30.819







Frequency (Hz)


2243-123 2025/12/07 8.55UT TOYOKAWA-FUJI












2243-123 2025/12/07 8.55UT TOYOKAWA-KISO







2243-123 2025/12/07 8.55UT FUJI -KISO



T20251207174223




BLK: 7, SNR1: 14.222 , SNR2: 25.571




Frequency (Hz)

F20251207174223






BLK: 7, SNR1: 22.669 , SNR2: 52.391



Frequency (Hz)

2254-248 2025/12/07 8.73UT TOYOKAWA-FUJI





2254-248 2025/12/07 8.73UT TOYOKAWA-KISO

