






T20260706060135




BLK: 1, SNR1: 7.7809 , SNR2: 20.035




F20260706060135





BLK: 1, SNR1: 1.3579 , SNR2: 5.6992




0103+422 2026/07/05 21.05UT TOYOKAWA-FUJI





T20260706060135




BLK: 1, SNR1: 1.5424 , SNR2: 12.131




K20260706060132



BLK: 1, SNR1: 5.2045 , SNR2: 26.386





0103+422 2026/07/05 21.05UT TOYOKAWA-KISO








F20260706060135




No.Good Data




K20260706060132




No.Good Data





0103+422 2026/07/05 21.05UT FUJI -KISO







BLK:20,SNR1: 4.3436 ,SNR2: 5.6640




BLK:20,SNR1: 6.3458 ,SNR2: 11.767





0116+31 2026/07/05 21.27UT TOYOKAWA-FUJI







BLK:22,SNR1: 6.0178 ,SNR2: 13.721









BLK:22,SNR1: 5.5194 ,SNR2: 13.365




0116+31 2026/07/05 21.27UT TOYOKAWA-KISO








0116+31 2026/07/05 21.27UT FUJI -KISO



T20260706063229





BLK: 7,SNR1: 2.9692 ,SNR2: 9.1430






3C48 2026/07/05 21.57UT TOYOKAWA-FUJI

F20260706063229





BLK: 7,SNR1: 3.4496 ,SNR2: 10.410







BLK: 9,SNR1: 10.767 ,SNR2: 22.805




BLK: 9,SNR1: 6.8941 ,SNR2: 16.284





3C48 2026/07/05 21.57UT TOYOKAWA-KISO







BLK: 2,SNR1: 1.2756 ,SNR2: 4.1252




BLK: 2,SNR1: 6.9017 ,SNR2: 10.781




3C48 2026/07/05 21.57UT FUJI -KISO




T20260706064612




BLK: 3, SNR1: 2.2764 , SNR2: 6.8986




F20260706064612



BLK: 3, SNR1: 8.0204 , SNR2: 18.374





0148+274 2026/07/05 21.80UT TOYOKAWA-FUJI






T20260706064612





BLK: 1, SNR1: 2.0328 , SNR2: 6.1256




Frequency (Hz)

K20260706064609




BLK: 1, SNR1: 7.2396 , SNR2: 21.027





Frequency (Hz)


0148+274 2026/07/05 21.80UT TOYOKAWA-KISO



F20260706064612





BLK: 6, SNR1: 7.5063 , SNR2: 18.706




Frequency (Hz)

K20260706064609




BLK: 6, SNR1: 8.2932 , SNR2: 20.747





Frequency (Hz)


0148+274 2026/07/05 21.80UT FUJI -KISO



T20260706065920





BLK: 1, SNR1: 12.218 , SNR2: 29.857




Frequency (Hz)

F20260706065920




BLK: 1, SNR1: 20.105 , SNR2: 35.390





Frequency (Hz)


0202+15 2026/07/05 22.02UT TOYOKAWA-FUJI



T20260706065920





BLK: 1, SNR1: 2.1438 , SNR2: 10.242




Frequency (Hz)

K20260706065917




BLK: 1, SNR1: 2.5308 , SNR2: 11.523





Frequency (Hz)


0202+15 2026/07/05 22.02UT TOYOKAWA-KISO



F20260706065920





BLK: 1, SNR1: 6.5899 , SNR2: 17.105




Frequency (Hz)

K20260706065917







BLK: 1, SNR1: 7.7008 , SNR2: 19.760




Frequency (Hz)



0202+15 2026/07/05 22.02UT FUJI -KISO









BLK: 2,SNR1: 11.744 ,SNR2: 28.727





BLK: 2,SNR1: 9.0721 ,SNR2: 22.366




0213+178 2026/07/05 22.21UT TOYOKAWA-KISO





F20260706071110




No.Good Data




K20260706071108



No.Good Data




0213+178 2026/07/05 22.21UT FUJI -KISO






T20260706071853





BLK: 1,SNR1: 0.81500 ,SNR2: 4.8103




3C67

2026/07/05 22.34UT TOYOKAWA-FUJI


F20260706071853





BLK: 1,SNR1: 35.879 ,SNR2: 53.290




Frequency (Hz)





T20260706071853




No.Good Data




K20260706071850





No.Good Data




3C67 2026/07/05 22.34UT TOYOKAWA-KISO



F20260706071853





No.Good Data




Frequency (Hz)

K20260706071850




No.Good Data





Frequency (Hz)


3C67 2026/07/05 22.34UT FUJI -KISO





T20260706073707




BLK: 5,SNR1: 0.12373 ,SNR2: 1.7484




F20260706073707






BLK: 5,SNR1: 0.28408 ,SNR2: 1.5118





3C71 2026/07/05 22.65UT TOYOKAWA-FUJI








F20260706073707




BLK:16,SNR1: 0.33389 ,SNR2: 1.4677




K20260706073704




BLK:16,SNR1: 1.8303 ,SNR2: 3.2823




3C71 2026/07/05 22.65UT FUJI -KISO




T20260706075623




BLK:23,SNR1: 6.5043 ,SNR2: 15.602




F20260706075623




BLK:23,SNR1: 6.7504 ,SNR2: 16.573




0258+350 2026/07/05 22.97UT TOYOKAWA-FUJI





T20260706075623




BLK:23,SNR1: 6.5063 ,SNR2: 17.820




K20260706075621



BLK:23,SNR1: 9.3945 ,SNR2: 17.080





0258+350 2026/07/05 22.97UT TOYOKAWA-KISO








F20260706075623




BLK:19,SNR1: 11.699 ,SNR2: 20.726




K20260706075621




BLK:19,SNR1: 10.179 ,SNR2: 23.989





0258+350 2026/07/05 22.97UT FUJI -KISO







BLK:14,SNR1: 7.7406 ,SNR2: 19.153







BLK:14,SNR1: 13.073 ,SNR2: 22.107




0308+305 2026/07/05 23.13UT TOYOKAWA-FUJI








0308+305 2026/07/05 23.13UT TOYOKAWA-KISO





F20260706080613




BLK:14,SNR1: 15.960 ,SNR2: 28.192




K20260706080610





BLK:14,SNR1: 9.9496 ,SNR2: 24.812




0308+305 2026/07/05 23.13UT FUJI -KISO



T20260706081743





No.Good Data




Frequency (Hz)

F20260706081743




No.Good Data





Frequency (Hz)


0320+05 2026/07/05 23.32UT TOYOKAWA-FUJI



T20260706081743





No.Good Data




Frequency (Hz)

K20260706081740




No.Good Data





Frequency (Hz)


0320+05 2026/07/05 23.32UT TOYOKAWA-KISO





F20260706081743




No.Good Data




K20260706081740




No.Good Data




0320+05 2026/07/05 23.32UT FUJI -KISO




T20260706083106




BLK: 3,SNR1: 0.85754E-01,SNR2: 2.5169




F20260706083106



BLK: 3,SNR1: 7.1815 ,SNR2: 17.146





0333+32 2026/07/05 23.55UT TOYOKAWA-FUJI






T20260706083106




BLK: 4, SNR1: 2.1137 , SNR2: 8.5599





0333+32 2026/07/05 23.55UT TOYOKAWA-KISO


K20260706083103




BLK: 4, SNR1: 3.5283 , SNR2: 16.432





F20260706083106




BLK: 4, SNR1: 13.038 , SNR2: 17.203




K20260706083103




BLK: 4, SNR1: 7.5714 , SNR2: 13.333




0333+32 2026/07/05 23.55UT FUJI -KISO



T20260706084406




BLK: 1,SNR1: 0.68028E-01,SNR2: 0.98158





0347+05 2026/07/05 23.76UT TOYOKAWA-FUJI



F20260706084406




BLK: 1,SNR1: 0.22173 ,SNR2: 5.6336



T20260706084406





No. Good Data




Frequency (Hz)

K20260706084403




No. Good Data





Frequency (Hz)


0347+05 2026/07/05 23.76UT TOYOKAWA-KISO





F20260706084406




No.Good Data




K20260706084403







No.Good Data








0347+05 2026/07/05 23.76UT FUJI -KISO






0411+05 2026/07/06 0.18UT TOYOKAWA-FUJI








0411+05 2026/07/06 0.18UT TOYOKAWA-KISO




F20260706090851




BLK: 1, SNR1: 26.613 , SNR2: 47.580




K20260706090848



BLK: 1, SNR1: 19.386 , SNR2: 45.383





0411+05 2026/07/06 0.18UT FUJI -KISO







T20260706091546




BLK: 3, SNR1: 2.9670 , SNR2: 9.2586




F20260706091546





BLK: 3, SNR1: 4.8886 , SNR2: 10.717




0418+236 2026/07/06 0.29UT TOYOKAWA-FUJI





T20260706091546




BLK: 1,SNR1: 0.45241 ,SNR2: 3.0100




K20260706091543




BLK: 1,SNR1: 1.3891 ,SNR2: 11.218




0418+236 2026/07/06 0.29UT TOYOKAWA-KISO




F20260706091546




BLK: 5,SNR1: 0.14893 ,SNR2: 2.4773




K20260706091543







BLK: 5,SNR1: 0.33687E-01,SNR2: 0.71505




0418+236 2026/07/06 0.29UT FUJI -KISO








3C119 2026/07/06 0.48UT TOYOKAWA-FUJI





T20260706092715




BLK:19,SNR1: 9.0809 ,SNR2: 16.230




K20260706092712







BLK:19,SNR1: 8.3085 ,SNR2: 21.516




3C119 2026/07/06 0.48UT TOYOKAWA-KISO








3C119 2026/07/06 0.48UT FUJI -KISO




T20260706101521




BLK:24,SNR1: 4.0511 ,SNR2: 15.119




F20260706101521




BLK:24,SNR1: 0.64929 ,SNR2: 2.4896




3C138 2026/07/06 1.28UT TOYOKAWA-FUJI





T20260706101521




BLK:28,SNR1: 3.5977 ,SNR2: 12.943




K20260706101518



BLK:28,SNR1: 4.1324 ,SNR2: 6.6693





3C138 2026/07/06 1.28UT TOYOKAWA-KISO








F20260706101521




BLK:18,SNR1: 0.80928 ,SNR2: 3.0265




K20260706101518




BLK:18,SNR1: 0.81090 ,SNR2: 5.0978




3C138 2026/07/06 1.28UT FUJI -KISO




T20260706102854




BLK: 8,SNR1: 1.6669 ,SNR2: 4.8232




F20260706102854







BLK: 8,SNR1: 8.5567 ,SNR2: 14.827




0531+194 2026/07/06 1.51UT TOYOKAWA-FUJI







0531+194 2026/07/06 1.51UT TOYOKAWA-KISO





F20260706102854




BLK: 2, SNR1: 7.0428 , SNR2: 11.039




K20260706102851





BLK: 2, SNR1: 9.7515 , SNR2: 22.809




0531+194 2026/07/06 1.51UT FUJI -KISO




T20260706103716




BLK:21,SNR1: 46.244 ,SNR2: 110.45




F20260706103716





BLK:21,SNR1: 3.7998 ,SNR2: 9.4100




3C147 2026/07/06 1.65UT TOYOKAWA-FUJI





T20260706103716




BLK:30,SNR1: 44.815 ,SNR2: 168.51




K20260706103713




BLK:30,SNR1: 8.2808 ,SNR2: 31.438




3C147 2026/07/06 1.65UT TOYOKAWA-KISO





F20260706103716




BLK:32,SNR1: 4.9238 ,SNR2: 8.7624




K20260706103713




BLK:32,SNR1: 7.8916 ,SNR2: 30.013




3C147 2026/07/06 1.65UT FUJI -KISO




T20260706104525




BLK: 5, SNR1: 8.4629 , SNR2: 20.863




F20260706104525



BLK: 5, SNR1: 7.8022 , SNR2: 19.705




0548+16 2026/07/06 1.79UT TOYOKAWA-FUJI







T20260706104525




BLK: 3, SNR1: 12.465 ,SNR2: 23.183




K20260706104522




BLK: 3, SNR1: 8.5467 ,SNR2: 15.957




0548+16 2026/07/06 1.79UT TOYOKAWA-KISO




F20260706104525




BLK: 7, SNR1: 10.712 , SNR2: 19.917




K20260706104522




BLK: 7, SNR1: 6.8397 , SNR2: 20.230




0548+16 2026/07/06 1.79UT FUJI -KISO





T20260706104936




BLK: 5, SNR1: 69.223 , SNR2: 149.61




F20260706104936




BLK: 5, SNR1: 7.3292 , SNR2: 16.545





0552+12 2026/07/06 1.85UT TOYOKAWA-FUJI







BLK: 7, SNR1: 35.413 , SNR2: 79.915





BLK: 7, SNR1: 17.237 , SNR2: 37.683




0552+12 2026/07/06 1.85UT TOYOKAWA-KISO





F20260706104936




BLK: 2,SNR1: 4.6102 ,SNR2: 10.654




K20260706104933





BLK: 2,SNR1: 4.5297 ,SNR2: 7.8894




0552+12 2026/07/06 1.85UT FUJI -KISO





T20260706105403




BLK: 4, SNR1: 22.290 , SNR2: 53.518




F20260706105403





BLK: 4, SNR1: 9.3671 , SNR2: 16.551




0556+191 2026/07/06 1.93UT TOYOKAWA-FUJI





T20260706105403




BLK: 2,SNR1: 9.5532 ,SNR2: 17.132




K20260706105400





BLK: 2,SNR1: 9.0424 ,SNR2: 22.269




0556+191 2026/07/06 1.93UT TOYOKAWA-KISO




F20260706105403




No. Good Data




K20260706105400



No. Good Data





0556+191 2026/07/06 1.93UT FUJI -KISO








T20260706110147




BLK: 3,SNR1: 0.29277 ,SNR2: 0.96228




F20260706110147




BLK: 3,SNR1: 0.68027E-01,SNR2: 0.48044




0605-08 2026/07/06 2.06UT TOYOKAWA-FUJI





T20260706110147




BLK: 4,SNR1: 0.24517 ,SNR2: 1.1323




K20260706110144




BLK: 4,SNR1: 0.44692 ,SNR2: 2.5875




0605-08 2026/07/06 2.06UT TOYOKAWA-KISO





F20260706110147




BLK: 3,SNR1:-0.48516E-01,SNR2: 0.0000




K20260706110144





BLK: 3,SNR1: 0.62521 ,SNR2: 2.2797




0605-08 2026/07/06 2.06UT FUJI -KISO





T20260706112055




BLK: 1, SNR1: 8.1046 , SNR2: 27.051




F20260706112056





BLK: 1, SNR1: 2.3857 , SNR2: 11.387




3C161 2026/07/06 2.38UT TOYOKAWA-FUJI





T20260706112055




BLK: 3, SNR1: 11.852 , SNR2: 28.949




K20260706112052





BLK: 3, SNR1: 15.054 , SNR2: 26.134




3C161 2026/07/06 2.38UT TOYOKAWA-KISO





F20260706112056




BLK: 3, SNR1: 4.7016 , SNR2: 12.168




K20260706112052




BLK: 3, SNR1: 0.57168E-01, SNR2: 4.5302




3C161 2026/07/06 2.38UT FUJI -KISO





T20260706114828




BLK: 7, SNR1: 8.1936 , SNR2: 14.666




F20260706114828




BLK: 7, SNR1: 10.098 , SNR2: 18.078




0652-130 2026/07/06 2.84UT TOYOKAWA-FUJI





T20260706114828




BLK:10,SNR1: 8.0437 ,SNR2: 14.042




K20260706114825



BLK:10,SNR1: 5.5621 ,SNR2: 13.604





0652-130 2026/07/06 2.84UT TOYOKAWA-KISO






F20260706114828





BLK:13,SNR1: 5.6913 ,SNR2: 10.193




Frequency (Hz)

K20260706114825








BLK:13,SNR1: 6.2389 ,SNR2: 15.010




Frequency (Hz)






0652-130 2026/07/06 2.84UT FUJI -KISO






0703+138 2026/07/06 3.03UT TOYOKAWA-FUJI








F20260706120005




BLK: 1, SNR1: 1.7074 , SNR2: 11.454




K20260706120002





BLK: 1, SNR1: 1.7968 , SNR2: 11.405









0703+138 2026/07/06 3.03UT FUJI -KISO






0713-024 2026/07/06 3.19UT TOYOKAWA-FUJI







F20260706120928




BLK: 1,SNR1: 8.5585 ,SNR2: 21.411




K20260706120925





BLK: 1,SNR1: 15.392 ,SNR2: 27.770




0713-024 2026/07/06 3.19UT FUJI -KISO




T20260706121940




BLK: 6,SNR1: 9.0778 ,SNR2: 20.702




F20260706121940



BLK: 6,SNR1: 6.7903 ,SNR2: 16.852





0723+10 2026/07/06 3.36UT TOYOKAWA-FUJI








T20260706121940




BLK: 4,SNR1: 0.97719 ,SNR2: 4.9621




K20260706121937




BLK: 4,SNR1: 3.0343 ,SNR2: 8.3981




0723+10 2026/07/06 3.36UT TOYOKAWA-KISO





F20260706121940




BLK: 4,SNR1: 6.6163 ,SNR2: 8.6416




K20260706121937




BLK: 4,SNR1: 5.4144 ,SNR2: 9.7502





0723+10 2026/07/06 3.36UT FUJI -KISO







BLK:12,SNR1: 1.1325 ,SNR2: 4.1887




BLK:12,SNR1: 2.5492 ,SNR2: 6.5327





0732+33 2026/07/06 3.53UT TOYOKAWA-FUJI







BLK: 7,SNR1: 1.3515 ,SNR2: 5.4691








BLK: 7,SNR1: 4.7238 ,SNR2: 9.3279





0732+33 2026/07/06 3.53UT TOYOKAWA-KISO







T20260706123756




BLK:10,SNR1: 111.37 ,SNR2: 165.04




F20260706123756





BLK:10,SNR1: 0.55627 ,SNR2: 2.1183




0741-06 2026/07/06 3.66UT TOYOKAWA-FUJI





T20260706123756




BLK: 8, SNR1: 7.3078 , SNR2: 11.234




K20260706123753




BLK: 8, SNR1: 8.8293 , SNR2: 16.478




0741-06 2026/07/06 3.66UT TOYOKAWA-KISO





F20260706123756




BLK:13,SNR1: 1.6214 ,SNR2: 3.9647




K20260706123753








BLK:13,SNR1: 8.9647 ,SNR2: 16.725




0741-06 2026/07/06 3.66UT FUJI -KISO













BLK: 5,SNR1: 1.3839 ,SNR2: 2.8214





BLK: 5,SNR1: 3.6221 ,SNR2: 9.4662




0752-200 2026/07/06 3.82UT TOYOKAWA-KISO





F20260706124740




BLK: 3,SNR1: 0.41760 ,SNR2: 2.6866




K20260706124737




BLK: 3,SNR1: 5.6807 ,SNR2: 14.514




0752-200 2026/07/06 3.82UT FUJI -KISO




T20260706125516




BLK: 9,SNR1: 8.5214 ,SNR2: 23.818




F20260706125516




BLK: 9,SNR1: 15.615 ,SNR2: 37.946




3C190 2026/07/06 3.95UT TOYOKAWA-FUJI





T20260706125516




BLK: 7, SNR1: 9.6905 , SNR2: 26.895




K20260706125513




BLK: 7, SNR1: 17.462 , SNR2: 41.209




3C190 2026/07/06 3.95UT TOYOKAWA-KISO





F20260706125516




BLK: 9,SNR1: 15.291 ,SNR2: 37.129




K20260706125513




BLK: 9,SNR1: 17.098 ,SNR2: 40.357





3C190 2026/07/06 3.95UT FUJI -KISO







BLK: 3,SNR1: 10.984 ,SNR2: 26.927





BLK: 3,SNR1: 18.699 ,SNR2: 33.233




3C196 2026/07/06 4.16UT TOYOKAWA-FUJI




T20260706130742




BLK: 3,SNR1: 18.713 ,SNR2: 32.708




K20260706130739



BLK: 3,SNR1: 17.212 ,SNR2: 29.938




3C196 2026/07/06 4.16UT TOYOKAWA-KISO







F20260706130742




BLK: 2, SNR1: 23.022 , SNR2: 38.807




K20260706130739





BLK: 2, SNR1: 18.356 , SNR2: 32.137




3C196 2026/07/06 4.16UT FUJI -KISO





T20260706131851




BLK: 7,SNR1: 0.62543 ,SNR2: 1.9764




F20260706131851





BLK: 7,SNR1: 0.38745E-01,SNR2: 1.9790




0821+394 2026/07/06 4.34UT TOYOKAWA-FUJI





T20260706131851




BLK:10,SNR1: 0.67974 ,SNR2: 3.9932




K20260706131848





BLK:10,SNR1: 0.59877 ,SNR2: 4.1341




0821+394 2026/07/06 4.34UT TOYOKAWA-KISO





F20260706131851




BLK: 3,SNR1: 0.37974 ,SNR2: 2.1872




K20260706131848




BLK: 3,SNR1: 0.20526 ,SNR2: 1.4127





0821+394 2026/07/06 4.34UT FUJI -KISO







BLK: 1,SNR1: 0.16172 ,SNR2: 0.51831




BLK: 1,SNR1: 0.73115 ,SNR2: 9.9059





0834-19 2026/07/06 4.54UT TOYOKAWA-FUJI







BLK: 6,SNR1: 0.91749E-01,SNR2: 0.73759




BLK: 6,SNR1: 0.87669 ,SNR2: 3.1628




0834-19 2026/07/06 4.54UT TOYOKAWA-KISO




F20260706133029




BLK: 8,SNR1: 0.15151 ,SNR2: 1.7619




K20260706133026





BLK: 8,SNR1: 0.97890 ,SNR2: 4.3029




0834-19 2026/07/06 4.54UT FUJI -KISO




T20260706133535




BLK: 3,SNR1: 0.75900 ,SNR2: 4.1421




F20260706133535







BLK: 3,SNR1: 1.3279 ,SNR2: 5.6889




0839-071 2026/07/06 4.62UT TOYOKAWA-FUJI










0839-071 2026/07/06 4.62UT TOYOKAWA-KISO







BLK: 2,SNR1:-0.83953E-01,SNR2: 0.83513





BLK: 2,SNR1: 1.1077 ,SNR2: 4.3008




0839-071 2026/07/06 4.62UT FUJI -KISO





T20260706134636




No.Good Data




F20260706134636





No.Good Data







3C208 2026/07/06 4.80UT TOYOKAWA-FUJI







3C208 2026/07/06 4.80UT TOYOKAWA-KISO








T20260706140319




BLK: 4,SNR1: 9.8334 ,SNR2: 24.471




F20260706140319




BLK: 4,SNR1: 10.759 ,SNR2: 26.369





3C216 2026/07/06 5.08UT TOYOKAWA-FUJI







BLK: 1,SNR1: 14.916 ,SNR2: 35.857




BLK: 1,SNR1: 10.612 ,SNR2: 26.012





3C216 2026/07/06 5.08UT TOYOKAWA-KISO







BLK: 4,SNR1: 5.0111 ,SNR2: 12.009



BLK: 4,SNR1: 0.13535 ,SNR2: 3.6512





3C216 2026/07/06 5.08UT FUJI -KISO








T20260706141528




BLK: 3,SNR1: 3.6355 ,SNR2: 9.9317




F20260706141528





BLK: 3,SNR1: 3.5304 ,SNR2: 8.5595




0919-142 2026/07/06 5.29UT TOYOKAWA-FUJI





T20260706141528




BLK: 5,SNR1: 1.3304 ,SNR2: 2.5712




K20260706141525




BLK: 5,SNR1: 3.6737 ,SNR2: 6.6557




0919-142 2026/07/06 5.29UT TOYOKAWA-KISO





F20260706141528




BLK: 1,SNR1: 0.27353 ,SNR2: 4.5959




K20260706141525




BLK: 1,SNR1: 11.108 ,SNR2: 28.488




0919-142 2026/07/06 5.29UT FUJI -KISO





T20260706142208




BLK: 5,SNR1: 0.53471 ,SNR2: 8.2762




F20260706142208




BLK: 5,SNR1: 0.51198 ,SNR2: 2.7269




0926+117 2026/07/06 5.40UT TOYOKAWA-FUJI




T20260706142208




BLK:11,SNR1: 0.49769 ,SNR2: 3.5998




K20260706142205





BLK:11,SNR1: 0.70342 ,SNR2: 2.2773




0926+117 2026/07/06 5.40UT TOYOKAWA-KISO





F20260706142208




BLK:12,SNR1: 0.69616 ,SNR2: 2.1208




K20260706142205





BLK:12,SNR1: 1.0887 ,SNR2: 2.1814




0926+117 2026/07/06 5.40UT FUJI -KISO





T20260706142952




BLK: 5,SNR1: 0.12968 ,SNR2: 1.1628




F20260706142952




BLK: 5,SNR1: 0.80776 ,SNR2: 2.9606





3C222 2026/07/06 5.53UT TOYOKAWA-FUJI







BLK: 7,SNR1: 0.12969 ,SNR2: 1.1275



BLK: 7,SNR1: 0.71415 ,SNR2: 2.9632




3C222 2026/07/06 5.53UT TOYOKAWA-KISO







F20260706142952




BLK: 5,SNR1: 0.11671 ,SNR2: 0.72251




K20260706142949




BLK: 5,SNR1: 0.59705 ,SNR2: 2.6794





3C222 2026/07/06 5.53UT FUJI -KISO







BLK: 2,SNR1: 9.4829 ,SNR2: 23.333






BLK: 2,SNR1: 10.120 ,SNR2: 25.210





0941-08 2026/07/06 5.64UT TOYOKAWA-FUJI






F20260706143652





No.Good Data




Frequency (Hz)

K20260706143649




No.Good Data





Frequency (Hz)


0941-08 2026/07/06 5.64UT FUJI -KISO





T20260706144514




BLK:16,SNR1: 9.1097 ,SNR2: 27.634




F20260706144514





BLK:16,SNR1: 14.731 ,SNR2: 34.174




3C230 2026/07/06 5.78UT TOYOKAWA-FUJI





T20260706144514




BLK:10,SNR1: 15.924 ,SNR2: 38.312




K20260706144511





BLK:10,SNR1: 12.850 ,SNR2: 31.170




3C230 2026/07/06 5.78UT TOYOKAWA-KISO





F20260706144514




BLK:15,SNR1: 9.0830 ,SNR2: 23.449




K20260706144511




BLK:15,SNR1: 14.227 ,SNR2: 34.029





3C230 2026/07/06 5.78UT FUJI -KISO







BLK: 5,SNR1: 3.3776 ,SNR2: 6.0250




BLK: 5,SNR1: 12.702 ,SNR2: 18.564





3C237 2026/07/06 6.05UT TOYOKAWA-FUJI









BLK:10,SNR1: 3.6098 ,SNR2: 6.4187




BLK:10,SNR1: 7.4179 ,SNR2: 18.799






3C237 2026/07/06 6.05UT TOYOKAWA-KISO




F20260706150115





K20260706150112




3C237 2026/07/06 6.05UT FUJI -KISO





T20260706150731




No.Good Data




F20260706150731





No.Good Data




1011+110 2026/07/06 6.15UT TOYOKAWA-FUJI





T20260706150731




No.Good Data




K20260706150728





No.Good Data




1011+110 2026/07/06 6.15UT TOYOKAWA-KISO



F20260706150731





No.Good Data




Frequency (Hz)

K20260706150728





No.Good Data





Frequency (Hz)

1011+110 2026/07/06 6.15UT FUJI -KISO







BLK: 2,SNR1:-0.16078E-01,SNR2: 0.65755




BLK: 2,SNR1:-0.14111,SNR2: 0.68225





3C241 2026/07/06 6.28UT TOYOKAWA-FUJI







BLK: 4,SNR1:-0.41704E-01,SNR2: 0.61199




BLK: 4,SNR1: 0.31543 ,SNR2: 1.7629





3C241 2026/07/06 6.28UT TOYOKAWA-KISO







BLK: 6,SNR1: 0.12139 ,SNR2: 1.1559



BLK: 6,SNR1: 0.62821 ,SNR2: 1.1498





3C241 2026/07/06 6.28UT FUJI -KISO








T20260706152641




BLK: 2, SNR1: 0.49059E-01, SNR2: 1.9075




F20260706152641




BLK: 2, SNR1: 5.5988, SNR2: 15.991





1031-11 2026/07/06 6.47UT TOYOKAWA-FUJI







BLK: 8,SNR1: 0.43650 ,SNR2: 1.5101




BLK: 8,SNR1: 9.6532 ,SNR2: 16.669





1031-11 2026/07/06 6.47UT TOYOKAWA-KISO








BLK: 5,SNR1: 5.4735 ,SNR2: 15.617




BLK: 5,SNR1: 6.6326 ,SNR2: 11.782




T20260706153115




BLK: 4,SNR1: 85.189 ,SNR2: 160.27




F20260706153115




BLK: 4,SNR1: 7.0203 ,SNR2: 16.987




1035-058 2026/07/06 6.55UT TOYOKAWA-FUJI





T20260706153115




BLK: 5, SNR1: 19.876 , SNR2: 49.458




K20260706153112






BLK: 5, SNR1: 8.0607 , SNR2: 14.513





1035-058 2026/07/06 6.55UT TOYOKAWA-KISO







T20260706154028




BLK: 2,SNR1: 0.34722E-01,SNR2: 0.70902




F20260706154028




BLK: 2,SNR1: 0.30544 ,SNR2: 1.7754





1044-008 2026/07/06 6.70UT TOYOKAWA-FUJI







BLK: 6,SNR1: 1.3144 ,SNR2: 3.4736



BLK: 6,SNR1: 3.5579 ,SNR2: 11.308





1044-008 2026/07/06 6.70UT TOYOKAWA-KISO








F20260706154028




BLK: 1,SNR1:-0.75445E-02,SNR2: 0.49874




K20260706154025




BLK: 1,SNR1: 0.51766 ,SNR2: 2.2170





1044-008 2026/07/06 6.70UT FUJI -KISO







BLK: 2,SNR1: 7.2249 ,SNR2: 26.462





BLK: 2,SNR1:-0.23025 ,SNR2: 0.10680




1055+01 2026/07/06 6.89UT TOYOKAWA-FUJI




T20260706155132




BLK: 9,SNR1: 3.2406 ,SNR2: 12.619




K20260706155129




BLK: 9,SNR1: 1.8525 ,SNR2: 4.6931





1055+01 2026/07/06 6.89UT TOYOKAWA-KISO









BLK: 7,SNR1: 0.42819 ,SNR2: 1.4763




BLK: 7,SNR1: 5.7090 ,SNR2: 16.030





T20260706160250




BLK: 4,SNR1: 0.59713E-01,SNR2: 1.0520




F20260706160250





BLK: 4,SNR1: 0.37698 ,SNR2: 2.8043




1107+109 2026/07/06 7.08UT TOYOKAWA-FUJI



T20260706160250





BLK: 3,SNR1: 0.32990E-01,SNR2: 0.31315




Frequency (Hz)

K20260706160247









BLK: 3,SNR1: 0.20853 ,SNR2: 0.65327





Frequency (Hz)




1107+109 2026/07/06 7.08UT TOYOKAWA-KISO









BLK: 3,SNR1: 0.70421E-01,SNR2: 2.0448





BLK: 3,SNR1: 0.24144E-01,SNR2: 0.84020





3C255 2026/07/06 7.24UT TOYOKAWA-FUJI









BLK:10,SNR1: 0.14121 ,SNR2: 1.1049





BLK:10,SNR1: 0.65769 ,SNR2: 2.0852






3C255 2026/07/06 7.24UT TOYOKAWA-KISO











BLK: 7,SNR1:-0.83521E-01,SNR2: 0.59298








BLK: 7,SNR1: 0.55902 ,SNR2: 1.8867






1127-14 2026/07/06 7.41UT TOYOKAWA-FUJI








1127-14 2026/07/06 7.41UT TOYOKAWA-KISO



F20260706162305




BLK: 3, SNR1: 18.589 , SNR2: 33.068




Frequency (Hz)

K20260706162302




BLK: 3, SNR1: 10.917 , SNR2: 19.394





Frequency (Hz)


1127-14 2026/07/06 7.41UT FUJI -KISO





T20260706163625




BLK: 9,SNR1: 16.351 ,SNR2: 69.273




F20260706163625







BLK: 9,SNR1: 3.1776 ,SNR2: 8.0865






3C263.1 2026/07/06 7.64UT TOYOKAWA-FUJI






3C263.1 2026/07/06 7.64UT TOYOKAWA-KISO








3C263.1 2026/07/06 7.64UT FUJI -KISO









BLK: 5,SNR1: 0.81970 ,SNR2: 13.948




BLK: 5,SNR1: 5.8550 ,SNR2: 14.617





3C267 2026/07/06 7.74UT TOYOKAWA-FUJI







BLK: 2,SNR1: 0.18871 ,SNR2: 1.1820









BLK: 2,SNR1: 8.7003 ,SNR2: 20.554





3C267 2026/07/06 7.74UT TOYOKAWA-KISO









BLK: 5,SNR1:-0.40427E-01,SNR2: 0.95216




BLK: 5,SNR1: 0.12859 ,SNR2: 1.0056





1206+439 2026/07/06 8.06UT TOYOKAWA-FUJI







BLK: 5,SNR1: 0.22459 ,SNR2: 1.3315




BLK: 5,SNR1: 1.2262 ,SNR2: 5.2905





1206+439 2026/07/06 8.06UT TOYOKAWA-KISO







BLK: 8,SNR1: 0.41385 ,SNR2: 1.2626




BLK: 8,SNR1: 0.96369 ,SNR2: 3.4673




1206+439 2026/07/06 8.06UT FUJI -KISO



T20260706180843




BLK: 3,SNR1: 0.30431 ,SNR2: 1.8707




Frequency (Hz)

F20260706180843







BLK: 3,SNR1: 5.8550 ,SNR2: 12.478







Frequency (Hz)

1313+453 2026/07/06 9.17UT TOYOKAWA-FUJI









1313+453 2026/07/06 9.17UT FUJI -KISO

