




T20260721055123





BLK: 3,SNR1: 7.3506 ,SNR2: 18.246




Frequency (Hz)

F20260721055123




BLK: 3,SNR1: 8.2734 ,SNR2: 14.907





Frequency (Hz)


0152+435 2026/07/20 20.88UT TOYOKAWA-FUJI



T20260721055123





No.Good Data




Frequency (Hz)

K20260721055120




No.Good Data





Frequency (Hz)


0152+435 2026/07/20 20.88UT TOYOKAWA-KISO





F20260721055123




BLK: 3, SNR1: 5.0335 , SNR2: 12.746




K20260721055120





BLK: 3, SNR1: 5.3908 , SNR2: 18.061




0152+435 2026/07/20 20.88UT FUJI -KISO



T20260721061955





No.Good Data




Frequency (Hz)

F20260721061955




No.Good Data





Frequency (Hz)


3067 2026/07/20 21.36UT TOYOKAWA-FUJI



T20260721061955





BLK: 1, SNR1: 0.46386 , SNR2: 2.4317





3C67 2026/07/20 21.36UT TOYOKAWA-KISO



K20260721061952




BLK: 1, SNR1: 1.0941 , SNR2: 3.5061





F20260721061955




No.Good Data




K20260721061952




No.Good Data





3C67 2026/07/20 21.36UT FUJI -KISO







BLK: 8,SNR1: 8.5158 ,SNR2: 15.951





BLK: 8,SNR1: 8.2449 ,SNR2: 14.909




0258+350 2026/07/20 21.99UT TOYOKAWA-FUJI





T20260721065725




BLK:13,SNR1: 9.0337 ,SNR2: 15.590




K20260721065722







BLK:13,SNR1: 8.8202 ,SNR2: 15.895




0258+350 2026/07/20 21.99UT TOYOKAWA-KISO







0258+350 2026/07/20 21.99UT FUJI -KISO



T20260721070714





BLK: 2,SNR1: 0.15537 ,SNR2: 1.0209




Frequency (Hz)

F20260721070714




BLK: 2,SNR1: 0.10709 ,SNR2: 3.6529




Frequency (Hz)


0308+305 2026/07/20 22.15UT TOYOKAWA-FUJI



T20260721070714





BLK: 1,SNR1:-0.13025 ,SNR2: 0.0000




Frequency (Hz)

K20260721070711




BLK: 1,SNR1: 0.39738 ,SNR2: 2.2722





Frequency (Hz)


0308+305 2026/07/20 22.15UT TOYOKAWA-KISO



F20260721070714




BLK: 3,SNR1: 0.27589 ,SNR2: 1.1660




Frequency (Hz)

K20260721070711




BLK: 3,SNR1: 0.29913 ,SNR2: 2.0074





Frequency (Hz)


0308+305 2026/07/20 22.15UT FUJI -KISO





T20260721071845




BLK: 5, SNR1: 20.130 , SNR2: 35.761




F20260721071845





BLK: 5, SNR1: 21.335 , SNR2: 39.525




0320+05 2026/07/20 22.34UT TOYOKAWA-FUJI




T20260721071845




BLK: 2, SNR1: 19.592 , SNR2: 35.486




K20260721071842





BLK: 2, SNR1: 20.364 , SNR2: 37.111




0320+05 2026/07/20 22.34UT TOYOKAWA-KISO



F20260721071845





BLK: 1, SNR1: 1.7091 ,SNR2: 8.2177




Frequency (Hz)

K20260721071842




BLK: 1, SNR1: 24.984 ,SNR2: 46.332





Frequency (Hz)


0320+05 2026/07/20 22.34UT FUJI -KISO



T20260721073207





No.Good Data




Frequency (Hz)

F20260721073207




No.Good Data





Frequency (Hz)


0333+32 2026/07/20 22.56UT TOYOKAWA-FUJI





T20260721073207




No.Good Data




K20260721073204





No.Good Data




0333+32 2026/07/20 22.56UT TOYOKAWA-KISO





F20260721073207




No.Good Data




K20260721073204




No.Good Data




0333+32 2026/07/20 22.56UT FUJI -KISO





T20260721074508




BLK: 1,SNR1: 2.0630 ,SNR2: 5.0203




F20260721074508




BLK: 1,SNR1: 7.0175 ,SNR2: 17.884




0347+05 2026/07/20 22.78UT TOYOKAWA-FUJI





T20260721074508




BLK: 1, SNR1: 2.0630 , SNR2: 5.0203




K20260721074505




BLK: 1, SNR1: 8.6383 , SNR2: 24.053




0347+05 2026/07/20 22.78UT TOYOKAWA-KISO





F20260721074508




BLK: 3,SNR1: 8.1817 ,SNR2: 20.077




K20260721074505





BLK: 3,SNR1: 10.678 ,SNR2: 30.929




0347+05 2026/07/20 22.78UT FUJI -KISO




T20260721080041




BLK: 4, SNR1: 1.5034 , SNR2: 3.8604




F20260721080041





BLK: 4, SNR1: 0.22422 , SNR2: 1.7114




0403-132 2026/07/20 23.04UT TOYOKAWA-FUJI




T20260721080041




BLK: 6, SNR1: 1.1604 , SNR2: 2.4025




K20260721080038




BLK: 6, SNR1: 1.1012 , SNR2: 4.0704




0403-132 2026/07/20 23.04UT TOYOKAWA-KISO




F20260721080041




BLK: 5, SNR1: 0.64738 , SNR2: 3.9819




K20260721080038




BLK: 5, SNR1: 1.0262 , SNR2: 4.0716




0403-132 2026/07/20 23.04UT FUJI -KISO





T20260721080953




BLK: 5, SNR1: 2.0871 , SNR2: 9.8911




F20260721080953




BLK: 5, SNR1: 6.7038 , SNR2: 22.864




0411+05 2026/07/20 23.19UT TOYOKAWA-FUJI





T20260721080953




BLK: 7, SNR1: 10.945 , SNR2: 27.593




K20260721080950





BLK: 7, SNR1: 6.1668 , SNR2: 15.803




0411+05 2026/07/20 23.19UT TOYOKAWA-KISO





F20260721080953




BLK: 5, SNR1: 6.7960 , SNR2: 23.175




K20260721080950





BLK: 5, SNR1: 6.3317 , SNR2: 16.062




0411+05 2026/07/20 23.19UT FUJI -KISO




T20260721081648




BLK: 3,SNR1:-0.15862E-02,SNR2: 0.56800




F20260721081648





BLK: 3,SNR1:-0.42989E-01,SNR2: 1.1078




0418+236 2026/07/20 23.31UT TOYOKAWA-FUJI





T20260721081648




BLK: 9,SNR1:-0.13277E-01,SNR2: 0.28345




K20260721081645





BLK: 9,SNR1: 0.46157 ,SNR2: 2.0742




0418+236 2026/07/20 23.31UT TOYOKAWA-KISO




F20260721081648




BLK: 9,SNR1: 0.27836 ,SNR2: 1.5870




K20260721081645




BLK: 9,SNR1: 0.14560E-01,SNR2: 1.7075





0418+236 2026/07/20 23.31UT FUJI -KISO







BLK: 5,SNR1: 0.34640 ,SNR2: 3.5646




BLK: 5,SNR1: 3.2541 ,SNR2: 8.0651





3C119 2026/07/20 23.50UT TOYOKAWA-FUJI







BLK: 5, SNR1: 6.7080 , SNR2: 17.088





BLK: 5, SNR1: 3.9908 , SNR2: 10.440




3C119 2026/07/20 23.50UT TOYOKAWA-KISO




F20260721082816




BLK:10,SNR1: 4.6889 ,SNR2: 11.758




K20260721082813





BLK:10,SNR1: 5.1471 ,SNR2: 17.864




3C119 2026/07/20 23.50UT FUJI -KISO




T20260721085358




BLK: 3,SNR1: 1.0747 ,SNR2: 10.908




F20260721085358




BLK: 3,SNR1:-0.29173 ,SNR2: 0.89728




0456+060 2026/07/20 23.93UT TOYOKAWA-FUJI




T20260721085358




BLK: 5,SNR1:-0.80421E-02,SNR2: 0.54143




K20260721085355




BLK: 5,SNR1: 0.88057 ,SNR2: 2.7866




0456+060 2026/07/20 23.93UT TOYOKAWA-KISO





F20260721085358




BLK: 4,SNR1: 0.13674 ,SNR2: 2.6695




K20260721085355





BLK: 4,SNR1: 0.94060 ,SNR2: 2.9863




0456+060 2026/07/20 23.93UT FUJI -KISO





T20260721091622




BLK: 5, SNR1: 7.8113 , SNR2: 20.419




F20260721091622





BLK: 5, SNR1: 7.9066 , SNR2: 19.330




3C138 2026/07/21 0.30UT TOYOKAWA-FUJI



T20260721091622





BLK: 9, SNR1: 9.0313 ,SNR2: 22.766





3C138 2026/07/21 0.30UT TOYOKAWA-KISO



K20260721091619




BLK: 9, SNR1: 8.7698 ,SNR2: 21.488





F20260721091622




BLK: 3, SNR1: 11.934 , SNR2: 21.158




K20260721091619












BLK: 3, SNR1: 13.297 , SNR2: 30.945




3C138 2026/07/21 0.30UT FUJI -KISO










0531+194 2026/07/21 0.53UT TOYOKAWA-KISO



F20260721092956





BLK: 2, SNR1: 7.6258 , SNR2: 18.798




Frequency (Hz)

K20260721092953




BLK: 2, SNR1: 6.4350 , SNR2: 22.591




Frequency (Hz)


0531+194 2026/07/21 0.53UT FUJI -KISO




T20260721093817




BLK:24,SNR1: 8.5371 ,SNR2: 28.367




F20260721093817





BLK:24,SNR1: 1.0161 ,SNR2: 3.1393




3C147 2026/07/21 0.67UT TOYOKAWA—FUJI





T20260721093817




BLK:30,SNR1: 7.5156 ,SNR2: 20.874




K20260721093814




BLK:30,SNR1: 1.1051 ,SNR2: 4.8730




3C147 2026/07/21 0.67UT TOYOKAWA-KISO





F20260721093817




BLK:21,SNR1: 0.90816 ,SNR2: 3.1812




K20260721093814





BLK:21,SNR1: 1.1392 ,SNR2: 4.8997




3C147 2026/07/21 0.67UT FUJI -KISO





T20260721094627




BLK: 6,SNR1: 0.79334 ,SNR2: 1.6612




F20260721094627





BLK: 6,SNR1: 0.22233 ,SNR2: 1.6646




0548+16 2026/07/21 0.80UT TOYOKAWA-FUJI





T20260721094627




BLK:13,SNR1: 0.28378 ,SNR2: 1.4003




K20260721094624




BLK:13,SNR1: 0.82209 ,SNR2: 2.9871




0548+16 2026/07/21 0.80UT TOYOKAWA-KISO





F20260721094627




BLK: 9,SNR1: 0.63339E-01,SNR2: 1.2873




K20260721094624





BLK: 9,SNR1: 0.92282 ,SNR2: 3.4406




0548+16 2026/07/21 0.80UT FUJI -KISO




T20260721095037




BLK: 5, SNR1: 2.0973 , SNR2: 5.6305




F20260721095037





BLK: 5, SNR1: 5.9851 , SNR2: 15.114




0552+12 2026/07/21 0.87UT TOYOKAWA-FUJI




T20260721095037




BLK: 4, SNR1: 1.0339 , SNR2: 3.6389




K20260721095034




BLK: 4, SNR1: 3.3222 , SNR2: 9.3347




0552+12 2026/07/21 0.87UT TOYOKAWA-KISO




F20260721095037




BLK: 7, SNR1: 4.8823 , SNR2: 12.107




K20260721095034





BLK: 7, SNR1: 4.0851 , SNR2: 10.718




0552+12 2026/07/21 0.87UT FUJI -KISO





T20260721095504




No. Good Data




F20260721095504




No. Good Data




0556+191 2026/07/21 0.95UT TOYOKAWA-FUJI




T20260721095504




BLK: 2, SNR1: 2.2392 , SNR2: 6.8452




K20260721095501




BLK: 2, SNR1: 9.3717 , SNR2: 23.630




0556+191 2026/07/21 0.95UT TOYOKAWA-KISO




F20260721095504




BLK: 1,SNR1: 3.3593 ,SNR2: 9.1835




K20260721095501





BLK: 1,SNR1: 0.94062 ,SNR2: 3.9038




0556+191 2026/07/21 0.95UT FUJI -KISO





T20260721100249




BLK:10,SNR1: 6.2839 ,SNR2: 16.810




F20260721100249





BLK:10,SNR1: 13.342 ,SNR2: 30.027




0605-08 2026/07/21 1.08UT TOYOKAWA-FUJI




T20260721100249




BLK:14,SNR1: 12.839 ,SNR2: 28.607




K20260721100246




BLK:14,SNR1: 13.197 ,SNR2: 29.416




0605-08 2026/07/21 1.08UT TOYOKAWA-KISO




F20260721100249




BLK:13,SNR1: 12.179 ,SNR2: 26.903




K20260721100246





BLK:13,SNR1: 15.594 ,SNR2: 34.708




0605-08 2026/07/21 1.08UT FUJI -KISO





T20260721102157




BLK:11,SNR1: 2.5725 ,SNR2: 7.6933




F20260721102157





BLK:11,SNR1: 0.33989 ,SNR2: 4.1063




3C161 2026/07/21 1.39UT TOYOKAWA-FUJI





T20260721102157




BLK:13,SNR1: 2.2264 ,SNR2: 9.0607




K20260721102154




BLK:13,SNR1: 1.0470 ,SNR2: 4.2303




3C161 2026/07/21 1.39UT TOYOKAWA-KISO





F20260721102157




BLK: 2, SNR1: 3.9401 , SNR2: 17.113




K20260721102154




BLK: 2, SNR1: 1.0794 , SNR2: 3.2782




3C161 2026/07/21 1.39UT FUJI -KISO




T20260721104930




BLK: 5, SNR1: 0.36726 , SNR2: 1.3657




F20260721104930





BLK: 5, SNR1: 8.7403 , SNR2: 26.954




0652-130 2026/07/21 1.85UT TOYOKAWA-FUJI





T20260721104930




BLK: 4, SNR1: 2.2416 , SNR2: 5.8351




K20260721104927




BLK: 4, SNR1: 5.6119 , SNR2: 17.300




0652-130 2026/07/21 1.85UT TOYOKAWA-KISO




F20260721104930




BLK: 3,SNR1: 0.96057 ,SNR2: 3.1149




K20260721104927





BLK: 3,SNR1: 7.6069 ,SNR2: 15.016




0652-130 2026/07/21 1.85UT FUJI -KISO





T20260721110107




BLK: 7,SNR1: 0.70280E-01,SNR2: 0.51859




F20260721110107





BLK: 7,SNR1: 9.1970 ,SNR2: 16.396




0703+138 2026/07/21 2.05UT TOYOKAWA-FUJI




T20260721110107




BLK:11,SNR1: 6.0976 ,SNR2: 10.478




K20260721110104




BLK:11,SNR1: 1.7575 ,SNR2: 5.9308




0703+138 2026/07/21 2.05UT TOYOKAWA-KISO




F20260721110107




BLK: 5, SNR1: 17.640 , SNR2: 30.826




K20260721110104







BLK: 5, SNR1: 1.6158 , SNR2: 5.3599




0703+138 2026/07/21 2.05UT FUJI -KISO








0713-024 2026/07/21 2.20UT TOYOKAWA-FUJI





T20260721111029




BLK: 1, SNR1: 1.6482 , SNR2: 12.937




K20260721111026







BLK: 1, SNR1: 19.713 , SNR2: 41.949




0713-024 2026/07/21 2.20UT TOYOKAWA-KISO








0713-024 2026/07/21 2.20UT FUJI -KISO





T20260721112041




BLK: 9,SNR1: 0.34367 ,SNR2: 3.8292




F20260721112041




BLK: 9,SNR1: 0.31484 ,SNR2: 0.90512




0723+10 2026/07/21 2.37UT TOYOKAWA-FUJI





T20260721112041




BLK:13,SNR1: 0.41231 ,SNR2: 3.4021




K20260721112038




BLK:13,SNR1: 0.71096 ,SNR2: 2.4646




0723+10 2026/07/21 2.37UT TOYOKAWA-KISO





F20260721112041




BLK: 7,SNR1: 0.26006 ,SNR2: 1.6463




K20260721112038





BLK: 7,SNR1: 0.62396 ,SNR2: 1.6681




0723+10 2026/07/21 2.37UT FUJI -KISO





T20260721113057




BLK: 9, SNR1: 9.5807 , SNR2: 16.573




F20260721113057





BLK: 9, SNR1: 0.14792 , SNR2: 5.2328




0732+33 2026/07/21 2.54UT TOYOKAWA-FUJI





T20260721113057




BLK:22,SNR1: 9.3196 ,SNR2: 16.121




K20260721113054





BLK:22,SNR1: 1.8539 ,SNR2: 6.1605




0732+33 2026/07/21 2.54UT TOYOKAWA-KISO





F20260721113057




BLK:19,SNR1: 0.14163 ,SNR2: 5.1797




K20260721113054





BLK:19,SNR1: 7.9659 ,SNR2: 20.622




0732+33 2026/07/21 2.54UT FUJI -KISO





T20260721113857




No.Good Data




F20260721113857




No.Good Data




0741-06 2026/07/21 2.68UT TOYOKAWA-FUJI





T20260721113857




BLK: 1,SNR1: 36.627 ,SNR2: 81.881




K20260721113854





BLK: 1,SNR1: 0.27979E-01,SNR2: 1.9108




0741-06 2026/07/21 2.68UT TOYOKAWA-KISO





F20260721113857




BLK: 2, SNR1: -0.21217 , SNR2: 1.1377




K20260721113854




BLK: 2, SNR1: 0.43051 , SNR2: 2.0771




0741-06 2026/07/21 2.68UT FUJI -KISO





T20260721114841




BLK:12,SNR1: 5.8823 ,SNR2: 10.774




F20260721114841




BLK:12,SNR1: 0.92929 ,SNR2: 3.9017




0752-200 2026/07/21 2.84UT TOYOKAWA-FUJI




T20260721114841




BLK:14,SNR1: 5.6622 ,SNR2: 8.2017




K20260721114838





BLK:14,SNR1: 1.6751 ,SNR2: 6.9542




0752-200 2026/07/21 2.84UT TOYOKAWA-KISO





F20260721114841




BLK: 8, SNR1: 1.2767 , SNR2: 3.1548




K20260721114838





BLK: 8, SNR1: 1.5562 , SNR2: 6.1798




0752-200 2026/07/21 2.84UT FUJI -KISO





T20260721115617




BLK:30,SNR1: 40.655 ,SNR2: 49.722




F20260721115617





BLK:30,SNR1: 5.6012 ,SNR2: 17.105




3C190 2026/07/21 2.97UT TOYOKAWA-FUJI




T20260721115617




BLK:33,SNR1: 35.365 ,SNR2: 42.741




K20260721115614





BLK:33,SNR1: 12.460 ,SNR2: 18.369




3C190 2026/07/21 2.97UT TOYOKAWA-KISO





F20260721115617




BLK:31,SNR1: 5.5440 ,SNR2: 16.690




K20260721115614




BLK:31,SNR1: 14.446 ,SNR2: 18.687





3C190 2026/07/21 2.97UT FUJI -KISO







BLK: 8,SNR1: 1.2183 ,SNR2: 4.0601








BLK: 8,SNR1: 15.733 ,SNR2: 27.939





3C196 2026/07/21 3.17UT TOYOKAWA-FUJI






F20260721120844




BLK: 4,SNR1: 2.3846 ,SNR2: 6.8831





3C196 2026/07/21 3.17UT FUJI -KISO



K20260721120841




BLK: 4,SNR1: 2.2781 ,SNR2: 9.5903




T20260721121953




BLK: 8,SNR1: 0.30440 ,SNR2: 2.1888




F20260721121953





BLK: 8,SNR1: 0.80686E-01,SNR2: 2.3323




0821+394 2026/07/21 3.36UT TOYOKAWA-FUJI





T20260721121953




BLK:15,SNR1: 0.34922 ,SNR2: 1.8345




K20260721121950




BLK:15,SNR1: 1.6096 ,SNR2: 5.0168




0821+394 2026/07/21 3.36UT TOYOKAWA-KISO





F20260721121953




BLK:11,SNR1: 0.50697 ,SNR2: 1.9502




K20260721121950





BLK:11,SNR1: 1.8000 ,SNR2: 5.6876




0821+394 2026/07/21 3.36UT FUJI -KISO




T20260721123130




BLK: 2,SNR1: 0.29460 ,SNR2: 1.4381




F20260721123130





BLK: 2,SNR1: 0.45843 ,SNR2: 1.5617




0834-19 2026/07/21 3.55UT TOYOKAWA-FUJI




T20260721123130




BLK: 3,SNR1: 0.10562 ,SNR2: 0.78196




K20260721123127




BLK: 3,SNR1: 0.38463 ,SNR2: 1.1106




0834-19 2026/07/21 3.55UT TOYOKAWA-KISO




F20260721123130




BLK: 3,SNR1:-0.12414 ,SNR2: 0.98957




K20260721123127





BLK: 3,SNR1: 1.6909 ,SNR2: 8.7731




0834-19 2026/07/21 3.55UT FUJI -KISO




T20260721123636




BLK: 5,SNR1: 0.58951E-01,SNR2: 0.73510




F20260721123636





BLK: 5,SNR1: 3.1204 ,SNR2: 4.2460




0839-071 2026/07/21 3.64UT TOYOKAWA-FUJI



T20260721123636





BLK: 1,SNR1:-0.79560E-01,SNR2: 0.37382




Frequency (Hz)

K20260721123633




BLK: 1,SNR1: 0.53307 ,SNR2: 3.7998




Frequency (Hz)


0839-071 2026/07/21 3.64UT TOYOKAWA-KISO





F20260721123636




BLK: 3,SNR1:-0.34592E-01,SNR2: 0.97405




K20260721123633




BLK: 3,SNR1: 0.36714 ,SNR2: 11.007





0839-071 2026/07/21 3.64UT FUJI -KISO







BLK:13,SNR1: 0.16373 ,SNR2: 2.7441




BLK:13,SNR1: 0.18886 ,SNR2: 0.99829




3C208 2026/07/21 3.82UT TOYOKAWA-FUJI




T20260721124738




BLK:13,SNR1: 0.32219 ,SNR2: 1.5297




K20260721124735




BLK:13,SNR1: 0.76328 ,SNR2: 3.3640




3C208 2026/07/21 3.82UT TOYOKAWA-KISO




F20260721124738




BLK:12,SNR1: 0.16241 ,SNR2: 0.94347




K20260721124735





BLK:12,SNR1: 0.99789 ,SNR2: 2.5602




3C208 2026/07/21 3.82UT FUJI -KISO





T20260721130420




BLK:13,SNR1: 0.75413E-01,SNR2: 1.4035




F20260721130420





BLK:13,SNR1: 4.7792 ,SNR2: 7.2642




3C216 2026/07/21 4.10UT TOYOKAWA-FUJI





T20260721130420




BLK: 3,SNR1: 0.23202E-01,SNR2: 0.87090




K20260721130417




BLK: 3,SNR1: 0.25409 ,SNR2: 2.1567




3C216 2026/07/21 4.10UT TOYOKAWA-KISO





F20260721130420




BLK: 8,SNR1: 4.3568 ,SNR2: 6.6300




K20260721130417





BLK: 8,SNR1: 0.28209 ,SNR2: 1.2996





3C216 2026/07/21 4.10UT FUJI -KISO




T20260721131630





F20260721131630




0919-142 2026/07/21 4.30UT TOYOKAWA-FUJI




T20260721131630




BLK: 3,SNR1: 5.7289 ,SNR2: 14.883




K20260721131627




BLK: 3,SNR1: 6.4215 ,SNR2: 19.537




0919-142 2026/07/21 4.30UT TOYOKAWA-KISO





F20260721131630




BLK: 9,SNR1: 5.8983 ,SNR2: 15.354




K20260721131627





BLK: 9,SNR1: 5.9269 ,SNR2: 15.197




0919-142 2026/07/21 4.30UT FUJI -KISO





T20260721132309




BLK:20,SNR1: 15.552 ,SNR2: 22.253




F20260721132309





BLK:20,SNR1: 10.408 ,SNR2: 10.002




0926+117 2026/07/21 4.41UT TOYOKAWA-FUJI





T20260721132309




BLK:20,SNR1: 17.239 ,SNR2: 24.661




K20260721132306





BLK:20,SNR1: 7.8735 ,SNR2: 20.368




0926+117 2026/07/21 4.41UT TOYOKAWA-KISO





F20260721132309




BLK:22,SNR1: 11.169 ,SNR2: 10.729




K20260721132306





BLK:22,SNR1: 7.9467 ,SNR2: 20.553




0926+117 2026/07/21 4.41UT FUJI -KISO





T20260721133054




BLK: 5,SNR1: 0.61746 ,SNR2: 1.5641




F20260721133054





BLK: 5,SNR1: 4.5608 ,SNR2: 9.9432




3C222 2026/07/21 4.54UT TOYOKAWA-FUJI





T20260721133054




BLK: 4,SNR1: 0.20611 ,SNR2: 0.77105




K20260721133051





BLK: 4,SNR1: 2.5628 ,SNR2: 5.3529





3C222 2026/07/21 4.54UT TOYOKAWA-KISO




F20260721133054




K20260721133051





3C222 2026/07/21 4.54UT FUJI -KISO







BLK: 6,SNR1: 5.0720 ,SNR2: 11.417




BLK: 6,SNR1: 0.95504 ,SNR2: 2.4129




0941-08 2026/07/21 4.66UT TOYOKAWA-FUJI




T20260721133754




BLK: 7,SNR1: 8.0085 ,SNR2: 23.043




K20260721133751





BLK: 7,SNR1: 12.702 ,SNR2: 30.834




0941-08 2026/07/21 4.66UT TOYOKAWA-KISO




F20260721133754




BLK: 8,SNR1: 0.55384 ,SNR2: 0.66069




K20260721133751













BLK: 8,SNR1: 7.2756 ,SNR2: 20.803




0941-08 2026/07/21 4.66UT FUJI -KISO













BLK: 6,SNR1: 20.202 ,SNR2: 44.701




BLK: 6,SNR1: 6.9646 ,SNR2: 21.974





3C230 2026/07/21 4.80UT FUJI -KISO







BLK: 8,SNR1: 0.89067E-01,SNR2: 1.2739




BLK: 8,SNR1: 4.7708 ,SNR2: 10.304





3C236 2026/07/21 5.03UT TOYOKAWA-FUJI







BLK:13,SNR1: 0.18800 ,SNR2: 1.1499





BLK:13,SNR1: 0.47847 ,SNR2: 1.7029




3C236 2026/07/21 5.03UT TOYOKAWA-KISO





F20260721140024




BLK:12,SNR1: 3.4296 ,SNR2: 7.5787




K20260721140021





BLK:12,SNR1: 0.71532 ,SNR2: 2.8530




3C236 2026/07/21 5.03UT FUJI -KISO




T20260721140833




BLK: 1,SNR1: 0.25001 ,SNR2: 7.1663




F20260721140833





BLK: 1,SNR1:-0.38031E-02,SNR2: 3.5267




1011+110 2026/07/21 5.17UT TOYOKAWA-FUJI





T20260721140833




BLK: 3,SNR1: 1.4494 ,SNR2: 6.2371




K20260721140830




BLK: 3,SNR1: 0.84405 ,SNR2: 4.2998




1011+110 2026/07/21 5.17UT TOYOKAWA-KISO





F20260721140833




BLK: 2,SNR1: 1.1159 ,SNR2: 5.4200




K20260721140830




BLK: 2,SNR1: 0.33721 ,SNR2: 0.94059





1011+110 2026/07/21 5.17UT FUJI -KISO







BLK:22,SNR1: 3.0297 ,SNR2: 9.0739




BLK:22,SNR1: 0.96387 ,SNR2: 1.3656




3C241 2026/07/21 5.30UT TOYOKAWA-FUJI





T20260721141614




BLK:26,SNR1: 3.1746 ,SNR2: 9.4727




K20260721141611






BLK:26,SNR1: 19.904 ,SNR2: 23.119





3C241 2026/07/21 5.30UT TOYOKAWA-KISO







T20260721142743




BLK: 6,SNR1: 12.264 ,SNR2: 30.464




F20260721142743





BLK: 6,SNR1: 1.8473 ,SNR2: 4.9289




1031-11 2026/07/21 5.49UT TOYOKAWA-FUJI





T20260721142743




BLK: 9,SNR1: 10.354 ,SNR2: 29.965




K20260721142740




BLK: 9,SNR1: 11.591 ,SNR2: 30.713




1031-11 2026/07/21 5.49UT TOYOKAWA-KISO





F20260721142743




BLK: 7,SNR1: 10.311 ,SNR2: 25.688




K20260721142740





BLK: 7,SNR1: 68.347 ,SNR2: 81.642




1031-11 2026/07/21 5.49UT FUJI -KISO




T20260721143216




BLK:11,SNR1: 2.2525 ,SNR2: 7.4756




F20260721143216





BLK:11,SNR1: 35.419 ,SNR2: 47.025




1035-058 2026/07/21 5.57UT TOYOKAWA-FUJI





T20260721143216




BLK:23,SNR1: 2.3904 ,SNR2: 7.8199




K20260721143213




BLK:23,SNR1: 1.9728 ,SNR2: 6.8482




1035-058 2026/07/21 5.57UT TOYOKAWA-KISO




F20260721143216




BLK:10,SNR1: 23.625 ,SNR2: 31.376




K20260721143213





BLK:10,SNR1: 1.9400 ,SNR2: 6.5832




1035-058 2026/07/21 5.57UT FUJI -KISO





T20260721144129




BLK: 8,SNR1: 0.28468 ,SNR2: 2.5400




F20260721144129




BLK: 8,SNR1: 96.635 ,SNR2: 144.16




1044-008 2026/07/21 5.72UT TOYOKAWA-FUJI



T20260721144129





No.Good Data




Frequency (Hz)

K20260721144126




No.Good Data





Frequency (Hz)


1044-008 2026/07/21 5.72UT TOYOKAWA-KISO





F20260721144129




BLK: 9,SNR1: 104.68 ,SNR2: 157.30




K20260721144126





BLK: 9,SNR1: 1.9028 ,SNR2: 8.8651




1044-008 2026/07/21 5.72UT FUJI -KISO





T20260721145234




BLK: 2,SNR1: 0.23776 ,SNR2: 0.44597




F20260721145234





BLK: 2,SNR1: 0.56233 ,SNR2: 3.7139




1055+01 2026/07/21 5.90UT TOYOKAWA-FUJI





T20260721145234




BLK: 6,SNR1: 11.132 ,SNR2: 26.288




K20260721145231




BLK: 6,SNR1: 1.3474 ,SNR2: 5.1783




1055+01 2026/07/21 5.90UT TOYOKAWA-KISO




F20260721145234




BLK: 1,SNR1: 0.18405 ,SNR2: 1.4501




K20260721145231




BLK: 1,SNR1: 0.22876 ,SNR2: 0.96464





1055+01 2026/07/21 5.90UT FUJI -KISO







BLK: 5,SNR1: 9.9573 ,SNR2: 23.779





BLK: 5,SNR1: 4.1556 ,SNR2: 10.241






1107+109 2026/07/21 6.09UT TOYOKAWA-FUJI







BLK: 3,SNR1: 0.45952E-01,SNR2: 1.5104








BLK: 3,SNR1: 1.7966 ,SNR2: 7.7706




1107+109 2026/07/21 6.09UT TOYOKAWA-KISO








T20260721151328




BLK: 8,SNR1: 19.801 ,SNR2: 35.195




F20260721151328




BLK: 8,SNR1: 3.5337 ,SNR2: 13.098





3C255 2026/07/21 6.25UT TOYOKAWA-FUJI









BLK: 9,SNR1: 19.498 ,SNR2: 34.653




BLK: 9,SNR1: 7.6698 ,SNR2: 14.264





F20260721151328




BLK: 7,SNR1: 33.351 ,SNR2: 44.517




K20260721151325




BLK: 7,SNR1: 8.2072 ,SNR2: 21.247




3C255 2026/07/21 6.25UT FUJI -KISO



T20260721152406




BLK: 3,SNR1: 16.627 ,SNR2: 29.379




Frequency (Hz)

F20260721152406





BLK: 3,SNR1: 6.7996 ,SNR2: 16.817





Frequency (Hz)

1127-14 2026/07/21 6.43UT TOYOKAWA-FUJI







BLK: 1,SNR1: 0.19511 ,SNR2: 3.9476








BLK: 1,SNR1: 15.968 ,SNR2: 35.477





1127-14 2026/07/21 6.43UT TOYOKAWA-KISO








T20260721153727




BLK: 4,SNR1: 7.5647 ,SNR2: 18.802




F20260721153727







BLK: 4,SNR1: 9.3632 ,SNR2: 23.067




3C263.1 2026/07/21 6.65UT TOYOKAWA-FUJI







3C263.1 2026/07/21 6.65UT TOYOKAWA-KISO





F20260721153727




BLK: 3,SNR1: 8.6976 ,SNR2: 21.494




K20260721153724




BLK: 3,SNR1: 77.404 ,SNR2: 109.10





3C263.1 2026/07/21 6.65UT FUJI -KISO







BLK: 2,SNR1: 0.19286 ,SNR2: 1.3680





BLK: 2,SNR1: 1.8685 ,SNR2: 2.9574






3C267 2026/07/21 6.76UT TOYOKAWA-FUJI







BLK: 1,SNR1: 0.11625E-01,SNR2: 0.0000




BLK: 1,SNR1: 1.1372 ,SNR2: 8.0125




3C267 2026/07/21 6.76UT TOYOKAWA-KISO





F20260721154353




BLK: 9,SNR1: 0.33294E-01,SNR2: 1.3139




K20260721154350




BLK: 9,SNR1: 1.9739 ,SNR2: 6.0810





3C267 2026/07/21 6.76UT FUJI -KISO







BLK: 3,SNR1: 12.937 ,SNR2: 31.585







BLK: 3,SNR1: 12.694 ,SNR2: 30.607





1213-17 2026/07/21 7.19UT TOYOKAWA-FUJI






1213-17 2026/07/21 7.19UT TOYOKAWA-KISO







BLK: 4, SNR1: 16.067 , SNR2: 38.476




Frequency (Hz)




BLK: 4, SNR1: 12.990 , SNR2: 31.306





Frequency (Hz)







BLK: 1,SNR1: 0.75105 ,SNR2: 11.844











BLK: 1,SNR1: 0.25437 ,SNR2: 3.4905




3C273 2026/07/21 7.41UT TOYOKAWA-FUJI













BLK: 6,SNR1: 0.68465E-01,SNR2: 0.85249




BLK: 6,SNR1: 0.54054 ,SNR2: 2.8002





3C275 2026/07/21 7.63UT TOYOKAWA-FUJI







BLK:10,SNR1: 1.9425 ,SNR2: 3.2625







BLK:10,SNR1: 9.3638 ,SNR2: 20.914







3C275 2026/07/21 7.63UT TOYOKAWA-KISO










3C275 2026/07/21 7.63UT FUJI -KISO


















3C279 2026/07/21 7.86UT TOYOKAWA-KISO










T20260721170945




BLK:10,SNR1: 0.34835 ,SNR2: 2.5324




K20260721170942








BLK:10,SNR1: 0.14189 ,SNR2: 0.30428





1313+453 2026/07/21 8.19UT TOYOKAWA-KISO






T20260721171951





BLK: 1,SNR1: 0.24351 ,SNR2: 1.3861




Frequency (Hz)

F20260721171951









BLK: 1,SNR1: 0.25899E-01,SNR2: 2.1985













Frequency (Hz)

1323+32 2026/07/21 8.36UT TOYOKAWA-FUJI












T20260721172442






BLK:11,SNR1: 0.68121 ,SNR2: 2.1180




Frequency (Hz)


K20260721172439

BLK:11,SNR1: -0.17149×10^{-1} , SNR2: 1.4593



Frequency (Hz)

3C286 2026/07/21 8.44UT TOYOKAWA-KISO





BLK: 9,SNR1: 0.76411E-01,SNR2: 0.39179



BLK: 9,SNR1: 0.13711E-01,SNR2: 1.5397

