








BLK: 3,SNR1: 0.24265E-01,SNR2: 1.9922




BLK: 3,SNR1: 4.4114 ,SNR2: 10.750





0152+435 2026/07/22 20.75UT TOYOKAWA-FUJI







BLK: 8,SNR1: 0.53144 ,SNR2: 2.0842



BLK: 8,SNR1: 11.387 ,SNR2: 26.506





0152+435 2026/07/22 20.75UT TOYOKAWA-KISO







F20260723054331




BLK: 9,SNR1: 8.5862 ,SNR2: 19.066




K20260723054328





BLK: 9,SNR1: 4.0539 ,SNR2: 9.8995




0152+435 2026/07/22 20.75UT FUJI -KISO



T20260723061203





No.Good Data




Frequency (Hz)

F20260723061203




No.Good Data





Frequency (Hz)


3C67 2026/07/22 21.23UT TOYOKAWA-FUJI



T20260723061203





No.Good Data




Frequency (Hz)

K20260723061200




No.Good Data





Frequency (Hz)


3C67 2026/07/22 21.23UT TOYOKAWA-KISO



F20260723061203





No.Good Data




Frequency (Hz)

K20260723061200




No.Good Data





Frequency (Hz)


3C67 2026/07/22 21.23UT FUJI -KISO





T20260723064933




BLK: 5, SNR1: 2.5730 , SNR2: 6.0047




F20260723064933





BLK: 5, SNR1: 5.2953 , SNR2: 12.827




0258+350 2026/07/22 21.85UT TOYOKAWA-FUJI





T20260723064933




BLK: 2, SNR1: 1.2681 , SNR2: 3.2146




K20260723064930





BLK: 2, SNR1: 12.350 , SNR2: 31.292




0258+350 2026/07/22 21.85UT TOYOKAWA-KISO





F20260723064933




BLK: 6, SNR1: 5.3574 , SNR2: 13.061




K20260723064930





BLK: 6, SNR1: 10.230 , SNR2: 26.010




0258+350 2026/07/22 21.85UT FUJI -KISO




T20260723065922




BLK: 2, SNR1: 10.395 , SNR2: 29.634




F20260723065922



BLK: 2, SNR1: 6.6099 , SNR2: 19.098





0308+305 2026/07/22 22.02UT TOYOKAWA-FUJI






T20260723065922





BLK: 4, SNR1: 9.6955 , SNR2: 24.533




Frequency (Hz)

K20260723065919




BLK: 4, SNR1: 11.672 , SNR2: 27.516





Frequency (Hz)


0308+305 2026/07/22 22.02UT TOYOKAWA-KISO



F20260723065922





BLK: 4, SNR1: 10.234 , SNR2: 24.769




Frequency (Hz)

K20260723065919




BLK: 4, SNR1: 10.053 , SNR2: 25.069





Frequency (Hz)


0308+305 2026/07/22 22.02UT FUJI -KISO




T20260723071053




BLK: 1,SNR1: 0.98460 ,SNR2: 4.3563




F20260723071053





BLK: 1,SNR1: 0.28093 ,SNR2: 1.6876




0320+05 2026/07/22 22.21UT TOYOKAWA-FUJI





T20260723071053




No.Good Data




K20260723071050




No.Good Data




0320+05 2026/07/22 22.21UT TOYOKAWA-KISO





F20260723071053




BLK: 1,SNR1: 0.28093 ,SNR2: 1.6876




K20260723071050





BLK: 1,SNR1: 1.0231 ,SNR2: 6.1698




0320+05 2026/07/22 22.21UT FUJI -KISO



T20260723072415





BLK:24,SNR1: 10.676 ,SNR2: 24.554




Frequency (Hz)

F20260723072415





BLK:24,SNR1: 9.2810 ,SNR2: 26.794





Frequency (Hz)

0333+32 2026/07/22 22.43UT TOYOKAWA-FUJI







BLK:26,SNR1: 9.4597 ,SNR2: 22.604





BLK:26,SNR1: 12.969 ,SNR2: 22.998




0333+32 2026/07/22 22.43UT TOYOKAWA-KISO





F20260723072415




BLK:28,SNR1: 8.1997 ,SNR2: 19.405




K20260723072412





BLK:28,SNR1: 8.1592 ,SNR2: 23.046




0333+32 2026/07/22 22.43UT FUJI -KISO










0347+05 2026/07/22 22.65UT TOYOKAWA-FUJI





T20260723073716




BLK: 1, SNR1: 3.7357 , SNR2: 15.445




K20260723073713







BLK: 1, SNR1: 4.0155 , SNR2: 16.513




0347+05 2026/07/22 22.65UT TOYOKAWA-KISO








0347+05 2026/07/22 22.65UT FUJI -KISO





T20260723075250




BLK: 2,SNR1: 0.17853 ,SNR2: 1.8097




F20260723075250





BLK: 2,SNR1: 0.94428 ,SNR2: 6.1398




0403-132 2026/07/22 22.91UT TOYOKAWA-FUJI




T20260723075250




BLK: 2,SNR1: 0.35637 ,SNR2: 2.3410




K20260723075247





BLK: 2,SNR1: 0.87276 ,SNR2: 3.4403




0403-132 2026/07/22 22.91UT TOYOKAWA-KISO





F20260723075250




BLK: 2,SNR1: 15.493 ,SNR2: 27.760




K20260723075247





BLK: 2,SNR1: 4.7985 ,SNR2: 12.219




0403-132 2026/07/22 22.91UT FUJI -KISO



T20260723080201





BLK: 1,SNR1: 6.3436 ,SNR2: 18.164




Frequency (Hz)

F20260723080201








BLK: 1,SNR1: 11.130 ,SNR2: 35.172




Frequency (Hz)

0411+05 2026/07/22 23.06UT TOYOKAWA-FUJI







0411+05 2026/07/22 23.08UT TOYOKAWA-KISO







F20260723080201




BLK: 1, SNR1: 10.978 ,SNR2: 24.948




K20260723080158




BLK: 1, SNR1: 9.1442 ,SNR2: 26.099





0411+05 2026/07/22 23.06UT FUJI -KISO







BLK: 1,SNR1: 66.041 ,SNR2: 102.42







BLK: 1,SNR1: 11.909 ,SNR2: 29.176





0418+236 2026/07/22 23.18UT TOYOKAWA-FUJI









BLK: 1, SNR1: 9.1584 , SNR2: 22.850







BLK: 1, SNR1: 3.0149 , SNR2: 13.691






0418+236 2026/07/22 23.18UT FUJI -KISO






3C119 2026/07/22 23.37UT TOYOKAWA-FUJI








3C119 2026/07/22 23.37UT TOYOKAWA-KISO



F20260723082024





BLK: 3,SNR1: 0.34265 ,SNR2: 3.8049




Frequency (Hz)

K20260723082021




BLK: 3,SNR1: 0.40715 ,SNR2: 2.7062





Frequency (Hz)


3C119 2026/07/22 23.37UT FUJI -KISO





T20260723085415




BLK: 5, SNR1: 3.0633 ,SNR2: 7.9765




F20260723085415



BLK: 5, SNR1: 12.430 ,SNR2: 27.524





0503+167 2026/07/22 23.93UT TOYOKAWA-FUJI







T20260723085415




BLK: 1,SNR1: -0.97625E-01,SNR2: 0.94744




K20260723085412




BLK: 1,SNR1: 0.54712E-01,SNR2: 1.9574




0503+167 2026/07/22 23.93UT TOYOKAWA-KISO




F20260723085415




BLK: 9, SNR1: 3.9494 , SNR2: 13.820




K20260723085412




BLK: 9, SNR1: 2.4641 , SNR2: 11.678




0503+167 2026/07/22 23.93UT FUJI -KISO




T20260723090830




BLK:20,SNR1: 2.4581 ,SNR2: 6.3658




F20260723090830




BLK:20,SNR1: 1.4139 ,SNR2: 4.6431




3C138 2026/07/23 0.17UT TOYOKAWA-FUJI




T20260723090830




BLK:21,SNR1: 2.8194 ,SNR2: 7.0251




K20260723090827




BLK:21,SNR1: 1.4787 ,SNR2: 6.1406




3C138 2026/07/23 0.17UT TOYOKAWA-KISO




F20260723090830




BLK:13,SNR1: 0.72506 ,SNR2: 3.3849




K20260723090827





BLK:13,SNR1: 1.0674 ,SNR2: 4.6138




3C138 2026/07/23 0.17UT FUJI -KISO




T20260723092204




BLK: 8,SNR1: 6.7946 ,SNR2: 19.612




F20260723092204





BLK: 8,SNR1: 7.1800 ,SNR2: 20.792




0531+194 2026/07/23 0.40UT TOYOKAWA-FUJI




T20260723092204




BLK: 8, SNR1: 2.6238 , SNR2: 7.5880




K20260723092201





BLK: 8, SNR1: 10.048 , SNR2: 29.145




0531+194 2026/07/23 0.40UT TOYOKAWA-KISO




F20260723092204




BLK: 7,SNR1: 8.4263 ,SNR2: 24.035




K20260723092201



BLK: 7,SNR1: 7.6012 ,SNR2: 21.724




0531+194 2026/07/23 0.40UT FUJI -KISO







T20260723093025




BLK:23,SNR1: 4.7039 ,SNR2: 21.353




F20260723093025




BLK:23,SNR1: 1.1246 ,SNR2: 3.8839




3C147 2026/07/23 0.54UT TOYOKAWA-FUJI




T20260723093025




BLK:24,SNR1: 5.1271 ,SNR2: 12.563




K20260723093022





BLK:24,SNR1: 1.2495 ,SNR2: 4.7549




3C147 2026/07/23 0.54UT TOYOKAWA-KISO





F20260723093025




BLK:16,SNR1: 1.2654 ,SNR2: 4.2224




K20260723093022




BLK:16,SNR1: 1.2919 ,SNR2: 5.1610




3C147 2026/07/23 0.54UT FUJI -KISO




T20260723093835




BLK: 5, SNR1: 23.581 , SNR2: 49.366




F20260723093835





BLK: 5, SNR1: 16.484 , SNR2: 29.091




0548+16 2026/07/23 0.67UT TOYOKAWA-FUJI



T20260723093835





BLK: 3, SNR1: 33.200 , SNR2: 57.160





0548+16 2026/07/23 0.67UT TOYOKAWA-KISO


K20260723093832




BLK: 3, SNR1: 22.378 , SNR2: 48.406




F20260723093835




BLK: 5, SNR1: 17.299 , SNR2: 30.490




K20260723093832





BLK: 5, SNR1: 19.916 , SNR2: 45.515




0548+16 2026/07/23 0.67UT FUJI -KISO





T20260723094245




BLK: 3,SNR1: 2.1512 ,SNR2: 6.3058




F20260723094245





BLK: 3,SNR1: 1.8788 ,SNR2: 4.7769




0552+12 2026/07/23 0.74UT TOYOKAWA-FUJI




T20260723094245




BLK: 4, SNR1: 0.37812 , SNR2: 1.8381




K20260723094242



BLK: 4, SNR1: 3.9420 , SNR2: 12.725





0552+12 2026/07/23 0.74UT TOYOKAWA-KISO







F20260723094245




BLK: 3, SNR1: 3.3365 , SNR2: 6.7465




K20260723094242





BLK: 3, SNR1: 6.5773 , SNR2: 12.932




0552+12 2026/07/23 0.74UT FUJI -KISO





T20260723094712




BLK: 8, SNR1: 1.7642 , SNR2: 4.7049




F20260723094712





BLK: 8, SNR1: 5.1980 , SNR2: 12.689




0556+191 2026/07/23 0.81UT TOYOKAWA-FUJI





T20260723094712




BLK: 8,SNR1: 2.0010 ,SNR2: 3.2028




K20260723094709




BLK: 8,SNR1: 8.5042 ,SNR2: 15.183




0556+191 2026/07/23 0.81UT TOYOKAWA-KISO




F20260723094712




BLK: 7,SNR1: 2.1710 ,SNR2: 7.1237




K20260723094709




BLK: 7,SNR1: 7.1145 ,SNR2: 18.297




0556+191 2026/07/23 0.81UT FUJI -KISO




T20260723095457




BLK: 3,SNR1:-0.66656E-01,SNR2: 0.85662




F20260723095457




BLK: 3,SNR1: 2.7536 ,SNR2: 9.4749




0605-08 2026/07/23 0.94UT TOYOKAWA-FUJI




T20260723095457




BLK: 5, SNR1: 0.46575 , SNR2: 1.7553




K20260723095454




BLK: 5, SNR1: 2.7173 , SNR2: 5.8309




0605-08 2026/07/23 0.94UT TOYOKAWA-KISO




F20260723095457




BLK: 4, SNR1: 7.2577 , SNR2: 18.351




K20260723095454





BLK: 4, SNR1: 1.4028 , SNR2: 7.6116




0605-08 2026/07/23 0.94UT FUJI -KISO




T20260723101405




BLK:13,SNR1: 7.5430 ,SNR2: 13.150




F20260723101405



BLK:13,SNR1: 2.0166 ,SNR2: 6.6271





3C161 2026/07/23 1.26UT TOYOKAWA-FUJI








T20260723101405




BLK:20,SNR1: 6.4741 ,SNR2: 11.367




K20260723101402





BLK:20,SNR1: 5.6276 ,SNR2: 14.251




3C161 2026/07/23 1.26UT TOYOKAWA-KISO



F20260723101405





BLK:23,SNR1: 1.7555 ,SNR2: 5.7257




Frequency (Hz)

3C161 2026/07/23 1.26UT FUJI -KISO


K20260723101402





BLK:23,SNR1: 17.568 ,SNR2: 39.469




Frequency (Hz)





T20260723104138




BLK: 4, SNR1: 0.41902 , SNR2: 1.7971




F20260723104138





BLK: 4, SNR1: 1.0596 , SNR2: 3.7979




0652-130 2026/07/23 1.72UT TOYOKAWA-FUJI




T20260723104138




BLK:13,SNR1: 0.42772 ,SNR2: 2.1814




K20260723104135




BLK:13,SNR1: 4.3055 ,SNR2: 19.268




0652-130 2026/07/23 1.72UT TOYOKAWA-KISO




F20260723104138




BLK: 7, SNR1: 2.7750 , SNR2: 8.3750




K20260723104135





BLK: 7, SNR1: 4.6545 , SNR2: 20.313




0652-130 2026/07/23 1.72UT FUJI -KISO





T20260723105315




BLK: 2, SNR1: 11.622 , SNR2: 28.319




F20260723105315





BLK: 2, SNR1: 11.396 , SNR2: 27.367




0703+138 2026/07/23 1.92UT TOYOKAWA-FUJI





T20260723105315




BLK: 1, SNR1: 19.659 , SNR2: 35.289




K20260723105312





BLK: 1, SNR1: 9.8084 , SNR2: 24.532




0703+138 2026/07/23 1.92UT TOYOKAWA-KISO




F20260723105315




BLK: 1, SNR1: 20.928 , SNR2: 37.527




K20260723105312



BLK: 1, SNR1: 14.415 , SNR2: 26.035




0703+138 2026/07/23 1.92UT FUJI -KISO







T20260723110237




BLK: 6,SNR1: 0.34094 ,SNR2: 1.7238




F20260723110237




BLK: 6,SNR1: 5.2949 ,SNR2: 14.547




0713-024 2026/07/23 2.07UT TOYOKAWA-FUJI




T20260723110237




BLK: 9,SNR1: 0.25604 ,SNR2: 1.2862




K20260723110234




BLK: 9,SNR1: 0.73845 ,SNR2: 3.1266




0713-024 2026/07/23 2.07UT TOYOKAWA-KISO





F20260723110237




BLK: 1, SNR1: 1.0803 , SNR2: 5.8082




K20260723110234





BLK: 1, SNR1: 0.36827 , SNR2: 3.9801




0713-024 2026/07/23 2.07UT FUJI -KISO




T20260723111250




BLK: 7,SNR1: 2.7503 ,SNR2: 6.9949




F20260723111250





BLK: 7,SNR1: 1.1177 ,SNR2: 2.8051




0723+10 2026/07/23 2.24UT TOYOKAWA-FUJI




T20260723111250




BLK:12,SNR1: 7.6901 ,SNR2: 13.718




K20260723111247




BLK:12,SNR1: 0.81213 ,SNR2: 2.6702




0723+10 2026/07/23 2.24UT TOYOKAWA-KISO




F20260723111250




BLK: 4, SNR1: 1.4377 , SNR2: 4.2403




K20260723111247





BLK: 4, SNR1: 0.41094 , SNR2: 3.9115




0723+10 2026/07/23 2.24UT FUJI -KISO




T20260723112305




BLK: 6, SNR1: 1.5110 , SNR2: 4.5355




F20260723112305





BLK: 6, SNR1: 11.149 , SNR2: 20.072




0732+33 2026/07/23 2.41UT TOYOKAWA-FUJI




T20260723112305




BLK: 9, SNR1: 5.5691 , SNR2: 8.4115




K20260723112302



BLK: 9, SNR1: 1.1899 , SNR2: 5.9487




0732+33 2026/07/23 2.41UT TOYOKAWA-KISO







F20260723112305




BLK: 6,SNR1: 9.0011 ,SNR2: 16.110




K20260723112302





BLK: 6,SNR1: 5.0334 ,SNR2: 8.5854




0732+33 2026/07/23 2.41UT FUJI -KISO





T20260723113105




BLK: 8,SNR1: 0.69861 ,SNR2: 3.3075




F20260723113105




BLK: 8,SNR1: 1.8177 ,SNR2: 6.5972




0741-06 2026/07/23 2.55UT TOYOKAWA-FUJI




T20260723113105




BLK: 7,SNR1: 0.83722 ,SNR2: 4.7266




K20260723113102




BLK: 7,SNR1: 1.4947 ,SNR2: 5.4014




0741-06 2026/07/23 2.55UT TOYOKAWA-KISO




F20260723113105




BLK: 4,SNR1: 2.9555 ,SNR2: 9.9738




K20260723113102




BLK: 4,SNR1: 2.0512 ,SNR2: 6.8722





0741-06 2026/07/23 2.55UT FUJI -KISO











BLK: 9,SNR1: 2.2418 ,SNR2: 4.9470




BLK: 9,SNR1: 0.11751 ,SNR2: 1.0660







0752-200 2026/07/23 2.71UT TOYOKAWA-KISO





F20260723114049




BLK: 3,SNR1:-0.20708 ,SNR2: 0.35538




K20260723114047




BLK: 3,SNR1: 0.20405 ,SNR2: 1.4324




0752-200 2026/07/23 2.71UT FUJI -KISO



T20260723114825




BLK:16,SNR1: 1.4047 ,SNR2: 11.684





3C190 2026/07/23 2.84UT TOYOKAWA-FUJI

F20260723114825




BLK:16,SNR1: 4.4599 ,SNR2: 8.5289







T20260723114825




BLK: 5, SNR1: 4.9140 , SNR2: 11.567




K20260723114822





BLK: 5, SNR1: 1.4865 , SNR2: 6.9053




3C190 2026/07/23 2.84UT TOYOKAWA-KISO





F20260723114825




BLK:15,SNR1: 3.1622 ,SNR2: 7.8409




K20260723114822




BLK:15,SNR1: 4.1948 ,SNR2: 8.3545




3C190 2026/07/23 2.84UT FUJI -KISO





T20260723120052




BLK:14,SNR1: 5.7842 ,SNR2: 12.825




F20260723120052




BLK:14,SNR1: 0.21071 ,SNR2: 1.4164




3C196 2026/07/23 3.04UT TOYOKAWA-FUJI





T20260723120052




BLK:18,SNR1: 4.2487 ,SNR2: 9.3976




K20260723120049





BLK:18,SNR1: 0.80858 ,SNR2: 3.6379




3C196 2026/07/23 3.04UT TOYOKAWA-KISO





F20260723120052




BLK:13,SNR1: 0.11550 ,SNR2: 1.1867




K20260723120049





BLK:13,SNR1: 0.71904 ,SNR2: 2.1317




3C196 2026/07/23 3.04UT FUJI -KISO




T20260723121201




BLK: 6,SNR1: 36.238 ,SNR2: 113.37




F20260723121201





BLK: 6,SNR1: 8.8852 ,SNR2: 15.603




0821+394 2026/07/23 3.23UT TOYOKAWA-FUJI




T20260723121201




BLK: 8,SNR1: 38.512 ,SNR2: 69.166




K20260723121158




BLK: 8,SNR1: 1.7875 ,SNR2: 7.0654




0821+394 2026/07/23 3.23UT TOYOKAWA-KISO




F20260723121201




BLK: 5,SNR1: 7.2633 ,SNR2: 25.572




K20260723121158



BLK: 5,SNR1: 2.1397 ,SNR2: 7.8744




0821+394 2026/07/23 3.23UT FUJI -KISO







T20260723122339




BLK:16,SNR1: 0.85904 ,SNR2: 2.3689




F20260723122339




BLK:16,SNR1: 1.9304 ,SNR2: 4.5443




0834-19 2026/07/23 3.42UT TOYOKAWA-FUJI





T20260723122339




BLK: 9,SNR1: 0.69273 ,SNR2: 4.8223




K20260723122336




BLK: 9,SNR1: 0.59113 ,SNR2: 2.2202




0834-19 2026/07/23 3.42UT TOYOKAWA-KISO





F20260723122339




BLK:11,SNR1: 2.3566 ,SNR2: 5.4167




K20260723122336





BLK:11,SNR1: 2.5607 ,SNR2: 12.148




0834-19 2026/07/23 3.42UT FUJI -KISO





T20260723122844




BLK:15,SNR1: 2.3016 ,SNR2: 5.6728




F20260723122844





BLK:15,SNR1: 1.6660 ,SNR2: 5.4338




0839-071 2026/07/23 3.51UT TOYOKAWA-FUJI





T20260723122844




BLK:21,SNR1: 3.6677 ,SNR2: 8.7941




K20260723122841




BLK:21,SNR1: 6.4911 ,SNR2: 16.946




0839-071 2026/07/23 3.51UT TOYOKAWA-KISO




F20260723122844




BLK:25,SNR1: 3.8853 ,SNR2: 8.9915




K20260723122841




BLK:25,SNR1: 7.2117 ,SNR2: 18.769




0839-071 2026/07/23 3.51UT FUJI -KISO



T20260723123946




BLK: 1,SNR1: 16.760 ,SNR2: 33.621




Frequency (Hz)

F20260723123946




BLK: 1,SNR1: 20.777 ,SNR2: 36.875




Frequency (Hz)


3C208 2026/07/23 3.69UT TOYOKAWA-FUJI




T20260723123946




BLK: 3,SNR1: 12.421 ,SNR2: 28.685




K20260723123943



BLK: 3,SNR1: 141.58 ,SNR2: 136.86




3C208 2026/07/23 3.69UT TOYOKAWA-KISO







F20260723123946




BLK: 1,SNR1: 14.147 ,SNR2: 24.877




K20260723123943




BLK: 1,SNR1: 11.848 ,SNR2: 23.029




3C208 2026/07/23 3.69UT FUJI -KISO




T20260723125628




BLK: 4,SNR1: 10.435 ,SNR2: 18.305




F20260723125628




BLK: 4,SNR1: 18.017 ,SNR2: 27.269





3C216 2026/07/23 3.97UT TOYOKAWA-FUJI







BLK: 5,SNR1: 10.437 ,SNR2: 18.270




BLK: 5,SNR1: 13.847 ,SNR2: 30.681




3C216 2026/07/23 3.97UT TOYOKAWA-KISO




F20260723125628




BLK: 8,SNR1: 13.753 ,SNR2: 24.481




K20260723125625





BLK: 8,SNR1: 13.517 ,SNR2: 23.771




3C216 2026/07/23 3.97UT FUJI -KISO




T20260723130838




BLK: 1,SNR1:-0.28079 ,SNR2: 0.0000




F20260723130838




BLK: 1,SNR1:-0.97025E-01,SNR2: 1.9227




0919-142 2026/07/23 4.17UT TOYOKAWA-FUJI





T20260723130838




BLK: 8,SNR1: 0.52428E-02,SNR2: 0.85729




K20260723130835




BLK: 8,SNR1: 0.71099,SNR2: 2.4749




0919-142 2026/07/23 4.17UT TOYOKAWA-KISO





F20260723130838




BLK: 4,SNR1: 0.62295E-02,SNR2: 1.3068




K20260723130835





BLK: 4,SNR1: 0.52354,SNR2: 1.7072




0919-142 2026/07/23 4.17UT FUJI -KISO




T20260723131518




BLK: 6,SNR1: 18.331 ,SNR2: 32.626




F20260723131518



BLK: 6,SNR1: 16.710 ,SNR2: 29.487




0926+117 2026/07/23 4.28UT TOYOKAWA-FUJI







T20260723131518




BLK: 7,SNR1: 14.847 ,SNR2: 25.757




K20260723131515




BLK: 7,SNR1: 16.359 ,SNR2: 28.845





0926+117 2026/07/23 4.28UT TOYOKAWA-KISO







BLK: 4,SNR1: 12.857 ,SNR2: 31.018




BLK: 4,SNR1: 16.162 ,SNR2: 28.490




0926+117 2026/07/23 4.28UT FUJI -KISO




T20260723132302




BLK:12,SNR1: 2.8643 ,SNR2: 8.8455




F20260723132302




BLK:12,SNR1: 1.5153 ,SNR2: 8.0728




3C222 2026/07/23 4.41UT TOYOKAWA-FUJI




T20260723132302




BLK:18,SNR1: 2.7167 ,SNR2: 8.4085




K20260723132259




BLK:18,SNR1: 8.0998 ,SNR2: 14.193




3C222 2026/07/23 4.41UT TOYOKAWA-KISO





F20260723132302




BLK:17,SNR1: 1.3292 ,SNR2: 7.3245




K20260723132259




BLK:17,SNR1: 8.0392 ,SNR2: 20.831




3C222 2026/07/23 4.41UT FUJI -KISO




T20260723133002




BLK: 5,SNR1: 0.35835 ,SNR2: 1.1930




F20260723133002





BLK: 5,SNR1: 0.12353 ,SNR2: 1.0522




0941-08 2026/07/23 4.53UT TOYOKAWA-FUJI








0941-08 2026/07/23 4.53UT TOYOKAWA-KISO





F20260723133002




BLK: 8,SNR1: 1.1118 ,SNR2: 1.9685




K20260723132959



BLK: 8,SNR1: 0.23716 ,SNR2: 0.83414





0941-08 2026/07/23 4.53UT FUJI -KISO






T20260723133824





BLK: 3,SNR1: 3.9050 ,SNR2: 12.133




Frequency (Hz)

F20260723133824




BLK: 3,SNR1: 6.7492 ,SNR2: 16.622





Frequency (Hz)


3C230 2026/07/23 4.67UT TOYOKAWA-FUJI




T20260723133824




BLK: 6,SNR1: 6.9143 ,SNR2: 20.280




K20260723133821




BLK: 6,SNR1: 10.512 ,SNR2: 27.124




3C230 2026/07/23 4.67UT TOYOKAWA-KISO




F20260723133824




BLK: 8, SNR1: 8.0711, SNR2: 19.764




K20260723133821





BLK: 8, SNR1: 8.2042, SNR2: 21.731




3C230 2026/07/23 4.67UT FUJI -KISO





T20260723135232




BLK: 4,SNR1: 5.2878 ,SNR2: 9.4393




F20260723135232





BLK: 4,SNR1: 10.050 ,SNR2: 22.944




3C236 2026/07/23 4.90UT TOYOKAWA-FUJI





T20260723135232




BLK:15,SNR1: 6.3415 ,SNR2: 11.725




K20260723135229





BLK:15,SNR1: 8.7484 ,SNR2: 15.323




3C236 2026/07/23 4.90UT TOYOKAWA-KISO





F20260723135232




BLK:13,SNR1: 3.5075 ,SNR2: 10.464




K20260723135229





BLK:13,SNR1: 8.0173 ,SNR2: 20.814




3C236 2026/07/23 4.90UT FUJI -KISO




T20260723140041




BLK: 1,SNR1: 0.18178 ,SNR2: 1.4510




F20260723140041





BLK: 1,SNR1: 1.1455 ,SNR2: 7.1588




1011+110 2026/07/23 5.04UT TOYOKAWA-FUJI




T20260723140041




BLK: 3,SNR1: 0.43899E-01,SNR2: 0.74582




K20260723140038



BLK: 3,SNR1: 0.42440 ,SNR2: 3.2177





1011+110 2026/07/23 5.04UT TOYOKAWA-KISO







F20260723140041




BLK: 2,SNR1: 0.34615 ,SNR2: 2.4955




K20260723140038





BLK: 2,SNR1: 0.72721 ,SNR2: 3.4948




1011+110 2026/07/23 5.04UT FUJI -KISO




T20260723140822




BLK:11,SNR1: 0.63327 ,SNR2: 3.5121




F20260723140822




BLK:11,SNR1: 8.8383 ,SNR2: 18.117




3C241 2026/07/23 5.17UT TOYOKAWA-FUJI




T20260723140822




BLK: 8,SNR1: 0.32759 ,SNR2: 1.1689




K20260723140819




BLK: 8,SNR1: 1.7814 ,SNR2: 8.4455




3C241 2026/07/23 5.17UT TOYOKAWA-KISO




F20260723140822




BLK: 8,SNR1: 4.5270 ,SNR2: 10.274




K20260723140819





BLK: 8,SNR1: 3.0364 ,SNR2: 14.715




3C241 2026/07/23 5.17UT FUJI -KISO



T20260723141951





No.Good Data




Frequency (Hz)

F20260723141951





No.Good Data





Frequency (Hz)

1031-11 2026/07/23 5.36UT TOYOKAWA-FUJI







BLK: 1,SNR1: 0.46184 ,SNR2: 9.1850








BLK: 1,SNR1: 11.420 ,SNR2: 25.078





1031-11 2026/07/23 5.36UT TOYOKAWA-KISO








T20260723142425




BLK: 3,SNR1: 16.922 ,SNR2: 29.302




F20260723142425




BLK: 3,SNR1: 10.773 ,SNR2: 26.429





1035-058 2026/07/23 5.44UT TOYOKAWA-FUJI









BLK: 3,SNR1: 6.5355 ,SNR2: 18.867





BLK: 3,SNR1: 8.7996 ,SNR2: 21.717




1035-058 2026/07/23 5.44UT TOYOKAWA-KISO





F20260723142425




BLK: 3,SNR1: 6.9477 ,SNR2: 20.322




K20260723142422





BLK: 3,SNR1: 6.3694 ,SNR2: 18.167




1035-058 2026/07/23 5.44UT FUJI -KISO




T20260723143337




BLK: 4,SNR1: 0.56702 ,SNR2: 2.0390




F20260723143337





BLK: 4,SNR1: 1.8427 ,SNR2: 6.9711




1044-008 2026/07/23 5.59UT TOYOKAWA-FUJI





T20260723143337




BLK: 3,SNR1: 0.73620 ,SNR2: 3.8086




K20260723143334





BLK: 3,SNR1: 0.68163 ,SNR2: 3.9057




1044-008 2026/07/23 5.59UT TOYOKAWA-KISO





F20260723143337




BLK: 5,SNR1: 1.0971 ,SNR2: 4.5745




K20260723143334





BLK: 5,SNR1: 1.0066 ,SNR2: 3.1158




1044-008 2026/07/23 5.59UT FUJI -KISO





T20260723144442




BLK: 1,SNR1: 9.7105 ,SNR2: 21.123




F20260723144442





BLK: 1,SNR1: 24.400 ,SNR2: 46.611




1055+01 2026/07/23 5.77UT TOYOKAWA-FUJI





T20260723144442




BLK: 2,SNR1: 14.381 ,SNR2: 29.842




K20260723144439





BLK: 2,SNR1: 12.974 ,SNR2: 27.214




1055+01 2026/07/23 5.77UT TOYOKAWA-KISO





F20260723144442




BLK: 3,SNR1: 16.890 ,SNR2: 32.082




K20260723144439



BLK: 3,SNR1: 15.175 ,SNR2: 31.517





1055+01 2026/07/23 5.77UT FUJI -KISO







T20260723145559




BLK: 1,SNR1: 7.4432 ,SNR2: 18.280




F20260723145600





BLK: 1,SNR1: 2.0505 ,SNR2: 8.9436




1107+109 2026/07/23 5.96UT TOYOKAWA-FUJI




T20260723145559




BLK: 1,SNR1: 10.708 ,SNR2: 18.624




K20260723145556





BLK: 1,SNR1: 2.7961 ,SNR2: 7.6402




1107+109 2026/07/23 5.96UT TOYOKAWA-KISO



F20260723145600





No.Good Data




Frequency (Hz)

K20260723145556





No.Good Data





Frequency (Hz)

1107+109 2026/07/23 5.96UT FUJI -KISO








BLK:10,SNR1: 5.8181 ,SNR2: 17.092





BLK:10,SNR1: 8.0045 ,SNR2: 21.655







BLK: 4,SNR1: 3.8047 ,SNR2: 11.100





BLK: 4,SNR1: 11.719 ,SNR2: 28.897




3C255 2026/07/23 6.12UT TOYOKAWA-KISO




F20260723150538




BLK:10,SNR1: 7.5664 ,SNR2: 19.509




K20260723150534




BLK:10,SNR1: 9.3020 ,SNR2: 23.608




3C255 2026/07/23 6.12UT FUJI -KISO




T20260723151614




BLK: 2,SNR1: 8.7188 ,SNR2: 15.556




F20260723151615




BLK: 2,SNR1: 12.874 ,SNR2: 40.115




1127-14 2026/07/23 6.30UT TOYOKAWA-FUJI



T20260723151614




BLK: 1,SNR1: 10.854 ,SNR2: 27.002




Frequency (Hz)

K20260723151611




BLK: 1,SNR1: 10.861 ,SNR2: 26.954




Frequency (Hz)

1127-14 2026/07/23 6.30UT TOYOKAWA-KISO







F20260723151615




BLK: 8,SNR1: 11.612 ,SNR2: 28.425




K20260723151611




BLK: 8,SNR1: 11.471 ,SNR2: 28.117





1127-14 2026/07/23 6.30UT FUJI -KISO







BLK: 9,SNR1: 19.348 ,SNR2: 54.642







BLK: 9,SNR1: 8.7710 ,SNR2: 25.730




3C263.1 2026/07/23 6.52UT TOYOKAWA-FUJI








3C263.1 2026/07/23 6.52UT TOYOKAWA-KISO





F20260723152936




BLK: 4,SNR1: 9.6307 ,SNR2: 24.764




K20260723152932





BLK: 4,SNR1: 12.312 ,SNR2: 29.954




3C263.1 2026/07/23 6.52UT FUJI -KISO




T20260723153602




BLK: 4,SNR1: 8.1219 ,SNR2: 20.028




F20260723153603




BLK: 4,SNR1: 10.400 ,SNR2: 25.403





3C267 2026/07/23 6.63UT TOYOKAWA-FUJI







BLK: 2,SNR1: 7.8398 ,SNR2: 19.526




BLK: 2,SNR1: 9.0216 ,SNR2: 22.212




3C267 2026/07/23 6.63UT TOYOKAWA-KISO





F20260723153603




BLK: 5, SNR1: 13.426 , SNR2: 32.295




K20260723153559




BLK: 5, SNR1: 2.2552 , SNR2: 10.486





3C267 2026/07/23 6.63UT FUJI -KISO







BLK: 3,SNR1: 8.9637 ,SNR2: 25.507







BLK: 3,SNR1: 11.151 ,SNR2: 28.402




1213-17 2026/07/23 7.06UT TOYOKAWA-FUJI









1213-17 2026/07/23 7.06UT TOYOKAWA-KISO




F20260723160150




BLK: 2, SNR1: 8.6319 , SNR2: 24.976




K20260723160146





BLK: 2, SNR1: 12.192 , SNR2: 35.147




1213-17 2026/07/23 7.06UT FUJI -KISO



T20260723161507





BLK: 5, SNR1: 3.3646 , SNR2: 8.3115




Frequency (Hz)

F20260723161508




BLK: 5, SNR1: 6.5261 , SNR2: 17.940





Frequency (Hz)


3C273 2026/07/23 7.28UT TOYOKAWA-FUJI





T20260723161507




BLK: 4, SNR1: 7.5766 , SNR2: 19.174




K20260723161504




BLK: 4, SNR1: 11.071 , SNR2: 28.571




3C273 2026/07/23 7.28UT TOYOKAWA-KISO




F20260723161508




BLK: 5, SNR1: 4.3125 , SNR2: 12.449




K20260723161504




BLK: 5, SNR1: 11.494 , SNR2: 28.943





3C273 2026/07/23 7.28UT FUJI -KISO







BLK: 5,SNR1: 8.8088 ,SNR2: 19.831




BLK: 5,SNR1: 7.5009 ,SNR2: 17.068




3C275 2026/07/23 7.50UT TOYOKAWA-FUJI



T20260723162817




BLK: 3,SNR1: 9.3299 ,SNR2: 20.992




Frequency (Hz)

K20260723162814




BLK: 3,SNR1: 10.993 ,SNR2: 24.653




Frequency (Hz)


3C275 2026/07/23 7.50UT TOYOKAWA-KISO



F20260723162818




BLK:10,SNR1: 7.4800 ,SNR2: 16.952




Frequency (Hz)

K20260723162814




BLK:10,SNR1: 9.3234 ,SNR2: 21.250




Frequency (Hz)


3C275 2026/07/23 7.50UT FUJI -KISO










BLK: 4,SNR1: 7.2123 ,SNR2: 11.479







3C279 2026/07/23 7.73UT TOYOKAWA-FUJI




BLK: 4,SNR1: 1.6965 ,SNR2: 7.9821







3C279 2026/07/23 7.73UT TOYOKAWA-KISO




F20260723164207




BLK: 5, SNR1: 1.3295 , SNR2: 5.9532




K20260723164203







BLK: 5, SNR1: 2.9697 , SNR2: 8.9416




3C279 2026/07/23 7.73UT FUJI -KISO








1313+453 2026/07/23 8.06UT TOYOKAWA-FUJI



T20260723170153




BLK: 5, SNR1: 1.2848 , SNR2: 3.4931




Frequency (Hz)

K20260723170150









BLK: 5, SNR1: 2.0553 , SNR2: 6.4813




Frequency (Hz)

1313+453 2026/07/23 8.06UT TOYOKAWA-KISO






T20260723171159





BLK:13,SNR1: 1.4910 ,SNR2: 6.6393




Frequency (Hz)

F20260723171200








BLK:13,SNR1: 22.634 ,SNR2: 24.575




Frequency (Hz)

1323+32 2026/07/23 8.23UT TOYOKAWA-FUJI














1323+32 2026/07/23 8.23UT TOYOKAWA-KISO















3C286 2026/07/23 8.31UT TOYOKAWA-FUJI








3C286 2026/07/23 8.31UT TOYOKAWA-KISO



F20260723171651





BLK: 1, SNR1: 1.6514 , SNR2: 4.3705




Frequency (Hz)

K20260723171647




BLK: 1, SNR1: 0.93683 , SNR2: 3.5572





Frequency (Hz)


3C286 2026/07/23 8.31UT FUJI -KISO



T20260723175612




BLK: 7, SNR1: 11.969 , SNR2: 28.518




Frequency (Hz)

F20260723175613




BLK: 7, SNR1: 10.035 , SNR2: 28.480





Frequency (Hz)



1408+370 2026/07/23 8.96UT TOYOKAWA-FUJI



T20260723175612



K20260723175609



1408+370 2026/07/23 8.96UT TOYOKAWA-KISO

