






T20260729062558




BLK: 2,SNR1: -0.84449E-01,SNR2: 0.16952




F20260729062558





BLK: 2,SNR1: 0.54870 ,SNR2: 2.5554




0258+350 2026/07/28 21.46UT TOYOKAWA-FUJI





T20260729062558




No.Good Data




K20260729062555



No.Good Data





0258+350 2026/07/28 21.46UT TOYOKAWA-KISO






F20260729062558





No.Good Data




Frequency (Hz)

K20260729062555







No.Good Data




Frequency (Hz)

0258+350 2026/07/28 21.46UT FUJI -KISO








T20260729063547




BLK: 1, SNR1: 0.52404 , SNR2: 0.95851




K20260729063544





BLK: 1, SNR1: 0.54300 , SNR2: 2.7330




0308+305 2026/07/28 21.62UT TOYOKAWA-KISO





F20260729063547




BLK: 2,SNR1: 9.3422 ,SNR2: 24.233




K20260729063544





BLK: 2,SNR1: 10.772 ,SNR2: 27.301




0308+305 2026/07/28 21.62UT FUJI -KISO





T20260729064718




BLK: 2,SNR1: 0.48808 ,SNR2: 1.7772




F20260729064718





BLK: 2,SNR1: 0.72154 ,SNR2: 7.6308






0320+05 2026/07/28 21.82UT TOYOKAWA-FUJI







BLK: 2, SNR1: 0.46085 , SNR2: 2.3368





BLK: 2, SNR1: 13.485 , SNR2: 32.365




0320+05 2026/07/28 21.82UT TOYOKAWA-KISO




F20260729064718




BLK: 3, SNR1: 12.471 , SNR2: 29.114




K20260729064715





BLK: 3, SNR1: 13.008 , SNR2: 32.010




0320+05 2026/07/28 21.82UT FUJI -KISO




T20260729070040




BLK: 4, SNR1: 0.12428 , SNR2: 0.45094




F20260729070040



BLK: 4, SNR1: 0.39256 , SNR2: 3.2874





0333+32 2026/07/28 22.04UT TOYOKAWA-FUJI







T20260729070040




BLK: 2,SNR1: 0.10847 ,SNR2: 0.85625




K20260729070037





BLK: 2,SNR1: 0.75326 ,SNR2: 1.9035




0333+32 2026/07/28 22.04UT TOYOKAWA-KISO




F20260729070040




BLK: 4, SNR1: 0.22019 , SNR2: 2.8103




K20260729070037





BLK: 4, SNR1: 0.61778 , SNR2: 1.4399




0333+32 2026/07/28 22.04UT FUJI -KISO



T20260729071341





BLK: 3,SNR1: 3.7142 ,SNR2: 9.3757




Frequency (Hz)

F20260729071341





BLK: 3,SNR1: 12.900 ,SNR2: 23.096





Frequency (Hz)

0347+05 2026/07/28 22.26UT TOYOKAWA-FUJI







BLK: 6,SNR1: 3.8270 ,SNR2: 9.4258







BLK: 6,SNR1: 8.2137 ,SNR2: 20.733




0347+05 2026/07/28 22.26UT TOYOKAWA-KISO







0347+05 2026/07/28 22.26UT FUJI -KISO





T20260729072914




BLK: 8, SNR1: 8.0084 , SNR2: 18.635




F20260729072914




BLK: 8, SNR1: 15.531 , SNR2: 32.059




0403-132 2026/07/28 22.52UT TOYOKAWA-FUJI




T20260729072914




BLK: 4, SNR1: 12.374 , SNR2: 25.528




K20260729072911




BLK: 4, SNR1: 24.080 , SNR2: 38.994




0403-132 2026/07/28 22.52UT TOYOKAWA-KISO




F20260729072914




BLK: 8,SNR1: 18.203 ,SNR2: 37.138




K20260729072911



BLK: 8,SNR1: 17.933 ,SNR2: 29.085





0403-132 2026/07/28 22.52UT FUJI -KISO






T20260729073826





BLK: 1, SNR1: 0.98028 , SNR2: 6.3743




Frequency (Hz)

F20260729073826




BLK: 1, SNR1: 11.698 , SNR2: 26.536




Frequency (Hz)


0411+05 2026/07/28 22.67UT TOYOKAWA-FUJI





T20260729073826




BLK: 1, SNR1: 13.919 , SNR2: 24.454




K20260729073823





BLK: 1, SNR1: 17.127 , SNR2: 29.867




0411+05 2026/07/28 22.67UT TOYOKAWA-KISO



F20260729073826





No.Good Data




Frequency (Hz)

K20260729073823




No.Good Data





Frequency (Hz)


0411+05 2026/07/28 22.67UT FUJI -KISO




T20260729074521




BLK: 2,SNR1: 0.18276E-01,SNR2: 1.4752




F20260729074521





BLK: 2,SNR1: 4.3489 ,SNR2: 7.9255





0418+236 2026/07/28 22.78UT TOYOKAWA-FUJI








0418+236 2026/07/28 22.78UT TOYOKAWA-KISO







BLK: 2,SNR1: 3.8422 ,SNR2: 9.3752




BLK: 2,SNR1: 0.21797 ,SNR2: 3.6838




0418+236 2026/07/28 22.78UT FUJI -KISO




T20260729075649




BLK:10,SNR1: 0.28780 ,SNR2: 0.78757




F20260729075649




BLK:10,SNR1: 0.80559 ,SNR2: 2.2286




3C119 2026/07/28 22.98UT TOYOKAWA-FUJI





T20260729075649




BLK:13,SNR1: 0.40604 ,SNR2: 1.6942




K20260729075646



BLK:13,SNR1: 0.97331E-01,SNR2: 0.70627




3C119 2026/07/28 22.98UT TOYOKAWA-KISO








F20260729075649




BLK: 8,SNR1: 0.58747 ,SNR2: 2.2465




K20260729075646




BLK: 8,SNR1: 0.74359E-02,SNR2: 0.68916




3C119 2026/07/28 22.98UT FUJI -KISO




T20260729084455




BLK:16,SNR1: 0.23070 ,SNR2: 1.1278




F20260729084455




BLK:16,SNR1: 0.19961 ,SNR2: 1.5808




3C138 2026/07/28 23.78UT TOYOKAWA-FUJI





T20260729084455




BLK:17,SNR1: 0.29924 ,SNR2: 3.2890




K20260729084452





BLK:17,SNR1:-0.11877E-01,SNR2: 0.52628




3C138 2026/07/28 23.78UT TOYOKAWA-KISO





F20260729084455




BLK: 7,SNR1: 0.40524 ,SNR2: 1.2957




K20260729084452




BLK: 7,SNR1: 0.47491E-01,SNR2: 0.81623




3C138 2026/07/28 23.78UT FUJI -KISO




T20260729090650




BLK:17,SNR1: 4.6233 ,SNR2: 22.003




F20260729090650





BLK:17,SNR1: 1.2630 ,SNR2: 3.5551




3C147 2026/07/29 0.14UT TOYOKAWA-FUJI





T20260729090650




BLK:31,SNR1: 4.1732 ,SNR2: 11.254




K20260729090647




BLK:31,SNR1: 0.18226 ,SNR2: 3.4637




3C147 2026/07/29 0.14UT TOYOKAWA-KISO





F20260729090650




BLK:18,SNR1: 1.4998 ,SNR2: 3.3401




K20260729090647




BLK:18,SNR1: 2.8122 ,SNR2: 7.5851




3C147 2026/07/29 0.14UT FUJI -KISO




T20260729091459




BLK: 7,SNR1: 0.93557E-01,SNR2: 0.38409




F20260729091459



BLK: 7,SNR1: 5.3947 ,SNR2: 12.262




0548+16 2026/07/29 0.28UT TOYOKAWA-FUJI








T20260729091459




BLK: 3,SNR1: 0.28482 ,SNR2: 0.77514




K20260729091456




BLK: 3,SNR1: 1.1395 ,SNR2: 5.7892




0548+16 2026/07/29 0.28UT TOYOKAWA-KISO





F20260729091459




BLK: 1,SNR1: 32.726 ,SNR2: 35.582




K20260729091456




BLK: 1,SNR1: 1.2635 ,SNR2: 7.2089




0548+16 2026/07/29 0.28UT FUJI -KISO




T20260729091910




BLK: 2, SNR1: 11.907 , SNR2: 28.393




F20260729091910




BLK: 2, SNR1: 19.929 , SNR2: 35.826




0552+12 2026/07/29 0.35UT TOYOKAWA-FUJI




T20260729091910




BLK: 7, SNR1: 24.264 , SNR2: 45.244




K20260729091907





BLK: 7, SNR1: 15.131 , SNR2: 26.810




0552+12 2026/07/29 0.35UT TOYOKAWA-KISO





F20260729091910




No.Good Data




K20260729091907




No.Good Data




0552+12 2026/07/29 0.35UT FUJI -KISO





T20260729092337




BLK: 1, SNR1: 0.13441 , SNR2: 3.1154




F20260729092337




BLK: 1, SNR1: 11.460 , SNR2: 28.059




0556+191 2026/07/29 0.42UT TOYOKAWA-FUJI




T20260729092337




BLK: 1,SNR1: 0.56404E-01,SNR2: 0.38691




K20260729092334






BLK: 1,SNR1: 2.1314 ,SNR2: 6.0755







0556+191 2026/07/29 0.42UT TOYOKAWA-KISO













3C152 2026/07/29 0.50UT TOYOKAWA-FUJI







BLK: 8,SNR1: 0.72925E-01,SNR2: 0.78480





BLK: 8,SNR1: 9.8134 ,SNR2: 21.209




3C152 2026/07/29 0.50UT TOYOKAWA-KISO



F20260729092810





BLK: 9,SNR1: 11.533 ,SNR2: 20.614




Frequency (Hz)

K20260729092807




BLK: 9,SNR1: 2.1239 ,SNR2: 6.9933





Frequency (Hz)


3C152 2026/07/29 0.50UT FUJI -KISO




T20260729095030




BLK: 6, SNR1: 1.1079 , SNR2: 10.081




F20260729095030





BLK: 6, SNR1: 0.65581 , SNR2: 5.3227




3C161 2026/07/29 0.87UT TOYOKAWA-FUJI





T20260729095030




BLK:17,SNR1: 0.98856 ,SNR2: 3.8765




K20260729095028




BLK:17,SNR1: 2.2900 ,SNR2: 7.5335




3C161 2026/07/29 0.87UT TOYOKAWA-KISO





F20260729095030




BLK: 6, SNR1: 1.6541 , SNR2: 4.2955




K20260729095028





BLK: 6, SNR1: 2.7262 , SNR2: 5.4987




3C161 2026/07/29 0.87UT FUJI -KISO





T20260729101802




BLK:10,SNR1: 3.1636 ,SNR2: 9.6844




F20260729101802





BLK:10,SNR1: 22.584 ,SNR2: 29.798




0652-130 2026/07/29 1.33UT TOYOKAWA-FUJI





T20260729101802




BLK:18,SNR1: 3.1111 ,SNR2: 9.5539




K20260729101759



BLK:18,SNR1: 8.4137 ,SNR2: 14.733





0652-130 2026/07/29 1.33UT TOYOKAWA-KISO








F20260729101802




BLK:13,SNR1: 11.166 ,SNR2: 23.864




K20260729101759




BLK:13,SNR1: 9.8197 ,SNR2: 16.931





0652-130 2026/07/29 1.33UT FUJI -KISO







BLK: 6,SNR1:-0.18351E-01,SNR2: 0.86886





BLK: 6,SNR1: 0.84077 ,SNR2: 2.4157




0703+138 2026/07/29 1.52UT TOYOKAWA-FUJI





T20260729102940




BLK: 9,SNR1: 0.20053E-01,SNR2: 0.79171




K20260729102937




BLK: 9,SNR1: 3.4566 ,SNR2: 5.3854




0703+138 2026/07/29 1.52UT TOYOKAWA-KISO





F20260729102940




BLK: 8,SNR1: 0.22154 ,SNR2: 0.93731




K20260729102937







BLK: 8,SNR1: 0.29350 ,SNR2: 1.6164









0703+138 2026/07/29 1.52UT FUJI -KISO






0713-024 2026/07/29 1.68UT TOYOKAWA-FUJI







F20260729103902




BLK: 6,SNR1: 15.013 ,SNR2: 25.273




K20260729103859








BLK: 6,SNR1: 7.4563 ,SNR2: 18.307





0713-024 2026/07/29 1.68UT FUJI -KISO










T20260729104914




BLK:15,SNR1: 1.0513 ,SNR2: 3.1803




K20260729104911




BLK:15,SNR1: 5.0556 ,SNR2: 8.2842




0723+10 2026/07/29 1.85UT TOYOKAWA-KISO




F20260729104914




BLK:17,SNR1: 0.29623 ,SNR2: 2.6006




K20260729104911







BLK:17,SNR1: 5.8594 ,SNR2: 13.148




0723+10 2026/07/29 1.85UT FUJI -KISO








0732+33 2026/07/29 2.02UT TOYOKAWA-FUJI





T20260729105930




BLK: 6,SNR1: 5.9346 ,SNR2: 16.839




K20260729105927







BLK: 6,SNR1: 10.660 ,SNR2: 26.773




0732+33 2026/07/29 2.02UT TOYOKAWA-KISO








0732+33 2026/07/29 2.02UT FUJI -KISO





T20260729110730




BLK: 1, SNR1: 0.58209 , SNR2: 4.8775




F20260729110730





BLK: 1, SNR1: 0.20495 , SNR2: 3.6615




0741-06 2026/07/29 2.15UT TOYOKAWA-FUJI



T20260729110730





BLK: 3,SNR1: 0.78828 ,SNR2: 2.9040





0741-06 2026/07/29 2.15UT TOYOKAWA-KISO


K20260729110727




BLK: 3,SNR1: 3.1186 ,SNR2: 8.1348





F20260729110730




No. Good Data




K20260729110727



No. Good Data




0741-06 2026/07/29 2.15UT FUJI -KISO







T20260729111714




BLK:10,SNR1: 0.29208 ,SNR2: 1.1234




F20260729111714




BLK:10,SNR1: 2.8103 ,SNR2: 6.2260




0752-200 2026/07/29 2.32UT TOYOKAWA-FUJI





T20260729111714




BLK:15,SNR1: 1.5691 ,SNR2: 4.9334




K20260729111711





BLK:15,SNR1: 10.738 ,SNR2: 12.848




0752-200 2026/07/29 2.32UT TOYOKAWA-KISO





F20260729111714




BLK:18,SNR1: 2.0031 ,SNR2: 4.8861




K20260729111711







BLK:18,SNR1: 6.2435 ,SNR2: 10.977




0752-200 2026/07/29 2.32UT FUJI -KISO








3C190 2026/07/29 2.44UT TOYOKAWA-FUJI





T20260729112450




BLK: 9,SNR1: 5.0122 ,SNR2: 45.019




K20260729112447





BLK: 9,SNR1: 5.2943 ,SNR2: 13.167




3C190 2026/07/29 2.44UT TOYOKAWA-KISO





F20260729112450




BLK: 3,SNR1: 0.19046 ,SNR2: 1.6673




K20260729112447







BLK: 3,SNR1: 1.4392 ,SNR2: 5.4410









3C190 2026/07/29 2.44UT FUJI -KISO







3C196 2026/07/29 2.65UT TOYOKAWA-FUJI










F20260729113716




BLK:10,SNR1: 0.24538 ,SNR2: 2.3247




K20260729113713




BLK:10,SNR1: 4.9663 ,SNR2: 8.4529




3C196 2026/07/29 2.65UT FUJI -KISO





T20260729114825




BLK: 5,SNR1: 4.9336 ,SNR2: 14.731




F20260729114825




BLK: 5,SNR1: 6.5475 ,SNR2: 16.621




0821+394 2026/07/29 2.84UT TOYOKAWA-FUJI





T20260729114825




BLK: 6,SNR1: 4.4593 ,SNR2: 13.132




K20260729114822




BLK: 6,SNR1: 6.8411 ,SNR2: 17.715




0821+394 2026/07/29 2.84UT TOYOKAWA-KISO





F20260729114825




BLK: 7, SNR1: 7.5969 , SNR2: 19.288




K20260729114822





BLK: 7, SNR1: 10.038 , SNR2: 29.018




0821+394 2026/07/29 2.84UT FUJI -KISO





T20260729120003




No.Good Data




F20260729120003





No.Good Data




0834-19 2026/07/29 3.03UT TOYOKAWA-FUJI





T20260729120003




BLK: 2, SNR1: 8.8954 , SNR2: 21.780




K20260729120000





BLK: 2, SNR1: 9.6287 , SNR2: 23.922




0834-19 2026/07/29 3.03UT TOYOKAWA-KISO



F20260729120003





No. Good Data




Frequency (Hz)

K20260729120000




No. Good Data





Frequency (Hz)


0834-19 2026/07/29 3.03UT FUJI -KISO





T20260729120509




BLK: 2,SNR1: 2.1041 ,SNR2: 10.190




F20260729120509



BLK: 2,SNR1: 2.7188 ,SNR2: 12.255





0839-071 2026/07/29 3.11UT TOYOKAWA-FUJI








T20260729120509




BLK: 2, SNR1: 9.8744 , SNR2: 24.285




K20260729120506





BLK: 2, SNR1: 11.708 , SNR2: 28.679




0839-071 2026/07/29 3.11UT TOYOKAWA-KISO





F20260729120509




BLK: 2,SNR1: 2.7000 ,SNR2: 12.181




K20260729120506





BLK: 2,SNR1: 11.708 ,SNR2: 28.679




0839-071 2026/07/29 3.11UT FUJI -KISO




T20260729121611




BLK: 3,SNR1: 4.1668 ,SNR2: 10.457




F20260729121611





BLK: 3,SNR1: 4.3908 ,SNR2: 9.8996




3C208 2026/07/29 3.30UT TOYOKAWA-FUJI




T20260729121611




BLK: 2, SNR1: 5.3741 , SNR2: 13.266




K20260729121608





BLK: 2, SNR1: 3.9466 , SNR2: 9.9573




3C208 2026/07/29 3.30UT TOYOKAWA-KISO





F20260729121611




BLK: 4,SNR1: 3.7509 ,SNR2: 9.2756




K20260729121608





BLK: 4,SNR1: 3.9199 ,SNR2: 9.4479




3C208 2026/07/29 3.30UT FUJI -KISO



T20260729123253





BLK: 1,SNR1: 3.2748 ,SNR2: 8.3254




Frequency (Hz)

F20260729123253




BLK: 1,SNR1: 4.6612 ,SNR2: 13.915




Frequency (Hz)


3C216 2026/07/29 3.58UT TOYOKAWA-FUJI





T20260729123253




BLK: 4,SNR1: 3.4602 ,SNR2: 10.419




K20260729123250




BLK: 4,SNR1: 34.515 ,SNR2: 78.058




3C216 2026/07/29 3.58UT TOYOKAWA-KISO





F20260729123253




BLK: 2,SNR1: 16.126 ,SNR2: 34.181




K20260729123250



BLK: 2,SNR1: 47.439 ,SNR2: 68.369





3C216 2026/07/29 3.58UT FUJI -KISO








T20260729124503




BLK: 4,SNR1: 8.4387 ,SNR2: 20.840




F20260729124503




BLK: 4,SNR1: 2.1366 ,SNR2: 10.073





0919-142 2026/07/29 3.78UT TOYOKAWA-FUJI







BLK: 1,SNR1: 9.2812 ,SNR2: 22.878





BLK: 1,SNR1: 10.500 ,SNR2: 26.095




0919-142 2026/07/29 3.78UT TOYOKAWA-KISO





F20260729124503




BLK: 1,SNR1: 1.6912 ,SNR2: 8.8254




K20260729124500




BLK: 1,SNR1: 9.2142 ,SNR2: 22.982




0919-142 2026/07/29 3.78UT FUJI -KISO




T20260729125142




BLK: 3, SNR1: 1.3067 , SNR2: 6.8035




F20260729125142





BLK: 3, SNR1: 7.9886 , SNR2: 23.411




0926+117 2026/07/29 3.89UT TOYOKAWA-FUJI





T20260729125142




No. Good Data




K20260729125139





No. Good Data




0926+117 2026/07/29 3.89UT TOYOKAWA-KISO





F20260729125142




No.Good Data




K20260729125139







No.Good Data








0926+117 2026/07/29 3.89UT FUJI -KISO






3C222 2026/07/29 4.02UT TOYOKAWA-FUJI







3C222 2026/07/29 4.02UT TOYOKAWA-KISO







F20260729125927




BLK: 7, SNR1: 9.0342 , SNR2: 26.656




K20260729125924




BLK: 7, SNR1: 8.6045 , SNR2: 21.087





3C222 2026/07/29 4.02UT FUJI -KISO







BLK: 2,SNR1: 8.0629 ,SNR2: 19.895




BLK: 2,SNR1: 7.0650 ,SNR2: 17.504





0941-08 2026/07/29 4.14UT TOYOKAWA-FUJI







BLK: 5,SNR1: 6.4573 ,SNR2: 20.424




BLK: 5,SNR1: 7.3879 ,SNR2: 24.071





0941-08 2026/07/29 4.14UT TOYOKAWA-KISO







BLK: 6,SNR1: 6.8012 ,SNR2: 20.809





BLK: 6,SNR1: 7.4956 ,SNR2: 23.934




0941-08 2026/07/29 4.14UT FUJI -KISO




T20260729131449




BLK: 3,SNR1: 0.53625 ,SNR2: 2.2208




F20260729131449





BLK: 3,SNR1: 0.38353 ,SNR2: 1.9131




3C230 2026/07/29 4.28UT TOYOKAWA-FUJI





T20260729131449




BLK: 5,SNR1: 0.42591 ,SNR2: 3.2530




K20260729131446




BLK: 5,SNR1: 0.74860E-04,SNR2: 0.54919





3C230 2026/07/29 4.28UT TOYOKAWA-KISO







BLK: 4,SNR1: 0.33017 ,SNR2: 1.3199





BLK: 4,SNR1: 0.18274 ,SNR2: 1.6708




3C230 2026/07/29 4.28UT FUJI -KISO





T20260729132856




BLK: 6,SNR1: 11.151 ,SNR2: 27.360




F20260729132856



BLK: 6,SNR1: 8.8880 ,SNR2: 22.012





3C236 2026/07/29 4.51UT TOYOKAWA-FUJI







T20260729132856




BLK: 2,SNR1: 15.438 ,SNR2: 37.119




K20260729132853





BLK: 2,SNR1: 9.8101 ,SNR2: 24.116




3C236 2026/07/29 4.51UT TOYOKAWA-KISO




F20260729132856




BLK: 4, SNR1: 21.728 , SNR2: 37.115




K20260729132853




BLK: 4, SNR1: 8.3275 , SNR2: 20.639




3C236 2026/07/29 4.51UT FUJI -KISO




T20260729133706




BLK: 3,SNR1: 0.84246 ,SNR2: 5.4563




F20260729133706




BLK: 3,SNR1: 0.46185 ,SNR2: 1.1678




1011+110 2026/07/29 4.65UT TOYOKAWA-FUJI





T20260729133706




BLK: 3,SNR1: 10.445 ,SNR2: 22.349




K20260729133703




BLK: 3,SNR1: 7.2605 ,SNR2: 17.234




1011+110 2026/07/29 4.65UT TOYOKAWA-KISO





F20260729133706




BLK: 3,SNR1: 1.1464 ,SNR2: 3.1139




K20260729133703





BLK: 3,SNR1: 9.0810 ,SNR2: 23.334




1011+110 2026/07/29 4.65UT FUJI -KISO





T20260729134447




BLK: 2,SNR1: 6.5002 ,SNR2: 22.352




F20260729134447





BLK: 2,SNR1: 13.821 ,SNR2: 33.692




3C241 2026/07/29 4.77UT TOYOKAWA-FUJI





T20260729134447




BLK: 2,SNR1: 10.582 ,SNR2: 26.086




K20260729134444





BLK: 2,SNR1: 13.521 ,SNR2: 33.122




3C241 2026/07/29 4.77UT TOYOKAWA-KISO





F20260729134447




BLK: 5, SNR1: 11.850 , SNR2: 29.004




K20260729134444



BLK: 5, SNR1: 13.801 , SNR2: 33.664





3C241 2026/07/29 4.77UT FUJI -KISO








T20260729135616




BLK: 3,SNR1: 8.8097 ,SNR2: 22.954




F20260729135616





BLK: 3,SNR1: 7.6018 ,SNR2: 22.317




1031-11 2026/07/29 4.97UT TOYOKAWA-FUJI





T20260729135616




BLK: 2,SNR1: 11.451 ,SNR2: 28.380




K20260729135613





BLK: 2,SNR1: 12.264 ,SNR2: 30.393




1031-11 2026/07/29 4.97UT TOYOKAWA-KISO





F20260729135616




BLK: 5,SNR1: 8.2185 ,SNR2: 20.505




K20260729135613




BLK: 5,SNR1: 11.377 ,SNR2: 28.183





1031-11 2026/07/29 4.97UT FUJI -KISO







BLK: 1,SNR1: 3.8515 ,SNR2: 11.621




BLK: 1,SNR1: 5.1147 ,SNR2: 13.620





1035-058 2026/07/29 5.04UT TOYOKAWA-FUJI







BLK: 1,SNR1: 8.6662 ,SNR2: 19.031




BLK: 1,SNR1: 5.4576 ,SNR2: 12.891





1035-058 2026/07/29 5.04UT TOYOKAWA-KISO







BLK: 2,SNR1: 14.170 ,SNR2: 31.105







BLK: 2,SNR1: 5.5616 ,SNR2: 13.123








1035-058 2026/07/29 5.04UT FUJI -KISO






1044-008 2026/07/29 5.20UT TOYOKAWA-FUJI







1044-008 2026/07/29 5.20UT TOYOKAWA-KISO







F20260729141002




BLK: 5,SNR1: 12.736 ,SNR2: 29.247




K20260729140959





BLK: 5,SNR1: 12.564 ,SNR2: 31.376




1044-008 2026/07/29 5.20UT FUJI -KISO





T20260729142106




BLK: 5,SNR1: 6.9183 ,SNR2: 14.206




F20260729142106




BLK: 5,SNR1: 3.3076 ,SNR2: 10.028




1055+01 2026/07/29 5.38UT TOYOKAWA-FUJI




T20260729142106




BLK:14,SNR1: 1.9316 ,SNR2: 5.7926




K20260729142103





BLK:14,SNR1: 4.4512 ,SNR2: 12.485




1055+01 2026/07/29 5.38UT TOYOKAWA-KISO





F20260729142106




BLK:13,SNR1: 3.6632 ,SNR2: 10.987




K20260729142103





BLK:13,SNR1: 5.4462 ,SNR2: 15.352




1055+01 2026/07/29 5.38UT FUJI -KISO





T20260729143224




No.Good Data




F20260729143224





No.Good Data




1107+109 2026/07/29 5.57UT TOYOKAWA-FUJI



T20260729143224





BLK: 7,SNR1: 1.1962 ,SNR2: 2.9647




Frequency (Hz)

K20260729143221




BLK: 7,SNR1: 1.1750 ,SNR2: 4.1238





Frequency (Hz)


1107+109 2026/07/29 5.57UT TOYOKAWA-KISO



F20260729143224





No.Good Data




Frequency (Hz)

K20260729143221




No.Good Data




Frequency (Hz)


1107+109 2026/07/29 5.57UT FUJI -KISO





T20260729144201




BLK:15,SNR1: 20.965 ,SNR2: 47.442




F20260729144201



BLK:15,SNR1: 48.713 ,SNR2: 81.129




3C255 2026/07/29 5.73UT TOYOKAWA-FUJI







T20260729144201




BLK: 6,SNR1: 19.062 ,SNR2: 44.079




K20260729144158




BLK: 6,SNR1: 4.1562 ,SNR2: 12.045





3C255 2026/07/29 5.73UT TOYOKAWA-KISO







BLK: 6,SNR1: 79.895 ,SNR2: 144.79





BLK: 6,SNR1: 4.4194 ,SNR2: 10.051




3C255 2026/07/29 5.73UT FUJI -KISO




T20260729145239




BLK: 8,SNR1: 0.21534 ,SNR2: 1.0972




F20260729145239





BLK: 8,SNR1: 4.4429 ,SNR2: 9.1399




1127-14 2026/07/29 5.91UT TOYOKAWA-FUJI




T20260729145239




BLK:16,SNR1: 0.31458 ,SNR2: 1.9259




K20260729145236




BLK:16,SNR1: 7.9179 ,SNR2: 17.354




1127-14 2026/07/29 5.91UT TOYOKAWA-KISO




F20260729145239




BLK: 9,SNR1: 1.2680 ,SNR2: 4.4523




K20260729145236





BLK: 9,SNR1: 8.3527 ,SNR2: 18.508





1127-14 2026/07/29 5.91UT FUJI -KISO




T20260729150559





F20260729150559




3C263.1 2026/07/29 6.13UT TOYOKAWA-FUJI





T20260729150559




BLK: 8,SNR1: 1.3545 ,SNR2: 4.2836




K20260729150556





BLK: 8,SNR1: 0.47379 ,SNR2: 1.8238




3C263.1 2026/07/29 6.13UT TOYOKAWA-KISO



F20260729150559





BLK: 3,SNR1: 0.34554 ,SNR2: 1.1968




Frequency (Hz)

K20260729150556




BLK: 3,SNR1: 1.5413 ,SNR2: 5.2043





Frequency (Hz)

3C263.1 2026/07/29 6.13UT FUJI -KISO








T20260729151226




BLK: 2,SNR1: 2.9341 ,SNR2: 8.8560




F20260729151226





BLK: 2,SNR1: 4.1809 ,SNR2: 13.007




3C267 2026/07/29 6.24UT TOYOKAWA-FUJI





T20260729151226




BLK: 2,SNR1: 0.28602 ,SNR2: 1.5523




K20260729151223






BLK: 2,SNR1: 1.9106 ,SNR2: 4.6494





3C267 2026/07/29 6.24UT TOYOKAWA-KISO








T20260729153814




BLK: 7,SNR1: 9.1019 ,SNR2: 24.026




F20260729153814





BLK: 7,SNR1: 10.501 ,SNR2: 23.851




1213-17 2026/07/29 6.67UT TOYOKAWA-FUJI




T20260729153814




BLK: 9,SNR1: 9.4292 ,SNR2: 24.878




K20260729153811




BLK: 9,SNR1: 12.014 ,SNR2: 27.200




1213-17 2026/07/29 6.67UT TOYOKAWA-KISO




F20260729153814




BLK: 5,SNR1: 12.382 ,SNR2: 27.673




K20260729153811




BLK: 5,SNR1: 6.4914 ,SNR2: 18.155





1213-17 2026/07/29 6.67UT FUJI -KISO







BLK:13,SNR1: 11.561 ,SNR2: 25.746




BLK:13,SNR1: 11.148 ,SNR2: 27.414





3C273 2026/07/29 6.89UT TOYOKAWA-FUJI







BLK:17,SNR1: 11.142 ,SNR2: 24.818



BLK:17,SNR1: 23.275 ,SNR2: 25.195





3C273 2026/07/29 6.89UT TOYOKAWA-KISO






F20260729155131





BLK:10,SNR1: 11.369 ,SNR2: 27.627




Frequency (Hz)

K20260729155128




BLK:10,SNR1: 11.865 ,SNR2: 27.333





Frequency (Hz)


3C273 2026/07/29 6.89UT FUJI -KISO




T20260729160442




BLK: 1,SNR1: 0.99979 ,SNR2: 4.1418




F20260729160442





BLK: 1,SNR1: 0.30804E-02,SNR2: 0.58617




3C275 2026/07/29 7.11UT TOYOKAWA-FUJI





T20260729160442




BLK: 5,SNR1: 0.22004 ,SNR2: 0.79591




K20260729160439





BLK: 5,SNR1: 0.12838 ,SNR2: 2.3811




3C275 2026/07/29 7.11UT TOYOKAWA-KISO





F20260729160442




No.Good Data




K20260729160439





No.Good Data




3C275 2026/07/29 7.11UT FUJI -KISO





T20260729161047




BLK: 8,SNR1: 6.5776 ,SNR2: 18.652




F20260729161047




BLK: 8,SNR1: 9.9391 ,SNR2: 28.998





1245-19 2026/07/29 7.21UT TOYOKAWA-FUJI







BLK:12,SNR1: 7.5422 ,SNR2: 20.314




BLK:12,SNR1: 8.4820 ,SNR2: 21.917




1245-19 2026/07/29 7.21UT TOYOKAWA-KISO




F20260729161047




BLK:12,SNR1: 9.1624 ,SNR2: 26.401




K20260729161044




BLK:12,SNR1: 9.2774 ,SNR2: 26.980





1245-19 2026/07/29 7.21UT FUJI -KISO








BLK: 9,SNR1: 3.4732 ,SNR2: 10.285





BLK: 9,SNR1: 2.6823 ,SNR2: 8.3819









BLK:13,SNR1: 3.3439 ,SNR2: 10.043




BLK:13,SNR1: 8.5241 ,SNR2: 15.924





3C279 2026/07/29 7.34UT TOYOKAWA-KISO









BLK:16,SNR1: 2.6791 ,SNR2: 8.3717




BLK:16,SNR1: 8.3626 ,SNR2: 15.629





T20260729163818




BLK: 5, SNR1: 0.15895 , SNR2: 1.4925




F20260729163818





BLK: 5, SNR1: 2.4925 , SNR2: 7.9964




1313+453 2026/07/29 7.67UT TOYOKAWA-FUJI



T20260729163818





BLK:14,SNR1: 10.503 ,SNR2: 23.408




Frequency (Hz)

K20260729163815




BLK:14,SNR1: 8.4100 ,SNR2: 18.978





Frequency (Hz)


1313+453 2026/07/29 7.67UT TOYOKAWA-KISO



F20260729163818





BLK:19,SNR1: 2.4987 ,SNR2: 8.0033




Frequency (Hz)

K20260729163815




BLK:19,SNR1: 11.861 ,SNR2: 17.093





Frequency (Hz)


1313+453 2026/07/29 7.67UT FUJI -KISO



T20260729164824





BLK: 8,SNR1: 0.10371 ,SNR2: 1.1121




Frequency (Hz)

F20260729164824




BLK: 8,SNR1: 6.7619 ,SNR2: 16.979





Frequency (Hz)


1323+32 2026/07/29 7.83UT TOYOKAWA-FUJI



T20260729164824





BLK: 7, SNR1: 15.570 , SNR2: 35.994




Frequency (Hz)

K20260729164821




BLK: 7, SNR1: 13.010 , SNR2: 32.396




Frequency (Hz)


1323+32 2026/07/29 7.83UT TOYOKAWA-KISO



F20260729164824




BLK: 9, SNR1: 10.697 , SNR2: 25.632




Frequency (Hz)

K20260729164821




BLK: 9, SNR1: 11.828 , SNR2: 29.450







Frequency (Hz)


1323+32 2026/07/29 7.83UT FUJI -KISO










3C286 2026/07/29 7.92UT TOYOKAWA-FUJI







BLK:12,SNR1: 0.34203 ,SNR2: 1.5838





BLK:12,SNR1: 1.7912 ,SNR2: 4.6533




3C286 2026/07/29 7.92UT TOYOKAWA-KISO



F20260729165314





BLK: 2,SNR1: 0.95572 ,SNR2: 4.9822




Frequency (Hz)

K20260729165311








BLK: 2,SNR1: 1.9779 ,SNR2: 5.3761




Frequency (Hz)





3C286 2026/07/29 7.92UT FUJI -KISO







1345+12 2026/07/29 8.19UT TOYOKAWA-FUJI







1345+12 2026/07/29 8.19UT TOYOKAWA-KISO






BLK: 6,SNR1: 9.6311 ,SNR2: 23.098



BLK: 6,SNR1: 11.810 ,SNR2: 29.317



1345+12 2026/07/29 8.19UT FUJI -KISO

