


















F20260730062202




No.Good Data




K20260730062159







No.Good Data









0258+350 2026/07/29 21.40UT FUJI -KISO








0308+305 2026/07/29 21.56UT TOYOKAWA-FUJI









BLK: 3,SNR1: 3.5274 ,SNR2: 10.028





BLK: 3,SNR1: 3.4072 ,SNR2: 10.168




0308+305 2026/07/29 21.56UT FUJI -KISO




T20260730064322




BLK: 1,SNR1: 0.48107 ,SNR2: 1.8502




F20260730064322













BLK: 1,SNR1: 0.17512E-01,SNR2: 1.3272





0320+05 2026/07/29 21.75UT TOYOKAWA-FUJI










T20260730065644




BLK: 1,SNR1: 0.23712 ,SNR2: 1.5660




F20260730065644



BLK: 1,SNR1: 0.16041 ,SNR2: 0.95354





0333+32 2026/07/29 21.97UT TOYOKAWA-FUJI






T20260730065644





BLK: 1,SNR1: 0.30290 ,SNR2: 1.3308




Frequency (Hz)

K20260730065641







BLK: 1,SNR1: 0.15155 ,SNR2: 0.86454




Frequency (Hz)

0333+32 2026/07/29 21.97UT TOYOKAWA-KISO







T20260730070945




BLK: 3, SNR1: 2.0504 , SNR2: 10.049




F20260730070945




BLK: 3, SNR1: 6.5186 , SNR2: 14.204




0347+05 2026/07/29 22.19UT TOYOKAWA-FUJI





T20260730070945




BLK: 2,SNR1:-0.23555E-01,SNR2: 0.76966




K20260730070942




BLK: 2,SNR1: 3.8049 ,SNR2: 9.6080




0347+05 2026/07/29 22.19UT TOYOKAWA-KISO





F20260730070945




BLK: 1, SNR1: 2.8712 , SNR2: 10.800




K20260730070942




BLK: 1, SNR1: 3.0274 , SNR2: 8.0302




0347+05 2026/07/29 22.19UT FUJI -KISO




T20260730072518




BLK: 5, SNR1: 1.0170 , SNR2: 3.4030




F20260730072518




BLK: 5, SNR1: 3.6481 , SNR2: 10.080




0403-132 2026/07/29 22.45UT TOYOKAWA-FUJI




T20260730072518




BLK: 6, SNR1: 0.15139 , SNR2: 1.2733




K20260730072515




BLK: 6, SNR1: 6.3979 , SNR2: 17.377




0403-132 2026/07/29 22.45UT TOYOKAWA-KISO





F20260730072518




BLK: 8,SNR1: 4.6188 ,SNR2: 14.200




K20260730072515



BLK: 8,SNR1: 7.6251 ,SNR2: 19.775





0403-132 2026/07/29 22.45UT FUJI -KISO






T20260730073430





No.Good Data




Frequency (Hz)

F20260730073430




No.Good Data





Frequency (Hz)


0411+05 2026/07/29 22.60UT TOYOKAWA-FUJI





T20260730073430




BLK: 5,SNR1: 0.26379 ,SNR2: 0.81357




K20260730073427




BLK: 5,SNR1: 2.0857 ,SNR2: 5.9693




0411+05 2026/07/29 22.60UT TOYOKAWA-KISO





F20260730073430




BLK: 1,SNR1: 2.2251 ,SNR2: 10.252




K20260730073427





BLK: 1,SNR1: 1.4668 ,SNR2: 5.9151





0411+05 2026/07/29 22.60UT FUJI -KISO







BLK: 3,SNR1: 0.51640 ,SNR2: 2.6616







BLK: 3,SNR1: 0.56640 ,SNR2: 3.4192




0418+236 2026/07/29 22.72UT TOYOKAWA-FUJI







0418+236 2026/07/29 22.72UT TOYOKAWA-KISO




F20260730074125




BLK: 8,SNR1: 0.13073 ,SNR2: 1.2077




K20260730074122




BLK: 8,SNR1: 0.26585 ,SNR2: 1.6210




0418+236 2026/07/29 22.72UT FUJI -KISO




T20260730075253




BLK: 4, SNR1: 1.5856 , SNR2: 3.7851




F20260730075253




BLK: 4, SNR1: 4.7098 , SNR2: 28.300




3C119 2026/07/29 22.91UT TOYOKAWA-FUJI




T20260730075253




BLK: 2,SNR1: 3.2220 ,SNR2: 10.247




K20260730075250



BLK: 2,SNR1: 4.2094 ,SNR2: 14.629




3C119 2026/07/29 22.91UT TOYOKAWA-KISO








F20260730075253




BLK: 2, SNR1: 17.188 , SNR2: 32.319




K20260730075250




BLK: 2, SNR1: 5.6824 , SNR2: 17.299





3C119 2026/07/29 22.91UT FUJI -KISO







BLK: 8,SNR1: 2.1969 ,SNR2: 7.4081




BLK: 8,SNR1: 1.4923 ,SNR2: 4.0044





3C138 2026/07/29 23.71UT TOYOKAWA-FUJI







BLK:13,SNR1: 2.2171 ,SNR2: 7.4590




BLK:13,SNR1: 8.2281 ,SNR2: 14.727




3C138 2026/07/29 23.71UT TOYOKAWA-KISO





F20260730084059




BLK:19,SNR1: 6.9649 ,SNR2: 17.854




K20260730084056





BLK:19,SNR1: 7.4118 ,SNR2: 13.221




3C138 2026/07/29 23.71UT FUJI -KISO





T20260730085416




BLK: 1,SNR1: 0.33400 ,SNR2: 4.8554




F20260730085416





BLK: 1,SNR1:-0.29430 ,SNR2: 1.6070




0531+050 2026/07/29 23.93UT TOYOKAWA-FUJI




T20260730085416




BLK: 2, SNR1: 1.1861 , SNR2: 9.9677




K20260730085413




BLK: 2, SNR1: 4.9428 , SNR2: 12.848




0531+050 2026/07/29 23.93UT TOYOKAWA-KISO




F20260730085416




BLK: 9,SNR1: 5.5744 ,SNR2: 16.907




K20260730085413





BLK: 9,SNR1: 5.8558 ,SNR2: 17.754




0531+050 2026/07/29 23.93UT FUJI -KISO





T20260730090254




BLK:18,SNR1: 1.8420 ,SNR2: 7.9973




F20260730090254







BLK:18,SNR1:-0.18591 ,SNR2: 1.9516




3C147 2026/07/30 0.08UT TOYOKAWA-FUJI










3C147 2026/07/30 0.08UT TOYOKAWA-KISO




F20260730090254




BLK:21,SNR1: 0.37783 ,SNR2: 2.7129




K20260730090251





BLK:21,SNR1: 8.5889 ,SNR2: 15.400




3C147 2026/07/30 0.08UT FUJI -KISO





T20260730091103




No.Good Data




F20260730091103




No.Good Data




0548+16 2026/07/30 0.21UT TOYOKAWA-FUJI




T20260730091103




BLK: 2,SNR1: 9.7531 ,SNR2: 23.820




K20260730091100




BLK: 2,SNR1: 17.396 ,SNR2: 31.393




0548+16 2026/07/30 0.21UT TOYOKAWA-KISO




F20260730091103




BLK: 1, SNR1: 1.6632 , SNR2: 7.9992




K20260730091100




BLK: 1, SNR1: 31.422 , SNR2: 96.437




0548+16 2026/07/30 0.21UT FUJI -KISO




T20260730091514




BLK: 5,SNR1: 23.921 ,SNR2: 57.779




F20260730091514





BLK: 5,SNR1: 3.2011 ,SNR2: 7.9180




0552+12 2026/07/30 0.28UT TOYOKAWA-FUJI




T20260730091514




BLK: 2, SNR1: 19.498 , SNR2: 47.325




K20260730091511





BLK: 2, SNR1: 7.2583 , SNR2: 18.565




0552+12 2026/07/30 0.28UT TOYOKAWA-KISO





F20260730091514




BLK: 2, SNR1: 3.1643 , SNR2: 8.9365




K20260730091511



BLK: 2, SNR1: 6.1595 , SNR2: 17.776




0552+12 2026/07/30 0.28UT FUJI -KISO







T20260730091941




BLK: 3,SNR1:-0.18272E-01,SNR2: 0.27272




F20260730091941





BLK: 3,SNR1: 2.0729 ,SNR2: 5.2152




0556+191 2026/07/30 0.36UT TOYOKAWA-FUJI





T20260730091941




BLK: 5,SNR1: 0.34108E-01,SNR2: 0.39947




K20260730091939




BLK: 5,SNR1: 0.91697 ,SNR2: 4.5560




0556+191 2026/07/30 0.36UT TOYOKAWA-KISO





F20260730091941




BLK: 3,SNR1: 1.2154 ,SNR2: 3.4996




K20260730091939





BLK: 3,SNR1: 0.85205 ,SNR2: 3.2358




0556+191 2026/07/30 0.36UT FUJI -KISO




T20260730092414




BLK: 6,SNR1: 0.24298 ,SNR2: 0.74649




F20260730092414





BLK: 6,SNR1: 2.8466 ,SNR2: 6.9736




3C152 2026/07/30 0.43UT TOYOKAWA-FUJI





T20260730092414




BLK: 7, SNR1: 0.29079 , SNR2: 0.99356




K20260730092412





BLK: 7, SNR1: 0.94806 , SNR2: 2.9409




3C152 2026/07/30 0.43UT TOYOKAWA-KISO





F20260730092414




BLK: 9, SNR1: 2.8358 , SNR2: 7.0509




K20260730092412




BLK: 9, SNR1: 0.51674 , SNR2: 2.0163




3C152 2026/07/30 0.43UT FUJI -KISO




T20260730094634




BLK: 3,SNR1: 1.8478 ,SNR2: 6.3310




F20260730094634




BLK: 3,SNR1: 4.9503 ,SNR2: 12.155




3C161 2026/07/30 0.80UT TOYOKAWA-FUJI




T20260730094634




BLK: 7, SNR1: 7.5722 , SNR2: 18.530




K20260730094631



BLK: 7, SNR1: 12.080 , SNR2: 21.492




3C161 2026/07/30 0.80UT TOYOKAWA-KISO







F20260730094634




BLK: 3, SNR1: 5.0746 , SNR2: 10.243




K20260730094631










BLK: 3, SNR1: 17.936 , SNR2: 32.174




3C161 2026/07/30 0.80UT FUJI -KISO









0652-130 2026/07/30 1.26UT TOYOKAWA-KISO





F20260730101406




BLK: 4, SNR1: 0.14468 , SNR2: 1.2095




K20260730101403





BLK: 4, SNR1: 0.56423 , SNR2: 1.4354




0652-130 2026/07/30 1.26UT FUJI -KISO





T20260730102544




BLK:11,SNR1: 0.72349E-01,SNR2: 0.79213




F20260730102544





BLK:11,SNR1: 1.9693 ,SNR2: 3.6822




0703+138 2026/07/30 1.46UT TOYOKAWA-FUJI





T20260730102544




BLK:10,SNR1: 0.14208 ,SNR2: 0.51892




K20260730102541





BLK:10,SNR1: 2.3195 ,SNR2: 4.6900




0703+138 2026/07/30 1.46UT TOYOKAWA-KISO



F20260730102544





BLK:17,SNR1: 3.3886 ,SNR2: 8.7945





0703+138 2026/07/30 1.46UT FUJI -KISO



K20260730102541




BLK:17,SNR1: 0.95500 ,SNR2: 3.2208





T20260730103506




BLK: 2, SNR1: 0.24809 , SNR2: 2.0173




F20260730103506



BLK: 2, SNR1: 6.2984 , SNR2: 16.070





0713-024 2026/07/30 1.61UT TOYOKAWA-FUJI








T20260730103506




BLK: 1, SNR1: 6.3124 , SNR2: 16.080




K20260730103503





BLK: 1, SNR1: 9.2487 , SNR2: 17.325




0713-024 2026/07/30 1.61UT TOYOKAWA-KISO





F20260730103506




BLK: 1, SNR1: 11.284 , SNR2: 19.923




K20260730103503





BLK: 1, SNR1: 9.2487 , SNR2: 17.325




0713-024 2026/07/30 1.61UT FUJI -KISO





T20260730104518




BLK:22,SNR1: 9.9393 ,SNR2: 17.376




F20260730104518





BLK:22,SNR1: 9.1788 ,SNR2: 14.389




0723+10 2026/07/30 1.78UT TOYOKAWA-FUJI





T20260730104518




BLK:27,SNR1: 9.5137 ,SNR2: 16.631




K20260730104515





BLK:27,SNR1: 10.919 ,SNR2: 25.390




0723+10 2026/07/30 1.78UT TOYOKAWA-KISO





F20260730104518




BLK:26,SNR1: 3.4382 ,SNR2: 10.331




K20260730104515








BLK:26,SNR1: 9.5182 ,SNR2: 24.223





0723+10 2026/07/30 1.78UT FUJI -KISO








T20260730105534




BLK: 2, SNR1: 1.8084 , SNR2: 8.6518




K20260730105531





BLK: 2, SNR1: 11.817 , SNR2: 27.908




0732+33 2026/07/30 1.95UT TOYOKAWA-KISO



F20260730105534





BLK: 3, SNR1: 9.1208 , SNR2: 22.876




Frequency (Hz)

K20260730105531




BLK: 3, SNR1: 9.4026 , SNR2: 22.358







Frequency (Hz)


0732+33 2026/07/30 1.95UT FUJI -KISO













0741-06 2026/07/30 2.09UT TOYOKAWA-FUJI








F20260730110334




BLK:11,SNR1: 0.78825 ,SNR2: 2.9802




K20260730110331





BLK:11,SNR1: 8.7519 ,SNR2: 17.030




0741-06 2026/07/30 2.09UT FUJI -KISO




T20260730111318




BLK: 4,SNR1: 2.4240 ,SNR2: 7.9662




F20260730111318





BLK: 4,SNR1: 5.5790 ,SNR2: 15.916




0752-200 2026/07/30 2.25UT TOYOKAWA-FUJI




T20260730111318




BLK: 9, SNR1: 10.585 , SNR2: 18.446




K20260730111316




BLK: 9, SNR1: 8.4147 , SNR2: 22.060




0752-200 2026/07/30 2.25UT TOYOKAWA-KISO




F20260730111318




BLK: 2, SNR1: 4.2828 , SNR2: 19.435




K20260730111316





BLK: 2, SNR1: 3.4376 , SNR2: 10.345




0752-200 2026/07/30 2.25UT FUJI -KISO





T20260730112054




BLK:13,SNR1: 0.61564 ,SNR2: 2.8970




F20260730112054





BLK:13,SNR1: 0.43097 ,SNR2: 1.3207




3C190 2026/07/30 2.38UT TOYOKAWA-FUJI





T20260730112054




BLK:16,SNR1: 0.63720 ,SNR2: 3.2322




K20260730112051






BLK:16,SNR1: 0.85975 ,SNR2: 3.5148




3C190 2026/07/30 2.38UT TOYOKAWA-KISO










T20260730113321




BLK: 7,SNR1: 0.22088 ,SNR2: 2.1277




F20260730113321




BLK: 7,SNR1: 0.34031 ,SNR2: 1.9777




3C196 2026/07/30 2.58UT TOYOKAWA-FUJI





T20260730113321




BLK: 9,SNR1: 0.36911 ,SNR2: 2.4222




K20260730113318





BLK: 9,SNR1: 1.5022 ,SNR2: 4.8355




3C196 2026/07/30 2.58UT TOYOKAWA-KISO





F20260730113321




BLK: 7,SNR1: 0.44208 ,SNR2: 1.9029




K20260730113318





BLK: 7,SNR1: 0.77942 ,SNR2: 3.3026




3C196 2026/07/30 2.58UT FUJI -KISO




T20260730114429




BLK: 3, SNR1: 2.9058 , SNR2: 12.990




F20260730114429





BLK: 3, SNR1: 8.4180 , SNR2: 20.774




0821+394 2026/07/30 2.77UT TOYOKAWA-FUJI




T20260730114429




BLK: 1,SNR1: 19.444 ,SNR2: 35.641




K20260730114426





BLK: 1,SNR1: 19.507 ,SNR2: 45.174




0821+394 2026/07/30 2.77UT TOYOKAWA-KISO




F20260730114429




BLK: 1, SNR1: 10.049 , SNR2: 24.760




K20260730114426





BLK: 1, SNR1: 2.8106 , SNR2: 12.587




0821+394 2026/07/30 2.77UT FUJI -KISO





T20260730115607




BLK: 4,SNR1: 1.1120 ,SNR2: 5.6976




F20260730115607



BLK: 4,SNR1: 1.9516 ,SNR2: 4.7062





0834-19 2026/07/30 2.96UT TOYOKAWA-FUJI








T20260730115607




BLK: 2,SNR1:-0.48964E-01,SNR2: 1.1926




K20260730115604




BLK: 2,SNR1: 6.8159 ,SNR2: 18.327




0834-19 2026/07/30 2.96UT TOYOKAWA-KISO





F20260730115607




BLK: 2,SNR1: 1.2035 ,SNR2: 6.3593




K20260730115604





BLK: 2,SNR1: 5.9467 ,SNR2: 15.620




0834-19 2026/07/30 2.96UT FUJI -KISO



T20260730120113




No. Good Data




Frequency (Hz)

F20260730120113




No. Good Data




Frequency (Hz)


0839-071 2026/07/30 3.05UT TOYOKAWA-FUJI




T20260730120113




BLK: 5, SNR1: 2.5638 , SNR2: 6.3185




K20260730120110




BLK: 5, SNR1: 5.4227 , SNR2: 10.532




0839-071 2026/07/30 3.05UT TOYOKAWA-KISO




F20260730120113




BLK: 2,SNR1: 0.44841 ,SNR2: 1.5436




K20260730120110




BLK: 2,SNR1: 5.1274 ,SNR2: 14.786




0839-071 2026/07/30 3.05UT FUJI -KISO




T20260730121215




BLK: 7,SNR1: 0.61880 ,SNR2: 1.3498




F20260730121215





BLK: 7,SNR1: 1.7562 ,SNR2: 5.0664




3C208 2026/07/30 3.23UT TOYOKAWA-FUJI





T20260730121215




BLK:10,SNR1: 0.69334 ,SNR2: 1.3633




K20260730121212




BLK:10,SNR1: 10.623 ,SNR2: 25.633




3C208 2026/07/30 3.23UT TOYOKAWA-KISO




F20260730121215




BLK: 6,SNR1: 3.8459 ,SNR2: 10.674




K20260730121212







BLK: 6,SNR1: 7.4262 ,SNR2: 19.921




3C208 2026/07/30 3.23UT FUJI -KISO










3C216 2026/07/30 3.51UT TOYOKAWA-FUJI







BLK: 4, SNR1: 16.258 , SNR2: 28.884




BLK: 4, SNR1: 10.292 , SNR2: 25.317




3C216 2026/07/30 3.51UT TOYOKAWA-KISO





F20260730122857




BLK: 2,SNR1: 19.195 ,SNR2: 33.845




K20260730122854





BLK: 2,SNR1: 9.9906 ,SNR2: 24.831




3C216 2026/07/30 3.51UT FUJI -KISO



T20260730124107





No.Good Data




Frequency (Hz)

F20260730124107





No.Good Data





Frequency (Hz)

0919-142 2026/07/30 3.71UT TOYOKAWA-FUJI







BLK: 2,SNR1: 10.568 ,SNR2: 25.935




BLK: 2,SNR1: 20.373 ,SNR2: 37.188




0919-142 2026/07/30 3.71UT TOYOKAWA-KISO





F20260730124107




BLK: 4,SNR1: 9.5708 ,SNR2: 23.281




K20260730124104





BLK: 4,SNR1: 11.544 ,SNR2: 28.305




0919-142 2026/07/30 3.71UT FUJI -KISO





T20260730124746




BLK: 5,SNR1: 9.2234 ,SNR2: 23.018




F20260730124746





BLK: 5,SNR1: 7.6957 ,SNR2: 21.126




0926+117 2026/07/30 3.82UT TOYOKAWA-FUJI





T20260730124746




BLK: 4,SNR1: 11.134 ,SNR2: 27.731




K20260730124743



BLK: 4,SNR1: 12.086 ,SNR2: 30.759





0926+117 2026/07/30 3.82UT TOYOKAWA-KISO








F20260730124746




BLK: 1,SNR1: 7.0832 ,SNR2: 19.456




K20260730124743




BLK: 1,SNR1: 16.715 ,SNR2: 40.478





0926+117 2026/07/30 3.82UT FUJI -KISO







BLK: 3, SNR1: 1.8698 , SNR2: 12.967




BLK: 3, SNR1: 17.208 , SNR2: 35.223




3C222 2026/07/30 3.95UT TOYOKAWA-FUJI




T20260730125531




BLK: 5, SNR1: 13.508 , SNR2: 27.712




K20260730125528




BLK: 5, SNR1: 27.889 , SNR2: 30.486




3C222 2026/07/30 3.95UT TOYOKAWA-KISO




F20260730125531




BLK: 6, SNR1: 13.205 , SNR2: 20.770




K20260730125528




BLK: 6, SNR1: 24.419 , SNR2: 39.535





3C222 2026/07/30 3.95UT FUJI -KISO







BLK: 5, SNR1: 8.3697 , SNR2: 20.417





BLK: 5, SNR1: 18.978 , SNR2: 33.381




0941-08 2026/07/30 4.07UT TOYOKAWA-FUJI




T20260730130231




BLK: 4,SNR1: 21.058 ,SNR2: 37.375




K20260730130228




BLK: 4,SNR1: 2.6506 ,SNR2: 11.959




0941-08 2026/07/30 4.07UT TOYOKAWA-KISO




F20260730130231




BLK: 4,SNR1: 10.656 ,SNR2: 26.128




K20260730130228






BLK: 4,SNR1: 10.889 ,SNR2: 26.719







0941-08 2026/07/30 4.07UT FUJI -KISO












3C230 2026/07/30 4.21UT TOYOKAWA-KISO





F20260730131053




BLK: 1,SNR1: 1.4908 ,SNR2: 5.1954




K20260730131051




BLK: 1,SNR1: 12.859 ,SNR2: 31.364





3C230 2026/07/30 4.21UT FUJI -KISO







BLK: 4,SNR1: 6.9973 ,SNR2: 17.329




BLK: 4,SNR1: 8.0811 ,SNR2: 20.025





3C236 2026/07/30 4.45UT TOYOKAWA-FUJI







BLK: 3,SNR1: 9.4827 ,SNR2: 23.319





BLK: 3,SNR1: 11.575 ,SNR2: 28.393




3C236 2026/07/30 4.45UT TOYOKAWA-KISO





F20260730132501




No.Good Data




K20260730132500





No.Good Data




3C236 2026/07/30 4.45UT FUJI -KISO





T20260730133310




BLK: 3,SNR1: 1.8330 ,SNR2: 8.9004




F20260730133310




BLK: 3,SNR1: 2.0664 ,SNR2: 5.4743




1011+110 2026/07/30 4.58UT TOYOKAWA-FUJI




T20260730133310




BLK: 3,SNR1: 3.6795 ,SNR2: 12.904




K20260730133309




BLK: 3,SNR1: 10.807 ,SNR2: 19.200




1011+110 2026/07/30 4.58UT TOYOKAWA-KISO




F20260730133310




BLK: 2,SNR1: 0.25992 ,SNR2: 1.7476




K20260730133309







BLK: 2,SNR1: 0.83895 ,SNR2: 5.7058




1011+110 2026/07/30 4.58UT FUJI -KISO












3C241 2026/07/30 4.71UT TOYOKAWA-FUJI









3C241 2026/07/30 4.71UT TOYOKAWA-KISO




F20260730134051





K20260730134050




3C241 2026/07/30 4.71UT FUJI -KISO





T20260730135220




BLK: 2,SNR1: 7.4600 ,SNR2: 21.891




F20260730135220





BLK: 2,SNR1: 3.7981 ,SNR2: 9.2179




1031-11 2026/07/30 4.90UT TOYOKAWA-FUJI




T20260730135220




BLK: 7,SNR1: 9.6732 ,SNR2: 24.035




K20260730135219





BLK: 7,SNR1: 10.448 ,SNR2: 26.661





1031-11 2026/07/30 4.90UT TOYOKAWA-KISO




F20260730135220







K20260730135219




1031-11 2026/07/30 4.90UT FUJI -KISO







1035-058 2026/07/30 4.98UT TOYOKAWA-FUJI




T20260730135653




BLK: 2,SNR1: 3.6424 ,SNR2: 9.7271




K20260730135652



BLK: 2,SNR1: 8.1665 ,SNR2: 19.857





1035-058 2026/07/30 4.98UT TOYOKAWA-KISO







F20260730135653




BLK:12,SNR1: 103.82 ,SNR2: 96.689




K20260730135652




BLK:12,SNR1: 13.956 ,SNR2: 24.651





1035-058 2026/07/30 4.98UT FUJI -KISO







BLK: 1,SNR1: 12.055 ,SNR2: 29.963





BLK: 1,SNR1: 9.4595 ,SNR2: 23.021




1044-008 2026/07/30 5.13UT TOYOKAWA-FUJI





T20260730140606




BLK: 3,SNR1: 12.248 ,SNR2: 30.476




K20260730140605




BLK: 3,SNR1: 13.943 ,SNR2: 31.036





1044-008 2026/07/30 5.13UT TOYOKAWA-KISO







BLK: 4,SNR1: 15.238 ,SNR2: 21.615




BLK: 4,SNR1: 13.715 ,SNR2: 24.514





1044-008 2026/07/30 5.13UT FUJI -KISO







BLK: 1,SNR1: 2.4097 ,SNR2: 7.1026




BLK: 1,SNR1: 8.0416 ,SNR2: 26.169





1055+01 2026/07/30 5.31UT TOYOKAWA-FUJI







BLK: 1,SNR1: 0.29585 ,SNR2: 1.1992




BLK: 1,SNR1: 7.3632 ,SNR2: 19.305




1055+01 2026/07/30 5.31UT TOYOKAWA-KISO




F20260730141710




BLK: 1,SNR1: 8.0415 ,SNR2: 26.169




K20260730141709




BLK: 1,SNR1: 0.39869 ,SNR2: 3.6360





1055+01 2026/07/30 5.31UT FUJI -KISO







BLK:13,SNR1: 3.7017 ,SNR2: 11.025



BLK:13,SNR1: 9.4069 ,SNR2: 16.436





1107+109 2026/07/30 5.50UT TOYOKAWA-FUJI








T20260730142828




BLK:19,SNR1: 3.4063 ,SNR2: 10.261




K20260730142827





BLK:19,SNR1: 7.9734 ,SNR2: 20.661




1107+109 2026/07/30 5.50UT TOYOKAWA-KISO





F20260730142828




BLK:18,SNR1: 9.4937 ,SNR2: 14.955




K20260730142827




BLK:18,SNR1: 7.9678 ,SNR2: 20.647




1107+109 2026/07/30 5.50UT FUJI -KISO





T20260730143805




BLK: 3,SNR1: 1.5953 ,SNR2: 4.4139




F20260730143805





BLK: 3,SNR1:-0.79863E-01,SNR2: 1.1514




3C255 2026/07/30 5.66UT TOYOKAWA-FUJI




T20260730143805




BLK: 5, SNR1: 12.677 , SNR2: 25.943




K20260730143804





BLK: 5, SNR1: 27.797 , SNR2: 39.269




3C255 2026/07/30 5.66UT TOYOKAWA-KISO



F20260730143805





BLK: 3,SNR1: 0.15537 ,SNR2: 2.0474




Frequency (Hz)

K20260730143804





BLK: 3,SNR1: 1.2110 ,SNR2: 5.5395





Frequency (Hz)

3C255 2026/07/30 5.66UT FUJI -KISO







BLK: 2,SNR1: 0.48860 ,SNR2: 2.1183




BLK: 2,SNR1:-0.18797E-01,SNR2: 0.98894





1127-14 2026/07/30 5.84UT TOYOKAWA-FUJI







BLK:12,SNR1: 0.83302 ,SNR2: 2.6634




BLK:12,SNR1: 5.4744 ,SNR2: 13.934





1127-14 2026/07/30 5.84UT TOYOKAWA-KISO








BLK: 8,SNR1: 0.57249 ,SNR2: 3.4934





BLK: 8,SNR1: 12.587 ,SNR2: 29.971









BLK: 4,SNR1: 0.37451 ,SNR2: 1.5205





BLK: 4,SNR1: 3.3800 ,SNR2: 7.6957




3C263.1 2026/07/30 6.06UT TOYOKAWA-FUJI





T20260730150203




BLK: 9,SNR1: 0.44796 ,SNR2: 1.8052




K20260730150202





BLK: 9,SNR1: 5.5684 ,SNR2: 16.308




3C263.1 2026/07/30 6.06UT TOYOKAWA-KISO





F20260730150203




BLK: 6,SNR1: 6.1274 ,SNR2: 13.589




K20260730150202




BLK: 6,SNR1: 3.7763 ,SNR2: 10.439





3C263.1 2026/07/30 6.06UT FUJI -KISO







BLK:12,SNR1: 0.30482 ,SNR2: 0.99708




BLK:12,SNR1: 1.2681 ,SNR2: 5.1725





3C267 2026/07/30 6.17UT TOYOKAWA-FUJI







BLK: 6,SNR1: 0.32936 ,SNR2: 0.95781





BLK: 6,SNR1: 1.4265 ,SNR2: 6.1344




3C267 2026/07/30 6.17UT TOYOKAWA-KISO





F20260730150830




BLK: 1,SNR1: 2.7853 ,SNR2: 12.783




K20260730150829





BLK: 1,SNR1: 0.17814 ,SNR2: 1.2894




3C267 2026/07/30 6.17UT FUJI -KISO





T20260730153418




BLK: 7,SNR1: 8.3540 ,SNR2: 22.346




F20260730153418





BLK: 7,SNR1: 8.0515 ,SNR2: 19.965




1213-17 2026/07/30 6.60UT TOYOKAWA-FUJI




T20260730153418




BLK: 7,SNR1: 14.836 ,SNR2: 34.265




K20260730153417




BLK: 7,SNR1: 8.5216 ,SNR2: 21.804





1213-17 2026/07/30 6.60UT TOYOKAWA-KISO











BLK: 5,SNR1: 6.4766 ,SNR2: 16.735




BLK: 5,SNR1: 2.3844 ,SNR2: 4.8342





T20260730154735




BLK:16,SNR1: 7.0977 ,SNR2: 10.258




F20260730154735




BLK:16,SNR1: 1.1614 ,SNR2: 3.6554





3C273 2026/07/30 6.82UT TOYOKAWA-FUJI







BLK:26,SNR1: 5.8452 ,SNR2: 8.4545








BLK:26,SNR1: 3.1140 ,SNR2: 9.4721





3C273 2026/07/30 6.82UT TOYOKAWA-KISO








T20260730160046




No.Good Data




F20260730160046





No.Good Data




3C275 2026/07/30 7.04UT TOYOKAWA-FUJI




T20260730160046




BLK: 3,SNR1: 0.39316 ,SNR2: 3.3729




K20260730160044





BLK: 3,SNR1: 2.6101 ,SNR2: 11.951




3C275 2026/07/30 7.04UT TOYOKAWA-KISO



F20260730160046





BLK: 2,SNR1: 0.39805 ,SNR2: 3.0053




Frequency (Hz)

K20260730160044





BLK: 2,SNR1: 0.94539 ,SNR2: 4.1310





Frequency (Hz)

3C275 2026/07/30 7.04UT FUJI -KISO







BLK: 7,SNR1: 11.127 ,SNR2: 26.337




BLK: 7,SNR1: 12.452 ,SNR2: 30.275





1245-19 2026/07/30 7.14UT TOYOKAWA-FUJI









BLK: 5,SNR1: 11.322 ,SNR2: 27.615




BLK: 5,SNR1: 10.829 ,SNR2: 26.265





1245-19 2026/07/30 7.14UT TOYOKAWA-KISO







BLK: 5,SNR1: 12.146 ,SNR2: 30.830




BLK: 5,SNR1: 11.643 ,SNR2: 28.399





1245-19 2026/07/30 7.14UT FUJI -KISO







BLK: 5,SNR1: 4.8201 ,SNR2: 15.895




BLK: 5,SNR1: 4.7968 ,SNR2: 16.258





3C279 2026/07/30 7.27UT TOYOKAWA-FUJI







BLK: 4,SNR1: 5.0764 ,SNR2: 16.648




BLK: 4,SNR1: 7.4205 ,SNR2: 24.392




3C279 2026/07/30 7.27UT TOYOKAWA-KISO



F20260730161435





BLK: 3,SNR1: 4.2474 ,SNR2: 14.615




Frequency (Hz)

K20260730161434







BLK: 3,SNR1: 7.3482 ,SNR2: 24.174







Frequency (Hz)

3C279 2026/07/30 7.27UT FUJI -KISO















BLK: 3,SNR1:-0.62502E-01,SNR2: 0.96464




BLK: 3,SNR1: 0.35212 ,SNR2: 1.4326










1323+32 2026/07/30 7.77UT TOYOKAWA-FUJI



T20260730164428





BLK: 6,SNR1: 1.4613 ,SNR2: 4.4165




Frequency (Hz)

K20260730164427





BLK: 6,SNR1: 7.7266 ,SNR2: 17.094





Frequency (Hz)

1323+32 2026/07/30 7.77UT TOYOKAWA-KISO







BLK: 9,SNR1: 6.8440 ,SNR2: 17.565





BLK: 9,SNR1: 7.6835 ,SNR2: 16.476




1323+32 2026/07/30 7.77UT FUJI -KISO



T20260730164918




BLK:15,SNR1: 0.32323 ,SNR2: 1.6710




Frequency (Hz)

F20260730164918








BLK:15,SNR1: 6.4379 ,SNR2: 15.837




Frequency (Hz)



3C286 2026/07/30 7.85UT TOYOKAWA-FUJI






3C286 2026/07/30 7.85UT TOYOKAWA-KISO








3C286 2026/07/30 7.85UT FUJI -KISO



T20260730170546





BLK: 5,SNR1: 0.85884 ,SNR2: 3.7086




Frequency (Hz)

F20260730170546




BLK: 5,SNR1: 3.0621 ,SNR2: 8.8679





Frequency (Hz)


1345+12 2026/07/30 8.12UT TOYOKAWA-FUJI



T20260730170546





BLK: 5, SNR1: 1.0803 , SNR2: 3.4585




Frequency (Hz)

K20260730170546




BLK: 5, SNR1: 3.7018 , SNR2: 10.579





Frequency (Hz)

1345+12 2026/07/30 8.12UT TOYOKAWA-KISO






F20260730170546





BLK:11,SNR1: 4.5920 ,SNR2: 11.875




Frequency (Hz)

K20260730170545




BLK:11,SNR1: 2.9907 ,SNR2: 6.2834




Frequency (Hz)


1345+12 2026/07/30 8.12UT FUJI -KISO



T20260730181144





BLK: 1, SNR1: 8.5832 , SNR2: 20.053




Frequency (Hz)

F20260730181144







BLK: 1, SNR1: 12.809 , SNR2: 31.328




Frequency (Hz)



1452+502 2026/07/30 9.22UT TOYOKAWA-FUJI








BLK: 3,SNR1: 14.459 ,SNR2: 31.416



BLK: 3,SNR1: 19.274 ,SNR2: 34.153



1452+502 2026/07/30 9.22UT FUJI -KISO

