



T20260808060449





No.Good Data




Frequency (Hz)

F20260808060449







No.Good Data






Frequency (Hz)

3084 2026/08/07 21.11UT TOYOKAWA-FUJI













T20260808062121




BLK: 5,SNR1: 0.73670E-01,SNR2: 0.63470




F20260808062121





BLK: 5,SNR1: 1.9016 ,SNR2: 6.5219




0333+32 2026/08/07 21.38UT TOYOKAWA-FUJI





T20260808062121




BLK: 6,SNR1: 0.64613E-01,SNR2: 0.48936




K20260808062120





BLK: 6,SNR1: 1.1681 ,SNR2: 3.7145




0333+32 2026/08/07 21.38UT TOYOKAWA-KISO





F20260808062121




BLK:13,SNR1: 0.90685 ,SNR2: 2.8941




K20260808062120





BLK:13,SNR1: 0.95717 ,SNR2: 3.2880




0333+32 2026/08/07 21.38UT FUJI -KISO




T20260808065907




BLK: 2,SNR1: 0.39512 ,SNR2: 3.3976




F20260808065907





BLK: 2,SNR1: 0.60023 ,SNR2: 5.2316




0411+05 2026/08/07 22.01UT TOYOKAWA-FUJI





T20260808065907




BLK: 2,SNR1: 0.71553E-01,SNR2: 0.35736




K20260808065906




BLK: 2,SNR1:-0.15965E-01,SNR2: 0.35288




0411+05 2026/08/07 22.01UT TOYOKAWA-KISO





F20260808065907




BLK: 5, SNR1: 0.36977 , SNR2: 2.3021




K20260808065906




BLK: 5, SNR1: 0.37322 , SNR2: 8.2841





0411+05 2026/08/07 22.01UT FUJI -KISO







BLK: 2,SNR1: 3.6493 ,SNR2: 9.0583






BLK: 2,SNR1: 16.157 ,SNR2: 28.485




0418+236 2026/08/07 22.13UT TOYOKAWA-FUJI










F20260808070602




BLK: 2, SNR1: 20.848 , SNR2: 31.559




K20260808070601





BLK: 2, SNR1: 19.216 , SNR2: 33.737




0418+236 2026/08/07 22.13UT FUJI -KISO





T20260808071730




BLK: 4,SNR1: 0.69438 ,SNR2: 3.7276




F20260808071730





BLK: 4,SNR1: 6.1222 ,SNR2: 13.818




3C119 2026/08/07 22.32UT TOYOKAWA-FUJI





T20260808071730




BLK: 3,SNR1: 0.47007 ,SNR2: 3.1486




K20260808071729





BLK: 3,SNR1: 1.7078 ,SNR2: 5.5315




3C119 2026/08/07 22.32UT TOYOKAWA-KISO




F20260808071730




BLK: 7,SNR1: 5.1760 ,SNR2: 11.859




K20260808071729




BLK: 7,SNR1: 2.6322 ,SNR2: 7.9989




3C119 2026/08/07 22.32UT FUJI -KISO



T20260808080536





BLK: 5, SNR1: 0.60533 , SNR2: 1.8322




Frequency (Hz)

F20260808080536




BLK: 5, SNR1: 0.12214 , SNR2: 1.4900





Frequency (Hz)


3C138 2026/08/07 23.12UT TOYOKAWA-FUJI





T20260808080536




BLK:14,SNR1: 0.52171 ,SNR2: 3.4210




K20260808080535




BLK:14,SNR1: 0.86259 ,SNR2: 3.8412




3C138 2026/08/07 23.12UT TOYOKAWA-KISO



F20260808080536





BLK: 5,SNR1:-0.13023 ,SNR2: 0.90195





3C138 2026/08/07 23.12UT FUJI -KISO


K20260808080535





BLK: 5,SNR1: 1.6830 ,SNR2: 5.4389









BLK: 4,SNR1: 8.1663 ,SNR2: 23.514





BLK: 4,SNR1: 6.5044 ,SNR2: 17.061





0531+194 2026/08/07 23.35UT TOYOKAWA-FUJI







0531+194 2026/08/07 23.35UT TOYOKAWA-KISO







BLK: 3,SNR1: 11.867 ,SNR2: 27.383





BLK: 3,SNR1: 12.967 ,SNR2: 32.316




0531+194 2026/08/07 23.35UT FUJI -KISO




T20260808082731




BLK: 7, SNR1: 11.471 ,SNR2: 20.077




F20260808082731





BLK: 7, SNR1: 8.7250 ,SNR2: 13.332




3C147 2026/08/07 23.49UT TOYOKAWA-FUJI





T20260808082731




BLK: 8, SNR1: 18.438 , SNR2: 39.536




K20260808082730




BLK: 8, SNR1: 10.515 , SNR2: 13.808




3C147 2026/08/07 23.49UT TOYOKAWA-KISO




F20260808082731




BLK: 5, SNR1: 1.5167 ,SNR2: 8.5385




K20260808082730







BLK: 5, SNR1: 8.9531 ,SNR2: 16.157




3C147 2026/08/07 23.49UT FUJI -KISO







0548+16 2026/08/07 23.62UT TOYOKAWA-FUJI





T20260808083540




BLK: 5, SNR1: 2.9504 , SNR2: 7.0182




K20260808083539




BLK: 5, SNR1: 8.0129 , SNR2: 19.844





0548+16 2026/08/07 23.62UT TOYOKAWA-KISO









BLK: 4, SNR1: 18.817 , SNR2: 34.688




BLK: 4, SNR1: 8.9349 , SNR2: 22.422





0548+16 2026/08/07 23.62UT FUJI -KISO







BLK:11,SNR1: 4.9716 ,SNR2: 14.663








BLK:11,SNR1: 118.54 ,SNR2: 146.72





0552+12 2026/08/07 23.69UT TOYOKAWA-FUJI







F20260808083951




BLK:14,SNR1: 90.530 ,SNR2: 112.07




K20260808083950





BLK:14,SNR1: 9.3978 ,SNR2: 26.557




0552+12 2026/08/07 23.69UT FUJI -KISO



T20260808084418





No.Good Data




Frequency (Hz)

F20260808084418




No.Good Data




Frequency (Hz)


0556+191 2026/08/07 23.77UT TOYOKAWA-FUJI




T20260808084418




BLK: 3, SNR1: 16.691 , SNR2: 29.206




K20260808084417





BLK: 3, SNR1: 13.042 , SNR2: 30.649




0556+191 2026/08/07 23.77UT TOYOKAWA-KISO





F20260808084418




No.Good Data




K20260808084417





No.Good Data




0556+191 2026/08/07 23.77UT FUJI -KISO





T20260808084851




No.Good Data




F20260808084851



No.Good Data





3C152 2026/08/07 23.84UT TOYOKAWA-FUJI








T20260808084851




No.Good Data




K20260808084850




No.Good Data




3C152 2026/08/07 23.84UT TOYOKAWA-KISO




F20260808084851




No.Good Data




K20260808084850




No.Good Data




3C152 2026/08/07 23.84UT FUJI -KISO





T20260808091111




BLK: 4, SNR1: 6.1871 , SNR2: 14.411




F20260808091111




BLK: 4, SNR1: 3.9402 , SNR2: 9.5867




3C161 2026/08/08 0.21UT TOYOKAWA-FUJI





T20260808091111




BLK: 5, SNR1: 7.0820 , SNR2: 17.039




K20260808091110




BLK: 5, SNR1: 9.5411 , SNR2: 29.335




3C161 2026/08/08 0.21UT TOYOKAWA-KISO




F20260808091111




BLK: 1,SNR1: 9.6884 ,SNR2: 23.138




K20260808091110





BLK: 1,SNR1: 14.124 ,SNR2: 33.883




3C161 2026/08/08 0.21UT FUJI -KISO





T20260808093843




No.Good Data




F20260808093843




No.Good Data




0652-130 2026/08/08 0.67UT TOYOKAWA-FUJI





T20260808093843




BLK: 1,SNR1: 0.35184 ,SNR2: 0.98803




K20260808093842





BLK: 1,SNR1: 1.3798 ,SNR2: 9.1150




0652-130 2026/08/08 0.67UT TOYOKAWA-KISO





F20260808093843




No.Good Data




K20260808093842



No.Good Data




0652-130 2026/08/08 0.67UT FUJI -KISO








T20260808095021




BLK: 2, SNR1: 8.9986 , SNR2: 23.405




F20260808095021





BLK: 2, SNR1: 6.7684 , SNR2: 22.271




0703+138 2026/08/08 0.87UT TOYOKAWA-FUJI



T20260808095021





BLK: 1,SNR1: 0.61618 ,SNR2: 0.70791




Frequency (Hz)

K20260808095020




BLK: 1,SNR1: 1.2678 ,SNR2: 9.3559




Frequency (Hz)


0703+138 2026/08/08 0.87UT TOYOKAWA-KISO




F20260808095021




BLK: 3, SNR1: 1.8285 , SNR2: 2.9837




K20260808095020





BLK: 3, SNR1: 1.2526 , SNR2: 4.5197




0703+138 2026/08/08 0.87UT FUJI -KISO





T20260808095943




BLK:11,SNR1: 2.6855 ,SNR2: 4.7571




F20260808095943





BLK:11,SNR1: 46.186 ,SNR2: 45.739




0713-024 2026/08/08 1.02UT TOYOKAWA-FUJI




T20260808095943




BLK: 3,SNR1: 0.39150 ,SNR2: 1.5191




K20260808095942





BLK: 3,SNR1: 2.6582 ,SNR2: 8.3336




0713-024 2026/08/08 1.02UT TOYOKAWA-KISO





F20260808095943




BLK: 7, SNR1: 30.313 ,SNR2: 41.345




K20260808095942





BLK: 7, SNR1: 2.1848 ,SNR2: 6.9613




0713-024 2026/08/08 1.02UT FUJI -KISO



T20260808100955





No.Good Data




Frequency (Hz)

F20260808100955




No.Good Data





Frequency (Hz)


0723+10 2026/08/08 1.19UT TOYOKAWA-FUJI




T20260808100955




No. Good Data




K20260808100954



No. Good Data




0723+10 2026/08/08 1.19UT TOYOKAWA-KISO







F20260808100955




BLK: 1, SNR1: 1.4776 , SNR2: 10.050




K20260808100954





BLK: 1, SNR1: 0.40049 , SNR2: 1.3403




0723+10 2026/08/08 1.19UT FUJI -KISO




T20260808102011




BLK: 8,SNR1: 0.16541 ,SNR2: 0.99529




F20260808102011





BLK: 8,SNR1: 1.4096 ,SNR2: 3.4718




0732+33 2026/08/08 1.36UT TOYOKAWA-FUJI





T20260808102011




BLK: 6, SNR1: 0.18875 , SNR2: 2.9816




K20260808102010




BLK: 6, SNR1: 0.42952 , SNR2: 2.2261




0732+33 2026/08/08 1.36UT TOYOKAWA-KISO





F20260808102011




BLK: 5, SNR1: 0.73702, SNR2: 2.2147




K20260808102010







BLK: 5, SNR1: 0.52179, SNR2: 2.2467








0732+33 2026/08/08 1.36UT FUJI -KISO






0741-06 2026/08/08 1.50UT TOYOKAWA-FUJI







0741-06 2026/08/08 1.50UT TOYOKAWA-KISO





F20260808102811




BLK: 3, SNR1: 14.633 , SNR2: 35.978




K20260808102810




BLK: 3, SNR1: 6.5157 , SNR2: 19.461




0741-06 2026/08/08 1.50UT FUJI -KISO





T20260808103755




BLK: 2, SNR1: 14.127 , SNR2: 25.274




F20260808103755



BLK: 2, SNR1: 1.8728 , SNR2: 10.164




0752-200 2026/08/08 1.66UT TOYOKAWA-FUJI








T20260808103755




BLK: 2, SNR1: 24.817 , SNR2: 40.105




K20260808103754





BLK: 2, SNR1: 14.063 , SNR2: 28.470




0752-200 2026/08/08 1.66UT TOYOKAWA-KISO





F20260808103755




BLK: 2, SNR1: 12.889 , SNR2: 28.750




K20260808103754





BLK: 2, SNR1: 1.2742 , SNR2: 9.8238




0752-200 2026/08/08 1.66UT FUJI -KISO





T20260808104531




BLK:10,SNR1: 0.21728 ,SNR2: 1.9896




F20260808104531





BLK:10,SNR1: 0.35924 ,SNR2: 1.4900




3C190 2026/08/08 1.79UT TOYOKAWA-FUJI





T20260808104531




BLK:15,SNR1: 0.23663 ,SNR2: 3.8249




K20260808104530




BLK:15,SNR1: 0.54776 ,SNR2: 2.4154




3C190 2026/08/08 1.79UT TOYOKAWA-KISO





F20260808104531




BLK: 3, SNR1: 0.77439 , SNR2: 2.5352




K20260808104530





BLK: 3, SNR1: 0.78462 , SNR2: 3.3904




3C190 2026/08/08 1.79UT FUJI -KISO





T20260808105757




BLK:19,SNR1: 3.1916 ,SNR2: 9.7739




F20260808105757





BLK:19,SNR1: 0.25064 ,SNR2: 1.7663




3C196 2026/08/08 1.99UT TOYOKAWA-FUJI





T20260808105757




BLK:25,SNR1: 3.2591 ,SNR2: 9.9486




K20260808105756





BLK:25,SNR1: 1.6634 ,SNR2: 5.3431




3C196 2026/08/08 1.99UT TOYOKAWA-KISO



F20260808105757





BLK:24,SNR1: 1.2832 ,SNR2: 3.7182




Frequency (Hz)

3C196 2026/08/08 1.99UT FUJI -KISO


K20260808105756



BLK:24,SNR1: 1.5304 ,SNR2: 4.9515





Frequency (Hz)








T20260808110906




BLK: 7,SNR1: 0.29103 ,SNR2: 2.9241




F20260808110906




BLK: 7,SNR1: 1.9431 ,SNR2: 10.485




0821+394 2026/08/08 2.18UT TOYOKAWA-FUJI




T20260808110906




BLK:14,SNR1: 0.25056 ,SNR2: 1.2855




K20260808110905







BLK:14,SNR1: 0.16917 ,SNR2: 0.80867




0821+394 2026/08/08 2.18UT TOYOKAWA-KISO







0821+394 2026/08/08 2.18UT FUJI -KISO





T20260808112044




BLK:10,SNR1: 0.25313 ,SNR2: 2.7215




F20260808112044




BLK:10,SNR1: 8.0804 ,SNR2: 17.438




0834-19 2026/08/08 2.37UT TOYOKAWA-FUJI





T20260808112044




BLK:11,SNR1: 2.9035 ,SNR2: 7.1922




K20260808112043




BLK:11,SNR1: 3.1827 ,SNR2: 9.7953




0834-19 2026/08/08 2.37UT TOYOKAWA-KISO





F20260808112044




BLK:17,SNR1: 5.7796 ,SNR2: 13.171




K20260808112043





BLK:17,SNR1: 2.2699 ,SNR2: 7.4216




0834-19 2026/08/08 2.37UT FUJI -KISO




T20260808112550




BLK:12,SNR1: 11.195 ,SNR2: 23.660




F20260808112550




BLK:12,SNR1: 41.272 ,SNR2: 48.425





0839-071 2026/08/08 2.46UT TOYOKAWA-FUJI







BLK:15,SNR1: 3.7524 ,SNR2: 11.127




BLK:15,SNR1: 12.974 ,SNR2: 28.868





0839-071 2026/08/08 2.46UT TOYOKAWA-KISO









BLK:10,SNR1: 44.446 ,SNR2: 52.150




BLK:10,SNR1: 7.3561 ,SNR2: 18.309




0839-071 2026/08/08 2.46UT FUJI -KISO




T20260808113652




BLK:11,SNR1: 0.95663 ,SNR2: 3.0668




F20260808113652




BLK:11,SNR1: 6.5790 ,SNR2: 16.200




3C208 2026/08/08 2.64UT TOYOKAWA-FUJI




T20260808113652




BLK: 8, SNR1: 0.41959 , SNR2: 1.6481




K20260808113651





BLK: 8, SNR1: 5.2107 , SNR2: 13.110




3C208 2026/08/08 2.64UT TOYOKAWA-KISO



F20260808113652





BLK: 5,SNR1: 0.93175 ,SNR2: 4.2198






3C208 2026/08/08 2.64UT FUJI -KISO

K20260808113651





BLK: 5,SNR1: 2.2686 ,SNR2: 7.9893







BLK:13,SNR1: 9.9932 ,SNR2: 17.438




BLK:13,SNR1: 7.9074 ,SNR2: 18.053





3C216 2026/08/08 2.92UT TOYOKAWA-FUJI







BLK:20,SNR1: 10.643 ,SNR2: 19.057












BLK:20,SNR1: 6.3391 ,SNR2: 16.197




3C216 2026/08/08 2.92UT TOYOKAWA-KISO










0919-142 2026/08/08 3.12UT TOYOKAWA-FUJI









BLK: 1,SNR1: 0.32221E-01,SNR2: 0.96788







BLK: 1,SNR1: 0.38258E-03,SNR2: 0.88168




0919-142 2026/08/08 3.12UT TOYOKAWA-KISO








0919-142 2026/08/08 3.12UT FUJI -KISO





T20260808121223




BLK: 4,SNR1: 10.444 ,SNR2: 31.180




F20260808121223





BLK: 4,SNR1: 17.921 ,SNR2: 34.257




0926+117 2026/08/08 3.23UT TOYOKAWA-FUJI





T20260808121223




BLK: 3, SNR1: 10.140 , SNR2: 30.257




K20260808121222







BLK: 3, SNR1: 6.5265 , SNR2: 17.755





0926+117 2026/08/08 3.23UT TOYOKAWA-KISO







0926+117 2026/08/08 3.23UT FUJI -KISO








BLK:19,SNR1: 1.3314 ,SNR2: 5.9105




BLK:19,SNR1: 0.45814 ,SNR2: 3.8899




T20260808122008




BLK:21,SNR1: 1.5088 ,SNR2: 4.2162




K20260808122007




BLK:21,SNR1: 1.2639 ,SNR2: 4.0927





3C222 2026/08/08 3.36UT TOYOKAWA-KISO







BLK: 9,SNR1: 0.93048 ,SNR2: 3.7723



BLK: 9,SNR1: 1.0362 ,SNR2: 5.5219





3C222 2026/08/08 3.36UT FUJI -KISO







T20260808122707




BLK: 8, SNR1: 10.316 , SNR2: 25.631




F20260808122707





BLK: 8, SNR1: 9.0405 , SNR2: 21.975




0941-08 2026/08/08 3.48UT TOYOKAWA-FUJI




T20260808122707




BLK: 5, SNR1: 10.035 , SNR2: 29.108




K20260808122706




BLK: 5, SNR1: 8.9610 , SNR2: 25.759




0941-08 2026/08/08 3.48UT TOYOKAWA-KISO




F20260808122707




BLK:10,SNR1: 7.9439 ,SNR2: 20.382




K20260808122706




BLK:10,SNR1: 9.9382 ,SNR2: 25.038




0941-08 2026/08/08 3.48UT FUJI -KISO




T20260808123529




BLK:12,SNR1: 0.73780 ,SNR2: 4.7234




F20260808123529




BLK:12,SNR1:-0.22986 ,SNR2: 1.9535





3C230 2026/08/08 3.62UT TOYOKAWA-FUJI







BLK:15,SNR1: 0.65988 ,SNR2: 4.1143




BLK:15,SNR1: 6.3294 ,SNR2: 8.2923




3C230 2026/08/08 3.62UT TOYOKAWA-KISO




F20260808123529




BLK: 9,SNR1:-0.19648 ,SNR2: 0.62450




K20260808123528





BLK: 9,SNR1: 2.1502 ,SNR2: 6.7037




3C230 2026/08/08 3.62UT FUJI -KISO




T20260808124937




BLK: 9,SNR1: 1.6107 ,SNR2: 12.884




F20260808124937




BLK: 9,SNR1: 10.451 ,SNR2: 24.901





3C236 2026/08/08 3.86UT TOYOKAWA-FUJI







BLK:14,SNR1: 9.2708 ,SNR2: 23.688




BLK:14,SNR1: 10.445 ,SNR2: 25.177





3C236 2026/08/08 3.86UT TOYOKAWA-KISO









BLK:12,SNR1: 10.346 ,SNR2: 25.592




BLK:12,SNR1: 28.038 ,SNR2: 31.104




3C236 2026/08/08 3.86UT FUJI -KISO




T20260808125747




BLK: 1,SNR1: 3.5776 ,SNR2: 11.503




F20260808125747




BLK: 1,SNR1: 0.54756 ,SNR2: 3.5650




1011+110 2026/08/08 3.99UT TOYOKAWA-FUJI





T20260808125747




BLK: 8,SNR1: 6.2801 ,SNR2: 16.059




K20260808125746




BLK: 8,SNR1: 0.52887 ,SNR2: 1.4173




1011+110 2026/08/08 3.99UT TOYOKAWA-KISO




F20260808125747




BLK: 6,SNR1: 7.2052 ,SNR2: 19.419




K20260808125746




BLK: 6,SNR1: 8.1623 ,SNR2: 20.482




1011+110 2026/08/08 3.99UT FUJI -KISO




T20260808130528




BLK:10,SNR1: 0.91261 ,SNR2: 6.2522




F20260808130528




BLK:10,SNR1: 8.6006 ,SNR2: 18.847




3C241 2026/08/08 4.12UT TOYOKAWA-FUJI





T20260808130528




BLK: 7,SNR1: 1.2415 ,SNR2: 5.1318




K20260808130527




BLK: 7,SNR1: 1.9950 ,SNR2: 5.6009





3C241 2026/08/08 4.12UT TOYOKAWA-KISO







BLK: 6,SNR1: 0.27954 ,SNR2: 3.2856




BLK: 6,SNR1: 0.92919 ,SNR2: 4.2843





3C241 2026/08/08 4.12UT FUJI -KISO







BLK: 2,SNR1:−0.90436E−01,SNR2: 0.59236




BLK: 2,SNR1:−0.65792E−01,SNR2: 1.7570





1031-11 2026/08/08 4.31UT TOYOKAWA-FUJI









BLK: 3,SNR1: 0.30550E-01,SNR2: 1.8742




BLK: 3,SNR1: 1.7846 ,SNR2: 6.8059




1031-11 2026/08/08 4.31UT TOYOKAWA-KISO




F20260808131657




BLK: 7,SNR1: 4.4904 ,SNR2: 11.289




K20260808131656




BLK: 7,SNR1: 3.1724 ,SNR2: 9.0275




1031-11 2026/08/08 4.31UT FUJI -KISO




T20260808132130




BLK: 7,SNR1: 11.204 ,SNR2: 28.064




F20260808132130




BLK: 7,SNR1: 8.1577 ,SNR2: 20.417




1035-058 2026/08/08 4.39UT TOYOKAWA-FUJI




T20260808132130




BLK:13,SNR1: 9.9463 ,SNR2: 28.258




K20260808132129




BLK:13,SNR1: 4.8585 ,SNR2: 7.3906




1035-058 2026/08/08 4.39UT TOYOKAWA-KISO




F20260808132130




BLK:14,SNR1: 5.9198 ,SNR2: 15.712




K20260808132129





BLK:14,SNR1: 10.218 ,SNR2: 18.084





1035-058 2026/08/08 4.39UT FUJI -KISO




T20260808133043





F20260808133043





1044-008 2026/08/08 4.54UT TOYOKAWA-FUJI




T20260808133043




K20260808133042




1044-008 2026/08/08 4.54UT TOYOKAWA-KISO





F20260808133043




BLK:11,SNR1: 14.325 ,SNR2: 29.219




K20260808133042




BLK:11,SNR1: 1.2842 ,SNR2: 1.2323





1044-008 2026/08/08 4.54UT FUJI -KISO









BLK: 6,SNR1: 5.0455 ,SNR2: 12.713








BLK: 6,SNR1: 2.9047 ,SNR2: 7.5916




1055+01 2026/08/08 4.72UT TOYOKAWA-FUJI








F20260808134147




BLK: 5,SNR1: 5.9025 ,SNR2: 14.016




K20260808134146




BLK: 5,SNR1: 5.5729 ,SNR2: 10.182




1055+01 2026/08/08 4.72UT FUJI -KISO





T20260808135305




BLK: 7,SNR1: 3.3747 ,SNR2: 9.4214




F20260808135305




BLK: 7,SNR1: 9.2590 ,SNR2: 17.389




1107+109 2026/08/08 4.91UT TOYOKAWA-FUJI





T20260808135305




BLK: 8,SNR1: 0.68821 ,SNR2: 2.7849




K20260808135304





BLK: 8,SNR1: 2.3404 ,SNR2: 8.7537




1107+109 2026/08/08 4.91UT TOYOKAWA-KISO





F20260808135305




BLK: 8,SNR1: 4.0879 ,SNR2: 9.6828




K20260808135304





BLK: 8,SNR1: 1.8683 ,SNR2: 7.0962




1107+109 2026/08/08 4.91UT FUJI -KISO





T20260808140242




BLK: 6,SNR1: 0.47164 ,SNR2: 2.5956




F20260808140242





BLK: 6,SNR1: 3.3079 ,SNR2: 5.0572




3C255 2026/08/08 5.07UT TOYOKAWA-FUJI





T20260808140242




BLK: 9,SNR1: 1.6401 ,SNR2: 7.7221




K20260808140241




BLK: 9,SNR1: 2.2282 ,SNR2: 8.0053





3C255 2026/08/08 5.07UT TOYOKAWA-KISO









BLK: 8,SNR1: 3.7767 ,SNR2: 5.5696




BLK: 8,SNR1: 0.75459 ,SNR2: 3.8081





3C255 2026/08/08 5.07UT FUJI -KISO







BLK: 3,SNR1: 0.21830 ,SNR2: 1.7759




BLK: 3,SNR1: 3.1410 ,SNR2: 7.9853





1127-14 2026/08/08 5.25UT TOYOKAWA-FUJI







BLK: 9,SNR1: 4.2343 ,SNR2: 5.6865




BLK: 9,SNR1: 7.4974 ,SNR2: 14.476





1127-14 2026/08/08 5.25UT TOYOKAWA-KISO







BLK: 7,SNR1: 0.10900 ,SNR2: 2.7608




BLK: 7,SNR1: 6.3544 ,SNR2: 16.937





1127-14 2026/08/08 5.25UT FUJI -KISO







BLK: 7,SNR1: 6.7720 ,SNR2: 17.381




BLK: 7,SNR1: 7.0100 ,SNR2: 12.306





3C263.1 2026/08/08 5.47UT TOYOKAWA-FUJI







BLK:11,SNR1: 3.8691 ,SNR2: 9.9830








BLK:11,SNR1: 4.7902 ,SNR2: 18.802




3C263.1 2026/08/08 5.47UT TOYOKAWA-KISO









T20260808143307




F20260808143307





3C267 2026/08/08 5.58UT TOYOKAWA-FUJI









BLK: 8,SNR1: 0.87091 ,SNR2: 5.4963




BLK: 8,SNR1: 71.727 ,SNR2: 97.711




3C267 2026/08/08 5.58UT TOYOKAWA-KISO




F20260808143307




BLK: 7,SNR1: 7.3114 ,SNR2: 18.380




K20260808143308




BLK: 7,SNR1: 71.727 ,SNR2: 97.711






3C267 2026/08/08 5.58UT FUJI -KISO




T20260808145855









F20260808145855




1213-17 2026/08/08 6.01UT TOYOKAWA-FUJI










T20260808151212




BLK: 4,SNR1: 2.0232 ,SNR2: 8.1115




F20260808151212




BLK: 4,SNR1: 2.9710 ,SNR2: 7.0584




3C273 2026/08/08 6.23UT TOYOKAWA-FUJI





T20260808151212




BLK: 8,SNR1: 3.1488 ,SNR2: 11.029




K20260808151211





BLK: 8,SNR1: 1.2624 ,SNR2: 3.7693




3C273 2026/08/08 6.23UT TOYOKAWA-KISO





F20260808151212




BLK:10,SNR1: 13.311 ,SNR2: 24.447




K20260808151211



BLK:10,SNR1: 2.2539 ,SNR2: 6.4099




3C273 2026/08/08 6.23UT FUJI -KISO








T20260808152523




BLK: 5,SNR1: 2.0234 ,SNR2: 5.1278




F20260808152523





BLK: 5,SNR1: 5.7327 ,SNR2: 9.3371




3C275 2026/08/08 6.45UT TOYOKAWA-FUJI





T20260808152523




BLK: 8,SNR1: 0.87700 ,SNR2: 2.5260




K20260808152522





BLK: 8,SNR1: 0.89862 ,SNR2: 5.5783




3C275 2026/08/08 6.45UT TOYOKAWA-KISO





F20260808152523




BLK:11,SNR1: 10.186 ,SNR2: 9.7204




K20260808152522




BLK:11,SNR1: 1.3431 ,SNR2: 7.4052





3C275 2026/08/08 6.45UT FUJI -KISO







BLK: 4,SNR1: 7.7555 ,SNR2: 19.505




BLK: 4,SNR1: 7.0936 ,SNR2: 17.728





1245-19 2026/08/08 6.55UT TOYOKAWA-FUJI







BLK: 3,SNR1: 6.9818 ,SNR2: 17.351





BLK: 3,SNR1: 3.1315 ,SNR2: 4.1561




1245-19 2026/08/08 6.55UT TOYOKAWA-KISO





F20260808153128




BLK: 5,SNR1: 5.6103 ,SNR2: 8.7715




K20260808153127



BLK: 5,SNR1: 2.7354 ,SNR2: 3.3891





1245-19 2026/08/08 6.55UT FUJI -KISO








T20260808153912




BLK: 5,SNR1: 1.5913 ,SNR2: 2.7161




K20260808153911




BLK: 5,SNR1: 2.9370 ,SNR2: 3.9216





3C279 2026/08/08 6.68UT TOYOKAWA-KISO









BLK: 6,SNR1: 3.1709 ,SNR2: 7.9357




BLK: 6,SNR1: 2.1423 ,SNR2: 4.9671




3C279 2026/08/08 6.68UT FUJI -KISO




T20260808155441




BLK: 8,SNR1: 7.3318 ,SNR2: 17.873




F20260808155441




BLK: 8,SNR1: 15.015 ,SNR2: 22.594





3C283 2026/08/08 6.94UT TOYOKAWA-FUJI







BLK: 7,SNR1: 6.3814 ,SNR2: 15.670




BLK: 7,SNR1: 4.2497 ,SNR2: 12.553




3C283 2026/08/08 6.94UT TOYOKAWA-KISO





F20260808155441




BLK:13,SNR1: 18.782 ,SNR2: 23.562




K20260808155440





BLK:13,SNR1: 2.2106 ,SNR2: 7.0501




3C283 2026/08/08 6.94UT FUJI -KISO




T20260808160905




BLK: 1, SNR1: 0.14646 , SNR2: 1.6509




F20260808160905







BLK: 1, SNR1: 1.1236 , SNR2: 10.002




1323+32 2026/08/08 7.18UT TOYOKAWA-FUJI







1323+32 2026/08/08 7.18UT TOYOKAWA-KISO





F20260808160905




BLK: 5, SNR1: 5.5996 , SNR2: 12.155




K20260808160904




BLK: 5, SNR1: 0.26886E-01, SNR2: 2.4386





1323+32 2026/08/08 7.18UT FUJI -KISO







BLK: 8,SNR1: 2.2642 ,SNR2: 7.4979







BLK: 8,SNR1: 0.82552 ,SNR2: 2.7642




3C286 2026/08/08 7.26UT TOYOKAWA-FUJI










3C286 2026/08/08 7.26UT TOYOKAWA-KISO







BLK: 9, SNR1: 1.8134 , SNR2: 4.5323





BLK: 9, SNR1: 2.7848 , SNR2: 3.5862




3C286 2026/08/08 7.26UT FUJI -KISO



T20260808163023





BLK: 2,SNR1: 8.7928 ,SNR2: 21.730




Frequency (Hz)

F20260808163023





BLK: 2,SNR1: 17.518 ,SNR2: 42.573





Frequency (Hz)

1345+12 2026/08/08 7.53UT TOYOKAWA-FUJI







BLK: 1,SNR1: 0.93475 ,SNR2: 8.9762





BLK: 1,SNR1: 1.2436 ,SNR2: 8.9822





1345+12 2026/08/08 7.53UT TOYOKAWA-KISO




F20260808163023




K20260808163022





1345+12 2026/08/08 7.53UT FUJI -KISO







BLK: 3,SNR1: 8.7084 ,SNR2: 20.852







BLK: 3,SNR1: 0.80308 ,SNR2: 2.0054




1355+01 2026/08/08 7.71UT TOYOKAWA-FUJI








1355+01 2026/08/08 7.71UT TOYOKAWA-KISO



F20260808164043




BLK: 8,SNR1: 0.30150E-01,SNR2: 3.3286




Frequency (Hz)

K20260808164042




BLK: 8,SNR1: 14.754 ,SNR2: 18.486







Frequency (Hz)


1355+01 2026/08/08 7.71UT FUJI -KISO










3C298 2026/08/08 8.06UT TOYOKAWA-FUJI







BLK:11,SNR1: 4.2961 ,SNR2: 8.0866




BLK:11,SNR1: 10.879 ,SNR2: 14.691





3C298 2026/08/08 8.06UT TOYOKAWA-KISO






BLK: 2,SNR1: 0.51565 ,SNR2: 2.4718



BLK: 2,SNR1: 3.0170 ,SNR2: 6.5045



3C298 2026/08/08 8.06UT FUJI -KISO

