




T20260809060053





BLK: 4,SNR1: 0.99540E-01,SNR2: 0.81831





3C84 2026/08/08 21.04UT TOYOKAWA-FUJI



F20260809060053




BLK: 4,SNR1: 0.30097 ,SNR2: 1.1923



T20260809060053





BLK: 9,SNR1: 0.99145E-01,SNR2: 0.76892





3C84 2026/08/08 21.04UT TOYOKAWA-KISO

K20260809060052




BLK: 9,SNR1: 0.19497 ,SNR2: 1.0644







F20260809060053




BLK: 6,SNR1: 0.17399 ,SNR2: 1.7333




K20260809060052









BLK: 6,SNR1: 0.18643 ,SNR2: 1.2818




3C84 2026/08/08 21.04UT FUJI -KISO













BLK: 7,SNR1: 0.86824 ,SNR2: 2.7601









BLK: 7,SNR1: 2.2087 ,SNR2: 5.4455





0333+32 2026/08/08 21.32UT FUJI -KISO








F20260809065511




BLK: 3,SNR1:-0.22266 ,SNR2: 2.3501




Frequency (Hz)

K20260809065510




BLK: 3,SNR1: 0.49485E-01,SNR2: 1.0298





Frequency (Hz)


0411+05 2026/08/08 21.95UT FUJI -KISO





T20260809070206




No.Good Data




F20260809070206






No.Good Data







0418+236 2026/08/08 22.06UT TOYOKAWA-FUJI















BLK:16,SNR1: 9.6813 ,SNR2: 16.910




BLK:16,SNR1: 2.1898 ,SNR2: 7.0372





3C119 2026/08/08 22.25UT TOYOKAWA-FUJI







BLK:27,SNR1: 9.1109 ,SNR2: 15.915




BLK:27,SNR1: 7.8682 ,SNR2: 13.811





3C119 2026/08/08 22.25UT TOYOKAWA-KISO







BLK:23,SNR1: 2.2739 ,SNR2: 7.1437




BLK:23,SNR1: 8.0640 ,SNR2: 14.151





3C119 2026/08/08 22.25UT FUJI -KISO







BLK: 9,SNR1: 0.22451 ,SNR2: 1.8740




BLK: 9,SNR1: 5.6561 ,SNR2: 14.812





3C138 2026/08/08 23.06UT TOYOKAWA-FUJI







BLK:16,SNR1: 0.29645 ,SNR2: 1.4787







BLK:16,SNR1: 6.4690 ,SNR2: 16.446




3C138 2026/08/08 23.06UT TOYOKAWA-KISO







3C138 2026/08/08 23.06UT FUJI -KISO






T20260809081514





No.Good Data




Frequency (Hz)

F20260809081514




No.Good Data





Frequency (Hz)


0531+194 2026/08/08 23.28UT TOYOKAWA-FUJI





T20260809081514




No.Good Data




K20260809081513





No.Good Data




0531+194 2026/08/08 23.28UT TOYOKAWA-KISO





F20260809081514




No.Good Data




K20260809081513




No.Good Data





0531+194 2026/08/08 23.28UT FUJI -KISO







BLK:14,SNR1: 3.9893 ,SNR2: 18.377





BLK:14,SNR1: 0.79777 ,SNR2: 4.0811




3C147 2026/08/08 23.42UT TOYOKAWA-FUJI



T20260809082335





BLK:21,SNR1: 3.9201 ,SNR2: 14.799








3C147 2026/08/08 23.42UT TOYOKAWA-KISO

K20260809082334





BLK:21,SNR1: 1.6643 ,SNR2: 3.3017






T20260809083144





BLK: 1,SNR1: 0.65280 ,SNR2: 3.2635




Frequency (Hz)

F20260809083144




BLK: 1,SNR1: 0.14705 ,SNR2: 1.9883





Frequency (Hz)


0548+16 2026/08/08 23.56UT TOYOKAWA-FUJI





T20260809083144




BLK: 7, SNR1: 2.9796 , SNR2: 9.8074




K20260809083143



BLK: 7, SNR1: 5.6870 , SNR2: 16.682




0548+16 2026/08/08 23.56UT TOYOKAWA-KISO







F20260809083144




BLK: 3, SNR1: 1.3922 , SNR2: 4.7395




K20260809083143




BLK: 3, SNR1: 8.6497 , SNR2: 23.478





0548+16 2026/08/08 23.56UT FUJI -KISO







BLK: 5, SNR1: 6.2504 , SNR2: 14.618





BLK: 5, SNR1: 0.26469 , SNR2: 1.9857




0552+12 2026/08/08 23.63UT TOYOKAWA-FUJI





T20260809083555




BLK: 7, SNR1: 13.290 , SNR2: 51.978




K20260809083554









BLK: 7, SNR1: 0.93746 , SNR2: 4.8603





0552+12 2026/08/08 23.63UT TOYOKAWA-KISO









BLK: 3,SNR1: 11.913 ,SNR2: 29.646




BLK: 3,SNR1: 20.726 ,SNR2: 44.849





0556+191 2026/08/08 23.70UT TOYOKAWA-FUJI







BLK: 3,SNR1: 14.174 ,SNR2: 34.550




BLK: 3,SNR1: 16.094 ,SNR2: 28.678




0556+191 2026/08/08 23.70UT TOYOKAWA-KISO





F20260809084022




BLK: 1, SNR1: 18.472 , SNR2: 45.201




K20260809084021




BLK: 1, SNR1: 10.482 , SNR2: 25.786




0556+191 2026/08/08 23.70UT FUJI -KISO




T20260809084455




BLK: 3, SNR1: 9.7596 , SNR2: 23.636




F20260809084455



BLK: 3, SNR1: 10.500 , SNR2: 25.434




3C152 2026/08/08 23.78UT TOYOKAWA-FUJI







T20260809084455




BLK: 2, SNR1: 8.2298 , SNR2: 20.088




K20260809084454




BLK: 2, SNR1: 5.1760 , SNR2: 12.783




3C152 2026/08/08 23.78UT TOYOKAWA-KISO




F20260809084455




BLK: 2,SNR1: 22.604 ,SNR2: 41.661




K20260809084454




BLK: 2,SNR1: 8.6665 ,SNR2: 21.391




3C152 2026/08/08 23.78UT FUJI -KISO





T20260809085418




BLK: 6, SNR1: 8.8038 , SNR2: 23.675




F20260809085418




BLK: 6, SNR1: 9.0050 , SNR2: 22.871




0610+260 2026/08/08 23.93UT TOYOKAWA-FUJI





T20260809085418




BLK: 2, SNR1: 12.072 , SNR2: 34.855




K20260809085417




BLK: 2, SNR1: 9.6880 , SNR2: 28.064




0610+260 2026/08/08 23.93UT TOYOKAWA-KISO




F20260809085418




BLK: 7, SNR1: 8.1537 ,SNR2: 23.587




K20260809085417




BLK: 7, SNR1: 8.4448 ,SNR2: 21.316




0610+260 2026/08/08 23.93UT FUJI -KISO





T20260809090715




BLK: 9,SNR1: 8.4698 ,SNR2: 21.231




F20260809090715




BLK: 9,SNR1: 8.2215 ,SNR2: 21.172




3C161 2026/08/09 0.15UT TOYOKAWA—FUJI




T20260809090715




BLK: 9, SNR1: 11.846 , SNR2: 29.082




K20260809090714




BLK: 9, SNR1: 7.8268 , SNR2: 20.462




3C161 2026/08/09 0.15UT TOYOKAWA-KISO



F20260809090715




BLK: 3, SNR1: 10.427 , SNR2: 25.659





3C161 2026/08/09 0.15UT FUJI -KISO

K20260809090714




BLK: 3, SNR1: 10.274 , SNR2: 29.367








T20260809093447




BLK: 2, SNR1: 2.6716 , SNR2: 12.382




F20260809093447





BLK: 2, SNR1: 15.419 , SNR2: 25.082




0652-130 2026/08/09 0.61UT TOYOKAWA-FUJI





T20260809093447




BLK: 2, SNR1: 49.813 , SNR2: 56.852




K20260809093446





BLK: 2, SNR1: 9.1718 , SNR2: 23.534




0652-130 2026/08/09 0.61UT TOYOKAWA-KISO




F20260809093447




BLK: 2,SNR1: 3.7307 ,SNR2: 9.0524




K20260809093446







BLK: 2,SNR1: 17.103 ,SNR2: 36.168








0652-130 2026/08/09 0.61UT FUJI -KISO






0703+138 2026/08/09 0.80UT TOYOKAWA-FUJI








0703+138 2026/08/09 0.80UT TOYOKAWA-KISO




F20260809094625




BLK: 2, SNR1: 23.926 , SNR2: 43.340




K20260809094624




BLK: 2, SNR1: 12.722 , SNR2: 31.115




0703+138 2026/08/09 0.80UT FUJI -KISO




T20260809095547




BLK: 1,SNR1: 0.30612 ,SNR2: 1.3524




F20260809095547




BLK: 1,SNR1: 1.6299 ,SNR2: 5.6714




0713-024 2026/08/09 0.96UT TOYOKAWA-FUJI




T20260809095547




BLK: 4, SNR1: 5.3734 , SNR2: 9.6504




K20260809095546



BLK: 4, SNR1: 9.8028 , SNR2: 23.965




0713-024 2026/08/09 0.96UT TOYOKAWA-KISO







F20260809095547




BLK: 4, SNR1: 0.88810 , SNR2: 4.1363




K20260809095546





BLK: 4, SNR1: 1.8030 , SNR2: 3.2812




0713-024 2026/08/09 0.96UT FUJI -KISO





T20260809100559




BLK:14,SNR1: 2.1378 ,SNR2: 6.4490




F20260809100559





BLK:14,SNR1: 0.30397 ,SNR2: 1.5802




0723+10 2026/08/09 1.13UT TOYOKAWA-FUJI





T20260809100559




BLK:15,SNR1: 2.5323 ,SNR2: 7.4823




K20260809100558





BLK:15,SNR1: 6.0185 ,SNR2: 12.919




0723+10 2026/08/09 1.13UT TOYOKAWA-KISO





F20260809100559




BLK:15,SNR1: 3.0189 ,SNR2: 9.2357




K20260809100558





BLK:15,SNR1: 7.1306 ,SNR2: 15.274




0723+10 2026/08/09 1.13UT FUJI -KISO



T20260809101615





BLK: 6,SNR1: 0.27557 ,SNR2: 0.59961





0732+33 2026/08/09 1.30UT TOYOKAWA-FUJI



F20260809101615




BLK: 6,SNR1: 1.1553 ,SNR2: 3.0814





T20260809101615




BLK: 4,SNR1: 0.17805 ,SNR2: 0.89991




K20260809101614




BLK: 4,SNR1: 0.59967 ,SNR2: 2.6562




0732+33 2026/08/09 1.30UT TOYOKAWA-KISO




F20260809101615




BLK: 8,SNR1: 0.59765 ,SNR2: 2.3538




K20260809101614




BLK: 8,SNR1: 0.33728 ,SNR2: 2.5260




0732+33 2026/08/09 1.30UT FUJI -KISO





T20260809102415




BLK: 1, SNR1: 5.0403 , SNR2: 12.166




F20260809102415



BLK: 1, SNR1: 0.91798 , SNR2: 14.021





0741-06 2026/08/09 1.43UT TOYOKAWA-FUJI








T20260809102415




BLK: 3, SNR1: 5.8400 , SNR2: 14.607




K20260809102414





BLK: 3, SNR1: 6.6974 , SNR2: 16.613




0741-06 2026/08/09 1.43UT TOYOKAWA-KISO





F20260809102415




BLK: 1, SNR1: 8.8703 , SNR2: 21.776




K20260809102414




BLK: 1, SNR1: 9.6346 , SNR2: 23.906




0741-06 2026/08/09 1.43UT FUJI -KISO




T20260809103359




BLK: 4, SNR1: 3.7357 , SNR2: 11.229




F20260809103359




BLK: 4, SNR1: 2.0680 , SNR2: 13.603




0752-200 2026/08/09 1.59UT TOYOKAWA-FUJI




T20260809103359




BLK: 8, SNR1: 3.7614 , SNR2: 11.298




K20260809103358





BLK: 8, SNR1: 13.057 , SNR2: 27.835




0752-200 2026/08/09 1.59UT TOYOKAWA-KISO





F20260809103359




BLK: 2,SNR1: 6.2993 ,SNR2: 15.357




K20260809103358




BLK: 2,SNR1: 20.107 ,SNR2: 35.706




0752-200 2026/08/09 1.59UT FUJI -KISO





T20260809104135




BLK:10,SNR1: 0.86044 ,SNR2: 3.1418




F20260809104135




BLK:10,SNR1: 0.92452 ,SNR2: 3.4510




3C190 2026/08/09 1.72UT TOYOKAWA-FUJI





T20260809104135




BLK:14,SNR1: 0.90310 ,SNR2: 2.7519




K20260809104134





BLK:14,SNR1: 0.48569 ,SNR2: 3.7872




3C190 2026/08/09 1.72UT TOYOKAWA-KISO






3C190 2026/08/09 1.72UT FUJI -KISO








T20260809105402




BLK: 8, SNR1: 1.0405 , SNR2: 2.6748




F20260809105402




BLK: 8, SNR1: 2.4084 , SNR2: 9.2531




3C196 2026/08/09 1.93UT TOYOKAWA-FUJI





T20260809105402




BLK: 9,SNR1: 0.63723 ,SNR2: 4.3447




K20260809105401





BLK: 9,SNR1: 0.90522 ,SNR2: 3.8644




3C196 2026/08/09 1.93UT TOYOKAWA-KISO





F20260809105402




BLK: 6,SNR1: 1.5892 ,SNR2: 2.6035




K20260809105401




BLK: 6,SNR1: 1.3910 ,SNR2: 3.6882




3C196 2026/08/09 1.93UT FUJI -KISO





T20260809110511




BLK: 4,SNR1: 0.67085E-01,SNR2: 2.1362




F20260809110511




BLK: 4,SNR1: 6.2111 ,SNR2: 13.905





0821+394 2026/08/09 2.11UT TOYOKAWA-FUJI







BLK: 2,SNR1: 0.10781 ,SNR2: 1.0851







BLK: 2,SNR1: 2.8219 ,SNR2: 9.7442




0821+394 2026/08/09 2.11UT TOYOKAWA-KISO








0821+394 2026/08/09 2.11UT FUJI -KISO





T20260809111648




BLK: 4, SNR1: 0.12737 , SNR2: 1.4332




F20260809111648





BLK: 4, SNR1: 1.6630 , SNR2: 4.8917




0834-19 2026/08/09 2.31UT TOYOKAWA-FUJI





T20260809111648




BLK: 3,SNR1: 0.20562 ,SNR2: 3.7815




K20260809111647





BLK: 3,SNR1: 0.79855 ,SNR2: 8.8204




0834-19 2026/08/09 2.31UT TOYOKAWA-KISO









0834-19 2026/08/09 2.31UT FUJI -KISO





T20260809112154




BLK: 8,SNR1: 9.0945 ,SNR2: 23.893




F20260809112154








BLK: 8,SNR1: 10.975 ,SNR2: 27.122





0839-071 2026/08/09 2.39UT TOYOKAWA-FUJI







F20260809112154




BLK: 8, SNR1: 10.959 , SNR2: 27.080




K20260809112153




BLK: 8, SNR1: 8.6075 , SNR2: 21.553





0839-071 2026/08/09 2.39UT FUJI -KISO








BLK: 3,SNR1: 0.23536E-01,SNR2: 1.2816




BLK: 3,SNR1: 3.7821 ,SNR2: 6.2309



T20260809113256




BLK:10,SNR1: 5.2859 ,SNR2: 15.170









3C208 2026/08/09 2.58UT TOYOKAWA-KISO

K20260809113255








BLK:10,SNR1: 9.0672 ,SNR2: 27.526






3C208 2026/08/09 2.58UT FUJI -KISO







3C216 2026/08/09 2.86UT TOYOKAWA-FUJI







T20260809114938




BLK: 9,SNR1: 15.191 ,SNR2: 32.368




K20260809114937




BLK: 9,SNR1: 7.4541 ,SNR2: 16.301





3C216 2026/08/09 2.86UT TOYOKAWA-KISO







BLK:10,SNR1: 9.8637 ,SNR2: 28.620





BLK:10,SNR1: 7.4028 ,SNR2: 16.184




3C216 2026/08/09 2.86UT FUJI -KISO



T20260809120148





No.Good Data




Frequency (Hz)

F20260809120148




No.Good Data




Frequency (Hz)


0919-142 2026/08/09 3.06UT TOYOKAWA-FUJI





T20260809120148




BLK: 1,SNR1: 6.8853 ,SNR2: 13.279




K20260809120147





BLK: 1,SNR1: 7.6502 ,SNR2: 19.927





0919-142 2026/08/09 3.06UT TOYOKAWA-KISO




F20260809120148




K20260809120147





0919-142 2026/08/09 3.06UT FUJI -KISO







BLK: 8,SNR1: 13.859 ,SNR2: 33.697







BLK: 8,SNR1: 10.089 ,SNR2: 25.537





0926+117 2026/08/09 3.17UT TOYOKAWA-FUJI







0926+117 2026/08/09 3.17UT TOYOKAWA-KISO







BLK:10,SNR1: 12.148 ,SNR2: 28.741



BLK:10,SNR1: 13.751 ,SNR2: 31.152





0926+117 2026/08/09 3.17UT FUJI -KISO








T20260809121612




BLK: 4,SNR1: 12.531 ,SNR2: 29.910




F20260809121612





BLK: 4,SNR1: 8.9906 ,SNR2: 21.862




3C222 2026/08/09 3.30UT TOYOKAWA-FUJI





T20260809121612




BLK:15,SNR1: 4.3423 ,SNR2: 14.875




K20260809121611





BLK:15,SNR1: 7.9031 ,SNR2: 17.427




3C222 2026/08/09 3.30UT TOYOKAWA-KISO





F20260809121612




BLK:10,SNR1: 6.9071 ,SNR2: 16.910




K20260809121611





BLK:10,SNR1: 13.969 ,SNR2: 26.055




3C222 2026/08/09 3.30UT FUJI -KISO




T20260809122312




BLK: 9,SNR1: 4.3407 ,SNR2: 9.0284




F20260809122312




BLK: 9,SNR1: 8.9482 ,SNR2: 16.607




0941-08 2026/08/09 3.41UT TOYOKAWA-FUJI





T20260809122312




BLK:10,SNR1: 0.77218 ,SNR2: 3.7505




K20260809122311




BLK:10,SNR1: 3.8252 ,SNR2: 6.9202




0941-08 2026/08/09 3.41UT TOYOKAWA-KISO




F20260809122312




BLK: 7,SNR1: 5.0883 ,SNR2: 9.4664




K20260809122311




BLK: 7,SNR1: 9.9367 ,SNR2: 21.605





0941-08 2026/08/09 3.41UT FUJI -KISO







BLK: 8,SNR1: 8.1695 ,SNR2: 20.786





BLK: 8,SNR1: 6.1869 ,SNR2: 17.541




3C230 2026/08/09 3.55UT TOYOKAWA-FUJI




T20260809123134




BLK:12,SNR1: 9.3331 ,SNR2: 22.886




K20260809123133



BLK:12,SNR1: 10.014 ,SNR2: 24.486




3C230 2026/08/09 3.55UT TOYOKAWA-KISO







F20260809123134




BLK: 2,SNR1: 5.3860 ,SNR2: 15.738




K20260809123133





BLK: 2,SNR1: 9.6179 ,SNR2: 26.292




3C230 2026/08/09 3.55UT FUJI -KISO




T20260809124542




BLK:10,SNR1: 0.80221 ,SNR2: 2.6710




F20260809124542





BLK:10,SNR1: 8.1613 ,SNR2: 18.411




3C236 2026/08/09 3.79UT TOYOKAWA-FUJI




T20260809124542




BLK:17,SNR1: 0.83668 ,SNR2: 2.4915




K20260809124541




BLK:17,SNR1: 7.5361 ,SNR2: 18.573




3C236 2026/08/09 3.79UT TOYOKAWA-KISO




F20260809124542




BLK: 6,SNR1: 9.2088 ,SNR2: 27.864




K20260809124541







BLK: 6,SNR1: 8.9074 ,SNR2: 21.727









3C236 2026/08/09 3.79UT FUJI -KISO






1011+110 2026/08/09 3.93UT TOYOKAWA-FUJI








F20260809125351




BLK: 4,SNR1: 1.7304 ,SNR2: 4.3189




K20260809125350




BLK: 4,SNR1: 0.21115 ,SNR2: 1.1419





1011+110 2026/08/09 3.93UT FUJI -KISO







BLK: 8,SNR1: 1.6732 ,SNR2: 5.6189




BLK: 8,SNR1: 2.3023 ,SNR2: 5.8854





3C241 2026/08/09 4.05UT TOYOKAWA-FUJI









BLK: 7,SNR1: 1.7708 ,SNR2: 3.6336




BLK: 7,SNR1: 1.1008 ,SNR2: 3.8903





3C241 2026/08/09 4.05UT TOYOKAWA-KISO







BLK: 8,SNR1: 0.77873 ,SNR2: 2.6289




BLK: 8,SNR1: 0.40743 ,SNR2: 2.4857




3C241 2026/08/09 4.05UT FUJI -KISO




T20260809131301




BLK: 3,SNR1: 2.5947 ,SNR2: 5.8665




F20260809131301




BLK: 3,SNR1: 1.1484 ,SNR2: 4.8530





1031-11 2026/08/09 4.25UT TOYOKAWA-FUJI







BLK:13,SNR1: 0.79714 ,SNR2: 2.6401




BLK:13,SNR1: 8.4151 ,SNR2: 14.874




1031-11 2026/08/09 4.25UT TOYOKAWA-KISO




F20260809131301




BLK: 6,SNR1: 9.6236 ,SNR2: 17.025




K20260809131300




BLK: 6,SNR1: 3.4361 ,SNR2: 8.0158




1031-11 2026/08/09 4.25UT FUJI -KISO




T20260809131734




BLK:10,SNR1: 11.189 ,SNR2: 28.082




F20260809131734




BLK:10,SNR1: 8.3407 ,SNR2: 21.233




1035-058 2026/08/09 4.32UT TOYOKAWA-FUJI




T20260809131734




BLK:12,SNR1: 10.863 ,SNR2: 27.267




K20260809131733




BLK:12,SNR1: 9.2247 ,SNR2: 23.334




1035-058 2026/08/09 4.32UT TOYOKAWA-KISO





F20260809131734




BLK: 7,SNR1: 8.4819 ,SNR2: 20.995




K20260809131733



BLK: 7,SNR1: 8.5289 ,SNR2: 21.991





1035-058 2026/08/09 4.32UT FUJI -KISO








T20260809132647




BLK: 4,SNR1: 7.7081 ,SNR2: 13.583




F20260809132647





BLK: 4,SNR1: 1.3152 ,SNR2: 3.7334




1044-008 2026/08/09 4.47UT TOYOKAWA-FUJI







1044-008 2026/08/09 4.47UT TOYOKAWA-KISO




F20260809132647




BLK: 5,SNR1: 4.3471 ,SNR2: 13.179




K20260809132646




BLK: 5,SNR1: 3.1482 ,SNR2: 9.3239





1044-008 2026/08/09 4.47UT FUJI -KISO







BLK:13,SNR1: 7.9740 ,SNR2: 14.059




BLK:13,SNR1: 33.416 ,SNR2: 61.389





1055+01 2026/08/09 4.66UT TOYOKAWA-FUJI







BLK:17,SNR1: 8.8062 ,SNR2: 15.476





BLK:17,SNR1: 8.2670 ,SNR2: 21.389




1055+01 2026/08/09 4.66UT TOYOKAWA-KISO





F20260809133751




BLK:13,SNR1: 35.856 ,SNR2: 65.876




K20260809133750




BLK:13,SNR1: 8.2728 ,SNR2: 21.396




1055+01 2026/08/09 4.66UT FUJI -KISO




T20260809134909




BLK: 2,SNR1: 0.11340 ,SNR2: 1.6110




F20260809134909




BLK: 2,SNR1: 5.1064 ,SNR2: 15.777




1107+109 2026/08/09 4.85UT TOYOKAWA-FUJI




T20260809134909




BLK: 2,SNR1:-0.46165E-01,SNR2: 1.2681




K20260809134908



BLK: 2,SNR1: 8.1690 ,SNR2: 21.210




1107+109 2026/08/09 4.85UT TOYOKAWA-KISO







F20260809134909




BLK: 2,SNR1: 7.6840 ,SNR2: 18.439




K20260809134908




BLK: 2,SNR1: 1.3485 ,SNR2: 3.1843





1107+109 2026/08/09 4.85UT FUJI -KISO







BLK:13,SNR1: 2.1833 ,SNR2: 3.8427




BLK:13,SNR1: 4.9779 ,SNR2: 7.6696





3C255 2026/08/09 5.01UT TOYOKAWA-FUJI







BLK:12,SNR1: 1.5260 ,SNR2: 8.6578




BLK:12,SNR1: 3.3167 ,SNR2: 8.0727




3C255 2026/08/09 5.01UT TOYOKAWA-KISO





F20260809135846




BLK: 1,SNR1: 16.100 ,SNR2: 29.684




K20260809135845





BLK: 1,SNR1: 1.5119 ,SNR2: 4.1757




3C255 2026/08/09 5.01UT FUJI -KISO





T20260809140924




BLK: 3,SNR1: 0.17700 ,SNR2: 1.1781




F20260809140924





BLK: 3,SNR1: 0.85307 ,SNR2: 2.9640




1127-14 2026/08/09 5.18UT TOYOKAWA-FUJI





T20260809140924




BLK: 3,SNR1: 2.7750 ,SNR2: 8.5900




K20260809140923





BLK: 3,SNR1: 16.981 ,SNR2: 30.405




1127-14 2026/08/09 5.18UT TOYOKAWA-KISO



F20260809140924





No.Good Data




Frequency (Hz)

K20260809140923




No.Good Data





Frequency (Hz)


1127-14 2026/08/09 5.18UT FUJI -KISO




T20260809142244




BLK: 1,SNR1: 0.32543 ,SNR2: 0.87988




F20260809142244



BLK: 1,SNR1: 1.6247 ,SNR2: 7.9831





3C263.1 2026/08/09 5.41UT TOYOKAWA-FUJI








T20260809142244




BLK: 3,SNR1: 0.24359 ,SNR2: 1.1888




K20260809142243




BLK: 3,SNR1: 15.115 ,SNR2: 21.294




3C263.1 2026/08/09 5.41UT TOYOKAWA-KISO





F20260809142244




BLK: 3,SNR1: 2.6773 ,SNR2: 7.2779




K20260809142243




BLK: 3,SNR1: 13.503 ,SNR2: 18.390





3C263.1 2026/08/09 5.41UT FUJI -KISO







BLK: 8,SNR1: 5.5783 ,SNR2: 8.0116




BLK: 8,SNR1: 5.3353 ,SNR2: 13.408





3C267 2026/08/09 5.51UT TOYOKAWA-FUJI







BLK: 9,SNR1: 6.1939 ,SNR2: 15.442




BLK: 9,SNR1: 11.415 ,SNR2: 19.714





3C267 2026/08/09 5.51UT TOYOKAWA-KISO







BLK:12,SNR1: 1.1424 ,SNR2: 3.9648




BLK:12,SNR1: 5.1909 ,SNR2: 13.047




3C267 2026/08/09 5.51UT FUJI -KISO





T20260809145459




BLK: 4,SNR1: 1.0706 ,SNR2: 3.0847




F20260809145459




BLK: 4,SNR1: 0.97155 ,SNR2: 2.4565




1213-17 2026/08/09 5.94UT TOYOKAWA-FUJI





T20260809145459




BLK: 1,SNR1: 0.79814 ,SNR2: 3.9306




K20260809145458




BLK: 1,SNR1: 81.554 ,SNR2: 78.164




1213-17 2026/08/09 5.94UT TOYOKAWA-KISO




F20260809145459




BLK: 3,SNR1: 7.1916 ,SNR2: 17.455




K20260809145458



BLK: 3,SNR1: 13.135 ,SNR2: 17.128





1213-17 2026/08/09 5.94UT FUJI -KISO







T20260809150816




BLK: 6,SNR1: 1.1000 ,SNR2: 7.3327




F20260809150816




BLK: 6,SNR1: 5.2022 ,SNR2: 9.1090





3C273 2026/08/09 6.17UT TOYOKAWA-FUJI







BLK: 9,SNR1: 2.1730 ,SNR2: 5.3271





BLK: 9,SNR1: 0.49685 ,SNR2: 1.4098




3C273 2026/08/09 6.17UT TOYOKAWA-KISO





F20260809150816




BLK: 8,SNR1: 4.4209 ,SNR2: 7.6648




K20260809150815









BLK: 8,SNR1: 3.7400 ,SNR2: 5.5029





3C273 2026/08/09 6.17UT FUJI -KISO









BLK: 3,SNR1: 0.32223 ,SNR2: 1.9711




BLK: 3,SNR1:-0.30792 ,SNR2: 0.19027





3C275 2026/08/09 6.39UT TOYOKAWA-KISO







BLK: 2,SNR1:-0.19714 ,SNR2: 0.74307





BLK: 2,SNR1: 2.4317 ,SNR2: 5.0493




3C275 2026/08/09 6.39UT FUJI -KISO





T20260809152732




No.Good Data




F20260809152732





No.Good Data




1245-19 2026/08/09 6.49UT TOYOKAWA-FUJI





T20260809152732




No.Good Data




K20260809152731



No.Good Data





1245-19 2026/08/09 6.49UT TOYOKAWA-KISO






F20260809152732





No.Good Data




Frequency (Hz)

K20260809152731





No.Good Data





Frequency (Hz)

1245-19 2026/08/09 6.49UT FUJI -KISO








BLK: 1,SNR1: 24.941 ,SNR2: 55.926





BLK: 1,SNR1: 9.1707 ,SNR2: 25.292







BLK: 3,SNR1: 10.867 ,SNR2: 26.676




BLK: 3,SNR1: 7.0578 ,SNR2: 17.149





3C279 2026/08/09 6.62UT TOYOKAWA-KISO









BLK: 2,SNR1: 0.59144 ,SNR2: 5.7490




BLK: 2,SNR1: 7.5263 ,SNR2: 18.973





T20260809155046




No.Good Data




F20260809155046







No.Good Data




3C283 2026/08/09 6.87UT TOYOKAWA-FUJI







3C283 2026/08/09 6.87UT TOYOKAWA-KISO




F20260809155046




BLK: 3,SNR1: 9.2231 ,SNR2: 22.444




K20260809155045




BLK: 3,SNR1: 17.334 ,SNR2: 30.557





3C283 2026/08/09 6.87UT FUJI -KISO







BLK: 2,SNR1: 24.739 ,SNR2: 43.757




BLK: 2,SNR1: 11.369 ,SNR2: 27.503





1323+32 2026/08/09 7.11UT TOYOKAWA-FUJI









BLK: 4,SNR1: 12.388 ,SNR2: 21.825





BLK: 4,SNR1: 15.430 ,SNR2: 27.461




1323+32 2026/08/09 7.11UT TOYOKAWA-KISO



F20260809160509





BLK: 2, SNR1: 1.8186 , SNR2: 8.5671




Frequency (Hz)

K20260809160508








BLK: 2, SNR1: 4.4339 , SNR2: 10.532




Frequency (Hz)


1323+32 2026/08/09 7.11UT FUJI -KISO







3C286 2026/08/09 7.19UT TOYOKAWA-FUJI







BLK:10,SNR1: 1.3310 ,SNR2: 3.7805









BLK:10,SNR1: 3.3429 ,SNR2: 6.1304





3C286 2026/08/09 7.19UT TOYOKAWA-KISO









BLK: 2,SNR1: 2.4256 ,SNR2: 11.331




BLK: 2,SNR1: 14.334 ,SNR2: 25.066





1345+12 2026/08/09 7.47UT TOYOKAWA-FUJI







BLK: 5, SNR1: 10.932 , SNR2: 26.766




BLK: 5, SNR1: 14.202 , SNR2: 25.018





1345+12 2026/08/09 7.47UT TOYOKAWA-KISO







BLK: 4, SNR1: 2.1378 , SNR2: 6.8562




BLK: 4, SNR1: 6.4364 , SNR2: 15.554





1345+12 2026/08/09 7.47UT FUJI -KISO









BLK: 1,SNR1: 8.8732 ,SNR2: 22.153







BLK: 1,SNR1: 6.2546 ,SNR2: 15.824









1355+01 2026/08/09 7.64UT TOYOKAWA-FUJI








1355+01 2026/08/09 7.64UT TOYOKAWA-KISO









BLK:10,SNR1: 4.0682 ,SNR2: 13.687




BLK:10,SNR1: 0.69343 ,SNR2: 2.5819





3C298 2026/08/09 7.99UT TOYOKAWA-FUJI







BLK:15,SNR1: 4.6214 ,SNR2: 11.930




BLK:15,SNR1: 5.9335 ,SNR2: 14.832





3C298 2026/08/09 7.99UT TOYOKAWA-KISO






BLK: 8,SNR1: 4.2434 ,SNR2: 6.2499



BLK: 8,SNR1: 7.6045 ,SNR2: 19.950



3C298 2026/08/09 7.99UT FUJI -KISO

