



T20260810061329




BLK: 1, SNR1: 8.3828 , SNR2: 20.904




Frequency (Hz)

F20260810061329





BLK: 1, SNR1: 10.533 , SNR2: 25.569





Frequency (Hz)

0333+32 2026/08/09 21.25UT TOYOKAWA-FUJI







BLK: 4,SNR1: 8.2332 ,SNR2: 14.707




BLK: 4,SNR1: 8.1223 ,SNR2: 19.901





0333+32 2026/08/09 21.25UT TOYOKAWA-KISO









BLK: 4,SNR1: 9.0497 ,SNR2: 22.401





BLK: 4,SNR1: 12.550 ,SNR2: 22.401




0333+32 2026/08/09 21.25UT FUJI -KISO





T20260810061708




BLK: 1,SNR1: 0.25212 ,SNR2: 1.9862




F20260810061708





BLK: 1,SNR1:-0.11308 ,SNR2: 2.0046




0337+319 2026/08/09 21.31UT TOYOKAWA-FUJI





T20260810061708




BLK: 2,SNR1: 0.79653E-02,SNR2: 0.74687




K20260810061707





BLK: 2,SNR1: 0.20920 ,SNR2: 1.0122




0337+319 2026/08/09 21.31UT TOYOKAWA-KISO





F20260810061708




BLK: 8,SNR1:-0.10002 ,SNR2: 0.44635




K20260810061707




BLK: 8,SNR1:-0.52974E-01,SNR2: 0.86811




0337+319 2026/08/09 21.31UT FUJI -KISO



T20260810063013





No.Good Data




Frequency (Hz)

F20260810063013




No.Good Data





Frequency (Hz)


0349+382 2026/08/09 21.53UT TOYOKAWA-FUJI





T20260810063013




BLK: 2,SNR1: 0.17277 ,SNR2: 0.62945




K20260810063012





BLK: 2,SNR1: 0.94768E-01,SNR2: 0.84258




0349+382 2026/08/09 21.53UT TOYOKAWA-KISO





F20260810063013




BLK: 1,SNR1: 0.43736E-01,SNR2: 0.57335




K20260810063012




BLK: 1,SNR1: 0.21489 ,SNR2: 0.97414





0349+382 2026/08/09 21.53UT FUJI -KISO







BLK: 5,SNR1: 0.98641 ,SNR2: 2.8391








BLK: 5,SNR1: 2.9709 ,SNR2: 6.5858




0411+05 2026/08/09 21.88UT TOYOKAWA-FUJI













BLK:15,SNR1: 4.6387 ,SNR2: 10.942





BLK:15,SNR1: 5.3509 ,SNR2: 9.5090




0411+05 2026/08/09 21.88UT FUJI -KISO




T20260810065810




BLK: 2,SNR1: 0.69066E-01,SNR2: 1.6198




F20260810065810





BLK: 2,SNR1:-0.19205 ,SNR2: 1.1228




0418+236 2026/08/09 22.00UT TOYOKAWA-FUJI





T20260810065810




BLK: 6,SNR1: 0.18583 ,SNR2: 0.80007




K20260810065809





BLK: 6,SNR1: 3.2735 ,SNR2: 8.5513




0418+236 2026/08/09 22.00UT TOYOKAWA-KISO



F20260810065810





BLK: 5,SNR1: 0.87832 ,SNR2: 3.1527




Frequency (Hz)

K20260810065809




BLK: 5,SNR1: 4.3599 ,SNR2: 10.955





Frequency (Hz)


0418+236 2026/08/09 22.00UT FUJI -KISO





T20260810070938




BLK: 6,SNR1: 0.19110 ,SNR2: 1.9298




F20260810070938





BLK: 6,SNR1: 7.0644 ,SNR2: 12.101




3C119 2026/08/09 22.19UT TOYOKAWA-FUJI





T20260810070938




BLK: 6,SNR1: 0.28817 ,SNR2: 0.83845




K20260810070937





BLK: 6,SNR1: 1.2217 ,SNR2: 3.1963




3C119 2026/08/09 22.19UT TOYOKAWA-KISO





F20260810070938




BLK: 4, SNR1: 1.3214 , SNR2: 3.4417




K20260810070937



BLK: 4, SNR1: 1.0870 , SNR2: 3.2002




3C119 2026/08/09 22.19UT FUJI -KISO








T20260810075744




BLK: 9, SNR1: 11.833 , SNR2: 23.201




F20260810075744




BLK: 9, SNR1: 49.711 , SNR2: 57.346





3C138 2026/08/09 22.99UT TOYOKAWA-FUJI







BLK: 8,SNR1: 58.056 ,SNR2: 101.77





BLK: 8,SNR1: 62.974 ,SNR2: 70.252




3C138 2026/08/09 22.99UT TOYOKAWA-KISO



F20260810075744





BLK: 6,SNR1: 55.359 ,SNR2: 63.109




Frequency (Hz)

K20260810075743




BLK: 6,SNR1: 67.559 ,SNR2: 89.053





Frequency (Hz)


3C138 2026/08/09 22.99UT FUJI -KISO





T20260810081118




BLK: 2,SNR1: 7.0128 ,SNR2: 17.757




F20260810081118




BLK: 2,SNR1: 1.7881 ,SNR2: 9.1918





0531+194 2026/08/09 23.22UT TOYOKAWA-FUJI







BLK: 4,SNR1: 2.4406 ,SNR2: 11.245





BLK: 4,SNR1: 3.5854 ,SNR2: 10.660




0531+194 2026/08/09 23.22UT TOYOKAWA-KISO





F20260810081118




BLK: 2,SNR1: 5.2797 ,SNR2: 19.719




K20260810081117





BLK: 2,SNR1: 5.6997 ,SNR2: 16.359




0531+194 2026/08/09 23.22UT FUJI -KISO





T20260810081939




BLK: 7, SNR1: 11.449 , SNR2: 26.625




F20260810081939




BLK: 7, SNR1: 6.9519 , SNR2: 17.818





3C147 2026/08/09 23.36UT TOYOKAWA-FUJI







BLK: 9,SNR1: 10.636 ,SNR2: 25.015



BLK: 9,SNR1: 5.4546 ,SNR2: 13.849




3C147 2026/08/09 23.36UT TOYOKAWA-KISO







F20260810081939




BLK: 2, SNR1: 9.4148 , SNR2: 24.063




K20260810081938




BLK: 2, SNR1: 10.779 , SNR2: 26.328





3C147 2026/08/09 23.36UT FUJI -KISO







BLK: 1, SNR1: 0.17707 , SNR2: 3.5620





BLK: 1, SNR1: 1.6940 , SNR2: 5.4676




0548+16 2026/08/09 23.49UT TOYOKAWA-FUJI







0548+16 2026/08/09 23.49UT TOYOKAWA-KISO




F20260810082749




BLK: 1,SNR1:-0.18695 ,SNR2: 1.9701




K20260810082748




BLK: 1,SNR1: 1.4676 ,SNR2: 6.8070





0548+16 2026/08/09 23.49UT FUJI -KISO







BLK: 6,SNR1: 9.5033 ,SNR2: 23.386





BLK: 6,SNR1: 18.602 ,SNR2: 31.930




0552+12 2026/08/09 23.56UT TOYOKAWA-FUJI





T20260810083159




No.Good Data




K20260810083158





No.Good Data




0552+12 2026/08/09 23.56UT TOYOKAWA-KISO





F20260810083159




BLK: 3, SNR1: 13.372 , SNR2: 32.207




K20260810083158





BLK: 3, SNR1: 10.705 , SNR2: 26.289




0552+12 2026/08/09 23.56UT FUJI -KISO





T20260810083626




BLK: 1,SNR1: 14.616 ,SNR2: 34.760




F20260810083626



BLK: 1,SNR1: 8.4290 ,SNR2: 24.101





0556+191 2026/08/09 23.64UT TOYOKAWA-FUJI








T20260810083626




BLK: 3, SNR1: 8.4037 , SNR2: 24.341




K20260810083625




BLK: 3, SNR1: 14.271 , SNR2: 34.971




0556+191 2026/08/09 23.64UT TOYOKAWA-KISO





F20260810083626




BLK: 1, SNR1: 8.1969 , SNR2: 18.227




K20260810083625





BLK: 1, SNR1: 13.011 , SNR2: 37.433




0556+191 2026/08/09 23.64UT FUJI -KISO





T20260810084059




BLK: 4, SNR1: 5.8041 , SNR2: 16.829




F20260810084059





BLK: 4, SNR1: 8.3484 , SNR2: 24.078




3C152 2026/08/09 23.71UT TOYOKAWA-FUJI





T20260810084059




BLK:11,SNR1: 8.3411 ,SNR2: 20.346




K20260810084058





BLK:11,SNR1: 12.012 ,SNR2: 28.816




3C152 2026/08/09 23.71UT TOYOKAWA-KISO





F20260810084059




BLK: 6,SNR1: 8.9559 ,SNR2: 25.889




K20260810084058





BLK: 6,SNR1: 11.132 ,SNR2: 32.018




3C152 2026/08/09 23.71UT FUJI -KISO



T20260810085245





BLK: 2, SNR1: 8.8793 , SNR2: 22.313




Frequency (Hz)

F20260810085245




BLK: 2, SNR1: 1.1614 , SNR2: 3.9056





Frequency (Hz)


0613+119 2026/08/09 23.91UT TOYOKAWA-FUJI



T20260810085245





No.Good Data




Frequency (Hz)

K20260810085244








No.Good Data




Frequency (Hz)

0613+119 2026/08/09 23.91UT TOYOKAWA-KISO







0613+119 2026/08/09 23.91UT FUJI -KISO






T20260810090319





BLK: 2,SNR1: 11.099 ,SNR2: 27.574




Frequency (Hz)

3C161 2026/08/10 0.08UT TOYOKAWA-FUJI


F20260810090319




BLK: 2,SNR1: 24.147 ,SNR2: 36.502




Frequency (Hz)





T20260810090319




BLK: 1, SNR1: 9.9294 , SNR2: 24.736




K20260810090318





BLK: 1, SNR1: 16.586 , SNR2: 29.574




3C161 2026/08/10 0.08UT TOYOKAWA-KISO



F20260810090319





BLK: 3, SNR1: 9.6706 , SNR2: 24.112






3C161 2026/08/10 0.08UT FUJI -KISO

K20260810090318





BLK: 3, SNR1: 10.574 , SNR2: 26.296







BLK: 1,SNR1: 43.156 ,SNR2: 56.290







BLK: 1,SNR1: 17.525 ,SNR2: 30.999








0652-130 2026/08/10 0.54UT TOYOKAWA-FUJI






0652-130 2026/08/10 0.54UT TOYOKAWA-KISO








0652-130 2026/08/10 0.54UT FUJI -KISO



T20260810094229





BLK: 1, SNR1: 4.6781 , SNR2: 11.473




Frequency (Hz)

F20260810094229




BLK: 1, SNR1: 8.6931 , SNR2: 29.169




Frequency (Hz)


0703+138 2026/08/10 0.74UT TOYOKAWA-FUJI




T20260810094229




BLK: 3, SNR1: 9.8245 , SNR2: 24.361




K20260810094228







BLK: 3, SNR1: 13.314 , SNR2: 32.816




0703+138 2026/08/10 0.74UT TOYOKAWA-KISO









0703+138 2026/08/10 0.74UT FUJI -KISO





T20260810095151




BLK: 3, SNR1: 5.5738 , SNR2: 13.718




F20260810095151





BLK: 3, SNR1: 5.9837 , SNR2: 15.030




0713-024 2026/08/10 0.89UT TOYOKAWA-FUJI





T20260810095151




No.Good Data




K20260810095150




No.Good Data




0713-024 2026/08/10 0.89UT TOYOKAWA-KISO





F20260810095151




BLK: 3, SNR1: 4.1769 , SNR2: 10.548




K20260810095150





BLK: 3, SNR1: 17.460 , SNR2: 31.379




0713-024 2026/08/10 0.89UT FUJI -KISO



T20260810100203





BLK: 6,SNR1: 0.84446 ,SNR2: 3.5389




Frequency (Hz)

F20260810100203




BLK: 6,SNR1: 3.4955 ,SNR2: 10.479





Frequency (Hz)


0723+10 2026/08/10 1.06UT TOYOKAWA-FUJI



T20260810100203





BLK:11,SNR1: 1.0611 ,SNR2: 4.1511




Frequency (Hz)

K20260810100202




BLK:11,SNR1: 3.2870 ,SNR2: 9.9323





Frequency (Hz)


0723+10 2026/08/10 1.06UT TOYOKAWA-KISO





F20260810100203




BLK: 7, SNR1: 3.4902 , SNR2: 10.463




K20260810100202





BLK: 7, SNR1: 1.7519 , SNR2: 5.2482




0723+10 2026/08/10 1.06UT FUJI -KISO




T20260810101219




BLK: 3,SNR1: 0.54508 ,SNR2: 2.1521




F20260810101219



BLK: 3,SNR1:-0.12868 ,SNR2: 0.80301





0732+33 2026/08/10 1.23UT TOYOKAWA-FUJI








T20260810101219




BLK: 7, SNR1: 0.37858 , SNR2: 2.4318




K20260810101218





BLK: 7, SNR1: 0.30745 , SNR2: 1.7636




0732+33 2026/08/10 1.23UT TOYOKAWA-KISO







0732+33 2026/08/10 1.23UT FUJI -KISO



T20260810102019




BLK: 4, SNR1: 10.218 , SNR2: 24.753





0741-06 2026/08/10 1.37UT TOYOKAWA-FUJI


F20260810102019




BLK: 4, SNR1: 0.23950 , SNR2: 1.9814




T20260810102019




BLK:11,SNR1: 3.8605 ,SNR2: 10.248




K20260810102018




BLK:11,SNR1: 2.2355 ,SNR2: 6.7975




0741-06 2026/08/10 1.37UT TOYOKAWA-KISO




F20260810102019




BLK: 5,SNR1: 2.5439 ,SNR2: 7.5348




K20260810102018





BLK: 5,SNR1: 2.7515 ,SNR2: 8.1882




0741-06 2026/08/10 1.37UT FUJI -KISO





T20260810103003




BLK: 1, SNR1: 13.987 , SNR2: 33.849




F20260810103003





BLK: 1, SNR1: 7.6959 , SNR2: 10.779




0752-200 2026/08/10 1.53UT TOYOKAWA-FUJI




T20260810103003




BLK: 3, SNR1: 13.561 , SNR2: 32.835




K20260810103002




BLK: 3, SNR1: 10.398 , SNR2: 22.421




0752-200 2026/08/10 1.53UT TOYOKAWA-KISO




F20260810103003




BLK: 6,SNR1: 7.3523 ,SNR2: 19.444




K20260810103002



BLK: 6,SNR1: 9.2889 ,SNR2: 20.557





0752-200 2026/08/10 1.53UT FUJI -KISO








T20260810103739




BLK: 6, SNR1: 3.0247 , SNR2: 7.3206




F20260810103739





BLK: 6, SNR1: 10.351 , SNR2: 22.450




3C190 2026/08/10 1.66UT TOYOKAWA-FUJI





T20260810103739




BLK: 4, SNR1: 2.2585 , SNR2: 6.8623




K20260810103738





BLK: 4, SNR1: 7.3222 , SNR2: 11.334




3C190 2026/08/10 1.66UT TOYOKAWA-KISO




F20260810103739




BLK: 4, SNR1: 3.0635 , SNR2: 8.1759




K20260810103738





BLK: 4, SNR1: 2.4568 , SNR2: 7.7818




3C190 2026/08/10 1.66UT FUJI -KISO




T20260810105006




BLK: 7,SNR1: 0.34168 ,SNR2: 1.1333




F20260810105006





BLK: 7,SNR1: 1.9510 ,SNR2: 9.6430




3C196 2026/08/10 1.86UT TOYOKAWA-FUJI




T20260810105006




BLK: 8, SNR1: 0.25877 , SNR2: 1.0074




K20260810105005




BLK: 8, SNR1: 1.4025 , SNR2: 6.5885




3C196 2026/08/10 1.86UT TOYOKAWA-KISO




F20260810105006




BLK: 2, SNR1: 0.33183 , SNR2: 2.5608




K20260810105005







BLK: 2, SNR1: 4.0894 , SNR2: 7.9978




3C196 2026/08/10 1.86UT FUJI -KISO








0821+394 2026/08/10 2.05UT TOYOKAWA-FUJI




T20260810110115




BLK:12,SNR1: 0.85603 ,SNR2: 3.8771




K20260810110114



BLK:12,SNR1: 3.0300 ,SNR2: 9.2389





0821+394 2026/08/10 2.05UT TOYOKAWA-KISO







F20260810110115




BLK:16,SNR1: 10.702 ,SNR2: 18.650




K20260810110114





BLK:16,SNR1: 3.0335 ,SNR2: 9.2475





0821+394 2026/08/10 2.05UT FUJI -KISO




T20260810111252




F20260810111252




0834-19 2026/08/10 2.24UT TOYOKAWA-FUJI



T20260810111252





BLK: 2,SNR1: 0.17365 ,SNR2: 2.9850





0834-19 2026/08/10 2.24UT TOYOKAWA-KISO


K20260810111251




BLK: 2,SNR1: 7.7939 ,SNR2: 18.290




F20260810111252




BLK: 2,SNR1: 0.62768 ,SNR2: 2.7504




K20260810111251







BLK: 2,SNR1: 3.4883 ,SNR2: 8.6361








0834-19 2026/08/10 2.24UT FUJI -KISO






0839-071 2026/08/10 2.33UT TOYOKAWA-FUJI







0839-071 2026/08/10 2.33UT TOYOKAWA-KISO




F20260810111758




BLK:10,SNR1: 10.451 ,SNR2: 24.244




K20260810111757








BLK:10,SNR1: 9.5630 ,SNR2: 23.280




0839-071 2026/08/10 2.33UT FUJI -KISO













BLK:13,SNR1: 2.1223 ,SNR2: 16.141




BLK:13,SNR1: 0.58693 ,SNR2: 1.7845




3C208 2026/08/10 2.51UT TOYOKAWA-KISO




F20260810112900




BLK:14,SNR1: 23.358 ,SNR2: 30.398




K20260810112859





BLK:14,SNR1: 1.2855 ,SNR2: 4.1505




3C208 2026/08/10 2.51UT FUJI -KISO




T20260810114542




BLK: 6,SNR1: 0.17900 ,SNR2: 1.6386




F20260810114542





BLK: 6,SNR1: 0.69506 ,SNR2: 2.9084




3C216 2026/08/10 2.79UT TOYOKAWA-FUJI



T20260810114542





BLK: 9,SNR1: 0.16058 ,SNR2: 1.7549




Frequency (Hz)

K20260810114541




BLK: 9,SNR1: 1.5436 ,SNR2: 5.8290




Frequency (Hz)


3C216 2026/08/10 2.79UT TOYOKAWA-KISO





F20260810114542




BLK: 2,SNR1: 0.11569 ,SNR2: 1.5055




K20260810114541





BLK: 2,SNR1: 0.77699 ,SNR2: 2.9497




3C216 2026/08/10 2.79UT FUJI -KISO





T20260810115752




BLK: 7,SNR1: 0.95824 ,SNR2: 3.1029




F20260810115752





BLK: 7,SNR1: 2.3873 ,SNR2: 7.0992




0919-142 2026/08/10 2.99UT TOYOKAWA-FUJI





T20260810115752




BLK:14,SNR1: 3.2725 ,SNR2: 9.9420




K20260810115751





BLK:14,SNR1: 4.8191 ,SNR2: 12.704




0919-142 2026/08/10 2.99UT TOYOKAWA-KISO





F20260810115752




BLK:14,SNR1: 3.8584 ,SNR2: 9.1478




K20260810115751



BLK:14,SNR1: 1.6093 ,SNR2: 5.1829





0919-142 2026/08/10 2.99UT FUJI -KISO







T20260810120431




BLK:11,SNR1: 16.210 ,SNR2: 37.918




F20260810120431




BLK:11,SNR1: 13.109 ,SNR2: 32.251





0926+117 2026/08/10 3.10UT TOYOKAWA-FUJI







BLK:10,SNR1: 14.630 ,SNR2: 34.140




BLK:10,SNR1: 10.233 ,SNR2: 24.253




0926+117 2026/08/10 3.10UT TOYOKAWA-KISO




F20260810120431




BLK: 2,SNR1: 13.763 ,SNR2: 26.382




K20260810120430





BLK: 2,SNR1: 6.3137 ,SNR2: 17.258




0926+117 2026/08/10 3.10UT FUJI -KISO




T20260810121216




BLK: 4,SNR1: 10.731 ,SNR2: 26.104




F20260810121216







BLK: 4,SNR1: 9.7807 ,SNR2: 24.075




3C222 2026/08/10 3.23UT TOYOKAWA-FUJI







3C222 2026/08/10 3.23UT TOYOKAWA-KISO




F20260810121216




BLK: 6,SNR1: 7.8577 ,SNR2: 19.706




K20260810121215




BLK: 6,SNR1: 8.4951 ,SNR2: 21.358




3C222 2026/08/10 3.23UT FUJI -KISO




T20260810121916




BLK: 8,SNR1: 1.6536 ,SNR2: 4.9943




F20260810121916




BLK: 8,SNR1:-0.10292 ,SNR2: 1.4903




0941-08 2026/08/10 3.35UT TOYOKAWA-FUJI




T20260810121916




BLK:12,SNR1: 0.65082 ,SNR2: 3.4580




K20260810121915



BLK:12,SNR1: 6.0573 ,SNR2: 10.518




0941-08 2026/08/10 3.35UT TOYOKAWA-KISO







F20260810121916




BLK: 8,SNR1:-0.28988 ,SNR2: 0.90133




K20260810121915





BLK: 8,SNR1: 5.1579 ,SNR2: 9.1952




0941-08 2026/08/10 3.35UT FUJI -KISO



T20260810122738





BLK:11,SNR1: 5.2074 ,SNR2: 15.765





3C230 2026/08/10 3.49UT TOYOKAWA-FUJI



F20260810122738




BLK:11,SNR1: 19.149 ,SNR2: 45.890





T20260810122738




BLK:18,SNR1: 7.8846 ,SNR2: 19.912




K20260810122737





BLK:18,SNR1: 8.0232 ,SNR2: 23.105




3C230 2026/08/10 3.49UT TOYOKAWA-KISO





F20260810122738




BLK:10,SNR1: 23.804 ,SNR2: 55.619




K20260810122737




BLK:10,SNR1: 7.6821 ,SNR2: 20.370





3C230 2026/08/10 3.49UT FUJI -KISO







BLK:16,SNR1: 1.9543 ,SNR2: 5.9217




BLK:16,SNR1: 14.614 ,SNR2: 16.156





3C236 2026/08/10 3.72UT TOYOKAWA-FUJI







BLK:27,SNR1: 1.7148 ,SNR2: 5.1298





BLK:27,SNR1: 2.6463 ,SNR2: 8.2581




3C236 2026/08/10 3.72UT TOYOKAWA-KISO





F20260810124146




BLK:19,SNR1: 2.3300 ,SNR2: 7.5061




K20260810124145





BLK:19,SNR1: 2.6480 ,SNR2: 8.2639




3C236 2026/08/10 3.72UT FUJI -KISO





T20260810124955




BLK: 4,SNR1: 7.7660 ,SNR2: 22.860




F20260810124955



BLK: 4,SNR1: 10.409 ,SNR2: 26.335





1011+110 2026/08/10 3.86UT TOYOKAWA-FUJI








T20260810124955




BLK: 7,SNR1: 3.9474 ,SNR2: 11.201




K20260810124954





BLK: 7,SNR1: 11.853 ,SNR2: 27.883




1011+110 2026/08/10 3.86UT TOYOKAWA-KISO





F20260810124955




BLK: 5, SNR1: 9.1707 , SNR2: 26.142




K20260810124954




BLK: 5, SNR1: 9.3823 , SNR2: 26.350




1011+110 2026/08/10 3.86UT FUJI -KISO





T20260810125736




BLK:12,SNR1: 2.1747 ,SNR2: 5.8239




F20260810125736




BLK:12,SNR1: 1.8392 ,SNR2: 5.4439




3C241 2026/08/10 3.99UT TOYOKAWA-FUJI





T20260810125736




BLK:12,SNR1: 1.7597 ,SNR2: 3.5655




K20260810125735




BLK:12,SNR1: 4.9872 ,SNR2: 13.726





3C241 2026/08/10 3.99UT TOYOKAWA-KISO







BLK: 2,SNR1:-0.22853E-01,SNR2: 1.6852




BLK: 2,SNR1: 8.1374 ,SNR2: 22.575




3C241 2026/08/10 3.99UT FUJI -KISO




T20260810130905




BLK: 9,SNR1: 1.4746 ,SNR2: 5.1882




F20260810130905




BLK: 9,SNR1: 1.5269 ,SNR2: 3.8369




1031-11 2026/08/10 4.18UT TOYOKAWA-FUJI




T20260810130905




BLK:13,SNR1: 0.59855 ,SNR2: 3.2063




K20260810130904




BLK:13,SNR1: 3.5097 ,SNR2: 9.3688




1031-11 2026/08/10 4.18UT TOYOKAWA-KISO





F20260810130905




BLK: 9,SNR1: 0.34094 ,SNR2: 4.1540




K20260810130904



BLK: 9,SNR1: 2.0224 ,SNR2: 6.2709




1031-11 2026/08/10 4.18UT FUJI -KISO







T20260810131338




BLK:10,SNR1: 7.4010 ,SNR2: 18.069




F20260810131338




BLK:10,SNR1: 1.6781 ,SNR2: 5.4495




1035-058 2026/08/10 4.26UT TOYOKAWA-FUJI




T20260810131338




BLK:15,SNR1: 10.613 ,SNR2: 17.892




K20260810131337




BLK:15,SNR1: 10.081 ,SNR2: 21.706




1035-058 2026/08/10 4.26UT TOYOKAWA-KISO




F20260810131338




BLK:18,SNR1: 1.1625 ,SNR2: 6.0363




K20260810131337




BLK:18,SNR1: 6.8635 ,SNR2: 15.553




1035-058 2026/08/10 4.26UT FUJI -KISO




T20260810132251




BLK:12,SNR1: 0.80509 ,SNR2: 3.1641




F20260810132251




BLK:12,SNR1: 8.9685 ,SNR2: 25.731




1044-008 2026/08/10 4.41UT TOYOKAWA-FUJI






T20260810132251




K20260810132250





1044-008 2026/08/10 4.41UT TOYOKAWA-KISO







BLK:11,SNR1: 4.5524 ,SNR2: 22.220




BLK:11,SNR1: 4.9501 ,SNR2: 14.814




1044-008 2026/08/10 4.41UT FUJI -KISO




T20260810133356




BLK: 4,SNR1: 1.3395 ,SNR2: 3.9867




F20260810133356




BLK: 4,SNR1: 2.1198 ,SNR2: 6.3590




1055+01 2026/08/10 4.59UT TOYOKAWA-FUJI




T20260810133356




BLK: 6,SNR1: 1.7402 ,SNR2: 5.0385




K20260810133355



BLK: 6,SNR1: 8.1334 ,SNR2: 20.863




1055+01 2026/08/10 4.59UT TOYOKAWA-KISO







F20260810133356




BLK: 3,SNR1: 1.9623 ,SNR2: 6.3654




K20260810133355




BLK: 3,SNR1: 5.7794 ,SNR2: 11.790





1055+01 2026/08/10 4.59UT FUJI -KISO







BLK:11,SNR1: 1.7138 ,SNR2: 3.0110




BLK:11,SNR1: 5.8520 ,SNR2: 16.279





1107+109 2026/08/10 4.78UT TOYOKAWA-FUJI







BLK: 9,SNR1: 1.2811 ,SNR2: 2.5359




BLK: 9,SNR1: 4.0585 ,SNR2: 9.9266




1107+109 2026/08/10 4.78UT TOYOKAWA-KISO




F20260810134513




BLK:11,SNR1: 6.0124 ,SNR2: 15.243




K20260810134512




BLK:11,SNR1: 6.3433 ,SNR2: 15.273




1107+109 2026/08/10 4.78UT FUJI -KISO




T20260810135450




BLK: 5,SNR1: 8.2830 ,SNR2: 20.208




F20260810135450





BLK: 5,SNR1: 8.4725 ,SNR2: 20.847




3C255 2026/08/10 4.94UT TOYOKAWA-FUJI





T20260810135450




BLK: 5,SNR1: 8.2788 ,SNR2: 20.198




K20260810135449




BLK: 5,SNR1: 8.0449 ,SNR2: 27.461





3C255 2026/08/10 4.94UT TOYOKAWA-KISO







BLK: 6,SNR1: 8.5870 ,SNR2: 21.182




BLK: 6,SNR1: 11.153 ,SNR2: 18.955




3C255 2026/08/10 4.94UT FUJI -KISO





T20260810140528




BLK: 1,SNR1: 0.99147E-01,SNR2: 2.8169




F20260810140528



BLK: 1,SNR1: 14.865 ,SNR2: 32.928




1127-14 2026/08/10 5.12UT TOYOKAWA-FUJI








T20260810140528




BLK: 4,SNR1: 0.54837 ,SNR2: 2.5123




K20260810140527




BLK: 4,SNR1: 2.5258 ,SNR2: 8.0542




1127-14 2026/08/10 5.12UT TOYOKAWA-KISO





F20260810140528




BLK: 4,SNR1: 3.3789 ,SNR2: 10.359




K20260810140527





BLK: 4,SNR1: 2.5881 ,SNR2: 8.2217




1127-14 2026/08/10 5.12UT FUJI -KISO





T20260810141849




BLK: 4,SNR1: 10.261 ,SNR2: 25.196




F20260810141849





BLK: 4,SNR1: 11.531 ,SNR2: 27.892




3C263.1 2026/08/10 5.34UT TOYOKAWA-FUJI





T20260810141849




BLK: 6,SNR1: 5.0269 ,SNR2: 9.0782




K20260810141848





BLK: 6,SNR1: 9.6953 ,SNR2: 9.4693




3C263.1 2026/08/10 5.34UT TOYOKAWA-KISO





F20260810141849




BLK: 1,SNR1: 18.658 ,SNR2: 32.877




K20260810141848




BLK: 1,SNR1: 7.2366 ,SNR2: 17.801





3C263.1 2026/08/10 5.34UT FUJI -KISO







BLK: 2,SNR1: 0.55525 ,SNR2: 2.0245




BLK: 2,SNR1: 6.8345 ,SNR2: 17.252





3C267 2026/08/10 5.45UT TOYOKAWA-FUJI







BLK: 4,SNR1: 0.28379 ,SNR2: 1.1787





BLK: 4,SNR1: 6.3884 ,SNR2: 13.025




3C267 2026/08/10 5.45UT TOYOKAWA-KISO





F20260810142515




BLK: 2,SNR1: 2.4961 ,SNR2: 11.684




K20260810142514



BLK: 2,SNR1: 2.1736 ,SNR2: 8.1129





3C267 2026/08/10 5.45UT FUJI -KISO






T20260810145103





BLK: 3,SNR1: 13.312 ,SNR2: 23.186




Frequency (Hz)

F20260810145103





BLK: 3,SNR1: 13.398 ,SNR2: 23.717





Frequency (Hz)

1213-17 2026/08/10 5.88UT TOYOKAWA-FUJI







BLK: 8,SNR1: 9.0305 ,SNR2: 16.136




BLK: 8,SNR1: 5.9990 ,SNR2: 15.775





1213-17 2026/08/10 5.88UT TOYOKAWA-KISO







BLK: 1,SNR1: 13.227 ,SNR2: 30.287





BLK: 1,SNR1: 9.2027 ,SNR2: 16.436




1213-17 2026/08/10 5.88UT FUJI -KISO




T20260810150420




BLK:16,SNR1: 1.2234 ,SNR2: 3.9260




F20260810150420





BLK:16,SNR1: 3.1978 ,SNR2: 7.7296




3C273 2026/08/10 6.10UT TOYOKAWA-FUJI





T20260810150420




BLK:17,SNR1: 3.4443 ,SNR2: 3.2631




K20260810150419




BLK:17,SNR1: 8.3817 ,SNR2: 15.043




3C273 2026/08/10 6.10UT TOYOKAWA-KISO





F20260810150420




BLK:21,SNR1: 10.688 ,SNR2: 11.927




K20260810150419









BLK:21,SNR1: 8.4060 ,SNR2: 15.076





3C273 2026/08/10 6.10UT FUJI -KISO









BLK: 2,SNR1: 14.145 ,SNR2: 24.243




BLK: 2,SNR1: 28.742 ,SNR2: 30.591





3C275 2026/08/10 6.32UT TOYOKAWA-KISO









BLK: 1,SNR1: 9.4717 ,SNR2: 21.079




BLK: 1,SNR1: 24.639 ,SNR2: 40.190





3C275 2026/08/10 6.32UT FUJI -KISO







BLK: 4, SNR1: 5.8557 , SNR2: 10.776





BLK: 4, SNR1: 17.703 , SNR2: 31.798




1245-19 2026/08/10 6.42UT TOYOKAWA-FUJI




T20260810152336




BLK: 5,SNR1: 9.3529 ,SNR2: 23.360




K20260810152335











BLK: 5,SNR1: 2.6136 ,SNR2: 11.859







1245-19 2026/08/10 6.42UT TOYOKAWA-KISO















BLK: 7,SNR1: 6.7450 ,SNR2: 16.842




BLK: 7,SNR1: 7.1325 ,SNR2: 17.853





3C279 2026/08/10 6.55UT FUJI -KISO







BLK: 1,SNR1: 21.016 ,SNR2: 38.273




BLK: 1,SNR1: 12.174 ,SNR2: 28.426





3C283 2026/08/10 6.81UT TOYOKAWA-FUJI









BLK: 1,SNR1: 22.004 ,SNR2: 45.546










BLK: 1,SNR1: 9.9115 ,SNR2: 22.832




3C283 2026/08/10 6.81UT TOYOKAWA-KISO










1323+32 2026/08/10 7.05UT TOYOKAWA-FUJI







BLK: 7,SNR1: 9.5741 ,SNR2: 20.493













BLK: 7,SNR1: 10.677 ,SNR2: 18.791







1323+32 2026/08/10 7.05UT TOYOKAWA-KISO













3C286 2026/08/10 7.13UT TOYOKAWA-KISO



F20260810160604





BLK: 1, SNR1: 4.6143 , SNR2: 11.584




Frequency (Hz)

K20260810160603




BLK: 1, SNR1: 2.2527 , SNR2: 11.808







Frequency (Hz)

3C286 2026/08/10 7.13UT FUJI -KISO













BLK: 1,SNR1: 0.46983 ,SNR2: 3.1967





BLK: 1,SNR1: 12.933 ,SNR2: 22.768




1345+12 2026/08/10 7.40UT TOYOKAWA-KISO



F20260810162231





BLK: 1, SNR1: 22.458 , SNR2: 42.028




Frequency (Hz)

K20260810162230







BLK: 1, SNR1: 10.411 , SNR2: 25.875




Frequency (Hz)



1345+12 2026/08/10 7.40UT FUJI -KISO









BLK: 2, SNR1: 12.250 , SNR2: 29.954








BLK: 2, SNR1: 9.8396 , SNR2: 23.920





1355+01 2026/08/10 7.58UT TOYOKAWA-KISO






T20260810165402




BLK: 6, SNR1: 11.276 , SNR2: 19.693




Frequency (Hz)

F20260810165402








BLK: 6, SNR1: 3.1252 , SNR2: 9.3144




Frequency (Hz)

3C298 2026/08/10 7.93UT TOYOKAWA-FUJI






3C298 2026/08/10 7.93UT TOYOKAWA-KISO






F20260810165402





BLK:10,SNR1: 2.4681 ,SNR2: 7.3723




Frequency (Hz)

K20260810165401



BLK:10,SNR1: 6.5981 ,SNR2: 17.179



Frequency (Hz)

3C298 2026/08/10 7.93UT FUJI -KISO

