








BLK: 5,SNR1: 0.46248 ,SNR2: 3.6479








BLK: 5,SNR1: 0.33714E-01,SNR2: 3.7098




3C161 2026/09/18 21.46UT TOYOKAWA-FUJI








F20260919062603





BLK: 2,SNR1:-0.11743 ,SNR2: 1.1519








3C161 2026/09/18 21.46UT FUJI -KISO

K20260919062602





BLK: 2,SNR1: 0.12147 ,SNR2: 3.4945








T20260919065332




BLK: 2,SNR1: 16.761 ,SNR2: 30.425




K20260919065334





BLK: 2,SNR1: 16.860 ,SNR2: 30.856




0652-130 2026/09/18 21.92UT TOYOKAWA-KISO








0652-130 2026/09/18 21.92UT FUJI -KISO



T20260919070510





BLK: 6,SNR1: 7.5020 ,SNR2: 18.638




Frequency (Hz)

F20260919070513




BLK: 6,SNR1: 8.0078 ,SNR2: 23.426





Frequency (Hz)


0703+138 2026/09/18 22.12UT TOYOKAWA-FUJI



T20260919070510





BLK: 4, SNR1: 8.6231 , SNR2: 20.488




Frequency (Hz)

K20260919070512




BLK: 4, SNR1: 7.5547 , SNR2: 23.046





Frequency (Hz)


0703+138 2026/09/18 22.12UT TOYOKAWA-KISO





F20260919070513




BLK: 2, SNR1: 8.1610 , SNR2: 20.163




K20260919070512






BLK: 2, SNR1: 8.8248 , SNR2: 21.269





0703+138 2026/09/18 22.12UT FUJI -KISO













0713-024 2026/09/18 22.27UT TOYOKAWA-KISO





F20260919071435




No.Good Data




K20260919071434





No.Good Data




0713-024 2026/09/18 22.27UT FUJI -KISO





T20260919072444




BLK: 7, SNR1: 8.0137 , SNR2: 13.917




F20260919072447





BLK: 7, SNR1: 1.0694 , SNR2: 4.6346




0723+10 2026/09/18 22.44UT TOYOKAWA-FUJI





T20260919072444




BLK:12,SNR1: 7.8739 ,SNR2: 13.648




K20260919072446




BLK:12,SNR1: 7.0907 ,SNR2: 18.079




0723+10 2026/09/18 22.44UT TOYOKAWA-KISO





F20260919072447




BLK:12,SNR1: 4.4988 ,SNR2: 6.9466




K20260919072446






BLK:12,SNR1: 6.6152 ,SNR2: 16.851





0723+10 2026/09/18 22.44UT FUJI -KISO







T20260919073500




BLK: 1,SNR1: 2.2016 ,SNR2: 6.6119




K20260919073502





BLK: 1,SNR1: 1.3708 ,SNR2: 7.0806




0732+33 2026/09/18 22.61UT TOYOKAWA-KISO





F20260919073503




BLK: 1, SNR1: 2.9016 , SNR2: 7.6593




K20260919073502



BLK: 1, SNR1: 1.5320 , SNR2: 6.0014





0732+33 2026/09/18 22.61UT FUJI -KISO








T20260919074300




No.Good Data




F20260919074303





No.Good Data




0741-06 2026/09/18 22.75UT TOYOKAWA-FUJI





T20260919074300




BLK: 1, SNR1: 20.510 , SNR2: 37.140




K20260919074302





BLK: 1, SNR1: 9.8658 , SNR2: 24.271




0741-06 2026/09/18 22.75UT TOYOKAWA-KISO





F20260919074303




BLK: 1,SNR1: 0.15955E-02,SNR2: 1.3339




K20260919074302







BLK: 1,SNR1: 3.1395 ,SNR2: 15.008







0741-06 2026/09/18 22.75UT FUJI -KISO










0752-200 2026/09/18 22.91UT TOYOKAWA-FUJI










0752-200 2026/09/18 22.91UT FUJI -KISO




T20260919080020




BLK: 2,SNR1: 2.9551 ,SNR2: 10.294




F20260919080023





BLK: 2,SNR1: 12.591 ,SNR2: 29.977




3C190 2026/09/18 23.03UT TOYOKAWA-FUJI




T20260919080020




BLK: 2, SNR1: 4.7385 , SNR2: 11.279




K20260919080022



BLK: 2, SNR1: 16.371 , SNR2: 37.964




3C190 2026/09/18 23.03UT TOYOKAWA-KISO







F20260919080023




BLK: 7,SNR1: 10.551 ,SNR2: 26.688




K20260919080022





BLK: 7,SNR1: 8.7443 ,SNR2: 24.238




3C190 2026/09/18 23.03UT FUJI -KISO





T20260919081247




No.Good Data




F20260919081250





No.Good Data




3C196 2026/09/18 23.24UT TOYOKAWA-FUJI




T20260919081247




BLK: 2, SNR1: 0.78117 , SNR2: 3.5171




K20260919081249




BLK: 2, SNR1: 2.0318 , SNR2: 6.0851




3C196 2026/09/18 23.24UT TOYOKAWA-KISO





F20260919081250




No.Good Data




K20260919081249






No.Good Data





3C196 2026/09/18 23.24UT FUJI -KISO








T20260919082356




No.Good Data




K20260919082358






No.Good Data





0821+394 2026/09/18 23.43UT TOYOKAWA-KISO






T20260919083533





No.Good Data




Frequency (Hz)

F20260919083536




No.Good Data





Frequency (Hz)

0834-19 2026/09/18 23.62UT TOYOKAWA-FUJI








T20260919083533




No.Good Data




K20260919083535




No.Good Data




0834-19 2026/09/18 23.62UT TOYOKAWA-KISO





F20260919083536




BLK: 1, SNR1: 3.0749 , SNR2: 10.243




K20260919083535





BLK: 1, SNR1: 4.2379 , SNR2: 12.606




0834-19 2026/09/18 23.62UT FUJI -KISO





T20260919084039




No.Good Data




F20260919084042




No.Good Data




0839-071 2026/09/18 23.71UT TOYOKAWA-FUJI





T20260919084039




BLK: 1, SNR1: 1.1101 , SNR2: 10.342




K20260919084041




BLK: 1, SNR1: 20.142 , SNR2: 36.154




0839-071 2026/09/18 23.71UT TOYOKAWA-KISO





F20260919084042




BLK: 6, SNR1: 15.886 , SNR2: 27.728




K20260919084041









BLK: 6, SNR1: 13.570 , SNR2: 24.906




0839-071 2026/09/18 23.71UT FUJI -KISO













BLK: 1,SNR1: 0.70047 ,SNR2: 9.8590



BLK: 1,SNR1: 2.4506 ,SNR2: 6.2187





3C208 2026/09/18 23.89UT FUJI -KISO







T20260919090823




BLK: 4,SNR1:-0.65430E-01,SNR2: 0.83084




F20260919090826





BLK: 4,SNR1: 0.49801 ,SNR2: 5.5535




3C216 2026/09/19 0.17UT TOYOKAWA-FUJI





T20260919090823




BLK: 4,SNR1: 0.50253E-01,SNR2: 0.44013




K20260919090825




BLK: 4,SNR1: 0.15580 ,SNR2: 2.7807




3C216 2026/09/19 0.17UT TOYOKAWA-KISO





F20260919090826




BLK:10,SNR1: 1.1277 ,SNR2: 4.7374




K20260919090825





BLK:10,SNR1: 0.71389E-01,SNR2: 2.2303




3C216 2026/09/19 0.17UT FUJI -KISO




T20260919092033




BLK: 5,SNR1: 0.30833 ,SNR2: 3.1219




F20260919092036





BLK: 5,SNR1:-0.22366 ,SNR2: 1.9511




0919-142 2026/09/19 0.37UT TOYOKAWA-FUJI




T20260919092033




BLK: 2,SNR1: 0.15070E-02,SNR2: 1.3464




K20260919092035







BLK: 2,SNR1: 0.79082 ,SNR2: 6.7130




0919-142 2026/09/19 0.37UT TOYOKAWA-KISO







0919-142 2026/09/19 0.37UT FUJI -KISO




T20260919092712




BLK: 2, SNR1: 2.7153 , SNR2: 8.6105




F20260919092715




BLK: 2, SNR1: 2.3361 , SNR2: 8.5413




0926+117 2026/09/19 0.48UT TOYOKAWA-FUJI





T20260919092712




BLK: 2, SNR1: 2.7153 , SNR2: 8.6105




K20260919092714



BLK: 2, SNR1: 14.745 , SNR2: 35.208




0926+117 2026/09/19 0.48UT TOYOKAWA-KISO







F20260919092715




BLK: 2, SNR1: 13.016 , SNR2: 26.924




K20260919092714





BLK: 2, SNR1: 5.8239 , SNR2: 12.772




0926+117 2026/09/19 0.48UT FUJI -KISO




T20260919093457




BLK: 2, SNR1: 1.3800 , SNR2: 6.6480




F20260919093500




BLK: 2, SNR1: 11.795 , SNR2: 18.203




3C222 2026/09/19 0.61UT TOYOKAWA-FUJI




T20260919093457




BLK: 3, SNR1: 7.5950 , SNR2: 23.188




K20260919093459




BLK: 3, SNR1: 0.21382 , SNR2: 1.6372




3C222 2026/09/19 0.61UT TOYOKAWA-KISO





F20260919093500




BLK: 1, SNR1: 12.615 , SNR2: 30.628




K20260919093459





BLK: 1, SNR1: 6.2816 , SNR2: 16.214




3C222 2026/09/19 0.61UT FUJI -KISO





T20260919094157




BLK:26,SNR1: 44.892 ,SNR2: 58.101




F20260919094200





BLK:26,SNR1: 6.7242 ,SNR2: 19.710




0941-08 2026/09/19 0.73UT TOYOKAWA-FUJI



T20260919094157





BLK:19,SNR1: 18.512 ,SNR2: 31.377





0941-08 2026/09/19 0.73UT TOYOKAWA-KISO



K20260919094159




BLK:19,SNR1: 8.4541 ,SNR2: 23.008





F20260919094200




BLK:18,SNR1: 6.7074 ,SNR2: 19.665




K20260919094159





BLK:18,SNR1: 9.3608 ,SNR2: 17.444




0941-08 2026/09/19 0.73UT FUJI -KISO





T20260919095019




BLK: 4, SNR1: 4.7046 , SNR2: 12.499




F20260919095022



BLK: 4, SNR1: 6.7561 , SNR2: 12.082





3C230 2026/09/19 0.87UT TOYOKAWA-FUJI








T20260919095019




BLK: 1, SNR1: 0.64122 , SNR2: 6.4316




K20260919095021




BLK: 1, SNR1: 6.4681 , SNR2: 16.381





3C230 2026/09/19 0.87UT TOYOKAWA-KISO







BLK: 6,SNR1: 4.9649 ,SNR2: 15.006












BLK: 6,SNR1: 6.6310 ,SNR2: 16.917




3C230 2026/09/19 0.87UT FUJI -KISO












3C237 2026/09/19 1.13UT TOYOKAWA-KISO








3C237 2026/09/19 1.13UT FUJI -KISO




T20260919101236




BLK: 5, SNR1: 3.9755 ,SNR2: 13.831




F20260919101239




BLK: 5, SNR1: 8.2835 ,SNR2: 18.602




1011+110 2026/09/19 1.24UT TOYOKAWA-FUJI




T20260919101236




BLK: 6,SNR1: 1.9522 ,SNR2: 6.0561




K20260919101238





BLK: 6,SNR1: 5.0228 ,SNR2: 8.9512




1011+110 2026/09/19 1.24UT TOYOKAWA-KISO




F20260919101239




BLK: 4, SNR1: 4.2505 , SNR2: 10.633




K20260919101238



BLK: 4, SNR1: 3.3315 , SNR2: 6.2145





1011+110 2026/09/19 1.24UT FUJI -KISO






T20260919102017





BLK: 2, SNR1: 15.587 , SNR2: 42.320





3C241 2026/09/19 1.37UT TOYOKAWA-FUJI



F20260919102020




BLK: 2, SNR1: 12.821 , SNR2: 30.395



T20260919102017





BLK: 3, SNR1: 10.103 , SNR2: 25.670





3C241 2026/09/19 1.37UT TOYOKAWA-KISO



K20260919102019




BLK: 3, SNR1: 12.170 , SNR2: 30.270





F20260919102020




BLK: 1, SNR1: 14.323 , SNR2: 32.528




K20260919102019












BLK: 1, SNR1: 9.6773 , SNR2: 26.759




3C241 2026/09/19 1.37UT FUJI -KISO










1031-11 2026/09/19 1.56UT TOYOKAWA-KISO





F20260919103149




BLK: 3, SNR1: 5.8503 , SNR2: 14.841




K20260919103148




BLK: 3, SNR1: 27.954 , SNR2: 65.253





1031-11 2026/09/19 1.56UT FUJI -KISO







BLK: 1,SNR1: 32.009 ,SNR2: 76.083




BLK: 1,SNR1: 0.53441 ,SNR2: 7.1039




1035-058 2026/09/19 1.63UT TOYOKAWA-FUJI




T20260919103619




BLK: 5, SNR1: 37.016 , SNR2: 90.742




K20260919103621






BLK: 5, SNR1: 9.3512 , SNR2: 23.330





1035-058 2026/09/19 1.63UT TOYOKAWA-KISO










T20260919104532




BLK: 5,SNR1: 2.6403 ,SNR2: 12.169




F20260919104535





BLK: 5,SNR1: 1.7509 ,SNR2: 4.7423




1044-008 2026/09/19 1.79UT TOYOKAWA-FUJI





T20260919104532




BLK: 9,SNR1: 3.0926 ,SNR2: 14.363




K20260919104534




BLK: 9,SNR1: 12.630 ,SNR2: 26.439




1044-008 2026/09/19 1.79UT TOYOKAWA-KISO





F20260919104535




BLK:12,SNR1: 0.99525 ,SNR2: 4.5154




K20260919104534




BLK:12,SNR1: 12.688 ,SNR2: 26.228




1044-008 2026/09/19 1.79UT FUJI -KISO




T20260919105631




BLK: 5, SNR1: 0.59720 , SNR2: 1.5715




F20260919105634




BLK: 5, SNR1: 10.302 , SNR2: 24.592




1055+20 2026/09/19 1.97UT TOYOKAWA-FUJI




T20260919105631




BLK:10,SNR1: 2.3397 ,SNR2: 5.8377




K20260919105633




BLK:10,SNR1: 8.8240 ,SNR2: 22.361




1055+20 2026/09/19 1.97UT TOYOKAWA-KISO




F20260919105634




BLK: 9, SNR1: 7.0054 , SNR2: 16.836




K20260919105633





BLK: 9, SNR1: 7.4000 , SNR2: 21.752




1055+20 2026/09/19 1.97UT FUJI -KISO




T20260919110754




BLK: 5,SNR1: 8.1973 ,SNR2: 21.472




F20260919110757



BLK: 5,SNR1: 11.922 ,SNR2: 28.046





1107+109 2026/09/19 2.16UT TOYOKAWA-FUJI







T20260919110754




BLK: 4,SNR1: 10.570 ,SNR2: 31.115




K20260919110756




BLK: 4,SNR1: 9.5813 ,SNR2: 25.525




1107+109 2026/09/19 2.16UT TOYOKAWA-KISO




F20260919110757




BLK: 2,SNR1: 9.8427 ,SNR2: 24.843




K20260919110756













BLK: 2,SNR1: 10.033 ,SNR2: 28.995




1107+109 2026/09/19 2.16UT FUJI -KISO









F20260919111734




BLK:15,SNR1: 9.5571 ,SNR2: 16.667




K20260919111733




BLK:15,SNR1: 3.7467 ,SNR2: 8.8739




3C255 2026/09/19 2.32UT FUJI -KISO





T20260919112809




BLK: 2, SNR1: 6.1128 , SNR2: 15.257




F20260919112812




BLK: 2, SNR1: 11.344 , SNR2: 28.575




1127-14 2026/09/19 2.50UT TOYOKAWA-FUJI




T20260919112809




BLK: 3,SNR1: 6.5932 ,SNR2: 17.437




K20260919112811




BLK: 3,SNR1: 9.1546 ,SNR2: 23.443





1127-14 2026/09/19 2.50UT TOYOKAWA-KISO







BLK: 4,SNR1: 11.249 ,SNR2: 28.314



BLK: 4,SNR1: 10.297 ,SNR2: 26.119





1127-14 2026/09/19 2.50UT FUJI -KISO








T20260919114129




BLK: 6,SNR1: 8.7518 ,SNR2: 22.132




F20260919114132





BLK: 6,SNR1: 4.6474 ,SNR2: 15.612




3C263.1 2026/09/19 2.72UT TOYOKAWA-FUJI




T20260919114129




BLK:12,SNR1: 9.6859 ,SNR2: 24.755




K20260919114131





BLK:12,SNR1: 8.5268 ,SNR2: 22.228




3C263.1 2026/09/19 2.72UT TOYOKAWA-KISO




F20260919114132




BLK: 8,SNR1: 4.9635 ,SNR2: 12.982




K20260919114131





BLK: 8,SNR1: 13.110 ,SNR2: 16.156




3C263.1 2026/09/19 2.72UT FUJI -KISO





T20260919114756




BLK: 7, SNR1: 1.7532 , SNR2: 4.4447




F20260919114759





BLK: 7, SNR1: 6.9139 , SNR2: 14.792




3C267 2026/09/19 2.83UT TOYOKAWA-FUJI





T20260919114756




BLK:10,SNR1: 1.0435 ,SNR2: 2.9433




K20260919114758




BLK:10,SNR1: 7.5052 ,SNR2: 13.966




3C267 2026/09/19 2.83UT TOYOKAWA-KISO



F20260919114759




BLK:11,SNR1: 11.629 ,SNR2: 20.589






3C267 2026/09/19 2.83UT FUJI -KISO

K20260919114758





BLK:11,SNR1: 7.1681 ,SNR2: 18.475







BLK: 8,SNR1: 2.5753 ,SNR2: 7.2994




BLK: 8,SNR1: 1.8511 ,SNR2: 6.7260





1213-17 2026/09/19 3.26UT TOYOKAWA-FUJI







BLK: 7,SNR1: 2.7491 ,SNR2: 7.4238



BLK: 7,SNR1: 4.3113 ,SNR2: 11.616





1213-17 2026/09/19 3.26UT TOYOKAWA-KISO







F20260919121347




BLK: 5,SNR1: 0.98424 ,SNR2: 3.4743




K20260919121346




BLK: 5,SNR1: 4.4877 ,SNR2: 11.584





1213-17 2026/09/19 3.26UT FUJI -KISO







BLK:17,SNR1: 25.361 ,SNR2: 83.075




BLK:17,SNR1: 1.5202 ,SNR2: 7.6834





3C273 2026/09/19 3.48UT TOYOKAWA-FUJI







BLK:22,SNR1: 26.969 ,SNR2: 82.987




BLK:22,SNR1: 7.4787 ,SNR2: 14.040




3C273 2026/09/19 3.48UT TOYOKAWA-KISO




F20260919122704




BLK:23,SNR1: 6.4057 ,SNR2: 16.384




K20260919122703





BLK:23,SNR1: 8.2682 ,SNR2: 15.464




3C273 2026/09/19 3.48UT FUJI -KISO




T20260919124012




BLK: 4,SNR1: 0.44095 ,SNR2: 2.5399




F20260919124015





BLK: 4,SNR1:-0.14338 ,SNR2: 0.44976




3C275 2026/09/19 3.70UT TOYOKAWA-FUJI




T20260919124012




BLK: 6,SNR1: 0.17425 ,SNR2: 1.7631




K20260919124014




BLK: 6,SNR1: 1.4406 ,SNR2: 2.9116




3C275 2026/09/19 3.70UT TOYOKAWA-KISO





F20260919124015




BLK: 7,SNR1:-0.54641E-01,SNR2: 0.75597




K20260919124014




BLK: 7,SNR1: 1.5407 ,SNR2: 3.9546




3C275 2026/09/19 3.70UT FUJI -KISO




T20260919124617




BLK: 1,SNR1: 5.2676 ,SNR2: 13.658




F20260919124620



BLK: 1,SNR1: 0.96962 ,SNR2: 5.5485




1245-19 2026/09/19 3.80UT TOYOKAWA-FUJI







T20260919124617




BLK: 1,SNR1: 23.086 ,SNR2: 42.449




K20260919124619




BLK: 1,SNR1: 18.568 ,SNR2: 32.762




1245-19 2026/09/19 3.80UT TOYOKAWA-KISO




F20260919124620




BLK: 3,SNR1: 19.727 ,SNR2: 36.048




K20260919124619





BLK: 3,SNR1: 17.736 ,SNR2: 37.515




1245-19 2026/09/19 3.80UT FUJI -KISO




T20260919125401




BLK:12,SNR1: 8.9295 ,SNR2: 16.600




F20260919125404





BLK:12,SNR1: 6.8559 ,SNR2: 17.164




3C279 2026/09/19 3.93UT TOYOKAWA-FUJI




T20260919125401




BLK:13,SNR1: 8.7714 ,SNR2: 16.295




K20260919125403




BLK:13,SNR1: 4.3067 ,SNR2: 10.567




3C279 2026/09/19 3.93UT TOYOKAWA-KISO




F20260919125404




BLK: 9,SNR1: 26.926 ,SNR2: 39.911




K20260919125403




BLK: 9,SNR1: 1.9858 ,SNR2: 6.7448





3C279 2026/09/19 3.93UT FUJI -KISO







BLK: 4,SNR1: 16.815 ,SNR2: 30.743




BLK: 4,SNR1: 17.209 ,SNR2: 30.490





3C283 2026/09/19 4.19UT TOYOKAWA-FUJI







BLK: 3,SNR1: 18.551 ,SNR2: 33.410





BLK: 3,SNR1: 19.024 ,SNR2: 33.217




3C283 2026/09/19 4.19UT TOYOKAWA-KISO




F20260919130934




No.Good Data




K20260919130933



No.Good Data





3C283 2026/09/19 4.19UT FUJI -KISO








T20260919132354




BLK: 8,SNR1: 0.93157E-01,SNR2: 1.2238




F20260919132357





BLK: 8,SNR1: 0.97279 ,SNR2: 3.4102




1323+32 2026/09/19 4.43UT TOYOKAWA-FUJI





T20260919132354




BLK: 5,SNR1: 0.56483 ,SNR2: 1.5873




K20260919132356




BLK: 5,SNR1: 8.6691 ,SNR2: 21.002




1323+32 2026/09/19 4.43UT TOYOKAWA-KISO





F20260919132357




BLK: 9,SNR1: 7.1207 ,SNR2: 18.311




K20260919132356




BLK: 9,SNR1: 0.69988 ,SNR2: 3.9249




1323+32 2026/09/19 4.43UT FUJI -KISO




T20260919132844




BLK:12,SNR1: 0.57045 ,SNR2: 7.3671




F20260919132847




BLK:12,SNR1: 6.4533 ,SNR2: 20.003




3C286 2026/09/19 4.51UT TOYOKAWA-FUJI




T20260919132844




BLK: 8,SNR1: 0.81718 ,SNR2: 3.7123




K20260919132846




BLK: 8,SNR1: 7.1445 ,SNR2: 16.647




3C286 2026/09/19 4.51UT TOYOKAWA-KISO



F20260919132847




BLK: 2,SNR1: 8.0094 ,SNR2: 19.840






3C286 2026/09/19 4.51UT FUJI -KISO

K20260919132846





BLK: 2,SNR1: 6.7685 ,SNR2: 16.539







BLK:22,SNR1: 75.996 ,SNR2: 71.109




BLK:22,SNR1: 10.079 ,SNR2: 34.513





1345+12 2026/09/19 4.78UT TOYOKAWA-FUJI







BLK:14,SNR1: 86.149 ,SNR2: 85.313




BLK:14,SNR1: 2.0784 ,SNR2: 7.0065





1345+12 2026/09/19 4.78UT TOYOKAWA-KISO









BLK: 5,SNR1: 7.1252 ,SNR2: 27.085




BLK: 5,SNR1: 5.3816 ,SNR2: 9.1945




1345+12 2026/09/19 4.78UT FUJI -KISO




T20260919135533




BLK: 6,SNR1: 0.21369 ,SNR2: 3.3570




F20260919135536




BLK: 6,SNR1: 4.8987 ,SNR2: 11.764





1355+01 2026/09/19 4.95UT TOYOKAWA-FUJI







BLK:12,SNR1: 0.22545 ,SNR2: 1.7686





BLK:12,SNR1: 1.0747 ,SNR2: 3.2041





1355+01 2026/09/19 4.95UT TOYOKAWA-KISO




F20260919135536





K20260919135535




1355+01 2026/09/19 4.95UT FUJI -KISO




T20260919141643




BLK:14,SNR1: 1.0381 ,SNR2: 2.5355




F20260919141646





BLK:14,SNR1: 2.3566 ,SNR2: 6.2310




3C298 2026/09/19 5.31UT TOYOKAWA-FUJI




T20260919141643




BLK:21,SNR1: 3.8661 ,SNR2: 6.8770




K20260919141645




BLK:21,SNR1: 7.8262 ,SNR2: 20.293




3C298 2026/09/19 5.31UT TOYOKAWA-KISO




F20260919141646




BLK:19,SNR1: 5.9319 ,SNR2: 10.588




K20260919141645





BLK:19,SNR1: 7.9541 ,SNR2: 20.633





3C298 2026/09/19 5.31UT FUJI -KISO




T20260919142827



F20260919142830





1428-03 2026/09/19 5.50UT TOYOKAWA-FUJI








T20260919142827





K20260919142829




1428-03 2026/09/19 5.50UT TOYOKAWA-KISO





F20260919142830




BLK: 1,SNR1:-0.19218 ,SNR2: 1.0798




K20260919142829





BLK: 1,SNR1: 0.77579 ,SNR2: 4.4902




1428-03 2026/09/19 5.50UT FUJI -KISO



T20260919143708





No.Good Data




Frequency (Hz)

F20260919143711




No.Good Data





Frequency (Hz)


1436-16 2026/09/19 5.65UT TOYOKAWA-FUJI





T20260919143708




No.Good Data




K20260919143710




No.Good Data




1436-16 2026/09/19 5.65UT TOYOKAWA-KISO




F20260919143711




BLK: 1,SNR1: 4.4365 ,SNR2: 11.373




K20260919143710





BLK: 1,SNR1: 11.766 ,SNR2: 28.348




1436-16 2026/09/19 5.65UT FUJI -KISO





T20260919145332




BLK: 4,SNR1: 0.83348 ,SNR2: 2.3183




F20260919145335




BLK: 4,SNR1: 2.1232 ,SNR2: 7.8278





1453-10 2026/09/19 5.92UT TOYOKAWA-FUJI







BLK: 3,SNR1: 0.67894E-01,SNR2: 1.2057





BLK: 3,SNR1: 5.5782 ,SNR2: 14.011




1453-10 2026/09/19 5.92UT TOYOKAWA-KISO




F20260919145335




BLK: 4,SNR1: 5.0697 ,SNR2: 12.780




K20260919145334



BLK: 4,SNR1: 7.2543 ,SNR2: 17.887





1453-10 2026/09/19 5.92UT FUJI -KISO








T20260919150824




BLK: 6,SNR1: 1.6499 ,SNR2: 2.8311




F20260919150827





BLK: 6,SNR1: 6.8808 ,SNR2: 17.908




1508-05 2026/09/19 6.17UT TOYOKAWA-FUJI





T20260919150824




BLK: 8,SNR1: 6.7996 ,SNR2: 12.061




K20260919150826





BLK: 8,SNR1: 8.8355 ,SNR2: 15.809




1508-05 2026/09/19 6.17UT TOYOKAWA-KISO





F20260919150827




BLK: 6,SNR1: 6.7488 ,SNR2: 17.585




K20260919150826





BLK: 6,SNR1: 8.7904 ,SNR2: 15.852




1508-05 2026/09/19 6.17UT FUJI -KISO




T20260919151723




BLK:11,SNR1: 0.22577 ,SNR2: 1.6765




F20260919151726





BLK:11,SNR1: 5.4484 ,SNR2: 12.217




3C318 2026/09/19 6.32UT TOYOKAWA-FUJI





T20260919151723




BLK:10,SNR1: 0.53742 ,SNR2: 2.3797




K20260919151725




BLK:10,SNR1: 1.4575 ,SNR2: 3.8594




3C318 2026/09/19 6.32UT TOYOKAWA-KISO




F20260919151726




BLK:13,SNR1: 4.4863 ,SNR2: 13.495




K20260919151725




BLK:13,SNR1: 2.8107 ,SNR2: 3.7188





3C318 2026/09/19 6.32UT FUJI -KISO







BLK: 6,SNR1: 0.12739 ,SNR2: 1.5201




BLK: 6,SNR1:-0.14484 ,SNR2: 0.51691





1523+03 2026/09/19 6.42UT TOYOKAWA-FUJI







BLK:10,SNR1: 2.7669 ,SNR2: 8.4610



BLK:10,SNR1: 1.3543 ,SNR2: 4.3663





1523+03 2026/09/19 6.42UT TOYOKAWA-KISO








F20260919152314




BLK:11,SNR1: 0.20922 ,SNR2: 2.5829




K20260919152313




BLK:11,SNR1: 3.1908 ,SNR2: 5.1735





1523+03 2026/09/19 6.42UT FUJI -KISO







BLK:10,SNR1: 0.30504 ,SNR2: 1.0738





BLK:10,SNR1: 2.5889 ,SNR2: 4.5651





1535+139 2026/09/19 6.61UT TOYOKAWA-FUJI







BLK:14,SNR1: 0.56703E-01,SNR2: 0.33744





BLK:14,SNR1: 2.1471 ,SNR2: 5.0789




1535+139 2026/09/19 6.61UT TOYOKAWA-KISO





F20260919153453




BLK:14,SNR1: 2.4646 ,SNR2: 4.4671




K20260919153452




BLK:14,SNR1: 0.41570 ,SNR2: 1.5001





1535+139 2026/09/19 6.61UT FUJI -KISO







BLK: 4,SNR1: 8.8407 ,SNR2: 21.818




BLK: 4,SNR1: 17.711 ,SNR2: 31.826





1545-12 2026/09/19 6.78UT TOYOKAWA-FUJI







BLK: 4,SNR1: 9.5640 ,SNR2: 23.546




BLK: 4,SNR1: 10.228 ,SNR2: 25.074





1545-12 2026/09/19 6.78UT TOYOKAWA-KISO








BLK: 3,SNR1: 2.6869 ,SNR2: 12.266





BLK: 3,SNR1: 11.832 ,SNR2: 28.600







BLK:16,SNR1: 0.71453 ,SNR2: 2.4387




BLK:16,SNR1: 0.97709 ,SNR2: 3.2637





1607+26 2026/09/19 7.13UT TOYOKAWA-FUJI









BLK: 9,SNR1: 0.53715 ,SNR2: 2.0376





BLK: 9,SNR1: 0.44706 ,SNR2: 2.1780




1607+26 2026/09/19 7.13UT TOYOKAWA-KISO



F20260919160619





BLK: 3,SNR1: 0.21183 ,SNR2: 2.2640




Frequency (Hz)

K20260919160618





BLK: 3,SNR1:-0.22439E-01,SNR2: 0.35945





Frequency (Hz)

1607+26 2026/09/19 7.13UT FUJI -KISO







BLK: 6, SNR1: 6.2700 , SNR2: 16.521





BLK: 6, SNR1: 8.0939 , SNR2: 22.212




1623-228 2026/09/19 7.43UT TOYOKAWA-FUJI



T20260919162349




BLK: 9, SNR1: 8.1406 , SNR2: 20.548




Frequency (Hz)

K20260919162351





BLK: 9, SNR1: 8.2865 , SNR2: 23.980





Frequency (Hz)

1623-228 2026/09/19 7.43UT TOYOKAWA-KISO







BLK: 2,SNR1: 4.9842 ,SNR2: 12.821






BLK: 2,SNR1: 7.6085 ,SNR2: 21.555





1623-228 2026/09/19 7.43UT FUJI -KISO






T20260919163219





BLK: 6,SNR1: 0.33516E-01,SNR2: 1.3997




Frequency (Hz)

K20260919163221




BLK: 6,SNR1: 1.5351 ,SNR2: 3.9885




Frequency (Hz)


1631-222 2026/09/19 7.57UT TOYOKAWA-KISO





F20260919163222




BLK: 5, SNR1: 0.44609 , SNR2: 2.0741




K20260919163221




BLK: 5, SNR1: 4.0563 , SNR2: 8.6340





1631-222 2026/09/19 7.57UT FUJI -KISO









BLK: 5,SNR1: 7.1482 ,SNR2: 18.221




BLK: 5,SNR1: 5.8309 ,SNR2: 14.879





1638-025 2026/09/19 7.66UT TOYOKAWA-FUJI







BLK: 4,SNR1: 6.3896 ,SNR2: 19.624





BLK: 4,SNR1: 8.2721 ,SNR2: 20.734




1638-025 2026/09/19 7.66UT TOYOKAWA-KISO



F20260919163758





BLK: 8, SNR1: 5.5791 , SNR2: 14.583




Frequency (Hz)

K20260919163757









BLK: 8, SNR1: 5.9618 , SNR2: 20.724





Frequency (Hz)

1638-025 2026/09/19 7.66UT FUJI -KISO






T20260919164450





BLK: 9,SNR1: 0.10992 ,SNR2: 0.85098




Frequency (Hz)

K20260919164452




BLK: 9,SNR1: 4.0570 ,SNR2: 11.174





Frequency (Hz)

1644-106 2026/09/19 7.78UT TOYOKAWA-KISO








T20260919165010




No.Good Data




F20260919165013





No.Good Data




1650+004 2026/09/19 7.87UT TOYOKAWA-FUJI



T20260919165010





BLK: 5, SNR1: 3.7286 , SNR2: 10.991




Frequency (Hz)

K20260919165012




BLK: 5, SNR1: 25.363 , SNR2: 29.782




Frequency (Hz)

1650+004 2026/09/19 7.87UT TOYOKAWA-KISO






F20260919165013





BLK: 3, SNR1: 1.7857 , SNR2: 5.5245




Frequency (Hz)

K20260919165012









BLK: 3, SNR1: 10.359 , SNR2: 25.344






Frequency (Hz)


1650+004 2026/09/19 7.87UT FUJI -KISO









F20260919165545




BLK: 1, SNR1: 27.459 , SNR2: 63.476



K20260919165544



BLK: 1, SNR1: 1.3516 , SNR2: 6.9739



1656+053 2026/09/19 7.96UT FUJI -KISO

