








BLK: 2,SNR1: 23.353 ,SNR2: 43.287






BLK: 2,SNR1: 17.696 ,SNR2: 31.172





0652-130 2026/09/23 21.59UT TOYOKAWA-FUJI








F20260924063356




BLK: 2,SNR1: 22.809 ,SNR2: 41.203




K20260924063355





BLK: 2,SNR1: 18.086 ,SNR2: 32.346




0652-130 2026/09/23 21.59UT FUJI -KISO



T20260924064531





No.Good Data




Frequency (Hz)

F20260924064533




No.Good Data






Frequency (Hz)



0703+138 2026/09/23 21.79UT TOYOKAWA-FUJI










F20260924064533




No.Good Data




K20260924064532









No.Good Data






0703+138 2026/09/23 21.79UT FUJI -KISO












T20260924070506





BLK: 3,SNR1: 7.2497 ,SNR2: 18.139




Frequency (Hz)

F20260924070508







BLK: 3,SNR1: 2.6195 ,SNR2: 6.5509





Frequency (Hz)


0723+10 2026/09/23 22.11UT TOYOKAWA-FUJI












0723+10 2026/09/23 22.11UT FUJI -KISO









BLK: 4,SNR1: 0.60475E-01,SNR2: 1.7545





BLK: 4,SNR1: 0.31150 ,SNR2: 1.2248




0732+33 2026/09/23 22.28UT TOYOKAWA-FUJI





T20260924071522




BLK: 4,SNR1: 0.70678E-01,SNR2: 0.73965




K20260924071523





BLK: 4,SNR1: 2.5215 ,SNR2: 7.4390




0732+33 2026/09/23 22.28UT TOYOKAWA-KISO





F20260924071524




BLK: 4,SNR1: 0.76008E-01,SNR2: 0.93256




K20260924071523





BLK: 4,SNR1: 0.60929 ,SNR2: 1.9816




0732+33 2026/09/23 22.28UT FUJI -KISO





T20260924072322




BLK: 2,SNR1: 0.62032 ,SNR2: 5.5320




F20260924072324





BLK: 2,SNR1: 0.14655 ,SNR2: 0.72853




0741-06 2026/09/23 22.42UT TOYOKAWA-FUJI



T20260924072322




BLK: 2, SNR1: 6.3666 , SNR2: 17.107







0741-06 2026/09/23 22.42UT TOYOKAWA-KISO

K20260924072323





BLK: 2, SNR1: 3.6009 , SNR2: 7.2270







BLK: 1, SNR1: 0.54867 , SNR2: 3.8947





BLK: 1, SNR1: 2.2724 , SNR2: 6.1379




0741-06 2026/09/23 22.42UT FUJI -KISO



T20260924073305




BLK: 2,SNR1:-0.11897 ,SNR2: 0.94505




Frequency (Hz)

F20260924073307




BLK: 2,SNR1:-0.19419 ,SNR2: 0.0000





Frequency (Hz)


0752-200 2026/09/23 22.58UT TOYOKAWA-FUJI



T20260924073305





BLK: 5, SNR1: 0.85311 , SNR2: 1.6550




Frequency (Hz)

K20260924073306




BLK: 5, SNR1: 3.0597 , SNR2: 8.9016




Frequency (Hz)

0752-200 2026/09/23 22.58UT TOYOKAWA-KISO







F20260924073307




BLK: 6,SNR1: 0.13296 ,SNR2: 2.1924




K20260924073306





BLK: 6,SNR1: 0.94262 ,SNR2: 3.6950




0752-200 2026/09/23 22.58UT FUJI -KISO



T20260924074042





BLK:16,SNR1: 12.121 ,SNR2: 29.128





3C190 2026/09/23 22.71UT TOYOKAWA-FUJI



F20260924074044




BLK:16,SNR1: 9.4325 ,SNR2: 22.814





T20260924074042




BLK:16,SNR1: 8.0896 ,SNR2: 20.230




K20260924074043





BLK:16,SNR1: 8.2228 ,SNR2: 21.516




3C190 2026/09/23 22.71UT TOYOKAWA-KISO





F20260924074044




BLK:14,SNR1: 7.7523 ,SNR2: 20.508




K20260924074043




BLK:14,SNR1: 10.017 ,SNR2: 24.218




3C190 2026/09/23 22.71UT FUJI -KISO





T20260924075308




BLK: 2,SNR1: 0.80513E-01,SNR2: 0.70721




F20260924075310





BLK: 2,SNR1: 3.1640 ,SNR2: 6.5044




3C196 2026/09/23 22.91UT TOYOKAWA-FUJI





T20260924075308




BLK: 3, SNR1: 15.522 , SNR2: 35.216




K20260924075309




BLK: 3, SNR1: 18.853 , SNR2: 35.968




3C196 2026/09/23 22.91UT TOYOKAWA-KISO





F20260924075310




BLK: 2, SNR1: 1.5312 , SNR2: 6.5131




K20260924075309




BLK: 2, SNR1: 13.045 , SNR2: 36.970





3C196 2026/09/23 22.91UT FUJI -KISO







BLK: 1,SNR1:-0.17826 ,SNR2: 0.0000







BLK: 1,SNR1: 10.472 ,SNR2: 29.137




0821+394 2026/09/23 23.10UT TOYOKAWA-FUJI









0821+394 2026/09/23 23.10UT TOYOKAWA-KISO





F20260924080419




BLK: 1,SNR1: 8.5564 ,SNR2: 19.932




K20260924080418








BLK: 1,SNR1: 0.23395 ,SNR2: 5.5434




0821+394 2026/09/23 23.10UT FUJI -KISO









0834-19 2026/09/23 23.29UT TOYOKAWA-KISO





F20260924081557




BLK: 1, SNR1: 11.231 ,SNR2: 19.991




K20260924081556




BLK: 1, SNR1: 11.072 ,SNR2: 19.433




0834-19 2026/09/23 23.29UT FUJI -KISO





T20260924082101




BLK: 2, SNR1: 10.762 ,SNR2: 26.233




F20260924082103




BLK: 2, SNR1: 1.0726 ,SNR2: 10.357




0839-071 2026/09/23 23.38UT TOYOKAWA-FUJI




T20260924082101




BLK: 2, SNR1: 10.982 ,SNR2: 26.743




K20260924082102




BLK: 2, SNR1: 7.2662 ,SNR2: 17.882




0839-071 2026/09/23 23.38UT TOYOKAWA-KISO




F20260924082103








K20260924082102





0839-071 2026/09/23 23.38UT FUJI -KISO










T20260924083202




BLK: 2, SNR1: 7.9119 , SNR2: 22.868




K20260924083203







BLK: 2, SNR1: 7.4132 , SNR2: 18.717




3C208 2026/09/23 23.56UT TOYOKAWA-KISO








3C208 2026/09/23 23.56UT FUJI -KISO





T20260924084845




BLK: 5,SNR1: 0.11295E-01,SNR2: 1.2738




F20260924084847





BLK: 5,SNR1: 1.7979 ,SNR2: 4.2222




3C216 2026/09/23 23.84UT TOYOKAWA-FUJI





T20260924084845




BLK: 1,SNR1: 0.48520E-01,SNR2: 0.82439




K20260924084846





BLK: 1,SNR1: 1.0383 ,SNR2: 4.0028




3C216 2026/09/23 23.84UT TOYOKAWA-KISO





F20260924084847




BLK: 2, SNR1: 0.67747 , SNR2: 3.3230




K20260924084846




BLK: 2, SNR1: 9.2369 , SNR2: 20.364




3C216 2026/09/23 23.84UT FUJI -KISO




T20260924090054




BLK: 4,SNR1: 0.99224E-01,SNR2: 1.9925




F20260924090056






BLK: 4,SNR1: 5.0712 ,SNR2: 13.246






0919-142 2026/09/24 0.04UT TOYOKAWA-FUJI














T20260924090734




BLK: 2, SNR1: 7.3855 , SNR2: 18.906




F20260924090736









BLK: 2, SNR1: 8.8066 , SNR2: 15.473







0926+117 2026/09/24 0.15UT TOYOKAWA-FUJI

















3C222 2026/09/24 0.28UT TOYOKAWA-FUJI










T20260924092218




BLK:21,SNR1: 3.5430 ,SNR2: 8.4935




F20260924092220






BLK:21,SNR1: 3.0402 ,SNR2: 7.0157






0941-08 2026/09/24 0.40UT TOYOKAWA-FUJI












T20260924093040




BLK: 3,SNR1: 0.64342 ,SNR2: 2.7913




F20260924093042









BLK: 3,SNR1: 0.34206E-01,SNR2: 4.5050





3C230 2026/09/24 0.54UT TOYOKAWA-FUJI









T20260924094641




BLK:11,SNR1: 1.6224 ,SNR2: 3.6598




F20260924094643









BLK:11,SNR1: 0.39473 ,SNR2: 2.1262



3C237 2026/09/24 0.81UT TOYOKAWA-FUJI












T20260924095257




BLK: 5, SNR1: 1.5281 , SNR2: 5.0100




F20260924095259




BLK: 5, SNR1: 4.3844 , SNR2: 12.039




1011+110 2026/09/24 0.91UT TOYOKAWA-FUJI



T20260924095257





No. Good Data




Frequency (Hz)

KISO







No. Good Data





Frequency (Hz)

1011+110 2026/09/24 0.91UT TOYOKAWA-KISO







T20260924100038




BLK: 5, SNR1: 8.5899 , SNR2: 21.130




F20260924100040









BLK: 5, SNR1: 10.031 , SNR2: 24.407




3C241 2026/09/24 1.04UT TOYOKAWA-FUJI









T20260924101207




BLK: 2, SNR1: 2.9256 , SNR2: 8.6130




F20260924101209






BLK: 2, SNR1: 1.9049 , SNR2: 6.4938






1031-11 2026/09/24 1.23UT TOYOKAWA-FUJI












T20260924101641




BLK:11,SNR1: 12.675 ,SNR2: 44.499




F20260924101643









BLK:11,SNR1: 0.62970 ,SNR2: 4.8802





1035-058 2026/09/24 1.31UT TOYOKAWA-FUJI










T20260924102553









BLK: 7, SNR1: 15.825 , SNR2: 27.658




F20260924102555









T20260924103658




BLK:10,SNR1: 0.83617 ,SNR2: 2.6952




F20260924103700






BLK:10,SNR1: 3.1709 ,SNR2: 7.1749






1055+01 2026/09/24 1.64UT TOYOKAWA-FUJI












T20260924104816





No.Good Data




Frequency (Hz)

F20260924104818







No.Good Data






Frequency (Hz)



1107+109 2026/09/24 1.83UT TOYOKAWA-FUJI










T20260924105753




BLK:16,SNR1: 4.8920 ,SNR2: 14.233




F20260924105755









BLK:16,SNR1: 8.0591 ,SNR2: 18.959



3C255 2026/09/24 1.99UT TOYOKAWA-FUJI













T20260924110830




BLK: 5, SNR1: 0.20815 , SNR2: 2.4224




F20260924110832









BLK: 5, SNR1: 0.94990 , SNR2: 3.6578





1127-14 2026/09/24 2.17UT TOYOKAWA-FUJI









T20260924112151




BLK:11,SNR1: 13.990 ,SNR2: 34.457




F20260924112153









BLK:11,SNR1: 5.7549 ,SNR2: 16.342




3C263.1 2026/09/24 2.39UT TOYOKAWA-FUJI









T20260924112818




BLK:13,SNR1: 0.76263 ,SNR2: 2.3237




F20260924112820






BLK:13,SNR1: 8.1481 ,SNR2: 19.285






3C267 2026/09/24 2.50UT TOYOKAWA-FUJI













T20260924115406




BLK: 1,SNR1: 0.96227E-02,SNR2: 2.8592




F20260924115408









BLK: 1,SNR1: 7.7405 ,SNR2: 29.015




1213-17 2026/09/24 2.93UT TOYOKAWA-FUJI









T20260924120723




BLK: 5, SNR1: 26.453 , SNR2: 47.183




F20260924120725









BLK: 5, SNR1: 7.6672 , SNR2: 14.356




3C273 2026/09/24 3.15UT TOYOKAWA-FUJI









T20260924122034




BLK: 3,SNR1: 0.98864 ,SNR2: 7.6170




F20260924122036






BLK: 3,SNR1: 0.40130 ,SNR2: 2.2460






3C275 2026/09/24 3.37UT TOYOKAWA-FUJI













T20260924122639




BLK: 6,SNR1: 0.22081 ,SNR2: 2.1910




F20260924122641









BLK: 6,SNR1:-0.16164 ,SNR2: 0.15365





1245-19 2026/09/24 3.47UT TOYOKAWA-FUJI










T20260924123422




No.Good Data




F20260924123424









No.Good Data



3C279 2026/09/24 3.60UT TOYOKAWA-FUJI














T20260924124952




BLK: 8,SNR1: 2.5150 ,SNR2: 6.2601




F20260924124954









BLK: 8,SNR1: 1.3918 ,SNR2: 4.7156





3C283 2026/09/24 3.86UT TOYOKAWA-FUJI









T20260924130416




BLK: 6,SNR1: 8.0828 ,SNR2: 14.488




F20260924130418









BLK: 6,SNR1: 4.0547 ,SNR2: 11.034




1323+32 2026/09/24 4.10UT TOYOKAWA-FUJI









T20260924130906




BLK: 2,SNR1: 9.6975 ,SNR2: 22.844




F20260924130908






BLK: 2,SNR1: 18.228 ,SNR2: 39.389






3C286 2026/09/24 4.18UT TOYOKAWA-FUJI













T20260924132533




BLK: 5,SNR1: 15.076 ,SNR2: 26.499




F20260924132535





BLK: 5,SNR1: 11.459 ,SNR2: 27.505







1345+12 2026/09/24 4.45UT TOYOKAWA-FUJI







1345+12 2026/09/24 4.45UT TOYOKAWA-KISO







T20260924133554




BLK:11,SNR1: 0.30839 ,SNR2: 3.0868




F20260924133556









BLK:11,SNR1: 0.58298 ,SNR2: 3.2579





1355+01 2026/09/24 4.63UT TOYOKAWA-FUJI









T20260924135705




BLK:10,SNR1: 3.2546 ,SNR2: 9.4231




F20260924135707






BLK:10,SNR1: 1.2784 ,SNR2: 3.4301






3C298 2026/09/24 4.98UT TOYOKAWA-FUJI














T20260924140848




BLK:11,SNR1: 11.778 ,SNR2: 25.431




F20260924140850









BLK:11,SNR1: 3.7899 ,SNR2: 8.5158




1428-03 2026/09/24 5.18UT TOYOKAWA-FUJI










T20260924141730




BLK: 3,SNR1: 13.125 ,SNR2: 32.157




F20260924141732





BLK: 3,SNR1: 12.665 ,SNR2: 30.972







1436-16 2026/09/24 5.32UT TOYOKAWA-FUJI






1436-16 2026/09/24 5.32UT TOYOKAWA-KISO










T20260924143353




BLK: 3,SNR1: 10.180 ,SNR2: 25.310




F20260924143355









BLK: 3,SNR1: 24.688 ,SNR2: 37.252




1453-10 2026/09/24 5.59UT TOYOKAWA-FUJI










T20260924144845




BLK: 2,SNR1: 19.910 ,SNR2: 35.914




F20260924144847









BLK: 2,SNR1: 11.353 ,SNR2: 27.805




1508-05 2026/09/24 5.84UT TOYOKAWA-FUJI













BLK: 7,SNR1: 3.9051 ,SNR2: 11.090






BLK: 7,SNR1: 4.4374 ,SNR2: 11.400






3C318 2026/09/24 5.99UT TOYOKAWA-FUJI












T20260924150332




BLK: 1,SNR1: 11.034 ,SNR2: 27.043




F20260924150334









BLK: 1,SNR1: 2.3045 ,SNR2: 17.886




1523+03 2026/09/24 6.09UT TOYOKAWA-FUJI













BLK: 3,SNR1: 7.7235 ,SNR2: 18.868









BLK: 3,SNR1: 9.6996 ,SNR2: 23.285




1535+139 2026/09/24 6.28UT TOYOKAWA-FUJI













BLK: 6,SNR1: 144.97 ,SNR2: 153.27





BLK: 6,SNR1: 14.193 ,SNR2: 25.837




1545-12 2026/09/24 6.46UT TOYOKAWA-FUJI












1545-12 2026/09/24 6.46UT TOYOKAWA-KISO






T20260924154638





BLK: 4, SNR1: 12.210 , SNR2: 30.607




Frequency (Hz)

F20260924154640







BLK: 4, SNR1: 6.5877 , SNR2: 10.671







Frequency (Hz)

1607+26 2026/09/24 6.81UT TOYOKAWA-FUJI













BLK: 2,SNR1: 9.7435 ,SNR2: 26.659









BLK: 2,SNR1: 4.8263 ,SNR2: 11.882





1623-228 2026/09/24 7.10UT TOYOKAWA-FUJI


















1631-222 2026/09/24 7.24UT TOYOKAWA-FUJI








1631-222 2026/09/24 7.24UT TOYOKAWA-KISO









BLK: 3,SNR1:-0.93051E-02,SNR2: 1.3898









BLK: 3,SNR1: 0.64866 ,SNR2: 2.2453




1638-025 2026/09/24 7.33UT TOYOKAWA-FUJI








T20260924162511





BLK: 2, SNR1: 3.4193 , SNR2: 8.2011




Frequency (Hz)

F20260924162513






BLK: 2, SNR1: 2.8564 , SNR2: 8.5334




Frequency (Hz)

1644-106 2026/09/24 7.45UT TOYOKAWA-FUJI









1644-106 2026/09/24 7.45UT TOYOKAWA-KISO













BLK: 3,SNR1: 7.3449 ,SNR2: 20.674





BLK: 3,SNR1: 4.4447 ,SNR2: 12.316







1650+004 2026/09/24 7.54UT TOYOKAWA-FUJI














1650+004 2026/09/24 7.54UT TOYOKAWA-KISO














T20260924165233




BLK: 2, SNR1: 5.9859 , SNR2: 15.234




Frequency (Hz)

F20260924165235



BLK: 2, SNR1: 8.5562 , SNR2: 21.114



Frequency (Hz)

1712-033 2026/09/24 7.90UT TOYOKAWA-FUJI

